

Date Time	Action	Battery %	Video Cour	Firmware \	GB Remain	Evidence ID
44:30.0	Device connected to charger					
44:30.0	Device powered on due to charger connection	50	0		56.365	
44:31.0	Camera connected to Axon Dock X62YY0XFV	50	0		56.364	
44:32.9	Audit log rolled	50	0		56.365	
45:38.0	Date/Time synced to 03/08/2021 05:45:38.02 PM from 03/08/2021 05:45:02.37 PM					
46:07.0	Date/Time synced to 03/08/2021 05:46:07.01 PM from 03/08/2021 05:46:07.31 PM					
46:12.7	Select button pressed					
46:12.9	Select button released					
46:13.7	Device registered to martapdga.evidence.com using Axon application					
46:14.1	Volume changed to medium from low using Axon application					
46:14.7	Device registered to MARTA POLICE DEPT.					
46:38.0	Date/Time synced to 03/08/2021 05:46:38.02 PM from 03/08/2021 05:46:36.99 PM					
46:38.8	Audit log successfully uploaded					
46:38.8	Audit log successfully uploaded					
46:38.8	Audit log successfully uploaded					
46:38.8	Audit log successfully uploaded					
46:38.8	Audit log successfully uploaded					
46:39.0	Audit log successfully uploaded and deleted from device	50	0		56.367	
46:39.0	Audit log successfully uploaded and deleted from device	50	0		56.367	
46:39.1	Audit log successfully uploaded and deleted from device	50	0		56.367	
46:39.1	Audit log successfully uploaded and deleted from device	50	0		56.367	
46:39.1	Audit log successfully uploaded and deleted from device	50	0		56.367	
46:43.2	Camera disconnected from Axon Dock X62YY0XFV	50	0		56.367	
46:43.3	Audio recording disabled due to video buffering default					
46:43.6	Device disconnected from charger	50	0		56.367	
55:03.2	Power button pressed					
55:06.2	Device powered off using button	49	0		56.366	
55:06.6	Power button released					
58:20.4	Device reassigned from MARTA POLICE DEPT. to MORAES, NILSON (M1225) by Salters, Chablis (R1071)					
58:20.4	Device status updated from In Stock to Assigned by Salters, Chablis (R1071)					
48:04.0	Device connected to charger					
48:04.0	Device powered on due to charger connection	43	0		56.366	
48:05.0	Camera connected to Axon Dock X62001W9H	44	0		56.361	
48:06.9	Audit log rolled	43	0		56.366	
48:11.9	Audit log successfully uploaded					
48:11.9	Audit log successfully uploaded					
48:12.1	Audit log successfully uploaded and deleted from device	43	0		56.366	
48:12.1	Audit log successfully uploaded and deleted from device	43	0		56.366	
48:47.0	Date/Time synced to 04/02/2021 01:48:47.01 AM from 04/02/2021 01:48:36.39 AM					
18:47.0	Date/Time synced to 04/02/2021 02:18:47.01 AM from 04/02/2021 02:18:47.03 AM					
48:22.5	Audit log successfully uploaded					
48:22.7	Audit log successfully uploaded and deleted from device	72	0		56.353	
48:47.0	Date/Time synced to 04/02/2021 02:48:47.01 AM from 04/02/2021 02:48:46.92 AM					
18:47.0	Date/Time synced to 04/02/2021 03:18:47.01 AM from 04/02/2021 03:18:46.90 AM					
48:23.0	Audit log successfully uploaded					
48:23.2	Audit log successfully uploaded and deleted from device	97	0		56.353	

48:47.0 Date/Time synced to 04/02/2021 03:48:47.01 AM from 04/02/2021 03:48:46.92 AM			
18:47.0 Date/Time synced to 04/02/2021 04:18:47.01 AM from 04/02/2021 04:18:46.89 AM			
48:23.5 Audit log successfully uploaded			
48:23.7 Audit log successfully uploaded and deleted from device	100	0	56.353
48:47.0 Date/Time synced to 04/02/2021 04:48:47.01 AM from 04/02/2021 04:48:46.92 AM			
18:47.0 Date/Time synced to 04/02/2021 05:18:47.01 AM from 04/02/2021 05:18:46.92 AM			
48:24.0 Audit log successfully uploaded			
48:24.2 Audit log successfully uploaded and deleted from device	100	0	56.352
48:47.0 Date/Time synced to 04/02/2021 05:48:47.01 AM from 04/02/2021 05:48:46.92 AM			
18:47.0 Date/Time synced to 04/02/2021 06:18:47.01 AM from 04/02/2021 06:18:46.92 AM			
48:24.4 Audit log successfully uploaded			
48:24.6 Audit log successfully uploaded and deleted from device	100	0	56.352
48:35.6 Firmware version 1.12.23 detected		1.10.24	
48:47.0 Date/Time synced to 04/02/2021 06:48:47.01 AM from 04/02/2021 06:48:46.93 AM			
49:49.2 Firmware version 1.12.23 downloaded	100	0 1.10.24	55.732
53:42.5 Firmware update to version 1.12.23 started	100	0 1.10.24	55.732
53:42.5 Device restarting due to firmware update	100	0	55.732
55:54.9 Camera connected to Axon Dock X62001W9H	99	0	55.732
55:54.9 Device restarted due to firmware update	98	0	55.732
55:55.2 Firmware successfully updated to 1.12.23		1.12.23	
55:55.9 Camera connected to Axon Dock X62001W9H	99	0	55.732
55:57.8 Audit log rolled	98	0	55.732
55:57.8 Audit log created	98	0 1.12.23	55.732
55:58.1 Led brightness mode changed to Auto from Dim			
56:01.9 Audit log successfully uploaded			
56:02.0 Audit log successfully uploaded and deleted from device	98	0	55.732
56:39.0 Date/Time synced to 04/02/2021 06:56:39.02 AM from 04/02/2021 06:56:27.41 AM			
26:39.0 Date/Time synced to 04/02/2021 07:26:39.01 AM from 04/02/2021 07:26:39.04 AM			
56:08.1 Audit log created	100	0 1.12.23	55.731
56:38.8 Audit log successfully uploaded			
56:39.0 Date/Time synced to 04/02/2021 07:56:39.01 AM from 04/02/2021 07:56:38.89 AM			
56:39.0 Audit log successfully uploaded and deleted from device	100	0	55.732
26:39.0 Date/Time synced to 04/02/2021 08:26:39.01 AM from 04/02/2021 08:26:38.92 AM			
56:08.2 Audit log created	100	0 1.12.23	55.731
56:39.0 Date/Time synced to 04/02/2021 08:56:39.01 AM from 04/02/2021 08:56:38.92 AM			
56:39.3 Audit log successfully uploaded			
56:39.4 Audit log successfully uploaded and deleted from device	100	0	55.731
26:39.0 Date/Time synced to 04/02/2021 09:26:39.01 AM from 04/02/2021 09:26:38.92 AM			
56:08.2 Audit log created	100	0 1.12.23	55.731
56:39.0 Date/Time synced to 04/02/2021 09:56:39.01 AM from 04/02/2021 09:56:38.92 AM			
56:39.6 Audit log successfully uploaded			
56:39.9 Audit log successfully uploaded and deleted from device	100	0	55.731
26:39.0 Date/Time synced to 04/02/2021 10:26:39.01 AM from 04/02/2021 10:26:38.90 AM			
56:08.1 Audit log created	100	0 1.12.23	55.731
56:39.0 Date/Time synced to 04/02/2021 10:56:39.01 AM from 04/02/2021 10:56:38.88 AM			
56:40.1 Audit log successfully uploaded			
56:40.3 Audit log successfully uploaded and deleted from device	100	0	55.731

26:39.0 Date/Time synced to 04/02/2021 11:26:39.01 AM from 04/02/2021 11:26:38.92 AM			
56:08.2 Audit log created	100	0 1.12.23	55.731
56:39.0 Date/Time synced to 04/02/2021 11:56:39.01 AM from 04/02/2021 11:56:38.90 AM			
56:40.5 Audit log successfully uploaded			
56:40.7 Audit log successfully uploaded and deleted from device	100	0	55.731
26:39.0 Date/Time synced to 04/02/2021 12:26:39.01 PM from 04/02/2021 12:26:38.90 PM			
56:08.2 Audit log created	100	0 1.12.23	55.73
56:39.0 Date/Time synced to 04/02/2021 12:56:39.01 PM from 04/02/2021 12:56:38.90 PM			
56:40.9 Audit log successfully uploaded			
56:41.1 Audit log successfully uploaded and deleted from device	100	0	55.73
26:39.0 Date/Time synced to 04/02/2021 01:26:39.01 PM from 04/02/2021 01:26:38.93 PM			
56:08.2 Audit log created	100	0 1.12.23	55.73
56:39.0 Date/Time synced to 04/02/2021 01:56:39.01 PM from 04/02/2021 01:56:38.91 PM			
56:41.3 Audit log successfully uploaded			
56:41.5 Audit log successfully uploaded and deleted from device	100	0	55.73
26:39.0 Date/Time synced to 04/02/2021 02:26:39.01 PM from 04/02/2021 02:26:38.92 PM			
56:08.2 Audit log created	100	0 1.12.23	55.73
56:39.0 Date/Time synced to 04/02/2021 02:56:39.01 PM from 04/02/2021 02:56:38.91 PM			
56:41.8 Audit log successfully uploaded			
56:42.0 Audit log successfully uploaded and deleted from device	100	0	55.73
26:39.0 Date/Time synced to 04/02/2021 03:26:39.01 PM from 04/02/2021 03:26:38.92 PM			
56:08.2 Audit log created	100	0 1.12.23	55.73
56:39.0 Date/Time synced to 04/02/2021 03:56:39.01 PM from 04/02/2021 03:56:38.92 PM			
56:42.2 Audit log successfully uploaded			
56:42.4 Audit log successfully uploaded and deleted from device	100	0	55.73
26:39.0 Date/Time synced to 04/02/2021 04:26:39.01 PM from 04/02/2021 04:26:38.92 PM			
56:08.2 Audit log created	100	0 1.12.23	55.729
56:39.0 Date/Time synced to 04/02/2021 04:56:39.01 PM from 04/02/2021 04:56:38.92 PM			
56:42.6 Audit log successfully uploaded			
56:42.9 Audit log successfully uploaded and deleted from device	100	0	55.73
26:39.0 Date/Time synced to 04/02/2021 05:26:39.01 PM from 04/02/2021 05:26:38.91 PM			
56:08.2 Audit log created	100	0 1.12.23	55.729
56:39.0 Date/Time synced to 04/02/2021 05:56:39.01 PM from 04/02/2021 05:56:38.92 PM			
56:43.2 Audit log successfully uploaded			
56:43.4 Audit log successfully uploaded and deleted from device	100	0	55.729
26:39.0 Date/Time synced to 04/02/2021 06:26:39.01 PM from 04/02/2021 06:26:38.91 PM			
44:39.9 Camera disconnected from Axon Dock X62001W9H	98	0	55.729
44:40.0 Device disconnected from charger	98	0	55.729
44:40.1 Audio recording disabled due to video buffering default			
44:43.2 Power button pressed			
44:46.2 Led brightness mode changed to On from Auto			
44:46.2 Device powered off using button	100	0	55.729
44:46.2 Front led auto brightness disabled using button			
44:46.2 Top led auto brightness disabled using button			
44:46.5 Power button released			
41:08.9 Audit log created		1.12.23	
41:09.0 Device powered on using button	100	0	55.729

41:11.0 Audio recording disabled due to video buffering default			
45:15.4 Volume up button pressed			
45:18.4 Led brightness mode changed to Dim from On			
45:18.5 Front led brightness changed to 1% from 30% using button			
45:18.5 Top led brightness changed to 1% from 15% using button			
45:22.9 Volume up button released			
45:29.9 Volume up button pressed			
45:33.0 Led brightness mode changed to Off from Dim			
45:33.0 Front led disabled using button			
45:33.0 Top led disabled using button			
45:35.0 Volume up button released			
45:41.0 Volume up button pressed			
45:44.0 Led brightness mode changed to On from Off			
45:44.1 Front led brightness changed to 30% from 1% using button			
45:44.1 Front led enabled using button			
45:44.1 Top led brightness changed to 15% from 1% using button			
45:44.1 Top led enabled using button			
45:44.9 Volume up button released			
46:45.3 Volume up button pressed			
46:45.5 Volume up button released			
46:45.6 Volume changed to high from medium using button			
46:54.5 Select button pressed			
46:59.2 Select button released			
47:00.5 Select button pressed			
47:01.6 Select button released			
47:03.1 Volume up button pressed			
47:06.1 Led brightness mode changed to Dim from On			
47:06.1 Front led brightness changed to 1% from 30% using button			
47:06.2 Top led brightness changed to 1% from 15% using button			
47:07.2 Volume up button released			
47:08.5 Volume up button pressed			
47:11.5 Led brightness mode changed to Off from Dim			
47:11.5 Front led disabled using button			
47:11.5 Top led disabled using button			
47:12.1 Volume up button released			
47:15.3 Volume up button pressed			
47:18.4 Led brightness mode changed to On from Off			
47:18.4 Front led brightness changed to 30% from 1% using button			
47:18.4 Front led enabled using button			
47:18.4 Top led brightness changed to 15% from 1% using button			
47:18.5 Top led enabled using button			
47:18.9 Volume up button released			
47:56.6 Power button pressed			
47:59.6 Device powered off using button	98	0	55.728
48:00.1 Power button released			
50:36.0 Device powered on using button	98	0	55.728
50:38.0 Audio recording disabled due to video buffering default			

51:51.3 Event button pressed			
51:51.6 Event button released			
51:51.8 Event button pressed			
51:51.9 Audio recording enabled due to video recording default			
51:52.0 Event button released			
51:52.1 Recording started due to button press	97	1	55.727 8411a7b93d374ad3a83341c0212a2542
51:55.1 Event button pressed			
51:55.4 Event button released			
51:58.9 Event button pressed			
52:01.4 Event button released			
52:01.5 Event button pressed			
52:01.6 Event button released			
52:12.1 Event button pressed			
52:15.1 Recording stopped due to button press	97	1	55.7 8411a7b93d374ad3a83341c0212a2542
52:15.7 Event button released			
52:21.3 Event button pressed			
52:21.5 Event button released			
52:21.6 Event button pressed			
52:21.8 Recording started due to button press	97	1	55.7 821006a0526046deb9f52c6e91b5aca7
52:21.8 Event button released			
52:23.5 Event button pressed			
52:26.5 Recording stopped due to button press	97	2	55.695 821006a0526046deb9f52c6e91b5aca7
52:26.9 Event button released			
00:05.4 Volume up button pressed			
00:05.8 Volume up button released			
00:05.8 Volume up button pressed			
00:05.9 Volume changed to very high from high using button			
00:05.9 Volume up button released			
00:05.9 Volume up button pressed			
00:06.0 Volume up button released			
24:41.0 Select button pressed			
24:41.0 Select button released			
24:41.1 Select button pressed			
24:41.1 Select button released			
24:48.9 Event button pressed			
24:49.0 Programmable button pressed			
24:49.2 Event button released			
24:49.2 Programmable button released			
25:48.9 Axon application connected to device			
26:30.1 Categories 'Accidental Recording' added to video metadata using Axon applicator			821006a0526046deb9f52c6e91b5aca7
26:45.9 Title changed in video metadata from " to 'Training' using Axon application			821006a0526046deb9f52c6e91b5aca7
27:08.8 Video played back using Axon application			8411a7b93d374ad3a83341c0212a2542
28:15.4 Video played back using Axon application			8411a7b93d374ad3a83341c0212a2542
28:16.1 Video played back using Axon application			8411a7b93d374ad3a83341c0212a2542
28:33.9 Categories 'Accidental Recording' added to video metadata using Axon applicator			8411a7b93d374ad3a83341c0212a2542
29:03.9 Title changed in video metadata from " to 'Training' using Axon application			8411a7b93d374ad3a83341c0212a2542
29:30.6 Top led brightness changed to 20% from 15% using Axon application			

30:50.7 Axon application disconnected from device			
31:50.0 Axon application connected to device			
35:30.1 Axon application disconnected from device			
41:08.0 Audit log created	90	2 1.12.23	55.693
42:13.1 Recording started due to TASER activation	90	3	55.692 16e2605e142c44f0bb3773740db16ce4
42:39.3 Event button pressed			
42:42.3 Recording stopped due to button press	90	3	55.638 16e2605e142c44f0bb3773740db16ce4
42:42.8 Event button released			
43:21.7 Recording started due to TASER activation	90	4	55.614 8442150274344ed0ab55822b9486fde4
43:26.5 Select button pressed			
43:32.8 Select button released			
43:33.6 Select button pressed			
43:34.8 Select button released			
43:34.8 Marker added to video due to button			
43:36.6 Select button pressed			
43:37.8 Select button released			
43:37.8 Marker added to video due to button			
43:39.2 Event button pressed			
43:42.2 Recording stopped due to button press	90	4	55.583 8442150274344ed0ab55822b9486fde4
43:42.6 Event button released			
43:45.3 Recording started due to TASER activation	90	4	55.583 018490b8776440258e6be8a5736e7f95
43:48.4 Select button pressed			
43:53.4 Select button released			
43:54.8 Select button pressed			
43:55.0 Select button released			
43:55.6 Marker added to video due to button			
43:57.0 Event button pressed			
44:00.0 Recording stopped due to button press	90	5	55.574 018490b8776440258e6be8a5736e7f95
44:00.4 Event button released			
44:02.3 Recording started due to TASER activation	90	6	55.574 6ebb439fad5c47009a13e941e1c365be
44:04.7 Select button pressed			
44:05.1 Select button released			
44:05.5 Signal alert dismissal sent to Axon Evidence			
44:08.6 Recording stopped due to signal alert dismissal	90	6	55.57 6ebb439fad5c47009a13e941e1c365be
44:13.0 Select button pressed			
44:13.3 Select button released			
44:49.0 Recording started due to TASER activation	90	7	55.569 a133c9ae34074287a758eb1339ee9c1f
44:54.4 Select button pressed			
44:55.0 Select button released			
44:55.1 Signal alert dismissal sent to Axon Evidence			
44:58.2 Recording stopped due to signal alert dismissal	90	7	55.552 a133c9ae34074287a758eb1339ee9c1f
46:10.9 Camera connected to Axon Dock X62001W9H	90	7	55.546
46:10.9 Audit log rolled	90	7	55.544
46:10.9 Audit log created	90	7 1.12.23	55.544
46:12.0 Device connected to charger	90	7	55.544
46:35.8 Video upload started when camera was docked			8411a7b93d374ad3a83341c0212a2542
46:36.0 Audit log successfully uploaded			

46:36.0	Audit log successfully uploaded			
46:36.0	Audit log successfully uploaded			
46:36.2	Audit log successfully uploaded and deleted from device	90	7	55.546
46:36.2	Audit log successfully uploaded and deleted from device	90	7	55.546
46:36.3	Audit log successfully uploaded and deleted from device	90	7	55.546
46:48.0	Date/Time synced to 04/13/2021 11:46:48.01 PM from 04/13/2021 11:46:40.96 PM			
46:50.4	Video successfully uploaded from device when docked			8411a7b93d374ad3a83341c0212a2542
46:50.6	Video deleted from device when docked	90	6	55.573 8411a7b93d374ad3a83341c0212a2542
46:50.8	Video upload started when camera was docked			821006a0526046deb9f52c6e91b5aca7
46:53.5	Video successfully uploaded from device when docked			821006a0526046deb9f52c6e91b5aca7
46:53.7	Video deleted from device when docked	90	5	55.579 821006a0526046deb9f52c6e91b5aca7
46:53.9	Video upload started when camera was docked			16e2605e142c44f0bb3773740db16ce4
47:14.6	Video successfully uploaded from device when docked			16e2605e142c44f0bb3773740db16ce4
47:14.8	Video deleted from device when docked	90	4	55.657 16e2605e142c44f0bb3773740db16ce4
47:15.0	Video upload started when camera was docked			8442150274344ed0ab55822b9486fde4
47:23.5	Video successfully uploaded from device when docked			8442150274344ed0ab55822b9486fde4
47:23.7	Video deleted from device when docked	90	3	55.688 8442150274344ed0ab55822b9486fde4
47:23.9	Video upload started when camera was docked			018490b8776440258e6be8a5736e7f95
47:30.8	Video successfully uploaded from device when docked			018490b8776440258e6be8a5736e7f95
47:31.0	Video deleted from device when docked	90	2	55.696 018490b8776440258e6be8a5736e7f95
47:31.2	Video upload started when camera was docked			6ebb439fad5c47009a13e941e1c365be
47:35.1	Video successfully uploaded from device when docked			6ebb439fad5c47009a13e941e1c365be
47:35.3	Video deleted from device when docked	90	1	55.701 6ebb439fad5c47009a13e941e1c365be
47:35.8	Video upload started when camera was docked			a133c9ae34074287a758eb1339ee9c1f
47:52.1	Video successfully uploaded from device when docked			a133c9ae34074287a758eb1339ee9c1f
47:52.3	Video deleted from device when docked	90	0	55.726 a133c9ae34074287a758eb1339ee9c1f
47:52.3	Audit log rolled	90	0	55.726
47:52.3	Audit log created	90	0 1.12.23	55.726
56:26.8	Camera disconnected from Axon Dock X62001W9H	94	0	55.726
56:26.9	Device disconnected from charger	94	0	55.727
56:55.6	Programmable button pressed			
56:55.9	Programmable button released			
57:12.8	Programmable button pressed			
57:12.8	Programmable button released			
47:52.0	Audit log created	88	0 1.12.23	55.726
43:27.6	Axon application connected to device			
44:48.8	Axon application disconnected from device			
47:52.0	Audit log created	82	0 1.12.23	55.725
47:52.0	Audit log created	76	0 1.12.23	55.723
47:52.0	Audit log created	70	0 1.12.23	55.722
29:27.9	Device connected to charger	65	0	55.722
31:21.9	Device disconnected from charger	66	0	55.721
47:52.0	Audit log created	64	0 1.12.23	55.721
47:52.0	Audit log created	59	0 1.12.23	55.72
56:23.9	Select button pressed			
56:24.0	Select button released			
56:26.7	Select button pressed			

56:26.9 Select button released
56:27.2 Select button pressed
56:27.4 Select button released
56:28.0 Select button pressed
56:30.6 Select button released
56:31.5 Select button pressed
56:32.8 Select button released
56:35.1 Select button pressed
56:38.3 Select button released
04:50.5 Programmable button pressed
04:57.8 Programmable button released
28:53.5 Volume down button pressed
28:53.6 Volume down button released
28:53.8 Volume changed to high from very high using button
28:53.8 Volume down button pressed
28:54.1 Volume down button released
28:54.2 Volume changed to medium from high using button
28:59.3 Volume down button pressed
29:00.7 Volume down button released
29:00.8 Volume changed to low from medium using button
29:02.0 Volume down button pressed
29:03.5 Volume down button released
29:03.6 Volume changed to very low from low using button
29:07.1 Select button pressed
29:07.3 Select button released
29:08.3 Select button pressed
29:10.5 Select button released
29:13.4 Volume up button pressed
29:15.5 Volume up button released
29:15.6 Volume changed to low from very low using button
29:16.2 Volume up button pressed
29:18.4 Volume up button released
29:18.5 Volume changed to medium from low using button
29:19.0 Volume up button pressed
29:22.1 Led brightness mode changed to Dim from On
29:22.2 Front led brightness changed to 1% from 30% using button
29:22.2 Top led brightness changed to 1% from 20% using button
29:22.7 Volume up button released
29:27.2 Volume down button pressed
29:28.9 Volume down button released
29:29.0 Volume changed to low from medium using button
29:30.7 Volume up button pressed
29:31.5 Volume up button released
29:31.6 Volume changed to medium from low using button
29:35.5 Select button pressed
29:35.7 Select button released
29:37.7 Select button pressed

29:37.9 Select button released
29:38.7 Select button pressed
29:38.9 Select button released
29:39.5 Select button pressed
29:43.0 Select button released
29:47.2 Volume down button pressed
29:50.7 Volume down button released
29:51.2 Volume down button pressed
29:52.1 Volume down button released
29:52.2 Volume changed to low from medium using button
29:54.3 Volume up button pressed
29:56.3 Volume up button released
29:56.3 Volume changed to medium from low using button
29:56.5 Volume up button pressed
29:56.7 Volume up button released
29:56.8 Volume changed to high from medium using button
29:57.6 Volume up button pressed
29:57.8 Volume up button released
29:57.9 Volume changed to very high from high using button
29:58.7 Volume up button pressed
29:58.9 Volume up button released
30:03.4 Select button pressed
30:03.7 Select button released
30:04.8 Volume down button pressed
30:05.2 Volume down button released
30:05.3 Volume changed to high from very high using button
30:06.8 Volume up button pressed
30:07.1 Volume up button released
30:07.2 Volume changed to very high from high using button
30:13.9 Programmable button pressed
30:14.1 Programmable button released
30:17.0 Programmable button pressed
30:17.1 Programmable button released
30:20.8 Volume down button pressed
30:21.1 Volume down button released
30:21.2 Volume changed to high from very high using button
30:23.0 Volume up button pressed
30:23.4 Volume up button released
30:23.5 Volume changed to very high from high using button
30:24.3 Volume up button pressed
30:24.5 Volume up button released
30:25.5 Volume up button pressed
30:25.8 Volume up button released
30:28.9 Select button pressed
30:32.4 Select button released
30:35.2 Volume down button pressed
30:35.5 Volume down button released

30:35.6	Volume changed to high from very high using button			
30:37.1	Volume up button pressed			
30:37.4	Volume up button released			
30:37.5	Volume changed to very high from high using button			
30:38.3	Volume up button pressed			
30:38.6	Volume up button released			
30:41.9	Select button pressed			
30:46.6	Select button released			
30:52.6	Volume up button pressed			
30:52.9	Volume up button released			
30:53.5	Volume up button pressed			
30:53.7	Volume up button released			
30:54.2	Volume up button pressed			
30:57.2	Led brightness mode changed to Off from Dim			
30:57.2	Front led disabled using button			
30:57.3	Top led disabled using button			
30:57.7	Volume up button released			
31:22.6	Volume up button pressed			
31:22.9	Volume up button released			
31:25.9	Volume up button pressed			
31:29.0	Led brightness mode changed to On from Off			
31:29.0	Front led brightness changed to 30% from 1% using button			
31:29.0	Front led enabled using button			
31:29.0	Top led brightness changed to 15% from 1% using button			
31:29.0	Top led enabled using button			
31:30.0	Volume up button released			
31:33.8	Volume down button pressed			
31:34.2	Volume down button released			
31:34.2	Volume changed to high from very high using button			
31:35.7	Volume up button pressed			
31:35.9	Volume up button released			
31:36.0	Volume changed to very high from high using button			
31:56.7	Power button pressed			
31:59.8	Device powered off using button	53	0	55.719
32:00.3	Power button released			
39:10.0	Device powered on due to charger connection	53	0	55.718
39:10.0	Device connected to charger			
39:10.1	Camera connected to Axon Dock X630020W7	54	0	55.718
39:10.1	Audit log rolled			
39:10.1	Audit log created		1.12.23	
39:11.0	Camera connected to Axon Dock X630020W7	54	0	55.718
39:12.9	Audit log created	53	0 1.12.23	55.718
39:12.9	Audit log rolled	53	0	55.718
39:12.0	Audit log created	81	0 1.12.23	55.717
39:12.0	Audit log created	100	0 1.12.23	55.716
39:12.0	Audit log created	100	0 1.12.23	55.716
39:12.0	Audit log created	100	0 1.12.23	55.715

39:12.0 Audit log created	100	0 1.12.23	55.715
39:12.0 Audit log created	100	0 1.12.23	55.714
39:12.0 Audit log created	100	0 1.12.23	55.714
39:12.0 Audit log created	100	0 1.12.23	55.713
39:12.0 Audit log created	100	0 1.12.23	55.713
39:12.0 Audit log created	100	0 1.12.23	55.712
08:06.0 Device disconnected from charger	100	0	55.712
08:06.2 Camera disconnected from Axon Dock X630020W7	100	0	55.712
08:06.3 Audio recording enabled due to video buffering default			
08:23.3 Power button pressed			
08:26.3 Device powered off using button	100	0	55.716
08:26.8 Power button released			
58:46.0 Audit log created		1.12.23	
58:46.1 Device powered on using button	100	0	55.715
58:47.7 Power button released			
58:48.0 Audio recording enabled due to video buffering default			
58:49.4 Power button pressed			
58:50.0 Power button released			
58:46.0 Audit log created	92	0 1.12.23	55.714
58:46.0 Audit log created	85	0 1.12.23	55.713
58:46.0 Audit log created	79	0 1.12.23	55.712
58:46.0 Audit log created	73	0 1.12.23	55.711
58:46.0 Audit log created	65	0 1.12.23	55.71
58:46.1 Audit log created	59	0 1.12.23	55.708
58:46.1 Audit log created	52	0 1.12.23	55.707
58:46.1 Audit log created	45	0 1.12.23	55.706
58:46.1 Audit log created	38	0 1.12.23	55.705
58:46.1 Audit log created	32	0 1.12.23	55.704
14:29.7 Volume up button pressed			
14:29.9 Volume up button released			
14:29.9 Volume up button pressed			
14:30.0 Volume up button released			
14:40.4 Power button pressed			
14:43.1 Power button released			
14:44.7 Power button pressed			
14:47.7 Device powered off using button	30	0	55.703
14:48.2 Power button released			
14:59.0 Audit log rolled	30	0	55.703
14:59.0 Audit log created	30	0 1.12.23	55.703
15:00.1 Device connected to charger	30	0	55.703
15:47.1 Device connected to charger			
15:47.1 Device powered on due to charger connection	30	0	55.703
15:47.2 Camera connected to Axon Dock X630020W7	31	0	55.703
15:47.2 Audit log created		1.12.23	
15:47.2 Audit log rolled			
15:48.1 Camera connected to Axon Dock X630020W7	31	0	55.702
15:50.0 Audit log created	30	0 1.12.23	55.703

15:50.0 Audit log rolled	30	0	55.703
15:50.0 Audit log created	57	0 1.12.23	55.702
15:50.0 Audit log created	83	0 1.12.23	55.701
15:50.0 Audit log created	100	0 1.12.23	55.7
15:50.0 Audit log created	100	0 1.12.23	55.7
15:50.0 Audit log created	100	0 1.12.23	55.699
15:50.0 Audit log created	100	0 1.12.23	55.699
15:50.1 Audit log created	100	0 1.12.23	55.698
15:50.1 Audit log created	100	0 1.12.23	55.698
15:50.1 Audit log created	100	0 1.12.23	55.697
15:50.1 Audit log created	100	0 1.12.23	55.697
15:50.1 Audit log created	100	0 1.12.23	55.696
15:50.1 Audit log created	100	0 1.12.23	55.696
15:50.1 Audit log created	100	0 1.12.23	55.695
28:35.8 Camera disconnected from Axon Dock X630020W7	100	0	55.695
28:35.9 Audio recording enabled due to video buffering default			
28:36.1 Device disconnected from charger	100	0	55.702
15:50.1 Audit log created	94	0 1.12.23	55.701
15:50.1 Audit log created	88	0 1.12.23	55.7
15:50.1 Audit log created	82	0 1.12.23	55.699
05:49.3 Recording started due to TASER activation	76	0	55.698 c06d264e1b0d4171b50e542d7fa6d6d9
05:54.0 Event button pressed			
05:57.0 Recording stopped due to button press	76	1	55.684 c06d264e1b0d4171b50e542d7fa6d6d9
05:57.6 Event button released			
15:50.1 Audit log created	75	1 1.12.23	55.631
15:50.1 Audit log created	69	1 1.12.23	55.63
15:50.1 Audit log created	63	1 1.12.23	55.629
15:50.2 Audit log created	56	1 1.12.23	55.628
15:50.2 Audit log created	49	1 1.12.23	55.626
15:50.2 Audit log created	42	1 1.12.23	55.625
15:50.2 Audit log created	36	1 1.12.23	55.624
15:50.2 Audit log created	30	1 1.12.23	55.623
16:24.7 Power button pressed			
16:27.8 Device powered off using button	30	1	55.623
16:28.2 Power button released			
16:29.2 Volume up button pressed			
16:29.6 Volume up button released			
16:29.6 Volume up button pressed			
16:29.7 Volume up button released			
16:34.7 Audit log created	30	1 1.12.23	55.624
16:34.7 Audit log rolled	30	1	55.624
16:35.1 Device connected to charger	30	1	55.624
17:18.0 Device connected to charger			
17:18.0 Device powered on due to charger connection	32	1	55.624
17:18.0 Camera connected to Axon Dock X630020W7	32	1	55.624
17:18.0 Audit log created		1.12.23	
17:18.0 Audit log rolled			

17:18.9 Camera connected to Axon Dock X630020W7	32	1	55.624
17:20.8 Audit log created	32	1 1.12.23	55.624
17:20.8 Audit log rolled	32	1	55.624
17:20.0 Audit log created	57	1 1.12.23	55.624
17:20.0 Audit log created	83	1 1.12.23	55.623
17:20.0 Audit log created	100	1 1.12.23	55.623
17:20.0 Audit log created	100	1 1.12.23	55.622
17:20.0 Audit log created	100	1 1.12.23	55.622
17:20.1 Audit log created	100	1 1.12.23	55.622
17:20.1 Audit log created	100	1 1.12.23	55.622
17:20.1 Audit log created	100	1 1.12.23	55.622
17:20.1 Audit log created	100	1 1.12.23	55.621
17:20.1 Audit log created	100	1 1.12.23	55.621
17:20.1 Audit log created	100	1 1.12.23	55.621
17:20.1 Audit log created	100	1 1.12.23	55.621
17:20.1 Audit log created	100	1 1.12.23	55.621
17:20.1 Audit log created	100	1 1.12.23	55.62
53:08.0 Device disconnected from charger	100	1	55.62
53:08.2 Camera disconnected from Axon Dock X630020W7	100	1	55.62
53:08.3 Audio recording enabled due to video buffering default			
53:19.1 Programmable button pressed			
53:19.2 Programmable button released			
17:20.1 Audit log created	97	1 1.12.23	55.626
17:20.1 Audit log created	90	1 1.12.23	55.625
17:20.1 Audit log created	84	1 1.12.23	55.624
17:20.1 Audit log created	78	1 1.12.23	55.623
17:20.1 Audit log created	72	1 1.12.23	55.622
17:20.2 Audit log created	65	1 1.12.23	55.621
17:20.2 Audit log created	59	1 1.12.23	55.62
17:20.2 Audit log created	52	1 1.12.23	55.619
17:20.2 Audit log created	45	1 1.12.23	55.617
17:20.2 Audit log created	39	1 1.12.23	55.616
17:20.2 Audit log created	33	1 1.12.23	55.615
18:43.9 Power button pressed			
18:44.2 Power button released			
18:44.4 Camera connected to Axon Dock X630020W7	33	1	55.615
18:44.4 Audit log created	33	1 1.12.23	55.615
18:44.4 Audit log rolled	33	1	55.615
18:45.0 Device connected to charger	33	1	55.615
18:44.0 Audit log created	59	1 1.12.23	55.615
18:44.0 Audit log created	85	1 1.12.23	55.614
18:44.0 Audit log created	100	1 1.12.23	55.614
18:44.0 Audit log created	100	1 1.12.23	55.613
18:44.0 Audit log created	100	1 1.12.23	55.614
18:44.1 Audit log created	100	1 1.12.23	55.614
18:44.1 Audit log created	100	1 1.12.23	55.614
18:44.1 Audit log created	100	1 1.12.23	55.614
51:39.5 Camera disconnected from Axon Dock X630020W7	98	1	55.613

51:40.0 Device disconnected from charger	100	1	55.62
18:44.1 Audit log created	96	1 1.12.23	55.619
18:44.1 Audit log created	90	1 1.12.23	55.618
18:44.1 Audit log created	84	1 1.12.23	55.617
18:44.1 Audit log created	77	1 1.12.23	55.616
18:44.1 Audit log created	71	1 1.12.23	55.615
26:50.8 Event button pressed			
26:51.0 Event button released			
26:51.3 Event button pressed			
26:51.5 Event button released			
26:51.6 Recording started due to button press	70	2	55.614 f9f85ca0321749dfb067d958dc61a3c3
41:20.9 Event button pressed			
41:21.1 Event button released			
41:21.3 Event button pressed			
41:21.5 Event button released			
41:21.6 Event button pressed			
41:21.8 Event button released			
41:22.7 Event button pressed			
41:25.7 Recording stopped due to button press	67	2	55.095 f9f85ca0321749dfb067d958dc61a3c3
41:26.2 Event button released			
18:44.1 Audit log created	63	2 1.12.23	55.092
18:44.1 Audit log created	57	2 1.12.23	55.091
18:44.2 Audit log created	49	2 1.12.23	55.09
18:44.2 Audit log created	42	2 1.12.23	55.089
18:44.2 Audit log created	36	2 1.12.23	55.088
05:30.1 Volume up button pressed			
05:30.3 Volume up button released			
06:14.8 Camera connected to Axon Dock X630020W7	32	2	55.087
06:14.8 Audit log rolled	32	2	55.087
06:14.8 Audit log created	32	2 1.12.23	55.087
06:15.0 Device connected to charger	32	2	55.087
06:14.0 Audit log created	58	2 1.12.23	55.086
06:14.0 Audit log created	84	2 1.12.23	55.085
06:14.0 Audit log created	100	2 1.12.23	55.084
06:14.0 Audit log created	100	2 1.12.23	55.086
06:14.0 Audit log created	100	2 1.12.23	55.086
06:14.1 Audit log created	100	2 1.12.23	55.086
06:14.1 Audit log created	100	2 1.12.23	55.086
06:14.1 Audit log created	100	2 1.12.23	55.086
06:14.1 Audit log created	100	2 1.12.23	55.085
06:14.1 Audit log created	100	2 1.12.23	55.085
06:14.1 Audit log created	100	2 1.12.23	55.085
06:14.1 Audit log created	100	2 1.12.23	55.085
39:40.0 Device disconnected from charger	98	2	55.084
39:40.2 Camera disconnected from Axon Dock X630020W7	100	2	55.084
39:56.4 Power button pressed			
39:59.4 Device powered off using button	100	2	55.091

39:59.9	Power button released			
51:36.1	Audit log created		1.12.23	
51:36.2	Device powered on using button	100	2	55.09
51:39.2	Audio recording enabled due to video buffering default			
51:36.1	Audit log created	92	2 1.12.23	55.089
51:36.2	Audit log created	85	2 1.12.23	55.088
51:36.2	Audit log created	79	2 1.12.23	55.087
51:36.2	Audit log created	73	2 1.12.23	55.086
49:54.5	Axon application connected to device			
50:56.9	Categories 'Person Stuck in Elevator' added to video metadata using Axon applicator			f9f85ca0321749dfb067d958dc61a3c3
51:36.2	Audit log created	65	2 1.12.23	55.084
55:08.4	Title changed in video metadata from " to 'N5 Family Of 7 On The Elevator' using Axon applicator			f9f85ca0321749dfb067d958dc61a3c3
55:22.6	Categories 'Accidental Recording' added to video metadata using Axon applicator			c06d264e1b0d4171b50e542d7fa6d6d9
55:32.7	Axon application disconnected from device			
51:36.2	Audit log created	59	2 1.12.23	55.083
51:36.2	Audit log created	51	2 1.12.23	55.082
16:19.2	Camera connected to Axon Dock X630020W7	48	2	55.082
16:19.3	Audit log created	48	2 1.12.23	55.082
16:19.3	Audit log rolled	48	2	55.082
16:20.2	Device connected to charger	48	2	55.082
16:19.0	Audit log created	76	2 1.12.23	55.081
16:19.0	Audit log created	98	2 1.12.23	55.083
16:19.0	Audit log created	100	2 1.12.23	55.083
16:19.0	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.082
16:19.1	Audit log created	100	2 1.12.23	55.081
16:19.1	Audit log created	100	2 1.12.23	55.081
16:19.1	Audit log created	100	2 1.12.23	55.081
16:19.1	Audit log created	100	2 1.12.23	55.081
31:50.2	Camera disconnected from Axon Dock X630020W7	100	2	55.086
31:50.2	Device disconnected from charger	100	2	55.086
31:50.3	Audio recording disabled due to video buffering default			
16:19.1	Audit log created	94	2 1.12.23	55.085
16:19.2	Audit log created	88	2 1.12.23	55.083
16:19.2	Audit log created	82	2 1.12.23	55.082
16:19.2	Audit log created	75	2 1.12.23	55.081
16:19.2	Audit log created	69	2 1.12.23	55.08
16:19.2	Audit log created	62	2 1.12.23	55.079
16:19.2	Audit log created	56	2 1.12.23	55.078
16:19.2	Audit log created	48	2 1.12.23	55.077
16:19.2	Audit log created	42	2 1.12.23	55.076
16:19.3	Audit log created	35	2 1.12.23	55.075
16:19.3	Audit log created	30	2 1.12.23	55.073
55:13.9	Power button pressed			

55:14.1	Power button released			
55:14.4	Camera connected to Axon Dock X630020W7	27	2	55.073
55:14.4	Audit log rolled	27	2	55.073
55:14.4	Audit log created	27	2 1.12.23	55.073
55:15.2	Device connected to charger	27	2	55.073
55:14.0	Audit log created	53	2 1.12.23	55.072
55:14.0	Audit log created	78	2 1.12.23	55.072
55:14.0	Audit log created	99	2 1.12.23	55.071
55:14.0	Audit log created	100	2 1.12.23	55.071
55:14.1	Audit log created	100	2 1.12.23	55.073
55:14.1	Audit log created	100	2 1.12.23	55.073
55:14.1	Audit log created	100	2 1.12.23	55.073
55:14.1	Audit log created	100	2 1.12.23	55.073
55:14.1	Audit log created	100	2 1.12.23	55.073
55:14.1	Audit log created	100	2 1.12.23	55.072
55:14.1	Audit log created	100	2 1.12.23	55.072
55:14.1	Audit log created	100	2 1.12.23	55.072
55:14.1	Audit log created	100	2 1.12.23	55.072
55:14.2	Audit log created	100	2 1.12.23	55.072
55:14.2	Audit log created	100	2 1.12.23	55.071
57:28.7	Volume down button pressed			
57:28.8	Volume down button released			
57:30.2	Device disconnected from charger	98	2	55.071
57:30.3	Camera disconnected from Axon Dock X630020W7	98	2	55.071
55:14.2	Audit log created	93	2 1.12.23	55.077
55:14.2	Audit log created	86	2 1.12.23	55.076
55:14.2	Audit log created	80	2 1.12.23	55.075
55:14.2	Audit log created	74	2 1.12.23	55.074
55:14.2	Audit log created	68	2 1.12.23	55.073
55:14.3	Audit log created	62	2 1.12.23	55.072
55:14.3	Audit log created	54	2 1.12.23	55.071
55:14.3	Audit log created	47	2 1.12.23	55.07
55:14.3	Audit log created	41	2 1.12.23	55.069
55:14.3	Audit log created	35	2 1.12.23	55.067
55:14.3	Audit log created	29	2 1.12.23	55.066
04:17.9	Volume up button pressed			
04:20.1	Volume up button released			
04:20.1	Select button pressed			
04:20.2	Select button released			
04:23.6	Power button pressed			
04:23.9	Power button released			
04:24.2	Camera connected to Axon Dock X630020W7	29	2	55.066
04:24.2	Audit log created	29	2 1.12.23	55.066
04:24.2	Audit log rolled	29	2	55.066
04:25.2	Device connected to charger	29	2	55.066
04:24.0	Audit log created	54	2 1.12.23	55.066
04:24.0	Audit log created	80	2 1.12.23	55.065
04:24.0	Audit log created	100	2 1.12.23	55.064

04:24.1 Audit log created	100	2 1.12.23	55.064
04:24.1 Audit log created	100	2 1.12.23	55.066
04:24.1 Audit log created	100	2 1.12.23	55.066
04:24.1 Audit log created	100	2 1.12.23	55.066
04:24.1 Audit log created	100	2 1.12.23	55.066
04:24.1 Audit log created	100	2 1.12.23	55.066
04:24.1 Audit log created	100	2 1.12.23	55.065
04:24.1 Audit log created	100	2 1.12.23	55.065
19:25.9 Camera disconnected from Axon Dock X630020W7	100	2	55.065
19:26.2 Device disconnected from charger	100	2	55.072
04:24.2 Audit log created	94	2 1.12.23	55.071
04:24.2 Audit log created	87	2 1.12.23	55.07
04:24.2 Audit log created	82	2 1.12.23	55.069
04:24.2 Audit log created	75	2 1.12.23	55.068
04:24.2 Audit log created	69	2 1.12.23	55.067
04:24.2 Audit log created	62	2 1.12.23	55.066
04:24.3 Audit log created	55	2 1.12.23	55.065
04:24.3 Audit log created	48	2 1.12.23	55.063
04:24.3 Audit log created	41	2 1.12.23	55.062
04:24.3 Audit log created	35	2 1.12.23	55.061
04:24.3 Audit log created	30	2 1.12.23	55.06
04:24.3 Audit log created	24	2 1.12.23	55.059
04:24.4 Audit log created	18	2 1.12.23	55.058
04:24.4 Audit log created	10	2 1.12.23	55.057
12:48.7 Volume up button pressed			
12:49.2 Volume up button released			
13:01.3 Power button pressed			
13:01.5 Power button released			
13:01.8 Camera connected to Axon Dock X630020W7	9	2	55.056
13:01.9 Audit log created	9	2 1.12.23	55.057
13:01.9 Audit log rolled	9	2	55.056
13:02.2 Device connected to charger	9	2	55.057
13:01.0 Audit log created	36	2 1.12.23	55.058
13:01.0 Audit log created	62	2 1.12.23	55.058
13:01.0 Audit log created	87	2 1.12.23	55.058
13:01.0 Audit log created	100	2 1.12.23	55.057
13:01.1 Audit log created	100	2 1.12.23	55.057
13:01.1 Audit log created	100	2 1.12.23	55.057
13:01.1 Audit log created	100	2 1.12.23	55.057
13:01.1 Audit log created	100	2 1.12.23	55.057
13:01.1 Audit log created	100	2 1.12.23	55.056
13:01.1 Audit log created	100	2 1.12.23	55.056
21:02.2 Camera disconnected from Axon Dock X630020W7	100	2	55.056
21:02.2 Device disconnected from charger	100	2	55.056
13:01.2 Audit log created	93	2 1.12.23	55.063
13:01.2 Audit log created	87	2 1.12.23	55.062
13:01.2 Audit log created	81	2 1.12.23	55.061

13:01.2 Audit log created	75	2 1.12.23	55.06
13:01.2 Audit log created	68	2 1.12.23	55.059
13:01.2 Audit log created	62	2 1.12.23	55.058
13:01.3 Audit log created	55	2 1.12.23	55.057
13:01.3 Audit log created	47	2 1.12.23	55.056
21:49.4 Event button pressed			
21:49.6 Event button released			
21:53.7 Event button pressed			
21:53.9 Event button released			
21:54.1 Event button pressed			
21:54.2 Audio recording enabled due to video recording default			
21:54.3 Event button released			
21:54.3 Recording started due to button press	47	2	55.055 6b91e55c69ea474c8619d3b7cbd085ae
25:10.4 Event button pressed			
25:13.4 Recording stopped due to button press	46	3	54.89 6b91e55c69ea474c8619d3b7cbd085ae
25:14.0 Event button released			
25:14.4 Audio recording disabled due to video buffering default			
13:01.3 Audit log created	41	3 1.12.23	54.888
13:01.3 Audit log created	35	3 1.12.23	54.887
25:10.1 Power button pressed			
25:13.1 Device powered off using button	34	3	54.887
25:13.7 Power button released			
47:25.0 Device connected to charger			
47:25.0 Device powered on due to charger connection	34	3	54.886
47:25.0 Camera connected to Axon Dock X630020W7	34	3	54.886
47:25.1 Audit log rolled			
47:25.1 Audit log created		1.12.23	
47:26.0 Camera connected to Axon Dock X630020W7	34	3	54.886
47:27.9 Audit log created	34	3 1.12.23	54.886
47:27.9 Audit log rolled	34	3	54.886
47:27.0 Audit log created	61	3 1.12.23	54.886
47:27.0 Audit log created	87	3 1.12.23	54.885
47:27.0 Audit log created	100	3 1.12.23	54.885
47:27.1 Audit log created	100	3 1.12.23	54.885
47:27.1 Audit log created	100	3 1.12.23	54.886
47:27.1 Audit log created	100	3 1.12.23	54.886
47:27.1 Audit log created	100	3 1.12.23	54.886
47:27.1 Audit log created	100	3 1.12.23	54.885
47:27.1 Audit log created	100	3 1.12.23	54.885
47:27.1 Audit log created	100	3 1.12.23	54.885
47:27.2 Audit log created	100	3 1.12.23	54.885
47:27.2 Audit log created	100	3 1.12.23	54.885
47:27.2 Audit log created	100	3 1.12.23	54.884
47:27.2 Audit log created	100	3 1.12.23	54.884
41:53.0 Device disconnected from charger	98	3	54.884
41:53.4 Camera disconnected from Axon Dock X630020W7	100	3	54.884
41:53.5 Audio recording disabled due to video buffering default			
42:02.6 Volume down button pressed			

42:02.7	Volume down button released			
42:03.3	Volume changed to high from very high using button			
42:11.4	Select button pressed			
42:11.6	Select button released			
42:13.7	Volume up button pressed			
42:14.1	Volume up button released			
42:14.2	Volume changed to very high from high using button			
42:37.7	Volume down button pressed			
42:37.8	Volume down button released			
42:37.9	Volume changed to high from very high using button			
42:40.4	Volume up button pressed			
42:40.9	Volume up button released			
42:41.0	Volume changed to very high from high using button			
42:41.0	Volume up button pressed			
42:41.4	Volume up button released			
42:41.5	Volume up button pressed			
42:41.7	Volume up button released			
42:41.7	Volume up button pressed			
42:41.9	Volume up button released			
47:27.2	Audit log created	99	3 1.12.23	54.89
47:27.2	Audit log created	92	3 1.12.23	54.889
47:27.3	Audit log created	86	3 1.12.23	54.888
47:27.3	Audit log created	80	3 1.12.23	54.887
47:27.3	Audit log created	73	3 1.12.23	54.886
47:27.3	Audit log created	67	3 1.12.23	54.884
17:47.7	Axon application connected to device			
18:12.4	Axon application connected to device			
20:03.4	Categories 'Disorderly Person' added to video metadata using Axon applicator			6b91e55c69ea474c8619d3b7cbd085ae
20:03.4	Title changed in video metadata from '' to 'Disorderly Person At N11 on The Train' using Axon applicator			6b91e55c69ea474c8619d3b7cbd085ae
20:13.5	Axon application disconnected from device			
47:27.4	Audit log created	61	3 1.12.23	54.883
47:27.4	Audit log created	53	3 1.12.23	54.882
47:27.4	Audit log created	46	3 1.12.23	54.881
47:27.4	Audit log created	40	3 1.12.23	54.88
32:31.3	Power button pressed			
32:34.3	Device powered off using button	35	3	54.879
32:34.8	Power button released			
50:20.9	Audit log created		1.12.23	
50:21.0	Device connected to charger			
50:21.0	Device powered on due to charger connection	35	3	54.878
50:21.0	Camera connected to Axon Dock X630020W7	35	3	54.878
50:21.0	Audit log rolled			
50:21.0	Audit log created		1.12.23	
50:22.0	Camera connected to Axon Dock X630020W7	36	3	54.878
50:23.9	Audit log created	35	3 1.12.23	54.879
50:23.9	Audit log rolled	35	3	54.879
50:23.0	Audit log created	62	3 1.12.23	54.878

50:23.0 Audit log created	88	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.1 Audit log created	100	3 1.12.23	54.879
50:23.2 Audit log created	100	3 1.12.23	54.878
50:23.2 Audit log created	100	3 1.12.23	54.878
50:23.2 Audit log created	100	3 1.12.23	54.878
50:23.2 Audit log created	100	3 1.12.23	54.878
50:23.2 Audit log created	100	3 1.12.23	54.877
50:23.2 Audit log created	100	3 1.12.23	54.877
50:23.3 Audit log created	100	3 1.12.23	54.877
50:23.3 Audit log created	100	3 1.12.23	54.877
50:23.3 Audit log created	100	3 1.12.23	54.876
50:23.3 Audit log created	100	3 1.12.23	54.877
55:57.8 Camera disconnected from Axon Dock X630020W7	98	3	54.877
55:57.9 Audio recording disabled due to video buffering default			
55:58.0 Device disconnected from charger	98	3	54.883
56:19.4 Volume up button pressed			
56:19.6 Volume up button released			
56:19.9 Volume up button pressed			
56:20.1 Volume up button released			
56:20.3 Volume up button pressed			
56:20.3 Volume up button released			
56:20.9 Volume up button pressed			
56:21.0 Volume up button released			
56:32.8 Camera connected to Axon Dock X630020W7	100	3	54.885
56:32.8 Audit log created	100	3 1.12.23	54.885
56:32.8 Audit log rolled	100	3	54.885
56:34.0 Device connected to charger	100	3	54.885
56:32.0 Audit log created	100	3 1.12.23	54.885
56:32.0 Audit log created	100	3 1.12.23	54.885
56:32.0 Audit log created	100	3 1.12.23	54.885
56:32.1 Audit log created	100	3 1.12.23	54.884
56:32.1 Audit log created	100	3 1.12.23	54.884
56:32.1 Audit log created	100	3 1.12.23	54.884
56:32.1 Audit log created	100	3 1.12.23	54.884
56:32.1 Audit log created	100	3 1.12.23	54.884
56:32.2 Audit log created	100	3 1.12.23	54.883
56:32.2 Audit log created	100	3 1.12.23	54.883
56:32.2 Audit log created	100	3 1.12.23	54.883
56:32.2 Audit log created	100	3 1.12.23	54.884
56:32.2 Audit log created	100	3 1.12.23	54.886
56:32.3 Audit log created	100	3 1.12.23	54.885
56:32.3 Audit log created	100	3 1.12.23	54.885

56:32.3 Audit log created	100	3 1.12.23	54.885
56:32.3 Audit log created	100	3 1.12.23	54.885
56:32.3 Audit log created	100	3 1.12.23	54.885
56:32.3 Audit log created	100	3 1.12.23	54.885
56:32.4 Audit log created	100	3 1.12.23	54.884
56:32.4 Audit log created	100	3 1.12.23	54.884
56:32.4 Audit log created	100	3 1.12.23	54.884
56:32.4 Audit log created	100	3 1.12.23	54.884
56:32.4 Audit log created	100	3 1.12.23	54.885
56:32.5 Audit log created	100	3 1.12.23	54.886
11:58.4 Camera disconnected from Axon Dock X630020W7	98	3	54.887
11:59.0 Device disconnected from charger	100	3	54.887
56:32.5 Audit log created	94	3 1.12.23	54.886
56:32.5 Audit log created	88	3 1.12.23	54.884
56:32.5 Audit log created	82	3 1.12.23	54.883
56:32.5 Audit log created	76	3 1.12.23	54.882
37:55.2 Volume down button pressed			
37:55.3 Volume down button released			
37:55.4 Volume changed to high from very high using button			
38:25.6 Volume up button pressed			
38:25.8 Volume up button released			
38:25.9 Volume changed to very high from high using button			
42:17.0 Volume down button pressed			
42:20.1 Volume down button released			
42:20.5 Volume down button pressed			
42:20.9 Volume down button released			
42:21.0 Volume changed to high from very high using button			
56:32.6 Audit log created	70	3 1.12.23	54.881
56:32.6 Audit log created	63	3 1.12.23	54.88
56:32.6 Audit log created	56	3 1.12.23	54.879
59:06.7 Select button pressed			
59:07.3 Select button released			
56:32.6 Audit log created	49	3 1.12.23	54.878
56:32.7 Audit log created	42	3 1.12.23	54.876
56:32.7 Audit log created	36	3 1.12.23	54.875
15:24.0 Camera connected to Axon Dock X630020W7	35	3	54.875
15:24.1 Audit log created	34	3 1.12.23	54.875
15:24.1 Audit log rolled	34	3	54.875
15:25.0 Device connected to charger	34	3	54.875
15:24.0 Audit log created	61	3 1.12.23	54.875
15:24.0 Audit log created	87	3 1.12.23	54.874
15:24.1 Audit log created	100	3 1.12.23	54.874
15:24.1 Audit log created	100	3 1.12.23	54.874
15:24.1 Audit log created	100	3 1.12.23	54.873
15:24.1 Audit log created	100	3 1.12.23	54.873
15:24.1 Audit log created	100	3 1.12.23	54.873
15:24.1 Audit log created	100	3 1.12.23	54.873
15:24.2 Audit log created	100	3 1.12.23	54.873

00:53.8	Camera disconnected from Axon Dock X630020W7	99	3	54.872
00:54.0	Device disconnected from charger	99	3	54.879
15:24.2	Audit log created	98	3 1.12.23	54.878
16:56.6	Volume up button pressed			
16:56.8	Volume up button released			
16:56.9	Volume changed to very high from high using button			
15:24.2	Audit log created	91	3 1.12.23	54.877
15:24.2	Audit log created	85	3 1.12.23	54.876
15:24.3	Audit log created	79	3 1.12.23	54.875
15:24.3	Audit log created	73	3 1.12.23	54.874
53:34.9	Volume up button pressed			
53:35.0	Volume up button released			
54:17.9	Volume up button pressed			
54:18.2	Volume up button released			
54:26.6	Volume up button pressed			
54:26.9	Volume up button released			
56:16.0	Power button pressed			
56:19.0	Device powered off using button	68	3	54.873
56:19.5	Power button released			
34:55.9	Audit log created		1.12.23	
34:56.0	Device powered on using button	68	3	54.875
34:57.9	Audio recording disabled due to video buffering default			
34:56.0	Audit log created	61	3 1.12.23	54.874
34:29.6	Volume up button pressed			
34:32.6	Led brightness mode changed to Dim from On			
34:32.7	Front led brightness changed to 1% from 30% using button			
34:32.7	Top led brightness changed to 1% from 15% using button			
34:33.8	Volume up button released			
34:56.0	Audit log created	54	3 1.12.23	54.873
37:59.0	Volume up button pressed			
37:59.3	Volume up button released			
39:17.0	Volume up button pressed			
39:17.7	Volume up button released			
39:18.0	Volume up button pressed			
39:18.2	Volume up button released			
39:24.1	Volume up button pressed			
39:27.1	Led brightness mode changed to Off from Dim			
39:27.1	Front led disabled using button			
39:27.1	Top led disabled using button			
39:28.1	Volume up button released			
39:28.3	Volume up button pressed			
39:28.7	Volume up button released			
14:19.9	Volume up button pressed			
14:20.2	Volume up button released			
34:56.0	Audit log created	46	3 1.12.23	54.872
34:56.0	Audit log created	40	3 1.12.23	54.871
34:56.1	Audit log created	34	3 1.12.23	54.869

18:36.1	Volume up button pressed			
18:36.2	Volume up button released			
18:52.3	Camera connected to Axon Dock X630020W7	30	3	54.869
18:52.4	Audit log rolled	30	3	54.869
18:52.4	Audit log created	30	3 1.12.23	54.869
18:53.0	Device connected to charger	30	3	54.869
18:53.2	Power button pressed			
18:53.4	Power button released			
18:52.0	Audit log created	55	3 1.12.23	54.868
18:52.0	Audit log created	82	3 1.12.23	54.868
18:52.1	Audit log created	100	3 1.12.23	54.868
18:52.1	Audit log created	100	3 1.12.23	54.869
18:52.1	Audit log created	100	3 1.12.23	54.869
18:52.1	Audit log created	100	3 1.12.23	54.869
18:52.1	Audit log created	100	3 1.12.23	54.869
18:52.1	Audit log created	100	3 1.12.23	54.869
18:52.2	Audit log created	100	3 1.12.23	54.869
18:52.2	Audit log created	100	3 1.12.23	54.868
18:52.2	Audit log created	100	3 1.12.23	54.868
18:52.2	Audit log created	100	3 1.12.23	54.868
18:52.2	Audit log created	100	3 1.12.23	54.868
18:52.3	Audit log created	100	3 1.12.23	54.868
13:52.0	Device disconnected from charger	98	3	54.868
13:52.8	Camera disconnected from Axon Dock X630020W7	100	3	54.868
14:32.1	Power button pressed			
14:35.1	Device powered off using button	100	3	54.871
14:35.6	Power button released			
15:43.1	Device powered on using button	100	3	54.87
15:45.0	Audio recording disabled due to video buffering default			
16:08.9	Event button pressed			
16:09.0	Event button released			
16:09.3	Event button pressed			
16:09.4	Audio recording enabled due to video recording default			
16:09.5	Event button released			
16:09.6	Recording started due to button press	100	4	54.87 4a6a30ae669e47c1827621c8efc2114d
16:12.5	Event button pressed			
16:15.5	Recording stopped due to button press	100	4	54.857 4a6a30ae669e47c1827621c8efc2114d
16:16.0	Event button released			
16:16.3	Audio recording disabled due to video buffering default			
18:52.0	Audit log created	99	4 1.12.23	54.855
58:18.2	Volume up button pressed			
58:18.4	Volume up button released			
58:18.6	Volume up button pressed			
58:18.7	Volume up button released			
58:19.0	Volume up button pressed			
58:19.2	Volume up button released			
58:19.6	Volume up button pressed			
58:19.7	Volume up button released			
58:20.0	Volume up button pressed			

58:20.1 Volume up button released
58:20.4 Volume down button pressed
58:20.6 Volume down button released
58:20.7 Volume changed to high from very high using button
58:20.7 Volume down button pressed
58:20.9 Volume down button released
58:21.1 Volume changed to medium from high using button
58:21.9 Select button pressed
58:22.1 Select button released
58:22.2 Select button pressed
58:22.4 Select button released
58:22.9 Select button pressed
58:23.1 Select button released
58:23.6 Select button pressed
58:23.9 Select button released
58:24.1 Select button pressed
58:24.6 Select button released
58:25.1 Volume up button pressed
58:25.4 Volume up button released
58:25.4 Volume changed to high from medium using button
58:25.5 Volume up button pressed
58:25.7 Volume up button released
58:25.7 Volume up button pressed
58:25.9 Volume up button released
58:25.9 Volume changed to very high from high using button
58:25.9 Volume up button pressed
58:26.0 Volume up button released
58:26.1 Volume up button pressed
58:26.2 Volume up button released
59:21.3 Volume down button pressed
59:21.5 Volume down button released
59:21.6 Volume changed to high from very high using button
59:24.4 Programmable button pressed
59:24.6 Programmable button released
59:25.2 Programmable button pressed
59:25.6 Programmable button released
59:33.8 Select button pressed
59:34.0 Select button released
59:34.3 Select button pressed
59:34.6 Select button released
59:41.7 Event button pressed
59:41.9 Event button released
59:42.0 Event button pressed
59:42.0 Audio recording enabled due to video recording default
59:42.1 Event button released
59:42.2 Recording started due to button press
59:45.4 Event button pressed

59:48.4 Recording stopped due to button press	94	5	54.84	d41a9596d0e946689b55ddfc688d2f61
59:48.9 Event button released				
59:49.2 Audio recording disabled due to video buffering default				
00:00.9 Volume up button pressed				
00:01.1 Volume up button released				
00:01.2 Volume changed to very high from high using button				
02:42.6 Axon application connected to device				
06:36.8 Categories 'Accidental Recording' added to video metadata using Axon applicator				4a6a30ae669e47c1827621c8efc2114d
06:36.8 Title changed in video metadata from " " to 'Test Only' using Axon applicator				4a6a30ae669e47c1827621c8efc2114d
07:01.9 Categories 'Accidental Recording' added to video metadata using Axon applicator				d41a9596d0e946689b55ddfc688d2f61
08:11.8 Top led enabled using Axon application				
08:11.8 Front led enabled using Axon application				
08:12.2 Led brightness mode changed to Dim from Off				
08:48.7 Axon application disconnected from device				
18:52.0 Audit log created	92	5 1.12.23	54.789	
18:52.1 Audit log created	85	5 1.12.23	54.788	
18:52.1 Audit log created	79	5 1.12.23	54.787	
18:52.1 Audit log created	73	5 1.12.23	54.786	
24:34.9 Volume up button pressed				
24:35.0 Volume up button released				
24:38.4 Volume up button pressed				
24:38.6 Volume up button released				
18:52.1 Audit log created	66	5 1.12.23	54.785	
40:07.5 Volume up button pressed				
40:07.8 Volume up button released				
18:52.2 Audit log created	60	5 1.12.23	54.783	
18:52.2 Audit log created	52	5 1.12.23	54.782	
36:57.5 Volume up button pressed				
36:59.3 Volume up button released				
18:52.2 Audit log created	45	5 1.12.23	54.781	
18:52.2 Audit log created	39	5 1.12.23	54.78	
05:43.2 Volume up button pressed				
05:43.5 Volume up button released				
13:51.7 Volume up button pressed				
13:51.9 Volume up button released				
18:52.3 Audit log created	33	5 1.12.23	54.779	
18:52.3 Audit log created	27	5 1.12.23	54.778	
18:52.3 Audit log created	22	5 1.12.23	54.777	
36:52.6 Power button pressed				
36:52.8 Power button released				
36:53.2 Camera connected to Axon Dock X630020W7	20	5	54.776	
36:53.3 Audit log created	20	5 1.12.23	54.776	
36:53.3 Audit log rolled	20	5	54.776	
36:54.1 Device connected to charger	20	5	54.776	
36:53.0 Audit log created	46	5 1.12.23	54.776	
36:53.0 Audit log created	71	5 1.12.23	54.775	
36:53.1 Audit log created	96	5 1.12.23	54.775	

36:53.1 Audit log created	100	5 1.12.23	54.774
36:53.1 Audit log created	100	5 1.12.23	54.774
36:53.1 Audit log created	100	5 1.12.23	54.774
36:53.1 Audit log created	100	5 1.12.23	54.773
36:53.2 Audit log created	100	5 1.12.23	54.773
36:53.2 Audit log created	100	5 1.12.23	54.773
36:53.2 Audit log created	100	5 1.12.23	54.773
36:53.2 Audit log created	100	5 1.12.23	54.772
36:53.2 Audit log created	100	5 1.12.23	54.772
36:53.2 Audit log created	100	5 1.12.23	54.772
36:53.3 Audit log created	100	5 1.12.23	54.772
36:53.3 Audit log created	100	5 1.12.23	54.772
36:53.3 Audit log created	100	5 1.12.23	54.772
36:53.3 Audit log created	100	5 1.12.23	54.771
03:13.1 Device disconnected from charger	98	5	54.771
03:13.4 Camera disconnected from Axon Dock X630020W7	98	5	54.771
31:40.7 Select button pressed			
31:40.8 Select button released			
36:53.4 Audit log created	96	5 1.12.23	54.779
13:37.8 Power button pressed			
13:40.8 Device powered off using button	92	5	54.778
13:41.2 Power button released			
25:52.2 Audit log created		1.12.23	
25:52.3 Device powered on using button	92	5	54.777
25:55.4 Audio recording disabled due to video buffering default			
04:52.7 Event button pressed			
04:53.1 Event button released			
05:20.3 Event button pressed			
05:21.4 Event button released			
05:21.7 Event button pressed			
05:21.8 Event button released			
05:21.9 Event button pressed			
05:21.9 Audio recording enabled due to video recording default			
05:22.1 Event button released			
05:22.1 Recording started due to button press	87	6	54.777 fc00e10b148748c989a95fc583fe6017
05:51.1 Event button pressed			
05:53.9 Event button released			
05:56.9 Event button pressed			
05:58.0 Event button released			
05:59.1 Event button pressed			
06:02.1 Recording stopped due to button press	87	6	54.695 fc00e10b148748c989a95fc583fe6017
06:02.6 Event button released			
06:02.8 Audio recording disabled due to video buffering default			
25:52.3 Audit log created	85	6 1.12.23	54.694
29:10.5 Axon application connected to device			
29:46.4 Categories 'Loitering' added to video metadata using Axon applicator			fc00e10b148748c989a95fc583fe6017
30:35.4 Title changed in video metadata from " to 'Sig. 70 Doraville' using Axon applicator			fc00e10b148748c989a95fc583fe6017
31:07.0 Axon application disconnected from device			

25:52.3	Audit log created	79	6 1.12.23	54.693
25:52.3	Audit log created	73	6 1.12.23	54.692
25:52.3	Audit log created	67	6 1.12.23	54.691
08:00.5	Volume up button pressed			
08:00.8	Volume up button released			
09:43.2	Volume up button pressed			
09:43.3	Volume up button released			
14:48.5	Volume up button pressed			
14:48.6	Volume up button released			
14:55.2	Camera connected to Axon Dock X630020W7	62	6	54.69
14:55.3	Audit log rolled	62	6	54.69
14:55.3	Audit log created	62	6 1.12.23	54.69
14:56.3	Device connected to charger	62	6	54.69
14:55.0	Audit log created	89	6 1.12.23	54.689
14:55.0	Audit log created	100	6 1.12.23	54.689
14:55.1	Audit log created	100	6 1.12.23	54.688
14:55.1	Audit log created	100	6 1.12.23	54.688
14:55.1	Audit log created	100	6 1.12.23	54.688
14:55.1	Audit log created	100	6 1.12.23	54.688
14:55.2	Audit log created	100	6 1.12.23	54.688
14:55.2	Audit log created	100	6 1.12.23	54.687
14:55.2	Audit log created	100	6 1.12.23	54.687
45:52.3	Device disconnected from charger	98	6	54.687
45:52.5	Camera disconnected from Axon Dock X630020W7	100	6	54.687
14:55.2	Audit log created	96	6 1.12.23	54.689
15:28.0	Volume up button pressed			
15:28.3	Volume up button released			
31:14.6	Power button pressed			
31:17.6	Device powered off using button	94	6	54.689
31:18.0	Power button released			
58:34.9	Audit log created		1.12.23	
58:35.0	Device powered on due to charger connection	94	6	54.688
58:35.0	Device connected to charger			
58:35.0	Camera connected to Axon Dock X630020W7	94	6	54.688
58:35.1	Audit log created		1.12.23	
58:35.1	Audit log rolled			
58:36.0	Camera connected to Axon Dock X630020W7	95	6	54.688
58:37.9	Audit log rolled	94	6	54.688
58:37.9	Audit log created	94	6 1.12.23	54.688
58:37.0	Audit log created	100	6 1.12.23	54.688
58:37.0	Audit log created	100	6 1.12.23	54.688
58:37.1	Audit log created	100	6 1.12.23	54.687
58:37.1	Audit log created	100	6 1.12.23	54.687
58:37.1	Audit log created	100	6 1.12.23	54.687
58:37.1	Audit log created	100	6 1.12.23	54.687
58:37.2	Audit log created	100	6 1.12.23	54.689
29:57.8	Select button pressed			

29:57.9	Camera disconnected from Axon Dock X630020W7	99	6	54.689
29:58.0	Device disconnected from charger	99	6	54.689
29:58.0	Select button released			
29:58.1	Audio recording disabled due to video buffering default			
57:00.3	Volume up button pressed			
57:03.3	Led brightness mode changed to Off from Dim			
57:03.3	Front led disabled using button			
57:03.3	Top led disabled using button			
57:05.6	Volume up button released			
57:27.3	Power button pressed			
57:30.3	Device powered off using button	96	6	54.689
57:30.7	Power button released			
44:37.0	Audit log created		1.12.23	
44:37.0	Device powered on using button	96	6	54.688
44:39.0	Audio recording disabled due to video buffering default			
53:34.3	Power button pressed			
53:37.3	Device powered off using button	95	6	54.688
53:37.7	Power button released			
57:32.0	Audit log created		1.12.23	
57:32.1	Camera connected to Axon Dock X630020W7	95	6	54.688
57:32.1	Device powered on due to charger connection	95	6	54.688
57:33.1	Camera connected to Axon Dock X630020W7	96	6	54.688
57:35.0	Audit log rolled	95	6	54.688
57:35.0	Audit log created	95	6 1.12.23	54.688
57:34.0	Audit log created	100	6 1.12.23	54.688
57:34.0	Audit log created	100	6 1.12.23	54.687
57:34.1	Audit log created	100	6 1.12.23	54.687
57:34.1	Audit log created	100	6 1.12.23	54.687
57:34.1	Audit log created	100	6 1.12.23	54.687
57:34.1	Audit log created	100	6 1.12.23	54.688
57:34.2	Audit log created	100	6 1.12.23	54.689
57:34.2	Audit log created	100	6 1.12.23	54.689
57:34.2	Audit log created	100	6 1.12.23	54.689
57:34.2	Audit log created	100	6 1.12.23	54.689
57:34.3	Audit log created	100	6 1.12.23	54.689
57:34.3	Audit log created	100	6 1.12.23	54.688
57:34.3	Audit log created	100	6 1.12.23	54.688
57:34.3	Audit log created	100	6 1.12.23	54.688
57:34.4	Audit log created	100	6 1.12.23	54.688
57:34.4	Audit log created	100	6 1.12.23	54.687
57:34.4	Audit log created	100	6 1.12.23	54.687
57:34.4	Audit log created	100	6 1.12.23	54.687
57:34.4	Audit log created	100	6 1.12.23	54.687
57:34.4	Audit log created	100	6 1.12.23	54.687
57:34.5	Audit log created	100	6 1.12.23	54.687
57:34.5	Audit log created	100	6 1.12.23	54.688
57:34.5	Audit log created	100	6 1.12.23	54.69
57:34.5	Audit log created	100	6 1.12.23	54.689

57:34.6	Audit log created	100	6 1.12.23	54.689
57:34.6	Audit log created	100	6 1.12.23	54.689
57:34.6	Audit log created	100	6 1.12.23	54.689
57:34.6	Audit log created	100	6 1.12.23	54.689
57:34.7	Audit log created	100	6 1.12.23	54.688
57:34.7	Audit log created	100	6 1.12.23	54.688
57:34.7	Audit log created	100	6 1.12.23	54.688
57:34.8	Audit log created	100	6 1.12.23	54.688
57:34.8	Audit log created	100	6 1.12.23	54.688
40:41.1	Device disconnected from charger	100	6	54.687
40:41.7	Camera disconnected from Axon Dock X630020W7	100	6	54.687
40:41.8	Audio recording disabled due to video buffering default			
40:44.7	Camera connected to Axon Dock X630020W7	100	6	54.688
40:44.7	Audit log rolled	100	6	54.688
40:44.7	Audit log created	100	6 1.12.23	54.688
40:45.1	Device connected to charger	100	6	54.688
40:44.0	Audit log created	100	6 1.12.23	54.687
40:44.1	Audit log created	100	6 1.12.23	54.687
40:44.1	Audit log created	100	6 1.12.23	54.687
40:44.1	Audit log created	100	6 1.12.23	54.687
40:44.1	Audit log created	100	6 1.12.23	54.686
40:44.2	Audit log created	100	6 1.12.23	54.688
40:44.2	Audit log created	100	6 1.12.23	54.688
40:44.2	Audit log created	100	6 1.12.23	54.688
40:44.2	Audit log created	100	6 1.12.23	54.688
40:44.2	Audit log created	100	6 1.12.23	54.688
40:44.3	Audit log created	100	6 1.12.23	54.688
40:44.3	Audit log created	100	6 1.12.23	54.687
40:44.3	Audit log created	100	6 1.12.23	54.687
40:44.4	Audit log created	100	6 1.12.23	54.687
40:44.4	Audit log created	100	6 1.12.23	54.687
40:44.4	Audit log created	100	6 1.12.23	54.686
40:44.4	Audit log created	100	6 1.12.23	54.687
45:21.8	Camera disconnected from Axon Dock X630020W7	99	6	54.687
45:22.1	Device disconnected from charger	99	6	54.687
45:53.4	Volume up button pressed			
45:53.9	Volume up button released			
45:54.5	Volume up button pressed			
45:54.8	Volume up button released			
45:55.2	Volume up button pressed			
45:55.3	Volume up button released			
45:59.9	Volume down button pressed			
46:00.3	Volume down button released			
46:00.4	Volume changed to high from very high using button			
46:03.8	Volume up button pressed			
46:04.0	Volume up button released			
46:04.1	Volume changed to very high from high using button			
46:04.8	Volume up button pressed			

46:05.1	Volume up button released			
46:05.7	Volume up button pressed			
46:06.1	Volume up button released			
46:07.1	Volume up button pressed			
46:07.3	Volume up button released			
46:08.4	Select button pressed			
46:08.9	Select button released			
46:10.5	Select button pressed			
46:10.6	Select button released			
46:11.2	Select button pressed			
46:14.1	Select button released			
46:14.3	Select button pressed			
46:14.5	Select button released			
46:20.2	Volume up button pressed			
46:20.3	Volume up button released			
46:27.5	Select button pressed			
46:29.9	Select button released			
46:30.3	Select button pressed			
46:30.7	Select button released			
46:34.3	Programmable button pressed			
46:34.9	Programmable button released			
46:35.5	Programmable button pressed			
46:36.8	Programmable button released			
46:39.0	Programmable button pressed			
46:40.2	Programmable button released			
46:43.9	Select button pressed			
46:44.1	Select button released			
46:44.5	Select button pressed			
46:44.7	Select button released			
46:45.8	Programmable button pressed			
46:46.5	Programmable button released			
46:47.4	Volume up button pressed			
46:47.7	Volume up button released			
46:47.8	Volume up button pressed			
46:48.0	Volume up button released			
46:48.3	Volume up button pressed			
46:48.5	Volume up button released			
46:49.0	Programmable button pressed			
46:49.3	Programmable button released			
46:49.7	Programmable button pressed			
46:50.0	Programmable button released			
46:51.2	Volume up button pressed			
46:51.4	Volume up button released			
47:04.2	Power button pressed			
47:07.2	Device powered off using button	100	6	54.686
47:07.6	Power button released			
47:54.1	Device powered on using button	100	6	54.686

47:56.0	Audio recording disabled due to video buffering default			
40:44.0	Audit log created	93	6 1.12.23	54.684
07:53.8	Volume up button pressed			
07:54.4	Volume up button released			
37:05.2	Axon application connected to device			
38:40.0	Camera connected to Axon Dock X62001W9H	86	6	54.728
38:40.0	Axon application disconnected from device			
38:40.1	Audit log rolled	86	6	54.683
38:40.1	Audit log created	86	6 1.12.23	54.683
38:41.1	Device connected to charger	86	6	54.683
39:05.3	Video upload started when camera was docked			c06d264e1b0d4171b50e542d7fa6d6d9
39:14.0	Date/Time synced to 05/04/2021 09:39:14.01 PM from 05/04/2021 09:39:10.03 PM			
39:21.5	Audit log successfully uploaded			
39:21.5	Audit log successfully uploaded			
39:21.5	Audit log successfully uploaded			
39:21.5	Audit log successfully uploaded			
39:21.5	Audit log successfully uploaded			
39:21.7	Audit log successfully uploaded and deleted from device	87	6	54.795
39:21.7	Audit log successfully uploaded and deleted from device	87	6	54.795
39:21.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:21.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:21.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:21.9	Audit log successfully uploaded			
39:21.9	Audit log successfully uploaded			
39:21.9	Audit log successfully uploaded			
39:21.9	Audit log successfully uploaded			
39:22.0	Audit log successfully uploaded			
39:22.1	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.1	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.1	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.2	Audit log successfully uploaded			
39:22.2	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.3	Audit log successfully uploaded			
39:22.3	Audit log successfully uploaded			
39:22.3	Audit log successfully uploaded			
39:22.4	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.5	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.5	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.6	Audit log successfully uploaded			
39:22.6	Audit log successfully uploaded			
39:22.6	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.6	Audit log successfully uploaded			
39:22.7	Audit log successfully uploaded			
39:22.7	Audit log successfully uploaded			
39:22.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:22.8	Audit log successfully uploaded and deleted from device	87	6	54.795

39:27.5	Audit log successfully uploaded			
39:27.5	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.6	Audit log successfully uploaded			
39:27.6	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.6	Audit log successfully uploaded			
39:27.7	Audit log successfully uploaded			
39:27.7	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.7	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.7	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.8	Audit log successfully uploaded			
39:27.8	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.8	Audit log successfully uploaded			
39:27.9	Audit log successfully uploaded			
39:27.9	Audit log successfully uploaded and deleted from device	87	6	54.795
39:27.9	Audit log successfully uploaded			
39:28.0	Audit log successfully uploaded and deleted from device	87	6	54.795
39:28.0	Audit log successfully uploaded			
39:28.0	Video successfully uploaded from device when docked			c06d264e1b0d4171b50e542d7fa6d6d9
39:28.0	Audit log successfully uploaded and deleted from device	87	6	54.795
39:28.1	Audit log successfully uploaded and deleted from device	87	6	54.795
39:28.1	Audit log successfully uploaded			
39:28.1	Audit log successfully uploaded and deleted from device	87	6	54.795
39:28.2	Audit log successfully uploaded			
39:28.2	Audit log successfully uploaded and deleted from device	87	6	54.795
39:28.2	Audit log successfully uploaded			
39:28.3	Audit log successfully uploaded			
39:28.3	Video deleted from device when docked	87	5	54.861 c06d264e1b0d4171b50e542d7fa6d6d9
39:28.3	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.4	Audit log successfully uploaded			
39:28.4	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.5	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.5	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.5	Video upload started when camera was docked			f9f85ca0321749dfb067d958dc61a3c3
39:28.5	Audit log successfully uploaded			
39:28.5	Audit log successfully uploaded			
39:28.6	Audit log successfully uploaded			
39:28.6	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.6	Audit log successfully uploaded			
39:28.7	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.7	Audit log successfully uploaded			
39:28.7	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.8	Audit log successfully uploaded			
39:28.8	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.8	Audit log successfully uploaded and deleted from device	87	5	54.862
39:28.9	Audit log successfully uploaded and deleted from device	87	5	54.862
39:29.0	Audit log successfully uploaded			
39:29.0	Audit log successfully uploaded			

39:51.9	Audit log successfully uploaded			
39:51.9	Audit log successfully uploaded			
39:52.0	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.0	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.0	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.0	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.1	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.1	Audit log successfully uploaded			
39:52.1	Audit log successfully uploaded			
39:52.1	Audit log successfully uploaded			
39:52.2	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.2	Audit log successfully uploaded and deleted from device	87	5	54.861
39:52.3	Audit log successfully uploaded and deleted from device	87	5	54.861
41:49.2	Video successfully uploaded from device when docked			f9f85ca0321749dfb067d958dc61a3c3
41:49.5	Video deleted from device when docked	87	4	55.391 f9f85ca0321749dfb067d958dc61a3c3
41:49.7	Video upload started when camera was docked			6b91e55c69ea474c8619d3b7cbd085ae
42:36.1	Video successfully uploaded from device when docked			6b91e55c69ea474c8619d3b7cbd085ae
42:36.4	Video deleted from device when docked	88	3	55.556 6b91e55c69ea474c8619d3b7cbd085ae
42:36.6	Video upload started when camera was docked			4a6a30ae669e47c1827621c8efc2114d
42:42.0	Video successfully uploaded from device when docked			4a6a30ae669e47c1827621c8efc2114d
42:42.2	Video deleted from device when docked	88	2	55.571 4a6a30ae669e47c1827621c8efc2114d
42:42.4	Video upload started when camera was docked			d41a9596d0e946689b55ddfc688d2f61
43:03.5	Video successfully uploaded from device when docked			d41a9596d0e946689b55ddfc688d2f61
43:03.7	Video deleted from device when docked	88	1	55.635 d41a9596d0e946689b55ddfc688d2f61
43:04.0	Video upload started when camera was docked			fc00e10b148748c989a95fc583fe6017
43:27.7	Video successfully uploaded from device when docked			fc00e10b148748c989a95fc583fe6017
43:28.0	Video deleted from device when docked	88	0	55.717 fc00e10b148748c989a95fc583fe6017
43:28.0	Audit log rolled	88	0	55.717
43:28.0	Audit log created	88	0	1.12.23 55.717
55:20.8	Device disconnected from charger	93	0	55.717
55:20.9	Camera disconnected from Axon Dock X62001W9H	93	0	55.717
56:03.1	Axon application connected to device			
56:36.1	Vibration disabled using Axon application			
56:38.5	Vibration enabled using Axon application			
57:42.8	Top led enabled using Axon application			
57:42.9	Front led enabled using Axon application			
57:43.2	Led brightness mode changed to Dim from Off			
58:05.1	Top led disabled using Axon application			
58:05.1	Front led disabled using Axon application			
58:05.5	Led brightness mode changed to Off from Dim			
58:35.9	Top led enabled using Axon application			
58:36.0	Front led enabled using Axon application			
58:36.3	Led brightness mode changed to Dim from Off			
58:37.3	Top led auto brightness enabled using Axon application			
58:37.3	Front led auto brightness enabled using Axon application			
58:37.7	Led brightness mode changed to Auto from Dim			
58:41.9	Top led auto brightness disabled using Axon application			

58:42.0	Front led auto brightness disabled using Axon applicator				
58:42.3	Led brightness mode changed to Dim from Auto				
59:36.1	Axon application disconnected from device				
10:55.7	Power button pressed				
10:58.7	Device powered off using button	92	0	55.719	
10:59.2	Power button released				
16:05.2	Audit log created				1.12.23
16:05.3	Device powered on using button	91	0	55.719	
16:08.3	Audio recording disabled due to video buffering default				
52:15.8	Event button pressed				
52:16.5	Event button released				
52:16.7	Event button pressed				
52:16.8	Event button released				
52:16.9	Event button pressed				
52:16.9	Audio recording enabled due to video recording default				
52:17.1	Event button released				
52:17.1	Recording started due to button press	87	1	55.718	a219ee423280450f9e7aff22300ebd9e
56:59.0	Event button pressed				
57:02.0	Recording stopped due to button press	86	1	55.507	a219ee423280450f9e7aff22300ebd9e
57:02.4	Event button released				
57:02.8	Audio recording disabled due to video buffering default				
04:35.4	Axon application connected to device				
05:04.3	Video played back using Axon application				a219ee423280450f9e7aff22300ebd9e
09:01.3	Categories 'Ambulance Call' added to video metadata using Axon applicator				a219ee423280450f9e7aff22300ebd9e
09:01.3	Title changed in video metadata from '' to 'Self Initiated Call. Code 32' using Axon applicator				a219ee423280450f9e7aff22300ebd9e
09:26.4	Axon application disconnected from device				
16:05.2	Audit log created	84	1	55.505	1.12.23
08:01.5	Event button pressed				
08:02.0	Event button released				
08:02.3	Event button pressed				
08:02.3	Audio recording enabled due to video recording default				
08:02.4	Recording started due to button press	79	2	55.504	fc89c6eeca44d159426722171db791a
08:02.4	Event button released				
13:37.4	Event button pressed				
13:40.4	Recording stopped due to button press	78	2	55.265	fc89c6eeca44d159426722171db791a
13:40.9	Event button released				
13:41.2	Audio recording disabled due to video buffering default				
15:46.9	Axon application connected to device				
16:05.2	Audit log created	77	2	55.264	1.12.23
16:08.0	Categories 'Customer Assist' added to video metadata using Axon applicator				fc89c6eeca44d159426722171db791a
16:17.0	Video played back using Axon application				fc89c6eeca44d159426722171db791a
18:37.1	Axon application disconnected from device				
31:21.5	Event button pressed				
31:21.7	Event button released				
31:21.9	Event button pressed				
31:22.0	Audio recording enabled due to video recording default				
31:22.1	Recording started due to button press	76	3	55.263	8289e741e2b14a5db2f7f2a9cab14193

31:22.1	Event button released			
34:26.0	Event button pressed			
34:26.4	Event button released			
34:26.7	Event button pressed			
34:32.2	Event button released			
34:32.7	Event button pressed			
34:35.7	Recording stopped due to button press	75	3	55.102 8289e741e2b14a5db2f7f2a9cab14193
34:36.4	Event button released			
34:36.5	Audio recording disabled due to video buffering default			
55:12.3	Volume up button pressed			
55:12.5	Volume up button released			
07:14.7	Power button pressed			
07:17.3	Power button released			
07:23.8	Power button pressed			
07:26.8	Device powered off using button	72	3	55.1
07:27.2	Power button released			
51:28.9	Audit log created		1.12.23	
51:29.0	Device powered on using button	72	3	55.101
51:31.0	Audio recording disabled due to video buffering default			
51:28.9	Audit log created	65	3 1.12.23	55.1
51:28.9	Audit log created	58	3 1.12.23	55.099
51:28.9	Audit log created	51	3 1.12.23	55.097
00:27.7	Power button pressed			
00:30.7	Device powered off using button	49	3	55.097
00:31.3	Power button released			
15:20.0	Device powered on due to charger connection	49	3	55.097
15:20.0	Device connected to charger			
15:20.0	Camera connected to Axon Dock X630020W7	49	3	55.097
15:20.1	Audit log created		1.12.23	
15:20.1	Audit log rolled			
15:21.0	Camera connected to Axon Dock X630020W7	50	3	55.097
15:22.9	Audit log rolled	49	3	55.097
15:22.9	Audit log created	49	3 1.12.23	55.097
15:22.0	Audit log created	77	3 1.12.23	55.096
15:22.0	Audit log created	99	3 1.12.23	55.096
15:22.0	Audit log created	100	3 1.12.23	55.095
15:22.0	Audit log created	100	3 1.12.23	55.095
15:22.0	Audit log created	100	3 1.12.23	55.095
15:22.0	Audit log created	100	3 1.12.23	55.095
15:22.0	Audit log created	100	3 1.12.23	55.094
15:22.0	Audit log created	100	3 1.12.23	55.094
15:22.1	Audit log created	100	3 1.12.23	55.094
15:22.1	Audit log created	100	3 1.12.23	55.094
15:22.1	Audit log created	100	3 1.12.23	55.094
15:22.1	Audit log created	100	3 1.12.23	55.093
15:22.1	Audit log created	100	3 1.12.23	55.093
45:08.0	Device disconnected from charger	98	3	55.093

45:08.5	Camera disconnected from Axon Dock X630020W7	100	3	55.093
45:08.6	Audio recording disabled due to video buffering default			
45:28.1	Power button pressed			
45:31.1	Device powered off using button	100	3	55.095
45:31.6	Power button released			
52:57.0	Audit log created		1.12.23	
52:57.1	Device powered on using button	100	3	55.094
52:59.0	Audio recording disabled due to video buffering default			
19:08.4	Select button pressed			
19:08.6	Select button released			
32:25.5	Select button pressed			
32:25.6	Select button released			
32:27.1	Volume up button pressed			
32:27.4	Volume up button released			
32:27.5	Volume up button pressed			
32:28.7	Volume up button released			
52:57.0	Audit log created	92	3 1.12.23	55.093
52:57.0	Audit log created	86	3 1.12.23	55.091
52:57.0	Audit log created	80	3 1.12.23	55.09
52:57.0	Audit log created	73	3 1.12.23	55.089
52:57.0	Audit log created	66	3 1.12.23	55.087
52:57.0	Audit log created	60	3 1.12.23	55.086
18:55.0	Power button pressed			
18:58.0	Device powered off using button	57	3	55.085
18:58.6	Power button released			
18:59.9	Volume up button pressed			
19:00.4	Volume up button released			
19:00.5	Volume up button pressed			
19:00.7	Volume up button released			
19:05.0	Audit log created	57	3 1.12.23	55.085
19:05.0	Audit log rolled	57	3	55.085
19:06.1	Device connected to charger	57	3	55.085
19:48.0	Device powered on due to charger connection	57	3	55.085
19:48.0	Device connected to charger			
19:48.0	Camera connected to Axon Dock X630020W7	58	3	55.085
19:48.0	Audit log rolled			
19:48.0	Audit log created		1.12.23	
19:48.9	Camera connected to Axon Dock X630020W7	58	3	55.085
19:50.9	Audit log created	57	3 1.12.23	55.085
19:50.9	Audit log rolled	57	3	55.085
19:50.0	Audit log created	84	3 1.12.23	55.084
19:50.0	Audit log created	100	3 1.12.23	55.083
19:50.0	Audit log created	100	3 1.12.23	55.083
19:50.0	Audit log created	100	3 1.12.23	55.083
19:50.0	Audit log created	100	3 1.12.23	55.083
19:50.0	Audit log created	100	3 1.12.23	55.082
19:50.0	Audit log created	100	3 1.12.23	55.082

19:50.0	Audit log created	100	3	1.12.23	55.082	
19:50.1	Audit log created	100	3	1.12.23	55.082	
19:50.1	Audit log created	100	3	1.12.23	55.081	
19:50.1	Audit log created	100	3	1.12.23	55.081	
19:50.1	Audit log created	100	3	1.12.23	55.081	
19:50.1	Audit log created	100	3	1.12.23	55.081	
00:37.0	Device disconnected from charger	98	3		55.08	
00:37.5	Camera disconnected from Axon Dock X630020W7	100	3		55.08	
00:37.7	Audio recording disabled due to video buffering default					
19:50.1	Audit log created	97	3	1.12.23	55.084	
09:51.7	Power button pressed					
09:54.7	Device powered off using button	91	3		55.083	
09:55.1	Power button released					
20:07.9	Audit log created			1.12.23		
20:08.0	Device powered on using button	91	3		55.083	
20:09.9	Audio recording disabled due to video buffering default					
23:35.7	Event button pressed					
23:35.8	Event button released					
23:36.0	Event button pressed					
23:36.0	Audio recording enabled due to video recording default					
23:36.1	Event button released					
23:36.2	Recording started due to button press	91	4		55.083	266f9d96865a464ca0d44cbeba6203ed
25:56.6	Event button pressed					
25:58.6	Event button released					
27:45.1	Event button pressed					
27:48.1	Recording stopped due to button press	90	4		54.89	266f9d96865a464ca0d44cbeba6203ed
27:48.6	Event button released					
27:49.1	Audio recording disabled due to video buffering default					
29:02.0	Axon application connected to device					
29:24.5	Axon application connected to device					
29:59.5	Video played back using Axon application					8289e741e2b14a5db2f7f2a9cab14193
30:51.5	Categories 'Sleeper' added to video metadata using Axon applicator					8289e741e2b14a5db2f7f2a9cab14193
30:51.5	Video played back using Axon application					8289e741e2b14a5db2f7f2a9cab14193
37:36.8	Categories 'Accidental Recording', 'Customer Assist' added to video metadata using Axon applicator					266f9d96865a464ca0d44cbeba6203ed
37:52.4	Title changed in video metadata from " to 'Code 22' using Axon applicator					266f9d96865a464ca0d44cbeba6203ed
38:06.3	Axon application disconnected from device					
50:58.9	Select button pressed					
51:03.1	Select button released					
51:29.4	Select button pressed					
51:29.5	Select button released					
51:30.7	Select button pressed					
51:30.8	Select button released					
57:11.6	Select button pressed					
57:12.0	Select button released					
08:08.0	Volume up button pressed					
08:08.1	Volume up button released					
08:53.3	Volume up button pressed					

08:53.6	Volume up button released			
08:53.9	Volume up button pressed			
08:54.1	Volume up button released			
08:54.1	Volume up button pressed			
08:54.2	Volume up button released			
20:07.9	Audit log created	85	4 1.12.23	54.887
23:06.1	Volume up button pressed			
23:09.1	Led brightness mode changed to Off from Dim			
23:09.1	Front led disabled using button			
23:09.1	Top led disabled using button			
23:18.2	Volume up button released			
23:18.6	Volume up button pressed			
23:18.6	Volume up button released			
23:18.8	Volume up button pressed			
23:18.9	Volume up button released			
23:19.0	Volume up button pressed			
23:19.4	Volume up button released			
23:19.4	Volume up button pressed			
23:22.5	Led brightness mode changed to Auto from Off			
23:22.6	Front led auto brightness enabled using button			
23:22.6	Front led brightness changed to 0% from 1% using button			
23:22.6	Front led enabled using button			
23:22.6	Top led auto brightness enabled using ambient light change			
23:22.6	Top led brightness changed to 0% from 1% using ambient light change			
23:22.6	Top led enabled using ambient light change			
23:23.1	Volume up button released			
23:23.2	Volume up button pressed			
23:23.3	Volume up button released			
23:23.3	Volume up button pressed			
23:23.3	Led brightness mode changed to Dim from Auto			
23:23.3	Front led auto brightness disabled using button			
23:23.4	Front led brightness changed to 1% from 0% using button			
23:23.4	Volume up button released			
23:23.4	Top led auto brightness disabled using button			
23:23.4	Top led brightness changed to 1% from 0% using button			
23:24.9	Volume up button pressed			
23:27.9	Led brightness mode changed to Off from Dim			
23:28.0	Front led disabled using button			
23:28.0	Top led disabled using button			
23:28.4	Volume up button released			
27:45.4	Volume up button pressed			
27:45.7	Volume up button released			
20:07.9	Audit log created	79	4 1.12.23	54.885
12:39.1	Power button pressed			
12:42.1	Device powered off using button	73	4	54.884
12:42.7	Power button released			
03:14.9	Audit log created		1.12.23	

03:15.0 Device powered on using button	73	4	54.886
03:17.0 Audio recording disabled due to video buffering default			
03:14.9 Audit log created	66	4 1.12.23	54.884
03:14.9 Audit log created	61	4 1.12.23	54.883
36:51.2 Power button pressed			
36:54.2 Device powered off using button	56	4	54.882
36:54.7 Power button released			
36:57.9 Audit log rolled	56	4	54.882
36:57.9 Audit log created	56	4 1.12.23	54.882
36:59.0 Device connected to charger	56	4	54.882
37:44.0 Device powered on due to charger connection	57	4	54.882
37:44.0 Device connected to charger			
37:44.1 Camera connected to Axon Dock X630020W7	57	4	54.882
37:44.1 Audit log created		1.12.23	
37:44.1 Audit log rolled			
37:45.0 Camera connected to Axon Dock X630020W7	57	4	54.881
37:47.0 Audit log rolled	57	4	54.882
37:47.0 Audit log created	57	4 1.12.23	54.882
37:46.0 Audit log created	84	4 1.12.23	54.881
37:46.0 Audit log created	100	4 1.12.23	54.88
37:46.0 Audit log created	100	4 1.12.23	54.88
37:46.0 Audit log created	100	4 1.12.23	54.88
37:46.0 Audit log created	100	4 1.12.23	54.879
37:46.0 Audit log created	100	4 1.12.23	54.879
37:46.1 Audit log created	100	4 1.12.23	54.879
37:46.1 Audit log created	100	4 1.12.23	54.879
37:46.1 Audit log created	100	4 1.12.23	54.878
37:46.1 Audit log created	100	4 1.12.23	54.878
37:46.1 Audit log created	100	4 1.12.23	54.878
37:46.1 Audit log created	100	4 1.12.23	54.878
37:46.1 Audit log created	100	4 1.12.23	54.878
30:13.9 Camera disconnected from Axon Dock X630020W7	100	4	54.878
30:14.0 Device disconnected from charger	100	4	54.878
30:14.0 Audio recording disabled due to video buffering default			
30:38.3 Power button pressed			
30:41.3 Device powered off using button	100	4	54.879
30:41.7 Power button released			
33:41.0 Device powered on using button	100	4	54.878
33:43.0 Audio recording disabled due to video buffering default			
37:46.1 Audit log created	99	4 1.12.23	54.878
10:36.9 Power button pressed			
10:39.9 Device powered off using button	95	4	54.877
10:40.3 Power button released			
33:13.2 Audit log created		1.12.23	
33:13.3 Device powered on using button	95	4	54.877
33:16.3 Audio recording disabled due to video buffering default			
37:37.7 Event button pressed			
37:38.3 Event button released			

37:39.3 Event button pressed			
37:39.5 Event button released			
37:39.8 Event button pressed			
37:39.8 Audio recording enabled due to video recording default			
37:39.9 Event button released			
37:40.0 Recording started due to button press	94	5	54.877 e9645bedd59945cb95daeb252754a0f7
37:41.8 Event button pressed			
37:44.8 Recording stopped due to button press	94	5	54.866 e9645bedd59945cb95daeb252754a0f7
37:45.3 Event button released			
37:45.7 Audio recording disabled due to video buffering default			
38:28.9 Axon application connected to device			
38:59.4 Video played back using Axon application			e9645bedd59945cb95daeb252754a0f7
40:00.8 Categories 'Accidental Recording' added to video metadata using Axon applicator			e9645bedd59945cb95daeb252754a0f7
40:20.1 Top led enabled using Axon application			
40:20.1 Front led enabled using Axon application			
40:20.5 Led brightness mode changed to Dim from Off			
40:29.7 Top led disabled using Axon application			
40:29.8 Front led disabled using Axon application			
40:30.1 Led brightness mode changed to Off from Dim			
40:33.1 Top led enabled using Axon application			
40:33.1 Front led enabled using Axon application			
40:33.5 Led brightness mode changed to Dim from Off			
43:41.7 Axon application disconnected from device			
33:13.2 Audit log created	88	5 1.12.23	54.812
33:13.2 Audit log created	82	5 1.12.23	54.811
49:38.7 Event button pressed			
49:39.3 Event button released			
49:40.2 Event button pressed			
49:40.5 Event button released			
49:40.6 Event button pressed			
49:40.6 Audio recording enabled due to video recording default			
49:40.7 Event button released			
49:40.8 Recording started due to button press	81	6	54.81 d80eb7f5707b403e8f4a85e4595ea24b
50:20.9 Event button pressed			
50:23.9 Recording stopped due to button press	80	6	54.727 d80eb7f5707b403e8f4a85e4595ea24b
50:24.5 Event button released			
50:24.8 Audio recording disabled due to video buffering default			
52:33.1 Axon application connected to device			
53:38.0 Categories 'Loitering' added to video metadata using Axon applicator			d80eb7f5707b403e8f4a85e4595ea24b
53:49.2 Axon application disconnected from device			
33:13.2 Audit log created	76	6 1.12.23	54.725
33:13.2 Audit log created	70	6 1.12.23	54.724
33:13.2 Audit log created	64	6 1.12.23	54.722
33:13.2 Audit log created	58	6 1.12.23	54.721
23:45.5 Volume up button pressed			
23:45.8 Volume up button released			
23:49.0 Power button pressed			

23:52.0 Device powered off using button	51	6	54.72
23:52.3 Power button released			
23:56.0 Audit log rolled	51	6	54.72
23:56.0 Audit log created	51	6 1.12.23	54.72
23:57.3 Device connected to charger	51	6	54.72
24:42.0 Device powered on due to charger connection	51	6	54.719
24:42.0 Device connected to charger			
24:42.0 Camera connected to Axon Dock X630020W7	51	6	54.719
24:42.1 Audit log rolled			
24:42.1 Audit log created		1.12.23	
24:43.0 Camera connected to Axon Dock X630020W7	52	6	54.719
24:45.0 Audit log created	51	6 1.12.23	54.719
24:45.0 Audit log rolled	51	6	54.719
24:44.0 Audit log created	79	6 1.12.23	54.719
24:44.0 Audit log created	100	6 1.12.23	54.718
24:44.0 Audit log created	100	6 1.12.23	54.718
24:44.0 Audit log created	100	6 1.12.23	54.719
24:44.0 Audit log created	100	6 1.12.23	54.719
24:44.0 Audit log created	100	6 1.12.23	54.72
24:44.1 Audit log created	100	6 1.12.23	54.719
24:44.1 Audit log created	100	6 1.12.23	54.719
24:44.1 Audit log created	100	6 1.12.23	54.719
31:00.0 Device disconnected from charger	98	6	54.719
31:00.1 Camera disconnected from Axon Dock X630020W7	98	6	54.719
31:00.2 Audio recording disabled due to video buffering default			
07:20.5 Power button pressed			
07:23.5 Device powered off using button	95	6	54.722
07:24.0 Power button released			
59:27.0 Audit log created		1.12.23	
59:27.0 Device connected to charger			
59:27.0 Device powered on due to charger connection	95	6	54.721
59:27.1 Camera connected to Axon Dock X630020W7	96	6	54.721
59:27.1 Audit log created		1.12.23	
59:27.1 Audit log rolled			
59:28.0 Camera connected to Axon Dock X630020W7	96	6	54.721
59:29.9 Audit log created	95	6 1.12.23	54.721
59:29.9 Audit log rolled	95	6	54.721
59:29.0 Audit log created	100	6 1.12.23	54.726
59:29.0 Audit log created	100	6 1.12.23	54.726
59:29.0 Audit log created	100	6 1.12.23	54.726
59:29.0 Audit log created	100	6 1.12.23	54.726
59:29.1 Audit log created	100	6 1.12.23	54.726
59:29.1 Audit log created	100	6 1.12.23	54.726
59:29.1 Audit log created	100	6 1.12.23	54.725
59:29.1 Audit log created	100	6 1.12.23	54.725
59:29.1 Audit log created	100	6 1.12.23	54.725
59:29.1 Audit log created	100	6 1.12.23	54.725

59:29.6	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.724
59:29.7	Audit log created	99	6 1.12.23	54.723
59:29.7	Audit log created	99	6 1.12.23	54.723
59:29.7	Audit log created	99	6 1.12.23	54.723
38:47.0	Device disconnected from charger	99	6	54.723
38:47.4	Camera disconnected from Axon Dock X630020W7	99	6	54.723
38:47.5	Audio recording disabled due to video buffering default			
39:01.3	Power button pressed			
39:04.3	Device powered off using button	99	6	54.723
39:04.7	Power button released			
28:26.1	Audit log created		1.12.23	
28:26.2	Device powered on using button	99	6	54.722
28:28.1	Audio recording disabled due to video buffering default			
28:26.1	Audit log created	91	6 1.12.23	54.721
47:08.1	Power button pressed			
47:10.1	Power button released			
47:10.5	Power button pressed			
47:10.5	Power button released			
47:14.9	Power button pressed			
47:15.7	Power button released			
47:17.4	Power button pressed			
47:20.4	Device powered off using button	89	6	54.721
47:20.8	Power button released			
15:50.1	Device powered on using button	89	6	54.721
15:52.0	Audio recording disabled due to video buffering default			
28:26.1	Audit log created	88	6 1.12.23	54.72
14:06.0	Volume up button pressed			
14:07.3	Volume up button released			
15:49.4	Volume up button pressed			
15:50.0	Volume up button released			
18:10.0	Volume up button pressed			
18:10.2	Volume up button released			
28:26.1	Audit log created	82	6 1.12.23	54.719
36:51.4	Power button pressed			
36:54.4	Device powered off using button	80	6	54.719
36:54.9	Power button released			
25:12.0	Audit log created		1.12.23	
25:12.1	Device powered on due to charger connection	81	6	54.718
25:12.1	Device connected to charger			
25:12.1	Camera connected to Axon Dock X630020W7	81	6	54.718
25:12.1	Audit log created		1.12.23	
25:12.1	Audit log rolled			

25:13.0 Camera connected to Axon Dock X630020W7	81	6	54.718
25:15.0 Audit log created	81	6 1.12.23	54.718
25:15.0 Audit log rolled	81	6	54.718
25:14.0 Audit log created	100	6 1.12.23	54.718
25:14.0 Audit log created	100	6 1.12.23	54.717
25:14.0 Audit log created	100	6 1.12.23	54.717
25:14.1 Audit log created	100	6 1.12.23	54.717
25:14.1 Audit log created	100	6 1.12.23	54.717
25:14.1 Audit log created	100	6 1.12.23	54.716
35:17.0 Camera disconnected from Axon Dock X630020W7	100	6	54.716
35:17.0 Device disconnected from charger	99	6	54.716
35:17.1 Audio recording disabled due to video buffering default			
35:36.7 Power button pressed			
35:39.7 Device powered off using button	100	6	54.717
35:40.1 Power button released			
22:21.0 Audit log created		1.12.23	
22:21.1 Device powered on using button	100	6	54.716
22:23.0 Audio recording disabled due to video buffering default			
22:29.6 Event button pressed			
22:29.8 Event button released			
22:30.1 Event button pressed			
22:30.1 Audio recording enabled due to video recording default			
22:30.3 Event button released			
22:30.3 Recording started due to button press	100	7	54.716 a39d2c77fba649d78f2079a5da1218c4
26:21.5 Event button pressed			
26:24.5 Recording stopped due to button press	99	7	54.59 a39d2c77fba649d78f2079a5da1218c4
26:25.1 Event button released			
26:25.2 Audio recording disabled due to video buffering default			
22:21.0 Audit log created	92	7 1.12.23	54.588
35:29.4 Event button pressed			
35:29.5 Event button released			
35:29.7 Event button pressed			
35:29.7 Audio recording enabled due to video recording default			
35:29.8 Event button released			
35:29.8 Recording started due to button press	91	8	54.587 8a5fda29774449e8ad8a4d63ff00e3c5
50:39.4 Event button pressed			
50:42.4 Recording stopped due to button press	88	8	54.049 8a5fda29774449e8ad8a4d63ff00e3c5
50:43.0 Event button released			
50:43.3 Audio recording disabled due to video buffering default			
59:28.8 Axon application connected to device			
59:56.6 Categories 'Ambulance Call' added to video metadata using Axon applicator			a39d2c77fba649d78f2079a5da1218c4
00:25.3 Title changed in video metadata from " to 'Code 9 by 3601 Sgt Peaco' using Axon applicator			a39d2c77fba649d78f2079a5da1218c4
00:44.4 Categories 'Assault' added to video metadata using Axon applicator			8a5fda29774449e8ad8a4d63ff00e3c5
01:33.1 Title changed in video metadata from " to 'Supposed Aggravated Assault At S6' using Axon applicator			8a5fda29774449e8ad8a4d63ff00e3c5
01:42.5 Axon application disconnected from device			
22:21.0 Audit log created	85	8 1.12.23	54.045
22:21.0 Audit log created	79	8 1.12.23	54.044

05:33.5	Volume up button pressed			
05:34.1	Volume up button released			
22:21.0	Audit log created	73	8 1.12.23	54.042
22:21.0	Audit log created	66	8 1.12.23	54.041
22:21.1	Audit log created	60	8 1.12.23	54.04
13:46.9	Power button pressed			
13:49.9	Device powered off using button	54	8	54.038
13:50.3	Power button released			
13:51.3	Volume up button pressed			
13:51.6	Volume up button released			
13:51.6	Select button pressed			
13:51.7	Select button released			
13:51.7	Volume up button pressed			
13:51.8	Volume up button released			
13:51.8	Select button pressed			
13:51.9	Select button released			
13:54.9	Volume up button pressed			
13:55.0	Volume up button released			
13:55.4	Audit log rolled	54	8	54.038
13:55.4	Audit log created	54	8 1.12.23	54.038
13:56.1	Device connected to charger	54	8	54.038
14:00.9	Power button pressed			
14:01.1	Power button released			
14:43.0	Device connected to charger			
14:43.0	Device powered on due to charger connection	54	8	54.038
14:43.0	Camera connected to Axon Dock X630020W7	54	8	54.038
14:43.1	Audit log created		1.12.23	
14:43.1	Audit log rolled			
14:43.9	Camera connected to Axon Dock X630020W7	54	8	54.038
14:45.9	Audit log rolled	54	8	54.038
14:45.9	Audit log created	54	8 1.12.23	54.038
14:45.0	Audit log created	82	8 1.12.23	54.037
14:45.0	Audit log created	100	8 1.12.23	54.037
14:45.0	Audit log created	100	8 1.12.23	54.036
14:45.1	Audit log created	100	8 1.12.23	54.036
14:45.1	Audit log created	100	8 1.12.23	54.036
14:45.1	Audit log created	100	8 1.12.23	54.036
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.1	Audit log created	100	8 1.12.23	54.035
14:45.2	Audit log created	100	8 1.12.23	54.034
14:45.2	Audit log created	100	8 1.12.23	54.034
13:14.9	Camera disconnected from Axon Dock X630020W7	100	8	54.034
13:14.9	Device disconnected from charger	100	8	54.034
13:15.0	Audio recording disabled due to video buffering default			
13:26.4	Power button pressed			

13:29.4 Device powered off using button	100	8	54.039	
13:29.8 Power button released				
00:28.1 Audit log created				1.12.23
00:28.2 Device powered on using button	100	8	54.038	
00:31.2 Audio recording disabled due to video buffering default				
00:42.1 Event button pressed				
00:42.3 Event button released				
00:42.5 Event button pressed				
00:42.5 Audio recording enabled due to video recording default				
00:42.7 Event button released				
00:42.7 Recording started due to button press	100	9	54.038	9823e23f7c954a51bb75d2650bb9b4de
08:57.3 Event button pressed				
09:00.3 Recording stopped due to button press	98	9	53.771	9823e23f7c954a51bb75d2650bb9b4de
09:00.7 Event button released				
09:01.0 Audio recording disabled due to video buffering default				
09:19.3 Axon application connected to device				
09:50.1 Categories 'Ambulance Call' added to video metadata using Axon applicator				9823e23f7c954a51bb75d2650bb9b4de
10:19.1 Axon application disconnected from device				
00:28.1 Audit log created	92	9	53.768	1.12.23
31:03.0 Event button pressed				
31:03.2 Event button released				
31:04.5 Event button pressed				
31:04.7 Event button released				
31:04.9 Event button pressed				
31:04.9 Audio recording enabled due to video recording default				
31:05.0 Event button released				
31:05.0 Recording started due to button press	89	10	53.767	258bdaf182684f4e8b9714089b8d1a49
33:13.2 Event button pressed				
33:16.2 Recording stopped due to button press	88	10	53.637	258bdaf182684f4e8b9714089b8d1a49
33:17.0 Event button released				
33:17.0 Audio recording disabled due to video buffering default				
45:55.6 Event button pressed				
45:55.8 Event button released				
45:56.0 Event button pressed				
45:56.1 Audio recording enabled due to video recording default				
45:56.2 Event button released				
45:56.2 Recording started due to button press	87	11	53.636	1f3e5a18331d46c195a145f9682fd235
00:28.2 Audit log created	84	11	53.115	1.12.23
20:01.7 Event button pressed				
20:04.7 Recording stopped due to button press	81	11	52.492	1f3e5a18331d46c195a145f9682fd235
20:05.6 Event button released				
20:05.8 Audio recording disabled due to video buffering default				
30:21.0 Event button pressed				
30:21.2 Event button released				
30:21.3 Event button pressed				
30:21.4 Audio recording enabled due to video recording default				
30:21.5 Event button released				

30:21.5	Recording started due to button press	80	12	52.486	71aa3068255c4f5abdbad38af9950d89
36:56.4	Event button pressed				
36:59.4	Recording stopped due to button press	78	12	52.215	71aa3068255c4f5abdbad38af9950d89
37:00.0	Event button released				
37:00.3	Audio recording disabled due to video buffering default				
51:00.5	Axon application connected to device				
51:39.7	Categories 'Ambulance Call' added to video metadata using Axon applicator				258bdaf182684f4e8b9714089b8d1a49
51:54.3	Title changed in video metadata from "" to 'Code 9 By 3610' using Axon applicator				258bdaf182684f4e8b9714089b8d1a49
52:17.5	Video played back using Axon application				9823e23f7c954a51bb75d2650bb9b4de
53:14.2	Title changed in video metadata from "" to 'Sig. 4 Code By 3610' using Axon applicator				9823e23f7c954a51bb75d2650bb9b4de
53:33.2	Title changed in video metadata from 'Sig. 4 Code By 3610' to 'Sig. 4 Code 9 By 3610' using Axon applicator				9823e23f7c954a51bb75d2650bb9b4de
53:47.3	Title changed in video metadata from 'Code 9 By 3610' to 'Sig. 4 Code 9 By 3610' using Axon applicator				258bdaf182684f4e8b9714089b8d1a49
54:05.7	Categories 'Ambulance Call' added to video metadata using Axon applicator				71aa3068255c4f5abdbad38af9950d89
55:21.9	Categories 'Disorderly Person' added to video metadata using Axon applicator				71aa3068255c4f5abdbad38af9950d89
55:21.9	Title changed in video metadata from "" to 'Sig. 22 on AMR 35 To Saint Joseph's Hospital' using Axon applicator				71aa3068255c4f5abdbad38af9950d89
55:54.2	Categories 'Ambulance Call', 'Loitering', 'Disorderly Person' added to video metadata using Axon applicator				1f3e5a18331d46c195a145f9682fd235
56:31.6	Title changed in video metadata from "" to 'Sig. 4 Code 9 By 3610' using Axon applicator				1f3e5a18331d46c195a145f9682fd235
56:57.9	Video played back using Axon application				1f3e5a18331d46c195a145f9682fd235
00:28.4	Audit log created	76	12 1.12.23	52.213	
05:08.9	Video played back using Axon application				1f3e5a18331d46c195a145f9682fd235
08:19.0	Video played back using Axon application				1f3e5a18331d46c195a145f9682fd235
10:13.7	Axon application disconnected from device				
00:28.4	Audit log created	70	12 1.12.23	52.211	
00:28.4	Audit log created	63	12 1.12.23	52.21	
00:28.4	Audit log created	57	12 1.12.23	52.209	
35:57.6	Power button pressed				
36:00.7	Device powered off using button	52	12	52.208	
36:01.1	Power button released				
36:02.7	Volume up button pressed				
36:02.9	Volume up button released				
36:06.9	Audit log rolled	52	12	52.208	
36:06.9	Audit log created	52	12 1.12.23	52.208	
36:07.2	Device connected to charger	52	12	52.208	
37:05.0	Device powered on due to charger connection	53	12	52.207	
37:05.0	Device connected to charger				
37:05.1	Camera connected to Axon Dock X630020W7	53	12	52.207	
37:05.2	Audit log created		1.12.23		
37:05.2	Audit log rolled				
37:06.0	Camera connected to Axon Dock X630020W7	53	12	52.207	
37:07.9	Audit log rolled	53		52.207	
37:07.9	Audit log created	53	12 1.12.23	52.207	
37:07.0	Audit log created	80	12 1.12.23	52.206	
37:07.0	Audit log created	100	12 1.12.23	52.206	
37:07.0	Audit log created	100	12 1.12.23	52.205	
37:07.1	Audit log created	100	12 1.12.23	52.205	
37:07.1	Audit log created	100	12 1.12.23	52.205	
37:07.1	Audit log created	100	12 1.12.23	52.205	

37:07.1 Audit log created	100	12 1.12.23	52.204
37:07.1 Audit log created	100	12 1.12.23	52.204
37:07.1 Audit log created	100	12 1.12.23	52.204
37:07.2 Audit log created	100	12 1.12.23	52.204
37:07.2 Audit log created	100	12 1.12.23	52.204
37:07.2 Audit log created	100	12 1.12.23	52.203
57:06.9 Camera disconnected from Axon Dock X630020W7	100	12	52.203
57:07.0 Device disconnected from charger	100	12	52.203
57:07.1 Audio recording disabled due to video buffering default			
57:19.5 Power button pressed			
57:22.5 Device powered off using button	100	12	52.208
57:22.9 Power button released			
45:06.0 Audit log created		1.12.23	
45:06.0 Device powered on using button	100	12	52.207
45:08.0 Audio recording disabled due to video buffering default			
45:44.5 Event button pressed			
45:44.6 Event button released			
45:44.8 Event button pressed			
45:44.8 Audio recording enabled due to video recording default			
45:44.9 Event button released			
45:45.0 Recording started due to button press	100	13	52.207 eea361daf5904b5fad536c99d01ac624
52:39.4 Event button pressed			
52:42.4 Recording stopped due to button press	98	13	51.97 eea361daf5904b5fad536c99d01ac624
52:42.9 Event button released			
52:43.2 Audio recording disabled due to video buffering default			
21:45.8 Volume up button pressed			
21:46.0 Volume up button released			
35:59.8 Volume up button pressed			
35:59.9 Volume up button released			
45:06.0 Audit log created	92	13 1.12.23	51.967
47:39.9 Event button pressed			
47:41.0 Event button released			
09:36.1 Volume up button pressed			
09:36.3 Volume up button released			
21:47.7 Volume up button pressed			
21:47.9 Volume up button released			
22:02.2 Volume up button pressed			
22:02.4 Volume up button released			
45:06.0 Audit log created	86	13 1.12.23	51.966
26:18.4 Power button pressed			
26:21.4 Device powered off using button	82	13	51.965
26:21.9 Power button released			
51:52.2 Audit log created		1.12.23	
51:52.2 Device powered on using button	82	13	51.964
51:55.3 Audio recording disabled due to video buffering default			
51:52.2 Audit log created	75	13 1.12.23	51.964
55:55.2 Volume up button pressed			

55:55.5	Volume up button released			
56:12.6	Volume up button pressed			
56:13.0	Volume up button released			
59:15.6	Volume up button pressed			
59:15.7	Volume up button released			
59:27.9	Volume up button pressed			
59:28.4	Volume up button released			
10:11.6	Volume up button pressed			
10:11.7	Volume up button released			
51:52.2	Audit log created	69	13 1.12.23	51.963
51:52.2	Audit log created	62	13 1.12.23	51.962
08:19.0	Power button pressed			
08:22.0	Device powered off using button	60	13	51.961
08:22.5	Power button released			
08:23.4	Volume up button pressed			
08:23.6	Volume up button released			
08:23.7	Volume up button pressed			
08:23.8	Volume up button released			
08:27.6	Audit log rolled	60	13	51.961
08:27.6	Audit log created	60	13 1.12.23	51.962
08:28.2	Device connected to charger	60	13	51.962
09:11.1	Device powered on due to charger connection	61	13	51.961
09:11.1	Device connected to charger			
09:11.2	Camera connected to Axon Dock X630020W7	61	13	51.961
09:11.2	Audit log created		1.12.23	
09:11.2	Audit log rolled			
09:12.1	Camera connected to Axon Dock X630020W7	61	13	51.961
09:14.0	Audit log rolled	61		51.961
09:14.0	Audit log created	61	13 1.12.23	51.961
09:13.0	Audit log created	88	13 1.12.23	51.96
09:13.0	Audit log created	100	13 1.12.23	51.96
09:13.0	Audit log created	100	13 1.12.23	51.959
09:13.1	Audit log created	100	13 1.12.23	51.959
09:13.1	Audit log created	100	13 1.12.23	51.959
09:13.1	Audit log created	100	13 1.12.23	51.958
08:49.3	Camera disconnected from Axon Dock X630020W7	98	13	51.958
08:49.4	Audio recording disabled due to video buffering default			
08:50.1	Device disconnected from charger	98	13	51.96
09:01.7	Power button pressed			
09:04.2	Power button released			
09:13.1	Power button pressed			
09:13.1	Audit log created	100	13 1.12.23	51.96
09:16.1	Device powered off using button	100	13	51.96
09:16.6	Power button released			
40:19.0	Audit log created		1.12.23	
40:19.0	Device connected to charger			

40:19.0 Device powered on due to charger connection	98	13	51.96
40:19.0 Camera connected to Axon Dock X630020W7	98	13	51.959
40:19.0 Audit log rolled			
40:19.0 Audit log created		1.12.23	
40:20.0 Camera connected to Axon Dock X630020W7	98	13	51.959
40:21.9 Audit log rolled	98		51.96
40:21.9 Audit log created	98	13 1.12.23	51.96
40:21.0 Audit log created	98	13 1.12.23	51.959
40:21.0 Audit log created	98	13 1.12.23	51.959
40:21.1 Audit log created	98	13 1.12.23	51.959
40:21.1 Audit log created	98	13 1.12.23	51.958
46:15.9 Camera disconnected from Axon Dock X630020W7	98	13	51.958
46:16.0 Device disconnected from charger	98	13	51.958
46:16.1 Audio recording disabled due to video buffering default			
46:24.9 Volume down button pressed			
46:25.0 Volume down button released			
46:25.6 Volume changed to high from very high using button			
00:15.4 Volume up button pressed			
00:15.9 Volume up button released			
00:16.0 Volume changed to very high from high using button			
00:34.8 Power button pressed			
00:37.8 Device powered off using button	96	13	51.958
00:38.5 Power button released			
09:28.0 Audit log created		1.12.23	
09:28.0 Device powered on using button	96	13	51.957
09:30.0 Audio recording disabled due to video buffering default			
09:28.0 Audit log created	89	13 1.12.23	51.956
09:28.0 Audit log created	83	13 1.12.23	51.955
09:28.0 Audit log created	77	13 1.12.23	51.953
09:28.1 Audit log created	70	13 1.12.23	51.952
09:28.1 Audit log created	63	13 1.12.23	51.951
09:28.1 Audit log created	57	13 1.12.23	51.949
50:20.0 Volume up button pressed			
50:20.0 Volume up button released			
53:00.9 Volume up button pressed			
53:01.0 Volume up button released			
09:28.1 Audit log created	49	13 1.12.23	51.948
24:39.4 Volume up button pressed			
24:39.9 Volume up button released			
24:40.1 Volume up button pressed			
24:40.2 Volume up button released			
24:43.0 Power button pressed			
24:46.0 Device powered off using button	47	13	51.947
24:46.4 Power button released			
24:50.5 Audit log rolled	47	13	51.948
24:50.5 Audit log created	47	13 1.12.23	51.948
24:51.0 Device connected to charger	47	13	51.948

25:36.1 Device powered on due to charger connection	47	13	51.949
25:36.1 Device connected to charger			
25:36.1 Camera connected to Axon Dock X630020W7	47	13	51.949
25:36.1 Audit log rolled			
25:36.1 Audit log created		1.12.23	
25:37.0 Camera connected to Axon Dock X630020W7	48	13	51.949
25:39.0 Audit log created	47	13 1.12.23	51.949
25:39.0 Audit log rolled	47	13	51.949
25:38.0 Audit log created	76	13 1.12.23	51.948
25:38.0 Audit log created	99	13 1.12.23	51.948
25:38.1 Audit log created	100	13 1.12.23	51.947
25:38.1 Audit log created	100	13 1.12.23	51.947
25:38.1 Audit log created	100	13 1.12.23	51.947
25:38.1 Audit log created	100	13 1.12.23	51.947
25:38.1 Audit log created	100	13 1.12.23	51.946
25:38.2 Audit log created	100	13 1.12.23	51.947
25:38.2 Audit log created	100	13 1.12.23	51.95
25:38.2 Audit log created	100	13 1.12.23	51.95
25:38.2 Audit log created	100	13 1.12.23	51.95
25:38.2 Audit log created	100	13 1.12.23	51.95
25:38.2 Audit log created	100	13 1.12.23	51.95
31:41.7 Camera disconnected from Axon Dock X630020W7	98	13	51.95
31:41.8 Audio recording disabled due to video buffering default			
31:42.1 Device disconnected from charger	98	13	51.954
31:54.6 Power button pressed			
31:57.6 Device powered off using button	100	13	51.954
31:58.1 Power button released			
51:08.0 Audit log created		1.12.23	
51:08.1 Device powered on using button	100	13	51.953
51:10.0 Audio recording disabled due to video buffering default			
51:08.0 Audit log created	92	13 1.12.23	51.952
51:08.0 Audit log created	86	13 1.12.23	51.951
51:08.0 Audit log created	79	13 1.12.23	51.949
51:08.1 Audit log created	73	13 1.12.23	51.948
51:08.1 Audit log created	66	13 1.12.23	51.947
51:08.1 Audit log created	60	13 1.12.23	51.945
51:08.1 Audit log created	51	13 1.12.23	51.944
16:33.8 Power button pressed			
16:36.8 Device powered off using button	48	13	51.943
16:37.2 Power button released			
16:41.1 Audit log rolled	48	13	51.943
16:41.1 Audit log created	48	13 1.12.23	51.944
16:42.1 Device connected to charger	48	13	51.944
17:27.0 Device connected to charger			
17:27.0 Device powered on due to charger connection	48	13	51.943
17:27.0 Camera connected to Axon Dock X630020W7	49	13	51.943
17:27.1 Audit log rolled			

17:27.1 Audit log created		1.12.23	
17:28.0 Camera connected to Axon Dock X630020W7	49	13	51.943
17:29.9 Audit log created	48	13 1.12.23	51.943
17:29.9 Audit log rolled	48		51.943
17:29.0 Audit log created	76	13 1.12.23	51.942
17:29.0 Audit log created	99	13 1.12.23	51.942
17:29.1 Audit log created	100	13 1.12.23	51.941
17:29.1 Audit log created	100	13 1.12.23	51.941
17:29.1 Audit log created	100	13 1.12.23	51.941
17:29.1 Audit log created	100	13 1.12.23	51.941
17:29.1 Audit log created	100	13 1.12.23	51.94
17:29.1 Audit log created	100	13 1.12.23	51.94
17:29.2 Audit log created	100	13 1.12.23	51.951
17:29.2 Audit log created	100	13 1.12.23	51.952
17:29.2 Audit log created	100	13 1.12.23	51.952
17:29.2 Audit log created	100	13 1.12.23	51.952
17:29.2 Audit log created	100	13 1.12.23	51.951
17:29.3 Audit log created	100	13 1.12.23	51.951
17:29.3 Audit log created	100	13 1.12.23	51.951
17:29.3 Audit log created	100	13 1.12.23	51.951
17:29.3 Audit log created	100	13 1.12.23	51.951
17:29.3 Audit log created	100	13 1.12.23	51.951
17:29.4 Audit log created	100	13 1.12.23	51.95
17:29.4 Audit log created	100	13 1.12.23	51.95
17:29.4 Audit log created	100	13 1.12.23	51.95
17:29.4 Audit log created	100	13 1.12.23	51.95
17:29.4 Audit log created	100	13 1.12.23	51.949
17:29.5 Audit log created	100	13 1.12.23	51.95
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.5 Audit log created	100	13 1.12.23	51.952
17:29.6 Audit log created	100	13 1.12.23	51.952
17:29.6 Audit log created	100	13 1.12.23	51.951
08:14.0 Device disconnected from charger	99	13	51.951
08:14.4 Camera disconnected from Axon Dock X630020W7	100	13	51.951
08:14.6 Audio recording disabled due to video buffering default			
08:25.9 Power button pressed			
08:28.9 Device powered off using button	100	13	51.956
08:29.4 Power button released			
08:28.9 Audit log created		1.12.23	
08:29.0 Device powered on using button	100	13	51.955
08:31.0 Audio recording disabled due to video buffering default			
08:29.0 Audit log created	92	13 1.12.23	51.953
47:44.9 Volume up button pressed			
47:45.1 Volume up button released			

47:45.2	Volume up button pressed			
47:45.3	Volume up button released			
47:52.3	Camera connected to Axon Dock X62001W9H	88	13	52.02
47:52.4	Audit log created	88	13 1.12.23	51.952
47:52.4	Audit log rolled	88	13	51.952
47:53.0	Device connected to charger	88	13	51.952
48:15.6	Video upload started when camera was docked			a219ee423280450f9e7aff22300ebd9e
48:37.0	Date/Time synced to 05/18/2021 05:48:37.01 PM from 05/18/2021 05:48:22.35 PM			
48:40.4	Audit log successfully uploaded			
48:40.4	Audit log successfully uploaded			
48:40.5	Audit log successfully uploaded			
48:40.5	Audit log successfully uploaded			
48:40.5	Audit log successfully uploaded			
48:40.6	Audit log successfully uploaded and deleted from device	88	13	52.052
48:40.6	Audit log successfully uploaded and deleted from device	88	13	52.052
48:40.7	Audit log successfully uploaded and deleted from device	88	13	52.052
48:40.7	Audit log successfully uploaded and deleted from device	88	13	52.052
48:40.8	Audit log successfully uploaded			
48:40.8	Audit log successfully uploaded			
48:40.8	Audit log successfully uploaded			
48:40.8	Audit log successfully uploaded			
48:40.9	Audit log successfully uploaded			
48:40.9	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.0	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.0	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.0	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.1	Audit log successfully uploaded			
48:41.1	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.1	Audit log successfully uploaded			
48:41.1	Audit log successfully uploaded			
48:41.2	Audit log successfully uploaded			
48:41.3	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.3	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.3	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.3	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.4	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.4	Audit log successfully uploaded			
48:41.4	Audit log successfully uploaded			
48:41.4	Audit log successfully uploaded			
48:41.5	Audit log successfully uploaded			
48:41.6	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.6	Audit log successfully uploaded			
48:41.6	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.7	Audit log successfully uploaded and deleted from device	88	13	52.052
48:41.7	Audit log successfully uploaded			
48:41.7	Audit log successfully uploaded			
48:41.8	Audit log successfully uploaded and deleted from device	88	13	52.052

49:01.3	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:01.3	Audit log successfully uploaded				
49:01.4	Audit log successfully uploaded				
49:01.5	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:01.5	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:01.6	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:01.7	Audit log successfully uploaded				
49:01.9	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:03.1	Audit log successfully uploaded				
49:03.2	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:03.7	Audit log successfully uploaded				
49:03.9	Audit log successfully uploaded and deleted from device	88	13	52.051	
49:28.4	Video successfully uploaded from device when docked				a219ee423280450f9e7aff22300ebd9e
49:28.6	Video deleted from device when docked	88	12	52.269	a219ee423280450f9e7aff22300ebd9e
49:28.8	Video upload started when camera was docked				fc89c6eecae44d159426722171db791a
50:35.8	Video successfully uploaded from device when docked				fc89c6eecae44d159426722171db791a
50:36.1	Video deleted from device when docked	89	11	52.507	fc89c6eecae44d159426722171db791a
50:36.3	Video upload started when camera was docked				8289e741e2b14a5db2f7f2a9cab14193
51:22.4	Video successfully uploaded from device when docked				8289e741e2b14a5db2f7f2a9cab14193
51:22.7	Video deleted from device when docked	89	10	52.67	8289e741e2b14a5db2f7f2a9cab14193
51:22.9	Video upload started when camera was docked				266f9d96865a464ca0d44cbeba6203ed
52:18.9	Video successfully uploaded from device when docked				266f9d96865a464ca0d44cbeba6203ed
52:19.2	Video deleted from device when docked	90	9	52.863	266f9d96865a464ca0d44cbeba6203ed
52:19.4	Video upload started when camera was docked				e9645bedd59945cb95daeb252754a0f7
52:38.4	Video successfully uploaded from device when docked				e9645bedd59945cb95daeb252754a0f7
52:38.5	Video deleted from device when docked	90	8	52.926	e9645bedd59945cb95daeb252754a0f7
52:38.7	Video upload started when camera was docked				d80eb7f5707b403e8f4a85e4595ea24b
53:01.8	Video successfully uploaded from device when docked				d80eb7f5707b403e8f4a85e4595ea24b
53:02.1	Video deleted from device when docked	90	7	53.009	d80eb7f5707b403e8f4a85e4595ea24b
53:02.3	Video upload started when camera was docked				a39d2c77fba649d78f2079a5da1218c4
53:38.8	Video successfully uploaded from device when docked				a39d2c77fba649d78f2079a5da1218c4
53:39.1	Video deleted from device when docked	90	6	53.136	a39d2c77fba649d78f2079a5da1218c4
53:39.3	Video upload started when camera was docked				8a5fda29774449e8ad8a4d63ff00e3c5
56:13.1	Video successfully uploaded from device when docked				8a5fda29774449e8ad8a4d63ff00e3c5
56:13.5	Video deleted from device when docked	92	5	53.674	8a5fda29774449e8ad8a4d63ff00e3c5
56:13.7	Video upload started when camera was docked				9823e23f7c954a51bb75d2650bb9b4de
57:29.0	Video successfully uploaded from device when docked				9823e23f7c954a51bb75d2650bb9b4de
57:29.3	Video deleted from device when docked	92	4	53.941	9823e23f7c954a51bb75d2650bb9b4de
57:29.6	Video upload started when camera was docked				258bdaf182684f4e8b9714089b8d1a49
58:06.9	Video successfully uploaded from device when docked				258bdaf182684f4e8b9714089b8d1a49
58:07.2	Video deleted from device when docked	92	3	54.073	258bdaf182684f4e8b9714089b8d1a49
58:07.4	Video upload started when camera was docked				1f3e5a18331d46c195a145f9682fd235
03:22.7	Video successfully uploaded from device when docked				1f3e5a18331d46c195a145f9682fd235
03:23.2	Video deleted from device when docked	94	2	55.208	1f3e5a18331d46c195a145f9682fd235
03:23.6	Video upload started when camera was docked				71aa3068255c4f5abdbad38af9950d89
04:38.2	Video successfully uploaded from device when docked				71aa3068255c4f5abdbad38af9950d89
04:38.5	Video deleted from device when docked	95	1	55.478	71aa3068255c4f5abdbad38af9950d89

04:38.7	Video upload started when camera was docked			eea361daf5904b5fad536c99d01ac624
05:47.1	Video successfully uploaded from device when docked			eea361daf5904b5fad536c99d01ac624
05:47.4	Video deleted from device when docked	95	0	55.715 eea361daf5904b5fad536c99d01ac624
05:47.5	Audit log created	95	0 1.12.23	55.715
05:47.5	Audit log rolled	95	0	55.715
18:37.0	Date/Time synced to 05/18/2021 06:18:37.02 PM from 05/18/2021 06:18:37.02 PM			
29:36.9	Camera disconnected from Axon Dock X62001W9H	100	0	55.715
29:37.3	Device disconnected from charger	100	0	55.716
05:46.9	Audit log created	95	0 1.12.23	55.715
59:07.6	Power button pressed			
59:10.6	Device powered off using button	89	0	55.714
59:11.1	Power button released			
11:03.8	Audit log created		1.12.23	
11:03.9	Device powered on due to charger connection	90	0	55.713
11:04.0	Device connected to charger			
11:04.0	Audit log created		1.12.23	
11:04.0	Audit log rolled			
11:04.0	Camera connected to Axon Dock X630020W7	90	0	55.713
11:04.9	Camera connected to Axon Dock X630020W7	90	0	55.713
11:06.8	Audit log created	89	0 1.12.23	55.713
11:06.8	Audit log rolled	89	0	55.713
11:06.0	Audit log created	100	0 1.12.23	55.712
11:06.0	Audit log created	100	0 1.12.23	55.712
11:06.0	Audit log created	100	0 1.12.23	55.712
11:06.0	Audit log created	100	0 1.12.23	55.712
11:06.0	Audit log created	100	0 1.12.23	55.711
11:06.0	Audit log created	100	0 1.12.23	55.711
11:06.0	Audit log created	100	0 1.12.23	55.711
11:06.0	Audit log created	100	0 1.12.23	55.711
11:06.1	Audit log created	100	0 1.12.23	55.711
11:06.1	Audit log created	100	0 1.12.23	55.711
11:06.1	Audit log created	100	0 1.12.23	55.713
11:06.1	Audit log created	100	0 1.12.23	55.713
59:10.7	Camera disconnected from Axon Dock X630020W7	99	0	55.712
59:10.8	Audio recording disabled due to video buffering default			
59:10.9	Device disconnected from charger	99	0	55.713
59:22.3	Power button pressed			
59:25.3	Device powered off using button	100	0	55.713
59:25.9	Power button released			
05:25.0	Audit log created		1.12.23	
05:25.1	Device connected to charger			
05:25.1	Device powered on due to charger connection	100	0	55.713
05:25.1	Camera connected to Axon Dock X630020W7	100	0	55.713
05:25.1	Audit log created		1.12.23	
05:25.1	Audit log rolled			
05:26.0	Camera connected to Axon Dock X630020W7	100	0	55.713
05:28.0	Audit log created	100	0 1.12.23	55.713

05:28.0 Audit log rolled	100	0	55.713
05:27.0 Audit log created	100	0 1.12.23	55.713
05:27.0 Audit log created	100	0 1.12.23	55.713
05:27.0 Audit log created	100	0 1.12.23	55.713
05:27.0 Audit log created	100	0 1.12.23	55.712
05:27.0 Audit log created	100	0 1.12.23	55.712
05:27.0 Audit log created	100	0 1.12.23	55.712
05:27.0 Audit log created	100	0 1.12.23	55.712
05:27.1 Audit log created	100	0 1.12.23	55.711
05:27.1 Audit log created	100	0 1.12.23	55.711
05:27.1 Audit log created	100	0 1.12.23	55.711
05:27.1 Audit log created	100	0 1.12.23	55.711
05:27.1 Audit log created	100	0 1.12.23	55.71
05:27.1 Audit log created	100	0 1.12.23	55.71
05:27.1 Audit log created	100	0 1.12.23	55.71
05:27.1 Audit log created	100	0 1.12.23	55.71
05:27.1 Audit log created	100	0 1.12.23	55.709
05:27.1 Audit log created	100	0 1.12.23	55.709
05:27.1 Audit log created	100	0 1.12.23	55.709
05:27.1 Audit log created	100	0 1.12.23	55.709
05:27.1 Audit log created	100	0 1.12.23	55.708
05:27.1 Audit log created	100	0 1.12.23	55.708
18:55.9 Camera disconnected from Axon Dock X630020W7	98	0	55.708
18:56.1 Device disconnected from charger	98	0	55.708
18:56.1 Audio recording disabled due to video buffering default			
19:11.5 Power button pressed			
19:14.5 Device powered off using button	100	0	55.708
19:14.8 Power button released			
48:53.1 Audit log created		1.12.23	
48:53.2 Device powered on using button	100	0	55.707
48:56.2 Audio recording disabled due to video buffering default			
48:53.1 Audit log created	92	0 1.12.23	55.706
48:53.1 Audit log created	86	0 1.12.23	55.705
18:13.5 Volume up button pressed			
18:14.5 Volume up button released			
25:47.3 Volume up button pressed			
25:47.4 Volume up button released			
25:59.6 Volume up button pressed			
25:59.7 Volume up button released			
48:53.1 Audit log created	80	0 1.12.23	55.703
48:53.1 Audit log created	73	0 1.12.23	55.702
48:53.1 Audit log created	66	0 1.12.23	55.701
36:07.5 Event button pressed			
36:08.2 Event button released			
48:53.1 Audit log created	59	0 1.12.23	55.699
22:26.9 Power button pressed			
22:29.9 Device powered off using button	55	0	55.699

22:30.3	Power button released			
22:31.2	Volume up button pressed			
22:31.6	Volume up button released			
22:31.6	Volume up button pressed			
22:31.8	Volume up button released			
22:34.7	Audit log rolled	55	0	55.699
22:34.7	Audit log created	55	0 1.12.23	55.699
22:36.2	Device connected to charger	55	0	55.699
23:19.0	Device powered on due to charger connection	55	0	55.698
23:19.0	Device connected to charger			
23:19.0	Camera connected to Axon Dock X630020W7	55	0	55.698
23:19.1	Audit log created		1.12.23	
23:19.1	Audit log rolled			
23:20.0	Camera connected to Axon Dock X630020W7	55	0	55.698
23:21.9	Audit log rolled	55	0	55.698
23:21.9	Audit log created	55	0 1.12.23	55.698
23:21.0	Audit log created	82	0 1.12.23	55.697
23:21.0	Audit log created	100	0 1.12.23	55.697
23:21.0	Audit log created	100	0 1.12.23	55.697
23:21.0	Audit log created	100	0 1.12.23	55.696
23:21.0	Audit log created	100	0 1.12.23	55.696
23:21.0	Audit log created	100	0 1.12.23	55.696
23:21.0	Audit log created	100	0 1.12.23	55.697
23:21.1	Audit log created	100	0 1.12.23	55.698
23:21.1	Audit log created	100	0 1.12.23	55.697
23:21.1	Audit log created	100	0 1.12.23	55.697
23:21.1	Audit log created	100	0 1.12.23	55.697
23:21.1	Audit log created	100	0 1.12.23	55.696
02:50.6	Camera disconnected from Axon Dock X630020W7	98	0	55.696
02:50.7	Audio recording disabled due to video buffering default			
02:51.0	Device disconnected from charger	100	0	55.7
03:13.9	Power button pressed			
03:17.0	Device powered off using button	100	0	55.7
03:17.4	Power button released			
16:15.9	Audit log created		1.12.23	
16:16.0	Device powered on using button	100	0	55.699
16:18.0	Audio recording disabled due to video buffering default			
16:16.0	Audit log created	92	0 1.12.23	55.698
16:16.0	Audit log created	86	0 1.12.23	55.696
16:16.0	Audit log created	79	0 1.12.23	55.695
16:16.0	Audit log created	73	0 1.12.23	55.693
16:16.0	Audit log created	66	0 1.12.23	55.692
16:16.0	Audit log created	60	0 1.12.23	55.691
16:16.0	Audit log created	52	0 1.12.23	55.689
17:13.5	Power button pressed			
17:16.5	Device powered off using button	51	0	55.689
17:17.1	Power button released			

07:37.8	Audit log created		1.12.23	
07:38.0	Device connected to charger			
07:38.0	Device powered on due to charger connection	52	0	55.689
07:38.0	Camera connected to Axon Dock X630020W7	52	0	55.689
07:38.0	Audit log created		1.12.23	
07:38.0	Audit log rolled			
07:38.9	Camera connected to Axon Dock X630020W7	52	0	55.689
07:40.8	Audit log created	52	0	1.12.23
07:40.8	Audit log rolled	52	0	55.689
30:09.9	Camera disconnected from Axon Dock X630020W7	62	0	55.688
30:10.0	Device disconnected from charger	62	0	55.688
30:10.0	Audio recording disabled due to video buffering default			
07:40.0	Audit log created	59	0	1.12.23
48:17.9	Power button pressed			
48:20.9	Device powered off using button	53	0	55.691
48:21.5	Power button released			
48:22.6	Volume up button pressed			
48:22.7	Volume up button released			
48:26.5	Audit log created	53	0	1.12.23
48:26.5	Audit log rolled	53	0	55.691
49:15.0	Device connected to charger			
49:15.0	Device powered on due to charger connection	53	0	55.69
49:15.0	Camera connected to Axon Dock X630020W7	53	0	55.69
49:15.1	Audit log rolled			
49:15.1	Audit log created		1.12.23	
49:16.0	Camera connected to Axon Dock X630020W7	54	0	55.69
49:17.9	Audit log created	53	0	1.12.23
49:17.9	Audit log rolled	53	0	55.69
49:17.0	Audit log created	81	0	1.12.23
49:17.0	Audit log created	100	0	1.12.23
49:17.0	Audit log created	100	0	1.12.23
49:17.1	Audit log created	100	0	1.12.23
49:17.1	Audit log created	100	0	1.12.23
49:56.0	Select button pressed			
49:56.2	Select button released			
49:56.9	Camera disconnected from Axon Dock X630020W7	100	0	55.689
49:57.0	Device disconnected from charger	100	0	55.689
49:57.1	Audio recording disabled due to video buffering default			
50:08.7	Power button pressed			
50:11.7	Device powered off using button	100	0	55.689
50:12.0	Power button released			
58:25.0	Audit log created		1.12.23	
58:25.0	Device powered on using button	100	0	55.689
58:27.0	Audio recording disabled due to video buffering default			
58:25.0	Audit log created	92	0	1.12.23
01:07.7	Select button pressed			
01:07.8	Select button released			

35:25.0 Event button pressed			
35:25.3 Event button released			
35:25.5 Event button pressed			
35:25.5 Audio recording enabled due to video recording default			
35:25.6 Event button released			
35:25.7 Recording started due to button press	89	0	55.686 d136afd5c0c54049a8b0833c2efa6553
37:12.4 Event button pressed			
37:15.4 Recording stopped due to button press	88	1	55.568 d136afd5c0c54049a8b0833c2efa6553
37:15.9 Event button released			
37:16.2 Audio recording disabled due to video buffering default			
46:26.9 Volume up button pressed			
46:27.0 Volume up button released			
47:09.3 Volume up button pressed			
47:09.5 Volume up button released			
55:54.3 Event button pressed			
55:54.4 Event button released			
55:54.6 Event button pressed			
55:54.7 Audio recording enabled due to video recording default			
55:54.8 Event button released			
55:54.8 Recording started due to button press	86	2	55.567 af66d7e3322548c9a7627d09fa58d76a
56:37.1 Event button pressed			
56:40.1 Recording stopped due to button press	86	2	55.483 af66d7e3322548c9a7627d09fa58d76a
56:40.8 Event button released			
56:41.0 Audio recording disabled due to video buffering default			
58:25.0 Audit log created	85	2 1.12.23	55.482
58:49.0 Axon application connected to device			
59:39.1 Axon application connected to device			
00:01.7 Categories 'Fare Evasion' added to video metadata using Axon application			d136afd5c0c54049a8b0833c2efa6553
01:11.9 Title changed in video metadata from '' to 'Sig. 19 Bus 1657 Route 12 Bl. 01' using Axon applicator			d136afd5c0c54049a8b0833c2efa6553
01:40.8 Categories 'Sleeper' added to video metadata using Axon applicator			af66d7e3322548c9a7627d09fa58d76a
01:41.0 Video played back using Axon application			af66d7e3322548c9a7627d09fa58d76a
01:57.7 Title changed in video metadata from '' to 'Sig 31 At N5' using Axon applicator			af66d7e3322548c9a7627d09fa58d76a
02:08.2 Axon application disconnected from device			
26:32.1 Event button pressed			
26:32.2 Event button released			
26:32.3 Event button pressed			
26:32.3 Audio recording enabled due to video recording default			
26:32.4 Event button released			
26:32.5 Recording started due to button press	83	3	55.481 83587336141042e0992d5cafd41ca4ca
28:16.2 Event button pressed			
28:19.2 Recording stopped due to button press	82	3	55.364 83587336141042e0992d5cafd41ca4ca
28:19.6 Event button released			
28:20.2 Audio recording disabled due to video buffering default			
29:07.1 Event button pressed			
29:07.2 Event button released			
29:07.3 Event button pressed			
29:07.4 Audio recording enabled due to video recording default			

29:07.5	Event button released			
29:07.5	Recording started due to button press	82	4	55.363 40fdbba0e72344cb8f8496be36a05e4f
31:09.7	Event button pressed			
31:12.7	Recording stopped due to button press	82	4	55.274 40fdbba0e72344cb8f8496be36a05e4f
31:13.2	Event button released			
31:13.4	Audio recording disabled due to video buffering default			
38:52.8	Event button pressed			
38:53.0	Event button released			
38:53.1	Event button pressed			
38:53.1	Audio recording enabled due to video recording default			
38:53.2	Event button released			
38:53.3	Recording started due to button press	81	5	55.273 fe3a0ddf9cd6424283f5690cee2275bd
40:57.0	Event button pressed			
41:00.0	Recording stopped due to button press	81	5	55.146 fe3a0ddf9cd6424283f5690cee2275bd
41:00.5	Event button released			
41:00.9	Audio recording disabled due to video buffering default			
45:29.1	Axon application connected to device			
46:03.1	Categories 'Person Wayside' added to video metadata using Axon applicator			83587336141042e0992d5cafd41ca4ca
46:09.4	Title changed in video metadata from '' to 'Code 22' using Axon applicator			83587336141042e0992d5cafd41ca4ca
46:24.4	Categories 'Loitering' added to video metadata using Axon applicator			40fdbba0e72344cb8f8496be36a05e4f
46:42.7	Categories 'Sleeper' added to video metadata using Axon applicator			fe3a0ddf9cd6424283f5690cee2275bd
46:57.3	Axon application disconnected from device			
58:25.0	Audit log created	79	5 1.12.23	55.144
01:27.5	Volume up button pressed			
01:27.7	Volume up button released			
01:28.0	Volume up button pressed			
01:28.3	Volume up button released			
04:26.3	Volume up button pressed			
04:26.4	Volume up button released			
29:41.6	Volume up button pressed			
29:41.8	Volume up button released			
49:41.7	Volume up button pressed			
49:41.8	Volume up button released			
58:25.0	Audit log created	73	5 1.12.23	55.143
05:33.9	Volume up button pressed			
05:33.9	Volume up button released			
58:25.0	Audit log created	66	5 1.12.23	55.141
52:29.3	Volume up button pressed			
52:29.4	Volume up button released			
56:07.9	Volume up button pressed			
56:08.0	Volume up button released			
56:25.2	Volume up button pressed			
56:25.4	Volume up button released			
57:04.8	Volume up button pressed			
57:05.1	Volume up button released			
58:25.0	Audit log created	61	5 1.12.23	55.14
59:49.2	Volume up button pressed			

59:49.3	Volume up button released			
58:25.0	Audit log created	53	5 1.12.23	55.139
29:55.2	Power button pressed			
29:58.2	Device powered off using button	49	5	55.138
29:58.6	Power button released			
30:00.4	Audit log created	49	5 1.12.23	55.138
30:00.4	Audit log rolled	49	5	55.138
30:01.1	Device connected to charger	49	5	55.138
30:47.1	Device powered on due to charger connection	50	5	55.138
30:47.1	Device connected to charger			
30:47.1	Camera connected to Axon Dock X630020W7	50	5	55.138
30:47.2	Audit log rolled			
30:47.2	Audit log created		1.12.23	
30:48.0	Camera connected to Axon Dock X630020W7	50	5	55.138
30:50.0	Audit log created	50	5 1.12.23	55.138
30:50.0	Audit log rolled	50	5	55.138
30:49.0	Audit log created	78	5 1.12.23	55.137
30:49.0	Audit log created	100	5 1.12.23	55.137
30:49.0	Audit log created	100	5 1.12.23	55.136
30:49.0	Audit log created	100	5 1.12.23	55.136
30:49.1	Audit log created	100	5 1.12.23	55.136
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.135
30:49.1	Audit log created	100	5 1.12.23	55.134
30:49.1	Audit log created	100	5 1.12.23	55.134
30:49.1	Audit log created	100	5 1.12.23	55.134
53:53.1	Device disconnected from charger	98	5	55.134
53:53.6	Camera disconnected from Axon Dock X630020W7	98	5	55.134
53:53.7	Audio recording disabled due to video buffering default			
54:11.4	Power button pressed			
54:14.4	Device powered off using button	100	5	55.139
54:14.9	Power button released			
59:12.1	Audit log created		1.12.23	
59:12.2	Device powered on using button	100	5	55.138
59:14.2	Audio recording disabled due to video buffering default			
55:05.4	Volume up button pressed			
55:05.8	Volume up button released			
59:12.1	Audit log created	92	5 1.12.23	55.137
00:41.9	Volume up button pressed			
00:42.3	Volume up button released			
17:18.8	Volume up button pressed			
17:19.8	Volume up button released			
59:12.1	Audit log created	86	5 1.12.23	55.135
23:24.9	Volume up button pressed			

23:25.0	Volume up button released			
24:05.9	Volume up button pressed			
24:06.0	Volume up button released			
49:00.4	Event button pressed			
49:00.6	Event button released			
49:00.7	Event button pressed			
49:00.8	Audio recording enabled due to video recording default			
49:00.9	Event button released			
49:01.0	Recording started due to button press	81	6	55.134 4ea159da3a0d4eec9a201466c52bbd96
51:28.9	Event button pressed			
51:31.9	Recording stopped due to button press	80	6	54.994 4ea159da3a0d4eec9a201466c52bbd96
51:32.3	Event button released			
51:32.7	Audio recording disabled due to video buffering default			
52:01.6	Event button pressed			
52:01.8	Event button released			
52:01.9	Event button pressed			
52:01.9	Audio recording enabled due to video recording default			
52:02.1	Event button released			
52:02.1	Recording started due to button press	80	7	54.993 bff9ed722a1d4983b493f50e384e9320
59:12.1	Audit log created	79	7 1.12.23	54.752
27:22.6	Event button pressed			
27:25.6	Recording stopped due to button press	74	7	53.861 bff9ed722a1d4983b493f50e384e9320
27:26.4	Event button released			
27:26.4	Audio recording disabled due to video buffering default			
35:37.3	Axon application connected to device			
36:11.6	Categories 'Loitering' added to video metadata using Axon applicator			4ea159da3a0d4eec9a201466c52bbd96
37:08.2	Categories 'Wagon Call', 'Criminal Trespass' added to video metadata using Axon applicator			bff9ed722a1d4983b493f50e384e9320
37:42.5	Axon application disconnected from device			
59:12.3	Audit log created	71	7 1.12.23	53.855
56:44.8	Volume up button pressed			
56:45.5	Volume up button released			
59:12.3	Audit log created	64	7 1.12.23	53.854
59:12.3	Audit log created	58	7 1.12.23	53.852
59:12.3	Audit log created	51	7 1.12.23	53.851
02:07.0	Volume up button pressed			
02:07.6	Volume up button released			
19:12.2	Volume up button pressed			
19:12.3	Volume up button released			
36:09.8	Power button pressed			
36:12.9	Device powered off using button	46	7	53.85
36:13.5	Power button released			
36:15.3	Volume up button pressed			
36:15.4	Volume up button released			
36:19.7	Volume up button pressed			
36:19.9	Audit log rolled	46	7	53.85
36:19.9	Audit log created	46	7 1.12.23	53.85
36:19.9	Volume up button released			

36:21.2 Device connected to charger	46	7	53.85
37:18.0 Device connected to charger			
37:18.0 Device powered on due to charger connection	47	7	53.85
37:18.1 Camera connected to Axon Dock X630020W7	47	7	53.85
37:18.1 Audit log rolled			
37:18.1 Audit log created		1.12.23	
37:19.0 Camera connected to Axon Dock X630020W7	47	7	53.85
37:20.9 Audit log created	47	7 1.12.23	53.85
37:20.9 Audit log rolled	47	7	53.85
37:20.0 Audit log created	75	7 1.12.23	53.849
37:20.0 Audit log created	98	7 1.12.23	53.848
37:20.0 Audit log created	100	7 1.12.23	53.848
37:20.0 Audit log created	100	7 1.12.23	53.848
37:20.1 Audit log created	100	7 1.12.23	53.848
37:20.1 Audit log created	100	7 1.12.23	53.847
37:20.1 Audit log created	100	7 1.12.23	53.847
37:20.1 Audit log created	100	7 1.12.23	53.847
37:20.1 Audit log created	100	7 1.12.23	53.847
37:20.1 Audit log created	100	7 1.12.23	53.846
37:20.1 Audit log created	100	7 1.12.23	53.846
37:20.1 Audit log created	100	7 1.12.23	53.846
52:53.0 Select button pressed			
52:53.0 Device disconnected from charger	98	7	53.846
52:53.2 Select button released			
52:53.3 Camera disconnected from Axon Dock X630020W7	98	7	53.846
52:53.5 Audio recording disabled due to video buffering default			
53:12.8 Power button pressed			
53:15.8 Device powered off using button	100	7	53.851
53:16.2 Power button released			
27:21.3 Audit log created		1.12.23	
27:21.3 Device powered on using button	100	7	53.85
27:24.3 Audio recording disabled due to video buffering default			
27:21.3 Audit log created	92	7 1.12.23	53.849
27:21.3 Audit log created	86	7 1.12.23	53.847
10:13.2 Volume up button pressed			
10:13.2 Volume up button released			
27:21.3 Audit log created	80	7 1.12.23	53.846
27:21.3 Audit log created	73	7 1.12.23	53.845
27:21.3 Audit log created	66	7 1.12.23	53.843
45:39.1 Power button pressed			
45:42.1 Device powered off using button	64	7	53.843
45:42.4 Power button released			
47:54.0 Device powered on due to charger connection	65	7	53.845
47:54.0 Device connected to charger			
47:54.1 Camera connected to Axon Dock X630020W7	65	7	53.845
47:54.1 Audit log created		1.12.23	
47:54.1 Audit log rolled			

47:55.0 Camera connected to Axon Dock X630020W7	65	7	53.845
47:56.9 Audit log rolled	65	7	53.845
47:56.9 Audit log created	65	7 1.12.23	53.845
47:56.0 Audit log created	92	7 1.12.23	53.844
47:56.0 Audit log created	100	7 1.12.23	53.844
47:56.0 Audit log created	100	7 1.12.23	53.844
47:56.0 Audit log created	100	7 1.12.23	53.844
47:56.1 Audit log created	100	7 1.12.23	53.844
47:56.1 Audit log created	100	7 1.12.23	53.843
47:56.1 Audit log created	100	7 1.12.23	53.843
47:56.1 Audit log created	100	7 1.12.23	53.843
47:56.1 Audit log created	100	7 1.12.23	53.842
47:56.1 Audit log created	100	7 1.12.23	53.842
47:56.1 Audit log created	100	7 1.12.23	53.842
47:56.2 Audit log created	100	7 1.12.23	53.842
47:56.2 Audit log created	100	7 1.12.23	53.841
47:56.2 Audit log created	100	7 1.12.23	53.842
47:56.2 Audit log created	100	7 1.12.23	53.844
47:56.2 Audit log created	100	7 1.12.23	53.844
47:56.2 Audit log created	100	7 1.12.23	53.844
47:56.3 Audit log created	100	7 1.12.23	53.844
47:56.3 Audit log created	100	7 1.12.23	53.844
47:56.3 Audit log created	100	7 1.12.23	53.844
47:56.3 Audit log created	100	7 1.12.23	53.843
47:56.3 Audit log created	100	7 1.12.23	53.843
47:56.4 Audit log created	100	7 1.12.23	53.843
47:56.4 Audit log created	100	7 1.12.23	53.848
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.4 Audit log created	100	7 1.12.23	53.847
47:56.5 Audit log created	100	7 1.12.23	53.846
47:56.5 Audit log created	100	7 1.12.23	53.846
47:56.5 Audit log created	100	7 1.12.23	53.846
48:08.1 Device disconnected from charger	99	7	53.846
48:08.5 Camera disconnected from Axon Dock X630020W7	99	7	53.846
48:08.6 Audio recording disabled due to video buffering default			
48:11.3 Power button pressed			
48:14.3 Device powered off using button	100	7	53.849
48:14.8 Power button released			
17:08.0 Audit log created		1.12.23	
17:08.0 Device connected to charger			
17:08.0 Device powered on due to charger connection	100	7	53.849
17:08.1 Camera connected to Axon Dock X630020W7	100	7	53.849
17:08.1 Audit log rolled			

17:08.1 Audit log created		1.12.23	
17:09.0 Camera connected to Axon Dock X630020W7	100	7	53.849
17:10.9 Audit log created	100	7 1.12.23	53.849
17:10.9 Audit log rolled	100	7	53.849
17:10.0 Audit log created	100	7 1.12.23	53.848
17:10.0 Audit log created	100	7 1.12.23	53.848
17:10.0 Audit log created	100	7 1.12.23	53.848
17:10.0 Audit log created	100	7 1.12.23	53.848
17:10.1 Audit log created	100	7 1.12.23	53.848
17:10.1 Audit log created	100	7 1.12.23	53.848
17:10.1 Audit log created	100	7 1.12.23	53.853
17:10.1 Audit log created	100	7 1.12.23	53.854
17:10.1 Audit log created	100	7 1.12.23	53.854
17:10.1 Audit log created	100	7 1.12.23	53.853
17:10.1 Audit log created	100	7 1.12.23	53.853
17:10.2 Audit log created	100	7 1.12.23	53.853
17:10.2 Audit log created	100	7 1.12.23	53.853
17:10.2 Audit log created	100	7 1.12.23	53.853
17:10.2 Audit log created	100	7 1.12.23	53.853
17:10.2 Audit log created	100	7 1.12.23	53.852
17:10.2 Audit log created	100	7 1.12.23	53.852
17:10.2 Audit log created	100	7 1.12.23	53.852
17:10.3 Audit log created	100	7 1.12.23	53.852
17:10.3 Audit log created	100	7 1.12.23	53.851
17:10.3 Audit log created	100	7 1.12.23	53.851
17:10.3 Audit log created	100	7 1.12.23	53.851
17:10.3 Audit log created	100	7 1.12.23	53.851
17:10.3 Audit log created	100	7 1.12.23	53.853
17:10.4 Audit log created	100	7 1.12.23	53.852
17:10.4 Audit log created	100	7 1.12.23	53.852
17:10.4 Audit log created	100	7 1.12.23	53.852
17:10.5 Audit log created	100	7 1.12.23	53.852
17:10.5 Audit log created	100	7 1.12.23	53.852
17:10.5 Audit log created	100	7 1.12.23	53.851
17:10.5 Audit log created	100	7 1.12.23	53.851
17:10.5 Audit log created	100	7 1.12.23	53.851
17:10.6 Audit log created	100	7 1.12.23	53.85
17:10.6 Audit log created	100	7 1.12.23	53.85
17:10.6 Audit log created	100	7 1.12.23	53.85
17:10.6 Audit log created	100	7 1.12.23	53.85
17:10.6 Audit log created	100	7 1.12.23	53.849
17:10.6 Audit log created	100	7 1.12.23	53.849
17:10.6 Audit log created	100	7 1.12.23	53.849
17:10.7 Audit log created	100	7 1.12.23	53.849
17:10.7 Audit log created	100	7 1.12.23	53.848
17:10.7 Audit log created	100	7 1.12.23	53.848

17:10.7	Audit log created	100	7 1.12.23	53.848
17:10.7	Audit log created	100	7 1.12.23	53.848
17:10.7	Audit log created	100	7 1.12.23	53.847
17:10.7	Audit log created	100	7 1.12.23	53.847
54:18.6	Camera disconnected from Axon Dock X630020W7	98	7	53.847
54:18.8	Audio recording disabled due to video buffering default			
54:19.0	Device disconnected from charger	98	7	53.847
54:27.1	Power button pressed			
54:29.8	Power button released			
54:34.5	Power button pressed			
54:37.5	Device powered off using button	100	7	53.847
54:38.0	Power button released			
27:40.0	Audit log created		1.12.23	
27:40.1	Device powered on using button	100	7	53.846
27:42.0	Audio recording disabled due to video buffering default			
27:40.0	Audit log created	92	7 1.12.23	53.845
27:40.0	Audit log created	85	7 1.12.23	53.843
27:40.0	Audit log created	79	7 1.12.23	53.842
27:40.1	Audit log created	73	7 1.12.23	53.841
24:42.1	Volume up button pressed			
24:42.1	Volume up button released			
27:40.1	Audit log created	65	7 1.12.23	53.839
16:02.2	Volume up button pressed			
16:02.3	Volume up button released			
16:03.3	Volume up button pressed			
16:03.7	Volume up button released			
17:55.5	Power button pressed			
17:58.5	Device powered off using button	60	7	53.838
17:59.0	Power button released			
09:28.0	Audit log created		1.12.23	
09:28.0	Device connected to charger			
09:28.0	Device powered on due to charger connection	60	7	53.838
09:28.1	Camera connected to Axon Dock X630020W7	61	7	53.838
09:28.1	Audit log rolled			
09:28.1	Audit log created		1.12.23	
09:29.0	Camera connected to Axon Dock X630020W7	61	7	53.838
09:31.0	Audit log rolled	60	7	53.838
09:31.0	Audit log created	60	7 1.12.23	53.838
09:30.0	Audit log created	87	7 1.12.23	53.837
09:30.0	Audit log created	100	7 1.12.23	53.837
09:30.1	Audit log created	100	7 1.12.23	53.836
09:30.1	Audit log created	100	7 1.12.23	53.836
09:30.1	Audit log created	100	7 1.12.23	53.836
09:30.1	Audit log created	100	7 1.12.23	53.836
09:30.1	Audit log created	100	7 1.12.23	53.835
09:30.1	Audit log created	100	7 1.12.23	53.835
09:30.2	Audit log created	100	7 1.12.23	53.835

09:30.2 Audit log created	100	7 1.12.23	53.835
23:29.8 Camera disconnected from Axon Dock X630020W7	100	7	53.835
23:30.0 Audio recording disabled due to video buffering default			
23:30.0 Device disconnected from charger	100	7	53.838
09:30.2 Audit log created	94	7 1.12.23	53.837
09:30.2 Audit log created	88	7 1.12.23	53.836
09:30.2 Audit log created	82	7 1.12.23	53.834
09:30.3 Audit log created	76	7 1.12.23	53.833
09:30.3 Audit log created	70	7 1.12.23	53.831
09:30.3 Audit log created	63	7 1.12.23	53.83
09:30.3 Audit log created	56	7 1.12.23	53.828
09:30.3 Audit log created	49	7 1.12.23	53.827
09:30.4 Audit log created	42	7 1.12.23	53.826
09:30.4 Audit log created	36	7 1.12.23	53.824
09:30.4 Audit log created	30	7 1.12.23	53.823
09:30.4 Audit log created	24	7 1.12.23	53.822
39:57.6 Camera connected to Axon Dock X630020W7	21	7	53.821
39:57.6 Audit log rolled	20	7	53.821
39:57.6 Audit log created	20	7 1.12.23	53.821
39:58.0 Device connected to charger	20	7	53.821
39:57.0 Audit log created	47	7 1.12.23	53.821
39:57.0 Audit log created	73	7 1.12.23	53.82
39:57.1 Audit log created	97	7 1.12.23	53.819
39:57.1 Audit log created	100	7 1.12.23	53.819
39:57.1 Audit log created	100	7 1.12.23	53.819
39:57.2 Audit log created	100	7 1.12.23	53.818
39:57.2 Audit log created	100	7 1.12.23	53.818
39:57.2 Audit log created	100	7 1.12.23	53.818
39:57.2 Audit log created	100	7 1.12.23	53.817
48:09.6 Select button pressed			
48:09.7 Camera disconnected from Axon Dock X630020W7	98	7	53.817
48:09.8 Select button released			
48:10.0 Device disconnected from charger	98	7	53.825
48:12.0 Power button pressed			
48:15.0 Device powered off using button	100	7	53.825
48:15.6 Power button released			
54:55.1 Audit log created		1.12.23	
54:55.2 Device powered on using button	100	7	53.824
54:58.2 Audio recording disabled due to video buffering default			
55:04.7 Power button pressed			
55:07.8 Device powered off using button	100	7	53.824
55:08.2 Power button released			
29:56.0 Audit log created		1.12.23	
29:56.1 Device powered on using button	100	7	53.823
29:58.0 Audio recording disabled due to video buffering default			
29:56.0 Audit log created	92	7 1.12.23	53.822

29:56.0 Audit log created	85	7 1.12.23	53.821
29:56.0 Audit log created	79	7 1.12.23	53.819
29:56.0 Audit log created	73	7 1.12.23	53.818
06:28.2 Power button pressed			
06:30.4 Power button released			
08:26.4 Power button pressed			
08:29.5 Device powered off using button	68	7	53.817
08:30.0 Power button released			
51:25.0 Audit log created		1.12.23	
51:25.0 Device powered on due to charger connection	68	7	53.817
51:25.0 Device connected to charger			
51:25.1 Camera connected to Axon Dock X630020W7	68	7	53.817
51:25.1 Audit log rolled			
51:25.1 Audit log created		1.12.23	
51:26.0 Camera connected to Axon Dock X630020W7	69	7	53.817
51:27.9 Audit log rolled	68	7	53.817
51:27.9 Audit log created	68	7 1.12.23	53.817
51:27.0 Audit log created	95	7 1.12.23	53.816
51:27.0 Audit log created	100	7 1.12.23	53.816
51:27.1 Audit log created	100	7 1.12.23	53.815
51:27.1 Audit log created	100	7 1.12.23	53.815
51:27.1 Audit log created	100	7 1.12.23	53.815
51:27.1 Audit log created	100	7 1.12.23	53.815
51:27.1 Audit log created	100	7 1.12.23	53.814
51:27.2 Audit log created	100	7 1.12.23	53.814
51:27.2 Audit log created	100	7 1.12.23	53.814
51:27.2 Audit log created	100	7 1.12.23	53.814
51:27.2 Audit log created	100	7 1.12.23	53.813
51:27.2 Audit log created	100	7 1.12.23	53.813
51:27.2 Audit log created	100	7 1.12.23	53.813
51:27.3 Audit log created	100	7 1.12.23	53.813
51:27.3 Audit log created	100	7 1.12.23	53.813
51:27.3 Audit log created	100	7 1.12.23	53.812
51:27.3 Audit log created	100	7 1.12.23	53.812
54:43.0 Device disconnected from charger	98	7	53.812
54:43.6 Camera disconnected from Axon Dock X630020W7	98	7	53.812
54:43.8 Audio recording disabled due to video buffering default			
54:54.1 Select button pressed			
54:54.2 Select button released			
54:57.4 Power button pressed			
55:00.4 Device powered off using button	100	7	53.815
55:00.8 Power button released			
04:31.0 Audit log created		1.12.23	
04:31.0 Device powered on using button	100	7	53.814
04:33.0 Audio recording disabled due to video buffering default			
29:06.1 Power button pressed			
29:09.1 Device powered off using button	96	7	53.813

29:09.5	Power button released			
53:03.3	Audit log created		1.12.23	
53:03.3	Device powered on using button	94	7	53.813
53:06.3	Audio recording disabled due to video buffering default			
07:51.0	Volume up button pressed			
07:51.6	Volume up button released			
07:51.6	Volume up button pressed			
07:51.8	Volume up button released			
07:59.9	Camera connected to Axon Dock X62001V12	92	7	53.899
08:00.0	Audit log created	92	7	1.12.23 53.813
08:00.0	Audit log rolled	92	7	53.813
08:00.3	Device connected to charger	92	7	53.813
08:13.1	Video upload started when camera was docked			d136afd5c0c54049a8b0833c2efa6553
08:22.1	Audit log successfully uploaded			
08:22.1	Audit log successfully uploaded			
08:22.2	Audit log successfully uploaded			
08:22.2	Audit log successfully uploaded			
08:22.2	Audit log successfully uploaded			
08:22.4	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.4	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.4	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.4	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.5	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.5	Audit log successfully uploaded			
08:22.5	Audit log successfully uploaded			
08:22.6	Audit log successfully uploaded			
08:22.6	Audit log successfully uploaded			
08:22.6	Audit log successfully uploaded			
08:22.7	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.7	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.8	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.8	Audit log successfully uploaded and deleted from device	92	7	53.899
08:22.8	Audit log successfully uploaded			
08:22.9	Audit log successfully uploaded			
08:22.9	Audit log successfully uploaded			
08:22.9	Audit log successfully uploaded			
08:23.0	Audit log successfully uploaded			
08:23.0	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.1	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.1	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.1	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.1	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.2	Audit log successfully uploaded			
08:23.2	Audit log successfully uploaded and deleted from device	92	7	53.899
08:23.3	Audit log successfully uploaded			
08:23.3	Audit log successfully uploaded			
08:23.3	Audit log successfully uploaded			
08:23.3	Audit log successfully uploaded			

08:30.2 Audit log successfully uploaded			
08:30.2 Audit log successfully uploaded			
08:30.2 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.0 Date/Time synced to 06/04/2021 08:08:44.01 PM from 06/04/2021 08:08:29.94 PM			
08:44.0 Audit log successfully uploaded			
08:44.1 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.1 Audit log successfully uploaded			
08:44.1 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.2 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.2 Audit log successfully uploaded			
08:44.2 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.3 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.4 Audit log successfully uploaded			
08:44.4 Audit log successfully uploaded			
08:44.4 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.5 Audit log successfully uploaded			
08:44.5 Audit log successfully uploaded			
08:44.5 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.6 Audit log successfully uploaded			
08:44.6 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.7 Audit log successfully uploaded			
08:44.7 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.7 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.7 Audit log successfully uploaded			
08:44.8 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.8 Audit log successfully uploaded			
08:44.9 Audit log successfully uploaded and deleted from device	92	7	53.899
08:44.9 Audit log successfully uploaded			
08:45.0 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.0 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.0 Audit log successfully uploaded			
08:45.1 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.1 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.2 Audit log successfully uploaded			
08:45.2 Audit log successfully uploaded			
08:45.3 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.3 Audit log successfully uploaded			
08:45.4 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.4 Audit log successfully uploaded			
08:45.4 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.5 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.5 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.6 Audit log successfully uploaded			
08:45.6 Audit log successfully uploaded and deleted from device	92	7	53.899
08:45.7 Audit log successfully uploaded			
08:45.7 Audit log successfully uploaded			
08:45.7 Audit log successfully uploaded			

08:56.5	Audit log successfully uploaded			
08:56.6	Audit log successfully uploaded			
08:56.6	Audit log successfully uploaded and deleted from device	92	7	53.898
08:56.7	Audit log successfully uploaded			
08:56.7	Audit log successfully uploaded and deleted from device	92	7	53.898
08:56.7	Audit log successfully uploaded and deleted from device	92	7	53.898
08:56.7	Audit log successfully uploaded			
08:56.7	Audit log successfully uploaded and deleted from device	92	7	53.898
08:56.8	Audit log successfully uploaded			
08:56.9	Audit log successfully uploaded			
08:56.9	Audit log successfully uploaded and deleted from device	92	7	53.898
08:56.9	Audit log successfully uploaded			
08:57.0	Audit log successfully uploaded			
08:57.0	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.0	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.1	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.1	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.2	Audit log successfully uploaded			
08:57.2	Audit log successfully uploaded			
08:57.3	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.3	Audit log successfully uploaded			
08:57.3	Audit log successfully uploaded			
08:57.4	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.4	Audit log successfully uploaded			
08:57.4	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.5	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.5	Audit log successfully uploaded and deleted from device	92	7	53.898
08:57.6	Audit log successfully uploaded and deleted from device	92	7	53.898
09:02.7	Video successfully uploaded from device when dockec			d136afd5c0c54049a8b0833c2efa6553
09:03.0	Video deleted from device when docked	92	6	54.023 d136afd5c0c54049a8b0833c2efa6553
09:03.3	Video upload started when camera was docked			af66d7e3322548c9a7627d09fa58d76a
09:30.9	Video successfully uploaded from device when dockec			af66d7e3322548c9a7627d09fa58d76a
09:31.2	Video deleted from device when docked	93	5	54.107 af66d7e3322548c9a7627d09fa58d76a
09:31.5	Video upload started when camera was docked			83587336141042e0992d5cafd41ca4ca
10:05.2	Video successfully uploaded from device when dockec			83587336141042e0992d5cafd41ca4ca
10:05.4	Video deleted from device when docked	93	4	54.224 83587336141042e0992d5cafd41ca4ca
10:05.6	Video upload started when camera was docked			40fdbba0e72344cb8f8496be36a05e4f
10:32.3	Video successfully uploaded from device when dockec			40fdbba0e72344cb8f8496be36a05e4f
10:32.5	Video deleted from device when docked	93	3	54.314 40fdbba0e72344cb8f8496be36a05e4f
10:32.8	Video upload started when camera was docked			fe3a0ddf9cd6424283f5690cee2275bd
11:08.3	Video successfully uploaded from device when dockec			fe3a0ddf9cd6424283f5690cee2275bd
11:08.6	Video deleted from device when docked	93	2	54.441 fe3a0ddf9cd6424283f5690cee2275bd
11:08.8	Video upload started when camera was docked			4ea159da3a0d4eec9a201466c52bbd96
11:47.8	Video successfully uploaded from device when dockec			4ea159da3a0d4eec9a201466c52bbd96
11:48.0	Video deleted from device when docked	94	1	54.581 4ea159da3a0d4eec9a201466c52bbd96
11:48.3	Video upload started when camera was docked			bff9ed722a1d4983b493f50e384e9320
16:54.5	Video successfully uploaded from device when dockec			bff9ed722a1d4983b493f50e384e9320

16:55.0 Video deleted from device when docked	95	0	55.709 bff9ed722a1d4983b493f50e384e9320
16:55.1 Audit log created	95	0 1.12.23	55.709
16:55.1 Audit log rolled	95	0	55.709
27:08.5 Select button pressed			
27:08.7 Select button released			
27:08.8 Camera disconnected from Axon Dock X62001V12	97	0	55.709
27:09.1 Device disconnected from charger	97	0	55.709
16:55.0 Audit log created	92	0 1.12.23	55.71
20:37.4 Volume up button pressed			
20:37.5 Volume up button released			
21:59.7 Power button pressed			
22:02.8 Device powered off using button	91	0	55.71
22:03.2 Power button released			
13:00.2 Audit log created		1.12.23	
13:00.2 Device powered on using button	91	0	55.709
13:03.2 Audio recording disabled due to video buffering default			
29:31.6 Volume up button pressed			
29:31.7 Volume up button released			
38:37.5 Volume up button pressed			
38:38.9 Volume up button released			
45:03.1 Volume up button pressed			
45:03.2 Volume up button released			
50:53.1 Volume up button pressed			
50:53.3 Volume up button released			
50:54.4 Volume up button pressed			
50:54.7 Volume up button released			
50:56.9 Volume up button pressed			
50:56.9 Volume up button released			
54:43.1 Volume up button pressed			
54:43.6 Volume up button released			
03:13.1 Volume up button pressed			
03:13.4 Volume up button released			
13:00.2 Audit log created	85	0 1.12.23	55.708
13:59.3 Volume up button pressed			
13:59.9 Volume up button released			
14:24.8 Volume up button pressed			
14:26.5 Volume up button released			
34:09.6 Volume up button pressed			
34:10.4 Volume up button released			
13:00.2 Audit log created	78	0 1.12.23	55.707
53:22.9 Event button pressed			
53:23.1 Event button released			
53:23.2 Event button pressed			
53:23.3 Audio recording enabled due to video recording default			
53:23.4 Event button released			
53:23.5 Recording started due to button press	74	0	55.705 fe19455593944e6b94d8c23c64bb0620
02:37.9 Event button pressed			

02:39.6	Event button released				
02:42.6	Event button pressed				
02:45.6	Recording stopped due to button press	72	1	55.348	fe19455593944e6b94d8c23c64bb0620
02:46.2	Event button released				
02:46.4	Audio recording disabled due to video buffering default				
08:54.9	Axon application connected to device				
09:12.7	Axon application connected to device				
10:15.0	Categories 'Sleeper', 'Special Detail', 'Loitering' added to video metadata using Axon applicator				fe19455593944e6b94d8c23c64bb0620
10:57.5	Title changed in video metadata from " to 'Clearing Last Train at Doraville' using Axon applicator				fe19455593944e6b94d8c23c64bb0620
11:13.8	Title changed in video metadata from 'Clearing Last Train at Doraville' to 'Clearing Last Train at Doraville - Unit 360A' using Axon applicator				fe19455593944e6b94d8c23c64bb0620
11:24.3	Axon application disconnected from device				
13:00.2	Audit log created	71	1	1.12.23	55.346
13:23.7	Event button pressed				
13:23.9	Event button released				
13:24.0	Event button pressed				
13:24.0	Audio recording enabled due to video recording default				
13:24.1	Event button released				
13:24.2	Recording started due to button press	71	2	55.346	432161b2f3544fb0ae3e7b5194c0e80a
15:28.7	Event button pressed				
15:31.7	Recording stopped due to button press	71	2	55.218	432161b2f3544fb0ae3e7b5194c0e80a
15:32.4	Audio recording disabled due to video buffering default				
15:32.5	Event button released				
16:41.3	Select button pressed				
16:41.5	Select button released				
21:20.4	Axon application connected to device				
22:08.4	Categories 'Loitering' added to video metadata using Axon applicator				432161b2f3544fb0ae3e7b5194c0e80a
23:16.5	Title changed in video metadata from " to 'Sig 70 Doraville' using Axon applicator				432161b2f3544fb0ae3e7b5194c0e80a
23:28.8	Axon application disconnected from device				
23:37.5	Axon application connected to device				
23:40.0	Axon application disconnected from device				
28:19.2	Event button pressed				
28:19.3	Event button released				
28:19.5	Event button pressed				
28:19.5	Audio recording enabled due to video recording default				
28:19.6	Event button released				
28:19.6	Recording started due to button press	70	2	55.217	4429959b2a864290a6ee4b182c9678a6
31:27.2	Event button pressed				
31:30.2	Recording stopped due to button press	69	3	55.055	4429959b2a864290a6ee4b182c9678a6
31:30.6	Event button released				
31:31.2	Audio recording disabled due to video buffering default				
32:21.1	Axon application connected to device				
32:40.0	Categories 'Sleeper' added to video metadata using Axon applicator				4429959b2a864290a6ee4b182c9678a6
32:53.9	Title changed in video metadata from " to 'Sig 31 NE9' using Axon application				4429959b2a864290a6ee4b182c9678a6
33:00.8	Axon application disconnected from device				
54:56.0	Select button pressed				
54:56.2	Select button released				
55:30.3	Volume up button pressed				

55:30.4	Volume up button released			
13:00.2	Audit log created	64	3 1.12.23	55.053
13:00.2	Audit log created	58	3 1.12.23	55.052
13:00.2	Audit log created	51	3 1.12.23	55.051
46:44.2	Power button pressed			
46:47.2	Device powered off using button	47	3	55.05
46:48.0	Power button released			
20:59.9	Audit log created		1.12.23	
21:00.0	Device connected to charger			
21:00.0	Device powered on due to charger connection	47	3	55.049
21:00.0	Camera connected to Axon Dock X630020W7	47	3	55.049
21:00.0	Audit log rolled			
21:00.0	Audit log created		1.12.23	
21:01.0	Camera connected to Axon Dock X630020W7	47	3	55.049
21:02.9	Audit log created	47	3 1.12.23	55.049
21:02.9	Audit log rolled	47	3	55.049
21:02.0	Audit log created	75	3 1.12.23	55.049
21:02.0	Audit log created	98	3 1.12.23	55.048
21:02.0	Audit log created	100	3 1.12.23	55.048
21:02.0	Audit log created	100	3 1.12.23	55.048
21:02.0	Audit log created	100	3 1.12.23	55.05
21:02.0	Audit log created	100	3 1.12.23	55.049
21:02.0	Audit log created	100	3 1.12.23	55.049
21:02.0	Audit log created	100	3 1.12.23	55.049
42:54.0	Device disconnected from charger	98	3	55.049
42:54.2	Camera disconnected from Axon Dock X630020W7	98	3	55.049
42:54.4	Audio recording disabled due to video buffering default			
43:39.7	Power button pressed			
43:39.8	Power button released			
44:02.1	Power button pressed			
44:05.1	Device powered off using button	100	3	55.053
44:05.7	Power button released			
57:45.0	Audit log created		1.12.23	
57:45.0	Device powered on using button	100	3	55.053
57:47.0	Audio recording disabled due to video buffering default			
57:45.0	Audit log created	92	3 1.12.23	55.052
45:20.5	Event button pressed			
45:20.6	Event button released			
45:20.7	Event button pressed			
45:20.8	Audio recording enabled due to video recording default			
45:20.8	Event button released			
45:21.0	Recording started due to button press	87	3	55.05 04c3b7a38bfc4a388e3322296d43419a
57:45.0	Audit log created	85	4 1.12.23	54.596
59:28.0	Event button pressed			
59:31.0	Recording stopped due to button press	84	4	54.54 04c3b7a38bfc4a388e3322296d43419a
59:31.8	Audio recording disabled due to video buffering default			
59:31.8	Event button released			

00:38.4	Axon application connected to device			
00:54.7	Categories 'Ambulance Call' added to video metadata using Axon applicator			04c3b7a38bfc4a388e3322296d43419a
02:09.9	Title changed in video metadata from '' to 'Sig 4. Codes 32, 33, 08. At NE9' using Axon applicator			04c3b7a38bfc4a388e3322296d43419a
02:17.7	Axon application disconnected from device			
26:40.9	Event button pressed			
26:42.4	Event button released			
26:42.7	Event button pressed			
26:42.9	Event button released			
26:43.0	Event button pressed			
26:43.0	Audio recording enabled due to video recording default			
26:43.1	Event button released			
26:43.2	Recording started due to button press	82	5	54.537 0f74c1f984ab4a18a8cec6187203c596
28:13.1	Event button pressed			
28:16.1	Recording stopped due to button press	82	5	54.428 0f74c1f984ab4a18a8cec6187203c596
28:16.9	Audio recording disabled due to video buffering default			
28:18.4	Event button released			
29:52.5	Axon application connected to device			
30:27.4	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			0f74c1f984ab4a18a8cec6187203c596
30:52.4	Title changed in video metadata from '' to 'Clearing Train At Doraville' using Axon applicator			0f74c1f984ab4a18a8cec6187203c596
31:29.2	Axon application disconnected from device			
54:20.3	Event button pressed			
54:20.4	Event button released			
54:20.5	Event button pressed			
54:20.6	Audio recording enabled due to video recording default			
54:20.6	Event button released			
54:20.7	Recording started due to button press	79	6	54.426 f13d34de2ce44f89afd4cfbf53b443f3
57:45.0	Audit log created	78	6 1.12.23	54.258
08:09.2	Event button pressed			
08:12.3	Recording stopped due to button press	77	6	53.928 f13d34de2ce44f89afd4cfbf53b443f3
08:12.7	Event button released			
08:13.2	Audio recording disabled due to video buffering default			
09:08.6	Event button pressed			
09:08.8	Event button released			
09:08.8	Event button pressed			
09:08.9	Audio recording enabled due to video recording default			
09:09.0	Event button released			
09:09.0	Recording started due to button press	76	7	53.925 d5800fa97863461a97614227d5741306
09:52.7	Event button pressed			
09:54.7	Event button released			
11:11.2	Event button pressed			
11:14.2	Recording stopped due to button press	76	7	53.832 d5800fa97863461a97614227d5741306
11:15.1	Event button released			
11:15.2	Audio recording disabled due to video buffering default			
23:13.3	Camera connected to Axon Dock X62001W9H	75	7	53.846
23:13.6	Audit log created	75	7 1.12.23	53.831
23:13.6	Audit log rolled	75	7	53.831
23:14.0	Device connected to charger	75	7	53.831

23:40.4 Video upload started when camera was docked			
23:41.7 Audit log successfully uploaded			
23:41.7 Audit log successfully uploaded			
23:41.7 Audit log successfully uploaded			
23:41.8 Audit log successfully uploaded			
23:41.8 Audit log successfully uploaded			
23:42.0 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.0 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.0 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.1 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.1 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.1 Audit log successfully uploaded			
23:42.2 Audit log successfully uploaded			
23:42.2 Audit log successfully uploaded			
23:42.2 Audit log successfully uploaded			
23:42.2 Audit log successfully uploaded			
23:42.4 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.4 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.4 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.4 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.5 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.5 Audit log successfully uploaded			
23:42.5 Audit log successfully uploaded			
23:42.6 Audit log successfully uploaded			
23:42.6 Audit log successfully uploaded			
23:42.7 Audit log successfully uploaded			
23:42.7 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.7 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.8 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.8 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.9 Audit log successfully uploaded and deleted from device	75	7	53.846
23:42.9 Audit log successfully uploaded			
23:42.9 Audit log successfully uploaded			
23:43.0 Audit log successfully uploaded			
23:43.0 Audit log successfully uploaded			
23:43.1 Audit log successfully uploaded and deleted from device	75	7	53.846
23:43.2 Audit log successfully uploaded and deleted from device	75	7	53.846
23:43.2 Audit log successfully uploaded and deleted from device	75	7	53.846
23:43.2 Audit log successfully uploaded and deleted from device	75	7	53.846
23:43.2 Audit log successfully uploaded			
23:43.2 Audit log successfully uploaded and deleted from device	75	7	53.846
23:43.3 Audit log successfully uploaded			
23:43.3 Audit log successfully uploaded			
23:43.4 Audit log successfully uploaded			
23:43.4 Audit log successfully uploaded			
23:43.4 Audit log successfully uploaded and deleted from device	75	7	53.846

23:43.5	Audit log successfully uploaded and deleted from device	75	7	53.846	
23:43.5	Audit log successfully uploaded and deleted from device	75	7	53.846	
23:43.6	Audit log successfully uploaded and deleted from device	75	7	53.846	
23:43.6	Audit log successfully uploaded and deleted from device	75	7	53.846	
23:44.0	Date/Time synced to 06/06/2021 02:23:44.03 AM from 06/06/2021 02:23:43.70 AM				
25:18.7	Video successfully uploaded from device when docked				fe19455593944e6b94d8c23c64bb0620
25:19.1	Video deleted from device when docked	76	6	54.203	fe19455593944e6b94d8c23c64bb0620
25:19.3	Video upload started when camera was docked				432161b2f3544fb0ae3e7b5194c0e80a
25:55.6	Video successfully uploaded from device when docked				432161b2f3544fb0ae3e7b5194c0e80a
25:55.9	Video deleted from device when docked	76	5	54.33	432161b2f3544fb0ae3e7b5194c0e80a
25:56.1	Video upload started when camera was docked				4429959b2a864290a6ee4b182c9678a6
26:40.8	Video successfully uploaded from device when docked				4429959b2a864290a6ee4b182c9678a6
26:41.1	Video deleted from device when docked	76	4	54.492	4429959b2a864290a6ee4b182c9678a6
26:41.3	Video upload started when camera was docked				04c3b7a38bfc4a388e3322296d43419a
29:00.5	Video successfully uploaded from device when docked				04c3b7a38bfc4a388e3322296d43419a
29:00.9	Video deleted from device when docked	77	3	54.998	04c3b7a38bfc4a388e3322296d43419a
29:01.4	Video upload started when camera was docked				0f74c1f984ab4a18a8cec6187203c596
29:31.4	Video successfully uploaded from device when docked				0f74c1f984ab4a18a8cec6187203c596
29:31.7	Video deleted from device when docked	78	2	55.108	0f74c1f984ab4a18a8cec6187203c596
29:32.2	Video upload started when camera was docked				f13d34de2ce44f89afd4cfbf53b443f3
31:46.1	Video successfully uploaded from device when docked				f13d34de2ce44f89afd4cfbf53b443f3
31:46.5	Video deleted from device when docked	79	1	55.604	f13d34de2ce44f89afd4cfbf53b443f3
31:46.8	Video upload started when camera was docked				d5800fa97863461a97614227d5741306
32:12.8	Video successfully uploaded from device when docked				d5800fa97863461a97614227d5741306
32:13.0	Video deleted from device when docked	79	0	55.703	d5800fa97863461a97614227d5741306
32:13.1	Audit log created	79	0	1.12.23	55.703
32:13.1	Audit log rolled	79	0	1.12.23	55.703
39:14.7	Firmware version 1.13.32 detected				1.12.23
40:28.1	Firmware version 1.13.32 downloaded from Evidence.com	83	0	1.12.23	55.082
43:17.7	Device restarting due to firmware update	84	0		55.082
43:17.7	Firmware update to version 1.13.32 started	84	0	1.12.23	55.082
45:41.9	Device connected to charger				
45:41.9	Device restarted due to firmware update	84	0		55.081
45:42.0	Camera connected to Axon Dock X62001W9H	84	0		55.08
45:42.0	Audit log rolled				
45:42.0	Audit log created				1.13.32
45:42.3	Firmware successfully updated to 1.13.32				1.13.32
45:42.9	Camera connected to Axon Dock X62001W9H	85	0		55.071
45:44.8	Audit log rolled	84	0		55.081
45:44.8	Audit log created	84	0	1.13.32	55.081
46:04.4	Audit log successfully uploaded				
46:04.7	Audit log successfully uploaded and deleted from device	84	0		55.082
46:07.2	Audit log successfully uploaded				
46:07.4	Audit log successfully uploaded and deleted from device	84	0		55.08
46:15.0	Date/Time synced to 06/06/2021 02:46:15.01 AM from 06/06/2021 02:46:14.50 AM				
46:29.9	Audit log successfully uploaded				
46:30.2	Audit log successfully uploaded and deleted from device	85	0		55.077

16:15.0	Date/Time synced to 06/06/2021 03:16:15.01 AM from 06/06/2021 03:16:15.04 AM			
21:31.0	Device disconnected from charger	97	0	55.069
21:31.5	Camera disconnected from Axon Dock X62001W9H	97	0	55.069
21:31.5	Audio recording disabled due to video buffering default			
45:44.1	Audit log created	94	0 1.13.32	55.071
45:44.1	Audit log created	88	0 1.13.32	55.07
45:44.1	Audit log created	83	0 1.13.32	55.068
18:12.9	Power button pressed			
18:15.9	Device powered off using button	80	0	55.068
18:16.5	Power button released			
18:20.9	Audit log created	80	0 1.13.32	55.068
18:20.9	Audit log rolled	80	0	55.068
18:22.0	Device connected to charger	80	0	55.068
19:05.1	Device connected to charger			
19:05.1	Device powered on due to charger connection	80	0	55.068
19:05.1	Camera connected to Axon Dock X630020W7	80	0	55.068
19:05.2	Audit log created		1.13.32	
19:05.2	Audit log rolled			
19:06.1	Camera connected to Axon Dock X630020W7	80	0	55.068
19:07.9	Audit log rolled	80	0	55.068
19:07.9	Audit log created	80	0 1.13.32	55.068
19:07.0	Audit log created	100	0 1.13.32	55.067
19:07.0	Audit log created	100	0 1.13.32	55.067
19:07.0	Audit log created	100	0 1.13.32	55.066
19:07.0	Audit log created	100	0 1.13.32	55.066
19:07.0	Audit log created	100	0 1.13.32	55.066
19:07.0	Audit log created	100	0 1.13.32	55.067
19:07.0	Audit log created	100	0 1.13.32	55.067
19:07.0	Audit log created	100	0 1.13.32	55.068
19:07.1	Audit log created	100	0 1.13.32	55.067
19:07.1	Audit log created	100	0 1.13.32	55.067
19:07.1	Audit log created	100	0 1.13.32	55.067
19:07.1	Audit log created	100	0 1.13.32	55.067
19:07.1	Audit log created	100	0 1.13.32	55.066
35:13.1	Device disconnected from charger	98	0	55.066
35:13.9	Camera disconnected from Axon Dock X630020W7	100	0	55.066
35:14.0	Audio recording disabled due to video buffering default			
19:07.1	Audit log created	94	0 1.13.32	55.067
19:07.1	Audit log created	89	0 1.13.32	55.066
19:07.1	Audit log created	83	0 1.13.32	55.064
19:07.1	Audit log created	77	0 1.13.32	55.063
19:07.1	Audit log created	71	0 1.13.32	55.062
19:07.1	Audit log created	65	0 1.13.32	55.06
44:01.3	Event button pressed			
44:01.4	Event button released			
44:01.6	Event button pressed			
44:01.6	Audio recording enabled due to video recording default			

44:01.8	Event button released			
44:01.8	Recording started due to button press	63	1	55.059 ab63260410524634a9a6d97edc952cfc
00:04.3	Event button pressed			
00:07.3	Recording stopped due to button press	60	1	54.492 ab63260410524634a9a6d97edc952cfc
00:07.9	Event button released			
00:08.1	Audio recording disabled due to video buffering default			
00:08.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-07 0144 X6033271L' using Axon applicator			ab63260410524634a9a6d97edc952cfc
03:54.7	Axon application connected to device			
04:58.3	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			ab63260410524634a9a6d97edc952cfc
05:30.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-07 0144 X6033271L' to 'Sig. 31 Times 8 At N2' using Axon applicator			ab63260410524634a9a6d97edc952cfc
05:41.3	Axon application disconnected from device			
19:07.1	Audit log created	58	1 1.13.32	54.488
19:07.1	Audit log created	51	1 1.13.32	54.487
19:07.1	Audit log created	45	1 1.13.32	54.486
19:07.1	Audit log created	39	1 1.13.32	54.484
56:12.2	Power button pressed			
56:15.2	Device powered off using button	36	1	54.484
56:15.6	Power button released			
24:13.9	Audit log created		1.13.32	
24:14.0	Device powered on due to charger connection	36	1	54.483
24:14.0	Device connected to charger			
24:14.1	Camera connected to Axon Dock X630020W7	36	1	54.483
24:14.1	Audit log created		1.13.32	
24:14.1	Audit log rolled			
24:15.0	Camera connected to Axon Dock X630020W7	36	1	54.483
24:16.9	Audit log created	36	1 1.13.32	54.483
24:16.9	Audit log rolled	36	1	54.483
24:16.0	Audit log created	63	1 1.13.32	54.482
24:16.0	Audit log created	89	1 1.13.32	54.482
24:16.0	Audit log created	100	1 1.13.32	54.481
24:16.0	Audit log created	100	1 1.13.32	54.481
24:16.0	Audit log created	100	1 1.13.32	54.48
24:16.0	Audit log created	100	1 1.13.32	54.48
24:16.1	Audit log created	100	1 1.13.32	54.48
24:16.1	Audit log created	100	1 1.13.32	54.48
53:35.0	Device disconnected from charger	99	1	54.479
53:35.2	Camera disconnected from Axon Dock X630020W7	99	1	54.479
53:35.3	Audio recording disabled due to video buffering default			
53:52.8	Power button pressed			
53:55.8	Device powered off using button	100	1	54.486
53:56.2	Power button released			
15:38.1	Audit log created		1.13.32	
15:38.2	Device powered on using button	100	1	54.485
15:41.2	Audio recording disabled due to video buffering default			
15:38.1	Audit log created	93	1 1.13.32	54.484
30:14.9	Event button pressed			
30:15.1	Event button released			

30:15.2	Event button pressed			
30:15.2	Audio recording enabled due to video recording default			
30:15.3	Event button released			
30:15.4	Recording started due to button press	91	2	54.483 0a2013747d9846c49ec2e85b7daa0743
44:01.1	Event button pressed			
44:04.1	Recording stopped due to button press	89	2	53.987 0a2013747d9846c49ec2e85b7daa0743
44:04.6	Event button released			
44:05.1	Audio recording disabled due to video buffering default			
44:05.5	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-08 0030 X6033271L' using Axon applicator			0a2013747d9846c49ec2e85b7daa0743
56:03.8	Event button pressed			
56:03.9	Event button released			
56:03.9	Event button pressed			
56:04.0	Audio recording enabled due to video recording default			
56:04.1	Event button released			
56:04.1	Recording started due to button press	88	3	53.984 169ddca8daa641518471de36a599c85c
02:42.6	Event button pressed			
02:45.6	Recording stopped due to button press	87	3	53.711 169ddca8daa641518471de36a599c85c
02:46.1	Event button released			
02:46.3	Audio recording disabled due to video buffering default			
02:46.6	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-08 0056 X6033271L' using Axon applicator			169ddca8daa641518471de36a599c85c
03:06.8	Axon application connected to device			
03:40.2	Categories 'Sleeper', 'Drunk Person' added to video metadata using Axon applicator			0a2013747d9846c49ec2e85b7daa0743
04:12.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0030 X6033271L' to 'Sig 28 At NE10 Code 9 By 3610' using Axon applicator			0a2013747d9846c49ec2e85b7daa0743
04:30.3	Categories 'Ambulance Call' added to video metadata using Axon applicator			169ddca8daa641518471de36a599c85c
04:56.6	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0056 X6033271L' to 'Sig 4 At Doraville. Code 9 By 3610' using Axon applicator			169ddca8daa641518471de36a599c85c
05:11.4	Axon application disconnected from device			
15:38.1	Audit log created	85	3 1.13.32	53.709
22:45.5	Event button pressed			
22:45.6	Event button released			
22:45.7	Event button pressed			
22:45.7	Audio recording enabled due to video recording default			
22:45.8	Event button released			
22:45.9	Recording started due to button press	85	4	53.709 62a8e0f1179b4aa293353511ff733b0f
24:49.0	Event button pressed			
24:52.0	Recording stopped due to button press	84	4	53.582 62a8e0f1179b4aa293353511ff733b0f
24:52.6	Event button released			
24:52.8	Audio recording disabled due to video buffering default			
24:53.0	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-08 0122 X6033271L' using Axon applicator			62a8e0f1179b4aa293353511ff733b0f
29:03.4	Volume up button pressed			
29:03.5	Volume up button released			
29:13.6	Volume up button pressed			
29:13.8	Volume up button released			
29:14.5	Volume up button pressed			
29:14.7	Volume up button released			
29:18.8	Volume up button pressed			
29:19.1	Volume up button released			
29:19.2	Volume up button pressed			

29:20.1	Volume up button released				
50:15.7	Event button pressed				
50:15.9	Event button released				
50:16.1	Event button pressed				
50:16.1	Audio recording enabled due to video recording default				
50:16.2	Event button released				
50:16.3	Recording started due to button press	82	5	53.58	8a7d4a46fc4349a794214230ad0fd076
55:19.3	Event button pressed				
55:19.3	Event button released				
06:52.5	Event button pressed				
06:55.5	Recording stopped due to button press	79	5	52.992	8a7d4a46fc4349a794214230ad0fd076
06:56.2	Audio recording disabled due to video buffering default				
06:56.4	Event button released				
06:56.9	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-08 0150 X6033271L' using Axon application				8a7d4a46fc4349a794214230ad0fd076
15:38.3	Audit log created	78	5 1.13.32	52.989	
21:26.5	Volume up button pressed				
21:26.8	Volume up button released				
27:50.6	Event button pressed				
27:50.8	Event button released				
27:51.0	Event button pressed				
27:51.0	Audio recording enabled due to video recording default				
27:51.1	Event button released				
27:51.2	Recording started due to button press	77	6	52.988	e9920d2370b9492bb0dff9d1ecc4b01f
35:53.5	Event button pressed				
35:56.5	Recording stopped due to button press	76	6	52.672	e9920d2370b9492bb0dff9d1ecc4b01f
35:57.1	Event button released				
35:57.2	Audio recording disabled due to video buffering default				
35:57.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-08 0227 X6033271L' using Axon application				e9920d2370b9492bb0dff9d1ecc4b01f
40:08.6	Volume up button pressed				
40:08.9	Volume up button released				
40:09.8	Volume up button pressed				
40:10.1	Volume up button released				
48:32.1	Event button pressed				
48:32.2	Event button released				
48:32.3	Event button pressed				
48:32.4	Audio recording enabled due to video recording default				
48:32.4	Event button released				
48:32.5	Recording started due to button press	75	6	52.669	e31b578658c642f8b50e1e6074b38ce8
49:03.6	Event button pressed				
49:06.6	Recording stopped due to button press	74	7	52.597	e31b578658c642f8b50e1e6074b38ce8
49:07.1	Event button released				
49:07.3	Audio recording disabled due to video buffering default				
49:09.9	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-08 0248 X6033271L' using Axon application				e31b578658c642f8b50e1e6074b38ce8
53:25.3	Event button pressed				
53:25.5	Event button released				
53:25.6	Event button pressed				
53:25.6	Audio recording enabled due to video recording default				

53:25.7	Event button released			
53:25.7	Recording started due to button press	74	8	52.59 572add2f8b654128bbe60ccefc33a239
15:38.4	Audit log created	70	8 1.13.32	51.823
16:53.8	Event button pressed			
16:56.9	Recording stopped due to button press	70	8	51.781 572add2f8b654128bbe60ccefc33a239
16:57.9	Audio recording disabled due to video buffering default			
16:58.6	Event button released			
16:58.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-08 0253 X6033271L' using Axon application			572add2f8b654128bbe60ccefc33a239
15:38.4	Audit log created	64	8 1.13.32	51.777
15:38.4	Audit log created	59	8 1.13.32	51.775
12:47.4	Event button pressed			
12:48.5	Event button released			
15:38.4	Audit log created	51	8 1.13.32	51.774
15:59.1	Camera connected to Axon Dock X630020W7	52	8	51.775
15:59.3	Audit log created	51	8 1.13.32	51.775
15:59.3	Audit log rolled	51	8	51.775
16:00.3	Device connected to charger	51	8	51.775
15:59.0	Audit log created	79	8 1.13.32	51.774
15:59.0	Audit log created	100	8 1.13.32	51.775
15:59.0	Audit log created	100	8 1.13.32	51.774
15:59.0	Audit log created	100	8 1.13.32	51.774
15:59.0	Audit log created	100	8 1.13.32	51.773
15:59.0	Audit log created	100	8 1.13.32	51.773
15:59.1	Audit log created	100	8 1.13.32	51.773
15:59.1	Audit log created	100	8 1.13.32	51.772
11:55.9	Camera disconnected from Axon Dock X630020W7	99	8	51.777
11:56.2	Device disconnected from charger	99	8	51.782
12:07.5	Power button pressed			
12:10.6	Device powered off using button	100	8	51.782
12:11.1	Power button released			
51:58.0	Audit log created		1.13.32	
51:58.1	Device powered on due to charger connection	100	8	51.782
51:58.1	Device connected to charger			
51:58.1	Audit log rolled			
51:58.1	Audit log created		1.13.32	
52:01.0	Audit log rolled	100	8	51.782
52:01.0	Audit log created	100	8 1.13.32	51.782
52:26.1	Device disconnected from charger	100	8	51.782
52:26.6	Camera disconnected from Axon Dock	100	8	51.782
52:26.6	Audio recording disabled due to video buffering default			
52:29.0	Power button pressed			
52:32.0	Device powered off using button	100	8	51.782
52:32.4	Power button released			
41:40.0	Audit log created		1.13.32	
41:40.1	Device connected to charger			
41:40.1	Device powered on due to charger connection	100	8	51.782
41:40.1	Camera connected to Axon Dock X630020W7	100	8	51.782

41:40.1	Audit log rolled				
41:40.1	Audit log created			1.13.32	
41:41.1	Camera connected to Axon Dock X630020W7	100	8		51.782
41:43.0	Audit log created	100	8	1.13.32	51.782
41:43.0	Audit log rolled	100	8		51.782
17:00.0	Camera disconnected from Axon Dock X630020W7	100	8		51.782
17:00.1	Device disconnected from charger	100	8		51.782
17:00.1	Audio recording disabled due to video buffering default				
17:01.8	Power button pressed				
17:04.8	Device powered off using button	100	8		51.782
17:05.2	Power button released				
33:31.1	Audit log created			1.13.32	
33:31.2	Device powered on using button	100	8		51.781
33:34.1	Audio recording disabled due to video buffering default				
33:31.1	Audit log created	93	8	1.13.32	51.78
08:14.1	Event button pressed				
08:14.3	Event button released				
08:14.6	Event button pressed				
08:14.6	Audio recording enabled due to video recording default				
08:14.7	Event button released				
08:14.8	Recording started due to button press	89	9		51.779 36fc741c3d4e4bb7a4baa5a1c32c5e2f
11:40.4	Event button pressed				
11:40.6	Event button released				
11:40.8	Event button pressed				
11:41.0	Event button released				
11:41.0	Event button pressed				
11:44.0	Recording stopped due to button press	89	9		51.608 36fc741c3d4e4bb7a4baa5a1c32c5e2f
11:44.5	Event button released				
11:44.9	Audio recording disabled due to video buffering default				
11:45.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-12 0308 X6033271L' using Axon applicator				36fc741c3d4e4bb7a4baa5a1c32c5e2f
20:25.9	Axon application connected to device				
22:32.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0122 X6033271L' to 'Clearing Train At NE10' using Axon applicator				62a8e0f1179b4aa293353511ff733b0f
22:32.7	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				62a8e0f1179b4aa293353511ff733b0f
23:14.8	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				8a7d4a46fc4349a794214230ad0fd076
23:14.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0150 X6033271L' to 'Clearing Train At NE10' using Axon applicator				8a7d4a46fc4349a794214230ad0fd076
24:33.2	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator				e9920d2370b9492bb0dff9d1ecc4b01f
24:33.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0227 X6033271L' to 'Sig 70s At NE9' using Axon applicator				e9920d2370b9492bb0dff9d1ecc4b01f
25:10.8	Categories 'Loitering' added to video metadata using Axon applicator				e31b578658c642f8b50e1e6074b38ce8
25:10.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0248 X6033271L' to 'Sig 70 At NE9' using Axon applicator				e31b578658c642f8b50e1e6074b38ce8
26:12.0	Categories 'Loitering' added to video metadata using Axon applicator				572add2f8b654128bbe60ccfc33a239
26:12.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-08 0253 X6033271L' to 'Sig. 70 At NE9' using Axon applicator				572add2f8b654128bbe60ccfc33a239
27:34.5	Categories 'Ambulance Call' added to video metadata using Axon applicator				36fc741c3d4e4bb7a4baa5a1c32c5e2f
27:34.5	Title changed in video metadata from 'Axon Body 3 Video 2021-06-12 0308 X6033271L' to 'Sig 4 At N2 Self Initiated Call' using Axon applicator				36fc741c3d4e4bb7a4baa5a1c32c5e2f
27:52.1	Axon application disconnected from device				
33:31.1	Audit log created	87	9	1.13.32	51.606
33:31.1	Audit log created	81	9	1.13.32	51.604
37:38.5	Event button pressed				

37:38.7	Event button released			
37:38.8	Event button pressed			
37:38.8	Audio recording enabled due to video recording default			
37:38.9	Event button released			
37:38.9	Recording started due to button press	80	10	51.604 eba47c9cebbd437183521d307b20d2cc
18:29.0	Event button pressed			
18:32.1	Recording stopped due to button press	73	10	50.245 eba47c9cebbd437183521d307b20d2cc
18:32.5	Event button released			
18:32.9	Audio recording disabled due to video buffering default			
18:34.5	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-12 0437 X6033271L' using Axon applicator			eba47c9cebbd437183521d307b20d2cc
22:16.2	Axon application connected to device			
25:14.5	Categories 'Assault' added to video metadata using Axon applicator			eba47c9cebbd437183521d307b20d2cc
25:14.5	Title changed in video metadata from 'Axon Body 3 Video 2021-06-12 0437 X6033271L' to 'Sig. 58 At 10th St In Front Of N4 Code By APD' using			eba47c9cebbd437183521d307b20d2cc
25:27.5	Axon application disconnected from device			
33:31.2	Audit log created	72	10 1.13.32	50.238
12:34.4	Power button pressed			
12:37.5	Device powered off using button	68	10	50.237
12:37.8	Power button released			
15:04.0	Device connected to charger			
15:04.0	Device powered on due to charger connection	68	10	50.236
15:04.0	Camera connected to Axon Dock X630020W7	68	10	50.236
15:04.0	Audit log created		1.13.32	
15:04.0	Audit log rolled			
15:05.0	Camera connected to Axon Dock X630020W7	69	10	50.236
15:06.9	Audit log created	68	10 1.13.32	50.236
15:06.9	Audit log rolled	68		50.236
15:06.0	Audit log created	95	10 1.13.32	50.236
15:06.0	Audit log created	100	10 1.13.32	50.236
15:06.0	Audit log created	100	10 1.13.32	50.241
15:06.0	Audit log created	100	10 1.13.32	50.241
15:06.0	Audit log created	100	10 1.13.32	50.241
15:06.0	Audit log created	100	10 1.13.32	50.241
15:06.1	Audit log created	100	10 1.13.32	50.241
15:06.1	Audit log created	100	10 1.13.32	50.24
15:06.1	Audit log created	100	10 1.13.32	50.24
15:06.1	Audit log created	100	10 1.13.32	50.24
15:06.1	Audit log created	100	10 1.13.32	50.239
15:06.1	Audit log created	100	10 1.13.32	50.239
15:06.1	Audit log created	100	10 1.13.32	50.239
15:06.1	Audit log created	100	10 1.13.32	50.238
15:06.1	Audit log created	100	10 1.13.32	50.239
15:06.6	Camera disconnected from Axon Dock X630020W7	98	10	50.239
15:06.7	Audio recording disabled due to video buffering default			
15:07.0	Device disconnected from charger	98	10	50.243
15:08.1	Power button pressed			
15:11.1	Device powered off using button	100	10	50.243
15:11.5	Power button released			
14:47.1	Audit log created		1.13.32	

14:47.2 Device powered on using button	100	10	50.242	
14:50.2 Audio recording disabled due to video buffering default				
17:08.4 Event button pressed				
17:09.6 Event button released				
17:09.8 Event button pressed				
17:10.0 Event button released				
17:10.1 Event button pressed				
17:10.1 Audio recording enabled due to video recording default				
17:10.2 Event button released				
17:10.3 Recording started due to button press	99	10	50.242	71ba4a85c40d4c13bae977121ebe5bac
35:26.6 Event button pressed				
35:29.6 Recording stopped due to button press	95	11	49.603	71ba4a85c40d4c13bae977121ebe5bac
35:30.3 Audio recording disabled due to video buffering default				
35:30.5 Event button released				
35:30.9 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0017 X6033271L' using Axon applicator				71ba4a85c40d4c13bae977121ebe5bac
42:39.3 Audio recording enabled due to video recording default				
42:39.4 Recording started due to Axon Signal Sidearm activation	94	12	49.599	908de0c3c75b479694d84cd0e1aa8ceb
52:41.8 Event button pressed				
52:44.8 Recording stopped due to button press	93	12	49.219	908de0c3c75b479694d84cd0e1aa8ceb
52:45.4 Event button released				
52:45.7 Audio recording disabled due to video buffering default				
52:46.1 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0042 X6033271L' using Axon applicator				908de0c3c75b479694d84cd0e1aa8ceb
58:23.9 Axon application connected to device				
59:20.6 Categories 'Public Indecency' added to video metadata using Axon applicator				908de0c3c75b479694d84cd0e1aa8ceb
59:20.6 Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0042 X6033271L' to 'Sig 71 At NE10 Code 9 By 3610' using Axon applicator				908de0c3c75b479694d84cd0e1aa8ceb
01:30.1 Categories 'Auto Accident' added to video metadata using Axon applicator				71ba4a85c40d4c13bae977121ebe5bac
02:20.3 Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0017 X6033271L' to 'Sig.41 At NE9 Parking Lot' using Axon applicator				71ba4a85c40d4c13bae977121ebe5bac
02:46.2 Axon application disconnected from device				
14:47.2 Audit log created	90	12	1.13.32	49.217
20:24.0 Event button pressed				
20:24.2 Event button released				
20:24.2 Event button pressed				
20:24.3 Audio recording enabled due to video recording default				
20:24.4 Event button released				
20:24.4 Recording started due to button press	90	13	49.217	4e9cbc4b1eb54fed9854e1a52e366114
22:45.3 Event button pressed				
22:48.4 Recording stopped due to button press	89	13	49.08	4e9cbc4b1eb54fed9854e1a52e366114
22:48.9 Event button released				
22:49.2 Audio recording disabled due to video buffering default				
22:49.4 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0120 X6033271L' using Axon applicator				4e9cbc4b1eb54fed9854e1a52e366114
36:04.7 Event button pressed				
36:04.8 Event button released				
36:04.9 Event button pressed				
36:05.0 Audio recording enabled due to video recording default				
36:05.1 Event button released				
36:05.1 Recording started due to button press	88	14	49.079	31b44a65ca344b638f6e6f738f59cd61
49:13.3 Event button pressed				

49:16.3	Recording stopped due to button press	86	14	48.6	31b44a65ca344b638f6e6f738f59cd61
49:16.8	Event button released				
49:17.1	Audio recording disabled due to video buffering default				
49:17.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0136 X6033271L' using Axon applicator				31b44a65ca344b638f6e6f738f59cd61
51:50.0	Axon application connected to device				
53:28.5	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				4e9cbc4b1eb54fed9854e1a52e366114
53:28.5	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0120 X6033271L' to 'Clearing Train NE10' using Axon applicator				4e9cbc4b1eb54fed9854e1a52e366114
54:07.3	Categories 'Ambulance Call' added to video metadata using Axon applicator				31b44a65ca344b638f6e6f738f59cd61
54:07.3	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0136 X6033271L' to 'Sig. 4 At NE10 Code 9 By 3610' using Axon applicator				31b44a65ca344b638f6e6f738f59cd61
54:27.6	Axon application disconnected from device				
56:52.8	Event button pressed				
56:52.9	Event button released				
56:53.0	Event button pressed				
56:53.0	Audio recording enabled due to video recording default				
56:53.1	Event button released				
56:53.1	Recording started due to button press	85	15	48.597	427d346954b14f078f2f2854527d23d7
59:42.7	Event button pressed				
59:42.9	Event button released				
59:43.0	Event button pressed				
59:48.9	Event button released				
59:50.0	Event button pressed				
59:53.0	Recording stopped due to button press	85	15	48.442	427d346954b14f078f2f2854527d23d7
59:53.5	Event button released				
59:53.9	Audio recording disabled due to video buffering default				
59:54.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0156 X6033271L' using Axon applicator				427d346954b14f078f2f2854527d23d7
00:15.4	Axon application connected to device				
00:56.6	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				427d346954b14f078f2f2854527d23d7
00:56.6	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0156 X6033271L' to 'Clearing Train At NE10' using Axon applicator				427d346954b14f078f2f2854527d23d7
01:00.5	Axon application disconnected from device				
01:12.2	Event button pressed				
01:12.4	Event button released				
01:12.4	Event button pressed				
01:12.5	Audio recording enabled due to video recording default				
01:12.5	Event button released				
01:12.6	Recording started due to button press	85	16	48.441	515e261639e54e3ca8f0ee8445d4ce28
02:59.0	Event button pressed				
03:02.0	Recording stopped due to button press	84	16	48.345	515e261639e54e3ca8f0ee8445d4ce28
03:02.6	Event button released				
03:03.0	Audio recording disabled due to video buffering default				
03:03.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0201 X6033271L' using Axon applicator				515e261639e54e3ca8f0ee8445d4ce28
11:13.0	Event button pressed				
11:13.2	Event button released				
11:13.3	Event button pressed				
11:13.4	Audio recording enabled due to video recording default				
11:13.5	Event button released				
11:13.5	Recording started due to button press	84	17	48.344	ae652959325e48c588f74fea67149669
12:22.7	Event button pressed				

12:25.7	Recording stopped due to button press	83	17	48.246	ae652959325e48c588f74fea67149669
12:26.3	Event button released				
12:26.4	Audio recording disabled due to video buffering default				
12:26.5	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0211 X6033271L' using Axon applicator				ae652959325e48c588f74fea67149669
14:35.5	Axon application connected to device				
14:47.2	Audit log created	83	17	1.13.32	48.245
15:48.8	Audio recording enabled due to video recording default				
15:49.0	Recording started due to Axon Signal Sidearm activation	83	18	48.244	7a0f9ad2b8964685b5b934b1ba01ec65
15:56.4	Event button pressed				
15:59.4	Recording stopped due to button press	83	18	48.221	7a0f9ad2b8964685b5b934b1ba01ec65
15:59.9	Event button released				
16:00.3	Audio recording disabled due to video buffering default				
16:13.2	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				515e261639e54e3ca8f0ee8445d4ce28
16:13.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0201 X6033271L' to 'Clearing Train NE10' using Axon applicator				515e261639e54e3ca8f0ee8445d4ce28
16:27.2	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0215 X6033271L' using Axon applicator				7a0f9ad2b8964685b5b934b1ba01ec65
16:40.3	Categories 'Loitering' added to video metadata using Axon applicator				ae652959325e48c588f74fea67149669
16:40.3	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0211 X6033271L' to 'Sig. 70 NE10' using Axon applicator				ae652959325e48c588f74fea67149669
17:00.0	Categories 'Accidental Recording' added to video metadata using Axon applicator				7a0f9ad2b8964685b5b934b1ba01ec65
17:09.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0215 X6033271L' to 'Code 4' using Axon applicator				7a0f9ad2b8964685b5b934b1ba01ec65
17:13.7	Axon application disconnected from device				
03:39.8	Audio recording enabled due to video recording default				
03:39.9	Recording started due to Axon Signal Sidearm activation	78	19	48.177	7ce35323ee2c4dfe9131fba3472ae017
03:47.8	Event button pressed				
03:50.8	Recording stopped due to button press	78	19	48.152	7ce35323ee2c4dfe9131fba3472ae017
03:51.5	Event button released				
03:51.7	Audio recording disabled due to video buffering default				
04:18.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 0303 X6033271L' using Axon applicator				7ce35323ee2c4dfe9131fba3472ae017
05:49.9	Axon application connected to device				
06:19.7	Categories 'Accidental Recording' added to video metadata using Axon applicator				7ce35323ee2c4dfe9131fba3472ae017
06:19.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 0303 X6033271L' to 'Code 4' using Axon applicator				7ce35323ee2c4dfe9131fba3472ae017
06:32.0	Axon application disconnected from device				
14:47.2	Audit log created	77	19	1.13.32	48.11
31:55.2	Volume up button pressed				
31:55.7	Volume up button released				
31:55.8	Volume up button pressed				
31:55.9	Volume up button released				
32:03.9	Camera connected to Axon Dock X62001W9H	76	19	48.167	
32:04.1	Audit log created	75	19	1.13.32	48.11
32:04.1	Audit log rolled	75	19		48.11
32:04.2	Device connected to charger	75	19		48.11
32:28.0	Video upload started when camera was docked				ab63260410524634a9a6d97edc952cfc
32:41.0	Date/Time synced to 06/13/2021 03:32:41.02 AM from 06/13/2021 03:32:34.19 AM				
32:48.7	Audit log successfully uploaded				
32:48.9	Audit log successfully uploaded and deleted from device	76	19	48.167	
33:12.9	Audit log successfully uploaded				
33:13.0	Audit log successfully uploaded and deleted from device	76	19	48.167	
33:13.9	Audit log successfully uploaded				

33:14.1 Audit log successfully uploaded and deleted from device	76	19	48.167
33:19.2 Audit log successfully uploaded			
33:19.3 Audit log successfully uploaded			
33:19.4 Audit log successfully uploaded and deleted from device	76	19	48.167
33:19.5 Audit log successfully uploaded and deleted from device	76	19	48.167
33:26.5 Audit log successfully uploaded			
33:26.7 Audit log successfully uploaded and deleted from device	76	19	48.167
33:28.9 Audit log successfully uploaded			
33:29.1 Audit log successfully uploaded and deleted from device	76	19	48.167
33:31.6 Audit log successfully uploaded			
33:31.8 Audit log successfully uploaded and deleted from device	76	19	48.167
33:35.2 Audit log successfully uploaded			
33:35.3 Audit log successfully uploaded and deleted from device	76	19	48.167
33:47.5 Audit log successfully uploaded			
33:47.6 Audit log successfully uploaded and deleted from device	76	19	48.167
33:54.0 Audit log successfully uploaded			
33:54.2 Audit log successfully uploaded and deleted from device	77	19	48.167
34:03.8 Audit log successfully uploaded			
34:03.9 Audit log successfully uploaded and deleted from device	77	19	48.167
34:07.4 Audit log successfully uploaded			
34:07.6 Audit log successfully uploaded and deleted from device	77	19	48.167
34:08.1 Audit log successfully uploaded			
34:08.3 Audit log successfully uploaded and deleted from device	77	19	48.167
34:16.4 Audit log successfully uploaded			
34:16.8 Audit log successfully uploaded and deleted from device	77	19	48.167
34:22.0 Audit log successfully uploaded			
34:22.1 Audit log successfully uploaded and deleted from device	77	19	48.167
34:24.7 Audit log successfully uploaded			
34:24.8 Audit log successfully uploaded and deleted from device	77	19	48.167
34:28.0 Audit log successfully uploaded			
34:28.2 Audit log successfully uploaded and deleted from device	77	19	48.167
34:45.3 Audit log successfully uploaded			
34:45.5 Audit log successfully uploaded and deleted from device	77	19	48.167
34:51.3 Audit log successfully uploaded			
34:51.5 Audit log successfully uploaded and deleted from device	77	19	48.167
35:00.8 Audit log successfully uploaded			
35:00.9 Audit log successfully uploaded and deleted from device	77	19	48.167
35:03.5 Audit log successfully uploaded			
35:03.7 Audit log successfully uploaded and deleted from device	77	19	48.167
35:07.1 Video successfully uploaded from device when docked			ab63260410524634a9a6d97edc952cfc
35:07.4 Video deleted from device when docked	77	18	48.736 ab63260410524634a9a6d97edc952cfc
35:07.6 Audit log created	77	18 1.13.32	48.736
35:07.6 Audit log rolled	77	18	48.736
35:07.8 Video upload started when camera was docked			0a2013747d9846c49ec2e85b7daa0743
35:13.1 Audit log successfully uploaded			
35:13.2 Audit log successfully uploaded and deleted from device	77	18	48.736
35:24.4 Audit log successfully uploaded			

35:24.5	Audit log successfully uploaded and deleted from device	77	18	48.736
35:24.8	Audit log successfully uploaded			
35:25.0	Audit log successfully uploaded and deleted from device	77	18	48.736
35:36.2	Audit log successfully uploaded			
35:36.4	Audit log successfully uploaded and deleted from device	77	18	48.736
35:47.5	Audit log successfully uploaded			
35:47.7	Audit log successfully uploaded and deleted from device	77	18	48.736
35:48.7	Audit log successfully uploaded			
35:48.9	Audit log successfully uploaded and deleted from device	77	18	48.736
35:56.8	Audit log successfully uploaded			
35:57.0	Audit log successfully uploaded and deleted from device	77	18	48.736
36:07.0	Audit log successfully uploaded			
36:07.3	Audit log successfully uploaded and deleted from device	77	18	48.736
36:22.2	Audit log successfully uploaded			
36:22.4	Audit log successfully uploaded and deleted from device	78	18	48.736
36:32.4	Audit log successfully uploaded			
36:32.6	Audit log successfully uploaded and deleted from device	78	18	48.736
36:36.5	Audit log successfully uploaded			
36:36.7	Audit log successfully uploaded and deleted from device	78	18	48.736
37:00.7	Audit log successfully uploaded			
37:00.8	Audit log successfully uploaded and deleted from device	78	18	48.736
37:02.0	Audit log successfully uploaded			
37:02.1	Audit log successfully uploaded and deleted from device	78	18	48.736
37:19.0	Audit log successfully uploaded			
37:19.2	Audit log successfully uploaded and deleted from device	78	18	48.736
37:23.5	Audit log successfully uploaded			
37:23.7	Audit log successfully uploaded and deleted from device	78	18	48.736
37:24.2	Video successfully uploaded from device when docked			0a2013747d9846c49ec2e85b7daa0743
37:24.7	Video deleted from device when docked	78	17	49.23 0a2013747d9846c49ec2e85b7daa0743
37:24.7	Audit log rolled	78	17	49.23
37:24.7	Audit log created	78	17 1.13.32	49.23
37:24.9	Video upload started when camera was docked			169ddca8daa641518471de36a599c85c
37:31.3	Audit log successfully uploaded			
37:31.5	Audit log successfully uploaded and deleted from device	78	17	49.23
37:33.6	Audit log successfully uploaded			
37:33.8	Audit log successfully uploaded and deleted from device	78	17	49.23
37:33.9	Audit log successfully uploaded			
37:34.1	Audit log successfully uploaded and deleted from device	78	17	49.23
37:35.8	Audit log successfully uploaded			
37:36.1	Audit log successfully uploaded and deleted from device	78	17	49.23
37:47.2	Audit log successfully uploaded			
37:47.4	Audit log successfully uploaded and deleted from device	78	17	49.23
37:59.3	Audit log successfully uploaded			
37:59.5	Audit log successfully uploaded and deleted from device	78	17	49.23
37:59.6	Audit log successfully uploaded			
37:59.8	Audit log successfully uploaded and deleted from device	78	17	49.23
37:59.9	Audit log successfully uploaded			

38:00.1	Audit log successfully uploaded and deleted from device	78	17	49.23
38:00.6	Audit log successfully uploaded			
38:00.8	Audit log successfully uploaded and deleted from device	78	17	49.23
38:04.9	Audit log successfully uploaded			
38:05.1	Audit log successfully uploaded and deleted from device	78	17	49.23
38:20.3	Audit log successfully uploaded			
38:20.5	Audit log successfully uploaded and deleted from device	78	17	49.23
38:23.2	Audit log successfully uploaded			
38:23.4	Audit log successfully uploaded and deleted from device	78	17	49.23
38:25.6	Audit log successfully uploaded			
38:25.8	Audit log successfully uploaded and deleted from device	78	17	49.23
38:34.0	Audit log successfully uploaded			
38:34.1	Audit log successfully uploaded and deleted from device	79	17	49.23
38:37.5	Video successfully uploaded from device when dockec			169ddca8daa641518471de36a599c85c
38:37.8	Video deleted from device when docked	79	16	49.501 169ddca8daa641518471de36a599c85c
38:37.8	Audit log rolled	79	16	49.502
38:37.8	Audit log created	79	16 1.13.32	49.502
38:38.0	Video upload started when camera was docked			62a8e0f1179b4aa293353511ff733b0f
38:39.6	Audit log successfully uploaded			
38:39.8	Audit log successfully uploaded and deleted from device	79	16	49.502
38:40.3	Audit log successfully uploaded			
38:40.5	Audit log successfully uploaded and deleted from device	79	16	49.501
38:42.7	Audit log successfully uploaded			
38:42.9	Audit log successfully uploaded and deleted from device	79	16	49.501
39:04.0	Audit log successfully uploaded			
39:04.2	Audit log successfully uploaded and deleted from device	79	16	49.501
39:05.0	Audit log successfully uploaded			
39:05.2	Audit log successfully uploaded and deleted from device	79	16	49.501
39:12.0	Video successfully uploaded from device when dockec			62a8e0f1179b4aa293353511ff733b0f
39:12.2	Video deleted from device when docked	79	15	49.628 62a8e0f1179b4aa293353511ff733b0f
39:12.3	Audit log created	79	15 1.13.32	49.628
39:12.3	Audit log rolled	79	15	49.628
39:12.5	Video upload started when camera was docked			8a7d4a46fc4349a794214230ad0fd076
39:17.4	Audit log successfully uploaded			
39:17.6	Audit log successfully uploaded and deleted from device	79	15	49.628
39:27.4	Audit log successfully uploaded			
39:27.5	Audit log successfully uploaded and deleted from device	79	15	49.628
39:32.6	Audit log successfully uploaded			
39:32.8	Audit log successfully uploaded and deleted from device	79	15	49.628
39:48.7	Audit log successfully uploaded			
39:48.8	Audit log successfully uploaded and deleted from device	79	15	49.628
39:57.0	Audit log successfully uploaded			
39:57.2	Audit log successfully uploaded and deleted from device	79	15	49.628
40:13.0	Audit log successfully uploaded			
40:13.2	Audit log successfully uploaded and deleted from device	80	15	49.628
40:19.4	Audit log successfully uploaded			
40:19.6	Audit log successfully uploaded and deleted from device	80	15	49.628

40:24.3	Audit log successfully uploaded			
40:24.5	Audit log successfully uploaded and deleted from device	80	15	49.628
40:35.7	Audit log successfully uploaded			
40:35.9	Audit log successfully uploaded and deleted from device	80	15	49.628
40:40.1	Audit log successfully uploaded			
40:40.2	Audit log successfully uploaded and deleted from device	80	15	49.628
40:40.4	Audit log successfully uploaded			
40:40.6	Audit log successfully uploaded and deleted from device	80	15	49.628
40:47.7	Audit log successfully uploaded			
40:48.0	Audit log successfully uploaded and deleted from device	80	15	49.628
40:50.8	Audit log successfully uploaded			
40:51.0	Audit log successfully uploaded and deleted from device	80	15	49.628
40:55.2	Audit log successfully uploaded			
40:55.4	Audit log successfully uploaded and deleted from device	80	15	49.628
41:00.5	Audit log successfully uploaded			
41:00.7	Audit log successfully uploaded and deleted from device	80	15	49.628
41:01.3	Audit log successfully uploaded			
41:01.5	Audit log successfully uploaded and deleted from device	80	15	49.628
41:01.9	Audit log successfully uploaded			
41:02.1	Audit log successfully uploaded and deleted from device	80	15	49.628
41:14.7	Audit log successfully uploaded			
41:15.0	Audit log successfully uploaded and deleted from device	80	15	49.628
41:16.2	Audit log successfully uploaded			
41:16.4	Audit log successfully uploaded and deleted from device	80	15	49.628
41:32.6	Audit log successfully uploaded			
41:32.9	Audit log successfully uploaded and deleted from device	80	15	49.628
41:40.2	Audit log successfully uploaded			
41:40.3	Audit log successfully uploaded and deleted from device	80	15	49.628
41:52.1	Audit log successfully uploaded			
41:52.3	Audit log successfully uploaded and deleted from device	80	15	49.628
41:53.5	Audit log successfully uploaded			
41:53.6	Audit log successfully uploaded and deleted from device	80	15	49.628
42:02.6	Audit log successfully uploaded			
42:02.8	Audit log successfully uploaded and deleted from device	80	15	49.628
42:14.8	Audit log successfully uploaded			
42:15.0	Audit log successfully uploaded and deleted from device	80	15	49.628
42:17.9	Audit log successfully uploaded			
42:18.1	Audit log successfully uploaded and deleted from device	80	15	49.628
42:32.3	Audit log successfully uploaded			
42:32.5	Audit log successfully uploaded and deleted from device	80	15	49.628
42:34.1	Audit log successfully uploaded			
42:34.3	Audit log successfully uploaded and deleted from device	81	15	49.628
42:41.6	Audit log successfully uploaded			
42:41.8	Audit log successfully uploaded and deleted from device	81	15	49.628
42:49.5	Audit log successfully uploaded			
42:49.6	Audit log successfully uploaded and deleted from device	81	15	49.628
43:02.7	Audit log successfully uploaded			

43:02.9	Audit log successfully uploaded and deleted from device	81	15	49.628	
43:05.9	Audit log successfully uploaded				
43:06.1	Audit log successfully uploaded and deleted from device	81	15	49.628	
43:21.9	Video successfully uploaded from device when docked				8a7d4a46fc4349a794214230ad0fd076
43:22.3	Video deleted from device when docked	81	14	50.213	8a7d4a46fc4349a794214230ad0fd076
43:22.4	Audit log created	81	14	1.13.32	50.213
43:22.4	Audit log rolled	81	14		50.213
43:22.5	Video upload started when camera was docked				e9920d2370b9492bb0dff9d1ecc4b01f
43:29.1	Audit log successfully uploaded				
43:29.3	Audit log successfully uploaded and deleted from device	81	14	50.213	
44:47.4	Video successfully uploaded from device when docked				e9920d2370b9492bb0dff9d1ecc4b01f
44:47.8	Video deleted from device when docked	82	13	50.529	e9920d2370b9492bb0dff9d1ecc4b01f
44:47.8	Audit log created	82	13	1.13.32	50.529
44:47.8	Audit log rolled	82	13		50.529
44:48.0	Video upload started when camera was docked				e31b578658c642f8b50e1e6074b38ce8
45:09.8	Video successfully uploaded from device when docked				e31b578658c642f8b50e1e6074b38ce8
45:10.0	Video deleted from device when docked	82	12	50.607	e31b578658c642f8b50e1e6074b38ce8
45:10.1	Audit log rolled	82	12		50.608
45:10.1	Audit log created	82	12	1.13.32	50.608
45:10.3	Video upload started when camera was docked				572add2f8b654128bbe60ccefc33a239
48:43.9	Video successfully uploaded from device when docked				572add2f8b654128bbe60ccefc33a239
48:44.3	Video deleted from device when docked	84	11	51.413	572add2f8b654128bbe60ccefc33a239
48:44.3	Audit log rolled	84	11		51.413
48:44.3	Audit log created	84	11	1.13.32	51.413
48:44.5	Video upload started when camera was docked				36fc741c3d4e4bb7a4baa5a1c32c5e2f
49:30.9	Video successfully uploaded from device when docked				36fc741c3d4e4bb7a4baa5a1c32c5e2f
49:31.1	Video deleted from device when docked	84	10	51.584	36fc741c3d4e4bb7a4baa5a1c32c5e2f
49:31.2	Audit log rolled	84	10		51.584
49:31.2	Audit log created	84	10	1.13.32	51.584
49:31.4	Video upload started when camera was docked				eba47c9cebbd437183521d307b20d2cc
55:34.8	Video successfully uploaded from device when docked				eba47c9cebbd437183521d307b20d2cc
55:35.2	Video deleted from device when docked	87	9	52.931	eba47c9cebbd437183521d307b20d2cc
55:35.3	Audit log created	87	9	1.13.32	52.931
55:35.3	Audit log rolled	87	9		52.931
55:35.4	Video upload started when camera was docked				71ba4a85c40d4c13bae977121ebe5bac
58:24.4	Video successfully uploaded from device when docked				71ba4a85c40d4c13bae977121ebe5bac
58:24.8	Video deleted from device when docked	88	8	53.567	71ba4a85c40d4c13bae977121ebe5bac
58:24.8	Audit log rolled	88	8		53.568
58:24.8	Audit log created	88	8	1.13.32	53.568
58:25.0	Video upload started when camera was docked				908de0c3c75b479694d84cd0e1aa8ceb
00:06.0	Video successfully uploaded from device when docked				908de0c3c75b479694d84cd0e1aa8ceb
00:06.4	Video deleted from device when docked	89	7	53.945	908de0c3c75b479694d84cd0e1aa8ceb
00:06.5	Audit log created	89	7	1.13.32	53.945
00:06.5	Audit log rolled	89	7		53.945
00:06.7	Video upload started when camera was docked				4e9cbc4b1eb54fed9854e1a52e366114
00:42.9	Video successfully uploaded from device when docked				4e9cbc4b1eb54fed9854e1a52e366114
00:43.2	Video deleted from device when docked	89	6	54.081	4e9cbc4b1eb54fed9854e1a52e366114

00:43.3	Audit log rolled	89	6	54.081	
00:43.3	Audit log created	89	6 1.13.32	54.081	
00:43.5	Video upload started when camera was docked				31b44a65ca344b638f6e6f738f59cd61
02:42.0	Date/Time synced to 06/13/2021 04:02:42.02 AM from 06/13/2021 04:02:41.04 AM				
02:55.7	Video successfully uploaded from device when dockec				31b44a65ca344b638f6e6f738f59cd61
02:56.1	Video deleted from device when docked	90	5	54.561	31b44a65ca344b638f6e6f738f59cd61
02:56.1	Audit log rolled	90	5	54.561	
02:56.1	Audit log created	90	5 1.13.32	54.561	
02:56.4	Video upload started when camera was docked				427d346954b14f078f2f2854527d23d7
03:38.6	Video successfully uploaded from device when dockec				427d346954b14f078f2f2854527d23d7
03:38.8	Video deleted from device when docked	90	4	54.716	427d346954b14f078f2f2854527d23d7
03:38.9	Audit log created	90	4 1.13.32	54.716	
03:38.9	Audit log rolled	90	4	54.716	
03:39.1	Video upload started when camera was docked				515e261639e54e3ca8f0ee8445d4ce28
04:05.1	Video successfully uploaded from device when dockec				515e261639e54e3ca8f0ee8445d4ce28
04:05.3	Video deleted from device when docked	90	3	54.813	515e261639e54e3ca8f0ee8445d4ce28
04:05.4	Audit log created	90	3 1.13.32	54.814	
04:05.4	Audit log rolled	90	3	54.814	
04:05.6	Video upload started when camera was docked				ae652959325e48c588f74fea67149669
04:32.0	Video successfully uploaded from device when dockec				ae652959325e48c588f74fea67149669
04:32.2	Video deleted from device when docked	90	2	54.912	ae652959325e48c588f74fea67149669
04:32.3	Audit log created	90	2 1.13.32	54.912	
04:32.3	Audit log rolled	90	2	54.912	
04:32.5	Video upload started when camera was docked				7a0f9ad2b8964685b5b934b1ba01ec65
04:49.7	Video successfully uploaded from device when dockec				7a0f9ad2b8964685b5b934b1ba01ec65
04:49.9	Video deleted from device when docked	91	1	54.978	7a0f9ad2b8964685b5b934b1ba01ec65
04:50.0	Audit log rolled	91	1	54.978	
04:50.0	Audit log created	91	1 1.13.32	54.978	
04:50.2	Video upload started when camera was docked				7ce35323ee2c4dfe9131fba3472ae017
05:08.4	Video successfully uploaded from device when dockec				7ce35323ee2c4dfe9131fba3472ae017
05:08.6	Video deleted from device when docked	91	0	55.044	7ce35323ee2c4dfe9131fba3472ae017
05:08.6	Audit log rolled	91	0	55.045	
05:08.6	Audit log created	91	0 1.13.32	55.045	
05:08.7	Audit log created	91	0 1.13.32	55.045	
05:08.7	Audit log rolled	91	0	55.045	
22:03.5	Device disconnected from charger	97	0	55.044	
22:03.7	Camera disconnected from Axon Dock X62001W9H	97	0	55.044	
43:41.4	Axon application connected to device				
43:55.2	Axon application disconnected from device				
05:08.0	Audit log created	91	0 1.13.32	55.046	
05:08.0	Audit log created	85	0 1.13.32	55.045	
23:58.6	Power button pressed				
24:01.8	Device powered off using button	84	0	55.045	
24:02.2	Power button released				
24:08.1	Audit log created	84	0 1.13.32	55.045	
24:08.1	Audit log rolled	84	0	55.045	
24:08.5	Device connected to charger	84	0	55.045	

25:06.0 Device connected to charger				
25:06.0 Device powered on due to charger connection	84	0	55.045	
25:06.0 Camera connected to Axon Dock X630020W7	85	0	55.045	
25:06.1 Audit log created		1.13.32		
25:06.1 Audit log rolled				
25:07.0 Camera connected to Axon Dock X630020W7	85	0	55.045	
25:08.9 Audit log created	84	0 1.13.32	55.045	
25:08.9 Audit log rolled	84	0	55.045	
25:08.0 Audit log created	100	0 1.13.32	55.051	
25:08.0 Audit log created	100	0 1.13.32	55.058	
25:08.0 Audit log created	100	0 1.13.32	55.058	
25:08.0 Audit log created	100	0 1.13.32	55.058	
25:08.0 Audit log created	100	0 1.13.32	55.058	
25:08.0 Audit log created	100	0 1.13.32	55.058	
25:08.1 Audit log created	100	0 1.13.32	55.058	
25:08.1 Audit log created	100	0 1.13.32	55.058	
25:08.1 Audit log created	100	0 1.13.32	55.057	
25:08.1 Audit log created	100	0 1.13.32	55.057	
25:08.1 Audit log created	100	0 1.13.32	55.057	
00:47.0 Device disconnected from charger	98	0	55.056	
00:47.1 Camera disconnected from Axon Dock X630020W7	100	0	55.056	
00:47.1 Audio recording disabled due to video buffering default				
00:49.1 Power button pressed				
00:52.1 Device powered off using button	100	0	55.057	
00:52.6 Power button released				
33:12.1 Audit log created		1.13.32		
33:12.2 Device powered on using button	100	0	55.057	
33:15.2 Audio recording disabled due to video buffering default				
33:12.1 Audit log created	93	0 1.13.32	55.056	
48:15.4 Volume up button pressed				
48:15.6 Volume up button released				
33:12.2 Audit log created	87	0 1.13.32	55.054	
33:12.2 Audit log created	82	0 1.13.32	55.053	
42:47.6 Event button pressed				
42:47.6 Event button released				
42:47.7 Event button pressed				
42:47.7 Audio recording enabled due to video recording default				
42:47.8 Event button released				
42:47.9 Recording started due to button press	80	1	55.052	ed856bc3aa4b4461b9cddb732fb0658d
43:13.7 Event button pressed				
43:16.7 Recording stopped due to button press	80	1	54.988	ed856bc3aa4b4461b9cddb732fb0658d
43:17.5 Event button released				
43:17.7 Audio recording disabled due to video buffering default				
43:24.4 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 2342 X6033271L' using Axon application				ed856bc3aa4b4461b9cddb732fb0658d
59:26.5 Event button pressed				
59:26.6 Event button released				

59:26.6	Event button pressed			
59:26.6	Audio recording enabled due to video recording default			
59:26.7	Event button released			
59:26.8	Event button pressed			
59:26.8	Recording started due to button press	79	2	54.976 4bbbba1039d940afac9b0ec31365318d
59:26.9	Event button released			
00:02.7	Event button pressed			
00:05.7	Recording stopped due to button press	78	2	54.895 4bbbba1039d940afac9b0ec31365318d
00:06.1	Event button released			
00:06.5	Audio recording disabled due to video buffering default			
00:06.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-13 2359 X6033271L' using Axon applicator			4bbbba1039d940afac9b0ec31365318d
33:12.2	Audit log created	76	2 1.13.32	54.894
39:29.2	Volume up button pressed			
39:29.4	Volume up button released			
04:53.4	Volume up button pressed			
04:53.8	Volume up button released			
04:59.3	Volume up button pressed			
04:59.5	Volume up button released			
11:00.5	Volume up button pressed			
11:01.0	Volume up button released			
23:01.3	Event button pressed			
23:01.5	Event button released			
23:01.6	Event button pressed			
23:01.6	Audio recording enabled due to video recording default			
23:01.7	Recording started due to button press	71	3	54.893 7051a6ac0ab849aba1f7e2fc9ef54e23
23:01.7	Event button released			
23:56.9	Event button pressed			
23:59.9	Recording stopped due to button press	71	3	54.802 7051a6ac0ab849aba1f7e2fc9ef54e23
24:00.5	Event button released			
24:00.7	Audio recording disabled due to video buffering default			
24:00.8	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-14 0123 X6033271L' using Axon applicator			7051a6ac0ab849aba1f7e2fc9ef54e23
33:12.2	Audit log created	70	3 1.13.32	54.801
44:10.7	Event button pressed			
44:10.9	Event button released			
44:10.9	Event button pressed			
44:11.0	Audio recording enabled due to video recording default			
44:11.0	Event button released			
44:11.1	Recording started due to button press	69	4	54.801 63fb46d2e8aa488b9e507194484f1edd
45:25.6	Event button pressed			
45:28.6	Recording stopped due to button press	68	4	54.699 63fb46d2e8aa488b9e507194484f1edd
45:29.4	Audio recording disabled due to video buffering default			
45:29.4	Event button released			
45:29.5	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-14 0144 X6033271L' using Axon applicator			63fb46d2e8aa488b9e507194484f1edd
46:14.7	Event button pressed			
46:14.9	Event button released			
46:15.0	Event button pressed			
46:15.0	Audio recording enabled due to video recording default			

46:15.1	Event button released			
46:15.1	Recording started due to button press	68	5	54.698 ba8df91b311a4168ac6f07969e27acd2
46:32.6	Event button pressed			
46:35.6	Recording stopped due to button press	68	5	54.664 ba8df91b311a4168ac6f07969e27acd2
46:36.2	Event button released			
46:36.4	Audio recording disabled due to video buffering default			
46:36.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-14 0146 X6033271L' using Axon applicator			ba8df91b311a4168ac6f07969e27acd2
49:00.1	Event button pressed			
49:00.2	Event button released			
49:00.3	Event button pressed			
49:00.4	Audio recording enabled due to video recording default			
49:00.4	Event button released			
49:00.5	Recording started due to button press	68	6	54.664 3e3d14f061fc479bb11ec4ce15112cb4
51:10.2	Event button pressed			
51:13.2	Recording stopped due to button press	67	6	54.533 3e3d14f061fc479bb11ec4ce15112cb4
51:14.0	Event button released			
51:14.2	Audio recording disabled due to video buffering default			
51:14.3	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-14 0149 X6033271L' using Axon applicator			3e3d14f061fc479bb11ec4ce15112cb4
33:12.2	Audit log created	63	6 1.13.32	54.532
33:12.2	Audit log created	57	6 1.13.32	54.53
33:12.2	Audit log created	50	6 1.13.32	54.529
33:12.3	Audit log created	44	6 1.13.32	54.528
21:07.6	Power button pressed			
21:10.6	Device powered off using button	39	6	54.527
21:11.0	Power button released			
21:11.9	Select button pressed			
21:12.1	Select button released			
21:15.9	Audit log created	39	6 1.13.32	54.527
21:15.9	Audit log rolled	39	6	54.527
21:17.2	Device connected to charger	39	6	54.526
22:00.1	Device connected to charger			
22:00.1	Device powered on due to charger connection	39	6	54.526
22:00.1	Camera connected to Axon Dock X630020W7	39	6	54.526
22:00.1	Audit log rolled			
22:00.1	Audit log created		1.13.32	
22:01.0	Camera connected to Axon Dock X630020W7	40	6	54.526
22:03.0	Audit log created	39	6 1.13.32	54.526
22:03.0	Audit log rolled	39	6	54.526
22:02.0	Audit log created	66	6 1.13.32	54.525
22:02.0	Audit log created	93	6 1.13.32	54.525
22:02.0	Audit log created	100	6 1.13.32	54.531
22:02.0	Audit log created	100	6 1.13.32	54.535
22:02.0	Audit log created	100	6 1.13.32	54.535
22:02.0	Audit log created	100	6 1.13.32	54.535
22:02.0	Audit log created	100	6 1.13.32	54.535
22:02.0	Audit log created	100	6 1.13.32	54.535
22:02.1	Audit log created	100	6 1.13.32	54.535
22:02.1	Audit log created	100	6 1.13.32	54.534

22:02.1	Audit log created	100	6 1.13.32	54.534
22:02.1	Audit log created	100	6 1.13.32	54.534
22:02.1	Audit log created	100	6 1.13.32	54.534
17:57.4	Volume up button pressed			
17:57.7	Volume up button released			
17:57.9	Camera disconnected from Axon Dock X630020W7	100	6	54.533
17:57.9	Audio recording disabled due to video buffering default			
17:58.0	Device disconnected from charger	100	6	54.533
17:58.6	Power button pressed			
18:01.6	Device powered off using button	100	6	54.54
18:02.0	Power button released			
32:11.1	Audit log created		1.13.32	
32:11.2	Device powered on using button	100	6	54.539
32:13.2	Audio recording disabled due to video buffering default			
33:29.7	Select button pressed			
33:30.9	Select button released			
33:31.8	Programmable button pressed			
33:32.3	Select button pressed			
33:36.3	Programmable button released			
33:36.6	Select button released			
33:43.8	Volume up button pressed			
33:44.5	Programmable button pressed			
33:46.9	Led brightness mode changed to Off from Dim			
33:46.9	Front led disabled using button			
33:46.9	Top led disabled using button			
33:47.5	Programmable button released			
33:47.7	Volume up button released			
33:49.0	Volume up button pressed			
33:49.2	Programmable button pressed			
33:50.5	Programmable button released			
33:50.6	Volume up button released			
33:52.4	Volume up button pressed			
33:52.7	Volume up button released			
33:52.7	Volume up button pressed			
33:52.8	Volume up button released			
34:03.7	Select button pressed			
34:09.0	Select button released			
34:09.0	Volume up button released			
34:11.9	Volume down button pressed			
34:12.4	Select button pressed			
34:16.5	Volume down button released			
34:16.5	Select button released			
34:17.6	Programmable button pressed			
34:18.0	Select button pressed			
34:21.4	Programmable button released			
34:21.5	Select button released			
34:23.2	Volume up button pressed			

34:23.3 Volume down button pressed
34:24.6 Volume down button released
34:25.5 Volume up button released
34:26.3 Programmable button pressed
34:28.4 Programmable button released
34:31.6 Programmable button pressed
34:33.8 Programmable button released
34:35.2 Volume up button pressed
34:37.4 Volume up button released
34:39.3 Volume up button pressed
34:39.6 Volume up button released
34:42.5 Select button pressed
34:43.0 Programmable button pressed
34:49.6 Programmable button released
34:49.7 Select button released
34:51.2 Programmable button pressed
34:51.5 Programmable button released
34:51.9 Programmable button pressed
34:52.0 Programmable button released
34:53.0 Select button pressed
34:56.7 Select button released
35:00.6 Volume up button pressed
35:01.5 Volume up button released
35:04.8 Select button pressed
35:05.0 Programmable button pressed
35:07.7 Programmable button released
35:07.8 Select button released
35:08.6 Programmable button pressed
35:09.5 Programmable button released
35:10.8 Programmable button pressed
35:11.0 Programmable button released
32:11.1 Audit log created
53:25.0 Select button pressed
53:25.0 Volume down button pressed
53:33.6 Volume down button released
53:33.7 Select button released
53:34.9 Select button pressed
53:35.0 Programmable button pressed
53:41.6 Programmable button released
53:41.6 Select button released
53:43.6 Volume up button pressed
53:43.7 Programmable button pressed
53:46.0 Programmable button released
53:46.1 Volume up button released
53:59.2 Select button pressed
53:59.8 Programmable button pressed
54:00.9 Programmable button released

93

6 1.13.32

54.537

54:00.9 Select button released
54:02.8 Volume down button pressed
54:04.2 Select button pressed
54:08.3 Select button released
54:08.3 Volume down button released
54:28.6 Select button pressed
54:28.6 Programmable button pressed
54:29.0 Programmable button released
54:29.0 Select button released
54:33.6 Select button pressed
54:34.1 Programmable button pressed
54:34.3 Programmable button released
54:34.4 Select button released
54:36.6 Select button pressed
54:36.6 Programmable button pressed
54:36.9 Programmable button released
54:36.9 Select button released
54:38.1 Select button pressed
54:38.1 Programmable button pressed
54:38.3 Programmable button released
54:38.4 Select button released
54:40.5 Select button pressed
54:40.5 Programmable button pressed
54:43.7 Select button released
54:46.8 Select button pressed
54:47.2 Programmable button pressed
54:47.8 Programmable button released
54:47.8 Select button released
54:49.9 Select button pressed
54:50.1 Programmable button pressed
54:51.0 Select button released
54:51.0 Programmable button released
54:51.7 Select button pressed
54:51.7 Programmable button pressed
54:53.3 Programmable button released
54:55.4 Select button pressed
54:55.5 Programmable button pressed
54:57.2 Programmable button released
54:57.2 Select button released
54:58.3 Select button pressed
54:58.4 Programmable button pressed
55:01.4 Select button released
55:01.5 Programmable button released
55:18.6 Select button pressed
55:18.7 Event button pressed
55:19.6 Event button released
55:19.6 Select button released

55:21.6 Select button pressed
55:21.6 Event button pressed
55:24.7 Select button released
55:24.7 Event button released
55:27.2 Programmable button pressed
55:27.2 Event button pressed
55:28.6 Event button released
55:28.6 Programmable button released
58:02.5 Select button pressed
58:02.7 Event button pressed
58:03.8 Event button released
58:03.8 Select button released
58:06.0 Programmable button pressed
58:06.1 Event button pressed
58:08.1 Programmable button released
58:08.1 Event button released
04:44.7 Programmable button pressed
04:44.7 Event button pressed
04:48.2 Event button released
04:48.3 Programmable button released
04:49.8 Programmable button pressed
04:49.9 Event button pressed
04:53.5 Event button released
04:53.5 Programmable button released
04:54.3 Programmable button pressed
04:54.3 Event button pressed
04:54.6 Event button released
04:54.7 Programmable button released
12:55.0 Programmable button pressed
12:55.0 Event button pressed
12:55.8 Event button released
12:55.9 Programmable button released
13:54.2 Axon application connected to device
14:52.6 Title changed in video metadata from 'Axon Body 3 Video 2021-06-14 0149 X6033271L' to 'Sig. 70 NE10' using Axon applicator
14:52.6 Categories 'Loitering' added to video metadata using Axon applicator
15:39.8 Title changed in video metadata from 'Axon Body 3 Video 2021-06-14 0146 X6033271L' to 'Sig. 70 NE10' using Axon applicator
15:39.8 Categories 'Loitering' added to video metadata using Axon applicator
16:29.4 Title changed in video metadata from 'Axon Body 3 Video 2021-06-14 0144 X6033271L' to 'Clearing Trains NE10' using Axon applicator
16:29.4 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator
17:16.8 Title changed in video metadata from 'Axon Body 3 Video 2021-06-14 0123 X6033271L' to 'Clearing Trains NE10' using Axon applicator
17:16.8 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator
17:58.9 Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 2359 X6033271L' to 'Clearing Trains NE10' using Axon applicator
17:58.9 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator
18:51.9 Title changed in video metadata from 'Axon Body 3 Video 2021-06-13 2342 X6033271L' to 'Clearing Trains NE10' using Axon applicator
18:51.9 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator
19:37.2 Axon application disconnected from device
19:54.2 Select button pressed

3e3d14f061fc479bb11ec4ce15112cb4
3e3d14f061fc479bb11ec4ce15112cb4
ba8df91b311a4168ac6f07969e27acd2
ba8df91b311a4168ac6f07969e27acd2
63fb46d2e8aa488b9e507194484f1edd
63fb46d2e8aa488b9e507194484f1edd
7051a6ac0ab849aba1f7e2fc9ef54e23
7051a6ac0ab849aba1f7e2fc9ef54e23
4bbba1039d940afac9b0ec31365318d
4bbba1039d940afac9b0ec31365318d
ed856bc3aa4b4461b9cddb732fb0658d
ed856bc3aa4b4461b9cddb732fb0658d

19:54.8 Programmable button pressed
19:59.9 Programmable button released
20:00.0 Select button released
20:03.5 Volume up button pressed
20:03.6 Programmable button pressed
20:05.4 Programmable button released
20:05.4 Volume up button released
20:05.9 Programmable button pressed
20:05.9 Volume up button pressed
20:07.3 Programmable button released
20:07.5 Volume up button released
20:08.4 Volume up button pressed
20:10.5 Volume up button released
20:11.1 Volume up button pressed
20:14.1 Led brightness mode changed to Auto from Off
20:14.3 Front led auto brightness enabled using button
20:14.3 Top led auto brightness enabled using button
20:14.3 Front led brightness changed to 0% from 1% using ambient light change
20:14.3 Top led brightness changed to 0% from 1% using ambient light change
20:14.3 Front led enabled using button
20:14.3 Top led enabled using button
20:14.3 Volume up button released
20:23.4 Volume up button pressed
20:26.4 Led brightness mode changed to Dim from Auto
20:26.4 Front led auto brightness disabled using button
20:26.5 Top led auto brightness disabled using button
20:26.5 Front led brightness changed to 1% from 0% using button
20:26.5 Top led brightness changed to 1% from 0% using button
20:29.5 Volume up button released
20:38.3 Volume up button pressed
20:38.5 Volume up button released
20:38.8 Volume up button pressed
20:39.0 Volume up button released
20:39.1 Volume up button pressed
20:39.3 Volume up button released
20:41.4 Volume down button pressed
20:41.6 Volume down button released
20:41.7 Volume changed to high from very high using button
20:42.2 Volume down button pressed
20:42.3 Volume down button released
20:42.4 Volume changed to medium from high using button
20:44.5 Volume up button pressed
20:44.7 Volume up button released
20:44.8 Volume changed to high from medium using button
20:45.3 Volume up button pressed
20:45.4 Volume up button released
20:45.5 Volume changed to very high from high using button

20:57.2	Select button pressed			
20:57.3	Select button released			
32:11.1	Audit log created	87	6 1.13.32	54.535
46:49.2	Volume up button pressed			
46:50.4	Volume up button released			
46:54.2	Volume up button pressed			
46:54.9	Volume up button released			
18:15.5	Volume up button pressed			
18:15.8	Volume up button released			
24:58.1	Event button pressed			
24:58.3	Event button released			
24:58.4	Event button pressed			
24:58.4	Audio recording enabled due to video recording default			
24:58.5	Event button released			
24:58.6	Recording started due to button press	82	7	54.533 1c61ba2a5a4f44f1919a6f8da47b5ad0
25:51.3	Event button pressed			
25:54.3	Recording stopped due to button press	82	7	54.444 1c61ba2a5a4f44f1919a6f8da47b5ad0
25:55.1	Audio recording disabled due to video buffering default			
25:55.2	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-15 0124 X6033271L' using Axon applicator			1c61ba2a5a4f44f1919a6f8da47b5ad0
25:55.3	Event button released			
32:11.1	Audit log created	82	7 1.13.32	54.443
01:25.3	Event button pressed			
01:25.4	Event button released			
01:25.5	Event button pressed			
01:25.5	Audio recording enabled due to video recording default			
01:25.6	Event button released			
01:25.7	Recording started due to button press	79	8	54.442 fef5e56e65e842d8b64bf5235595980f
13:59.2	Event button pressed			
14:02.2	Recording stopped due to button press	77	8	53.983 fef5e56e65e842d8b64bf5235595980f
14:03.2	Audio recording disabled due to video buffering default			
14:03.5	Event button released			
14:03.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-15 0201 X6033271L' using Axon applicator			fef5e56e65e842d8b64bf5235595980f
32:11.1	Audit log created	75	8 1.13.32	53.98
32:11.1	Audit log created	70	8 1.13.32	53.979
24:59.5	Volume up button pressed			
24:59.7	Volume up button released			
25:54.2	Volume up button pressed			
25:54.4	Volume up button released			
32:11.1	Audit log created	63	8 1.13.32	53.978
32:11.1	Audit log created	58	8 1.13.32	53.976
18:11.3	Camera connected to Axon Dock X630020W7	52	8	53.976
18:11.3	Audit log created	52	8 1.13.32	53.975
18:11.3	Audit log rolled	52	8	53.975
18:12.2	Device connected to charger	52	8	53.976
18:11.0	Audit log created	80	8 1.13.32	53.975
18:11.0	Audit log created	100	8 1.13.32	53.974
18:11.0	Audit log created	100	8 1.13.32	53.979

18:11.0 Audit log created	100	8 1.13.32	53.984
18:11.0 Audit log created	100	8 1.13.32	53.984
18:11.1 Audit log created	100	8 1.13.32	53.984
18:11.1 Audit log created	100	8 1.13.32	53.984
18:11.1 Audit log created	100	8 1.13.32	53.983
18:11.1 Audit log created	100	8 1.13.32	53.983
18:11.1 Audit log created	100	8 1.13.32	53.983
18:11.1 Audit log created	100	8 1.13.32	53.982
18:11.1 Audit log created	100	8 1.13.32	53.982
18:11.1 Audit log created	100	8 1.13.32	53.982
18:11.1 Audit log created	100	8 1.13.32	53.982
18:11.1 Audit log created	100	8 1.13.32	53.981
05:57.6 Camera disconnected from Axon Dock X630020W7	98	8	53.981
05:58.2 Device disconnected from charger	100	8	53.987
05:58.9 Power button pressed			
06:01.9 Device powered off using button	100	8	53.987
06:02.4 Power button released			
02:31.0 Audit log created		1.13.32	
02:31.1 Device powered on using button	100	8	53.986
02:33.0 Audio recording disabled due to video buffering default			
02:50.2 Select button pressed			
02:50.4 Event button pressed			
02:53.4 Event button released			
02:53.4 Select button released			
02:54.8 Select button pressed			
02:54.9 Event button pressed			
02:59.6 Select button released			
02:59.6 Event button released			
03:00.7 Select button pressed			
03:01.1 Event button pressed			
03:04.9 Event button released			
03:04.9 Select button released			
03:05.8 Programmable button pressed			
03:05.8 Event button pressed			
03:09.9 Event button released			
03:11.0 Programmable button pressed			
03:11.0 Event button pressed			
03:11.3 Event button released			
03:11.3 Programmable button released			
04:53.7 Programmable button pressed			
04:53.8 Event button pressed			
04:57.1 Event button released			
04:57.1 Programmable button released			
04:58.8 Programmable button pressed			
04:58.8 Event button pressed			
05:01.4 Event button released			
06:44.8 Volume down button pressed			
06:45.8 Volume down button released			

06:46.0 Volume changed to high from very high using button
06:46.0 Volume down button pressed
06:46.3 Volume down button released
06:46.4 Volume changed to medium from high using button
06:46.4 Volume down button pressed
06:46.7 Volume down button released
06:46.8 Volume changed to low from medium using button
06:50.3 Programmable button pressed
06:50.4 Event button pressed
06:54.7 Event button released
06:54.7 Programmable button released
06:55.5 Programmable button pressed
06:55.5 Event button pressed
06:59.8 Event button released
06:59.8 Programmable button released
07:01.1 Programmable button pressed
07:01.2 Event button pressed
07:04.6 Event button released
07:04.7 Programmable button released
07:06.3 Programmable button pressed
07:06.3 Event button pressed
07:11.7 Event button released
07:11.7 Programmable button released
07:15.3 Volume down button pressed
07:15.4 Event button pressed
07:18.3 Event button released
07:18.4 Volume down button released
07:19.0 Event button pressed
07:19.0 Volume down button pressed
07:20.1 Event button released
07:20.1 Volume down button released
07:21.1 Programmable button pressed
07:21.1 Event button pressed
07:22.4 Event button released
07:22.5 Programmable button released
08:17.9 Event button pressed
08:18.0 Event button released
08:21.5 Volume up button pressed
08:21.7 Volume up button released
08:21.8 Volume changed to medium from low using button
08:24.5 Volume down button pressed
08:24.7 Volume down button released
08:24.8 Volume changed to low from medium using button
09:04.6 Programmable button pressed
09:04.6 Event button pressed
09:06.0 Event button released
09:06.0 Programmable button released

09:47.1 Axon application connected to device				
11:13.2 Title changed in video metadata from 'Axon Body 3 Video 2021-06-15 0124 X6033271L' to 'Clearing Train NE10' using Axon applicator				1c61ba2a5a4f44f1919a6f8da47b5ad0
11:13.2 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				1c61ba2a5a4f44f1919a6f8da47b5ad0
12:00.6 Title changed in video metadata from 'Axon Body 3 Video 2021-06-15 0201 X6033271L' to 'Clearing Train NE10' using Axon applicator				fef5e56e65e842d8b64bf5235595980f
12:00.6 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				fef5e56e65e842d8b64bf5235595980f
13:17.6 Volume changed to medium from low using Axon application				
13:49.5 Volume up button pressed				
13:49.8 Volume up button released				
13:49.9 Volume changed to high from medium using button				
13:51.2 Volume up button pressed				
13:51.3 Volume up button released				
13:51.4 Volume changed to very high from high using button				
13:55.9 Volume up button pressed				
13:56.1 Volume up button released				
13:58.9 Volume down button pressed				
13:59.1 Volume down button released				
13:59.2 Volume changed to high from very high using button				
14:00.2 Volume down button pressed				
14:00.3 Volume down button released				
14:00.4 Volume changed to medium from high using button				
14:30.6 Power button pressed				
14:33.6 Device powered off using button	98	8		53.984
14:34.1 Power button released				
14:39.9 Axon application disconnected from device				
02:50.0 Audit log created			1.13.32	
02:50.1 Device powered on using button	98	8		53.984
02:53.2 Audio recording disabled due to video buffering default				
02:50.1 Audit log created	91	8	1.13.32	53.983
53:38.6 Power button pressed				
53:41.6 Device powered off using button	86	8		53.982
53:42.1 Power button released				
07:40.1 Audit log created			1.13.32	
07:40.2 Device powered on due to charger connection	86	8		53.981
07:40.2 Camera connected to Axon Dock X630020W7	86	8		53.981
07:40.2 Audit log rolled				
07:40.2 Audit log created			1.13.32	
07:41.2 Camera connected to Axon Dock X630020W7	87	8		53.981
07:41.2 Device connected to charger	86	8		53.981
07:44.1 Audit log created	86	8	1.13.32	53.981
07:44.1 Audit log rolled	86	8		53.981
07:44.0 Audit log created	100	8	1.13.32	53.98
07:44.0 Audit log created	100	8	1.13.32	53.98
07:44.0 Audit log created	100	8	1.13.32	53.98
07:44.0 Audit log created	100	8	1.13.32	53.979
07:44.1 Audit log created	100	8	1.13.32	53.979
07:44.1 Audit log created	100	8	1.13.32	53.978
07:44.1 Audit log created	100	8	1.13.32	53.978

07:44.1	Audit log created	100	8 1.13.32	53.978	
07:44.1	Audit log created	100	8 1.13.32	53.978	
07:44.1	Audit log created	100	8 1.13.32	53.978	
07:44.1	Audit log created	100	8 1.13.32	53.978	
07:44.1	Audit log created	100	8 1.13.32	53.978	
07:44.1	Audit log created	100	8 1.13.32	53.977	
07:44.1	Audit log created	100	8 1.13.32	53.977	
07:44.2	Audit log created	100	8 1.13.32	53.977	
07:44.2	Audit log created	100	8 1.13.32	53.977	
07:44.2	Audit log created	100	8 1.13.32	53.976	
07:44.2	Audit log created	100	8 1.13.32	53.976	
07:44.2	Audit log created	100	8 1.13.32	53.976	
07:44.2	Audit log created	100	8 1.13.32	53.976	
07:44.2	Audit log created	100	8 1.13.32	53.975	
07:44.2	Audit log created	100	8 1.13.32	53.975	
07:44.3	Audit log created	100	8 1.13.32	53.976	
17:48.8	Camera disconnected from Axon Dock X630020W7	100	8	53.975	
17:48.9	Audio recording disabled due to video buffering default				
17:49.2	Device disconnected from charger	100	8	53.977	
05:21.1	Volume up button pressed				
05:21.1	Volume up button released				
05:21.3	Volume changed to high from medium using button				
07:44.3	Audit log created	94	8 1.13.32	53.98	
37:07.4	Audit log created	91	8 1.13.32	53.98	
37:07.4	Audit log rolled	91	8	53.98	
37:07.4	Camera connected to Axon Dock X62001V12	91	8	54.014	
37:08.2	Device connected to charger	91	8	53.98	
37:32.6	Video upload started when camera was docked				ed856bc3aa4b4461b9cddb732fb0658d
37:44.0	Date/Time synced to 06/18/2021 08:37:44.02 PM from 06/18/2021 08:37:37.47 PM				
37:46.6	Audit log successfully uploaded				
37:46.9	Audit log successfully uploaded and deleted from device	91	8	54.014	
38:01.2	Audit log successfully uploaded				
38:01.5	Audit log successfully uploaded and deleted from device	91	8	54.014	
38:02.0	Video successfully uploaded from device when dockec				ed856bc3aa4b4461b9cddb732fb0658d
38:02.2	Video deleted from device when docked	91	7	54.09	ed856bc3aa4b4461b9cddb732fb0658d
38:02.3	Audit log created	91	7 1.13.32	54.09	
38:02.3	Audit log rolled	91	7	54.09	
38:02.6	Video upload started when camera was docked				4bbba1039d940afac9b0ec31365318d
38:12.0	Audit log successfully uploaded				
38:12.3	Audit log successfully uploaded and deleted from device	91	7	54.09	
38:17.0	Audit log successfully uploaded				
38:17.5	Audit log successfully uploaded and deleted from device	91	7	54.09	
38:26.4	Video successfully uploaded from device when dockec				4bbba1039d940afac9b0ec31365318d
38:26.7	Video deleted from device when docked	91	6	54.171	4bbba1039d940afac9b0ec31365318d
38:26.7	Audit log created	91	6 1.13.32	54.171	
38:26.7	Audit log rolled	91	6	54.171	
38:27.0	Video upload started when camera was docked				7051a6ac0ab849aba1f7e2fc9ef54e23

38:28.5	Audit log successfully uploaded			
38:28.7	Audit log successfully uploaded and deleted from device	91	6	54.171
38:39.6	Audit log successfully uploaded			
38:39.8	Audit log successfully uploaded and deleted from device	92	6	54.171
38:42.0	Audit log successfully uploaded			
38:42.2	Audit log successfully uploaded and deleted from device	92	6	54.171
38:53.8	Video successfully uploaded from device when dockec			7051a6ac0ab849aba1f7e2fc9ef54e23
38:54.0	Video deleted from device when docked	92	5	54.262 7051a6ac0ab849aba1f7e2fc9ef54e23
38:54.1	Audit log created	92	5 1.13.32	54.263
38:54.1	Audit log rolled	92	5	54.263
38:54.3	Video upload started when camera was docked			63fb46d2e8aa488b9e507194484f1edd
38:57.9	Audit log successfully uploaded			
38:58.2	Audit log successfully uploaded and deleted from device	92	5	54.263
38:58.4	Audit log successfully uploaded			
38:58.6	Audit log successfully uploaded and deleted from device	92	5	54.263
38:59.4	Audit log successfully uploaded			
38:59.6	Audit log successfully uploaded and deleted from device	92	5	54.263
39:09.8	Audit log successfully uploaded			
39:10.0	Audit log successfully uploaded and deleted from device	92	5	54.263
39:21.1	Audit log successfully uploaded			
39:21.3	Audit log successfully uploaded and deleted from device	92	5	54.263
39:23.4	Video successfully uploaded from device when dockec			63fb46d2e8aa488b9e507194484f1edd
39:23.7	Video deleted from device when docked	92	4	54.364 63fb46d2e8aa488b9e507194484f1edd
39:23.8	Audit log rolled	92	4	54.364
39:23.8	Audit log created	92	4 1.13.32	54.364
39:24.0	Video upload started when camera was docked			ba8df91b311a4168ac6f07969e27acd2
39:27.7	Audit log successfully uploaded			
39:28.0	Audit log successfully uploaded and deleted from device	92	4	54.364
39:32.5	Audit log successfully uploaded			
39:32.7	Audit log successfully uploaded and deleted from device	92	4	54.364
39:34.6	Video successfully uploaded from device when dockec			ba8df91b311a4168ac6f07969e27acd2
39:34.9	Video deleted from device when docked	92	3	54.398 ba8df91b311a4168ac6f07969e27acd2
39:34.9	Audit log created	92	3 1.13.32	54.398
39:34.9	Audit log rolled	92	3	54.398
39:35.2	Video upload started when camera was docked			3e3d14f061fc479bb11ec4ce15112cb4
39:44.2	Audit log successfully uploaded			
39:44.4	Audit log successfully uploaded and deleted from device	92	3	54.398
39:47.6	Audit log successfully uploaded			
39:47.9	Audit log successfully uploaded and deleted from device	92	3	54.398
39:48.0	Audit log successfully uploaded			
39:48.2	Audit log successfully uploaded and deleted from device	92	3	54.398
40:01.0	Audit log successfully uploaded			
40:01.3	Audit log successfully uploaded and deleted from device	92	3	54.398
40:13.4	Video successfully uploaded from device when dockec			3e3d14f061fc479bb11ec4ce15112cb4
40:13.7	Video deleted from device when docked	92	2	54.528 3e3d14f061fc479bb11ec4ce15112cb4
40:13.7	Audit log created	92	2 1.13.32	54.529
40:13.7	Audit log rolled	92	2	54.529

40:13.9	Video upload started when camera was docked				1c61ba2a5a4f44f1919a6f8da47b5ad0
40:15.5	Audit log successfully uploaded				
40:15.7	Audit log successfully uploaded and deleted from device	92	2	54.529	
40:15.9	Audit log successfully uploaded				
40:16.2	Audit log successfully uploaded and deleted from device	92	2	54.529	
40:17.4	Audit log successfully uploaded				
40:17.6	Audit log successfully uploaded and deleted from device	92	2	54.529	
40:29.8	Audit log successfully uploaded				
40:30.0	Audit log successfully uploaded and deleted from device	92	2	54.529	
40:40.8	Video successfully uploaded from device when docked				1c61ba2a5a4f44f1919a6f8da47b5ad0
40:41.1	Video deleted from device when docked	92	1	54.618	1c61ba2a5a4f44f1919a6f8da47b5ad0
40:41.2	Audit log created	92	1	1.13.32	54.618
40:41.2	Audit log rolled	92	1		54.618
40:41.2	Audit log successfully uploaded				
40:41.4	Video upload started when camera was docked				fef5e56e65e842d8b64bf5235595980f
40:41.5	Audit log successfully uploaded and deleted from device	92	1	54.618	
40:44.4	Audit log successfully uploaded				
40:44.6	Audit log successfully uploaded and deleted from device	92	1	54.618	
40:55.8	Audit log successfully uploaded				
40:56.0	Audit log successfully uploaded and deleted from device	92	1	54.618	
41:07.3	Audit log successfully uploaded				
41:07.5	Audit log successfully uploaded and deleted from device	92	1	54.618	
41:20.6	Audit log successfully uploaded				
41:20.9	Audit log successfully uploaded and deleted from device	93	1	54.618	
41:21.1	Audit log successfully uploaded				
41:21.3	Audit log successfully uploaded and deleted from device	93	1	54.618	
41:25.2	Audit log successfully uploaded				
41:25.4	Audit log successfully uploaded and deleted from device	93	1	54.618	
41:46.5	Audit log successfully uploaded				
41:46.8	Audit log successfully uploaded and deleted from device	93	1	54.618	
41:53.6	Audit log successfully uploaded				
41:53.8	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:01.0	Audit log successfully uploaded				
42:01.2	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:13.0	Audit log successfully uploaded				
42:13.3	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:17.4	Audit log successfully uploaded				
42:17.6	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:34.4	Audit log successfully uploaded				
42:34.6	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:39.8	Audit log successfully uploaded				
42:40.1	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:42.8	Audit log successfully uploaded				
42:43.0	Audit log successfully uploaded and deleted from device	93	1	54.618	
42:53.0	Video successfully uploaded from device when docked				fef5e56e65e842d8b64bf5235595980f
42:53.4	Video deleted from device when docked	93	0	55.075	fef5e56e65e842d8b64bf5235595980f
42:53.5	Audit log created	93	0	1.13.32	55.075

42:53.5 Audit log rolled	93	0	55.075
42:53.5 Audit log rolled	93	0	55.075
42:53.5 Audit log created	93	0 1.13.32	55.075
42:59.2 Audit log successfully uploaded			
42:59.4 Audit log successfully uploaded and deleted from device	93	0	55.075
43:08.8 Audit log successfully uploaded			
43:09.0 Audit log successfully uploaded and deleted from device	93	0	55.075
43:13.6 Audit log successfully uploaded			
43:13.9 Audit log successfully uploaded and deleted from device	93	0	55.075
43:16.2 Audit log successfully uploaded			
43:16.5 Audit log successfully uploaded and deleted from device	93	0	55.075
43:30.7 Audit log successfully uploaded			
43:30.9 Audit log successfully uploaded and deleted from device	93	0	55.075
43:34.1 Audit log successfully uploaded			
43:34.4 Audit log successfully uploaded and deleted from device	93	0	55.075
43:40.6 Audit log successfully uploaded			
43:40.8 Audit log successfully uploaded and deleted from device	94	0	55.075
43:41.0 Audit log successfully uploaded			
43:41.2 Audit log successfully uploaded and deleted from device	94	0	55.075
43:52.4 Audit log successfully uploaded			
43:52.6 Audit log successfully uploaded and deleted from device	94	0	55.075
43:59.8 Audit log successfully uploaded			
44:00.1 Audit log successfully uploaded and deleted from device	94	0	55.075
44:00.2 Audit log successfully uploaded			
44:00.4 Audit log successfully uploaded and deleted from device	94	0	55.075
44:00.6 Audit log successfully uploaded			
44:00.9 Audit log successfully uploaded and deleted from device	94	0	55.075
44:18.1 Audit log successfully uploaded			
44:18.3 Audit log successfully uploaded and deleted from device	94	0	55.075
44:20.3 Audit log successfully uploaded			
44:20.5 Audit log successfully uploaded and deleted from device	94	0	55.075
44:27.5 Audit log successfully uploaded			
44:27.8 Audit log successfully uploaded and deleted from device	94	0	55.075
44:28.0 Audit log successfully uploaded			
44:28.2 Audit log successfully uploaded and deleted from device	94	0	55.075
44:29.4 Audit log successfully uploaded			
44:29.6 Audit log successfully uploaded and deleted from device	94	0	55.075
44:45.7 Audit log successfully uploaded			
44:46.0 Audit log successfully uploaded and deleted from device	94	0	55.075
44:49.9 Audit log successfully uploaded			
44:50.1 Audit log successfully uploaded and deleted from device	94	0	55.075
44:54.3 Audit log successfully uploaded			
44:54.5 Audit log successfully uploaded and deleted from device	94	0	55.075
45:06.3 Audit log successfully uploaded			
45:06.5 Audit log successfully uploaded and deleted from device	94	0	55.075
45:06.7 Audit log successfully uploaded			
45:07.0 Audit log successfully uploaded and deleted from device	94	0	55.075

45:24.7	Audit log successfully uploaded			
45:24.9	Audit log successfully uploaded and deleted from device	94	0	55.075
45:31.2	Audit log successfully uploaded			
45:31.5	Audit log successfully uploaded and deleted from device	94	0	55.075
45:43.7	Audit log successfully uploaded			
45:44.0	Audit log successfully uploaded and deleted from device	94	0	55.075
45:44.1	Audit log successfully uploaded			
45:44.3	Audit log successfully uploaded and deleted from device	94	0	55.075
45:47.5	Audit log successfully uploaded			
45:47.8	Audit log successfully uploaded and deleted from device	94	0	55.075
46:09.3	Audit log successfully uploaded			
46:09.6	Audit log successfully uploaded and deleted from device	94	0	55.075
46:11.0	Audit log successfully uploaded			
46:11.2	Audit log successfully uploaded and deleted from device	94	0	55.075
46:12.4	Audit log successfully uploaded			
46:12.7	Audit log successfully uploaded and deleted from device	94	0	55.075
46:19.7	Audit log successfully uploaded			
46:20.0	Audit log successfully uploaded and deleted from device	94	0	55.075
46:24.9	Audit log successfully uploaded			
46:25.1	Audit log successfully uploaded and deleted from device	94	0	55.075
46:27.3	Audit log successfully uploaded			
46:27.6	Audit log successfully uploaded and deleted from device	94	0	55.075
46:44.8	Audit log successfully uploaded			
46:45.0	Audit log successfully uploaded and deleted from device	94	0	55.075
46:45.2	Audit log successfully uploaded			
46:45.4	Audit log successfully uploaded and deleted from device	94	0	55.075
46:51.6	Audit log successfully uploaded			
46:51.8	Audit log successfully uploaded and deleted from device	94	0	55.075
46:53.2	Audit log successfully uploaded			
46:53.4	Audit log successfully uploaded and deleted from device	94	0	55.075
47:00.0	Audit log successfully uploaded			
47:00.3	Audit log successfully uploaded and deleted from device	94	0	55.075
47:09.7	Audit log successfully uploaded			
47:09.9	Audit log successfully uploaded and deleted from device	94	0	55.075
47:15.4	Audit log successfully uploaded			
47:15.7	Audit log successfully uploaded and deleted from device	94	0	55.075
47:15.9	Audit log successfully uploaded			
47:16.1	Audit log successfully uploaded and deleted from device	94	0	55.075
47:25.2	Audit log successfully uploaded			
47:25.4	Audit log successfully uploaded and deleted from device	94	0	55.075
47:27.7	Audit log successfully uploaded			
47:27.9	Audit log successfully uploaded and deleted from device	94	0	55.075
47:42.4	Audit log successfully uploaded			
47:42.6	Audit log successfully uploaded and deleted from device	95	0	55.075
47:54.1	Audit log successfully uploaded			
47:54.3	Audit log successfully uploaded and deleted from device	95	0	55.075
48:07.8	Audit log successfully uploaded			

48:08.1 Audit log successfully uploaded and deleted from device	95	0	55.075
48:10.5 Audit log successfully uploaded			
48:10.6 Audit log successfully uploaded and deleted from device	95	0	55.075
48:17.3 Audit log successfully uploaded			
48:17.6 Audit log successfully uploaded and deleted from device	95	0	55.075
48:27.9 Audit log successfully uploaded			
48:28.1 Audit log successfully uploaded and deleted from device	95	0	55.075
48:33.8 Audit log successfully uploaded			
48:34.0 Audit log successfully uploaded and deleted from device	95	0	55.075
48:42.2 Audit log successfully uploaded			
48:42.5 Audit log successfully uploaded and deleted from device	95	0	55.075
48:48.2 Audit log successfully uploaded			
48:48.5 Audit log successfully uploaded and deleted from device	95	0	55.075
49:10.7 Audit log successfully uploaded			
49:10.9 Audit log successfully uploaded and deleted from device	95	0	55.075
49:16.7 Audit log successfully uploaded			
49:16.9 Audit log successfully uploaded and deleted from device	95	0	55.075
49:34.1 Audit log successfully uploaded			
49:34.3 Audit log successfully uploaded and deleted from device	95	0	55.075
49:40.5 Audit log successfully uploaded			
49:40.7 Audit log successfully uploaded and deleted from device	95	0	55.075
49:43.1 Audit log successfully uploaded			
49:43.3 Audit log successfully uploaded and deleted from device	95	0	55.075
49:43.6 Audit log successfully uploaded			
49:43.8 Audit log successfully uploaded and deleted from device	95	0	55.075
49:48.9 Audit log successfully uploaded			
49:49.2 Audit log successfully uploaded and deleted from device	95	0	55.075
50:03.0 Audit log successfully uploaded			
50:03.2 Audit log successfully uploaded and deleted from device	95	0	55.075
50:03.3 Audit log successfully uploaded			
50:03.5 Audit log successfully uploaded and deleted from device	95	0	55.075
50:06.4 Audit log successfully uploaded			
50:06.7 Audit log successfully uploaded and deleted from device	95	0	55.075
50:16.9 Audit log successfully uploaded			
50:17.1 Audit log successfully uploaded and deleted from device	96	0	55.075
50:24.8 Audit log successfully uploaded			
50:25.1 Audit log successfully uploaded and deleted from device	96	0	55.075
50:32.3 Audit log successfully uploaded			
50:32.5 Audit log successfully uploaded and deleted from device	96	0	55.075
50:33.7 Audit log successfully uploaded			
50:34.0 Audit log successfully uploaded and deleted from device	96	0	55.075
50:40.3 Audit log successfully uploaded			
50:40.5 Audit log successfully uploaded and deleted from device	96	0	55.075
50:55.2 Audit log successfully uploaded			
50:55.5 Audit log successfully uploaded and deleted from device	96	0	55.075
51:00.7 Audit log successfully uploaded			
51:01.0 Audit log successfully uploaded and deleted from device	96	0	55.075

51:08.7	Audit log successfully uploaded				
51:09.0	Audit log successfully uploaded and deleted from device	96	0	55.075	
51:27.2	Audit log successfully uploaded				
51:27.4	Audit log successfully uploaded and deleted from device	96	0	55.075	
51:29.1	Audit log successfully uploaded				
51:29.4	Audit log successfully uploaded and deleted from device	96	0	55.075	
51:34.7	Audit log successfully uploaded				
51:34.9	Audit log successfully uploaded and deleted from device	96	0	55.075	
51:35.6	Audit log successfully uploaded				
51:35.9	Audit log successfully uploaded and deleted from device	96	0	55.075	
51:54.1	Audit log successfully uploaded				
51:54.3	Audit log successfully uploaded and deleted from device	96	0	55.075	
52:00.1	Audit log successfully uploaded				
52:00.4	Audit log successfully uploaded and deleted from device	96	0	55.075	
52:11.5	Audit log successfully uploaded				
52:11.8	Audit log successfully uploaded and deleted from device	96	0	55.075	
52:20.0	Audit log successfully uploaded				
52:20.3	Audit log successfully uploaded and deleted from device	96	0	55.075	
52:26.6	Audit log successfully uploaded				
52:26.8	Audit log successfully uploaded and deleted from device	96	0	55.075	
52:31.5	Audit log successfully uploaded				
52:31.7	Audit log successfully uploaded and deleted from device	96	0	55.075	
58:48.4	Device disconnected from charger	97	0	55.076	
58:48.8	Camera disconnected from Axon Dock X62001V12	97	0	55.076	
27:50.9	Power button pressed				
27:53.9	Device powered off using button	94	0	55.076	
27:54.4	Power button released				
53:06.9	Audit log created			1.13.32	
53:07.1	Device powered on using button	94	0	55.076	
53:09.0	Audio recording disabled due to video buffering default				
17:40.3	Power button pressed				
17:43.3	Device powered off using button	92	0	55.075	
17:43.7	Power button released				
26:27.9	Audit log created			1.13.32	
26:28.0	Device powered on using button	92	0	55.075	
26:30.0	Audio recording disabled due to video buffering default				
35:25.4	Event button pressed				
35:25.5	Event button released				
35:25.6	Event button pressed				
35:25.7	Audio recording enabled due to video recording default				
35:25.7	Event button released				
35:25.9	Recording started due to button press	90	1	55.074	eaad36374fac4a2e9a62ab69f1f37bab
35:43.1	Event button pressed				
35:46.1	Recording stopped due to button press	90	1	55.028	eaad36374fac4a2e9a62ab69f1f37bab
35:46.6	Event button released				
35:47.0	Audio recording disabled due to video buffering default				
36:01.8	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-19 0135 X6033271L' using Axon applicator				eaad36374fac4a2e9a62ab69f1f37bab

05:34.3	Event button pressed			
05:34.4	Event button released			
05:34.5	Event button pressed			
05:34.5	Audio recording enabled due to video recording default			
05:34.6	Event button released			
05:34.7	Recording started due to button press	87	2	55.002 9c1a2fa34ab74f1a81103b769aa66f98
06:26.8	Event button pressed			
06:29.8	Recording stopped due to button press	87	2	54.913 9c1a2fa34ab74f1a81103b769aa66f98
06:30.4	Event button released			
06:30.7	Audio recording disabled due to video buffering default			
06:30.8	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-19 0205 X6033271L' using Axon application			9c1a2fa34ab74f1a81103b769aa66f98
26:27.9	Audit log created	85	2 1.13.32	54.912
26:27.9	Audit log created	80	2 1.13.32	54.911
52:33.7	Volume up button pressed			
52:33.9	Volume up button released			
52:34.0	Volume changed to very high from high using button			
26:28.0	Audit log created	74	2 1.13.32	54.909
26:28.0	Audit log created	68	2 1.13.32	54.908
56:23.4	Volume up button pressed			
56:23.6	Volume up button released			
14:33.0	Camera connected to Axon Dock X630020W7	63	2	54.907
14:33.0	Audit log created	63	2 1.13.32	54.907
14:33.0	Audit log rolled	63	2	54.907
14:33.1	Device connected to charger	63	2	54.907
14:32.0	Audit log created	90	2 1.13.32	54.907
14:32.0	Audit log created	100	2 1.13.32	54.906
14:32.0	Audit log created	100	2 1.13.32	54.906
14:32.0	Audit log created	100	2 1.13.32	54.905
14:32.0	Audit log created	100	2 1.13.32	54.905
14:32.0	Audit log created	100	2 1.13.32	54.905
14:32.0	Audit log created	100	2 1.13.32	54.91
14:32.1	Audit log created	100	2 1.13.32	54.91
14:32.1	Audit log created	100	2 1.13.32	54.91
14:32.1	Audit log created	100	2 1.13.32	54.91
14:32.1	Audit log created	100	2 1.13.32	54.91
14:32.1	Audit log created	100	2 1.13.32	54.909
14:32.1	Audit log created	100	2 1.13.32	54.909
58:16.0	Device disconnected from charger	98	2	54.909
58:16.5	Camera disconnected from Axon Dock X630020W7	98	2	54.909
58:22.1	Power button pressed			
58:25.1	Device powered off using button	100	2	54.912
58:25.5	Power button released			
49:40.1	Audit log created		1.13.32	
49:40.2	Device powered on using button	100	2	54.911
49:42.1	Audio recording disabled due to video buffering default			
22:22.6	Event button pressed			
22:22.7	Event button released			

22:22.9	Event button pressed			
22:22.9	Audio recording enabled due to video recording default			
22:23.0	Event button released			
22:23.1	Recording started due to button press	96	2	54.91 4fe59d026ddb4379862e31f85743bacf
26:18.2	Event button pressed			
26:18.4	Event button released			
26:18.6	Event button pressed			
26:23.6	Event button released			
28:28.2	Event button pressed			
28:31.2	Recording stopped due to button press	94	3	54.654 4fe59d026ddb4379862e31f85743bacf
28:31.8	Event button released			
28:32.1	Audio recording disabled due to video buffering default			
28:32.3	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-20 0122 X6033271L' using Axon applicator			4fe59d026ddb4379862e31f85743bacf
29:04.6	Axon application connected to device			
29:57.2	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			eaad36374fac4a2e9a62ab69f1f37bab
30:09.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-19 0135 X6033271L' to 'Clearing Train N11' using Axon applicator			eaad36374fac4a2e9a62ab69f1f37bab
30:40.9	Title changed in video metadata from 'Axon Body 3 Video 2021-06-19 0205 X6033271L' to 'Clearing Train N11' using Axon applicator			9c1a2fa34ab74f1a81103b769aa66f98
30:40.9	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			9c1a2fa34ab74f1a81103b769aa66f98
31:09.9	Title changed in video metadata from 'Axon Body 3 Video 2021-06-20 0122 X6033271L' to 'Clearing Train NE10' using Axon applicator			4fe59d026ddb4379862e31f85743bacf
31:09.9	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			4fe59d026ddb4379862e31f85743bacf
31:27.1	Axon application disconnected from device			
40:11.1	Event button pressed			
40:11.2	Event button released			
40:11.3	Event button pressed			
40:11.3	Audio recording enabled due to video recording default			
40:11.4	Event button released			
40:11.5	Recording started due to button press	93	4	54.652 41b8562d1ec24e529cc31dbe31c5c276
49:40.1	Audit log created	91	4 1.13.32	54.291
50:37.4	Event button pressed			
50:40.5	Recording stopped due to button press	91	4	54.259 41b8562d1ec24e529cc31dbe31c5c276
50:41.2	Audio recording disabled due to video buffering default			
50:41.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-20 0140 X6033271L' using Axon applicator			41b8562d1ec24e529cc31dbe31c5c276
50:41.8	Event button released			
54:49.0	Volume up button pressed			
54:49.1	Volume up button released			
55:05.5	Volume up button pressed			
55:05.7	Volume up button released			
57:29.2	Volume up button pressed			
57:29.3	Volume up button released			
57:32.7	Volume up button pressed			
57:33.0	Volume up button released			
49:40.1	Audit log created	85	4 1.13.32	54.256
49:40.1	Audit log created	80	4 1.13.32	54.255
37:17.3	Volume up button pressed			
37:17.7	Volume up button released			
41:34.0	Volume up button pressed			
41:34.3	Volume up button released			

49:40.1	Audit log created	74	4 1.13.32	54.253
35:35.8	Axon application connected to device			
36:24.0	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			41b8562d1ec24e529cc31dbe31c5c276
36:24.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-20 0140 X6033271L' to 'Clearing Train NE10' using Axon applicator			41b8562d1ec24e529cc31dbe31c5c276
37:08.2	Axon application disconnected from device			
49:40.1	Audit log created	69	4 1.13.32	54.252
26:24.8	Power button pressed			
26:27.8	Device powered off using button	65	4	54.251
26:28.2	Power button released			
28:11.0	Device powered on due to charger connection	65	4	54.251
28:11.0	Device connected to charger			
28:11.0	Camera connected to Axon Dock X630020W7	65	4	54.251
28:11.0	Audit log created		1.13.32	
28:11.0	Audit log rolled			
28:11.9	Camera connected to Axon Dock X630020W7	65	4	54.251
28:13.9	Audit log created	65	4 1.13.32	54.251
28:13.9	Audit log rolled	65	4	54.251
28:13.0	Audit log created	92	4 1.13.32	54.25
28:13.0	Audit log created	100	4 1.13.32	54.249
28:13.0	Audit log created	100	4 1.13.32	54.249
28:13.0	Audit log created	100	4 1.13.32	54.249
28:13.0	Audit log created	100	4 1.13.32	54.249
28:13.0	Audit log created	100	4 1.13.32	54.248
28:13.1	Audit log created	100	4 1.13.32	54.248
28:13.1	Audit log created	100	4 1.13.32	54.249
28:13.1	Audit log created	100	4 1.13.32	54.25
28:13.1	Audit log created	100	4 1.13.32	54.249
28:13.1	Audit log created	100	4 1.13.32	54.249
28:13.1	Audit log created	100	4 1.13.32	54.249
25:55.9	Camera disconnected from Axon Dock X630020W7	100	4	54.249
25:56.0	Device disconnected from charger	100	4	54.249
25:56.0	Audio recording disabled due to video buffering default			
28:13.1	Audit log created	100	4 1.13.32	54.252
28:13.1	Audit log created	92	4 1.13.32	54.251
16:15.2	Audio recording enabled due to video recording default			
16:15.4	Recording started due to Axon Signal Sidearm activation	88	5	54.25 99e3419c965441a782698e3a26adfa69
16:18.6	Event button pressed			
16:21.6	Recording stopped due to button press	88	5	54.236 99e3419c965441a782698e3a26adfa69
16:22.4	Audio recording disabled due to video buffering default			
16:23.9	Event button released			
16:31.7	Audio recording enabled due to video recording default			
16:31.9	Recording started due to Axon Signal Sidearm activation	88	6	54.217 ee29dcef7b1b4c388a3833b587a2f6d2
16:35.5	Event button pressed			
16:38.5	Recording stopped due to button press	88	6	54.193 ee29dcef7b1b4c388a3833b587a2f6d2
16:39.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-20 2116 X6033271L' using Axon applicator			ee29dcef7b1b4c388a3833b587a2f6d2
16:39.5	Event button released			
16:45.3	Audio recording disabled due to video buffering default			

16:45.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-20 2116 X6033271L' using Axon applicati				99e3419c965441a782698e3a26adfa69
17:10.3	Power button pressed				
17:12.3	Power button released				
17:26.3	Axon application connected to device				
18:15.1	Categories 'Accidental Recording' added to video metadata using Axon applicati				ee29dcef7b1b4c388a3833b587a2f6d2
18:29.4	Categories 'Accidental Recording' added to video metadata using Axon applicati				99e3419c965441a782698e3a26adfa69
19:04.7	Video played back using Axon application				99e3419c965441a782698e3a26adfa69
19:56.8	Video played back using Axon application				ee29dcef7b1b4c388a3833b587a2f6d2
20:24.7	Axon application disconnected from device				
21:46.1	Power button pressed				
21:49.2	Device powered off using button	87	6	54.177	
21:49.6	Power button released				
03:18.2	Audit log created			1.13.32	
03:18.3	Device powered on using button	87	6	54.178	
03:21.2	Audio recording disabled due to video buffering default				
52:13.7	Event button pressed				
52:13.8	Event button released				
52:13.9	Event button pressed				
52:14.0	Audio recording enabled due to video recording default				
52:14.0	Event button released				
52:14.2	Recording started due to button press	82	7	54.176	b09842e8f65f490a91ec60e63ef6fbb1
02:08.2	Event button pressed				
02:11.2	Recording stopped due to button press	80	7	53.8	b09842e8f65f490a91ec60e63ef6fbb1
02:11.6	Event button released				
02:12.1	Audio recording disabled due to video buffering default				
02:12.5	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-20 2352 X6033271L' using Axon applicati				b09842e8f65f490a91ec60e63ef6fbb1
02:48.2	Event button pressed				
02:48.4	Event button released				
02:50.7	Event button pressed				
02:50.8	Event button released				
02:51.1	Event button pressed				
02:51.1	Audio recording enabled due to video recording default				
02:51.1	Event button released				
02:51.3	Recording started due to button press	80	8	53.798	545b49909f884cd389b59554fff92fac
03:18.2	Audit log created	80	8	1.13.32	53.764
04:06.6	Event button pressed				
04:06.7	Event button released				
04:06.9	Event button pressed				
04:07.0	Event button released				
04:07.6	Event button pressed				
04:10.6	Recording stopped due to button press	80	8	53.737	545b49909f884cd389b59554fff92fac
04:11.3	Audio recording disabled due to video buffering default				
04:11.4	Event button released				
04:11.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-21 0002 X6033271L' using Axon applicati				545b49909f884cd389b59554fff92fac
03:18.2	Audit log created	75	8	1.13.32	53.735
03:18.2	Audit log created	69	8	1.13.32	53.733
03:18.2	Audit log created	63	8	1.13.32	53.732

03:18.3 Audit log created	57	8 1.13.32	53.731
21:07.6 Select button pressed			
21:08.2 Select button released			
03:18.3 Audit log created	49	8 1.13.32	53.73
03:18.3 Audit log created	44	8 1.13.32	53.728
20:59.7 Volume up button pressed			
20:59.9 Volume up button released			
20:59.9 Volume up button pressed			
21:00.0 Select button released			
21:00.1 Volume up button released			
21:00.1 Select button pressed			
21:00.2 Select button released			
03:18.3 Audit log created	38	8 1.13.32	53.727
03:18.3 Audit log created	32	8 1.13.32	53.725
03:18.3 Audit log created	27	8 1.13.32	53.724
03:18.3 Audit log created	20	8 1.13.32	53.722
03:18.3 Audit log created	13	8 1.13.32	53.721
03:18.3 Audit log created	6	8 1.13.32	53.719
41:21.3 Device powered off due to low battery	2	8	53.718
06:32.9 Audit log created		1.13.32	
06:33.0 Device powered on due to charger connection	2	8	53.717
06:34.0 Device powered off due to low battery	2	8	53.717
06:40.6 Power button pressed			
07:12.2 Device powered on using button	3	8	53.725
07:14.1 Audio recording disabled due to video buffering default			
07:42.1 Power button pressed			
07:45.1 Device powered off using button	3	8	53.725
07:45.5 Power button released			
07:50.2 Device powered off due to low battery	2	8	53.725
18:23.8 Audit log created		1.13.32	
18:24.0 Device connected to charger			
18:24.0 Device powered on due to charger connection	3	8	53.724
18:24.0 Camera connected to Axon Dock X630020W7	3	8	53.724
18:24.0 Audit log created		1.13.32	
18:24.0 Audit log rolled			
18:25.0 Camera connected to Axon Dock X630020W7	3	8	53.724
18:26.9 Audit log created	3	8 1.13.32	53.724
18:26.9 Audit log rolled	3	8	53.724
38:18.8 Camera disconnected from Axon Dock X630020W7	13	8	53.724
38:18.9 Audio recording disabled due to video buffering default			
38:19.0 Device disconnected from charger	13	8	53.724
38:19.8 Camera connected to Axon Dock X630020W7	13	8	53.724
38:19.8 Audit log created	13	8 1.13.32	53.724
38:19.8 Audit log rolled	13	8	53.724
38:21.0 Device connected to charger	13	8	53.724
38:19.0 Audit log created	41	8 1.13.32	53.723
38:19.0 Audit log created	65	8 1.13.32	53.723

40:54.1	Camera disconnected from Axon Dock X630020W7	66	8	53.723	
40:55.0	Device disconnected from charger	66	8	53.722	
41:00.1	Camera connected to Axon Dock X630020W7	66	8	53.723	
41:00.1	Audit log rolled	66	8	53.722	
41:00.1	Audit log created	66	8 1.13.32	53.723	
41:01.0	Device connected to charger	66	8	53.723	
57:42.0	Device disconnected from charger	73	8	53.722	
57:42.2	Camera disconnected from Axon Dock X630020W7	73	8	53.722	
57:49.6	Select button pressed				
57:49.7	Select button released				
41:00.0	Audit log created	66	8 1.13.32	53.721	
45:21.6	Event button pressed				
45:21.7	Event button released				
45:22.0	Event button pressed				
45:22.0	Audio recording enabled due to video recording default				
45:22.2	Event button released				
45:22.2	Recording started due to button press	66	9	53.721	b87bd0b202c241eeb7f07c24d2061815
49:43.1	Event button pressed				
49:46.1	Recording stopped due to button press	65	9	53.521	b87bd0b202c241eeb7f07c24d2061815
49:46.7	Event button released				
49:46.9	Audio recording disabled due to video buffering default				
49:47.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-21 2345 X6033271L' using Axon applicator				b87bd0b202c241eeb7f07c24d2061815
50:15.0	Axon application connected to device				
51:08.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-21 2345 X6033271L' to 'Ambulance Call N4' using Axon applicator				b87bd0b202c241eeb7f07c24d2061815
51:08.2	Categories 'Ambulance Call' added to video metadata using Axon applicator				b87bd0b202c241eeb7f07c24d2061815
54:43.2	Event button pressed				
54:43.4	Event button released				
54:43.5	Event button pressed				
54:43.5	Audio recording enabled due to video recording default				
54:43.6	Event button released				
54:43.6	Recording started due to button press	65	10	53.519	0ce575b50247485f80040ad9e6d9e0a9
56:17.3	Event button pressed				
56:20.3	Recording stopped due to button press	64	10	53.408	0ce575b50247485f80040ad9e6d9e0a9
56:20.8	Event button released				
56:21.3	Audio recording disabled due to video buffering default				
56:21.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-21 2354 X6033271L' using Axon applicator				0ce575b50247485f80040ad9e6d9e0a9
59:32.3	Title changed in video metadata from 'Axon Body 3 Video 2021-06-21 0002 X6033271L' to 'Sig. 23 N4' using Axon applicator				545b49909f884cd389b59554fff92fac
59:32.3	Categories 'Disorderly Person' added to video metadata using Axon applicator				545b49909f884cd389b59554fff92fac
01:58.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-20 2352 X6033271L' to 'Ambulance Call N4 Code 9 By 320' using Axon applicator				b09842e8f65f490a91ec60e63ef6fbb1
01:58.8	Categories 'Ambulance Call' added to video metadata using Axon applicator				b09842e8f65f490a91ec60e63ef6fbb1
02:27.7	Categories 'Disorderly Person' added to video metadata using Axon applicator				0ce575b50247485f80040ad9e6d9e0a9
02:27.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-21 2354 X6033271L' to 'Sig 23 N5' using Axon applicator				0ce575b50247485f80040ad9e6d9e0a9
17:35.9	Event button pressed				
17:36.1	Event button released				
17:36.2	Event button pressed				
17:36.2	Audio recording enabled due to video recording default				
17:36.2	Event button released				

17:36.3 Recording started due to button press	63	11	53.406	e60a85d4e2ee420080386f613363b0cb
19:45.8 Event button pressed				
19:48.8 Recording stopped due to button press	62	11	53.276	e60a85d4e2ee420080386f613363b0cb
19:49.3 Event button released				
19:49.6 Audio recording disabled due to video buffering default				
19:49.8 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0017 X6033271L' using Axon applicator				e60a85d4e2ee420080386f613363b0cb
41:00.0 Audit log created	60	11 1.13.32	53.275	
00:32.4 Event button pressed				
00:32.6 Event button released				
00:32.6 Event button pressed				
00:32.7 Audio recording enabled due to video recording default				
00:32.8 Event button released				
00:32.8 Recording started due to button press	58	12	53.274	de573e0239934264b75e97d87f3db55d
01:28.4 Event button pressed				
01:31.4 Recording stopped due to button press	57	12	53.183	de573e0239934264b75e97d87f3db55d
01:31.8 Event button released				
01:32.3 Audio recording disabled due to video buffering default				
01:32.4 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0100 X6033271L' using Axon applicator				de573e0239934264b75e97d87f3db55d
02:57.0 Event button pressed				
02:57.2 Event button released				
02:57.3 Event button pressed				
02:57.4 Audio recording enabled due to video recording default				
02:57.4 Event button released				
02:57.5 Recording started due to button press	57	13	53.182	c65a1f69b0d74bd59f7598210591254a
10:59.3 Event button pressed				
11:02.3 Recording stopped due to button press	55	13	52.882	c65a1f69b0d74bd59f7598210591254a
11:02.8 Event button released				
11:03.2 Audio recording disabled due to video buffering default				
11:03.5 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0102 X6033271L' using Axon applicator				c65a1f69b0d74bd59f7598210591254a
20:51.5 Axon application disconnected from device				
41:00.0 Audit log created	51	13 1.13.32	52.88	
48:48.2 Event button pressed				
48:48.3 Event button released				
48:48.4 Event button pressed				
48:48.4 Audio recording enabled due to video recording default				
48:48.4 Event button released				
48:48.5 Event button pressed				
48:48.5 Event button released				
48:48.5 Recording started due to button press	50	14	52.88	5e711d1bddde48fc9444c946308f1ef2
51:18.9 Event button pressed				
51:21.9 Recording stopped due to button press	49	14	52.738	5e711d1bddde48fc9444c946308f1ef2
51:22.4 Event button released				
51:22.7 Audio recording disabled due to video buffering default				
51:22.9 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0148 X6033271L' using Axon applicator				5e711d1bddde48fc9444c946308f1ef2
04:01.5 Event button pressed				
04:01.9 Event button released				
04:02.0 Event button pressed				

04:02.1	Audio recording enabled due to video recording default				
04:02.1	Event button released				
04:02.2	Recording started due to button press	48	15	52.737	5e70dbf666164dc79d397d7fdbd2009a
09:48.9	Event button pressed				
09:51.9	Recording stopped due to button press	47	15	52.492	5e70dbf666164dc79d397d7fdbd2009a
09:52.4	Event button released				
09:52.7	Audio recording disabled due to video buffering default				
09:53.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0204 X6033271L' using Axon applicator				5e70dbf666164dc79d397d7fdbd2009a
12:24.9	Volume up button pressed				
12:25.1	Volume up button released				
41:00.0	Audit log created	44	15 1.13.32	52.49	
41:00.0	Audit log created	38	15 1.13.32	52.489	
56:18.1	Volume up button pressed				
56:18.3	Volume up button released				
56:28.3	Volume up button pressed				
56:28.5	Volume up button released				
00:40.8	Volume up button pressed				
00:41.7	Volume up button released				
13:07.3	Event button pressed				
13:07.4	Event button released				
13:07.6	Event button pressed				
13:07.6	Audio recording enabled due to video recording default				
13:07.7	Event button released				
13:07.7	Recording started due to button press	35	16	52.488	7583d6ba0b5f4da4ad6d589c97ba747e
20:18.4	Event button pressed				
20:21.4	Recording stopped due to button press	33	16	52.197	7583d6ba0b5f4da4ad6d589c97ba747e
20:22.0	Event button released				
20:22.2	Audio recording disabled due to video buffering default				
20:22.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-22 0413 X6033271L' using Axon applicator				7583d6ba0b5f4da4ad6d589c97ba747e
41:00.1	Audit log created	32	16 1.13.32	52.195	
41:48.4	Axon application connected to device				
42:42.0	Axon application disconnected from device				
42:54.1	Axon application connected to device				
44:47.4	Categories 'Suspicious Person' added to video metadata using Axon applicator				7583d6ba0b5f4da4ad6d589c97ba747e
44:47.4	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0413 X6033271L' to 'Sig. 54 N6 Code 9 By 360' using Axon applicator				7583d6ba0b5f4da4ad6d589c97ba747e
46:12.1	Categories 'Loitering', 'Disorderly Person' added to video metadata using Axon applicator				5e70dbf666164dc79d397d7fdbd2009a
46:12.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0204 X6033271L' to 'Sig 24, 70 N4' using Axon applicator				5e70dbf666164dc79d397d7fdbd2009a
46:55.4	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				5e711d1bddde48fc9444c946308f1ef2
46:55.4	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0148 X6033271L' to 'Sig 31, 70 N2' using Axon applicator				5e711d1bddde48fc9444c946308f1ef2
47:41.1	Categories 'Ambulance Call' added to video metadata using Axon applicator				e60a85d4e2ee420080386f613363b0cb
47:41.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0017 X6033271L' to 'Sig.4 N5' using Axon applicator				e60a85d4e2ee420080386f613363b0cb
48:12.0	Categories 'Ambulance Call' added to video metadata using Axon applicator				de573e0239934264b75e97d87f3db55d
48:12.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0100 X6033271L' to 'Sig. 4 N5' using Axon applicator				de573e0239934264b75e97d87f3db55d
48:42.7	Categories 'Ambulance Call' added to video metadata using Axon applicator				c65a1f69b0d74bd59f7598210591254a
48:42.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-22 0102 X6033271L' to 'Sig. 4 N5' using Axon applicator				c65a1f69b0d74bd59f7598210591254a
49:23.0	Video played back using Axon application				c65a1f69b0d74bd59f7598210591254a
49:27.8	Video played back using Axon application				c65a1f69b0d74bd59f7598210591254a

52:40.6 Video played back using Axon application

c65a1f69b0d74bd59f7598210591254a

52:42.4 Video played back using Axon application

c65a1f69b0d74bd59f7598210591254a

54:42.9 Axon application disconnected from device

17:16.3 Volume up button pressed

17:16.8 Volume up button released

36:46.2 Volume up button pressed

36:46.2 Volume up button released

41:00.1 Audit log created

27 16 1.13.32 52.193

41:00.1 Audit log created

21 16 1.13.32 52.191

47:53.4 Volume down button pressed

47:53.6 Volume down button released

47:53.9 Volume changed to high from very high using button

47:56.8 Select button pressed

47:56.9 Select button released

47:57.6 Select button pressed

47:57.8 Select button released

47:59.5 Select button pressed

47:59.7 Select button released

48:00.6 Select button pressed

48:00.8 Select button released

48:05.1 Audit log created

20 16 1.13.32 52.191

48:05.1 Audit log rolled

20 16 52.191

48:05.1 Camera connected to Axon Dock X630020W7

20 16 52.191

48:06.0 Device connected to charger

20 16 52.191

48:05.0 Audit log created

46 16 1.13.32 52.19

48:05.0 Audit log created

71 16 1.13.32 52.19

48:05.0 Audit log created

96 16 1.13.32 52.189

48:05.0 Audit log created

100 16 1.13.32 52.188

48:05.1 Audit log created

100 16 1.13.32 52.188

48:05.1 Audit log created

100 16 1.13.32 52.188

48:05.1 Audit log created

100 16 1.13.32 52.188

48:05.1 Audit log created

100 16 1.13.32 52.187

48:05.1 Audit log created

100 16 1.13.32 52.187

22:22.8 Camera disconnected from Axon Dock X630020W7

100 16 52.187

22:23.0 Device disconnected from charger

100 16 52.187

22:28.4 Power button pressed

22:31.4 Device powered off using button

100 16 52.193

22:31.9 Power button released

22:30.9 Audit log created

1.13.32

22:31.0 Device powered on due to charger connection

100 16 52.193

22:31.0 Device connected to charger

22:31.0 Camera connected to Axon Dock X630020W7

100 16 52.193

22:31.0 Audit log created

1.13.32

22:31.0 Audit log rolled

22:32.0 Camera connected to Axon Dock X630020W7

100 16 52.193

22:33.9 Audit log created

100 16 1.13.32 52.193

22:33.9 Audit log rolled

100 16 52.193

01:37.9	Camera disconnected from Axon Dock X630020W7	100	16	52.193
01:37.9	Audio recording disabled due to video buffering default			
01:38.0	Device disconnected from charger	100	16	52.193
22:33.0	Audit log created	97	16 1.13.32	52.192
28:45.1	Camera connected to Axon Dock X62001V12	96	16	52.235
28:45.1	Audit log rolled	96	16	52.192
28:45.1	Audit log created	96	16 1.13.32	52.192
28:46.0	Device connected to charger	96	16	52.192
29:10.7	Video upload started when camera was docked			eaad36374fac4a2e9a62ab69f1f37bab
29:20.0	Date/Time synced to 06/24/2021 08:29:20.01 PM from 06/24/2021 08:29:15.10 PM			
29:20.7	Audit log successfully uploaded			
29:20.8	Audit log successfully uploaded and deleted from device	96	16	52.235
29:35.7	Video successfully uploaded from device when docked			eaad36374fac4a2e9a62ab69f1f37bab
29:35.9	Video deleted from device when docked	96	15	52.306 eaad36374fac4a2e9a62ab69f1f37bab
29:36.0	Audit log created	96	15 1.13.32	52.306
29:36.0	Audit log rolled	96	15	52.306
29:36.2	Video upload started when camera was docked			9c1a2fa34ab74f1a81103b769aa66f98
29:37.0	Audit log successfully uploaded			
29:37.1	Audit log successfully uploaded and deleted from device	96	15	52.306
29:57.1	Audit log successfully uploaded			
29:57.3	Audit log successfully uploaded and deleted from device	96	15	52.306
29:58.2	Audit log successfully uploaded			
29:58.4	Audit log successfully uploaded and deleted from device	96	15	52.306
30:02.0	Video successfully uploaded from device when docked			9c1a2fa34ab74f1a81103b769aa66f98
30:02.3	Video deleted from device when docked	96	14	52.395 9c1a2fa34ab74f1a81103b769aa66f98
30:02.4	Audit log created	96	14 1.13.32	52.395
30:02.4	Audit log rolled	96	14	52.395
30:02.6	Video upload started when camera was docked			4fe59d026ddb4379862e31f85743bacf
30:15.5	Audit log successfully uploaded			
30:15.7	Audit log successfully uploaded and deleted from device	97	14	52.395
30:16.4	Audit log successfully uploaded			
30:16.6	Audit log successfully uploaded and deleted from device	97	14	52.395
30:16.7	Audit log successfully uploaded			
30:16.9	Audit log successfully uploaded and deleted from device	97	14	52.395
30:24.1	Audit log successfully uploaded			
30:24.3	Audit log successfully uploaded and deleted from device	97	14	52.395
30:28.4	Audit log successfully uploaded			
30:28.6	Audit log successfully uploaded and deleted from device	97	14	52.395
30:33.8	Audit log successfully uploaded			
30:34.0	Audit log successfully uploaded and deleted from device	97	14	52.395
30:49.7	Audit log successfully uploaded			
30:49.9	Audit log successfully uploaded and deleted from device	97	14	52.395
30:52.2	Audit log successfully uploaded			
30:52.3	Audit log successfully uploaded and deleted from device	97	14	52.395
30:58.0	Audit log successfully uploaded			
30:58.2	Audit log successfully uploaded and deleted from device	97	14	52.395
31:00.4	Audit log successfully uploaded			

31:00.6	Audit log successfully uploaded and deleted from device	97	14	52.395
31:13.7	Audit log successfully uploaded			
31:13.9	Audit log successfully uploaded and deleted from device	97	14	52.395
31:15.3	Video successfully uploaded from device when dockec			4fe59d026ddb4379862e31f85743bacf
31:15.6	Video deleted from device when docked	97	13	52.65 4fe59d026ddb4379862e31f85743bacf
31:15.6	Audit log rolled	97	13	52.65
31:15.6	Audit log created	97	13 1.13.32	52.65
31:15.8	Video upload started when camera was docked			41b8562d1ec24e529cc31dbe31c5c276
31:19.3	Audit log successfully uploaded			
31:19.5	Audit log successfully uploaded and deleted from device	97	13	52.65
31:33.1	Audit log successfully uploaded			
31:33.2	Audit log successfully uploaded and deleted from device	97	13	52.65
31:39.3	Audit log successfully uploaded			
31:39.6	Audit log successfully uploaded and deleted from device	97	13	52.65
31:39.7	Audit log successfully uploaded			
31:39.9	Audit log successfully uploaded and deleted from device	97	13	52.65
31:41.6	Audit log successfully uploaded			
31:41.8	Audit log successfully uploaded and deleted from device	97	13	52.649
31:54.0	Audit log successfully uploaded			
31:54.2	Audit log successfully uploaded and deleted from device	97	13	52.649
32:02.0	Audit log successfully uploaded			
32:02.2	Audit log successfully uploaded and deleted from device	97	13	52.649
32:08.4	Audit log successfully uploaded			
32:08.6	Audit log successfully uploaded and deleted from device	97	13	52.649
32:12.3	Audit log successfully uploaded			
32:12.5	Audit log successfully uploaded and deleted from device	97	13	52.649
32:18.6	Audit log successfully uploaded			
32:18.8	Audit log successfully uploaded and deleted from device	97	13	52.649
32:19.7	Audit log successfully uploaded			
32:19.8	Audit log successfully uploaded and deleted from device	97	13	52.649
32:22.0	Audit log successfully uploaded			
32:22.2	Audit log successfully uploaded and deleted from device	97	13	52.649
32:23.9	Audit log successfully uploaded			
32:24.1	Audit log successfully uploaded and deleted from device	97	13	52.649
32:31.3	Audit log successfully uploaded			
32:31.4	Audit log successfully uploaded and deleted from device	97	13	52.649
32:41.5	Audit log successfully uploaded			
32:41.7	Audit log successfully uploaded and deleted from device	97	13	52.649
32:51.4	Audit log successfully uploaded			
32:51.5	Audit log successfully uploaded and deleted from device	97	13	52.649
32:55.7	Audit log successfully uploaded			
32:57.9	Audit log successfully uploaded			
32:58.1	Audit log successfully uploaded and deleted from device	97	13	52.649
33:00.9	Audit log successfully uploaded and deleted from device	97	13	52.649
33:02.8	Audit log successfully uploaded			
33:03.0	Audit log successfully uploaded and deleted from device	97	13	52.649
33:04.0	Audit log successfully uploaded			

33:04.2	Audit log successfully uploaded and deleted from device	97	13	52.649	
33:06.0	Video successfully uploaded from device when docked				41b8562d1ec24e529cc31dbe31c5c276
33:06.4	Video deleted from device when docked	97	12	53.04	41b8562d1ec24e529cc31dbe31c5c276
33:06.4	Audit log created	97	12	1.13.32	53.04
33:06.4	Audit log rolled	97	12		53.04
33:06.6	Video upload started when camera was docked				99e3419c965441a782698e3a26adfa69
33:21.4	Audit log successfully uploaded				
33:21.5	Audit log successfully uploaded and deleted from device	97	12		53.04
33:25.0	Video successfully uploaded from device when docked				99e3419c965441a782698e3a26adfa69
33:25.3	Video deleted from device when docked	97	11	53.104	99e3419c965441a782698e3a26adfa69
33:25.3	Audit log created	97	11	1.13.32	53.104
33:25.3	Audit log rolled	97	11		53.104
33:25.5	Video upload started when camera was docked				ee29dcef7b1b4c388a3833b587a2f6d2
33:28.7	Video successfully uploaded from device when docked				ee29dcef7b1b4c388a3833b587a2f6d2
33:29.0	Video deleted from device when docked	97	10	53.112	ee29dcef7b1b4c388a3833b587a2f6d2
33:29.0	Audit log rolled	97	10		53.112
33:29.0	Audit log created	97	10	1.13.32	53.112
33:29.2	Video upload started when camera was docked				b09842e8f65f490a91ec60e63ef6fbb1
33:31.1	Audit log successfully uploaded				
33:31.3	Audit log successfully uploaded and deleted from device	97	10		53.112
33:39.5	Audit log successfully uploaded				
33:39.6	Audit log successfully uploaded and deleted from device	97	10		53.112
33:41.7	Audit log successfully uploaded				
33:41.9	Audit log successfully uploaded and deleted from device	97	10		53.112
33:47.0	Audit log successfully uploaded				
33:47.2	Audit log successfully uploaded and deleted from device	97	10		53.112
33:59.4	Audit log successfully uploaded				
33:59.6	Audit log successfully uploaded and deleted from device	97	10		53.112
34:03.8	Audit log successfully uploaded				
34:04.0	Audit log successfully uploaded and deleted from device	97	10		53.112
34:13.1	Audit log successfully uploaded				
34:13.3	Audit log successfully uploaded and deleted from device	97	10		53.112
34:17.7	Audit log successfully uploaded				
34:17.9	Audit log successfully uploaded and deleted from device	97	10		53.112
34:27.5	Audit log successfully uploaded				
34:27.7	Audit log successfully uploaded and deleted from device	97	10		53.112
34:30.1	Audit log successfully uploaded				
34:30.2	Audit log successfully uploaded and deleted from device	97	10		53.112
34:36.9	Audit log successfully uploaded				
34:37.1	Audit log successfully uploaded and deleted from device	97	10		53.112
34:39.4	Audit log successfully uploaded				
34:39.5	Audit log successfully uploaded and deleted from device	97	10		53.112
34:43.3	Audit log successfully uploaded				
34:43.5	Audit log successfully uploaded and deleted from device	97	10		53.112
34:43.6	Audit log successfully uploaded				
34:43.9	Audit log successfully uploaded and deleted from device	97	10		53.112
34:44.7	Audit log successfully uploaded				

34:44.8	Audit log successfully uploaded and deleted from device	97	10	53.112	
34:49.1	Audit log successfully uploaded				
34:49.2	Audit log successfully uploaded and deleted from device	97	10	53.112	
34:56.4	Audit log successfully uploaded				
34:56.5	Audit log successfully uploaded and deleted from device	97	10	53.112	
35:02.9	Audit log successfully uploaded				
35:03.1	Audit log successfully uploaded and deleted from device	97	10	53.112	
35:11.7	Audit log successfully uploaded				
35:11.9	Audit log successfully uploaded and deleted from device	97	10	53.112	
35:13.0	Video successfully uploaded from device when dockec				b09842e8f65f490a91ec60e63ef6fbb1
35:13.3	Video deleted from device when docked	97	9	53.485	b09842e8f65f490a91ec60e63ef6fbb1
35:13.4	Audit log rolled	97	9	53.486	
35:13.4	Audit log created	97	9 1.13.32	53.486	
35:13.5	Video upload started when camera was docked				545b49909f884cd389b59554fff92fac
35:20.0	Audit log successfully uploaded				
35:20.2	Audit log successfully uploaded and deleted from device	97	9	53.485	
35:25.2	Audit log successfully uploaded				
35:25.4	Audit log successfully uploaded and deleted from device	97	9	53.485	
35:26.3	Audit log successfully uploaded				
35:26.5	Audit log successfully uploaded and deleted from device	97	9	53.485	
35:28.5	Audit log successfully uploaded				
35:28.7	Audit log successfully uploaded and deleted from device	97	9	53.485	
35:31.2	Video successfully uploaded from device when dockec				545b49909f884cd389b59554fff92fac
35:31.4	Video deleted from device when docked	97	8	53.547	545b49909f884cd389b59554fff92fac
35:31.5	Audit log created	97	8 1.13.32	53.547	
35:31.5	Audit log rolled	97	8	53.547	
35:31.7	Video upload started when camera was docked				b87bd0b202c241eeb7f07c24d2061815
35:42.8	Audit log successfully uploaded				
35:43.0	Audit log successfully uploaded and deleted from device	97	8	53.547	
35:54.7	Audit log successfully uploaded				
35:54.8	Audit log successfully uploaded and deleted from device	97	8	53.547	
35:56.1	Audit log successfully uploaded				
35:56.3	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:10.4	Audit log successfully uploaded				
36:10.6	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:12.0	Audit log successfully uploaded				
36:12.2	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:12.3	Audit log successfully uploaded				
36:12.6	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:14.9	Audit log successfully uploaded				
36:15.0	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:26.1	Audit log successfully uploaded				
36:26.3	Audit log successfully uploaded and deleted from device	97	8	53.547	
36:28.3	Video successfully uploaded from device when dockec				b87bd0b202c241eeb7f07c24d2061815
36:28.6	Video deleted from device when docked	97	7	53.745	b87bd0b202c241eeb7f07c24d2061815
36:28.7	Audit log created	97	7 1.13.32	53.749	
36:28.7	Audit log rolled	97	7	53.749	

36:28.8	Video upload started when camera was docked				Oce575b50247485f80040ad9e6d9e0a9
36:30.4	Audit log successfully uploaded				
36:30.7	Audit log successfully uploaded and deleted from device	97	7	53.749	
36:30.7	Audit log successfully uploaded				
36:30.9	Audit log successfully uploaded and deleted from device	97	7	53.749	
36:46.0	Audit log successfully uploaded				
36:46.2	Audit log successfully uploaded and deleted from device	98	7	53.749	
36:53.8	Audit log successfully uploaded				
36:54.0	Audit log successfully uploaded and deleted from device	98	7	53.749	
36:54.1	Audit log successfully uploaded				
36:54.4	Audit log successfully uploaded and deleted from device	98	7	53.749	
36:59.5	Audit log successfully uploaded				
36:59.7	Audit log successfully uploaded and deleted from device	98	7	53.749	
36:59.9	Audit log successfully uploaded				
37:00.1	Audit log successfully uploaded and deleted from device	98	7	53.749	
37:01.0	Video successfully uploaded from device when docked				Oce575b50247485f80040ad9e6d9e0a9
37:01.3	Video deleted from device when docked	98	6	53.86	Oce575b50247485f80040ad9e6d9e0a9
37:01.3	Audit log created	98	6 1.13.32	53.86	
37:01.3	Audit log rolled	98	6	53.86	
37:01.5	Video upload started when camera was docked				e60a85d4e2ee420080386f613363b0cb
37:11.4	Audit log successfully uploaded				
37:11.5	Audit log successfully uploaded and deleted from device	98	6	53.86	
37:12.2	Audit log successfully uploaded				
37:12.3	Audit log successfully uploaded and deleted from device	98	6	53.86	
37:22.7	Audit log successfully uploaded				
37:22.9	Audit log successfully uploaded and deleted from device	98	6	53.86	
37:26.5	Audit log successfully uploaded				
37:26.7	Audit log successfully uploaded and deleted from device	98	6	53.86	
37:32.0	Audit log successfully uploaded				
37:32.3	Audit log successfully uploaded and deleted from device	98	6	53.86	
37:39.3	Video successfully uploaded from device when docked				e60a85d4e2ee420080386f613363b0cb
37:39.5	Video deleted from device when docked	98	5	53.99	e60a85d4e2ee420080386f613363b0cb
37:39.6	Audit log created	98	5 1.13.32	53.991	
37:39.6	Audit log rolled	98	5	53.991	
37:39.7	Video upload started when camera was docked				de573e0239934264b75e97d87f3db55d
37:43.4	Audit log successfully uploaded				
37:43.6	Audit log successfully uploaded and deleted from device	98	5	53.991	
37:52.8	Audit log successfully uploaded				
37:53.0	Audit log successfully uploaded and deleted from device	98	5	53.991	
37:56.2	Audit log successfully uploaded				
37:56.3	Audit log successfully uploaded and deleted from device	98	5	53.991	
38:04.5	Audit log successfully uploaded				
38:04.6	Video successfully uploaded from device when docked				de573e0239934264b75e97d87f3db55d
38:04.7	Audit log successfully uploaded and deleted from device	98	5	53.991	
38:04.8	Video deleted from device when docked	98	4	54.082	de573e0239934264b75e97d87f3db55d
38:04.9	Audit log rolled	98	4	54.082	
38:04.9	Audit log created	98	4 1.13.32	54.082	

38:05.0	Video upload started when camera was docked				c65a1f69b0d74bd59f7598210591254a
38:09.8	Audit log successfully uploaded				
38:10.0	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:15.1	Audit log successfully uploaded				
38:15.3	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:15.8	Audit log successfully uploaded				
38:16.0	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:26.1	Audit log successfully uploaded				
38:26.3	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:30.4	Audit log successfully uploaded				
38:30.6	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:36.8	Audit log successfully uploaded				
38:37.0	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:38.4	Audit log successfully uploaded				
38:38.6	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:50.1	Audit log successfully uploaded				
38:50.3	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:50.8	Audit log successfully uploaded				
38:51.0	Audit log successfully uploaded and deleted from device	98	4	54.082	
38:58.1	Audit log successfully uploaded				
38:58.3	Audit log successfully uploaded and deleted from device	98	4	54.082	
39:07.4	Audit log successfully uploaded				
39:07.5	Audit log successfully uploaded and deleted from device	98	4	54.082	
39:10.7	Audit log successfully uploaded				
39:10.9	Audit log successfully uploaded and deleted from device	98	4	54.082	
39:12.5	Audit log successfully uploaded				
39:12.7	Audit log successfully uploaded and deleted from device	98	4	54.082	
39:28.4	Video successfully uploaded from device when docked				c65a1f69b0d74bd59f7598210591254a
39:28.7	Video deleted from device when docked	98	3	54.379	c65a1f69b0d74bd59f7598210591254a
39:28.8	Audit log rolled	98	3	54.38	
39:28.8	Audit log created	98	3 1.13.32	54.38	
39:29.0	Video upload started when camera was docked				5e711d1bddde48fc9444c946308f1ef2
40:08.7	Video successfully uploaded from device when docked				5e711d1bddde48fc9444c946308f1ef2
40:09.0	Video deleted from device when docked	98	2	54.521	5e711d1bddde48fc9444c946308f1ef2
40:09.0	Audit log rolled	98	2	54.521	
40:09.0	Audit log created	98	2 1.13.32	54.521	
40:09.2	Video upload started when camera was docked				5e70dbf666164dc79d397d7fdbd2009a
41:17.8	Video successfully uploaded from device when docked				5e70dbf666164dc79d397d7fdbd2009a
41:18.1	Video deleted from device when docked	98	1	54.765	5e70dbf666164dc79d397d7fdbd2009a
41:18.2	Audit log rolled	98	1	54.765	
41:18.2	Audit log created	98	1 1.13.32	54.765	
41:18.4	Video upload started when camera was docked				7583d6ba0b5f4da4ad6d589c97ba747e
42:40.7	Video successfully uploaded from device when docked				7583d6ba0b5f4da4ad6d589c97ba747e
42:41.0	Video deleted from device when docked	99	0	55.054	7583d6ba0b5f4da4ad6d589c97ba747e
42:41.0	Audit log created	99	0 1.13.32	55.054	
42:41.0	Audit log rolled	99	0	55.054	
42:41.1	Audit log rolled	99	0	55.054	

42:41.1	Audit log created	99	0 1.13.32	55.054
46:16.1	Camera disconnected from Axon Dock X62001V12	99	0	55.054
46:16.6	Device disconnected from charger	99	0	55.055
10:51.0	Power button pressed			
10:54.0	Device powered off using button	96	0	55.054
10:54.5	Power button released			
10:58.9	Audit log rolled	96	0	55.054
10:58.9	Audit log created	96	0 1.13.32	55.054
10:59.6	Device connected to charger	96	0	55.054
11:44.0	Device connected to charger			
11:44.0	Device powered on due to charger connection	96	0	55.054
11:44.0	Camera connected to Axon Dock X630020W7	96	0	55.054
11:44.1	Audit log created		1.13.32	
11:44.1	Audit log rolled			
11:45.0	Camera connected to Axon Dock X630020W7	96	0	55.054
11:46.9	Audit log created	96	0 1.13.32	55.054
11:46.9	Audit log rolled	96	0	55.054
11:46.0	Audit log created	100	0 1.13.32	55.053
11:46.0	Audit log created	100	0 1.13.32	55.053
11:46.0	Audit log created	100	0 1.13.32	55.053
11:46.0	Audit log created	100	0 1.13.32	55.052
11:46.0	Audit log created	100	0 1.13.32	55.053
11:46.0	Audit log created	100	0 1.13.32	55.057
09:21.5	Camera disconnected from Axon Dock X630020W7	99	0	55.057
09:21.6	Audio recording disabled due to video buffering default			
09:22.0	Device disconnected from charger	99	0	55.058
09:25.3	Power button pressed			
09:28.3	Device powered off using button	100	0	55.058
09:28.6	Power button released			
49:43.1	Audit log created		1.13.32	
49:43.2	Device powered on using button	100	0	55.057
49:46.1	Audio recording disabled due to video buffering default			
49:43.1	Audit log created	92	0 1.13.32	55.055
49:43.1	Audit log created	87	0 1.13.32	55.054
56:45.0	Event button pressed			
56:45.1	Event button released			
56:47.8	Event button pressed			
56:48.0	Event button released			
57:48.5	Event button pressed			
57:48.6	Event button released			
57:48.7	Event button pressed			
57:48.8	Audio recording enabled due to video recording default			
57:48.8	Event button released			
57:49.0	Recording started due to button press	86	1	55.053 094d5a3b0e8b4e4297bb247b80104c42
58:47.2	Event button pressed			
58:50.2	Recording stopped due to button press	85	1	54.961 094d5a3b0e8b4e4297bb247b80104c42
58:50.8	Event button released			

58:50.9	Audio recording disabled due to video buffering default			
58:51.0	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 1857 X6033271L' using Axon applicator			094d5a3b0e8b4e4297bb247b80104c42
02:00.9	Event button pressed			
02:01.0	Event button released			
02:01.1	Event button pressed			
02:01.1	Audio recording enabled due to video recording default			
02:01.2	Event button released			
02:01.3	Recording started due to button press	85	2	54.961 6d19e2f068b949fe8ce2de6af75c6a75
02:20.3	Event button pressed			
02:23.3	Recording stopped due to button press	85	2	54.91 6d19e2f068b949fe8ce2de6af75c6a75
02:24.0	Event button released			
02:24.1	Audio recording disabled due to video buffering default			
02:37.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 1902 X6033271L' using Axon applicator			6d19e2f068b949fe8ce2de6af75c6a75
11:36.4	Event button pressed			
11:36.6	Event button released			
11:36.6	Event button pressed			
11:36.6	Audio recording enabled due to video recording default			
11:36.7	Event button released			
11:36.8	Recording started due to button press	84	3	54.888 13632b2673754a7c9385203b77a7be62
14:30.2	Event button pressed			
14:33.2	Recording stopped due to button press	84	3	54.736 13632b2673754a7c9385203b77a7be62
14:33.8	Event button released			
14:34.1	Audio recording disabled due to video buffering default			
14:34.3	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 1911 X6033271L' using Axon applicator			13632b2673754a7c9385203b77a7be62
49:43.1	Audit log created	80	3 1.13.32	54.734
14:46.6	Event button pressed			
14:46.7	Event button released			
14:46.8	Event button pressed			
14:46.9	Audio recording enabled due to video recording default			
14:46.9	Event button released			
14:47.0	Recording started due to button press	78	4	54.734 51c445b89da044d49ea29c24f97b6778
15:33.0	Event button pressed			
15:33.1	Event button released			
15:33.2	Event button pressed			
15:33.3	Event button released			
15:35.3	Event button pressed			
15:35.4	Event button released			
15:35.5	Event button pressed			
15:35.8	Event button released			
15:35.9	Event button pressed			
15:38.9	Recording stopped due to button press	78	4	54.646 51c445b89da044d49ea29c24f97b6778
15:39.4	Event button released			
15:39.6	Audio recording disabled due to video buffering default			
15:39.7	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 2014 X6033271L' using Axon applicator			51c445b89da044d49ea29c24f97b6778
15:46.1	Event button pressed			
15:46.2	Event button released			
15:46.3	Event button pressed			

15:46.3	Audio recording enabled due to video recording default			
15:46.4	Event button released			
15:46.4	Recording started due to button press	77	5	54.645 9dd1c59806df44acb6c73be921c9b40a
15:59.2	Event button pressed			
15:59.4	Event button released			
15:59.4	Event button pressed			
16:07.9	Event button released			
16:08.2	Event button pressed			
16:10.8	Event button released			
16:11.9	Event button pressed			
16:14.9	Recording stopped due to button press	77	5	54.628 9dd1c59806df44acb6c73be921c9b40a
16:15.4	Event button released			
16:15.8	Audio recording disabled due to video buffering default			
16:15.9	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 2015 X6033271L' using Axon applicator			9dd1c59806df44acb6c73be921c9b40a
20:18.3	Axon application connected to device			
21:17.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 2015 X6033271L' to 'Sig. 31 Train N11' using Axon applicator			9dd1c59806df44acb6c73be921c9b40a
21:17.0	Categories 'Sleeper' added to video metadata using Axon applicator			9dd1c59806df44acb6c73be921c9b40a
22:08.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 2014 X6033271L' to 'Sig. 31 Train At N11' using Axon applicator			51c445b89da044d49ea29c24f97b6778
22:08.8	Categories 'Sleeper' added to video metadata using Axon applicator			51c445b89da044d49ea29c24f97b6778
23:14.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 1911 X6033271L' to 'Sig. 8 At N11' using Axon applicator			13632b2673754a7c9385203b77a7be62
23:14.2	Categories 'Found Property' added to video metadata using Axon applicator			13632b2673754a7c9385203b77a7be62
25:11.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 1902 X6033271L' to 'Sig. 15 / Sig. 6 At N11' using Axon applicator			6d19e2f068b949fe8ce2de6af75c6a75
25:11.2	Categories 'Lost Property', 'Customer Assist' added to video metadata using Axon applicator			6d19e2f068b949fe8ce2de6af75c6a75
26:33.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 1857 X6033271L' to 'Sig. 54 At N11 Male At Female Restroom' using Axon applicator			094d5a3b0e8b4e4297bb247b80104c42
26:33.7	Categories 'Suspicious Person' added to video metadata using Axon applicator			094d5a3b0e8b4e4297bb247b80104c42
26:55.6	Axon application disconnected from device			
34:19.0	Volume up button pressed			
34:19.1	Volume up button released			
34:19.2	Volume changed to very high from high using button			
34:35.2	Power button pressed			
34:35.4	Power button released			
34:35.7	Camera connected to Axon Dock X62001W9H	76	5	54.634
34:35.8	Audit log created	76	5 1.13.32	54.627
34:35.8	Audit log rolled	76	5	54.626
34:36.2	Device connected to charger	76	5	54.627
35:01.1	Video upload started when camera was docked			094d5a3b0e8b4e4297bb247b80104c42
35:02.7	Audit log successfully uploaded			
35:02.9	Audit log successfully uploaded and deleted from device	76	5	54.634
35:06.0	Date/Time synced to 06/25/2021 08:35:06.01 PM from 06/25/2021 08:35:05.77 PM			
35:13.0	Audit log successfully uploaded			
35:13.2	Audit log successfully uploaded and deleted from device	76	5	54.634
35:13.6	Audit log successfully uploaded			
35:13.8	Audit log successfully uploaded and deleted from device	76	5	54.634
35:27.1	Video successfully uploaded from device when docked			094d5a3b0e8b4e4297bb247b80104c42
35:27.3	Video deleted from device when docked	76	4	54.726 094d5a3b0e8b4e4297bb247b80104c42
35:27.3	Audit log created	76	4 1.13.32	54.726
35:27.3	Audit log rolled	76	4	54.726

35:27.5	Video upload started when camera was docked				6d19e2f068b949fe8ce2de6af75c6a75
35:39.5	Audit log successfully uploaded				
35:39.7	Audit log successfully uploaded and deleted from device	76	4	54.726	
35:45.6	Audit log successfully uploaded				
35:45.8	Audit log successfully uploaded and deleted from device	76	4	54.726	
35:46.7	Video successfully uploaded from device when dockec				6d19e2f068b949fe8ce2de6af75c6a75
35:46.9	Video deleted from device when docked	76	3	54.798	6d19e2f068b949fe8ce2de6af75c6a75
35:47.0	Audit log rolled	76	3	54.798	
35:47.0	Audit log created	76	3 1.13.32	54.798	
35:47.2	Video upload started when camera was docked				13632b2673754a7c9385203b77a7be62
35:56.0	Audit log successfully uploaded				
35:56.2	Audit log successfully uploaded and deleted from device	76	3	54.798	
36:06.8	Audit log successfully uploaded				
36:07.0	Audit log successfully uploaded and deleted from device	76	3	54.798	
36:17.2	Audit log successfully uploaded				
36:17.4	Audit log successfully uploaded and deleted from device	76	3	54.798	
36:23.3	Audit log successfully uploaded				
36:23.5	Audit log successfully uploaded and deleted from device	77	3	54.798	
36:28.7	Video successfully uploaded from device when dockec				13632b2673754a7c9385203b77a7be62
36:29.0	Video deleted from device when docked	77	2	54.951	13632b2673754a7c9385203b77a7be62
36:29.1	Audit log rolled	77	2	54.951	
36:29.1	Audit log created	77	2 1.13.32	54.951	
36:29.3	Video upload started when camera was docked				51c445b89da044d49ea29c24f97b6778
36:29.5	Audit log successfully uploaded				
36:29.7	Audit log successfully uploaded and deleted from device	77	2	54.951	
36:44.7	Audit log successfully uploaded				
36:44.9	Audit log successfully uploaded and deleted from device	77	2	54.951	
36:52.2	Video successfully uploaded from device when dockec				51c445b89da044d49ea29c24f97b6778
36:52.5	Video deleted from device when docked	77	1	55.039	51c445b89da044d49ea29c24f97b6778
36:52.5	Audit log created	77	1 1.13.32	55.039	
36:52.5	Audit log rolled	77	1	55.039	
36:52.7	Video upload started when camera was docked				9dd1c59806df44acb6c73be921c9b40a
36:56.9	Audit log successfully uploaded				
36:57.0	Audit log successfully uploaded and deleted from device	77	1	55.039	
36:59.6	Video successfully uploaded from device when dockec				9dd1c59806df44acb6c73be921c9b40a
36:59.8	Video deleted from device when docked	77	0	55.057	9dd1c59806df44acb6c73be921c9b40a
36:59.8	Audit log created	77	0 1.13.32	55.057	
36:59.8	Audit log rolled	77	0	55.057	
36:59.9	Audit log rolled	77	0	55.057	
36:59.9	Audit log created	77	0 1.13.32	55.057	
37:01.1	Audit log successfully uploaded				
37:01.3	Audit log successfully uploaded and deleted from device	77	0	55.057	
37:12.5	Audit log successfully uploaded				
37:12.7	Audit log successfully uploaded and deleted from device	77	0	55.057	
37:18.0	Audit log successfully uploaded				
37:18.2	Audit log successfully uploaded and deleted from device	77	0	55.057	
37:18.2	Audit log successfully uploaded				

37:18.4	Audit log successfully uploaded and deleted from device	77	0	55.057	
37:28.8	Camera disconnected from Axon Dock X62001W9H	77	0	55.06	
37:29.2	Device disconnected from charger	77	0	55.06	
37:30.1	Power button pressed				
37:33.1	Device powered off using button	77	0	55.06	
37:33.6	Power button released				
41:59.2	Device powered on using button	77	0	55.059	
42:02.2	Audio recording disabled due to video buffering default				
42:11.6	Event button pressed				
42:11.8	Event button released				
42:11.8	Event button pressed				
42:11.9	Audio recording enabled due to video recording default				
42:11.9	Event button released				
42:12.1	Recording started due to button press	77	0	55.059	940983dae1604882ae0fd11d3077885f
42:50.7	Event button pressed				
42:53.7	Recording stopped due to button press	77	1	55.033	940983dae1604882ae0fd11d3077885f
42:54.3	Event button released				
42:54.4	Audio recording disabled due to video buffering default				
42:54.5	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-25 2042 X6033271L' using Axon applicator				940983dae1604882ae0fd11d3077885f
44:02.6	Axon application connected to device				
44:39.7	Title changed in video metadata from 'Axon Body 3 Video 2021-06-25 2042 X6033271L' to 'Sig. 31 N9 PLATFORM' using Axon applicator				940983dae1604882ae0fd11d3077885f
44:39.7	Categories 'Sleeper' added to video metadata using Axon applicator				940983dae1604882ae0fd11d3077885f
44:49.4	Axon application disconnected from device				
54:25.5	Power button pressed				
54:28.5	Device powered off using button	75	1	55.032	
54:28.9	Power button released				
18:47.0	Device powered on due to charger connection	75	1	55.032	
18:47.0	Device connected to charger				
18:47.0	Camera connected to Axon Dock X630020W7	76	1	55.032	
18:47.1	Audit log rolled				
18:47.1	Audit log created				1.13.32
18:48.0	Camera connected to Axon Dock X630020W7	76	1	55.031	
18:49.8	Audit log created	75	1	55.032	1.13.32
18:49.8	Audit log rolled	75	1	55.032	
18:49.0	Audit log created	98	1	55.031	1.13.32
55:15.0	Device disconnected from charger	100	1	55.03	
55:15.6	Camera disconnected from Axon Dock X630020W7	100	1	55.03	
55:15.7	Audio recording disabled due to video buffering default				
18:00.1	Volume up button pressed				
18:00.2	Volume up button released				
18:00.4	Audit log created	97	1	55.03	1.13.32
18:00.4	Audit log rolled	97	1	55.03	
18:01.0	Device connected to charger	97	1	55.03	
18:12.4	Volume up button pressed				
18:12.4	Camera disconnected from Axon Dock X630020W7	97	1	55.03	
18:12.5	Select button pressed				
18:12.5	Select button released				

18:12.8	Volume up button released			
18:13.0	Device disconnected from charger	97	1	55.03
19:07.7	Axon application connected to device			
19:31.6	Axon application disconnected from device			
19:35.8	Power button pressed			
19:35.9	Power button released			
19:36.5	Camera connected to Axon Dock X62001W9H	97	0	55.059
19:36.5	Audit log rolled	96	1	55.03
19:36.5	Audit log created	96	1 1.13.32	55.03
19:37.5	Device connected to charger	96	1	55.03
19:50.4	Video upload started when camera was docked			940983dae1604882ae0fd11d3077885f
19:58.5	Video successfully uploaded from device when docked			940983dae1604882ae0fd11d3077885f
19:58.7	Video deleted from device when docked	97	0	55.059 940983dae1604882ae0fd11d3077885f
19:58.7	Audit log rolled	97	0	55.059
19:58.7	Audit log created	97	0 1.13.32	55.059
19:58.8	Audit log created	97	0 1.13.32	55.059
19:58.8	Audit log rolled	97	0	55.059
20:01.3	Audit log successfully uploaded			
20:01.5	Audit log successfully uploaded and deleted from device	97	0	55.059
20:07.0	Date/Time synced to 06/25/2021 11:20:07.01 PM from 06/25/2021 11:20:06.52 PM			
20:13.9	Audit log successfully uploaded			
20:14.1	Audit log successfully uploaded and deleted from device	97	0	55.059
20:16.2	Audit log successfully uploaded			
20:16.4	Audit log successfully uploaded and deleted from device	97	0	55.059
20:25.6	Audit log successfully uploaded			
20:25.8	Audit log successfully uploaded and deleted from device	97	0	55.059
20:28.3	Audit log successfully uploaded			
20:28.5	Audit log successfully uploaded and deleted from device	97	0	55.059
20:30.7	Audit log successfully uploaded			
20:30.9	Audit log successfully uploaded and deleted from device	97	0	55.059
20:46.9	Audit log successfully uploaded			
20:47.1	Audit log successfully uploaded and deleted from device	97	0	55.059
20:52.1	Audit log successfully uploaded			
20:52.3	Audit log successfully uploaded and deleted from device	97	0	55.059
21:00.5	Audit log successfully uploaded			
21:00.7	Audit log successfully uploaded and deleted from device	97	0	55.059
21:04.2	Audit log successfully uploaded			
21:04.4	Audit log successfully uploaded and deleted from device	97	0	55.059
21:15.9	Audit log successfully uploaded			
21:16.1	Audit log successfully uploaded and deleted from device	97	0	55.059
21:31.3	Audit log successfully uploaded			
21:31.5	Audit log successfully uploaded and deleted from device	97	0	55.059
21:33.6	Audit log successfully uploaded			
21:33.9	Audit log successfully uploaded and deleted from device	97	0	55.059
21:43.0	Audit log successfully uploaded			
21:43.2	Audit log successfully uploaded and deleted from device	97	0	55.059
21:52.7	Audit log successfully uploaded			

21:52.9	Audit log successfully uploaded and deleted from device	97	0	55.059
21:55.0	Audit log successfully uploaded			
21:55.1	Audit log successfully uploaded and deleted from device	97	0	55.059
22:05.4	Audit log successfully uploaded			
22:05.6	Audit log successfully uploaded and deleted from device	97	0	55.059
22:16.8	Audit log successfully uploaded			
22:17.0	Audit log successfully uploaded and deleted from device	97	0	55.059
22:17.3	Audit log successfully uploaded			
22:17.4	Audit log successfully uploaded and deleted from device	97	0	55.059
22:17.6	Audit log successfully uploaded			
22:17.7	Audit log successfully uploaded and deleted from device	97	0	55.059
22:26.9	Audit log successfully uploaded			
22:27.1	Audit log successfully uploaded and deleted from device	97	0	55.059
22:35.2	Audit log successfully uploaded			
22:35.4	Audit log successfully uploaded and deleted from device	97	0	55.059
22:45.6	Audit log successfully uploaded			
22:45.7	Audit log successfully uploaded and deleted from device	97	0	55.059
22:46.1	Audit log successfully uploaded			
22:46.3	Audit log successfully uploaded and deleted from device	97	0	55.059
23:10.9	Audit log successfully uploaded			
23:11.1	Audit log successfully uploaded and deleted from device	97	0	55.059
39:15.5	Volume up button pressed			
39:15.6	Volume up button released			
39:15.8	Camera disconnected from Axon Dock X62001W9H	100	0	55.063
39:15.8	Volume up button pressed			
39:16.0	Volume up button released			
39:16.2	Device disconnected from charger	100	0	55.063
19:58.2	Audit log created	95	0 1.13.32	55.062
19:58.2	Audit log created	89	0 1.13.32	55.06
43:25.8	Event button pressed			
43:25.9	Event button released			
43:26.0	Event button pressed			
43:26.0	Audio recording enabled due to video recording default			
43:26.1	Event button released			
43:26.2	Recording started due to button press	87	0	55.06 bd3473f910284c04b9b6341279361913
43:54.5	Event button pressed			
43:57.5	Recording stopped due to button press	86	1	54.991 bd3473f910284c04b9b6341279361913
43:58.0	Event button released			
43:58.4	Audio recording disabled due to video buffering default			
44:02.5	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-26 0143 X6033271L' using Axon applicator			bd3473f910284c04b9b6341279361913
03:24.8	Event button pressed			
03:24.9	Event button released			
03:25.0	Event button pressed			
03:25.0	Audio recording enabled due to video recording default			
03:25.1	Event button released			
03:25.2	Recording started due to button press	84	2	54.982 44dac44c510144969059a8d4584a04e1
04:32.5	Event button pressed			

04:35.5	Recording stopped due to button press	84	2	54.885	44dac44c510144969059a8d4584a04e1
04:36.3	Audio recording disabled due to video buffering default				
04:36.4	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-26 0203 X6033271L' using Axon application				44dac44c510144969059a8d4584a04e1
04:36.9	Event button released				
19:40.9	Power button pressed				
19:43.9	Device powered off using button	83	2	54.884	
19:44.3	Power button released				
19:58.2	Audit log created	83	1.13.32		
20:41.9	Audit log created		1.13.32		
20:42.0	Device powered on due to charger connection	83	2	54.883	
20:42.0	Device connected to charger				
20:42.0	Camera connected to Axon Dock X630020W7	83	2	54.883	
20:42.1	Audit log rolled				
20:42.1	Audit log created		1.13.32		
20:43.0	Camera connected to Axon Dock X630020W7	84	2	54.883	
20:44.9	Audit log created	83	2 1.13.32	54.883	
20:44.9	Audit log rolled	83	2	54.883	
20:44.0	Audit log created	100	2 1.13.32	54.883	
20:44.0	Audit log created	100	2 1.13.32	54.888	
20:44.0	Audit log created	100	2 1.13.32	54.892	
20:44.0	Audit log created	100	2 1.13.32	54.892	
20:44.0	Audit log created	100	2 1.13.32	54.892	
20:44.0	Audit log created	100	2 1.13.32	54.892	
20:44.0	Audit log created	100	2 1.13.32	54.891	
20:44.0	Audit log created	100	2 1.13.32	54.897	
20:44.0	Audit log created	100	2 1.13.32	54.901	
20:44.1	Audit log created	100	2 1.13.32	54.901	
20:44.1	Audit log created	100	2 1.13.32	54.901	
39:56.5	Camera disconnected from Axon Dock X630020W7	98	2	54.901	
39:56.5	Audio recording disabled due to video buffering default				
39:57.0	Device disconnected from charger	100	2	54.902	
40:11.9	Power button pressed				
40:14.9	Device powered off using button	100	2	54.902	
40:15.4	Power button released				
24:27.0	Audit log created		1.13.32		
24:27.1	Device powered on using button	100	2	54.902	
24:29.0	Audio recording disabled due to video buffering default				
32:05.8	Event button pressed				
32:06.0	Event button released				
32:06.0	Event button pressed				
32:06.1	Audio recording enabled due to video recording default				
32:06.1	Event button released				
32:06.3	Recording started due to button press	98	3	54.901	ace4789708254e6fb3c1af5d2890f981
36:38.8	Event button pressed				
36:41.8	Recording stopped due to button press	97	3	54.695	ace4789708254e6fb3c1af5d2890f981
36:42.5	Audio recording disabled due to video buffering default				

36:42.7 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-26 2032 X6033271L' using Axon applicator				ace4789708254e6fb3c1af5d2890f981
36:43.2 Event button released				
40:03.1 Event button pressed				
40:03.2 Event button released				
40:03.3 Event button pressed				
40:03.4 Audio recording enabled due to video recording default				
40:03.4 Event button released				
40:03.5 Recording started due to button press	97	4	54.694	db8aaaf89f574789be0ea4579e92ff67
41:06.1 Event button pressed				
41:06.2 Event button released				
41:06.3 Event button pressed				
41:06.4 Event button released				
42:13.1 Event button pressed				
42:16.1 Recording stopped due to button press	96	4	54.563	db8aaaf89f574789be0ea4579e92ff67
42:16.8 Audio recording disabled due to video buffering default				
42:17.0 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-26 2040 X6033271L' using Axon applicator				db8aaaf89f574789be0ea4579e92ff67
42:17.2 Event button released				
24:27.0 Audit log created	92	4 1.13.32	54.562	
41:57.6 Power button pressed				
42:00.6 Device powered off using button	90	4	54.562	
42:01.3 Power button released				
19:59.2 Device powered on using button	90	4	54.561	
19:59.2 Audit log created		1.13.32		
20:02.2 Audio recording disabled due to video buffering default				
20:15.8 Axon application connected to device				
20:53.2 Axon application connected to device				
24:11.1 Video played back using Axon application				ace4789708254e6fb3c1af5d2890f981
27:46.6 Title changed in video metadata from 'Axon Body 3 Video 2021-06-26 2032 X6033271L' to 'Sig. 31 Sig. 19 Sig 35 Issued By 360' using Axon applicator				ace4789708254e6fb3c1af5d2890f981
27:46.6 Categories 'Fare Evasion', 'Sleeper' added to video metadata using Axon applicator				ace4789708254e6fb3c1af5d2890f981
28:02.5 Video played back using Axon application				44dac44c510144969059a8d4584a04e1
29:04.0 Title changed in video metadata from 'Axon Body 3 Video 2021-06-26 0203 X6033271L' to 'Clearing Train N11' using Axon applicator				44dac44c510144969059a8d4584a04e1
29:04.0 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				44dac44c510144969059a8d4584a04e1
29:16.7 Video played back using Axon application				bd3473f910284c04b9b6341279361913
29:43.6 Title changed in video metadata from 'Axon Body 3 Video 2021-06-26 0143 X6033271L' to 'Clearing Train N11' using Axon applicator				bd3473f910284c04b9b6341279361913
29:43.6 Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				bd3473f910284c04b9b6341279361913
29:54.9 Axon application disconnected from device				
11:52.5 Event button pressed				
11:52.6 Event button released				
11:52.7 Event button pressed				
11:52.7 Audio recording enabled due to video recording default				
11:52.8 Event button released				
11:52.9 Recording started due to button press	85	5	54.559	0fc5b497fa0547758033b942bcacf6eba
13:57.3 Event button pressed				
14:00.3 Recording stopped due to button press	85	5	54.432	0fc5b497fa0547758033b942bcacf6eba
14:00.8 Event button released				
14:01.1 Audio recording disabled due to video buffering default				
14:01.2 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 0111 X6033271L' using Axon applicator				0fc5b497fa0547758033b942bcacf6eba

14:36.0	Event button pressed				
14:36.2	Event button released				
14:36.3	Event button pressed				
14:36.3	Audio recording enabled due to video recording default				
14:36.4	Event button released				
14:36.5	Recording started due to button press	85	6	54.431	c82ca6339d70446c94f00010aac2f729
15:52.8	Event button pressed				
15:55.8	Recording stopped due to button press	84	6	54.371	c82ca6339d70446c94f00010aac2f729
15:56.8	Audio recording disabled due to video buffering default				
15:56.9	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-27 0114 X6033271L' using Axon applicator				c82ca6339d70446c94f00010aac2f729
15:57.1	Event button released				
19:59.2	Audit log created	84	6 1.13.32	54.371	
32:32.6	Axon application connected to device				
33:07.5	Video played back using Axon application				ace4789708254e6fb3c1af5d2890f981
35:54.0	Video played back using Axon application				db8aaaf89f574789be0ea4579e92ff67
37:46.3	Title changed in video metadata from 'Axon Body 3 Video 2021-06-26 2040 X6033271L' to 'Unattended Package' using Axon applicator				db8aaaf89f574789be0ea4579e92ff67
37:46.3	Categories 'Suspicious Package', 'Disorderly Person' added to video metadata using Axon applicator				db8aaaf89f574789be0ea4579e92ff67
37:52.3	Title changed in video metadata from 'Unattended Package' to 'Unattended Package N6' using Axon applicator				db8aaaf89f574789be0ea4579e92ff67
38:44.9	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0111 X6033271L' to 'Unattended Package NE10' using Axon applicator				Ofc5b497fa0547758033b942bc6af6eba
40:15.0	Title changed in video metadata from 'Unattended Package NE10' to 'Clearing Train NE10' using Axon applicator				Ofc5b497fa0547758033b942bc6af6eba
40:15.0	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				Ofc5b497fa0547758033b942bc6af6eba
40:43.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0114 X6033271L' to 'Clearing Train NE10' using Axon applicator				c82ca6339d70446c94f00010aac2f729
40:43.1	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				c82ca6339d70446c94f00010aac2f729
40:47.8	Axon application disconnected from device				
43:22.9	Event button pressed				
43:23.1	Event button released				
43:23.1	Event button pressed				
43:23.2	Event button released				
43:23.2	Audio recording enabled due to video recording default				
43:23.3	Recording started due to button press	82	7	54.369	1e7bc2b1084d40dbb47c8da54d2ff387
44:43.3	Event button pressed				
44:46.3	Recording stopped due to button press	81	7	54.265	1e7bc2b1084d40dbb47c8da54d2ff387
44:47.2	Audio recording disabled due to video buffering default				
44:47.3	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-27 0143 X6033271L' using Axon applicator				1e7bc2b1084d40dbb47c8da54d2ff387
44:47.6	Event button released				
54:21.3	Event button pressed				
54:21.5	Event button released				
54:21.6	Event button pressed				
54:21.6	Audio recording enabled due to video recording default				
54:21.7	Event button released				
54:21.7	Recording started due to button press	80	8	54.264	3aa46034cfd4be38d30bcc1a5acbd92
56:15.9	Event button pressed				
56:18.9	Recording stopped due to button press	80	8	54.143	3aa46034cfd4be38d30bcc1a5acbd92
56:19.3	Event button released				
56:19.6	Audio recording disabled due to video buffering default				
56:19.7	Title changed in video metadata from " to 'Axon Body 3 Video 2021-06-27 0154 X6033271L' using Axon applicator				3aa46034cfd4be38d30bcc1a5acbd92
19:59.2	Audit log created	78	8 1.13.32	54.141	

20:19.1	Volume up button pressed				
20:19.4	Volume up button released				
51:51.2	Event button pressed				
51:51.3	Event button released				
51:51.4	Event button pressed				
51:51.4	Audio recording enabled due to video recording default				
51:51.5	Event button released				
51:51.6	Recording started due to button press	75	8	54.14	fd591c33e8d6425aacb2b4884fd99a63
53:27.0	Event button pressed				
53:27.1	Event button released				
53:27.2	Event button pressed				
53:27.4	Event button released				
53:27.8	Event button pressed				
53:30.0	Event button released				
53:33.4	Event button pressed				
53:36.4	Recording stopped due to button press	74	9	54.025	fd591c33e8d6425aacb2b4884fd99a63
53:36.8	Event button released				
53:37.1	Audio recording disabled due to video buffering default				
53:37.2	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 0251 X6033271L' using Axon applicator				fd591c33e8d6425aacb2b4884fd99a63
53:42.3	Event button pressed				
53:42.5	Event button released				
53:42.6	Event button pressed				
53:42.6	Audio recording enabled due to video recording default				
53:42.7	Recording started due to button press	74	10	54.024	a595d09ace0c406f841cafe9edd725a3
53:42.8	Event button released				
01:49.6	Event button pressed				
01:52.6	Recording stopped due to button press	73	10	53.761	a595d09ace0c406f841cafe9edd725a3
01:53.0	Event button released				
01:53.4	Audio recording disabled due to video buffering default				
01:53.6	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 0253 X6033271L' using Axon applicator				a595d09ace0c406f841cafe9edd725a3
18:52.8	Axon application connected to device				
19:59.3	Audit log created	71	10	1.13.32	53.759
21:59.0	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				1e7bc2b1084d40dbb47c8da54d2ff387
22:24.9	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0143 X6033271L' to 'Clearing Train NE10' using Axon applicator				1e7bc2b1084d40dbb47c8da54d2ff387
23:56.6	Volume up button pressed				
23:57.4	Volume up button released				
25:00.2	Categories 'Customer Assist' added to video metadata using Axon applicator				3aa46034cfd4be38d30bcc1a5acbd92
25:00.2	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0154 X6033271L' to 'Sig.15 Phone Call' using Axon applicator				3aa46034cfd4be38d30bcc1a5acbd92
25:34.2	Title changed in video metadata from 'Sig.15 Phone Call' to 'Sig.15 Phone Call NE10' using Axon applicator				3aa46034cfd4be38d30bcc1a5acbd92
26:39.9	Categories 'Loitering' added to video metadata using Axon applicator				fd591c33e8d6425aacb2b4884fd99a63
26:39.9	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0251 X6033271L' to 'Sig. 70 x2 NE9' using Axon applicator				fd591c33e8d6425aacb2b4884fd99a63
27:35.6	Categories 'Sleeper' added to video metadata using Axon applicator				a595d09ace0c406f841cafe9edd725a3
27:35.6	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 0253 X6033271L' to 'Sig. 31 X2 NE9' using Axon applicator				a595d09ace0c406f841cafe9edd725a3
27:54.9	Title changed in video metadata from 'Sig. 31 X2 NE9' to 'Sig. 31 x2 NE9' using Axon application				a595d09ace0c406f841cafe9edd725a3
40:37.3	Camera connected to Axon Dock X62001W9H	70	10	53.771	
40:37.3	Axon application disconnected from device				
40:37.4	Audit log rolled	70	10	53.758	

40:37.4	Audit log created	70	10	1.13.32	53.758	
40:38.2	Device connected to charger	70	10		53.758	
40:54.7	Video upload started when camera was docked					bd3473f910284c04b9b6341279361913
41:09.0	Date/Time synced to 06/27/2021 03:41:09.02 AM from 06/27/2021 03:41:07.47 AM					
41:11.1	Audit log successfully uploaded					
41:11.3	Audit log successfully uploaded and deleted from device	70	10		53.771	
41:18.3	Video successfully uploaded from device when docked					bd3473f910284c04b9b6341279361913
41:18.6	Video deleted from device when docked	70	9		53.848	bd3473f910284c04b9b6341279361913
41:18.6	Audit log created	70	9	1.13.32	53.849	
41:18.6	Audit log rolled	70	9		53.849	
41:18.8	Video upload started when camera was docked					44dac44c510144969059a8d4584a04e1
41:20.9	Audit log successfully uploaded					
41:21.1	Audit log successfully uploaded and deleted from device	70	9		53.848	
41:25.4	Audit log successfully uploaded					
41:25.7	Audit log successfully uploaded and deleted from device	70	9		53.848	
41:45.2	Audit log successfully uploaded					
41:45.5	Audit log successfully uploaded and deleted from device	70	9		53.848	
41:47.8	Video successfully uploaded from device when docked					44dac44c510144969059a8d4584a04e1
41:48.1	Video deleted from device when docked	70	8		53.946	44dac44c510144969059a8d4584a04e1
41:48.1	Audit log created	70	8	1.13.32	53.946	
41:48.1	Audit log rolled	70	8		53.946	
41:48.4	Video upload started when camera was docked					ace4789708254e6fb3c1af5d2890f981
41:50.8	Audit log successfully uploaded					
41:51.0	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:04.2	Audit log successfully uploaded					
42:04.4	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:13.6	Audit log successfully uploaded					
42:13.8	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:19.5	Audit log successfully uploaded					
42:19.7	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:39.9	Audit log successfully uploaded					
42:40.1	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:40.8	Audit log successfully uploaded					
42:41.0	Audit log successfully uploaded and deleted from device	70	8		53.946	
42:52.0	Video successfully uploaded from device when docked					ace4789708254e6fb3c1af5d2890f981
42:52.3	Video deleted from device when docked	70	7		54.151	ace4789708254e6fb3c1af5d2890f981
42:52.3	Audit log rolled	70	7		54.151	
42:52.3	Audit log created	70	7	1.13.32	54.151	
42:52.6	Video upload started when camera was docked					db8aaaf89f574789be0ea4579e92ff67
43:07.2	Audit log successfully uploaded					
43:07.3	Audit log successfully uploaded					
43:07.4	Audit log successfully uploaded and deleted from device	70	7		54.151	
43:07.5	Audit log successfully uploaded and deleted from device	70	7		54.151	
43:16.7	Audit log successfully uploaded					
43:16.9	Audit log successfully uploaded and deleted from device	71	7		54.151	
43:22.0	Audit log successfully uploaded					
43:22.2	Audit log successfully uploaded and deleted from device	71	7		54.151	

43:30.3 Video successfully uploaded from device when dockec			db8aaaf89f574789be0ea4579e92ff67
43:30.5 Video deleted from device when docked	71	6	54.281 db8aaaf89f574789be0ea4579e92ff67
43:30.6 Audit log created	71	6 1.13.32	54.281
43:30.6 Audit log rolled	71	6	54.281
43:30.8 Video upload started when camera was docked			0fc5b497fa0547758033b942bcacf6eba
43:32.6 Audit log successfully uploaded			
43:32.8 Audit log successfully uploaded and deleted from device	71	6	54.281
43:51.3 Audit log successfully uploaded			
43:51.5 Audit log successfully uploaded and deleted from device	71	6	54.281
43:51.6 Audit log successfully uploaded			
43:51.8 Audit log successfully uploaded and deleted from device	71	6	54.281
43:52.9 Audit log successfully uploaded			
43:53.1 Audit log successfully uploaded and deleted from device	71	6	54.281
43:53.2 Audit log successfully uploaded			
43:53.4 Audit log successfully uploaded and deleted from device	71	6	54.281
44:07.3 Video successfully uploaded from device when dockec			0fc5b497fa0547758033b942bcacf6eba
44:07.6 Video deleted from device when docked	71	5	54.409 0fc5b497fa0547758033b942bcacf6eba
44:07.7 Audit log created	71	5 1.13.32	54.409
44:07.7 Audit log rolled	71	5	54.409
44:07.9 Video upload started when camera was docked			c82ca6339d70446c94f00010aac2f729
44:09.5 Audit log successfully uploaded			
44:09.7 Audit log successfully uploaded and deleted from device	71	5	54.409
44:16.9 Audit log successfully uploaded			
44:17.1 Audit log successfully uploaded and deleted from device	71	5	54.409
44:25.5 Video successfully uploaded from device when dockec			c82ca6339d70446c94f00010aac2f729
44:25.7 Video deleted from device when docked	71	4	54.468 c82ca6339d70446c94f00010aac2f729
44:25.8 Audit log rolled	71	4	54.469
44:25.8 Audit log created	71	4 1.13.32	54.469
44:26.0 Video upload started when camera was docked			1e7bc2b1084d40dbb47c8da54d2ff387
44:27.9 Audit log successfully uploaded			
44:28.0 Audit log successfully uploaded and deleted from device	71	4	54.469
44:31.2 Audit log successfully uploaded			
44:31.3 Audit log successfully uploaded and deleted from device	71	4	54.469
44:37.2 Audit log successfully uploaded			
44:37.4 Audit log successfully uploaded and deleted from device	71	4	54.469
44:39.4 Audit log successfully uploaded			
44:39.6 Audit log successfully uploaded and deleted from device	71	4	54.469
44:41.7 Audit log successfully uploaded			
44:41.9 Audit log successfully uploaded and deleted from device	71	4	54.469
44:54.6 Video successfully uploaded from device when dockec			1e7bc2b1084d40dbb47c8da54d2ff387
44:54.9 Video deleted from device when docked	71	3	54.573 1e7bc2b1084d40dbb47c8da54d2ff387
44:55.0 Audit log rolled	71	3	54.573
44:55.0 Audit log created	71	3 1.13.32	54.573
44:55.2 Video upload started when camera was docked			3aa46034cfd4be38d30bcc1a5acbd92
45:03.5 Audit log successfully uploaded			
45:03.7 Audit log successfully uploaded and deleted from device	71	3	54.573
45:28.5 Video successfully uploaded from device when dockec			3aa46034cfd4be38d30bcc1a5acbd92

45:28.8 Video deleted from device when docked	71	2	54.695	3aa46034cfd4be38d30bcc1a5acbd92
45:28.8 Audit log rolled	71	2	54.695	
45:28.8 Audit log created	71	2 1.13.32	54.695	
45:29.0 Video upload started when camera was docked				fd591c33e8d6425aacb2b4884fd99a63
46:00.4 Video successfully uploaded from device when docked				fd591c33e8d6425aacb2b4884fd99a63
46:00.7 Video deleted from device when docked	72	1	54.811	fd591c33e8d6425aacb2b4884fd99a63
46:00.7 Audit log created	72	1 1.13.32	54.811	
46:00.7 Audit log rolled	72	1	54.811	
46:01.0 Video upload started when camera was docked				a595d09ace0c406f841cafe9edd725a3
47:13.3 Video successfully uploaded from device when docked				a595d09ace0c406f841cafe9edd725a3
47:13.7 Video deleted from device when docked	73	0	55.072	a595d09ace0c406f841cafe9edd725a3
47:13.7 Audit log rolled	73	0	55.072	
47:13.7 Audit log created	73	0 1.13.32	55.072	
47:13.7 Audit log created	73	0 1.13.32	55.072	
47:13.7 Audit log rolled	73	0	55.072	
04:40.7 Device disconnected from charger	80	0	55.072	
04:40.8 Camera disconnected from Axon Dock X62001W9H	80	0	55.072	
47:13.0 Audit log created	76	0 1.13.32	55.076	
47:13.0 Audit log created	70	0 1.13.32	55.074	
24:57.7 Volume up button pressed				
24:57.9 Volume up button released				
24:58.5 Volume down button pressed				
24:58.7 Volume down button released				
24:58.9 Volume changed to high from very high using button				
25:02.2 Camera connected to Axon Dock X630020W7	65	0	55.073	
25:02.3 Audit log created	65	0 1.13.32	55.073	
25:02.3 Audit log rolled	65	0	55.073	
25:02.5 Device connected to charger	65	0	55.073	
25:02.0 Audit log created	93	0 1.13.32	55.072	
25:02.0 Audit log created	100	0 1.13.32	55.072	
25:02.0 Audit log created	100	0 1.13.32	55.071	
25:02.0 Audit log created	100	0 1.13.32	55.071	
25:02.0 Audit log created	100	0 1.13.32	55.071	
25:02.1 Audit log created	100	0 1.13.32	55.07	
25:02.1 Audit log created	100	0 1.13.32	55.07	
25:02.1 Audit log created	100	0 1.13.32	55.069	
25:02.1 Audit log created	100	0 1.13.32	55.069	
31:14.5 Device disconnected from charger	98	0	55.069	
31:14.7 Camera disconnected from Axon Dock X630020W7	98	0	55.069	
25:02.1 Audit log created	93	0 1.13.32	55.069	
25:02.1 Audit log created	87	0 1.13.32	55.067	
50:10.2 Event button pressed				
50:10.3 Event button released				
50:10.4 Event button pressed				
50:10.5 Event button released				
50:10.5 Audio recording enabled due to video recording default				
50:10.6 Recording started due to button press	85	1	55.067	3ef1a290c3e944f58b12ee0dcd237433

50:49.9	Event button pressed				
50:52.9	Recording stopped due to button press	84	1	54.984	3ef1a290c3e944f58b12ee0dcd237433
50:53.6	Audio recording disabled due to video buffering default				
50:53.7	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 1750 X6033271L' using Axon applicator				3ef1a290c3e944f58b12ee0dcd237433
50:53.9	Event button released				
25:02.1	Audit log created	81	1	1.13.32	54.983
31:57.4	Event button pressed				
31:57.6	Event button released				
31:57.7	Event button pressed				
31:57.7	Audio recording enabled due to video recording default				
31:57.8	Event button released				
31:57.9	Recording started due to button press	80	2	54.983	1011cfa602014f16954b648643f889ec
40:39.0	Event button pressed				
40:42.0	Recording stopped due to button press	79	2	54.648	1011cfa602014f16954b648643f889ec
40:42.8	Audio recording disabled due to video buffering default				
40:43.0	Event button released				
40:43.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 1831 X6033271L' using Axon applicator				1011cfa602014f16954b648643f889ec
46:16.8	Axon application connected to device				
47:15.4	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 1750 X6033271L' to 'Sig. 23 N6 Bus Loop Code 22' using Axon applicator				3ef1a290c3e944f58b12ee0dcd237433
47:15.4	Categories 'Disorderly Person' added to video metadata using Axon applicator				3ef1a290c3e944f58b12ee0dcd237433
50:20.4	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 1831 X6033271L' to 'Releasing Officer Hartman's Detainee Grady' using A				1011cfa602014f16954b648643f889ec
50:20.4	Categories 'Ambulance Call' added to video metadata using Axon applicator				1011cfa602014f16954b648643f889ec
50:54.8	Title changed in video metadata from 'Releasing Officer Hartman's Detainee Grady' to 'Backing Up Officer Hartman At Grady' using Axon applicator				1011cfa602014f16954b648643f889ec
52:10.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				1011cfa602014f16954b648643f889ec
52:10.6	Categories 'Ambulance Call' removed from video metadata using Axon applicator				1011cfa602014f16954b648643f889ec
52:32.6	Axon application disconnected from device				
57:02.9	Event button pressed				
57:03.0	Event button released				
57:03.1	Event button pressed				
57:03.1	Audio recording enabled due to video recording default				
57:03.1	Event button released				
57:03.2	Recording started due to button press	77	3	54.645	416d5355b006424197b6dc5ba8c9b925
00:48.0	Event button pressed				
00:51.0	Recording stopped due to button press	77	3	54.466	416d5355b006424197b6dc5ba8c9b925
00:51.6	Event button released				
00:51.9	Audio recording disabled due to video buffering default				
00:52.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-27 1857 X6033271L' using Axon applicator				416d5355b006424197b6dc5ba8c9b925
02:29.5	Axon application connected to device				
03:21.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-27 1857 X6033271L' to 'Backing Up Officer Hartman At Grady' using Axon applicator				416d5355b006424197b6dc5ba8c9b925
03:21.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				416d5355b006424197b6dc5ba8c9b925
03:38.9	Axon application disconnected from device				
25:02.1	Audit log created	75	3	1.13.32	54.464
37:36.3	Camera connected to Axon Dock X62001V12	73	3		54.47
37:36.3	Audit log rolled	73	3		54.464
37:36.3	Audit log created	73	3	1.13.32	54.464
37:37.5	Device connected to charger	73	3		54.464
38:01.1	Video upload started when camera was docked				3ef1a290c3e944f58b12ee0dcd237433

38:01.6	Audit log successfully uploaded			
38:01.8	Audit log successfully uploaded and deleted from device	73	3	54.47
38:04.5	Audit log successfully uploaded			
38:04.7	Audit log successfully uploaded and deleted from device	73	3	54.47
38:06.0	Date/Time synced to 06/27/2021 07:38:06.02 PM from 06/27/2021 07:38:06.33 PM			
38:18.0	Audit log successfully uploaded			
38:18.2	Audit log successfully uploaded and deleted from device	73	3	54.47
38:23.3	Video successfully uploaded from device when dockec			3ef1a290c3e944f58b12ee0dcd237433
38:23.6	Video deleted from device when docked	73	2	54.553 3ef1a290c3e944f58b12ee0dcd237433
38:23.6	Audit log rolled	73	2	54.553
38:23.6	Audit log created	73	2 1.13.32	54.553
38:23.8	Video upload started when camera was docked			1011cfa602014f16954b648643f889ec
38:28.1	Audit log successfully uploaded			
38:28.2	Audit log successfully uploaded and deleted from device	74	2	54.553
38:33.4	Audit log successfully uploaded			
38:33.6	Audit log successfully uploaded and deleted from device	74	2	54.553
38:36.7	Audit log successfully uploaded			
38:36.9	Audit log successfully uploaded and deleted from device	74	2	54.553
38:41.4	Audit log successfully uploaded			
38:41.6	Audit log successfully uploaded and deleted from device	74	2	54.553
38:53.7	Audit log successfully uploaded			
38:53.8	Audit log successfully uploaded and deleted from device	74	2	54.553
39:06.0	Audit log successfully uploaded			
39:06.2	Audit log successfully uploaded and deleted from device	74	2	54.552
39:09.3	Audit log successfully uploaded			
39:09.5	Audit log successfully uploaded and deleted from device	74	2	54.552
39:16.0	Audit log successfully uploaded			
39:16.2	Audit log successfully uploaded and deleted from device	74	2	54.552
39:20.6	Audit log successfully uploaded			
39:20.8	Audit log successfully uploaded and deleted from device	74	2	54.552
39:30.0	Audit log successfully uploaded			
39:30.2	Audit log successfully uploaded and deleted from device	74	2	54.552
39:39.3	Audit log successfully uploaded			
39:39.5	Audit log successfully uploaded and deleted from device	74	2	54.552
39:43.7	Audit log successfully uploaded			
39:43.8	Audit log successfully uploaded and deleted from device	74	2	54.552
39:52.0	Audit log successfully uploaded			
39:52.2	Audit log successfully uploaded and deleted from device	74	2	54.552
39:54.3	Audit log successfully uploaded			
39:54.5	Audit log successfully uploaded and deleted from device	74	2	54.552
39:57.3	Audit log successfully uploaded			
39:57.5	Audit log successfully uploaded and deleted from device	74	2	54.552
39:59.0	Video successfully uploaded from device when dockec			1011cfa602014f16954b648643f889ec
39:59.4	Video deleted from device when docked	74	1	54.888 1011cfa602014f16954b648643f889ec
39:59.5	Audit log rolled	74	1	54.888
39:59.5	Audit log created	74	1 1.13.32	54.888
39:59.6	Video upload started when camera was docked			416d5355b006424197b6dc5ba8c9b925

40:10.7	Audit log successfully uploaded				
40:10.9	Audit log successfully uploaded and deleted from device	75	1	54.888	
40:17.6	Audit log successfully uploaded				
40:17.8	Audit log successfully uploaded and deleted from device	75	1	54.888	
40:34.1	Audit log successfully uploaded				
40:34.3	Audit log successfully uploaded and deleted from device	75	1	54.888	
40:43.0	Audit log successfully uploaded				
40:43.2	Audit log successfully uploaded and deleted from device	75	1	54.888	
40:49.8	Video successfully uploaded from device when dockec				416d5355b006424197b6dc5ba8c9b925
40:50.2	Video deleted from device when docked	75	0	55.068	416d5355b006424197b6dc5ba8c9b925
40:50.2	Audit log rolled	75	0	55.068	
40:50.2	Audit log created	75	0 1.13.32	55.068	
40:50.3	Audit log rolled	75	0	55.068	
40:50.3	Audit log created	75	0 1.13.32	55.068	
40:55.4	Audit log successfully uploaded				
40:55.6	Audit log successfully uploaded and deleted from device	75	0	55.068	
41:00.4	Audit log successfully uploaded				
41:00.6	Audit log successfully uploaded and deleted from device	75	0	55.068	
41:03.8	Audit log successfully uploaded				
41:04.0	Audit log successfully uploaded and deleted from device	75	0	55.068	
41:06.1	Audit log successfully uploaded				
41:06.3	Audit log successfully uploaded and deleted from device	75	0	55.068	
41:14.8	Audit log successfully uploaded				
41:15.0	Audit log successfully uploaded and deleted from device	75	0	55.068	
41:32.5	Audit log successfully uploaded				
41:32.7	Audit log successfully uploaded and deleted from device	75	0	55.068	
01:08.1	Device disconnected from charger	84	0	55.072	
01:08.1	Camera disconnected from Axon Dock X62001V12	84	0	55.072	
39:05.0	Power button pressed				
39:08.1	Device powered off using button	80	0	55.071	
39:08.6	Power button released				
19:54.1	Audit log created		1.13.32		
19:54.2	Device powered on using button	80	0	55.07	
19:57.2	Audio recording disabled due to video buffering default				
37:15.3	Audio recording enabled due to video recording default				
37:15.5	Recording started due to Axon Signal Vehicle activation	78	1	55.07	a5c1ba43fb024267a4df288f300e7e20
39:19.9	Event button pressed				
39:22.9	Recording stopped due to button press	77	1	54.944	a5c1ba43fb024267a4df288f300e7e20
39:23.6	Event button released				
39:23.9	Audio recording disabled due to video buffering default				
39:24.0	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-28 0037 X6033271L' using Axon applicator				a5c1ba43fb024267a4df288f300e7e20
14:18.2	Axon application connected to device				
15:21.0	Title changed in video metadata from 'Axon Body 3 Video 2021-06-28 0037 X6033271L' to 'Accidental recording' using Axon applicator				a5c1ba43fb024267a4df288f300e7e20
15:21.0	Categories 'Accidental Recording' added to video metadata using Axon applicator				a5c1ba43fb024267a4df288f300e7e20
15:47.3	Video played back using Axon application				a5c1ba43fb024267a4df288f300e7e20
16:06.2	Axon application disconnected from device				
19:54.1	Audit log created	73	1 1.13.32	54.942	

28:27.8	Event button pressed				
28:27.8	Event button released				
28:27.9	Event button pressed				
28:27.9	Event button released				
28:28.0	Audio recording enabled due to video recording default				
28:28.1	Recording started due to button press	72	2	54.941	8826d8c52eca4fe4830ab62d5a3e87ab
30:44.1	Event button pressed				
30:47.1	Recording stopped due to button press	72	2	54.808	8826d8c52eca4fe4830ab62d5a3e87ab
30:47.6	Event button released				
30:47.8	Audio recording disabled due to video buffering default				
30:48.0	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-28 0128 X6033271L' using Axon applicator				8826d8c52eca4fe4830ab62d5a3e87ab
47:08.6	Event button pressed				
47:08.7	Event button released				
47:08.8	Event button pressed				
47:08.8	Audio recording enabled due to video recording default				
47:08.9	Event button released				
47:09.0	Recording started due to button press	70	2	54.806	9e517d43bc3e4883ad5e106bba24112b
49:02.3	Event button pressed				
49:05.3	Recording stopped due to button press	70	3	54.685	9e517d43bc3e4883ad5e106bba24112b
49:06.0	Event button released				
49:06.0	Audio recording disabled due to video buffering default				
49:06.2	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-28 0147 X6033271L' using Axon applicator				9e517d43bc3e4883ad5e106bba24112b
53:54.1	Event button pressed				
53:54.2	Event button released				
53:54.3	Event button pressed				
53:54.4	Audio recording enabled due to video recording default				
53:54.4	Event button released				
53:54.5	Recording started due to button press	70	4	54.684	fc80372f9fd544b981a85abe38348fda
54:27.0	Event button pressed				
54:30.0	Recording stopped due to button press	69	4	54.606	fc80372f9fd544b981a85abe38348fda
54:30.7	Event button released				
54:30.8	Audio recording disabled due to video buffering default				
54:31.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-28 0153 X6033271L' using Axon applicator				fc80372f9fd544b981a85abe38348fda
19:54.1	Audit log created	66	4 1.13.32	54.604	
26:22.7	Axon application connected to device				
27:11.5	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				8826d8c52eca4fe4830ab62d5a3e87ab
27:11.5	Title changed in video metadata from 'Axon Body 3 Video 2021-06-28 0128 X6033271L' to 'Clearing Train NE10' using Axon applicator				8826d8c52eca4fe4830ab62d5a3e87ab
27:43.8	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator				9e517d43bc3e4883ad5e106bba24112b
27:43.8	Title changed in video metadata from 'Axon Body 3 Video 2021-06-28 0147 X6033271L' to 'Clearing Train NE10' using Axon applicator				9e517d43bc3e4883ad5e106bba24112b
27:52.2	Axon application disconnected from device				
19:54.1	Audit log created	61	4 1.13.32	54.602	
19:54.1	Audit log created	54	4 1.13.32	54.601	
19:54.1	Audit log created	47	4 1.13.32	54.599	
12:52.5	Power button pressed				
12:53.4	Power button released				
12:54.1	Volume up button pressed				
12:54.5	Volume up button released				

12:54.5	Volume up button pressed			
12:54.6	Volume up button released			
12:54.6	Volume changed to very high from high using button			
13:03.2	Camera connected to Axon Dock X630020W7	42	4	54.598
13:03.2	Audit log rolled	42	4	54.598
13:03.2	Audit log created	42	4 1.13.32	54.598
13:04.2	Device connected to charger	42	4	54.598
13:03.0	Audit log created	69	4 1.13.32	54.598
13:03.0	Audit log created	96	4 1.13.32	54.597
13:03.0	Audit log created	100	4 1.13.32	54.596
13:03.0	Audit log created	100	4 1.13.32	54.596
13:03.0	Audit log created	100	4 1.13.32	54.596
13:03.0	Audit log created	100	4 1.13.32	54.598
13:03.0	Audit log created	100	4 1.13.32	54.598
13:03.0	Audit log created	100	4 1.13.32	54.598
13:03.0	Audit log created	100	4 1.13.32	54.597
13:03.1	Audit log created	100	4 1.13.32	54.597
13:03.1	Audit log created	100	4 1.13.32	54.596
13:03.1	Audit log created	100	4 1.13.32	54.596
04:19.2	Device disconnected from charger	98	4	54.596
04:19.6	Camera disconnected from Axon Dock X630020W7	98	4	54.596
04:20.9	Power button pressed			
04:23.9	Device powered off using button	100	4	54.6
04:24.4	Power button released			
12:06.9	Audit log created		1.13.32	
12:07.0	Device connected to charger			
12:07.0	Device powered on due to charger connection	100	4	54.6
12:07.0	Camera connected to Axon Dock X62001W9H	100	4	54.607
12:07.0	Audit log rolled			
12:07.0	Audit log created		1.13.32	
12:08.0	Camera connected to Axon Dock X62001W9H	100	3	54.733
12:09.8	Audit log created	100	4 1.13.32	54.6
12:09.8	Audit log rolled	100	4	54.6
12:16.3	Video upload started when camera was docked			a5c1ba43fb024267a4df288f300e7e20
12:18.0	Audit log successfully uploaded			
12:18.2	Audit log successfully uploaded and deleted from device	100	4	54.608
12:36.4	Audit log successfully uploaded			
12:36.5	Audit log successfully uploaded and deleted from device	100	4	54.607
12:40.0	Date/Time synced to 06/28/2021 11:12:40.01 PM from 06/28/2021 11:12:39.46 PM			
12:48.0	Audit log successfully uploaded			
12:48.2	Audit log successfully uploaded and deleted from device	100	4	54.607
12:54.6	Video successfully uploaded from device when dockec			a5c1ba43fb024267a4df288f300e7e20
12:54.9	Video deleted from device when docked	100	3	54.733 a5c1ba43fb024267a4df288f300e7e20
12:54.9	Audit log created	100	3 1.13.32	54.734
12:54.9	Audit log rolled	100	3	54.734
12:55.1	Video upload started when camera was docked			8826d8c52eca4fe4830ab62d5a3e87ab
13:07.0	Audit log successfully uploaded			

13:07.2	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:15.4	Audit log successfully uploaded				
13:15.6	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:19.4	Audit log successfully uploaded				
13:19.6	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:20.8	Audit log successfully uploaded				
13:20.9	Audit log successfully uploaded				
13:21.0	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:21.1	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:28.3	Audit log successfully uploaded				
13:28.5	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:32.2	Audit log successfully uploaded				
13:32.4	Audit log successfully uploaded and deleted from device	100	3	54.733	
13:33.1	Video successfully uploaded from device when dockec				8826d8c52eca4fe4830ab62d5a3e87ab
13:33.3	Video deleted from device when docked	100	2	54.867	8826d8c52eca4fe4830ab62d5a3e87ab
13:33.3	Audit log rolled	100	2	54.867	
13:33.3	Audit log created	100	2 1.13.32	54.867	
13:33.5	Video upload started when camera was docked				9e517d43bc3e4883ad5e106bba24112b
13:47.6	Audit log successfully uploaded				
13:47.8	Audit log successfully uploaded and deleted from device	100	2	54.867	
13:48.0	Audit log successfully uploaded				
13:48.3	Audit log successfully uploaded and deleted from device	100	2	54.867	
13:58.6	Audit log successfully uploaded				
13:58.8	Audit log successfully uploaded and deleted from device	100	2	54.867	
14:09.9	Video successfully uploaded from device when dockec				9e517d43bc3e4883ad5e106bba24112b
14:10.2	Video deleted from device when docked	100	1	54.989	9e517d43bc3e4883ad5e106bba24112b
14:10.3	Audit log rolled	100	1	54.989	
14:10.3	Audit log created	100	1 1.13.32	54.989	
14:10.4	Video upload started when camera was docked				fc80372f9fd544b981a85abe38348fda
14:11.4	Audit log successfully uploaded				
14:11.6	Audit log successfully uploaded and deleted from device	100	1	54.989	
14:16.0	Audit log successfully uploaded				
14:16.2	Audit log successfully uploaded and deleted from device	100	1	54.989	
14:26.7	Audit log successfully uploaded				
14:26.9	Audit log successfully uploaded and deleted from device	100	1	54.989	
14:27.3	Audit log successfully uploaded				
14:27.6	Audit log successfully uploaded and deleted from device	100	1	54.989	
14:33.0	Audit log successfully uploaded				
14:33.2	Audit log successfully uploaded and deleted from device	100	1	54.989	
14:34.2	Video successfully uploaded from device when dockec				fc80372f9fd544b981a85abe38348fda
14:34.4	Video deleted from device when docked	100	0	55.068	fc80372f9fd544b981a85abe38348fda
14:34.5	Audit log created	100	0 1.13.32	55.07	
14:34.5	Audit log rolled	100	0	55.07	
14:34.5	Audit log created	100	0 1.13.32	55.07	
14:34.5	Audit log rolled	100	0	55.07	
14:40.7	Audit log successfully uploaded				
14:40.9	Audit log successfully uploaded and deleted from device	100	0	55.07	

14:51.4	Audit log successfully uploaded			
14:51.7	Audit log successfully uploaded and deleted from device	100	0	55.07
14:59.1	Audit log successfully uploaded			
14:59.3	Audit log successfully uploaded and deleted from device	100	0	55.07
15:08.8	Audit log successfully uploaded			
15:09.0	Audit log successfully uploaded and deleted from device	100	0	55.069
15:19.5	Audit log successfully uploaded			
15:19.7	Audit log successfully uploaded and deleted from device	100	0	55.069
15:19.8	Audit log successfully uploaded			
15:19.9	Audit log successfully uploaded and deleted from device	100	0	55.069
15:29.1	Audit log successfully uploaded			
15:29.2	Audit log successfully uploaded and deleted from device	100	0	55.069
15:30.2	Audit log successfully uploaded			
15:30.4	Audit log successfully uploaded and deleted from device	100	0	55.069
17:40.0	Camera disconnected from Axon Dock X62001W9H	100	0	55.07
17:40.0	Audio recording disabled due to video buffering default			
17:40.3	Device disconnected from charger	100	0	55.07
20:33.9	Event button pressed			
20:34.0	Event button released			
20:34.1	Event button pressed			
20:34.1	Audio recording enabled due to video recording default			
20:34.2	Event button released			
20:34.3	Recording started due to button press	100	1	55.07 317923d785354699a673e93f1a77cd7b
24:35.8	Event button pressed			
24:38.8	Recording stopped due to button press	98	1	54.882 317923d785354699a673e93f1a77cd7b
24:39.3	Event button released			
24:39.7	Audio recording disabled due to video buffering default			
24:39.9	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-28 2320 X6033271L' using Axon application			317923d785354699a673e93f1a77cd7b
28:55.6	Audit log created	98	1 1.13.32	54.881
28:55.6	Audit log rolled	98	1	54.881
28:56.3	Device connected to charger	98	1	54.881
29:01.3	Device disconnected from charger	98	1	54.881
29:01.6	Camera disconnected from Axon Dock X62001W9H	98	1	54.881
28:55.0	Audit log created	91	1 1.13.32	54.88
56:01.7	Volume up button pressed			
56:02.3	Volume up button released			
56:52.1	Volume up button pressed			
56:52.6	Volume up button released			
28:55.0	Audit log created	85	1 1.13.32	54.878
29:38.2	Event button pressed			
29:38.4	Event button released			
29:38.4	Event button pressed			
29:38.5	Audio recording enabled due to video recording default			
29:38.6	Event button released			
29:38.6	Recording started due to button press	85	2	54.878 49d0010a38ea49bebe8e77a5605026ae
29:56.1	Event button pressed			
29:59.1	Recording stopped due to button press	85	2	54.832 49d0010a38ea49bebe8e77a5605026ae

29:59.6	Event button released				
29:59.9	Audio recording disabled due to video buffering default				
30:16.1	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-29 0129 X6033271L' using Axon applicator				49d0010a38ea49bebe8e77a5605026ae
50:16.9	Event button pressed				
50:17.0	Event button released				
50:17.1	Event button pressed				
50:17.2	Audio recording enabled due to video recording default				
50:17.2	Event button released				
50:17.3	Recording started due to button press	84	2	54.806	ae453ee91da14ec3899ac857e38c1ee9
52:18.9	Event button pressed				
52:21.9	Recording stopped due to button press	83	3	54.68	ae453ee91da14ec3899ac857e38c1ee9
52:22.7	Audio recording disabled due to video buffering default				
52:22.8	Event button released				
52:22.9	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-29 0150 X6033271L' using Axon applicator				ae453ee91da14ec3899ac857e38c1ee9
55:33.2	Axon application connected to device				
56:20.1	Categories 'Special Detail' added to video metadata using Axon applicator				ae453ee91da14ec3899ac857e38c1ee9
56:20.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-29 0150 X6033271L' to 'Clearing Train N11' using Axon applicator				ae453ee91da14ec3899ac857e38c1ee9
56:30.7	Categories 'Special Detail' added to video metadata using Axon applicator				49d0010a38ea49bebe8e77a5605026ae
56:39.4	Title changed in video metadata from 'Axon Body 3 Video 2021-06-29 0129 X6033271L' to 'Clearing Train N11' using Axon applicator				49d0010a38ea49bebe8e77a5605026ae
57:07.6	Video played back using Axon application				317923d785354699a673e93f1a77cd7b
57:30.4	Categories 'Accidental Recording' added to video metadata using Axon applicator				317923d785354699a673e93f1a77cd7b
58:10.1	Title changed in video metadata from 'Axon Body 3 Video 2021-06-28 2320 X6033271L' to 'Officer Matos Had My Camera By Mistake' using Axc				317923d785354699a673e93f1a77cd7b
04:19.4	Volume up button pressed				
04:19.8	Volume up button released				
06:57.0	Volume up button pressed				
06:57.0	Volume up button released				
10:26.3	Power button pressed				
10:29.3	Device powered off using button	81	3	54.679	
10:29.7	Power button released				
10:35.6	Axon application disconnected from device				
16:58.9	Audit log created			1.13.32	
16:59.0	Device powered on using button	81	3	54.68	
17:01.0	Audio recording disabled due to video buffering default				
31:24.9	Axon application connected to device				
31:59.5	Axon application disconnected from device				
49:23.7	Power button pressed				
49:24.2	Power button released				
49:24.3	Audit log created	78	3	1.13.32	54.679
49:24.3	Audit log rolled	78	3		54.679
49:24.3	Camera connected to Axon Dock X62001W9H	78	3		54.682
49:25.0	Device connected to charger	78	3		54.679
49:50.1	Video upload started when camera was docked				317923d785354699a673e93f1a77cd7b
49:55.0	Date/Time synced to 06/29/2021 04:49:55.02 AM from 06/29/2021 04:49:54.38 AM				
50:12.9	Audit log successfully uploaded				
50:13.1	Audit log successfully uploaded and deleted from device	78	3		54.682
50:17.2	Audit log successfully uploaded				
50:17.4	Audit log successfully uploaded and deleted from device	78	3		54.682

50:19.5	Audit log successfully uploaded			
50:19.7	Audit log successfully uploaded and deleted from device	78	3	54.682
50:30.7	Audit log successfully uploaded			
50:30.9	Audit log successfully uploaded and deleted from device	78	3	54.682
50:42.0	Audit log successfully uploaded			
50:42.2	Audit log successfully uploaded and deleted from device	78	3	54.682
50:44.5	Video successfully uploaded from device when docked			317923d785354699a673e93f1a77cd7b
50:44.7	Video deleted from device when docked	78	2	54.871 317923d785354699a673e93f1a77cd7b
50:44.8	Audit log rolled	78	2	54.871
50:44.8	Audit log created	78	2 1.13.32	54.871
50:45.0	Video upload started when camera was docked			49d0010a38ea49bebe8e77a5605026ae
50:46.8	Audit log successfully uploaded			
50:47.0	Audit log successfully uploaded and deleted from device	79	2	54.871
50:48.2	Audit log successfully uploaded			
50:48.3	Audit log successfully uploaded and deleted from device	79	2	54.871
51:00.4	Audit log successfully uploaded			
51:00.6	Audit log successfully uploaded and deleted from device	79	2	54.871
51:03.5	Audit log successfully uploaded			
51:03.7	Audit log successfully uploaded and deleted from device	79	2	54.871
51:05.5	Video successfully uploaded from device when docked			49d0010a38ea49bebe8e77a5605026ae
51:05.7	Video deleted from device when docked	79	1	54.942 49d0010a38ea49bebe8e77a5605026ae
51:05.8	Audit log created	79	1 1.13.32	54.942
51:05.8	Audit log rolled	79	1	54.942
51:06.0	Video upload started when camera was docked			ae453ee91da14ec3899ac857e38c1ee9
51:24.7	Audit log successfully uploaded			
51:24.9	Audit log successfully uploaded and deleted from device	79	1	54.942
51:41.5	Video successfully uploaded from device when docked			ae453ee91da14ec3899ac857e38c1ee9
51:41.7	Video deleted from device when docked	79	0	55.068 ae453ee91da14ec3899ac857e38c1ee9
51:41.7	Audit log created	79	0 1.13.32	55.068
51:41.7	Audit log rolled	79	0	55.068
51:41.8	Audit log created	79	0 1.13.32	55.068
51:41.8	Audit log rolled	79	0	55.068
03:49.6	Device disconnected from charger	85	0	55.068
03:49.8	Camera disconnected from Axon Dock X62001W9H	85	0	55.068
11:04.4	Volume up button pressed			
11:04.5	Volume up button released			
11:38.9	Volume up button pressed			
11:39.3	Volume up button released			
47:22.3	Event button pressed			
47:22.4	Event button released			
47:22.5	Event button pressed			
47:22.5	Audio recording enabled due to video recording default			
47:22.5	Event button released			
47:22.7	Recording started due to button press	80	0	55.068 b55d5b02470c4b79860effd114743883
51:41.0	Audit log created	79	1 1.13.32	54.873
53:56.0	Event button pressed			
53:56.6	Event button released			

53:59.3	Event button pressed			
54:02.1	Event button released			
54:04.7	Event button pressed			
54:07.7	Recording stopped due to button press	79	1	54.796 b55d5b02470c4b79860effd114743883
54:08.3	Event button released			
54:08.4	Audio recording disabled due to video buffering default			
54:08.7	Title changed in video metadata from '' to 'Axon Body 3 Video 2021-06-29 0547 X6033271L' using Axon applicator			b55d5b02470c4b79860effd114743883
57:04.8	Volume down button pressed			
57:04.9	Volume down button released			
57:05.0	Volume changed to high from very high using button			
19:32.0	Volume up button pressed			
19:32.6	Volume up button released			
19:32.7	Volume changed to very high from high using button			
19:40.7	Power button pressed			
19:43.7	Device powered off using button	76	1	54.794
19:44.1	Power button released			
37:13.0	Device connected to charger			
37:13.0	Device powered on due to charger connection	77	1	54.793
37:13.0	Camera connected to Axon Dock X630020W7	77	1	54.793
37:13.0	Audit log created		1.13.32	
37:13.0	Audit log rolled			
37:14.0	Camera connected to Axon Dock X630020W7	77	1	54.793
37:15.9	Audit log rolled	77	1	54.793
37:15.9	Audit log created	77	1 1.13.32	54.793
05:27.0	Device disconnected from charger	90	1	54.793
05:27.1	Camera disconnected from Axon Dock X630020W7	90	1	54.793
05:27.2	Audio recording disabled due to video buffering default			
05:35.8	Axon application connected to device			
07:52.5	Categories 'Ambulance Call' added to video metadata using Axon applicator			b55d5b02470c4b79860effd114743883
07:52.5	Title changed in video metadata from 'Axon Body 3 Video 2021-06-29 0547 X6033271L' to 'AMR 80 Transp. Sig.47 To Northside Hosp' using Axo			b55d5b02470c4b79860effd114743883
08:46.5	Video played back using Axon application			b55d5b02470c4b79860effd114743883
11:45.3	Title changed in video metadata from 'AMR 80 Transp. Sig.47 To Northside Hosp' to 'N9 AMR 80 Transp. Him To Northside Hosp' using Axon ap			b55d5b02470c4b79860effd114743883
12:31.6	Axon application disconnected from device			
12:36.6	Camera connected to Axon Dock X630020W7	89	1	54.793
12:36.6	Audit log rolled	89	1	54.793
12:36.6	Audit log created	89	1 1.13.32	54.794
12:38.0	Device connected to charger	89	1	54.793
12:36.0	Audit log created	100	1 1.13.32	54.793
12:36.0	Audit log created	100	1 1.13.32	54.793
12:36.0	Audit log created	100	1 1.13.32	54.792
12:36.0	Audit log created	100	1 1.13.32	54.794
12:36.0	Audit log created	100	1 1.13.32	54.799
12:36.0	Audit log created	100	1 1.13.32	54.8
12:36.0	Audit log created	100	1 1.13.32	54.799
12:36.0	Audit log created	100	1 1.13.32	54.799
12:36.0	Audit log created	100	1 1.13.32	54.799
12:36.1	Audit log created	100	1 1.13.32	54.798

12:36.1	Audit log created	100	1 1.13.32	54.798	
17:26.0	Device disconnected from charger	98	1	54.798	
17:26.5	Camera disconnected from Axon Dock X630020W7	100	1	54.798	
17:28.5	Power button pressed				
17:30.5	Power button released				
17:31.0	Power button pressed				
17:34.0	Device powered off using button	100	1	54.798	
17:34.6	Power button released				
16:06.9	Audit log created		1.13.32		
16:07.1	Device powered on using button	100	1	54.797	
16:09.0	Audio recording disabled due to video buffering default				
20:37.9	Camera connected to Axon Dock X62001W9H	99	1	54.802	
20:38.0	Audit log created	99	1 1.13.32	54.797	
20:38.0	Audit log rolled	99	1	54.797	
20:39.1	Device connected to charger	99	1	54.797	
21:03.3	Video upload started when camera was docked				b55d5b02470c4b79860effd114743883
21:11.0	Date/Time synced to 07/01/2021 05:21:11.01 PM from 07/01/2021 05:21:08.02 PM				
21:33.1	Audit log successfully uploaded				
21:33.2	Audit log successfully uploaded and deleted from device	99	1	54.802	
21:39.8	Audit log successfully uploaded				
21:40.0	Audit log successfully uploaded and deleted from device	99	1	54.802	
21:44.3	Audit log successfully uploaded				
21:44.6	Audit log successfully uploaded and deleted from device	99	1	54.802	
21:48.1	Audit log successfully uploaded				
21:48.3	Audit log successfully uploaded and deleted from device	99	1	54.801	
21:52.5	Audit log successfully uploaded				
21:52.7	Audit log successfully uploaded and deleted from device	99	1	54.801	
22:07.7	Audit log successfully uploaded				
22:07.9	Audit log successfully uploaded and deleted from device	99	1	54.801	
22:09.8	Audit log successfully uploaded				
22:09.9	Audit log successfully uploaded and deleted from device	99	1	54.801	
22:25.0	Audit log successfully uploaded				
22:25.2	Audit log successfully uploaded and deleted from device	99	1	54.801	
22:27.1	Audit log successfully uploaded				
22:27.3	Audit log successfully uploaded and deleted from device	99	1	54.801	
22:28.5	Video successfully uploaded from device when docked				b55d5b02470c4b79860effd114743883
22:28.8	Video deleted from device when docked	99	0	55.074	b55d5b02470c4b79860effd114743883
22:28.8	Audit log created	99	0 1.13.32	55.074	
22:28.8	Audit log rolled	99	0	55.074	
22:28.8	Audit log created	99	0 1.13.32	55.074	
22:28.8	Audit log rolled	99	0	55.074	
22:33.7	Volume up button pressed				
22:33.9	Volume up button released				
22:34.7	Camera disconnected from Axon Dock X62001W9H	99	0	55.074	
22:34.8	Device disconnected from charger	99	0	55.074	
08:46.0	Camera connected to Axon Dock X630020W7	94	0	55.073	
08:46.1	Audit log created	94	0 1.13.32	55.073	

08:46.1 Audit log rolled	94	0	55.073
08:46.8 Device connected to charger	94	0	55.073
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.0 Audit log created	100	0 1.13.32	55.071
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.0 Audit log created	100	0 1.13.32	55.072
08:46.1 Audit log created	100	0 1.13.32	55.071
08:46.1 Audit log created	100	0 1.13.32	55.071
08:46.1 Audit log created	100	0 1.13.32	55.071
55:28.6 Camera disconnected from Axon Dock X630020W7	99	0	55.071
55:28.8 Device disconnected from charger	99	0	55.071
55:29.6 Power button pressed			
55:32.6 Device powered off using button	100	0	55.071
55:32.9 Power button released			
25:11.0 Audit log created		1.13.32	
25:11.2 Device powered on using button	100	0	55.07
25:14.2 Audio recording disabled due to video buffering default			
28:38.3 Select button pressed			
28:38.4 Select button released			
28:38.5 Select button pressed			
28:38.8 Select button released			
28:42.0 Camera connected to Axon Dock X62001V12	99	0	55.073
28:42.0 Audit log rolled	99	0	55.07
28:42.0 Audit log created	99	0 1.13.32	55.07
28:43.2 Device connected to charger	99	0	55.07
29:13.0 Date/Time synced to 07/02/2021 08:29:13.01 PM from 07/02/2021 08:29:12.09 PM			
29:39.0 Audit log successfully uploaded			
29:39.2 Audit log successfully uploaded and deleted from device	99	0	55.073
29:43.8 Audit log successfully uploaded			
29:44.0 Audit log successfully uploaded and deleted from device	99	0	55.073
29:51.3 Audit log successfully uploaded			
29:51.6 Audit log successfully uploaded and deleted from device	99	0	55.073
30:00.9 Audit log successfully uploaded			
30:01.1 Audit log successfully uploaded and deleted from device	99	0	55.073
30:11.1 Audit log successfully uploaded			
30:11.3 Audit log successfully uploaded and deleted from device	99	0	55.073
30:13.2 Audit log successfully uploaded			
30:13.4 Audit log successfully uploaded and deleted from device	99	0	55.073
30:37.5 Audit log successfully uploaded			
30:37.7 Audit log successfully uploaded and deleted from device	99	0	55.073
30:41.5 Audit log successfully uploaded			
30:41.8 Audit log successfully uploaded and deleted from device	99	0	55.073
30:50.9 Audit log successfully uploaded			
30:51.1 Audit log successfully uploaded and deleted from device	99	0	55.073

30:57.9	Audit log successfully uploaded			
30:58.1	Audit log successfully uploaded and deleted from device	99	0	55.073
31:13.2	Audit log successfully uploaded			
31:13.4	Audit log successfully uploaded and deleted from device	100	0	55.073
31:14.2	Audit log successfully uploaded			
31:14.4	Audit log successfully uploaded and deleted from device	100	0	55.073
31:19.6	Audit log successfully uploaded			
31:19.8	Audit log successfully uploaded and deleted from device	100	0	55.073
31:33.0	Audit log successfully uploaded			
31:33.2	Audit log successfully uploaded and deleted from device	100	0	55.073
31:38.3	Audit log successfully uploaded			
31:38.5	Audit log successfully uploaded and deleted from device	100	0	55.073
31:39.6	Audit log successfully uploaded			
31:39.8	Audit log successfully uploaded and deleted from device	100	0	55.073
31:41.6	Audit log successfully uploaded			
31:41.9	Audit log successfully uploaded and deleted from device	100	0	55.073
31:49.0	Audit log successfully uploaded			
31:49.2	Audit log successfully uploaded and deleted from device	100	0	55.073
31:53.1	Audit log successfully uploaded			
31:53.3	Audit log successfully uploaded and deleted from device	100	0	55.073
32:07.5	Audit log successfully uploaded			
32:07.7	Audit log successfully uploaded and deleted from device	100	0	55.073
32:10.3	Audit log successfully uploaded			
32:10.5	Audit log successfully uploaded and deleted from device	100	0	55.073
32:22.6	Audit log successfully uploaded			
32:22.8	Audit log successfully uploaded and deleted from device	100	0	55.073
32:32.0	Audit log successfully uploaded			
32:32.2	Audit log successfully uploaded and deleted from device	100	0	55.073
32:34.8	Audit log successfully uploaded			
32:35.0	Audit log successfully uploaded and deleted from device	100	0	55.073
32:52.4	Audit log successfully uploaded			
32:52.6	Audit log successfully uploaded and deleted from device	100	0	55.073
33:04.1	Audit log successfully uploaded			
33:04.3	Audit log successfully uploaded and deleted from device	100	0	55.073
33:13.7	Audit log successfully uploaded			
33:13.9	Audit log successfully uploaded and deleted from device	100	0	55.073
47:28.8	Device disconnected from charger	100	0	55.074
47:28.8	Camera disconnected from Axon Dock X62001V12	100	0	55.074
56:31.5	Power button pressed			
56:34.5	Device powered off using button	99	0	55.073
56:35.0	Power button released			
18:19.1	Audit log created		1.13.32	
18:19.2	Device powered on using button	99	0	55.073
18:21.1	Audio recording disabled due to video buffering default			
18:42.8	Volume down button pressed			
18:43.0	Volume down button released			
18:43.1	Volume changed to high from very high using button			

18:47.0	Volume down button pressed			
18:47.1	Volume down button released			
18:47.2	Volume changed to medium from high using button			
19:10.7	Volume down button pressed			
19:10.8	Volume down button released			
19:11.0	Volume changed to low from medium using button			
19:11.1	Volume down button pressed			
19:11.2	Volume down button released			
19:11.3	Volume down button pressed			
19:11.4	Volume changed to very low from low using button			
19:11.8	Volume down button released			
19:11.9	Volume down button pressed			
19:11.9	Volume changed to off from very low using button			
19:12.0	Volume down button released			
19:12.1	Volume down button pressed			
19:12.3	Volume down button released			
19:12.4	Volume down button pressed			
19:12.5	Volume down button released			
19:12.6	Volume down button pressed			
19:12.8	Volume down button released			
19:12.9	Volume down button pressed			
19:13.0	Volume down button released			
19:13.0	Volume down button pressed			
19:13.2	Volume down button released			
19:15.0	Volume up button pressed			
19:15.2	Volume up button released			
19:15.3	Volume changed to very low from off using button			
19:15.7	Volume up button pressed			
19:15.9	Volume up button released			
19:16.0	Volume changed to low from very low using button			
19:16.4	Volume up button pressed			
19:16.6	Volume up button released			
19:16.6	Volume changed to medium from low using button			
18:19.1	Audit log created	92	0 1.13.32	55.071
51:35.2	Power button pressed			
51:38.2	Device powered off using button	89	0	55.07
51:38.6	Power button released			
21:02.1	Audit log created		1.13.32	
21:02.2	Device powered on using button	89	0	55.071
21:05.1	Audio recording disabled due to video buffering default			
59:35.7	Power button pressed			
59:38.7	Device powered off using button	85	0	55.07
59:39.4	Power button released			
21:42.1	Audit log created		1.13.32	
21:42.2	Device powered on using button	85	0	55.069
21:44.1	Audio recording disabled due to video buffering default			
21:58.3	Axon application connected to device			

22:14.8	Axon application disconnected from device			
09:55.1	Power button pressed			
09:56.3	Power button released			
09:57.7	Volume up button pressed			
09:57.8	Volume up button released			
09:58.0	Volume changed to high from medium using button			
10:01.3	Volume up button pressed			
10:01.7	Volume up button released			
10:01.8	Volume changed to very high from high using button			
10:02.1	Volume up button pressed			
10:02.3	Volume up button released			
10:04.5	Volume down button pressed			
10:04.7	Volume down button released			
10:04.8	Volume changed to high from very high using button			
10:05.3	Volume down button pressed			
10:05.4	Volume down button released			
10:05.5	Volume changed to medium from high using button			
10:08.8	Audit log created	80	0 1.13.32	55.068
10:08.8	Camera connected to Axon Dock X630020W7	80	0	55.068
10:08.8	Audit log rolled	80	0	55.068
10:10.2	Device connected to charger	80	0	55.068
10:08.0	Audit log created	100	0 1.13.32	55.067
10:08.0	Audit log created	100	0 1.13.32	55.069
10:08.0	Audit log created	100	0 1.13.32	55.069
10:08.0	Audit log created	100	0 1.13.32	55.069
10:08.0	Audit log created	100	0 1.13.32	55.068
10:08.0	Audit log created	100	0 1.13.32	55.068
10:08.0	Audit log created	100	0 1.13.32	55.072
10:08.0	Audit log created	100	0 1.13.32	55.072
10:08.0	Audit log created	100	0 1.13.32	55.072
10:08.0	Audit log created	100	0 1.13.32	55.072
10:08.1	Audit log created	100	0 1.13.32	55.072
10:08.1	Audit log created	100	0 1.13.32	55.072
10:08.1	Audit log created	100	0 1.13.32	55.071
06:02.2	Device disconnected from charger	98	0	55.071
06:02.2	Camera disconnected from Axon Dock X630020W7	98	0	55.072
06:05.0	Power button pressed			
06:08.0	Device powered off using button	100	0	55.072
06:08.6	Power button released			
01:43.9	Audit log created		1.13.32	
01:44.0	Device powered on using button	100	0	55.071
01:45.9	Audio recording disabled due to video buffering default			
38:38.5	Event button pressed			
38:38.6	Event button released			
38:38.7	Event button pressed			
38:38.7	Audio recording enabled due to video recording default			
38:38.7	Event button released			
38:38.9	Recording started due to button press	95	1	55.07 17299e73820048eda2559ef605e463b2

40:37.5 Event button pressed			
40:40.5 Recording stopped due to button press	94	1	54.945 17299e73820048eda2559ef605e463b2
40:41.3 Audio recording disabled due to video buffering default			
40:41.5 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-07-04 0038 X6033271L' using Axon application			17299e73820048eda2559ef605e463b2
40:41.5 Event button released			
47:43.6 Select button pressed			
47:43.7 Event button pressed			
47:49.0 Event button released			
47:49.2 Select button released			
47:50.1 Event button pressed			
47:50.1 Select button pressed			
47:53.7 Event button released			
47:53.8 Select button released			
47:59.7 Event button pressed			
47:59.8 Select button pressed			
48:03.0 Select button released			
48:03.1 Event button released			
48:09.7 Event button pressed			
48:09.8 Event button released			
48:09.9 Event button pressed			
48:10.0 Audio recording enabled due to video recording default			
48:10.0 Event button released			
48:10.1 Recording started due to button press	94	2	54.944 ed796d4770ec45febe4ef637a5b4ab1f
48:11.4 Event button pressed			
48:14.4 Recording stopped due to button press	94	2	54.934 ed796d4770ec45febe4ef637a5b4ab1f
48:15.0 Event button released			
48:15.2 Audio recording disabled due to video buffering default			
48:48.2 Title changed in video metadata from '' to 'Axon Body 3 Video 2021-07-04 0048 X6033271L' using Axon application			ed796d4770ec45febe4ef637a5b4ab1f
49:27.5 Event button pressed			
49:27.6 Volume up button pressed			
49:32.1 Event button released			
49:32.1 Volume up button released			
49:36.7 Event button pressed			
49:36.8 Select button pressed			
49:46.5 Event button released			
49:49.0 Event button pressed			
49:49.5 Event button released			
49:50.7 Event button pressed			
49:51.7 Event button released			
49:53.1 Volume down button pressed			
49:53.6 Event button pressed			
49:54.6 Volume down button released			
49:54.6 Event button released			
49:54.9 Event button pressed			
49:54.9 Volume down button pressed			
49:58.6 Volume down button released			
49:58.6 Event button released			

50:00.0	Event button pressed			
50:00.0	Volume up button pressed			
50:01.7	Volume up button released			
50:01.7	Event button released			
50:04.0	Power button pressed			
50:07.0	Device powered off using button	93	2	54.881
50:07.5	Power button released			
50:15.7	Power button pressed			
50:18.4	Power button released			
50:48.1	Device powered on using button	93	2	54.881
50:50.0	Audio recording disabled due to video buffering default			
51:19.2	Event button pressed			
51:19.7	Select button pressed			
51:24.7	Select button released			
51:24.7	Event button released			
51:27.5	Event button pressed			
51:27.5	Select button pressed			
51:34.2	Event button released			
51:34.2	Select button released			
51:36.5	Programmable button pressed			
51:36.8	Programmable button released			
51:37.3	Event button pressed			
51:37.4	Programmable button pressed			
51:39.4	Programmable button released			
51:39.4	Event button released			
53:11.4	Event button pressed			
53:11.5	Programmable button pressed			
53:19.2	Programmable button released			
53:20.7	Event button pressed			
53:20.7	Programmable button pressed			
53:25.7	Programmable button released			
53:25.8	Event button released			
53:31.5	Event button pressed			
53:31.5	Programmable button pressed			
53:35.3	Programmable button released			
53:35.3	Event button released			
53:36.2	Event button pressed			
53:36.2	Volume down button pressed			
53:37.9	Volume down button released			
53:37.9	Event button released			
53:38.9	Event button pressed			
53:38.9	Select button pressed			
53:40.5	Select button released			
53:40.6	Event button released			
53:43.8	Event button pressed			
53:43.8	Select button pressed			
53:46.6	Select button released			

53:46.6	Event button released			
53:48.1	Event button pressed			
53:49.1	Event button released			
53:49.7	Programmable button pressed			
53:50.8	Programmable button released			
53:51.0	Event button released			
54:08.9	Axon application connected to device			
54:39.1	Categories 'Accidental Recording' added to video metadata using Axon applicator			ed796d4770ec45febe4ef637a5b4ab1f
55:42.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-04 0038 X6033271L' to 'Sig. 31/28 N2' using Axon applicator			17299e73820048eda2559ef605e463b2
55:42.7	Categories 'Sleeper' added to video metadata using Axon applicator			17299e73820048eda2559ef605e463b2
56:26.6	Axon application disconnected from device			
01:43.1	Audit log created	92	2 1.13.32	54.88
01:43.1	Audit log created	86	2 1.13.32	54.879
01:43.1	Audit log created	81	2 1.13.32	54.877
01:43.1	Audit log created	75	2 1.13.32	54.876
23:28.2	Power button pressed			
23:28.2	Power button released			
23:28.4	Camera connected to Axon Dock X62001V12	73	2	54.885
23:28.4	Audit log rolled	73	2	54.876
23:28.4	Audit log created	73	2 1.13.32	54.876
23:29.1	Device connected to charger	73	2	54.876
23:53.1	Video upload started when camera was docked			17299e73820048eda2559ef605e463b2
24:01.0	Date/Time synced to 07/04/2021 04:24:01.01 AM from 07/04/2021 04:23:58.39 AM			
24:13.5	Audit log successfully uploaded			
24:13.7	Audit log successfully uploaded and deleted from device	73	2	54.885
24:14.3	Audit log successfully uploaded			
24:14.5	Audit log successfully uploaded and deleted from device	73	2	54.885
24:14.8	Audit log successfully uploaded			
24:15.1	Audit log successfully uploaded and deleted from device	73	2	54.885
24:22.2	Audit log successfully uploaded			
24:22.4	Audit log successfully uploaded and deleted from device	73	2	54.885
24:23.7	Audit log successfully uploaded			
24:23.9	Audit log successfully uploaded and deleted from device	73	2	54.885
24:31.5	Video successfully uploaded from device when docked			17299e73820048eda2559ef605e463b2
24:31.7	Video deleted from device when docked	74	1	55.009 17299e73820048eda2559ef605e463b2
24:31.8	Audit log rolled	74	1	55.01
24:31.8	Audit log created	74	1 1.13.32	55.01
24:31.9	Video upload started when camera was docked			ed796d4770ec45febe4ef637a5b4ab1f
24:45.5	Audit log successfully uploaded			
24:45.7	Audit log successfully uploaded and deleted from device	74	1	55.009
24:47.1	Audit log successfully uploaded			
24:47.3	Audit log successfully uploaded and deleted from device	74	1	55.009
24:49.7	Video successfully uploaded from device when docked			ed796d4770ec45febe4ef637a5b4ab1f
24:50.0	Video deleted from device when docked	74	0	55.072 ed796d4770ec45febe4ef637a5b4ab1f
24:50.0	Audit log created	74	0 1.13.32	55.072
24:50.0	Audit log rolled	74	0	55.072
24:50.1	Audit log rolled	74	0	55.072

24:50.1 Audit log created	74	0 1.13.32	55.072
25:06.4 Audit log successfully uploaded			
25:06.6 Audit log successfully uploaded and deleted from device	74	0	55.072
25:07.8 Audit log successfully uploaded			
25:08.0 Audit log successfully uploaded and deleted from device	74	0	55.072
25:08.1 Audit log successfully uploaded			
25:08.3 Audit log successfully uploaded and deleted from device	74	0	55.072
25:15.7 Audit log successfully uploaded			
25:15.9 Audit log successfully uploaded and deleted from device	74	0	55.072
25:21.4 Audit log successfully uploaded			
25:21.6 Audit log successfully uploaded and deleted from device	74	0	55.072
25:29.1 Audit log successfully uploaded			
25:29.3 Audit log successfully uploaded and deleted from device	74	0	55.072
25:31.8 Audit log successfully uploaded			
25:32.0 Audit log successfully uploaded and deleted from device	74	0	55.072
25:33.1 Audit log successfully uploaded			
25:33.3 Audit log successfully uploaded and deleted from device	74	0	55.072
25:38.5 Audit log successfully uploaded			
25:38.7 Audit log successfully uploaded and deleted from device	74	0	55.072
25:51.8 Audit log successfully uploaded			
25:52.1 Audit log successfully uploaded and deleted from device	74	0	55.072
25:52.4 Audit log successfully uploaded			
25:52.6 Audit log successfully uploaded and deleted from device	74	0	55.072
25:55.8 Audit log successfully uploaded			
25:56.0 Audit log successfully uploaded and deleted from device	74	0	55.072
26:01.1 Audit log successfully uploaded			
26:01.3 Audit log successfully uploaded and deleted from device	74	0	55.072
26:20.2 Audit log successfully uploaded			
26:20.4 Audit log successfully uploaded and deleted from device	75	0	55.072
26:20.6 Audit log successfully uploaded			
26:20.9 Audit log successfully uploaded and deleted from device	75	0	55.072
26:37.5 Audit log successfully uploaded			
26:37.7 Audit log successfully uploaded and deleted from device	75	0	55.072
54:01.0 Date/Time synced to 07/04/2021 04:54:01.01 AM from 07/04/2021 04:54:01.03 AM			
24:01.0 Date/Time synced to 07/04/2021 05:24:01.01 AM from 07/04/2021 05:24:00.93 AM			
24:49.9 Audit log created	98	0 1.13.32	55.072
28:13.8 Audit log successfully uploaded			
28:14.0 Audit log successfully uploaded and deleted from device	98	0	55.073
28:22.6 Audit log successfully uploaded			
28:22.8 Audit log successfully uploaded and deleted from device	98	0	55.073
28:33.1 Audit log successfully uploaded			
28:33.3 Audit log successfully uploaded and deleted from device	98	0	55.073
28:37.0 Audit log successfully uploaded			
28:37.2 Audit log successfully uploaded and deleted from device	98	0	55.073
38:19.8 Firmware version 1.15.14 detected		1.13.32	
39:20.8 Firmware version 1.15.14 downloaded from Evidence.com	100	0 1.13.32	54.559
41:13.8 Firmware update to version 1.15.14 started	100	0 1.13.32	54.559

41:14.0 Device restarting due to firmware update	100	0	54.559
43:16.8 Device restarted due to firmware update	100	0	55.179
43:17.1 Firmware successfully updated to 1.15.14		1.15.14	
43:17.8 Camera connected to Axon Dock X62001V12	100	0	55.18
43:19.6 Audit log created	100	0 1.15.14	55.179
43:19.6 Audit log rolled	100	0	55.179
43:22.0 Device connected to charger	100	0	55.179
43:52.0 Date/Time synced to 07/04/2021 05:43:52.01 AM from 07/04/2021 05:43:49.33 AM			
43:56.4 Audit log successfully uploaded			
43:56.7 Audit log successfully uploaded and deleted from device	100	0	55.18
13:52.0 Date/Time synced to 07/04/2021 06:13:52.01 AM from 07/04/2021 06:13:52.03 AM			
43:21.2 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 06:43:52.01 AM from 07/04/2021 06:43:51.87 AM			
13:52.0 Date/Time synced to 07/04/2021 07:13:52.01 AM from 07/04/2021 07:13:51.89 AM			
28:47.5 Audit log successfully uploaded			
28:47.7 Audit log successfully uploaded and deleted from device	100	0	55.18
43:21.3 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 07:43:52.01 AM from 07/04/2021 07:43:51.90 AM			
13:52.0 Date/Time synced to 07/04/2021 08:13:52.01 AM from 07/04/2021 08:13:51.93 AM			
37:09.2 Audit log successfully uploaded			
37:09.4 Audit log successfully uploaded and deleted from device	100	0	55.18
43:21.3 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 08:43:52.01 AM from 07/04/2021 08:43:51.89 AM			
13:52.0 Date/Time synced to 07/04/2021 09:13:52.01 AM from 07/04/2021 09:13:51.87 AM			
33:30.4 Audit log successfully uploaded			
33:30.6 Audit log successfully uploaded and deleted from device	100	0	55.18
43:21.3 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 09:43:52.01 AM from 07/04/2021 09:43:51.92 AM			
13:52.0 Date/Time synced to 07/04/2021 10:13:52.01 AM from 07/04/2021 10:13:51.88 AM			
41:29.5 Audit log successfully uploaded			
41:29.7 Audit log successfully uploaded and deleted from device	100	0	55.18
43:21.3 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 10:43:52.01 AM from 07/04/2021 10:43:51.92 AM			
13:52.0 Date/Time synced to 07/04/2021 11:13:52.01 AM from 07/04/2021 11:13:51.88 AM			
42:04.8 Audit log successfully uploaded			
42:05.0 Audit log successfully uploaded and deleted from device	100	0	55.179
43:21.3 Audit log created	100	0 1.15.14	55.179
43:52.0 Date/Time synced to 07/04/2021 11:43:52.01 AM from 07/04/2021 11:43:51.92 AM			
13:52.0 Date/Time synced to 07/04/2021 12:13:52.01 PM from 07/04/2021 12:13:51.88 PM			
32:43.3 Audit log successfully uploaded			
32:43.5 Audit log successfully uploaded and deleted from device	100	0	55.18
43:21.3 Audit log created	100	0 1.15.14	55.18
43:52.0 Date/Time synced to 07/04/2021 12:43:52.01 PM from 07/04/2021 12:43:51.93 PM			
13:52.0 Date/Time synced to 07/04/2021 01:13:52.01 PM from 07/04/2021 01:13:51.93 PM			
40:23.1 Audit log successfully uploaded			
40:23.2 Audit log successfully uploaded and deleted from device	100	0	55.182
43:21.3 Audit log created	100	0 1.15.14	55.182

43:52.0 Date/Time synced to 07/04/2021 01:43:52.01 PM from 07/04/2021 01:43:51.89 PM			
13:52.0 Date/Time synced to 07/04/2021 02:13:52.01 PM from 07/04/2021 02:13:51.89 PM			
43:21.3 Audit log created	100	0 1.15.14	55.181
43:52.0 Date/Time synced to 07/04/2021 02:43:52.01 PM from 07/04/2021 02:43:51.91 PM			
50:38.2 Audit log successfully uploaded			
50:38.4 Audit log successfully uploaded and deleted from device	100	0	55.182
50:47.5 Audit log successfully uploaded			
50:47.7 Audit log successfully uploaded and deleted from device	100	0	55.182
13:52.0 Date/Time synced to 07/04/2021 03:13:52.01 PM from 07/04/2021 03:13:51.91 PM			
43:21.3 Audit log created	100	0 1.15.14	55.181
43:52.0 Date/Time synced to 07/04/2021 03:43:52.01 PM from 07/04/2021 03:43:51.92 PM			
13:52.0 Date/Time synced to 07/04/2021 04:13:52.01 PM from 07/04/2021 04:13:51.90 PM			
43:21.3 Audit log created	100	0 1.15.14	55.181
43:52.0 Date/Time synced to 07/04/2021 04:43:52.01 PM from 07/04/2021 04:43:51.91 PM			
44:39.7 Audit log successfully uploaded			
44:39.9 Audit log successfully uploaded and deleted from device	100	0	55.181
44:57.0 Audit log successfully uploaded			
44:57.2 Audit log successfully uploaded and deleted from device	100	0	55.181
13:52.0 Date/Time synced to 07/04/2021 05:13:52.01 PM from 07/04/2021 05:13:51.90 PM			
43:21.3 Audit log created	100	0 1.15.14	55.181
43:52.0 Date/Time synced to 07/04/2021 05:43:52.01 PM from 07/04/2021 05:43:51.91 PM			
44:13.2 Audit log successfully uploaded			
44:13.4 Audit log successfully uploaded and deleted from device	100	0	55.181
13:52.0 Date/Time synced to 07/04/2021 06:13:52.01 PM from 07/04/2021 06:13:51.91 PM			
43:21.3 Audit log created	100	0 1.15.14	55.182
43:52.0 Date/Time synced to 07/04/2021 06:43:52.01 PM from 07/04/2021 06:43:51.91 PM			
44:36.4 Audit log successfully uploaded			
44:36.6 Audit log successfully uploaded and deleted from device	100	0	55.182
13:52.0 Date/Time synced to 07/04/2021 07:13:52.01 PM from 07/04/2021 07:13:51.90 PM			
43:21.3 Audit log created	100	0 1.15.14	55.182
43:52.0 Date/Time synced to 07/04/2021 07:43:52.01 PM from 07/04/2021 07:43:51.90 PM			
13:52.0 Date/Time synced to 07/04/2021 08:13:52.01 PM from 07/04/2021 08:13:51.88 PM			
21:33.9 Select button pressed			
21:34.1 Select button released			
21:35.1 Device disconnected from charger	100	0	55.182
21:35.1 Camera disconnected from Axon Dock X62001V12	100	0	55.182
21:35.3 Audio recording disabled due to video buffering default			
43:21.3 Audit log created	97	0 1.15.14	55.184
23:48.4 Volume up button pressed			
23:49.2 Volume up button released			
23:49.4 Volume changed to high from medium using button			
23:55.4 Power button pressed			
23:58.4 Device powered off using button	92	0	55.183
23:59.1 Power button released			
38:06.1 Audit log created		1.15.14	
38:06.2 Device powered on using button	92	0	55.182
38:09.2 Audio recording disabled due to video buffering default			

38:06.1 Audit log created	87	0 1.15.14	55.181
38:06.1 Audit log created	81	0 1.15.14	55.18
14:09.1 Event button pressed			
14:09.2 Event button released			
14:09.3 Event button pressed			
14:09.4 Audio recording enabled due to video recording default			
14:09.4 Event button released			
14:09.5 Recording started due to button press	78	1	55.179 db37b08b4dbc44de97312dde1f306430
15:45.0 Event button pressed			
15:48.0 Recording stopped due to button press	77	1	55.066 db37b08b4dbc44de97312dde1f306430
15:48.5 Event button released			
15:48.7 Audio recording disabled due to video buffering default			
26:50.1 Event button pressed			
26:50.2 Event button released			
26:50.3 Event button pressed			
26:50.4 Audio recording enabled due to video recording default			
26:50.4 Event button released			
26:50.5 Recording started due to button press	76	2	55.065 759c5a96822b45a189d4f15466dac9f7
29:18.8 Event button pressed			
29:21.8 Recording stopped due to button press	75	2	54.925 759c5a96822b45a189d4f15466dac9f7
29:22.2 Event button released			
29:22.6 Audio recording disabled due to video buffering default			
38:06.1 Audit log created	75	2 1.15.14	54.924
38:45.8 Event button pressed			
38:45.9 Event button released			
38:46.1 Event button pressed			
38:46.1 Audio recording enabled due to video recording default			
38:46.2 Event button released			
38:46.2 Recording started due to button press	75	3	54.924 42b45f9730b240ea8c30697d47d1b4c3
39:56.6 Event button pressed			
39:59.6 Recording stopped due to button press	74	3	54.824 42b45f9730b240ea8c30697d47d1b4c3
40:00.1 Event button released			
40:00.3 Audio recording disabled due to video buffering default			
42:51.2 Event button pressed			
42:51.4 Event button released			
42:51.5 Event button pressed			
42:51.5 Audio recording enabled due to video recording default			
42:51.6 Event button released			
42:51.6 Recording started due to button press	74	4	54.824 9720959ee6dd4e9b89f26217e98e1320
44:23.6 Programmable button pressed			
44:23.7 Programmable button released			
44:24.4 Programmable button pressed			
44:24.6 Programmable button released			
44:28.5 Select button pressed			
44:28.9 Select button released			
44:29.3 Marker added to video due to button			
46:24.4 Select button pressed			

46:25.0 Select button released			
46:25.2 Marker added to video due to button			
50:50.7 Event button pressed			
50:53.7 Recording stopped due to button press	72	4	54.507 9720959ee6dd4e9b89f26217e98e1320
50:54.3 Event button released			
50:54.4 Audio recording disabled due to video buffering default			
00:15.6 Event button pressed			
00:15.7 Event button released			
00:15.8 Event button pressed			
00:15.9 Audio recording enabled due to video recording default			
00:15.9 Event button released			
00:16.0 Recording started due to button press	71	5	54.505 dd9b57b1131242639dba446e57122285
03:26.2 Event button pressed			
03:29.2 Recording stopped due to button press	71	5	54.343 dd9b57b1131242639dba446e57122285
03:29.7 Event button released			
03:29.9 Audio recording disabled due to video buffering default			
27:44.7 Volume up button pressed			
27:44.9 Volume up button released			
27:44.9 Volume up button pressed			
27:45.1 Volume up button released			
27:45.1 Volume changed to very high from high using button			
27:48.0 Volume down button pressed			
27:48.2 Volume down button released			
27:48.3 Volume changed to high from very high using button			
27:48.7 Volume down button pressed			
27:48.8 Volume down button released			
27:48.9 Volume changed to medium from high using button			
29:51.2 Axon application connected to device			
30:32.0 Categories 'Loitering' added to video metadata using Axon applicator			dd9b57b1131242639dba446e57122285
30:32.0 Title changed in video metadata from 'Axon Body 3 Video 2021-07-05 0300 X6033271L' to 'Sig. 70 N3' using Axon applicator			dd9b57b1131242639dba446e57122285
31:11.8 Categories 'Loitering' added to video metadata using Axon applicator			9720959ee6dd4e9b89f26217e98e1320
31:11.8 Title changed in video metadata from 'Axon Body 3 Video 2021-07-05 0242 X6033271L' to 'Sig. 31/70 N2' using Axon applicator			9720959ee6dd4e9b89f26217e98e1320
31:51.1 Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			42b45f9730b240ea8c30697d47d1b4c3
31:51.1 Title changed in video metadata from 'Axon Body 3 Video 2021-07-05 0238 X6033271L' to 'Sig. 31/70 N2' using Axon applicator			42b45f9730b240ea8c30697d47d1b4c3
32:20.8 Title changed in video metadata from 'Axon Body 3 Video 2021-07-05 0226 X6033271L' to 'Sig. 70 N4' using Axon applicator			759c5a96822b45a189d4f15466dac9f7
32:20.8 Categories 'Loitering' added to video metadata using Axon applicator			759c5a96822b45a189d4f15466dac9f7
32:38.7 Categories 'Loitering' added to video metadata using Axon applicator			db37b08b4dbc44de97312dde1f306430
32:50.6 Title changed in video metadata from 'Axon Body 3 Video 2021-07-05 0214 X6033271L' to 'Sig. 70 N5' using Axon applicator			db37b08b4dbc44de97312dde1f306430
33:12.4 Axon application disconnected from device			
33:25.0 Power button pressed			
33:25.2 Power button released			
33:25.6 Camera connected to Axon Dock X62001V12	68	5	54.346
33:25.7 Audit log rolled	67	5	54.34
33:25.7 Audit log created	67	5 1.15.14	54.341
33:26.2 Device connected to charger	67	5	54.341
33:40.3 Video upload started when camera was docked			db37b08b4dbc44de97312dde1f306430
33:52.1 Audit log successfully uploaded			

33:52.2	Audit log successfully uploaded and deleted from device	68	5	54.346	
33:52.4	Audit log successfully uploaded				
33:52.5	Audit log successfully uploaded and deleted from device	68	5	54.346	
33:57.0	Date/Time synced to 07/05/2021 03:33:57.02 AM from 07/05/2021 03:33:55.67 AM				
34:04.6	Audit log successfully uploaded				
34:04.8	Audit log successfully uploaded and deleted from device	68	5	54.346	
34:11.7	Video successfully uploaded from device when dockec				db37b08b4dbc44de97312dde1f306430
34:11.9	Video deleted from device when docked	68	4	54.459	db37b08b4dbc44de97312dde1f306430
34:12.0	Audit log rolled	68	4	54.459	
34:12.0	Audit log created	68	4 1.15.14	54.459	
34:12.2	Video upload started when camera was docked				759c5a96822b45a189d4f15466dac9f7
34:31.9	Audit log successfully uploaded				
34:32.1	Audit log successfully uploaded and deleted from device	68	4	54.459	
34:50.0	Video successfully uploaded from device when dockec				759c5a96822b45a189d4f15466dac9f7
34:50.2	Video deleted from device when docked	68	3	54.599	759c5a96822b45a189d4f15466dac9f7
34:50.2	Audit log rolled	68	3	54.599	
34:50.2	Audit log created	68	3 1.15.14	54.599	
34:50.4	Video upload started when camera was docked				42b45f9730b240ea8c30697d47d1b4c3
34:56.2	Audit log successfully uploaded				
34:56.4	Audit log successfully uploaded and deleted from device	68	3	54.599	
35:13.5	Audit log successfully uploaded				
35:13.6	Audit log successfully uploaded and deleted from device	68	3	54.599	
35:17.8	Audit log successfully uploaded				
35:18.0	Audit log successfully uploaded and deleted from device	68	3	54.599	
35:18.3	Video successfully uploaded from device when dockec				42b45f9730b240ea8c30697d47d1b4c3
35:18.6	Video deleted from device when docked	68	2	54.698	42b45f9730b240ea8c30697d47d1b4c3
35:18.6	Audit log rolled	68	2	54.699	
35:18.6	Audit log created	68	2 1.15.14	54.699	
35:18.8	Video upload started when camera was docked				9720959ee6dd4e9b89f26217e98e1320
36:45.8	Video successfully uploaded from device when dockec				9720959ee6dd4e9b89f26217e98e1320
36:46.1	Video deleted from device when docked	69	1	55.013	9720959ee6dd4e9b89f26217e98e1320
36:46.2	Audit log rolled	69	1	55.013	
36:46.2	Audit log created	69	1 1.15.14	55.013	
36:46.4	Video upload started when camera was docked				dd9b57b1131242639dba446e57122285
37:29.8	Video successfully uploaded from device when dockec				dd9b57b1131242639dba446e57122285
37:30.1	Video deleted from device when docked	69	0	55.175	dd9b57b1131242639dba446e57122285
37:30.1	Audit log rolled	69	0	55.175	
37:30.1	Audit log created	69	0 1.15.14	55.175	
37:30.1	Audit log rolled	69	0	55.175	
37:30.1	Audit log created	69	0 1.15.14	55.175	
56:44.1	Device disconnected from charger	78	0	55.175	
56:44.8	Camera disconnected from Axon Dock X62001V12	78	0	55.175	
37:30.0	Audit log created	74	0 1.15.14	55.177	
37:30.0	Audit log created	67	0 1.15.14	55.176	
21:30.3	Volume up button pressed				
21:30.5	Volume up button released				
21:30.6	Volume changed to high from medium using button				

21:35.5	Volume down button pressed			
21:35.7	Volume down button released			
21:35.8	Volume changed to medium from high using button			
21:38.8	Camera connected to Axon Dock X630020W7	63	0	55.175
21:38.8	Audit log created	63	0 1.15.14	55.175
21:38.8	Audit log rolled	63	0	55.175
21:40.1	Device connected to charger	63	0	55.175
21:38.0	Audit log created	90	0 1.15.14	55.174
21:38.0	Audit log created	100	0 1.15.14	55.174
21:38.0	Audit log created	100	0 1.15.14	55.173
21:38.0	Audit log created	100	0 1.15.14	55.173
21:38.0	Audit log created	100	0 1.15.14	55.173
21:38.0	Audit log created	100	0 1.15.14	55.173
21:38.0	Audit log created	100	0 1.15.14	55.172
21:38.0	Audit log created	100	0 1.15.14	55.172
21:38.0	Audit log created	100	0 1.15.14	55.172
21:38.1	Audit log created	100	0 1.15.14	55.172
21:38.1	Audit log created	100	0 1.15.14	55.172
21:38.1	Audit log created	100	0 1.15.14	55.171
21:38.1	Audit log created	100	0 1.15.14	55.171
21:38.1	Audit log created	100	0 1.15.14	55.171
21:38.1	Audit log created	100	0 1.15.14	55.17
21:38.1	Audit log created	100	0 1.15.14	55.17
40:41.1	Camera disconnected from Axon Dock X630020W7	98	0	55.17
40:41.1	Device disconnected from charger	98	0	55.171
21:38.1	Audit log created	95	0 1.15.14	55.17
21:38.1	Audit log created	89	0 1.15.14	55.169
21:38.1	Audit log created	84	0 1.15.14	55.168
22:35.6	Event button pressed			
22:35.7	Event button released			
22:35.8	Event button pressed			
22:35.8	Audio recording enabled due to video recording default			
22:35.9	Event button released			
22:36.0	Recording started due to button press	84	1	55.167 fd76edd9fa8b480b99027451aa5f9c5e
26:01.8	Event button pressed			
26:04.8	Recording stopped due to button press	83	1	54.998 fd76edd9fa8b480b99027451aa5f9c5e
26:05.3	Event button released			
26:05.7	Audio recording disabled due to video buffering default			
40:28.3	Event button pressed			
40:28.4	Event button released			
40:28.5	Event button pressed			
40:28.5	Audio recording enabled due to video recording default			
40:28.5	Event button released			
40:28.6	Recording started due to button press	81	2	54.996 275ff7f1a33a4cc2a1c30f1cb097b125
42:14.9	Event button pressed			
42:17.9	Recording stopped due to button press	81	2	54.878 275ff7f1a33a4cc2a1c30f1cb097b125
42:18.2	Event button released			

42:18.7	Audio recording disabled due to video buffering default			
59:41.0	Event button pressed			
59:41.2	Event button released			
59:41.2	Event button pressed			
59:41.2	Audio recording enabled due to video recording default			
59:41.3	Event button released			
59:41.4	Recording started due to button press	79	3	54.877 0db139f1d12a474f8ef16a311f83240b
03:46.7	Event button pressed			
03:49.8	Recording stopped due to button press	78	3	54.685 0db139f1d12a474f8ef16a311f83240b
03:50.2	Event button released			
03:50.7	Audio recording disabled due to video buffering default			
19:33.3	Event button pressed			
19:33.4	Event button released			
19:33.5	Event button pressed			
19:33.6	Audio recording enabled due to video recording default			
19:33.6	Event button released			
19:33.8	Recording started due to button press	77	4	54.683 f7fe58a3988b4f56a241f3af1236f7cc
21:38.1	Audit log created	77	4 1.15.14	54.557
26:34.0	Event button pressed			
26:37.0	Recording stopped due to button press	76	4	54.398 f7fe58a3988b4f56a241f3af1236f7cc
26:37.6	Event button released			
26:38.0	Audio recording disabled due to video buffering default			
44:59.5	Axon application connected to device			
46:00.8	Title changed in video metadata from 'Axon Body 3 Video 2021-07-06 0219 X6033271L' to 'Sig. 31/70 NE8' using Axon applicator			f7fe58a3988b4f56a241f3af1236f7cc
46:00.8	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			f7fe58a3988b4f56a241f3af1236f7cc
47:06.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-06 0159 X6033271L' to 'Sig. 31/70 NE9' using Axon applicator			0db139f1d12a474f8ef16a311f83240b
47:06.7	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			0db139f1d12a474f8ef16a311f83240b
47:25.9	Categories 'Sleeper' removed from video metadata using Axon applicator			f7fe58a3988b4f56a241f3af1236f7cc
47:34.9	Categories 'Sleeper' added to video metadata using Axon applicator			f7fe58a3988b4f56a241f3af1236f7cc
48:30.1	Title changed in video metadata from 'Sig. 31/70 NE9' to 'Sig. 70/31 NE9' using Axon application			0db139f1d12a474f8ef16a311f83240b
49:10.5	Title changed in video metadata from 'Axon Body 3 Video 2021-07-06 0140 X6033271L' to 'Clearing Train NE10' using Axon applicator			275ff7f1a33a4cc2a1c30f1cb097b125
49:10.5	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			275ff7f1a33a4cc2a1c30f1cb097b125
49:57.6	Title changed in video metadata from 'Axon Body 3 Video 2021-07-06 0122 X6033271L' to 'Clearing Train NE10' using Axon applicator			fd76edd9fa8b480b99027451aa5f9c5e
49:57.6	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			fd76edd9fa8b480b99027451aa5f9c5e
50:12.5	Axon application disconnected from device			
06:38.4	Camera connected to Axon Dock X62001W9H	72	4	54.405
06:38.7	Audit log rolled	72	4	54.395
06:38.7	Audit log created	72	4 1.15.14	54.395
06:39.1	Device connected to charger	72	4	54.395
07:04.1	Video upload started when camera was docked			fd76edd9fa8b480b99027451aa5f9c5e
07:08.0	Date/Time synced to 07/06/2021 03:07:08.01 AM from 07/06/2021 03:07:08.65 AM			
07:10.3	Audit log successfully uploaded			
07:10.5	Audit log successfully uploaded and deleted from device	72	4	54.405
07:28.7	Audit log successfully uploaded			
07:35.9	Audit log successfully uploaded			
07:36.1	Audit log successfully uploaded and deleted from device	73	4	54.405
07:40.2	Audit log successfully uploaded			

07:40.4	Audit log successfully uploaded and deleted from device	73	4	54.405
07:46.5	Audit log successfully uploaded			
07:46.7	Audit log successfully uploaded and deleted from device	73	4	54.405
07:49.9	Video successfully uploaded from device when dockec			fd76edd9fa8b480b99027451aa5f9c5e
07:50.2	Video deleted from device when docked	73	3	54.575 fd76edd9fa8b480b99027451aa5f9c5e
07:50.2	Audit log created	73	3 1.15.14	54.576
07:50.2	Audit log rolled	73	3	54.576
07:50.4	Video upload started when camera was docked			275ff7f1a33a4cc2a1c30f1cb097b125
07:50.8	Audit log successfully uploaded			
07:51.0	Audit log successfully uploaded and deleted from device	73	3	54.576
08:05.1	Audit log successfully uploaded			
08:05.3	Audit log successfully uploaded and deleted from device	73	3	54.576
08:06.4	Audit log successfully uploaded			
08:06.5	Audit log successfully uploaded and deleted from device	73	3	54.576
08:23.6	Video successfully uploaded from device when dockec			275ff7f1a33a4cc2a1c30f1cb097b125
08:23.9	Video deleted from device when docked	73	2	54.694 275ff7f1a33a4cc2a1c30f1cb097b125
08:24.0	Audit log created	73	2 1.15.14	54.697
08:24.0	Audit log rolled	73	2	54.697
08:24.3	Video upload started when camera was docked			Odb139f1d12a474f8ef16a311f83240b
08:26.7	Audit log successfully uploaded			
08:26.9	Audit log successfully uploaded and deleted from device	73	2	54.697
08:39.0	Audit log successfully uploaded			
08:39.1	Audit log successfully uploaded and deleted from device	73	2	54.696
09:01.3	Audit log successfully uploaded			
09:01.5	Audit log successfully uploaded and deleted from device	73	2	54.696
09:14.6	Video successfully uploaded from device when dockec			Odb139f1d12a474f8ef16a311f83240b
09:14.9	Video deleted from device when docked	73	1	54.888 Odb139f1d12a474f8ef16a311f83240b
09:14.9	Audit log rolled	73	1	54.888
09:14.9	Audit log created	73	1 1.15.14	54.888
09:15.1	Video upload started when camera was docked			f7fe58a3988b4f56a241f3af1236f7cc
09:25.6	Audit log successfully uploaded			
09:25.7	Audit log successfully uploaded and deleted from device	73	1	54.888
09:44.9	Audit log successfully uploaded			
09:45.1	Audit log successfully uploaded and deleted from device	73	1	54.888
10:14.2	Audit log successfully uploaded			
10:14.4	Audit log successfully uploaded and deleted from device	74	1	54.888
10:30.6	Video successfully uploaded from device when dockec			f7fe58a3988b4f56a241f3af1236f7cc
10:30.9	Video deleted from device when docked	74	0	55.172 f7fe58a3988b4f56a241f3af1236f7cc
10:31.0	Audit log rolled	74	0	55.172
10:31.0	Audit log created	74	0 1.15.14	55.172
10:31.0	Audit log rolled	74	0	55.172
10:31.0	Audit log created	74	0 1.15.14	55.172
10:38.5	Audit log successfully uploaded			
10:39.4	Device disconnected from charger	74	0	55.175
10:39.4	Camera disconnected from Axon Dock X62001W9H	74	0	55.175
10:31.0	Audit log created	67	0 1.15.14	55.174
20:44.6	Volume up button pressed			

20:45.1	Volume up button released			
20:45.3	Volume changed to high from medium using button			
20:45.6	Volume up button pressed			
20:45.6	Volume up button released			
20:45.7	Volume changed to very high from high using button			
20:55.4	Volume up button pressed			
20:55.5	Volume up button released			
20:59.2	Volume down button pressed			
20:59.4	Volume down button released			
20:59.5	Volume changed to high from very high using button			
20:59.9	Volume down button pressed			
21:00.1	Volume down button released			
21:00.2	Volume changed to medium from high using button			
10:31.0	Audit log created	61	0 1.15.14	55.173
10:31.0	Audit log created	54	0 1.15.14	55.171
22:34.1	Volume up button pressed			
22:34.3	Volume up button released			
22:34.4	Volume changed to high from medium using button			
22:37.3	Volume down button pressed			
22:37.5	Volume down button released			
22:37.6	Volume changed to medium from high using button			
22:37.6	Volume down button pressed			
22:37.8	Volume down button released			
22:38.0	Volume changed to low from medium using button			
22:39.2	Select button pressed			
22:39.4	Select button released			
22:41.1	Volume up button pressed			
22:41.3	Volume up button released			
22:41.4	Volume changed to medium from low using button			
22:44.9	Camera connected to Axon Dock X630020W7	53	0	55.171
22:44.9	Audit log rolled	53	0	55.171
22:44.9	Audit log created	53	0 1.15.14	55.171
22:46.4	Device connected to charger	53	0	55.171
22:44.0	Audit log created	81	0 1.15.14	55.17
22:44.0	Audit log created	100	0 1.15.14	55.17
22:44.0	Audit log created	100	0 1.15.14	55.169
22:44.0	Audit log created	100	0 1.15.14	55.169
22:44.0	Audit log created	100	0 1.15.14	55.169
22:44.0	Audit log created	100	0 1.15.14	55.168
22:44.1	Audit log created	100	0 1.15.14	55.168
22:44.1	Audit log created	100	0 1.15.14	55.168
22:44.1	Audit log created	100	0 1.15.14	55.168
47:11.4	Device disconnected from charger	100	0	55.167
47:11.4	Volume down button pressed			
47:11.5	Volume down button released			
47:11.9	Camera disconnected from Axon Dock X630020W7	100	0	55.167
47:17.1	Power button pressed			

47:20.2 Device powered off using button	100	0	55.169
47:20.5 Power button released			
41:16.9 Audit log created		1.15.14	
41:17.0 Device connected to charger			
41:17.0 Device powered on due to charger connection	100	0	55.168
41:18.0 Camera connected to Axon Dock X62001V12	100	0	55.173
41:19.9 Audit log created	100	0 1.15.14	55.168
41:19.9 Audit log rolled	100	0	55.168
41:51.0 Date/Time synced to 07/07/2021 08:41:51.03 PM from 07/07/2021 08:41:49.42 PM			
41:54.3 Audit log successfully uploaded			
41:54.6 Audit log successfully uploaded and deleted from device	100	0	55.173
42:18.9 Audit log successfully uploaded			
42:19.1 Audit log successfully uploaded and deleted from device	100	0	55.173
42:34.4 Audit log successfully uploaded			
42:34.6 Audit log successfully uploaded and deleted from device	100	0	55.173
42:57.8 Audit log successfully uploaded			
42:58.0 Audit log successfully uploaded and deleted from device	100	0	55.173
43:13.2 Audit log successfully uploaded			
43:13.4 Audit log successfully uploaded and deleted from device	100	0	55.173
43:15.6 Audit log successfully uploaded			
43:15.9 Audit log successfully uploaded and deleted from device	100	0	55.173
43:29.1 Audit log successfully uploaded			
43:29.4 Audit log successfully uploaded and deleted from device	100	0	55.173
43:54.5 Audit log successfully uploaded			
43:54.6 Audit log successfully uploaded and deleted from device	100	0	55.173
44:08.8 Audit log successfully uploaded			
44:09.1 Audit log successfully uploaded and deleted from device	100	0	55.173
44:38.2 Audit log successfully uploaded			
44:38.4 Audit log successfully uploaded and deleted from device	100	0	55.173
44:47.6 Audit log successfully uploaded			
44:47.8 Audit log successfully uploaded and deleted from device	100	0	55.173
45:04.9 Audit log successfully uploaded			
45:05.1 Audit log successfully uploaded and deleted from device	100	0	55.173
45:34.3 Audit log successfully uploaded			
45:34.5 Audit log successfully uploaded and deleted from device	100	0	55.173
46:03.9 Audit log successfully uploaded			
46:04.1 Audit log successfully uploaded and deleted from device	100	0	55.173
46:30.3 Audit log successfully uploaded			
46:30.5 Audit log successfully uploaded and deleted from device	100	0	55.173
46:38.6 Audit log successfully uploaded			
46:38.8 Audit log successfully uploaded and deleted from device	100	0	55.173
46:54.0 Audit log successfully uploaded			
46:54.1 Audit log successfully uploaded and deleted from device	100	0	55.173
47:15.3 Audit log successfully uploaded			
47:15.5 Audit log successfully uploaded and deleted from device	100	0	55.173
47:38.7 Audit log successfully uploaded			
47:38.9 Audit log successfully uploaded and deleted from device	100	0	55.173

48:06.0	Audit log successfully uploaded			
48:06.2	Audit log successfully uploaded and deleted from device	100	0	55.173
48:11.3	Audit log successfully uploaded			
48:11.5	Audit log successfully uploaded and deleted from device	100	0	55.173
48:11.6	Audit log successfully uploaded			
48:11.8	Audit log successfully uploaded and deleted from device	100	0	55.173
48:26.9	Audit log successfully uploaded			
48:27.1	Audit log successfully uploaded and deleted from device	100	0	55.173
48:30.4	Audit log successfully uploaded			
48:30.6	Audit log successfully uploaded and deleted from device	100	0	55.173
48:39.7	Audit log successfully uploaded			
48:39.9	Audit log successfully uploaded and deleted from device	100	0	55.173
48:59.1	Audit log successfully uploaded			
48:59.3	Audit log successfully uploaded and deleted from device	100	0	55.173
49:15.4	Audit log successfully uploaded			
49:15.6	Audit log successfully uploaded and deleted from device	100	0	55.173
49:19.7	Audit log successfully uploaded			
49:19.9	Audit log successfully uploaded and deleted from device	100	0	55.173
49:35.1	Audit log successfully uploaded			
49:35.3	Audit log successfully uploaded and deleted from device	100	0	55.173
50:03.4	Audit log successfully uploaded			
50:03.6	Audit log successfully uploaded and deleted from device	100	0	55.173
50:26.8	Audit log successfully uploaded			
50:27.0	Audit log successfully uploaded and deleted from device	100	0	55.173
50:46.1	Audit log successfully uploaded			
50:46.3	Audit log successfully uploaded and deleted from device	100	0	55.173
51:02.5	Audit log successfully uploaded			
51:02.7	Audit log successfully uploaded and deleted from device	100	0	55.173
51:13.8	Audit log successfully uploaded			
51:14.0	Audit log successfully uploaded and deleted from device	100	0	55.173
51:30.2	Audit log successfully uploaded			
51:30.3	Audit log successfully uploaded and deleted from device	100	0	55.173
51:41.5	Audit log successfully uploaded			
51:41.6	Audit log successfully uploaded and deleted from device	100	0	55.173
52:00.8	Audit log successfully uploaded			
52:01.0	Audit log successfully uploaded and deleted from device	100	0	55.173
54:57.2	Device disconnected from charger	100	0	55.173
54:57.4	Camera disconnected from Axon Dock X62001V12	100	0	55.173
54:57.6	Audio recording disabled due to video buffering default			
02:43.0	Power button pressed			
02:46.0	Device powered off using button	99	0	55.172
02:46.5	Power button released			
30:48.0	Audit log created		1.15.14	
30:48.1	Device powered on using button	99	0	55.172
30:50.0	Audio recording disabled due to video buffering default			
30:48.0	Audit log created	92	0 1.15.14	55.17
15:14.4	Camera connected to Axon Dock X62001V12	88	0	55.174

15:14.4	Audit log created	87	0	1.15.14	55.171
15:14.4	Audit log rolled	87	0		55.171
15:15.1	Device connected to charger	87	0		55.172
15:46.0	Date/Time synced to 07/08/2021 08:15:46.01 PM from 07/08/2021 08:15:44.42 PM				
15:50.7	Audit log successfully uploaded				
15:50.8	Audit log successfully uploaded and deleted from device	88	0		55.174
15:58.5	Audit log successfully uploaded				
15:58.7	Audit log successfully uploaded and deleted from device	88	0		55.174
16:03.9	Audit log successfully uploaded				
16:04.1	Audit log successfully uploaded and deleted from device	88	0		55.174
30:19.4	Device disconnected from charger	94	0		55.175
30:19.4	Camera disconnected from Axon Dock X62001V12	94	0		55.176
30:31.2	Event button pressed				
30:31.3	Event button released				
30:31.3	Event button pressed				
30:31.4	Event button released				
30:31.4	Audio recording enabled due to video recording default				
30:31.6	Recording started due to button press	94	1		55.175 0cd17357cdf4d5490ba7e5cac4bcc09
45:25.6	Event button pressed				
45:28.6	Recording stopped due to button press	91	1		54.699 0cd17357cdf4d5490ba7e5cac4bcc09
45:29.2	Event button released				
45:29.3	Audio recording disabled due to video buffering default				
52:45.1	Volume up button pressed				
52:45.2	Volume up button released				
52:45.3	Volume changed to high from medium using button				
53:41.5	Axon application connected to device				
53:43.7	Axon application disconnected from device				
53:48.4	Axon application connected to device				
55:01.8	Categories 'Special Detail' added to video metadata using Axon applicator				0cd17357cdf4d5490ba7e5cac4bcc09
55:01.8	Title changed in video metadata from 'Axon Body 3 Video 2021-07-08 2030 X6033271L' to 'Assisting 7401 On Code 23 N6' using Axon applicatio				0cd17357cdf4d5490ba7e5cac4bcc09
55:09.6	Volume up button pressed				
55:09.8	Volume up button released				
55:09.9	Volume changed to very high from high using button				
55:10.7	Volume up button pressed				
55:10.8	Volume up button released				
55:14.4	Camera connected to Axon Dock X62001V12	90	1		54.697
55:14.4	Axon application disconnected from device				
55:14.4	Audit log rolled	90	1		54.696
55:14.4	Audit log created	90	1	1.15.14	54.696
55:14.5	Device connected to charger	90	1		54.696
55:28.0	Video upload started when camera was docked				0cd17357cdf4d5490ba7e5cac4bcc09
55:34.9	Audit log successfully uploaded				
55:35.1	Audit log successfully uploaded and deleted from device	90	1		54.697
55:45.0	Date/Time synced to 07/08/2021 08:55:45.01 PM from 07/08/2021 08:55:44.39 PM				
57:43.1	Video successfully uploaded from device when docked				0cd17357cdf4d5490ba7e5cac4bcc09
57:43.4	Video deleted from device when docked	91	0		55.174 0cd17357cdf4d5490ba7e5cac4bcc09
57:43.5	Audit log created	91	0	1.15.14	55.174

57:43.5	Audit log rolled	91	0	55.174
57:43.5	Audit log rolled	91	0	55.174
57:43.5	Audit log created	91	0 1.15.14	55.174
08:16.0	Device disconnected from charger	95	0	55.174
08:16.0	Camera disconnected from Axon Dock X62001V12	95	0	55.174
11:26.5	Power button pressed			
11:29.5	Device powered off using button	95	0	55.175
11:29.6	Power button released			
58:51.0	Audit log created		1.15.14	
58:51.1	Device powered on due to charger connection	93	0	55.175
58:51.4	Device connected to charger			
58:51.4	Camera connected to Axon Dock X630020W7	93	0	55.175
58:51.4	Audit log rolled			
58:51.4	Audit log created		1.15.14	
58:52.1	Camera connected to Axon Dock X630020W7	94	0	55.175
58:54.0	Audit log rolled	93	0	55.175
58:54.0	Audit log created	93	0 1.15.14	55.175
58:54.0	Audit log created	100	0 1.15.14	55.174
58:54.0	Audit log created	100	0 1.15.14	55.174
58:54.0	Audit log created	100	0 1.15.14	55.174
58:54.0	Audit log created	100	0 1.15.14	55.174
58:54.0	Audit log created	100	0 1.15.14	55.173
58:54.0	Audit log created	100	0 1.15.14	55.173
58:54.0	Audit log created	100	0 1.15.14	55.173
58:54.0	Audit log created	100	0 1.15.14	55.173
58:54.0	Audit log created	100	0 1.15.14	55.172
58:54.0	Audit log created	100	0 1.15.14	55.172
58:54.0	Audit log created	100	0 1.15.14	55.172
25:48.1	Device disconnected from charger	98	0	55.172
25:48.4	Camera disconnected from Axon Dock X630020W7	98	0	55.172
25:48.5	Audio recording disabled due to video buffering default			
25:48.8	Power button pressed			
25:51.9	Device powered off using button	100	0	55.172
25:52.3	Power button released			
01:38.9	Audit log created		1.15.14	
01:39.1	Device powered on using button	100	0	55.171
01:40.9	Audio recording disabled due to video buffering default			
35:48.8	Audio recording enabled due to video recording default			
35:49.0	Recording started due to Axon Signal Sidearm activation	95	1	55.17 329b049cafc1413b9b228c3ceb0726b6
36:01.8	Event button pressed			
36:04.8	Recording stopped due to button press	95	1	55.133 329b049cafc1413b9b228c3ceb0726b6
36:05.8	Audio recording disabled due to video buffering default			
36:06.6	Event button released			
36:16.5	Volume down button pressed			
36:16.7	Volume down button released			
36:16.8	Volume changed to high from very high using button			
36:17.1	Audio recording enabled due to video recording default			

36:17.2	Volume down button pressed			
36:17.3	Recording started due to Axon Signal Sidearm activation	95	2	55.111 2cff30cc273e4a2dae5ca2b65f04a78c
36:17.4	Volume down button released			
36:17.6	Volume changed to medium from high using button			
36:24.3	Select button pressed			
36:26.3	Select button released			
36:26.3	Signal alert dismissal sent to Axon Evidence			
36:29.3	Recording stopped due to signal alert dismissal	95	2	55.089 2cff30cc273e4a2dae5ca2b65f04a78c
36:30.1	Audio recording disabled due to video buffering default			
45:29.3	Camera connected to Axon Dock X62001V12	94	2	55.093
45:29.4	Audit log rolled	94	2	55.088
45:29.4	Audit log created	94	2 1.15.14	55.088
45:30.1	Device connected to charger	94	2	55.089
45:46.3	Video upload started when camera was docked			329b049cafc1413b9b228c3ceb0726b6
45:50.8	Audit log successfully uploaded			
45:51.1	Audit log successfully uploaded and deleted from device	94	2	55.093
45:56.2	Audit log successfully uploaded			
45:56.4	Audit log successfully uploaded and deleted from device	94	2	55.093
45:59.5	Audit log successfully uploaded			
46:00.0	Date/Time synced to 07/09/2021 08:46:00.01 PM from 07/09/2021 08:45:59.35 PM			
46:00.1	Audit log successfully uploaded and deleted from device	94	2	55.093
46:06.0	Video successfully uploaded from device when docked			329b049cafc1413b9b228c3ceb0726b6
46:06.2	Video deleted from device when docked	94	1	55.161 329b049cafc1413b9b228c3ceb0726b6
46:06.2	Audit log rolled	94	1	55.162
46:06.2	Audit log created	94	1 1.15.14	55.162
46:06.4	Video upload started when camera was docked			2cff30cc273e4a2dae5ca2b65f04a78c
46:11.3	Video successfully uploaded from device when docked			2cff30cc273e4a2dae5ca2b65f04a78c
46:11.5	Video deleted from device when docked	94	0	55.174 2cff30cc273e4a2dae5ca2b65f04a78c
46:11.6	Audit log created	94	0 1.15.14	55.18
46:11.6	Audit log rolled	94	0	55.18
46:11.6	Audit log created	94	0 1.15.14	55.18
46:11.6	Audit log rolled	94	0	55.18
46:21.0	Audit log successfully uploaded			
46:21.1	Audit log successfully uploaded and deleted from device	94	0	55.18
46:33.3	Audit log successfully uploaded			
46:33.5	Audit log successfully uploaded and deleted from device	94	0	55.18
46:36.7	Audit log successfully uploaded			
46:36.9	Audit log successfully uploaded and deleted from device	94	0	55.18
46:59.1	Audit log successfully uploaded			
46:59.3	Audit log successfully uploaded and deleted from device	94	0	55.18
47:07.3	Audit log successfully uploaded			
47:07.5	Audit log successfully uploaded and deleted from device	95	0	55.18
47:33.7	Audit log successfully uploaded			
47:33.9	Audit log successfully uploaded and deleted from device	95	0	55.18
47:48.0	Audit log successfully uploaded			
47:48.2	Audit log successfully uploaded and deleted from device	95	0	55.18
48:03.6	Audit log successfully uploaded			

48:03.8	Audit log successfully uploaded and deleted from device	95	0	55.18
48:20.9	Audit log successfully uploaded			
48:21.1	Audit log successfully uploaded and deleted from device	95	0	55.18
48:40.2	Audit log successfully uploaded			
48:40.4	Audit log successfully uploaded and deleted from device	95	0	55.18
48:57.6	Audit log successfully uploaded			
48:57.9	Audit log successfully uploaded and deleted from device	95	0	55.18
49:25.1	Audit log successfully uploaded			
49:25.3	Audit log successfully uploaded and deleted from device	95	0	55.18
49:51.4	Audit log successfully uploaded			
49:51.6	Audit log successfully uploaded and deleted from device	95	0	55.18
50:06.4	Audit log successfully uploaded			
50:06.6	Audit log successfully uploaded and deleted from device	96	0	55.18
50:07.8	Audit log successfully uploaded			
50:08.0	Audit log successfully uploaded and deleted from device	96	0	55.18
50:17.1	Audit log successfully uploaded			
50:17.3	Audit log successfully uploaded and deleted from device	96	0	55.18
50:42.5	Audit log successfully uploaded			
50:42.6	Audit log successfully uploaded and deleted from device	96	0	55.18
50:48.8	Audit log successfully uploaded			
50:49.0	Audit log successfully uploaded and deleted from device	96	0	55.18
16:00.0	Date/Time synced to 07/09/2021 09:16:00.01 PM from 07/09/2021 09:16:00.03 PM			
46:00.0	Date/Time synced to 07/09/2021 09:46:00.01 PM from 07/09/2021 09:45:59.91 PM			
46:10.9	Audit log created	100	0 1.15.14	55.179
50:08.9	Audit log successfully uploaded			
50:09.1	Audit log successfully uploaded and deleted from device	100	0	55.18
08:54.3	Device disconnected from charger	100	0	55.18
08:54.3	Camera disconnected from Axon Dock X62001V12	100	0	55.18
09:17.6	Power button pressed			
09:20.6	Device powered off using button	100	0	55.18
09:21.0	Power button released			
01:43.0	Audit log created		1.15.14	
01:43.1	Device powered on using button	100	0	55.179
01:44.9	Audio recording disabled due to video buffering default			
37:00.9	Event button pressed			
37:01.0	Event button released			
37:01.2	Event button pressed			
37:01.2	Audio recording enabled due to video recording default			
37:01.3	Event button released			
37:01.4	Recording started due to button press	95	0	55.178 6d697edddcd142eb9e9277659650809e
50:36.6	Event button pressed			
50:39.6	Recording stopped due to button press	92	1	54.684 6d697edddcd142eb9e9277659650809e
50:40.3	Audio recording disabled due to video buffering default			
50:40.7	Event button released			
01:43.0	Audit log created	92	1 1.15.14	54.682
01:43.0	Audit log created	86	1 1.15.14	54.681
49:50.4	Event button pressed			

49:50.6	Event button released			
49:50.7	Event button pressed			
49:50.7	Audio recording enabled due to video recording default			
49:50.8	Event button released			
49:50.9	Recording started due to button press	81	2	54.679 ffabb5c8977741ae8b8257b54f8d77ef
59:11.2	Select button pressed			
59:11.6	Select button released			
59:11.9	Marker added to video due to button			
01:43.0	Audit log created	79	2 1.15.14	54.241
11:15.2	Event button pressed			
11:18.3	Recording stopped due to button press	77	2	53.936 ffabb5c8977741ae8b8257b54f8d77ef
11:18.7	Event button released			
11:19.2	Audio recording disabled due to video buffering default			
19:25.0	Event button pressed			
19:25.1	Event button released			
19:25.2	Event button pressed			
19:25.3	Audio recording enabled due to video recording default			
19:25.3	Event button released			
19:25.4	Recording started due to button press	77	2	53.933 c6acdbf4359f4bb19ce67bdec257a94e
20:36.2	Event button pressed			
20:39.2	Recording stopped due to button press	76	3	53.833 c6acdbf4359f4bb19ce67bdec257a94e
20:39.6	Event button released			
20:40.0	Audio recording disabled due to video buffering default			
25:01.6	Volume up button pressed			
25:02.1	Volume up button released			
25:02.4	Volume changed to high from medium using button			
01:43.0	Audit log created	73	3 1.15.14	53.832
01:43.0	Audit log created	66	3 1.15.14	53.831
37:19.0	Volume up button pressed			
37:19.2	Volume up button released			
37:19.3	Volume changed to very high from high using button			
01:43.1	Audit log created	61	3 1.15.14	53.829
55:21.1	Axon application connected to device			
56:12.4	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			6d697edddcd142eb9e9277659650809e
56:12.4	Title changed in video metadata from 'Axon Body 3 Video 2021-07-09 2337 X6033271L' to 'Sig. 31/70 N2' using Axon applicator			6d697edddcd142eb9e9277659650809e
57:27.9	Categories 'Ambulance Call', 'Person Armed' added to video metadata using Axon applicator			6d697edddcd142eb9e9277659650809e
57:27.9	Title changed in video metadata from 'Sig. 31/70 N2' to 'Sig. 69G N2 Code 24' using Axon applicator			6d697edddcd142eb9e9277659650809e
58:08.6	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			ffabb5c8977741ae8b8257b54f8d77ef
58:08.6	Title changed in video metadata from 'Axon Body 3 Video 2021-07-10 0149 X6033271L' to 'Sig. 31/70 N2' using Axon applicator			ffabb5c8977741ae8b8257b54f8d77ef
58:29.3	Categories 'Loitering' added to video metadata using Axon applicator			c6acdbf4359f4bb19ce67bdec257a94e
58:29.3	Title changed in video metadata from 'Axon Body 3 Video 2021-07-10 0219 X6033271L' to 'Sig. 70 N3' using Axon applicator			c6acdbf4359f4bb19ce67bdec257a94e
58:40.5	Axon application disconnected from device			
01:43.1	Audit log created	54	3 1.15.14	53.827
39:20.3	Volume up button pressed			
39:20.4	Volume up button released			
39:23.3	Volume down button pressed			
39:23.5	Volume down button released			

39:23.6	Volume changed to high from very high using button			
39:24.1	Volume down button pressed			
39:24.3	Volume down button released			
39:24.4	Volume changed to medium from high using button			
39:27.6	Camera connected to Axon Dock X630020W7	50	3	53.826
39:27.7	Audit log rolled	49	3	53.826
39:27.7	Audit log created	49	3 1.15.14	53.826
39:28.1	Device connected to charger	49	3	53.826
39:27.0	Audit log created	78	3 1.15.14	53.826
39:27.0	Audit log created	99	3 1.15.14	53.826
39:27.0	Audit log created	100	3 1.15.14	53.826
39:27.0	Audit log created	100	3 1.15.14	53.825
39:27.0	Audit log created	100	3 1.15.14	53.825
39:27.0	Audit log created	100	3 1.15.14	53.825
39:27.0	Audit log created	100	3 1.15.14	53.825
39:27.0	Audit log created	100	3 1.15.14	53.825
39:27.1	Audit log created	100	3 1.15.14	53.824
39:27.1	Audit log created	100	3 1.15.14	53.824
39:27.1	Audit log created	100	3 1.15.14	53.824
39:27.1	Audit log created	100	3 1.15.14	53.823
39:27.1	Audit log created	100	3 1.15.14	53.823
39:27.1	Audit log created	100	3 1.15.14	53.823
21:13.1	Device disconnected from charger	100	3	53.823
21:13.1	Camera disconnected from Axon Dock X630020W7	100	3	53.823
21:19.0	Power button pressed			
21:19.6	Power button released			
21:21.2	Power button pressed			
21:24.3	Device powered off using button	100	3	53.828
21:24.6	Power button released			
49:36.0	Audit log created		1.15.14	
49:36.1	Device powered on using button	100	3	53.827
49:37.9	Audio recording disabled due to video buffering default			
49:36.0	Audit log created	92	3 1.15.14	53.825
22:15.2	Event button pressed			
22:15.3	Event button released			
22:15.4	Event button pressed			
22:15.4	Audio recording enabled due to video recording default			
22:15.5	Event button released			
22:15.6	Recording started due to button press	89	4	53.824 e0fdafd2ae7b43c9af9f4d7c8bbdaba2
23:40.8	Event button pressed			
23:43.8	Recording stopped due to button press	89	4	53.719 e0fdafd2ae7b43c9af9f4d7c8bbdaba2
23:44.3	Event button released			
23:44.7	Audio recording disabled due to video buffering default			
32:52.3	Event button pressed			
32:52.5	Event button released			
32:52.6	Event button pressed			

32:52.6	Audio recording enabled due to video recording default				
32:52.6	Event button released				
32:52.7	Recording started due to button press	88	5	53.717	6d6910d86d064b68ba9164ed682b51af
33:42.5	Event button pressed				
33:44.7	Event button released				
34:04.9	Event button pressed				
34:07.9	Recording stopped due to button press	88	5	53.618	6d6910d86d064b68ba9164ed682b51af
34:08.5	Event button released				
34:08.7	Audio recording disabled due to video buffering default				
49:36.0	Audit log created	86	5	1.15.14	53.617
00:27.1	Axon application connected to device				
02:59.0	Categories 'Special Detail' added to video metadata using Axon applicator				e0fdafd2ae7b43c9af9f4d7c8bbdaba2
02:59.0	Title changed in video metadata from 'Axon Body 3 Video 2021-07-11 0022 X6033271L' to 'Upset Patron NE10 Code 9 By 3610' using Axon applicator				e0fdafd2ae7b43c9af9f4d7c8bbdaba2
03:34.6	Categories 'Stranded Person' added to video metadata using Axon applicator				6d6910d86d064b68ba9164ed682b51af
03:55.0	Title changed in video metadata from 'Axon Body 3 Video 2021-07-11 0032 X6033271L' to 'Sig.84 NE9' using Axon applicator				6d6910d86d064b68ba9164ed682b51af
05:00.5	Title changed in video metadata from 'Sig.84 NE9' to 'Sig.84 NE9 3601 Contacted' using Axon applicator				6d6910d86d064b68ba9164ed682b51af
11:50.6	Axon application disconnected from device				
37:04.1	Volume up button pressed				
37:04.4	Volume up button released				
37:04.5	Volume changed to high from medium using button				
43:11.8	Event button pressed				
43:12.0	Event button released				
43:12.1	Event button pressed				
43:12.1	Audio recording enabled due to video recording default				
43:12.2	Recording started due to button press	81	6	53.615	e14dce27580747aeb5ee35a3836614b9
43:12.2	Event button released				
47:14.6	Event button pressed				
47:17.6	Recording stopped due to button press	80	6	53.424	e14dce27580747aeb5ee35a3836614b9
47:18.1	Event button released				
47:18.3	Audio recording disabled due to video buffering default				
49:36.0	Audit log created	80	6	1.15.14	53.423
55:07.1	Event button pressed				
55:07.2	Event button released				
55:13.4	Event button pressed				
55:13.6	Event button released				
55:13.7	Event button pressed				
55:13.8	Audio recording enabled due to video recording default				
55:13.9	Recording started due to button press	80	7	53.423	f04c574115764bd5aa7d1600c91e6c05
55:13.9	Event button released				
04:43.0	Event button pressed				
04:46.0	Recording stopped due to button press	78	7	53.06	f04c574115764bd5aa7d1600c91e6c05
04:46.7	Event button released				
04:46.9	Audio recording disabled due to video buffering default				
06:53.5	Volume up button pressed				
06:54.2	Volume up button released				
06:54.4	Volume changed to very high from high using button				
35:31.5	Volume up button pressed				

35:31.6	Volume up button released			
35:55.8	Axon application connected to device			
36:27.9	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			e14dce27580747aeb5ee35a3836614b9
36:27.9	Title changed in video metadata from 'Axon Body 3 Video 2021-07-11 0143 X6033271L' to 'Clearing Train NE10' using Axon applicator			e14dce27580747aeb5ee35a3836614b9
36:36.2	Categories 'Special Detail' removed from video metadata using Axon applicator			e14dce27580747aeb5ee35a3836614b9
37:15.2	Categories 'Loitering' added to video metadata using Axon applicator			e14dce27580747aeb5ee35a3836614b9
37:15.2	Categories 'Sleeper' removed from video metadata using Axon applicator			e14dce27580747aeb5ee35a3836614b9
37:15.2	Title changed in video metadata from 'Clearing Train NE10' to 'Sig.70 NE9' using Axon applicator			e14dce27580747aeb5ee35a3836614b9
38:53.2	Categories 'Sleeper', 'Special Detail' added to video metadata using Axon applicator			f04c574115764bd5aa7d1600c91e6c05
38:53.2	Title changed in video metadata from 'Axon Body 3 Video 2021-07-11 0155 X6033271L' to 'Clearing Train NE10' using Axon applicator			f04c574115764bd5aa7d1600c91e6c05
39:05.8	Power button pressed			
39:05.8	Camera connected to Axon Dock X62001W9H	75	7	53.077
39:05.8	Axon application disconnected from device			
39:05.9	Audit log created	75	7 1.15.14	53.057
39:05.9	Audit log rolled	75	7	53.057
39:05.9	Power button released			
39:07.1	Device connected to charger	75	7	53.057
39:23.2	Video upload started when camera was docked			6d697edddcd142eb9e9277659650809e
39:35.0	Audit log successfully uploaded			
39:35.2	Audit log successfully uploaded and deleted from device	75	7	53.077
39:37.0	Date/Time synced to 07/11/2021 02:39:37.02 AM from 07/11/2021 02:39:35.84 AM			
39:55.5	Audit log successfully uploaded			
39:55.7	Audit log successfully uploaded and deleted from device	75	7	53.077
39:57.9	Audit log successfully uploaded			
39:58.1	Audit log successfully uploaded and deleted from device	75	7	53.077
40:06.2	Audit log successfully uploaded			
40:06.4	Audit log successfully uploaded and deleted from device	75	7	53.077
40:21.6	Audit log successfully uploaded			
40:21.8	Audit log successfully uploaded and deleted from device	75	7	53.077
40:40.9	Audit log successfully uploaded			
40:41.1	Audit log successfully uploaded and deleted from device	75	7	53.077
41:02.3	Audit log successfully uploaded			
41:02.5	Audit log successfully uploaded and deleted from device	76	7	53.077
41:28.7	Audit log successfully uploaded			
41:28.9	Audit log successfully uploaded and deleted from device	76	7	53.077
41:40.0	Audit log successfully uploaded			
41:40.2	Audit log successfully uploaded and deleted from device	76	7	53.077
41:42.4	Audit log successfully uploaded			
41:42.6	Audit log successfully uploaded and deleted from device	76	7	53.077
41:47.7	Audit log successfully uploaded			
41:47.9	Audit log successfully uploaded and deleted from device	76	7	53.077
42:12.1	Audit log successfully uploaded			
42:12.3	Audit log successfully uploaded and deleted from device	76	7	53.077
42:25.5	Audit log successfully uploaded			
42:25.7	Audit log successfully uploaded and deleted from device	76	7	53.077
42:45.8	Audit log successfully uploaded			
42:46.0	Audit log successfully uploaded and deleted from device	77	7	53.077

42:49.2	Audit log successfully uploaded			
42:49.4	Audit log successfully uploaded and deleted from device	77	7	53.077
42:58.5	Audit log successfully uploaded			
42:58.7	Audit log successfully uploaded and deleted from device	77	7	53.077
43:01.0	Audit log successfully uploaded			
43:01.1	Audit log successfully uploaded and deleted from device	77	7	53.077
43:08.8	Audit log successfully uploaded			
43:09.0	Audit log successfully uploaded and deleted from device	77	7	53.077
43:21.1	Audit log successfully uploaded			
43:21.3	Audit log successfully uploaded and deleted from device	77	7	53.077
43:24.4	Audit log successfully uploaded			
43:24.6	Audit log successfully uploaded and deleted from device	77	7	53.076
43:43.8	Audit log successfully uploaded			
43:44.0	Audit log successfully uploaded and deleted from device	77	7	53.076
43:46.1	Audit log successfully uploaded			
43:46.3	Audit log successfully uploaded and deleted from device	77	7	53.076
44:08.4	Audit log successfully uploaded			
44:08.6	Audit log successfully uploaded and deleted from device	77	7	53.076
44:22.8	Audit log successfully uploaded			
44:23.0	Audit log successfully uploaded and deleted from device	77	7	53.076
44:39.6	Video successfully uploaded from device when dockec			6d697edddcd142eb9e9277659650809e
44:39.9	Video deleted from device when docked	77	6	53.567 6d697edddcd142eb9e9277659650809e
44:40.0	Audit log rolled	77	6	53.568
44:40.0	Audit log created	77	6 1.15.14	53.568
44:40.2	Video upload started when camera was docked			ffabb5c8977741ae8b8257b54f8d77ef
44:47.1	Audit log successfully uploaded			
44:47.3	Audit log successfully uploaded and deleted from device	77	6	53.568
45:06.5	Audit log successfully uploaded			
45:06.7	Audit log successfully uploaded and deleted from device	78	6	53.568
45:21.8	Audit log successfully uploaded			
45:22.0	Audit log successfully uploaded and deleted from device	78	6	53.568
45:24.1	Audit log successfully uploaded			
45:24.3	Audit log successfully uploaded and deleted from device	78	6	53.567
45:29.4	Audit log successfully uploaded			
45:29.6	Audit log successfully uploaded and deleted from device	78	6	53.567
49:57.2	Video successfully uploaded from device when dockec			ffabb5c8977741ae8b8257b54f8d77ef
49:57.6	Video deleted from device when docked	80	5	54.305 ffabb5c8977741ae8b8257b54f8d77ef
49:57.6	Audit log rolled	80	5	54.31
49:57.6	Audit log created	80	5 1.15.14	54.31
49:57.8	Video upload started when camera was docked			c6acdbf4359f4bb19ce67bdec257a94e
50:26.0	Video successfully uploaded from device when dockec			c6acdbf4359f4bb19ce67bdec257a94e
50:26.3	Video deleted from device when docked	80	4	54.409 c6acdbf4359f4bb19ce67bdec257a94e
50:26.3	Audit log rolled	80	4	54.41
50:26.3	Audit log created	80	4 1.15.14	54.41
50:26.6	Video upload started when camera was docked			e0fdafd2ae7b43c9af9f4d7c8bbdaba2
50:57.5	Video successfully uploaded from device when dockec			e0fdafd2ae7b43c9af9f4d7c8bbdaba2
50:57.7	Video deleted from device when docked	80	3	54.517 e0fdafd2ae7b43c9af9f4d7c8bbdaba2

50:57.8 Audit log created	80	3 1.15.14	54.517
50:57.8 Audit log rolled	80	3	54.517
50:58.0 Video upload started when camera was docked			6d6910d86d064b68ba9164ed682b51af
51:26.2 Video successfully uploaded from device when docked			6d6910d86d064b68ba9164ed682b51af
51:26.6 Video deleted from device when docked	81	2	54.616 6d6910d86d064b68ba9164ed682b51af
51:26.6 Audit log created	81	2 1.15.14	54.617
51:26.6 Audit log rolled	81	2	54.617
51:27.2 Video upload started when camera was docked			e14dce27580747aeb5ee35a3836614b9
52:20.4 Video successfully uploaded from device when docked			e14dce27580747aeb5ee35a3836614b9
52:20.6 Video deleted from device when docked	81	1	54.806 e14dce27580747aeb5ee35a3836614b9
52:20.6 Audit log rolled	81	1	54.806
52:20.6 Audit log created	81	1 1.15.14	54.806
52:20.8 Video upload started when camera was docked			f04c574115764bd5aa7d1600c91e6c05
54:05.0 Video successfully uploaded from device when docked			f04c574115764bd5aa7d1600c91e6c05
54:05.4 Video deleted from device when docked	82	0	55.167 f04c574115764bd5aa7d1600c91e6c05
54:05.4 Audit log created	82	0 1.15.14	55.169
54:05.5 Audit log rolled	82	0	55.169
54:05.5 Audit log rolled	82	0	55.169
54:05.5 Audit log created	82	0 1.15.14	55.169
09:37.0 Date/Time synced to 07/11/2021 03:09:37.01 AM from 07/11/2021 03:09:37.03 AM			
39:37.0 Date/Time synced to 07/11/2021 03:39:37.01 AM from 07/11/2021 03:39:36.85 AM			
39:55.8 Device disconnected from charger	98	0	55.168
39:56.4 Camera disconnected from Axon Dock X62001W9H	98	0	55.169
54:04.9 Audit log created	96	0 1.15.14	55.172
54:04.9 Audit log created	90	0 1.15.14	55.17
54:04.9 Audit log created	84	0 1.15.14	55.169
22:22.8 Power button pressed			
22:23.9 Power button released			
22:25.0 Volume up button pressed			
22:25.3 Volume up button released			
22:26.2 Volume up button pressed			
22:26.7 Volume up button released			
22:29.1 Volume down button pressed			
22:29.3 Volume down button released			
22:29.4 Volume changed to high from very high using button			
22:29.8 Volume down button pressed			
22:29.9 Volume down button released			
22:30.1 Volume changed to medium from high using button			
22:33.5 Camera connected to Axon Dock X630020W7	81	0	55.169
22:33.5 Audit log rolled	81	0	55.168
22:33.5 Audit log created	81	0 1.15.14	55.169
22:33.8 Device connected to charger	81	0	55.169
22:33.0 Audit log created	100	0 1.15.14	55.168
22:33.0 Audit log created	100	0 1.15.14	55.168
22:33.0 Audit log created	100	0 1.15.14	55.167
22:33.0 Audit log created	100	0 1.15.14	55.167
22:33.0 Audit log created	100	0 1.15.14	55.167

22:33.0 Audit log created	100	0 1.15.14	55.167
22:33.0 Audit log created	100	0 1.15.14	55.166
22:33.0 Audit log created	100	0 1.15.14	55.167
22:33.1 Audit log created	100	0 1.15.14	55.168
12:32.2 Select button pressed			
12:32.5 Select button released			
12:32.8 Camera disconnected from Axon Dock X630020W7	98	0	55.167
12:32.9 Device disconnected from charger	98	0	55.169
12:48.9 Volume down button pressed			
12:49.1 Volume down button released			
12:49.3 Volume changed to low from medium using button			
12:51.9 Volume up button pressed			
12:52.1 Volume up button released			
12:52.2 Volume changed to medium from low using button			
22:33.1 Audit log created	98	0 1.15.14	55.169
22:33.1 Audit log created	92	0 1.15.14	55.167
22:33.1 Audit log created	85	0 1.15.14	55.166
29:57.1 Power button pressed			
30:00.2 Device powered off using button	85	0	55.166
30:00.6 Power button released			
30:09.4 Volume up button pressed			
30:09.4 Volume up button released			
30:13.7 Audit log rolled	85		55.167
30:13.7 Audit log created	85	1.15.14	55.167
30:13.8 Device connected to charger	85		55.167
30:54.0 Device powered on due to charger connection	85	0	55.166
30:54.2 Device connected to charger			
30:54.3 Camera connected to Axon Dock X630020W7	85	0	55.166
30:54.3 Audit log created		1.15.14	
30:54.3 Audit log rolled			
30:55.0 Camera connected to Axon Dock X630020W7	86	0	55.166
30:56.9 Audit log created	85	0 1.15.14	55.166
30:56.9 Audit log rolled	85	0	55.166
30:56.0 Audit log created	100	0 1.15.14	55.165
30:56.0 Audit log created	100	0 1.15.14	55.165
15:31.0 Device disconnected from charger	100	0	55.165
15:31.4 Camera disconnected from Axon Dock X630020W7	100	0	55.165
15:31.5 Audio recording disabled due to video buffering default			
30:56.0 Audit log created	98	0 1.15.14	55.166
49:48.6 Event button pressed			
49:48.8 Event button released			
49:48.9 Event button pressed			
49:48.9 Audio recording enabled due to video recording default			
49:49.0 Event button released			
49:49.1 Recording started due to button press	96	1	55.165 e77322725aa426f9ae061fd799b1057
21:08.3 Event button pressed			
21:11.3 Recording stopped due to button press	89	1	54.112 e77322725aa426f9ae061fd799b1057

21:12.3	Audio recording disabled due to video buffering default				
21:12.4	Event button released				
30:56.1	Audit log created	89	1 1.15.14	54.107	
30:56.2	Audit log created	82	1 1.15.14	54.106	
30:56.2	Audit log created	77	1 1.15.14	54.104	
29:08.7	Event button pressed				
29:08.9	Event button released				
29:08.9	Event button pressed				
29:09.0	Audio recording enabled due to video recording default				
29:09.0	Event button released				
29:09.1	Recording started due to button press	71	2	54.103	8c0e228159f84aa3aeb488ba39b5fd01
30:56.2	Audit log created	71	2 1.15.14	53.986	
35:47.0	Event button pressed				
35:47.2	Event button released				
35:47.3	Event button pressed				
35:47.5	Event button released				
35:52.9	Event button pressed				
35:53.7	Event button released				
36:25.9	Event button pressed				
36:28.5	Event button released				
39:13.2	Event button pressed				
39:16.2	Recording stopped due to button press	69	2	53.721	8c0e228159f84aa3aeb488ba39b5fd01
39:17.2	Audio recording disabled due to video buffering default				
39:17.5	Event button released				
51:41.0	Axon application connected to device				
52:24.4	Categories 'Special Detail', 'Loitering' added to video metadata using Axon applicator				8c0e228159f84aa3aeb488ba39b5fd01
52:24.4	Title changed in video metadata from 'Axon Body 3 Video 2021-07-12 0129 X6033271L' to 'Sig. 70 NE10' using Axon applicator				8c0e228159f84aa3aeb488ba39b5fd01
52:55.7	Categories 'Ambulance Call' added to video metadata using Axon applicator				e77322725aa426f9ae061fd799b1057
52:55.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-11 2149 X6033271L' to 'Sig. 47/4 N6' using Axon applicator				e77322725aa426f9ae061fd799b1057
53:08.6	Event button pressed				
53:08.7	Event button released				
53:08.8	Event button pressed				
53:08.9	Audio recording enabled due to video recording default				
53:08.9	Event button released				
53:09.0	Recording started due to button press	68	3	53.718	cfd65ad815664867946e71344e017ba1
00:27.9	Event button pressed				
00:30.9	Recording stopped due to button press	66	3	53.424	cfd65ad815664867946e71344e017ba1
00:31.6	Event button released				
00:31.8	Audio recording disabled due to video buffering default				
02:10.7	Categories 'Sleepers', 'Special Detail', 'Loitering' added to video metadata using Axon applicator				cfd65ad815664867946e71344e017ba1
02:10.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-12 0153 X6033271L' to 'Sig. 70 NE10' using Axon applicator				cfd65ad815664867946e71344e017ba1
02:20.6	Axon application disconnected from device				
19:53.0	Event button pressed				
19:53.0	Event button released				
19:53.1	Event button pressed				
19:53.1	Audio recording enabled due to video recording default				
19:53.2	Event button released				

19:53.3 Recording started due to button press	64	4	53.422 49b9d4ce05364028921016d7598afc61
30:56.3 Audit log created	62	4 1.15.14	53.012
37:55.8 Event button pressed			
37:58.8 Recording stopped due to button press	61	4	52.791 49b9d4ce05364028921016d7598afc61
37:59.8 Audio recording disabled due to video buffering default			
37:59.9 Event button released			
50:01.3 Axon application connected to device			
50:50.3 Categories 'Loitering' added to video metadata using Axon applicator			49b9d4ce05364028921016d7598afc61
50:50.3 Title changed in video metadata from 'Axon Body 3 Video 2021-07-12 0219 X6033271L' to 'Sig.70 x5 NE9' using Axon applicator			49b9d4ce05364028921016d7598afc61
51:03.3 Volume up button pressed			
51:03.4 Volume up button released			
51:03.8 Volume changed to high from medium using button			
51:06.7 Volume down button pressed			
51:07.0 Volume down button released			
51:07.1 Volume changed to medium from high using button			
51:14.3 Power button pressed			
51:14.5 Power button released			
51:15.1 Camera connected to Axon Dock X62001W9H	60	4	52.808
51:15.1 Axon application disconnected from device			
51:15.1 Audit log created	59	4 1.15.14	52.788
51:15.1 Audit log rolled	59	4	52.788
51:16.0 Device connected to charger	59	4	52.788
51:30.0 Video upload started when camera was docked			e77322725aa426f9ae061fd799b1057
51:36.1 Audit log successfully uploaded			
51:36.3 Audit log successfully uploaded and deleted from device	60	4	52.808
51:46.0 Date/Time synced to 07/12/2021 02:51:46.02 AM from 07/12/2021 02:51:45.17 AM			
51:51.0 Audit log successfully uploaded			
51:51.1 Audit log successfully uploaded and deleted from device	60	4	52.808
52:15.3 Audit log successfully uploaded			
52:15.4 Audit log successfully uploaded and deleted from device	60	4	52.808
52:17.6 Audit log successfully uploaded			
52:17.8 Audit log successfully uploaded and deleted from device	60	4	52.808
52:24.9 Audit log successfully uploaded			
52:25.0 Audit log successfully uploaded and deleted from device	60	4	52.808
52:52.1 Audit log successfully uploaded			
52:52.3 Audit log successfully uploaded and deleted from device	60	4	52.808
53:21.5 Audit log successfully uploaded			
53:21.6 Audit log successfully uploaded and deleted from device	61	4	52.808
53:39.7 Audit log successfully uploaded			
53:39.9 Audit log successfully uploaded and deleted from device	61	4	52.808
53:55.1 Audit log successfully uploaded			
53:55.2 Audit log successfully uploaded and deleted from device	61	4	52.807
54:16.4 Audit log successfully uploaded			
54:16.6 Audit log successfully uploaded and deleted from device	61	4	52.807
54:27.7 Audit log successfully uploaded			
54:27.9 Audit log successfully uploaded and deleted from device	61	4	52.807
54:31.0 Audit log successfully uploaded			

54:31.2	Audit log successfully uploaded and deleted from device	61	4	52.807
54:33.3	Audit log successfully uploaded			
54:33.5	Audit log successfully uploaded and deleted from device	61	4	52.807
54:45.6	Audit log successfully uploaded			
54:45.8	Audit log successfully uploaded and deleted from device	61	4	52.807
55:00.9	Audit log successfully uploaded			
55:01.1	Audit log successfully uploaded and deleted from device	61	4	52.807
55:04.3	Audit log successfully uploaded			
55:04.5	Audit log successfully uploaded and deleted from device	61	4	52.807
55:25.7	Audit log successfully uploaded			
55:25.9	Audit log successfully uploaded and deleted from device	61	4	52.807
55:29.0	Audit log successfully uploaded			
55:29.2	Audit log successfully uploaded and deleted from device	61	4	52.807
55:30.4	Audit log successfully uploaded			
55:30.6	Audit log successfully uploaded and deleted from device	61	4	52.807
55:41.7	Audit log successfully uploaded			
55:41.9	Audit log successfully uploaded and deleted from device	62	4	52.807
55:59.1	Audit log successfully uploaded			
55:59.2	Audit log successfully uploaded and deleted from device	62	4	52.807
56:10.4	Audit log successfully uploaded			
56:10.6	Audit log successfully uploaded and deleted from device	62	4	52.807
56:39.7	Audit log successfully uploaded			
56:39.9	Audit log successfully uploaded and deleted from device	62	4	52.807
57:07.1	Audit log successfully uploaded			
57:07.3	Audit log successfully uploaded and deleted from device	62	4	52.807
57:33.4	Audit log successfully uploaded			
57:33.6	Audit log successfully uploaded and deleted from device	63	4	52.807
58:02.6	Audit log successfully uploaded			
58:02.8	Audit log successfully uploaded and deleted from device	63	4	52.807
58:05.4	Audit log successfully uploaded			
58:05.6	Audit log successfully uploaded and deleted from device	63	4	52.807
58:17.7	Audit log successfully uploaded			
58:17.9	Audit log successfully uploaded and deleted from device	63	4	52.807
58:47.0	Audit log successfully uploaded			
58:47.2	Audit log successfully uploaded and deleted from device	63	4	52.807
59:07.3	Audit log successfully uploaded			
59:07.5	Audit log successfully uploaded and deleted from device	63	4	52.807
59:11.6	Audit log successfully uploaded			
59:11.8	Audit log successfully uploaded and deleted from device	63	4	52.807
59:18.0	Audit log successfully uploaded			
59:18.2	Audit log successfully uploaded and deleted from device	63	4	52.807
59:18.3	Audit log successfully uploaded			
59:18.6	Audit log successfully uploaded and deleted from device	63	4	52.807
59:28.7	Audit log successfully uploaded			
59:28.9	Audit log successfully uploaded and deleted from device	63	4	52.807
59:50.0	Audit log successfully uploaded			
59:50.2	Audit log successfully uploaded and deleted from device	64	4	52.807

59:58.4	Audit log successfully uploaded				
59:58.6	Audit log successfully uploaded and deleted from device	64	4	52.807	
00:11.1	Video successfully uploaded from device when docked				e77322725aa426f9ae061fd799b1057
00:11.5	Video deleted from device when docked	64	3	53.851	e77322725aa426f9ae061fd799b1057
00:11.8	Audit log created	64	3 1.15.14	53.851	
00:11.8	Audit log rolled	64	3	53.851	
00:12.0	Video upload started when camera was docked				8c0e228159f84aa3aeb488ba39b5fd01
01:59.5	Video successfully uploaded from device when docked				8c0e228159f84aa3aeb488ba39b5fd01
01:59.8	Video deleted from device when docked	65	2	54.231	8c0e228159f84aa3aeb488ba39b5fd01
01:59.8	Audit log rolled	65	2	54.231	
01:59.8	Audit log created	65	2 1.15.14	54.231	
02:00.0	Video upload started when camera was docked				cfd65ad815664867946e71344e017ba1
03:25.1	Video successfully uploaded from device when docked				cfd65ad815664867946e71344e017ba1
03:25.5	Video deleted from device when docked	65	1	54.523	cfd65ad815664867946e71344e017ba1
03:25.5	Audit log rolled	65	1	54.523	
03:25.5	Audit log created	65	1 1.15.14	54.523	
03:25.7	Video upload started when camera was docked				49b9d4ce05364028921016d7598afc61
06:30.4	Video successfully uploaded from device when docked				49b9d4ce05364028921016d7598afc61
06:30.8	Video deleted from device when docked	67	0	55.155	49b9d4ce05364028921016d7598afc61
06:30.8	Audit log rolled	67	0	55.155	
06:30.8	Audit log created	67	0 1.15.14	55.155	
06:30.8	Audit log created	67	0 1.15.14	55.155	
06:30.8	Audit log rolled	67	0	55.155	
21:46.0	Date/Time synced to 07/12/2021 03:21:46.02 AM from 07/12/2021 03:21:46.05 AM				
24:11.3	Device disconnected from charger	75	0	55.154	
24:11.8	Camera disconnected from Axon Dock X62001W9H	75	0	55.155	
06:29.8	Audit log created	71	0 1.15.14	55.158	
06:29.8	Audit log created	64	0 1.15.14	55.157	
06:29.8	Audit log created	58	0 1.15.14	55.156	
14:57.5	Camera connected to Axon Dock X630020W7	57	0	55.156	
14:57.5	Audit log rolled	57	0	55.155	
14:57.5	Audit log created	57	0 1.15.14	55.155	
14:58.3	Device connected to charger	57	0	55.156	
14:57.0	Audit log created	84	0 1.15.14	55.155	
14:57.0	Audit log created	100	0 1.15.14	55.154	
14:57.0	Audit log created	100	0 1.15.14	55.154	
14:57.0	Audit log created	100	0 1.15.14	55.154	
14:57.0	Audit log created	100	0 1.15.14	55.154	
14:57.0	Audit log created	100	0 1.15.14	55.154	
14:57.0	Audit log created	100	0 1.15.14	55.153	
14:57.0	Audit log created	100	0 1.15.14	55.153	
14:57.0	Audit log created	100	0 1.15.14	55.153	
14:57.1	Audit log created	100	0 1.15.14	55.159	
31:25.3	Device disconnected from charger	98	0	55.159	
31:25.7	Camera disconnected from Axon Dock X630020W7	100	0	55.158	
31:33.4	Power button pressed				
31:36.7	Device powered off using button	100	0	55.16	

31:37.0	Power button released				
26:22.0	Audit log created		1.15.14		
26:22.2	Device powered on using button	100	0	55.159	
26:24.1	Audio recording disabled due to video buffering default				
22:34.7	Event button pressed				
22:34.8	Event button released				
22:34.9	Event button pressed				
22:35.0	Audio recording enabled due to video recording default				
22:35.0	Event button released				
22:35.2	Recording started due to button press	93	0	55.162	fa4bd6c7d6fc4a408b801e8e70457193
24:08.0	Event button pressed				
24:11.0	Recording stopped due to button press	92	1	55.051	fa4bd6c7d6fc4a408b801e8e70457193
24:11.7	Event button released				
24:11.8	Audio recording disabled due to video buffering default				
26:22.1	Audit log created	92	1	1.15.14	55.05
52:23.5	Event button pressed				
52:23.6	Event button released				
52:23.7	Event button pressed				
52:23.7	Audio recording enabled due to video recording default				
52:23.7	Event button released				
52:23.8	Recording started due to button press	90	2	55.049	51785e8dbdcf4b42ad5c35dccf98a573
54:26.1	Event button pressed				
54:29.1	Recording stopped due to button press	89	2	54.923	51785e8dbdcf4b42ad5c35dccf98a573
54:29.7	Event button released				
54:30.0	Audio recording disabled due to video buffering default				
55:34.7	Event button pressed				
55:34.9	Event button released				
55:35.0	Event button pressed				
55:35.0	Audio recording enabled due to video recording default				
55:35.1	Event button released				
55:35.2	Recording started due to button press	89	3	54.922	f8591caafc5347148ebccc61e6d09a90
59:52.8	Event button pressed				
59:55.8	Recording stopped due to button press	89	3	54.751	f8591caafc5347148ebccc61e6d09a90
59:56.4	Event button released				
59:56.7	Audio recording disabled due to video buffering default				
05:42.3	Event button pressed				
05:42.6	Event button released				
05:42.7	Event button pressed				
05:42.7	Audio recording enabled due to video recording default				
05:42.8	Event button released				
05:42.9	Recording started due to button press	88	4	54.75	bdb8132d743f4befa1613a8d8e4136d4
09:42.6	Select button pressed				
09:42.8	Select button released				
09:43.3	Marker added to video due to button				
13:44.8	Event button pressed				
13:47.8	Recording stopped due to button press	86	4	54.432	bdb8132d743f4befa1613a8d8e4136d4
13:48.5	Event button released				

13:48.7	Audio recording disabled due to video buffering default			
14:47.5	Event button pressed			
14:47.6	Event button released			
14:47.7	Event button pressed			
14:47.7	Audio recording enabled due to video recording default			
14:47.8	Event button released			
14:47.9	Recording started due to button press	86	5	54.43 2cb684476b4642b084bf187b963b3013
17:17.9	Event button pressed			
17:20.9	Recording stopped due to button press	86	5	54.32 2cb684476b4642b084bf187b963b3013
17:21.7	Audio recording disabled due to video buffering default			
17:21.8	Event button released			
26:22.1	Audit log created	85	5 1.15.14	54.319
32:53.4	Volume up button pressed			
32:53.5	Volume up button released			
32:53.7	Volume changed to high from medium using button			
33:06.2	Volume down button pressed			
33:06.5	Volume down button released			
33:06.6	Volume changed to medium from high using button			
46:17.3	Axon application connected to device			
47:09.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-13 0122 X6033271L' to 'Clearing Train NE10' using Axon applicator			fa4bd6c7d6fc4a408b801e8e70457193
47:09.7	Categories 'Special Detail' added to video metadata using Axon applicator			fa4bd6c7d6fc4a408b801e8e70457193
47:37.8	Title changed in video metadata from 'Axon Body 3 Video 2021-07-13 0152 X6033271L' to 'Clearing Train NE10' using Axon applicator			51785e8dbdcf4b42ad5c35dccf98a573
47:37.8	Categories 'Special Detail' added to video metadata using Axon applicator			51785e8dbdcf4b42ad5c35dccf98a573
48:18.6	Video played back using Axon application			f8591caafc5347148ebccc61e6d09a90
48:55.2	Title changed in video metadata from 'Axon Body 3 Video 2021-07-13 0155 X6033271L' to 'Clearing Train NE10' using Axon applicator			f8591caafc5347148ebccc61e6d09a90
48:55.2	Categories 'Special Detail' added to video metadata using Axon applicator			f8591caafc5347148ebccc61e6d09a90
50:24.6	Title changed in video metadata from 'Axon Body 3 Video 2021-07-13 0205 X6033271L' to 'Sig. 70 NE9' using Axon applicator			bdb8132d743f4bfa1613a8d8e4136d4
50:24.6	Categories 'Loitering' added to video metadata using Axon applicator			bdb8132d743f4bfa1613a8d8e4136d4
50:56.4	Title changed in video metadata from 'Axon Body 3 Video 2021-07-13 0214 X6033271L' to 'Sig. 70 NE9' using Axon applicator			2cb684476b4642b084bf187b963b3013
50:56.4	Categories 'Loitering' added to video metadata using Axon applicator			2cb684476b4642b084bf187b963b3013
51:24.1	Axon application disconnected from device			
55:35.3	Power button pressed			
55:35.4	Power button released			
55:35.8	Camera connected to Axon Dock X62001V12	83	5	54.318
55:35.8	Audit log rolled	82	5	54.318
55:35.8	Audit log created	82	5 1.15.14	54.318
55:36.2	Device connected to charger	82	5	54.318
55:40.7	Volume up button pressed			
55:41.0	Volume up button released			
55:41.5	Volume up button pressed			
55:41.7	Volume up button released			
05:18.8	Camera disconnected from Axon Dock X62001V12	87	5	54.32
05:19.2	Device disconnected from charger	87	5	54.32
05:21.8	Camera connected to Axon Dock X62001V12	87	5	54.321
05:21.8	Audit log rolled	87	5	54.32
05:21.8	Audit log created	87	5 1.15.14	54.321
05:23.2	Device connected to charger	87	5	54.321

17:54.1	Volume up button pressed			
17:54.1	Volume up button released			
17:54.2	Device disconnected from charger	93	5	54.32
17:54.9	Camera disconnected from Axon Dock X62001V12	93	5	54.32
17:58.7	Volume up button pressed			
17:58.9	Volume up button released			
17:58.9	Camera connected to Axon Dock X62001V12	93	5	54.33
17:59.0	Audit log created	93	5 1.15.14	54.321
17:59.0	Audit log rolled	93	5	54.32
18:01.0	Device connected to charger	93	5	54.321
18:24.3	Video upload started when camera was docked			fa4bd6c7d6fc4a408b801e8e70457193
18:31.0	Date/Time synced to 07/13/2021 03:18:31.02 AM from 07/13/2021 03:18:28.97 AM			
18:38.0	Audit log successfully uploaded			
18:38.2	Audit log successfully uploaded and deleted from device	93	5	54.33
18:56.6	Video successfully uploaded from device when dockec			fa4bd6c7d6fc4a408b801e8e70457193
18:56.8	Video deleted from device when docked	93	4	54.441 fa4bd6c7d6fc4a408b801e8e70457193
18:56.9	Audit log rolled	93	4	54.441
18:56.9	Audit log created	93	4 1.15.14	54.441
18:57.1	Video upload started when camera was docked			51785e8dbdcf4b42ad5c35dccf98a573
19:01.3	Audit log successfully uploaded			
19:01.4	Audit log successfully uploaded and deleted from device	93	4	54.441
19:28.6	Audit log successfully uploaded			
19:28.8	Audit log successfully uploaded and deleted from device	94	4	54.441
19:30.8	Video successfully uploaded from device when dockec			51785e8dbdcf4b42ad5c35dccf98a573
19:31.1	Video deleted from device when docked	94	3	54.568 51785e8dbdcf4b42ad5c35dccf98a573
19:31.2	Audit log created	94	3 1.15.14	54.568
19:31.2	Audit log rolled	94	3	54.568
19:31.3	Video upload started when camera was docked			f8591caafc5347148ebccc61e6d09a90
19:55.9	Audit log successfully uploaded			
19:56.1	Audit log successfully uploaded and deleted from device	94	3	54.568
20:20.3	Video successfully uploaded from device when dockec			f8591caafc5347148ebccc61e6d09a90
20:20.6	Video deleted from device when docked	94	2	54.738 f8591caafc5347148ebccc61e6d09a90
20:20.7	Audit log created	94	2 1.15.14	54.738
20:20.7	Audit log rolled	94	2	54.738
20:20.9	Video upload started when camera was docked			bdb8132d743f4befa1613a8d8e4136d4
20:23.2	Audit log successfully uploaded			
20:23.5	Audit log successfully uploaded and deleted from device	94	2	54.738
20:38.6	Audit log successfully uploaded			
20:38.7	Audit log successfully uploaded and deleted from device	94	2	54.738
20:58.8	Audit log successfully uploaded			
20:59.0	Audit log successfully uploaded and deleted from device	94	2	54.738
21:15.2	Audit log successfully uploaded			
21:15.4	Audit log successfully uploaded and deleted from device	94	2	54.738
21:16.5	Audit log successfully uploaded			
21:16.7	Audit log successfully uploaded and deleted from device	94	2	54.738
21:42.9	Audit log successfully uploaded			
21:43.1	Audit log successfully uploaded and deleted from device	94	2	54.738

21:44.2	Audit log successfully uploaded			
21:44.4	Audit log successfully uploaded and deleted from device	94	2	54.738
21:47.4	Video successfully uploaded from device when docked			bdb8132d743f4bfa1613a8d8e4136d4
21:47.8	Video deleted from device when docked	94	1	55.053 bdb8132d743f4bfa1613a8d8e4136d4
21:47.8	Audit log rolled	94	1	55.054
21:47.8	Audit log created	94	1 1.15.14	55.054
21:48.0	Video upload started when camera was docked			2cb684476b4642b084bf187b963b3013
21:53.5	Audit log successfully uploaded			
21:53.7	Audit log successfully uploaded and deleted from device	94	1	55.054
22:06.0	Audit log successfully uploaded			
22:06.2	Audit log successfully uploaded and deleted from device	94	1	55.054
22:19.6	Video successfully uploaded from device when docked			2cb684476b4642b084bf187b963b3013
22:19.8	Video deleted from device when docked	94	0	55.164 2cb684476b4642b084bf187b963b3013
22:19.9	Audit log rolled	94	0	55.164
22:19.9	Audit log created	94	0 1.15.14	55.164
22:19.9	Audit log created	94	0 1.15.14	55.164
22:19.9	Audit log rolled	94	0	55.164
22:20.3	Audit log successfully uploaded			
22:20.5	Audit log successfully uploaded and deleted from device	94	0	55.164
22:43.7	Audit log successfully uploaded			
22:43.9	Audit log successfully uploaded and deleted from device	95	0	55.164
22:59.0	Audit log successfully uploaded			
22:59.2	Audit log successfully uploaded and deleted from device	95	0	55.164
23:08.4	Audit log successfully uploaded			
23:08.6	Audit log successfully uploaded and deleted from device	95	0	55.164
23:19.8	Audit log successfully uploaded			
23:20.0	Audit log successfully uploaded and deleted from device	95	0	55.164
23:43.2	Audit log successfully uploaded			
23:43.4	Audit log successfully uploaded and deleted from device	95	0	55.164
24:10.6	Audit log successfully uploaded			
24:10.8	Audit log successfully uploaded and deleted from device	95	0	55.164
24:30.9	Audit log successfully uploaded			
24:31.1	Audit log successfully uploaded and deleted from device	95	0	55.164
24:44.2	Audit log successfully uploaded			
24:44.4	Audit log successfully uploaded and deleted from device	95	0	55.164
25:13.5	Audit log successfully uploaded			
25:13.7	Audit log successfully uploaded and deleted from device	95	0	55.164
25:37.9	Audit log successfully uploaded			
25:38.1	Audit log successfully uploaded and deleted from device	96	0	55.164
25:40.2	Audit log successfully uploaded			
25:40.4	Audit log successfully uploaded and deleted from device	96	0	55.164
38:43.8	Device disconnected from charger	98	0	55.164
38:43.9	Camera disconnected from Axon Dock X62001V12	98	0	55.164
39:01.0	Volume up button pressed			
39:01.2	Volume up button released			
39:01.3	Volume changed to high from medium using button			
39:04.4	Volume down button pressed			

21:57.0	Volume changed to medium from high using button			
21:58.8	Power button pressed			
22:01.8	Device powered off using button	100	0	55.171
22:02.2	Power button released			
19:44.0	Audit log created		1.15.14	
19:44.1	Device powered on using button	100	0	55.175
19:44.3	Device connected to charger			
19:44.4	Camera connected to Axon Dock X62001V12	100	0	55.19
19:44.4	Audit log created		1.15.14	
19:44.4	Audit log rolled			
19:45.0	Camera connected to Axon Dock X62001V12	100	0	55.19
19:46.9	Audit log rolled	100	0	55.175
19:46.9	Audit log created	100	0 1.15.14	55.175
20:19.0	Date/Time synced to 07/15/2021 08:20:19.01 PM from 07/15/2021 08:20:16.50 PM			
20:48.4	Audit log successfully uploaded			
20:48.7	Audit log successfully uploaded and deleted from device	100	0	55.19
21:08.9	Audit log successfully uploaded			
21:09.2	Audit log successfully uploaded and deleted from device	100	0	55.189
21:18.4	Audit log successfully uploaded			
21:18.6	Audit log successfully uploaded and deleted from device	100	0	55.189
21:34.9	Audit log successfully uploaded			
21:35.1	Audit log successfully uploaded and deleted from device	100	0	55.189
21:46.4	Audit log successfully uploaded			
21:46.6	Audit log successfully uploaded and deleted from device	100	0	55.189
21:54.8	Audit log successfully uploaded			
21:55.1	Audit log successfully uploaded and deleted from device	100	0	55.189
22:05.6	Audit log successfully uploaded			
22:05.9	Audit log successfully uploaded and deleted from device	100	0	55.189
22:21.0	Audit log successfully uploaded			
22:21.3	Audit log successfully uploaded and deleted from device	100	0	55.189
22:50.5	Audit log successfully uploaded			
22:50.7	Audit log successfully uploaded and deleted from device	100	0	55.189
23:02.9	Audit log successfully uploaded			
23:03.1	Audit log successfully uploaded and deleted from device	100	0	55.189
23:31.3	Audit log successfully uploaded			
23:31.5	Audit log successfully uploaded and deleted from device	100	0	55.189
23:43.7	Audit log successfully uploaded			
23:43.9	Audit log successfully uploaded and deleted from device	100	0	55.189
23:59.1	Audit log successfully uploaded			
23:59.3	Audit log successfully uploaded and deleted from device	100	0	55.189
24:09.5	Audit log successfully uploaded			
24:09.6	Audit log successfully uploaded and deleted from device	100	0	55.189
24:37.7	Audit log successfully uploaded			
24:37.9	Audit log successfully uploaded and deleted from device	100	0	55.189
24:46.1	Audit log successfully uploaded			
24:46.3	Audit log successfully uploaded and deleted from device	100	0	55.189
24:53.5	Audit log successfully uploaded			

24:53.7 Audit log successfully uploaded and deleted from device	100	0	55.189
25:00.8 Audit log successfully uploaded			
25:01.0 Audit log successfully uploaded and deleted from device	100	0	55.189
25:07.1 Audit log successfully uploaded			
25:07.3 Audit log successfully uploaded and deleted from device	100	0	55.189
25:33.5 Audit log successfully uploaded			
25:33.7 Audit log successfully uploaded and deleted from device	100	0	55.189
25:33.8 Audit log successfully uploaded			
25:34.0 Audit log successfully uploaded and deleted from device	100	0	55.189
25:56.1 Audit log successfully uploaded			
25:56.3 Audit log successfully uploaded and deleted from device	100	0	55.189
26:25.5 Audit log successfully uploaded			
26:25.7 Audit log successfully uploaded and deleted from device	100	0	55.189
26:31.8 Audit log successfully uploaded			
26:32.0 Audit log successfully uploaded and deleted from device	100	0	55.189
26:58.2 Audit log successfully uploaded			
26:58.4 Audit log successfully uploaded and deleted from device	100	0	55.189
27:20.6 Audit log successfully uploaded			
27:20.8 Audit log successfully uploaded and deleted from device	100	0	55.189
27:33.0 Audit log successfully uploaded			
27:33.2 Audit log successfully uploaded and deleted from device	100	0	55.189
27:47.3 Audit log successfully uploaded			
27:47.5 Audit log successfully uploaded and deleted from device	100	0	55.189
28:09.7 Audit log successfully uploaded			
28:09.9 Audit log successfully uploaded and deleted from device	100	0	55.189
28:32.1 Audit log successfully uploaded			
28:32.3 Audit log successfully uploaded and deleted from device	100	0	55.189
28:36.4 Audit log successfully uploaded			
28:36.6 Audit log successfully uploaded and deleted from device	100	0	55.189
28:38.7 Audit log successfully uploaded			
28:38.9 Audit log successfully uploaded and deleted from device	100	0	55.189
29:02.1 Audit log successfully uploaded			
29:02.2 Audit log successfully uploaded and deleted from device	100	0	55.189
29:29.4 Audit log successfully uploaded			
29:29.6 Audit log successfully uploaded and deleted from device	100	0	55.189
29:43.8 Audit log successfully uploaded			
29:44.0 Audit log successfully uploaded and deleted from device	100	0	55.189
29:54.1 Audit log successfully uploaded			
29:54.3 Audit log successfully uploaded and deleted from device	100	0	55.189
30:19.5 Audit log successfully uploaded			
30:19.8 Audit log successfully uploaded and deleted from device	100	0	55.189
30:40.9 Audit log successfully uploaded			
30:41.1 Audit log successfully uploaded and deleted from device	100	0	55.189
30:53.2 Audit log successfully uploaded			
30:53.4 Audit log successfully uploaded and deleted from device	100	0	55.189
31:05.8 Audit log successfully uploaded			
31:05.9 Audit log successfully uploaded and deleted from device	100	0	55.189

31:23.1	Audit log successfully uploaded			
31:23.4	Audit log successfully uploaded and deleted from device	100	0	55.189
31:26.5	Audit log successfully uploaded			
31:26.7	Audit log successfully uploaded and deleted from device	100	0	55.189
31:48.9	Audit log successfully uploaded			
31:49.1	Audit log successfully uploaded and deleted from device	100	0	55.189
32:06.2	Audit log successfully uploaded			
32:06.5	Audit log successfully uploaded and deleted from device	100	0	55.189
32:23.6	Audit log successfully uploaded			
32:23.8	Audit log successfully uploaded and deleted from device	100	0	55.189
32:49.9	Audit log successfully uploaded			
32:50.1	Audit log successfully uploaded and deleted from device	100	0	55.189
32:50.3	Audit log successfully uploaded			
32:50.5	Audit log successfully uploaded and deleted from device	100	0	55.189
32:53.6	Audit log successfully uploaded			
32:53.9	Audit log successfully uploaded and deleted from device	100	0	55.189
32:58.0	Audit log successfully uploaded			
32:58.2	Audit log successfully uploaded and deleted from device	100	0	55.189
33:00.4	Audit log successfully uploaded			
33:00.6	Audit log successfully uploaded and deleted from device	100	0	55.189
33:10.8	Audit log successfully uploaded			
33:11.0	Audit log successfully uploaded and deleted from device	100	0	55.189
33:33.1	Audit log successfully uploaded			
33:33.3	Audit log successfully uploaded and deleted from device	100	0	55.189
33:52.4	Audit log successfully uploaded			
33:52.6	Audit log successfully uploaded and deleted from device	100	0	55.189
34:00.3	Device disconnected from charger	100	0	55.189
34:00.3	Camera disconnected from Axon Dock X62001V12	100	0	55.189
34:00.4	Audio recording disabled due to video buffering default			
10:44.3	Power button pressed			
10:47.3	Device powered off using button	95	0	55.188
10:47.7	Power button released			
13:37.1	Device powered on due to charger connection	95	0	55.187
13:37.3	Device connected to charger			
13:37.4	Camera connected to Axon Dock X630020W7	95	0	55.187
13:37.4	Audit log created		1.15.14	
13:37.4	Audit log rolled			
13:38.1	Camera connected to Axon Dock X630020W7	96	0	55.187
13:40.0	Audit log rolled	95	0	55.187
13:40.0	Audit log created	95	0 1.15.14	55.187
13:39.0	Audit log created	100	0 1.15.14	55.187
13:39.0	Audit log created	100	0 1.15.14	55.186
13:39.0	Audit log created	100	0 1.15.14	55.186
13:39.0	Audit log created	100	0 1.15.14	55.186
13:39.0	Audit log created	100	0 1.15.14	55.185
13:39.0	Audit log created	100	0 1.15.14	55.186
13:39.0	Audit log created	100	0 1.15.14	55.186

13:39.1 Audit log created	100	0 1.15.14	55.186
13:39.1 Audit log created	100	0 1.15.14	55.186
13:39.1 Audit log created	100	0 1.15.14	55.185
13:39.1 Audit log created	100	0 1.15.14	55.185
13:39.1 Audit log created	100	0 1.15.14	55.185
13:39.1 Audit log created	100	0 1.15.14	55.185
13:39.1 Audit log created	100	0 1.15.14	55.185
13:39.1 Audit log created	100	0 1.15.14	55.184
13:39.1 Audit log created	100	0 1.15.14	55.184
13:39.1 Audit log created	100	0 1.15.14	55.184
13:39.1 Audit log created	100	0 1.15.14	55.183
13:39.1 Audit log created	100	0 1.15.14	55.183
13:39.1 Audit log created	100	0 1.15.14	55.183
44:37.1 Device disconnected from charger	100	0	55.183
44:37.2 Camera disconnected from Axon Dock X630020W7	100	0	55.183
44:37.3 Audio recording disabled due to video buffering default			
44:48.7 Power button pressed			
44:51.7 Device powered off using button	100	0	55.183
44:52.2 Power button released			
29:35.9 Audit log created		1.15.14	
29:36.1 Device powered on using button	100	0	55.182
29:38.0 Audio recording disabled due to video buffering default			
29:36.0 Audit log created	92	0 1.15.14	55.181
42:03.9 Power button pressed			
42:06.9 Device powered off using button	91	0	55.18
42:07.4 Power button released			
29:55.0 Audit log created		1.15.14	
29:55.1 Device powered on using button	91	0	55.18
29:56.9 Audio recording disabled due to video buffering default			
36:04.1 Camera connected to Axon Dock X62001W9H	91	0	55.188
36:04.1 Audit log rolled	91	0	55.18
36:04.1 Audit log created	91	0 1.15.14	55.18
36:05.1 Device connected to charger	91	0	55.18
36:23.5 Audit log successfully uploaded			
36:23.7 Audit log successfully uploaded and deleted from device	91	0	55.188
36:23.8 Audit log successfully uploaded			
36:24.0 Audit log successfully uploaded and deleted from device	91	0	55.188
36:36.0 Date/Time synced to 07/17/2021 05:36:36.01 AM from 07/17/2021 05:36:34.11 AM			
36:50.7 Audit log successfully uploaded			
36:50.9 Audit log successfully uploaded and deleted from device	91	0	55.188
36:52.1 Audit log successfully uploaded			
36:52.3 Audit log successfully uploaded and deleted from device	91	0	55.188
37:15.4 Audit log successfully uploaded			
37:15.6 Audit log successfully uploaded and deleted from device	91	0	55.186
37:33.7 Audit log successfully uploaded			
37:33.9 Audit log successfully uploaded and deleted from device	91	0	55.186
37:39.2 Audit log successfully uploaded			

37:39.4	Audit log successfully uploaded and deleted from device	91	0	55.186
37:53.8	Camera disconnected from Axon Dock X62001W9H	91	0	55.186
37:53.8	Device disconnected from charger	91	0	55.186
30:49.8	Camera connected to Axon Dock X630020W7	86	0	55.185
30:49.8	Audit log rolled	86	0	55.185
30:49.8	Audit log created	86	0 1.15.14	55.185
30:50.8	Device connected to charger	86	0	55.185
30:49.0	Audit log created	100	0 1.15.14	55.185
30:49.0	Audit log created	100	0 1.15.14	55.184
30:49.0	Audit log created	100	0 1.15.14	55.184
30:49.0	Audit log created	100	0 1.15.14	55.184
30:49.0	Audit log created	100	0 1.15.14	55.183
30:49.0	Audit log created	100	0 1.15.14	55.183
30:49.1	Audit log created	100	0 1.15.14	55.183
30:49.1	Audit log created	100	0 1.15.14	55.183
30:49.1	Audit log created	100	0 1.15.14	55.182
30:49.1	Audit log created	100	0 1.15.14	55.182
36:47.8	Device disconnected from charger	100	0	55.182
36:47.8	Camera disconnected from Axon Dock X630020W7	100	0	55.182
36:59.1	Power button pressed			
37:02.1	Device powered off using button	100	0	55.182
37:02.5	Power button released			
27:44.0	Audit log created		1.15.14	
27:44.1	Device powered on using button	100	0	55.182
27:45.9	Audio recording disabled due to video buffering default			
32:08.3	Power button pressed			
32:11.3	Device powered off using button	99	0	55.181
32:11.7	Power button released			
33:00.0	Device powered on using button	99	0	55.181
33:02.1	Audio recording disabled due to video buffering default			
33:06.2	Power button pressed			
33:06.4	Power button released			
27:43.1	Audit log created	92	0 1.15.14	55.18
27:43.1	Audit log created	87	0 1.15.14	55.178
46:39.1	Event button pressed			
46:39.3	Event button released			
46:39.4	Event button pressed			
46:39.4	Audio recording enabled due to video recording default			
46:39.6	Event button released			
46:39.7	Recording started due to button press	85	0	55.178 d7ec85bccd3c4292b9e89187ac79019b
52:29.1	Event button pressed			
52:32.1	Recording stopped due to button press	84	1	54.932 d7ec85bccd3c4292b9e89187ac79019b
52:32.9	Event button released			
52:33.0	Audio recording disabled due to video buffering default			
54:35.0	Event button pressed			
54:35.2	Event button released			
54:35.3	Event button pressed			

54:35.3	Audio recording enabled due to video recording default				
54:35.4	Event button released				
54:35.5	Recording started due to button press	84	2	54.93	4d9945295b004f02a0b89c3272917db5
01:43.8	Event button pressed				
01:46.8	Recording stopped due to button press	82	2	54.642	4d9945295b004f02a0b89c3272917db5
01:47.5	Event button released				
01:47.7	Audio recording disabled due to video buffering default				
18:36.7	Power button pressed				
18:39.7	Device powered off using button	80	2	54.641	
18:40.4	Power button released				
54:22.1	Audit log created			1.15.14	
54:22.2	Device powered on using button	80	2	54.64	
54:25.5	Audio recording disabled due to video buffering default				
15:11.8	Axon application connected to device				
15:26.4	Axon application connected to device				
16:39.9	Title changed in video metadata from 'Axon Body 3 Video 2021-07-18 0146 X6033271L' to 'Sig. 70/23 N11' using Axon applicator				d7ec85bcdd3c4292b9e89187ac79019b
16:39.9	Categories 'Disorderly Person', 'Loitering' added to video metadata using Axon applicator				d7ec85bcdd3c4292b9e89187ac79019b
17:23.9	Title changed in video metadata from 'Axon Body 3 Video 2021-07-18 0154 X6033271L' to 'Sig. 70 N11' using Axon applicator				4d9945295b004f02a0b89c3272917db5
17:23.9	Categories 'Loitering' added to video metadata using Axon applicator				4d9945295b004f02a0b89c3272917db5
17:37.9	Axon application disconnected from device				
21:39.4	Camera connected to Axon Dock X62001W9H	78	2	54.648	
21:39.4	Audit log rolled	78	2	54.64	
21:39.4	Audit log created	78	2	1.15.14	54.64
21:40.2	Device connected to charger	78	2	54.64	
21:54.5	Video upload started when camera was docked				d7ec85bcdd3c4292b9e89187ac79019b
21:55.7	Audit log successfully uploaded				
21:55.9	Audit log successfully uploaded and deleted from device	78	2	54.648	
22:11.0	Date/Time synced to 07/18/2021 05:22:11.01 AM from 07/18/2021 05:22:09.43 AM				
22:13.3	Audit log successfully uploaded				
22:13.6	Audit log successfully uploaded and deleted from device	78	2	54.648	
22:17.8	Audit log successfully uploaded				
22:18.0	Audit log successfully uploaded and deleted from device	78	2	54.648	
22:44.1	Audit log successfully uploaded				
22:44.3	Audit log successfully uploaded and deleted from device	78	2	54.648	
22:54.4	Audit log successfully uploaded				
22:54.6	Audit log successfully uploaded and deleted from device	78	2	54.648	
23:10.7	Video successfully uploaded from device when docked				d7ec85bcdd3c4292b9e89187ac79019b
23:11.0	Video deleted from device when docked	79	1	54.893	d7ec85bcdd3c4292b9e89187ac79019b
23:11.0	Audit log created	79	1	1.15.14	54.894
23:11.0	Audit log rolled	79	1	54.894	
23:11.3	Video upload started when camera was docked				4d9945295b004f02a0b89c3272917db5
23:21.8	Audit log successfully uploaded				
23:21.9	Audit log successfully uploaded and deleted from device	79	1	54.894	
23:28.1	Audit log successfully uploaded				
23:28.3	Audit log successfully uploaded and deleted from device	79	1	54.894	
23:57.4	Audit log successfully uploaded				
23:57.6	Audit log successfully uploaded and deleted from device	79	1	54.893	

24:20.7	Audit log successfully uploaded			
24:20.9	Audit log successfully uploaded and deleted from device	79	1	54.893
24:22.0	Audit log successfully uploaded			
24:22.2	Audit log successfully uploaded and deleted from device	79	1	54.893
24:32.0	Video successfully uploaded from device when dockec			4d9945295b004f02a0b89c3272917db5
24:32.3	Video deleted from device when docked	79	0	55.18 4d9945295b004f02a0b89c3272917db5
24:32.3	Audit log rolled	79	0	55.18
24:32.3	Audit log created	79	0 1.15.14	55.18
24:32.3	Audit log rolled	79	0	55.18
24:32.3	Audit log created	79	0 1.15.14	55.18
24:32.4	Audit log successfully uploaded			
24:32.6	Audit log successfully uploaded and deleted from device	79	0	55.18
24:37.7	Audit log successfully uploaded			
24:37.8	Audit log successfully uploaded and deleted from device	79	0	55.18
24:40.0	Audit log successfully uploaded			
24:40.2	Audit log successfully uploaded and deleted from device	79	0	55.18
24:51.5	Device disconnected from charger	80	0	55.18
24:51.7	Camera disconnected from Axon Dock X62001W9H	80	0	55.181
24:59.4	Volume up button pressed			
24:59.5	Volume up button released			
25:00.1	Volume changed to high from medium using button			
25:02.0	Volume down button pressed			
25:02.3	Volume down button released			
25:02.4	Volume changed to medium from high using button			
16:18.5	Camera connected to Axon Dock X630020W7	75	0	55.18
16:18.6	Audit log rolled	74	0	55.18
16:18.6	Audit log created	74	0 1.15.14	55.18
16:19.5	Device connected to charger	74	0	55.18
16:18.0	Audit log created	98	0 1.15.14	55.179
16:18.0	Audit log created	100	0 1.15.14	55.178
16:18.0	Audit log created	100	0 1.15.14	55.178
16:18.0	Audit log created	100	0 1.15.14	55.178
16:18.1	Audit log created	100	0 1.15.14	55.178
16:18.1	Audit log created	100	0 1.15.14	55.177
16:18.1	Audit log created	100	0 1.15.14	55.177
16:18.1	Audit log created	100	0 1.15.14	55.177
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.176
16:18.1	Audit log created	100	0 1.15.14	55.175
16:18.1	Audit log created	100	0 1.15.14	55.175
16:18.2	Audit log created	100	0 1.15.14	55.175
32:11.5	Camera disconnected from Axon Dock X630020W7	100	0	55.175
32:11.5	Device disconnected from charger	100	0	55.175
32:23.2	Power button pressed			

32:26.2 Device powered off using button	100	0	55.175
32:26.6 Power button released			
14:02.0 Device powered on using button	100	0	55.174
14:04.0 Audio recording disabled due to video buffering default			
16:18.1 Audit log created	99	0 1.15.14	55.174
16:18.1 Audit log created	92	0 1.15.14	55.173
16:18.1 Audit log created	86	0 1.15.14	55.171
16:18.1 Audit log created	80	0 1.15.14	55.17
24:02.4 Power button pressed			
24:05.4 Device powered off using button	80	0	55.17
24:06.0 Power button released			
51:02.9 Audit log created		1.15.14	
51:03.1 Device powered on using button	80	0	55.171
51:05.1 Audio recording disabled due to video buffering default			
51:03.0 Audit log created	74	0 1.15.14	55.17
36:10.0 Camera connected to Axon Dock X62001W9H	70	0	55.176
36:10.0 Audit log rolled	70	0	55.169
36:10.0 Audit log created	70	0 1.15.14	55.169
36:10.2 Power button pressed			
36:10.2 Power button released			
36:11.1 Device connected to charger	70	0	55.169
36:41.0 Date/Time synced to 07/19/2021 05:36:41.01 AM from 07/19/2021 05:36:40.02 AM			
36:50.3 Audit log successfully uploaded			
36:50.5 Audit log successfully uploaded and deleted from device	70	0	55.176
37:16.7 Audit log successfully uploaded			
37:16.9 Audit log successfully uploaded and deleted from device	70	0	55.176
37:29.0 Audit log successfully uploaded			
37:29.2 Audit log successfully uploaded and deleted from device	70	0	55.176
37:32.1 Select button pressed			
37:32.5 Select button released			
37:32.8 Device disconnected from charger	70	0	55.176
37:32.8 Camera disconnected from Axon Dock X62001W9H	70	0	55.176
37:35.5 Volume up button pressed			
37:35.7 Volume up button released			
37:35.8 Volume changed to high from medium using button			
37:37.5 Volume down button pressed			
37:37.7 Volume down button released			
37:37.8 Volume changed to medium from high using button			
16:01.7 Camera connected to Axon Dock X630020W7	66	0	55.176
16:01.8 Audit log created	66	0 1.15.14	55.176
16:01.8 Audit log rolled	66	0	55.176
16:01.8 Device connected to charger	66	0	55.176
16:01.0 Audit log created	93	0 1.15.14	55.176
16:01.0 Audit log created	100	0 1.15.14	55.175
16:01.0 Audit log created	100	0 1.15.14	55.175
16:01.0 Audit log created	100	0 1.15.14	55.175
16:01.0 Audit log created	100	0 1.15.14	55.175

16:01.1	Audit log created	100	0	1.15.14	55.174
16:01.1	Audit log created	100	0	1.15.14	55.174
16:01.1	Audit log created	100	0	1.15.14	55.174
16:01.1	Audit log created	100	0	1.15.14	55.174
16:01.1	Audit log created	100	0	1.15.14	55.173
16:01.1	Audit log created	100	0	1.15.14	55.173
16:01.1	Audit log created	100	0	1.15.14	55.173
16:01.1	Audit log created	100	0	1.15.14	55.173
16:01.1	Audit log created	100	0	1.15.14	55.172
16:01.2	Audit log created	100	0	1.15.14	55.172
16:01.2	Audit log created	100	0	1.15.14	55.172
26:20.8	Device disconnected from charger	98	0		55.172
26:21.5	Camera disconnected from Axon Dock X630020W7	100	0		55.172
26:30.8	Power button pressed				
26:33.0	Power button released				
26:34.9	Power button pressed				
26:37.9	Device powered off using button	100	0		55.172
26:38.2	Power button released				
34:16.9	Audit log created			1.15.14	
34:17.0	Device powered on using button	100	0		55.171
34:18.8	Audio recording disabled due to video buffering default				
34:16.9	Audit log created	92	0	1.15.14	55.17
34:16.9	Audit log created	87	0	1.15.14	55.169
42:46.4	Event button pressed				
42:46.6	Event button released				
42:46.7	Event button pressed				
42:46.7	Audio recording enabled due to video recording default				
42:46.7	Event button released				
42:46.9	Recording started due to button press	85	1		55.168 3d76c20b2dd54905a296160f95aa2044
48:41.0	Event button pressed				
48:44.0	Recording stopped due to button press	84	1		54.92 3d76c20b2dd54905a296160f95aa2044
48:44.6	Event button released				
48:44.8	Audio recording disabled due to video buffering default				
50:53.5	Axon application connected to device				
51:29.5	Title changed in video metadata from 'Axon Body 3 Video 2021-07-20 0142 X6033271L' to 'Sig. 70 N11' using Axon applicator				3d76c20b2dd54905a296160f95aa2044
51:29.5	Categories 'Loitering' added to video metadata using Axon applicator				3d76c20b2dd54905a296160f95aa2044
51:40.2	Axon application disconnected from device				
34:16.9	Audit log created	80	1	1.15.14	54.917
34:17.0	Audit log created	75	1	1.15.14	54.916
34:17.0	Audit log created	68	1	1.15.14	54.914
34:17.0	Audit log created	62	1	1.15.14	54.913
38:08.1	Camera connected to Axon Dock X62001W9H	62	1		54.921
38:08.2	Audit log created	62	1	1.15.14	54.913
38:08.2	Audit log rolled	62	1		54.913
38:09.0	Device connected to charger	62	1		54.913
38:21.6	Video upload started when camera was docked				3d76c20b2dd54905a296160f95aa2044
38:38.3	Audit log successfully uploaded				

38:38.4	Audit log successfully uploaded and deleted from device	62	1	54.921
38:39.0	Date/Time synced to 07/20/2021 05:38:39.01 AM from 07/20/2021 05:38:38.18 AM			
38:54.1	Audit log successfully uploaded			
38:54.2	Audit log successfully uploaded and deleted from device	62	1	54.921
39:10.4	Audit log successfully uploaded			
39:10.6	Audit log successfully uploaded and deleted from device	62	1	54.921
39:13.7	Audit log successfully uploaded			
39:13.8	Audit log successfully uploaded and deleted from device	62	1	54.921
39:27.0	Audit log successfully uploaded			
39:27.2	Audit log successfully uploaded and deleted from device	62	1	54.921
39:29.1	Video successfully uploaded from device when docked			3d76c20b2dd54905a296160f95aa2044
39:29.5	Video deleted from device when docked	62	0	55.169 3d76c20b2dd54905a296160f95aa2044
39:29.5	Audit log created	62	0 1.15.14	55.169
39:29.5	Audit log rolled	62	0	55.169
39:29.5	Audit log created	62	0 1.15.14	55.169
39:29.5	Audit log rolled	62	0	55.169
39:49.4	Audit log successfully uploaded			
39:49.6	Audit log successfully uploaded and deleted from device	62	0	55.169
39:52.8	Audit log successfully uploaded			
39:58.0	Audit log successfully uploaded and deleted from device	63	0	55.169
40:02.4	Audit log successfully uploaded			
40:02.6	Audit log successfully uploaded and deleted from device	63	0	55.169
40:18.0	Audit log successfully uploaded			
40:18.2	Audit log successfully uploaded and deleted from device	63	0	55.169
40:24.3	Audit log successfully uploaded			
40:24.5	Audit log successfully uploaded and deleted from device	63	0	55.169
40:46.7	Audit log successfully uploaded			
40:46.9	Audit log successfully uploaded and deleted from device	63	0	55.169
40:55.0	Audit log successfully uploaded			
40:55.3	Audit log successfully uploaded and deleted from device	63	0	55.169
41:05.4	Audit log successfully uploaded			
41:05.6	Audit log successfully uploaded and deleted from device	63	0	55.169
41:24.7	Audit log successfully uploaded			
41:24.9	Audit log successfully uploaded and deleted from device	63	0	55.169
41:54.1	Audit log successfully uploaded			
41:54.2	Audit log successfully uploaded and deleted from device	63	0	55.169
42:20.4	Audit log successfully uploaded			
42:20.6	Audit log successfully uploaded and deleted from device	63	0	55.169
42:46.8	Audit log successfully uploaded			
42:46.9	Audit log successfully uploaded and deleted from device	64	0	55.169
43:04.3	Audit log successfully uploaded			
43:04.5	Audit log successfully uploaded and deleted from device	64	0	55.169
43:04.6	Audit log successfully uploaded			
43:04.8	Audit log successfully uploaded and deleted from device	64	0	55.169
43:23.9	Audit log successfully uploaded			
43:24.2	Audit log successfully uploaded and deleted from device	64	0	55.169
43:25.3	Audit log successfully uploaded			

43:25.5	Audit log successfully uploaded and deleted from device	64	0	55.169
43:30.7	Audit log successfully uploaded			
43:30.9	Audit log successfully uploaded and deleted from device	64	0	55.169
43:54.0	Audit log successfully uploaded			
43:54.2	Audit log successfully uploaded and deleted from device	64	0	55.169
43:58.4	Audit log successfully uploaded			
43:58.6	Audit log successfully uploaded and deleted from device	64	0	55.169
44:26.8	Audit log successfully uploaded			
44:27.0	Audit log successfully uploaded and deleted from device	65	0	55.169
44:43.2	Audit log successfully uploaded			
44:43.4	Audit log successfully uploaded and deleted from device	65	0	55.169
44:51.5	Audit log successfully uploaded			
44:51.7	Audit log successfully uploaded and deleted from device	65	0	55.169
45:17.9	Audit log successfully uploaded			
45:18.1	Audit log successfully uploaded and deleted from device	65	0	55.169
45:33.3	Audit log successfully uploaded			
45:33.5	Audit log successfully uploaded and deleted from device	65	0	55.169
45:44.7	Audit log successfully uploaded			
45:44.9	Audit log successfully uploaded and deleted from device	65	0	55.169
45:47.0	Audit log successfully uploaded			
45:47.2	Audit log successfully uploaded and deleted from device	65	0	55.169
45:55.4	Audit log successfully uploaded			
45:55.6	Audit log successfully uploaded and deleted from device	65	0	55.169
45:57.8	Audit log successfully uploaded			
45:58.0	Audit log successfully uploaded and deleted from device	65	0	55.169
46:11.1	Audit log successfully uploaded			
46:11.2	Audit log successfully uploaded and deleted from device	65	0	55.169
46:24.4	Audit log successfully uploaded			
46:24.6	Audit log successfully uploaded and deleted from device	65	0	55.169
46:30.5	Camera disconnected from Axon Dock X62001W9H	65	0	55.169
46:30.6	Device disconnected from charger	65	0	55.169
17:10.6	Volume up button pressed			
17:11.1	Volume up button released			
17:11.2	Volume changed to high from medium using button			
17:13.5	Volume down button pressed			
17:13.7	Volume down button released			
17:13.8	Volume changed to medium from high using button			
17:16.6	Camera connected to Axon Dock X630020W7	63	0	55.172
17:16.6	Audit log created	63	0 1.15.14	55.172
17:16.6	Audit log rolled	63	0	55.172
17:26.9	Device connected to charger	63	0	55.172
17:16.0	Audit log created	90	0 1.15.14	55.171
17:16.0	Audit log created	100	0 1.15.14	55.171
17:16.0	Audit log created	100	0 1.15.14	55.17
17:16.0	Audit log created	100	0 1.15.14	55.17
17:16.1	Audit log created	100	0 1.15.14	55.17
17:16.1	Audit log created	100	0 1.15.14	55.17

17:16.1	Audit log created	100	0 1.15.14	55.171
17:16.1	Audit log created	100	0 1.15.14	55.171
17:16.1	Audit log created	100	0 1.15.14	55.17
17:16.1	Audit log created	100	0 1.15.14	55.17
17:16.1	Audit log created	100	0 1.15.14	55.17
17:16.1	Audit log created	100	0 1.15.14	55.17
17:16.2	Audit log created	100	0 1.15.14	55.169
46:09.5	Camera disconnected from Axon Dock X630020W7	98	0	55.169
46:09.6	Device disconnected from charger	98	0	55.169
46:14.4	Power button pressed			
46:17.4	Device powered off using button	100	0	55.169
46:17.9	Power button released			
07:59.0	Audit log created		1.15.14	
07:59.1	Device powered on using button	100	0	55.169
08:01.1	Audio recording disabled due to video buffering default			
08:05.7	Power button pressed			
08:08.7	Device powered off using button	100	0	55.168
08:09.2	Power button released			
48:13.2	Device powered on using button	100	0	55.168
48:16.4	Audio recording disabled due to video buffering default			
07:58.0	Audit log created	97	0 1.15.14	55.167
07:58.0	Audit log created	90	0 1.15.14	55.166
07:58.0	Audit log created	84	0 1.15.14	55.165
07:58.1	Audit log created	78	0 1.15.14	55.163
07:58.1	Audit log created	72	0 1.15.14	55.162
09:00.1	Camera connected to Axon Dock X630020W7	73	0	55.162
09:00.1	Audit log created	72	0 1.15.14	55.162
09:00.1	Audit log rolled	72	0	55.162
09:00.2	Device connected to charger	72	0	55.162
09:00.0	Audit log created	97	0 1.15.14	55.161
09:00.0	Audit log created	100	0 1.15.14	55.161
09:00.0	Audit log created	100	0 1.15.14	55.162
09:00.0	Audit log created	100	0 1.15.14	55.165
09:00.0	Audit log created	100	0 1.15.14	55.165
09:00.0	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.164
09:00.1	Audit log created	100	0 1.15.14	55.163
09:00.1	Audit log created	100	0 1.15.14	55.163
09:00.1	Audit log created	100	0 1.15.14	55.162
09:00.1	Audit log created	100	0 1.15.14	55.162
09:00.1	Audit log created	100	0 1.15.14	55.162
49:01.9	Select button pressed			

49:02.3	Camera disconnected from Axon Dock X630020W7	99	0	55.162
49:02.6	Select button released			
49:03.2	Device disconnected from charger	99	0	55.164
09:00.1	Audit log created	97	0 1.15.14	55.163
09:00.2	Audit log created	89	0 1.15.14	55.161
09:00.2	Audit log created	82	0 1.15.14	55.16
21:46.6	Event button pressed			
21:46.8	Event button released			
22:54.2	Power button pressed			
22:57.2	Device powered off using button	80	0	55.159
22:57.7	Power button released			
26:10.2	Audit log created		1.15.14	
26:10.3	Device powered on using button	87	0	55.158
26:13.4	Audio recording disabled due to video buffering default			
26:37.7	Camera connected to Axon Dock X62001W9H	87	0	55.173
26:37.7	Audit log created	86	0 1.15.14	55.16
26:37.7	Audit log rolled	86	0	55.16
26:39.3	Device connected to charger	86	0	55.16
27:12.0	Date/Time synced to 07/26/2021 11:27:12.02 PM from 07/26/2021 11:27:07.73 PM			
27:29.4	Audit log successfully uploaded			
27:29.7	Audit log successfully uploaded and deleted from device	87	0	55.173
27:58.9	Audit log successfully uploaded			
27:59.1	Audit log successfully uploaded and deleted from device	87	0	55.173
28:23.4	Audit log successfully uploaded			
28:23.6	Audit log successfully uploaded and deleted from device	87	0	55.173
28:50.8	Audit log successfully uploaded			
28:51.0	Audit log successfully uploaded and deleted from device	87	0	55.173
29:03.1	Audit log successfully uploaded			
29:03.5	Audit log successfully uploaded and deleted from device	87	0	55.173
29:11.6	Audit log successfully uploaded			
29:11.9	Audit log successfully uploaded and deleted from device	88	0	55.173
29:40.1	Audit log successfully uploaded			
29:40.3	Audit log successfully uploaded and deleted from device	88	0	55.173
30:06.5	Audit log successfully uploaded			
30:06.7	Audit log successfully uploaded and deleted from device	88	0	55.173
30:25.8	Audit log successfully uploaded			
30:26.1	Audit log successfully uploaded and deleted from device	88	0	55.173
30:37.3	Audit log successfully uploaded			
30:37.5	Audit log successfully uploaded and deleted from device	88	0	55.173
30:39.6	Audit log successfully uploaded			
30:39.8	Audit log successfully uploaded and deleted from device	88	0	55.173
30:52.9	Audit log successfully uploaded			
30:53.2	Audit log successfully uploaded and deleted from device	89	0	55.173
30:58.3	Audit log successfully uploaded			
30:58.5	Audit log successfully uploaded and deleted from device	89	0	55.173
31:01.7	Audit log successfully uploaded			
31:01.9	Audit log successfully uploaded and deleted from device	89	0	55.173

31:11.1	Audit log successfully uploaded			
31:11.3	Audit log successfully uploaded and deleted from device	89	0	55.173
31:19.4	Audit log successfully uploaded			
31:19.6	Audit log successfully uploaded and deleted from device	89	0	55.173
31:40.8	Audit log successfully uploaded			
31:41.0	Audit log successfully uploaded and deleted from device	89	0	55.173
31:41.1	Audit log successfully uploaded			
31:41.3	Audit log successfully uploaded and deleted from device	89	0	55.173
31:56.5	Audit log successfully uploaded			
31:56.7	Audit log successfully uploaded and deleted from device	89	0	55.173
32:25.0	Audit log successfully uploaded			
32:25.2	Audit log successfully uploaded and deleted from device	89	0	55.173
32:27.4	Audit log successfully uploaded			
32:27.5	Audit log successfully uploaded and deleted from device	89	0	55.173
32:54.7	Audit log successfully uploaded			
32:54.9	Audit log successfully uploaded and deleted from device	89	0	55.173
33:11.3	Audit log successfully uploaded			
33:11.5	Audit log successfully uploaded and deleted from device	90	0	55.173
33:25.7	Audit log successfully uploaded			
33:25.9	Audit log successfully uploaded and deleted from device	90	0	55.173
33:46.1	Audit log successfully uploaded			
33:46.3	Audit log successfully uploaded and deleted from device	90	0	55.173
34:14.5	Audit log successfully uploaded			
34:14.7	Audit log successfully uploaded and deleted from device	90	0	55.173
34:42.9	Audit log successfully uploaded			
34:43.1	Audit log successfully uploaded and deleted from device	90	0	55.173
34:47.3	Audit log successfully uploaded			
34:47.6	Audit log successfully uploaded and deleted from device	90	0	55.173
35:02.8	Audit log successfully uploaded			
35:03.0	Audit log successfully uploaded and deleted from device	90	0	55.173
35:10.1	Audit log successfully uploaded			
35:10.4	Audit log successfully uploaded and deleted from device	90	0	55.173
35:35.5	Audit log successfully uploaded			
35:35.7	Audit log successfully uploaded and deleted from device	90	0	55.173
35:36.9	Audit log successfully uploaded			
35:37.1	Audit log successfully uploaded and deleted from device	90	0	55.173
35:39.2	Audit log successfully uploaded			
35:39.4	Audit log successfully uploaded and deleted from device	90	0	55.173
35:57.7	Audit log successfully uploaded			
35:57.9	Audit log successfully uploaded and deleted from device	91	0	55.173
36:27.1	Audit log successfully uploaded			
36:27.3	Audit log successfully uploaded and deleted from device	91	0	55.173
36:54.4	Audit log successfully uploaded			
36:54.6	Audit log successfully uploaded and deleted from device	91	0	55.173
36:56.7	Audit log successfully uploaded			
36:56.9	Audit log successfully uploaded and deleted from device	91	0	55.173
37:11.1	Audit log successfully uploaded			

37:11.3	Audit log successfully uploaded and deleted from device	91	0	55.173	
37:36.5	Audit log successfully uploaded				
37:36.7	Audit log successfully uploaded and deleted from device	92	0	55.173	
37:55.8	Audit log successfully uploaded				
37:56.0	Audit log successfully uploaded and deleted from device	92	0	55.173	
38:03.1	Audit log successfully uploaded				
38:03.3	Audit log successfully uploaded and deleted from device	92	0	55.173	
38:07.5	Audit log successfully uploaded				
38:07.6	Audit log successfully uploaded and deleted from device	92	0	55.173	
38:35.7	Audit log successfully uploaded				
38:35.9	Audit log successfully uploaded and deleted from device	92	0	55.173	
38:37.8	Event button pressed				
38:38.0	Event button released				
38:38.3	Device disconnected from charger	92	0	55.173	
38:38.3	Camera disconnected from Axon Dock X62001W9H	92	0	55.173	
38:50.2	Event button pressed				
38:50.3	Event button released				
38:50.4	Event button pressed				
38:50.5	Audio recording enabled due to video recording default				
38:50.5	Event button released				
38:50.7	Recording started due to button press	92	0	55.172	92a87b51f6bb4e249d09cf53a3ebbf1
38:53.7	Event button pressed				
38:56.7	Recording stopped due to button press	92	1	55.164	92a87b51f6bb4e249d09cf53a3ebbf1
38:57.3	Event button released				
38:57.4	Audio recording disabled due to video buffering default				
39:37.6	Axon application connected to device				
40:30.5	Title changed in video metadata from 'Axon Body 3 Video 2021-07-26 2338 X6033271L' to 'Test' using Axon applicator				92a87b51f6bb4e249d09cf53a3ebbf1
40:30.5	Categories 'Accidental Recording' added to video metadata using Axon applicator				92a87b51f6bb4e249d09cf53a3ebbf1
40:42.9	Camera connected to Axon Dock X62001W9H	92	0	55.173	
40:42.9	Audit log created	92	1 1.15.14	55.163	
40:42.9	Power button pressed				
40:42.9	Axon application disconnected from device				
40:42.9	Audit log rolled	92	1	55.163	
40:43.0	Power button released				
40:44.3	Device connected to charger	92	1	55.163	
41:08.6	Video upload started when camera was docked				92a87b51f6bb4e249d09cf53a3ebbf1
41:11.6	Video successfully uploaded from device when docked				92a87b51f6bb4e249d09cf53a3ebbf1
41:11.8	Video deleted from device when docked	92	0	55.173	92a87b51f6bb4e249d09cf53a3ebbf1
41:11.9	Audit log created	92	0 1.15.14	55.173	
41:11.9	Audit log rolled	92	0	55.173	
41:11.9	Audit log rolled	92	0	55.173	
41:11.9	Audit log created	92	0 1.15.14	55.173	
41:13.0	Date/Time synced to 07/26/2021 11:41:13.01 PM from 07/26/2021 11:41:12.95 PM				
41:17.3	Audit log successfully uploaded				
41:17.5	Audit log successfully uploaded and deleted from device	92	0	55.173	
41:44.7	Audit log successfully uploaded				
41:44.9	Audit log successfully uploaded and deleted from device	92	0	55.173	

42:00.0	Audit log successfully uploaded				
42:00.2	Audit log successfully uploaded and deleted from device	92	0	55.173	
42:04.4	Audit log successfully uploaded				
42:04.6	Audit log successfully uploaded and deleted from device	92	0	55.173	
42:22.7	Audit log successfully uploaded				
42:22.8	Audit log successfully uploaded and deleted from device	92	0	55.173	
42:44.1	Audit log successfully uploaded				
42:44.3	Audit log successfully uploaded and deleted from device	92	0	55.173	
43:08.4	Audit log successfully uploaded				
43:08.7	Audit log successfully uploaded and deleted from device	92	0	55.173	
43:15.8	Audit log successfully uploaded				
43:16.0	Audit log successfully uploaded and deleted from device	92	0	55.173	
43:18.1	Audit log successfully uploaded				
43:18.3	Audit log successfully uploaded and deleted from device	92	0	55.173	
43:24.5	Audit log successfully uploaded				
43:24.7	Audit log successfully uploaded and deleted from device	92	0	55.173	
43:35.9	Audit log successfully uploaded				
43:36.1	Audit log successfully uploaded and deleted from device	93	0	55.173	
43:51.2	Audit log successfully uploaded				
43:51.3	Audit log successfully uploaded and deleted from device	93	0	55.173	
44:03.2	Audit log successfully uploaded				
44:03.4	Audit log successfully uploaded and deleted from device	93	0	55.173	
44:17.3	Camera disconnected from Axon Dock X62001W9H	93	0	55.173	
44:17.3	Device disconnected from charger	93	0	55.173	
54:47.8	Axon application connected to device				
55:08.6	Axon application disconnected from device				
41:11.0	Audit log created	86	0 1.15.14	55.171	
41:11.0	Audit log created	80	0 1.15.14	55.17	
57:33.7	Event button pressed				
57:33.9	Event button released				
57:34.0	Event button pressed				
57:34.0	Audio recording enabled due to video recording default				
57:34.1	Event button released				
57:34.2	Recording started due to button press	78	1	55.169	56ecda0a7f244776802f39cb049c2d11
03:39.4	Event button pressed				
03:42.4	Recording stopped due to button press	77	1	54.916	56ecda0a7f244776802f39cb049c2d11
03:42.9	Event button released				
03:43.3	Audio recording disabled due to video buffering default				
12:32.2	Axon application connected to device				
13:29.7	Title changed in video metadata from 'Axon Body 3 Video 2021-07-27 0157 X6033271L' to 'Sig. 31/70 X2 N7' using Axon applicator				56ecda0a7f244776802f39cb049c2d11
13:29.7	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator				56ecda0a7f244776802f39cb049c2d11
13:42.4	Axon application disconnected from device				
39:16.9	Volume up button pressed				
39:17.0	Volume up button released				
39:17.1	Volume changed to high from medium using button				
39:19.8	Camera connected to Axon Dock X62001V12	74	1	54.916	
39:19.9	Audit log created	74	1 1.15.14	54.914	

39:19.9 Audit log rolled	74	1	54.914
39:19.9 Select button pressed			
39:20.1 Select button released			
39:20.3 Device connected to charger	74	1	54.914
39:33.3 Video upload started when camera was docked			56ecda0a7f244776802f39cb049c2d11
39:45.5 Audit log successfully uploaded			
39:45.7 Audit log successfully uploaded and deleted from device	74	1	54.916
39:50.0 Date/Time synced to 07/27/2021 02:39:50.01 AM from 07/27/2021 02:39:49.85 AM			
39:51.6 Audit log successfully uploaded			
39:51.8 Audit log successfully uploaded and deleted from device	74	1	54.916
40:04.0 Audit log successfully uploaded			
40:04.2 Audit log successfully uploaded and deleted from device	74	1	54.916
40:08.3 Audit log successfully uploaded			
40:08.5 Audit log successfully uploaded and deleted from device	74	1	54.916
40:13.6 Audit log successfully uploaded			
40:13.8 Audit log successfully uploaded and deleted from device	74	1	54.916
40:30.9 Audit log successfully uploaded			
40:31.1 Audit log successfully uploaded and deleted from device	74	1	54.916
40:41.6 Video successfully uploaded from device when docked			56ecda0a7f244776802f39cb049c2d11
40:41.9 Video deleted from device when docked	75	0	55.169 56ecda0a7f244776802f39cb049c2d11
40:42.0 Audit log created	75	0 1.15.14	55.169
40:42.0 Audit log rolled	75	0	55.169
40:42.0 Audit log created	75	0 1.15.14	55.169
40:42.0 Audit log rolled	75	0	55.169
40:46.4 Camera disconnected from Axon Dock X62001V12	75	0	55.169
40:46.4 Device disconnected from charger	75	0	55.171
40:49.2 Volume up button pressed			
40:49.3 Volume up button released			
40:49.9 Volume changed to very high from high using button			
40:49.9 Volume up button pressed			
40:50.2 Volume up button released			
40:51.0 Volume down button pressed			
40:51.2 Volume down button released			
40:51.3 Volume changed to high from very high using button			
40:51.3 Volume down button pressed			
40:51.5 Volume down button released			
40:51.7 Volume changed to medium from high using button			
40:42.0 Audit log created	68	0 1.15.14	55.17
40:42.0 Audit log created	62	0 1.15.14	55.168
40:42.0 Audit log created	55	0 1.15.14	55.167
23:31.5 Volume up button pressed			
23:31.6 Volume up button released			
23:31.7 Volume changed to high from medium using button			
23:35.2 Volume down button pressed			
23:35.4 Volume down button released			
23:35.5 Volume changed to medium from high using button			
23:39.4 Camera connected to Axon Dock X630020W7	50	0	55.166

23:39.4	Audit log rolled	50	0	55.166
23:39.4	Audit log created	50	0 1.15.14	55.166
23:40.4	Device connected to charger	50	0	55.166
23:39.0	Audit log created	78	0 1.15.14	55.168
23:39.0	Audit log created	99	0 1.15.14	55.167
23:39.0	Audit log created	100	0 1.15.14	55.167
23:39.0	Audit log created	100	0 1.15.14	55.167
23:39.1	Audit log created	100	0 1.15.14	55.167
23:39.1	Audit log created	100	0 1.15.14	55.166
23:39.1	Audit log created	100	0 1.15.14	55.166
23:39.2	Audit log created	100	0 1.15.14	55.166
23:39.2	Audit log created	100	0 1.15.14	55.166
23:39.2	Audit log created	100	0 1.15.14	55.165
23:39.2	Audit log created	100	0 1.15.14	55.165
31:46.4	Device disconnected from charger	98	0	55.165
31:46.4	Camera disconnected from Axon Dock X630020W7	98	0	55.165
31:49.4	Camera connected to Axon Dock X630020W7	100	0	55.167
31:49.5	Audit log rolled	100	0	55.167
31:49.5	Audit log created	100	0 1.15.14	55.167
31:50.4	Device connected to charger	100	0	55.167
36:34.4	Device disconnected from charger	100	0	55.167
36:34.5	Camera disconnected from Axon Dock X630020W7	100	0	55.167
31:49.0	Audit log created	93	0 1.15.14	55.166
57:34.1	Power button pressed			
57:37.1	Device powered off using button	90	0	55.165
57:37.5	Power button released			
26:19.0	Audit log created		1.15.14	
26:19.1	Device powered on using button	90	0	55.165
26:21.0	Audio recording disabled due to video buffering default			
35:56.1	Event button pressed			
35:56.3	Event button released			
35:56.3	Event button pressed			
35:56.4	Audio recording enabled due to video recording default			
35:56.5	Event button released			
35:56.6	Recording started due to button press	90	1	55.165 64a99ac617eb4e129e37cde7941afd1d
45:37.0	Event button pressed			
45:40.0	Recording stopped due to button press	88	1	54.799 64a99ac617eb4e129e37cde7941afd1d
45:40.6	Event button released			
45:40.8	Audio recording disabled due to video buffering default			
26:19.0	Audit log created	84	1 1.15.14	54.796
34:50.0	Axon application connected to device			
36:12.8	Title changed in video metadata from 'Axon Body 3 Video 2021-07-27 2135 X6033271L' to 'Sig. 3 @ N5. CODE 22. False Alarm' using Axon applic			64a99ac617eb4e129e37cde7941afd1d
36:12.8	Categories 'Alarm' added to video metadata using Axon application			64a99ac617eb4e129e37cde7941afd1d
36:28.0	Axon application disconnected from device			
26:19.0	Audit log created	78	1 1.15.14	54.795
26:19.0	Audit log created	72	1 1.15.14	54.793
26:19.0	Audit log created	66	1 1.15.14	54.792

17:40.5	Event button pressed				
17:40.6	Event button released				
17:40.8	Event button pressed				
17:40.8	Audio recording enabled due to video recording default				
17:40.9	Event button released				
17:41.0	Recording started due to button press	61	2	54.791	d739913a98f949c183448a60ebd40f23
26:19.0	Audit log created	59	2 1.15.14	54.456	
32:03.0	Event button pressed				
32:06.0	Recording stopped due to button press	58	2	54.272	d739913a98f949c183448a60ebd40f23
32:06.8	Audio recording disabled due to video buffering default				
32:06.8	Event button released				
38:10.8	Event button pressed				
38:10.9	Event button released				
38:10.9	Event button pressed				
38:10.9	Audio recording enabled due to video recording default				
38:11.0	Event button released				
38:11.1	Recording started due to button press	57	3	54.27	cc2a4bc120654632a97d74d5cc7eab12
43:59.3	Event button pressed				
44:02.3	Recording stopped due to button press	56	3	54.023	cc2a4bc120654632a97d74d5cc7eab12
44:02.7	Event button released				
44:03.1	Audio recording disabled due to video buffering default				
26:19.1	Audit log created	51	3 1.15.14	54.021	
34:33.1	Axon application connected to device				
35:32.5	Title changed in video metadata from 'Axon Body 3 Video 2021-07-28 0217 X6033271L' to 'Sig. 31/70 X8 N2' using Axon applicator				d739913a98f949c183448a60ebd40f23
35:32.5	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator				d739913a98f949c183448a60ebd40f23
36:16.1	Title changed in video metadata from 'Axon Body 3 Video 2021-07-28 0238 X6033271L' to 'Sig.31/70 X2 N3' using Axon applicator				cc2a4bc120654632a97d74d5cc7eab12
36:16.1	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator				cc2a4bc120654632a97d74d5cc7eab12
36:23.9	Axon application disconnected from device				
38:24.6	Camera connected to Axon Dock X62001V12	50	3	54.034	
38:24.9	Audit log rolled	49	3	54.021	
38:24.9	Audit log created	49	3 1.15.14	54.021	
38:25.1	Device connected to charger	49	3	54.021	
38:49.9	Video upload started when camera was docked				64a99ac617eb4e129e37cde7941afd1d
38:51.2	Audit log successfully uploaded				
38:51.4	Audit log successfully uploaded and deleted from device	50	3	54.034	
38:55.0	Date/Time synced to 07/28/2021 03:38:55.02 AM from 07/28/2021 03:38:54.91 AM				
39:15.9	Audit log successfully uploaded				
39:16.1	Audit log successfully uploaded and deleted from device	50	3	54.034	
39:45.2	Audit log successfully uploaded				
39:45.3	Audit log successfully uploaded and deleted from device	50	3	54.034	
40:02.2	Audit log successfully uploaded				
40:02.4	Audit log successfully uploaded and deleted from device	50	3	54.034	
40:07.5	Audit log successfully uploaded				
40:07.7	Audit log successfully uploaded and deleted from device	50	3	54.034	
40:07.9	Audit log successfully uploaded				
40:08.0	Audit log successfully uploaded and deleted from device	50	3	54.034	
40:17.2	Audit log successfully uploaded				

40:17.4	Audit log successfully uploaded and deleted from device	50	3	54.034
40:32.6	Video successfully uploaded from device when dockec			64a99ac617eb4e129e37cde7941afd1d
40:32.9	Video deleted from device when docked	50	2	54.399 64a99ac617eb4e129e37cde7941afd1d
40:33.0	Audit log created	50	2 1.15.14	54.399
40:33.0	Audit log rolled	50	2	54.399
40:33.2	Video upload started when camera was docked			d739913a98f949c183448a60ebd40f23
40:44.5	Audit log successfully uploaded			
40:44.7	Audit log successfully uploaded and deleted from device	51	2	54.399
41:09.9	Audit log successfully uploaded			
41:10.1	Audit log successfully uploaded and deleted from device	51	2	54.399
41:15.2	Audit log successfully uploaded			
41:15.4	Audit log successfully uploaded and deleted from device	51	2	54.399
41:22.5	Audit log successfully uploaded			
41:22.7	Audit log successfully uploaded and deleted from device	51	2	54.399
41:43.8	Audit log successfully uploaded			
41:43.9	Audit log successfully uploaded and deleted from device	51	2	54.399
42:03.6	Audit log successfully uploaded			
42:03.8	Audit log successfully uploaded and deleted from device	51	2	54.399
42:28.9	Audit log successfully uploaded			
42:29.1	Audit log successfully uploaded and deleted from device	51	2	54.399
42:40.2	Audit log successfully uploaded			
42:40.4	Audit log successfully uploaded and deleted from device	51	2	54.399
42:51.7	Video successfully uploaded from device when dockec			d739913a98f949c183448a60ebd40f23
42:52.1	Video deleted from device when docked	51	1	54.913 d739913a98f949c183448a60ebd40f23
42:52.2	Audit log created	51	1 1.15.14	54.913
42:52.2	Audit log rolled	51	1	54.913
42:52.4	Video upload started when camera was docked			cc2a4bc120654632a97d74d5cc7eab12
43:09.6	Audit log successfully uploaded			
43:09.8	Audit log successfully uploaded and deleted from device	51	1	54.913
43:35.9	Audit log successfully uploaded			
43:36.1	Audit log successfully uploaded and deleted from device	52	1	54.913
43:53.3	Audit log successfully uploaded			
43:53.5	Audit log successfully uploaded and deleted from device	52	1	54.913
43:56.0	Video successfully uploaded from device when dockec			cc2a4bc120654632a97d74d5cc7eab12
43:56.3	Video deleted from device when docked	52	0	55.158 cc2a4bc120654632a97d74d5cc7eab12
43:56.4	Audit log rolled	52	0	55.159
43:56.4	Audit log created	52	0 1.15.14	55.159
43:56.4	Audit log created	52	0 1.15.14	55.159
43:56.4	Audit log rolled	52	0	55.159
44:15.7	Audit log successfully uploaded			
44:15.9	Audit log successfully uploaded and deleted from device	52	0	55.159
44:42.0	Audit log successfully uploaded			
44:42.2	Audit log successfully uploaded and deleted from device	52	0	55.159
44:44.9	Camera disconnected from Axon Dock X62001V12	52	0	55.158
44:44.9	Device disconnected from charger	52	0	55.158
44:46.3	Volume up button pressed			
44:46.5	Volume up button released			

44:47.1	Volume changed to high from medium using button			
44:48.2	Volume down button pressed			
44:48.4	Volume down button released			
44:48.5	Volume changed to medium from high using button			
43:56.1	Audit log created	46	0 1.15.14	55.162
43:56.1	Audit log created	40	0 1.15.14	55.16
21:11.5	Volume up button pressed			
21:11.5	Volume up button released			
21:11.6	Volume changed to high from medium using button			
21:13.6	Volume down button pressed			
21:13.8	Volume down button released			
21:13.9	Volume changed to medium from high using button			
21:20.2	Camera connected to Axon Dock X630020W7	37	0	55.163
21:20.2	Audit log rolled	37	0	55.159
21:20.2	Audit log created	37	0 1.15.14	55.163
21:20.8	Device connected to charger	37	0	55.163
21:20.0	Audit log created	65	0 1.15.14	55.162
21:20.0	Audit log created	91	0 1.15.14	55.162
21:20.1	Audit log created	100	0 1.15.14	55.161
21:20.1	Audit log created	100	0 1.15.14	55.161
21:20.1	Audit log created	100	0 1.15.14	55.161
21:20.1	Audit log created	100	0 1.15.14	55.161
21:20.1	Audit log created	100	0 1.15.14	55.16
21:20.1	Audit log created	100	0 1.15.14	55.16
21:20.2	Audit log created	100	0 1.15.14	55.16
21:20.2	Audit log created	100	0 1.15.14	55.16
21:20.2	Audit log created	100	0 1.15.14	55.159
21:20.2	Audit log created	100	0 1.15.14	55.159
21:20.2	Audit log created	100	0 1.15.14	55.159
21:20.2	Audit log created	100	0 1.15.14	55.159
21:20.2	Audit log created	100	0 1.15.14	55.158
21:20.3	Audit log created	100	0 1.15.14	55.159
50:45.8	Camera disconnected from Axon Dock X630020W7	100	0	55.159
50:45.8	Device disconnected from charger	100	0	55.16
21:20.3	Audit log created	96	0 1.15.14	55.16
21:20.3	Audit log created	90	0 1.15.14	55.158
21:20.4	Audit log created	84	0 1.15.14	55.157
21:20.4	Audit log created	78	0 1.15.14	55.155
58:14.1	Power button pressed			
58:17.3	Device powered off using button	75	0	55.154
58:17.7	Power button released			
42:29.0	Audit log created		1.15.14	
42:29.1	Device powered on using button	74	0	55.156
42:31.1	Audio recording disabled due to video buffering default			
57:14.2	Power button pressed			
57:17.2	Device powered off using button	73	0	55.156
57:17.6	Power button released			

13:35.1 Camera connected to Axon Dock X630020W7	73	0	55.156
13:35.1 Device powered on due to charger connection	73	0	55.156
13:36.1 Camera connected to Axon Dock X630020W7	74	0	55.156
13:38.1 Audit log rolled	73	0	55.157
13:38.1 Audit log created	73	0 1.15.14	55.157
13:38.0 Audit log created	98	0 1.15.14	55.156
13:38.0 Audit log created	100	0 1.15.14	55.156
13:38.0 Audit log created	100	0 1.15.14	55.155
13:38.0 Audit log created	100	0 1.15.14	55.155
13:38.1 Audit log created	100	0 1.15.14	55.155
13:38.1 Audit log created	100	0 1.15.14	55.155
13:38.1 Audit log created	100	0 1.15.14	55.154
13:38.1 Audit log created	100	0 1.15.14	55.154
13:38.1 Audit log created	100	0 1.15.14	55.154
23:12.1 Device disconnected from charger	100	0	55.154
23:12.1 Camera disconnected from Axon Dock X630020W7	100	0	55.154
23:12.2 Audio recording disabled due to video buffering default			
23:35.3 Power button pressed			
23:38.3 Device powered off using button	100	0	55.154
23:38.6 Power button released			
05:53.9 Audit log created		1.15.14	
05:54.1 Device powered on using button	100	0	55.153
05:56.1 Audio recording disabled due to video buffering default			
05:54.0 Audit log created	92	0 1.15.14	55.152
05:54.0 Audit log created	86	0 1.15.14	55.15
05:54.0 Audit log created	80	0 1.15.14	55.149
05:54.0 Audit log created	75	0 1.15.14	55.148
05:54.0 Audit log created	69	0 1.15.14	55.146
57:58.6 Event button pressed			
57:58.6 Event button released			
57:58.7 Event button pressed			
57:58.7 Audio recording enabled due to video recording default			
57:58.8 Event button released			
57:58.9 Recording started due to button press	63	1	55.145 2a595bdf65134232ae57878808db7654
05:54.0 Audit log created	62	1 1.15.14	54.833
08:04.8 Event button pressed			
08:07.9 Recording stopped due to button press	61	1	54.762 2a595bdf65134232ae57878808db7654
08:08.6 Event button released			
08:08.7 Audio recording disabled due to video buffering default			
21:42.3 Event button pressed			
21:42.4 Event button released			
21:42.5 Event button pressed			
21:42.5 Audio recording enabled due to video recording default			
21:42.6 Event button released			
21:42.7 Recording started due to button press	60	2	54.76 28beeb24f41446fc97309a450e190a8c
24:12.1 Event button pressed			
24:15.1 Recording stopped due to button press	59	2	54.619 28beeb24f41446fc97309a450e190a8c

24:15.8	Event button released			
24:16.0	Audio recording disabled due to video buffering default			
59:51.5	Axon application connected to device			
00:16.4	Axon application connected to device			
01:05.1	Title changed in video metadata from 'Axon Body 3 Video 2021-07-30 0157 X6033271L' to 'Sig. 31/70 X7 N2' using Axon applicator			2a595bdf65134232ae57878808db7654
01:05.1	Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			2a595bdf65134232ae57878808db7654
02:27.9	Title changed in video metadata from 'Axon Body 3 Video 2021-07-30 0221 X6033271L' to 'Sig. 70 N4' using Axon applicator			28beeb24f41446fc97309a450e190a8c
02:27.9	Categories 'Loitering' added to video metadata using Axon applicator			28beeb24f41446fc97309a450e190a8c
02:50.6	Axon application disconnected from device			
05:15.4	Camera connected to Axon Dock X62001V12	55	2	54.633
05:15.4	Audit log rolled	54	2	54.617
05:15.4	Audit log created	54	2 1.15.14	54.617
05:17.0	Device connected to charger	54	2	54.617
05:33.5	Video upload started when camera was docked			2a595bdf65134232ae57878808db7654
05:40.5	Audit log successfully uploaded			
05:40.7	Audit log successfully uploaded and deleted from device	55	2	54.634
05:47.0	Date/Time synced to 07/30/2021 03:05:47.01 AM from 07/30/2021 03:05:45.45 AM			
05:48.2	Audit log successfully uploaded			
05:48.4	Audit log successfully uploaded and deleted from device	55	2	54.633
06:04.9	Audit log successfully uploaded			
06:05.1	Audit log successfully uploaded and deleted from device	55	2	54.633
06:08.2	Audit log successfully uploaded			
06:08.4	Audit log successfully uploaded and deleted from device	55	2	54.633
06:28.5	Audit log successfully uploaded			
06:28.7	Audit log successfully uploaded and deleted from device	55	2	54.633
06:31.9	Audit log successfully uploaded			
06:32.0	Audit log successfully uploaded and deleted from device	55	2	54.633
06:48.2	Audit log successfully uploaded			
06:48.3	Audit log successfully uploaded and deleted from device	55	2	54.633
06:50.5	Audit log successfully uploaded			
06:50.7	Audit log successfully uploaded and deleted from device	55	2	54.633
07:03.9	Audit log successfully uploaded			
07:04.1	Audit log successfully uploaded and deleted from device	55	2	54.633
07:22.3	Audit log successfully uploaded			
07:22.5	Audit log successfully uploaded and deleted from device	56	2	54.633
07:25.3	Video successfully uploaded from device when docked			2a595bdf65134232ae57878808db7654
07:25.7	Video deleted from device when docked	56	1	55.013 2a595bdf65134232ae57878808db7654
07:25.8	Audit log rolled	56	1	55.014
07:25.8	Audit log created	56	1 1.15.14	55.014
07:26.0	Video upload started when camera was docked			28beeb24f41446fc97309a450e190a8c
07:36.7	Audit log successfully uploaded			
07:36.9	Audit log successfully uploaded and deleted from device	56	1	55.014
07:38.0	Audit log successfully uploaded			
07:38.1	Audit log successfully uploaded and deleted from device	56	1	55.014
08:02.3	Audit log successfully uploaded			
08:02.4	Video successfully uploaded from device when docked			28beeb24f41446fc97309a450e190a8c
08:02.5	Audit log successfully uploaded and deleted from device	56	1	55.013

08:02.7 Video deleted from device when docked	56	0	55.154 28beeb24f41446fc97309a450e190a8c
08:02.8 Audit log rolled	56	0	55.154
08:02.8 Audit log created	56	0 1.15.14	55.154
08:02.8 Audit log rolled	56	0	55.154
08:02.8 Audit log created	56	0 1.15.14	55.154
08:10.6 Audit log successfully uploaded			
08:10.8 Audit log successfully uploaded and deleted from device	56	0	55.154
08:17.0 Audit log successfully uploaded			
08:17.2 Audit log successfully uploaded and deleted from device	56	0	55.154
08:37.1 Volume up button pressed			
08:37.4 Device disconnected from charger	56	0	55.154
08:37.5 Volume up button released			
08:37.8 Camera disconnected from Axon Dock X62001V12	56	0	55.159
08:40.8 Camera connected to Axon Dock X62001V12	56	0	55.159
08:40.8 Audit log rolled	56	0	55.159
08:40.8 Audit log created	56	0 1.15.14	55.159
08:41.4 Device connected to charger	56	0	55.159
09:11.0 Date/Time synced to 07/30/2021 03:09:11.01 AM from 07/30/2021 03:09:10.77 AM			
13:16.5 Device disconnected from charger	58	0	55.159
13:16.5 Camera disconnected from Axon Dock X62001V12	58	0	55.159
13:21.9 Camera connected to Axon Dock X62001V12	58	0	55.159
13:22.0 Audit log created	58	0 1.15.14	55.159
13:22.0 Audit log rolled	58	0	55.159
13:22.5 Device connected to charger	58	0	55.159
13:52.0 Date/Time synced to 07/30/2021 03:13:52.01 AM from 07/30/2021 03:13:51.97 AM			
14:03.5 Audit log successfully uploaded			
14:03.7 Audit log successfully uploaded and deleted from device	58	0	55.159
14:31.1 Audit log successfully uploaded			
14:31.3 Audit log successfully uploaded and deleted from device	59	0	55.159
14:32.4 Audit log successfully uploaded			
14:32.6 Audit log successfully uploaded and deleted from device	59	0	55.159
14:55.8 Audit log successfully uploaded			
14:56.0 Audit log successfully uploaded and deleted from device	59	0	55.159
15:08.5 Audit log successfully uploaded			
15:08.7 Audit log successfully uploaded and deleted from device	59	0	55.159
15:13.8 Audit log successfully uploaded			
15:14.0 Audit log successfully uploaded and deleted from device	59	0	55.159
15:24.2 Audit log successfully uploaded			
15:24.4 Audit log successfully uploaded and deleted from device	59	0	55.159
15:37.6 Audit log successfully uploaded			
15:37.7 Audit log successfully uploaded and deleted from device	59	0	55.159
15:43.8 Audit log successfully uploaded			
15:44.0 Audit log successfully uploaded and deleted from device	59	0	55.159
16:07.2 Audit log successfully uploaded			
16:07.4 Audit log successfully uploaded and deleted from device	59	0	55.159
16:24.6 Audit log successfully uploaded			
16:24.8 Audit log successfully uploaded and deleted from device	59	0	55.159

16:35.0	Audit log successfully uploaded			
16:35.1	Audit log successfully uploaded and deleted from device	60	0	55.159
16:58.3	Audit log successfully uploaded			
16:58.4	Audit log successfully uploaded and deleted from device	60	0	55.159
17:04.6	Audit log successfully uploaded			
17:04.7	Audit log successfully uploaded and deleted from device	60	0	55.159
17:12.8	Audit log successfully uploaded			
17:13.0	Audit log successfully uploaded and deleted from device	60	0	55.159
17:34.2	Audit log successfully uploaded			
17:34.5	Audit log successfully uploaded and deleted from device	60	0	55.159
17:48.1	Audit log successfully uploaded			
17:48.3	Audit log successfully uploaded and deleted from device	60	0	55.159
17:53.4	Device disconnected from charger	60	0	55.159
17:54.0	Camera disconnected from Axon Dock X62001V12	60	0	55.159
17:56.0	Camera connected to Axon Dock X62001V12	61	0	55.159
17:56.0	Audit log created	60	0 1.15.14	55.159
17:56.0	Audit log rolled	60	0	55.159
17:56.4	Device connected to charger	60	0	55.159
18:26.0	Date/Time synced to 07/30/2021 03:18:26.01 AM from 07/30/2021 03:18:25.98 AM			
18:47.1	Audit log successfully uploaded			
18:47.3	Audit log successfully uploaded and deleted from device	61	0	55.159
19:02.5	Audit log successfully uploaded			
19:02.7	Audit log successfully uploaded and deleted from device	61	0	55.159
19:13.8	Audit log successfully uploaded			
19:14.1	Audit log successfully uploaded and deleted from device	61	0	55.159
19:27.2	Audit log successfully uploaded			
19:27.4	Audit log successfully uploaded and deleted from device	61	0	55.159
19:36.4	Camera disconnected from Axon Dock X62001V12	61	0	55.159
19:37.4	Device disconnected from charger	61	0	55.159
19:48.6	Volume up button pressed			
19:48.8	Volume up button released			
19:48.9	Volume changed to high from medium using button			
19:51.6	Volume down button pressed			
19:51.9	Volume down button released			
19:52.0	Volume changed to medium from high using button			
20:05.5	Axon application connected to device			
20:15.3	Axon application disconnected from device			
17:54.9	Audit log created	55	0 1.15.14	55.157
17:54.9	Audit log created	48	0 1.15.14	55.156
17:54.9	Audit log created	42	0 1.15.14	55.155
26:04.3	Power button pressed			
26:07.3	Device powered off using button	41	0	55.154
26:07.7	Power button released			
28:24.0	Device powered on due to charger connection	41	0	55.154
28:24.2	Device connected to charger			
28:24.2	Camera connected to Axon Dock X630020W7	41	0	55.154
28:24.3	Audit log created		1.15.14	

28:24.3	Audit log rolled			
28:25.0	Camera connected to Axon Dock X630020W7	42	0	55.154
28:26.9	Audit log created	41	0 1.15.14	55.154
28:26.9	Audit log rolled	41	0	55.154
28:26.0	Audit log created	70	0 1.15.14	55.155
28:26.0	Audit log created	96	0 1.15.14	55.155
28:26.0	Audit log created	100	0 1.15.14	55.154
28:26.1	Audit log created	100	0 1.15.14	55.156
28:26.1	Audit log created	100	0 1.15.14	55.156
28:26.1	Audit log created	100	0 1.15.14	55.157
28:26.1	Audit log created	100	0 1.15.14	55.157
28:26.1	Audit log created	100	0 1.15.14	55.157
28:26.1	Audit log created	100	0 1.15.14	55.156
28:26.2	Audit log created	100	0 1.15.14	55.156
04:25.0	Device disconnected from charger	100	0	55.156
04:25.0	Camera disconnected from Axon Dock X630020W7	100	0	55.156
04:25.1	Audio recording disabled due to video buffering default			
04:36.9	Power button pressed			
04:39.9	Device powered off using button	100	0	55.158
04:40.4	Power button released			
29:15.2	Audit log created		1.15.14	
29:15.3	Device powered on using button	96	0	55.157
29:18.4	Audio recording disabled due to video buffering default			
29:15.3	Audit log created	89	0 1.15.14	55.156
29:15.3	Audit log created	84	0 1.15.14	55.154
35:08.4	Power button pressed			
35:11.5	Device powered off using button	83	0	55.154
35:11.8	Power button released			
44:00.0	Device powered on due to charger connection	83	0	55.153
44:00.2	Device connected to charger			
44:00.2	Camera connected to Axon Dock X630020W7	83	0	55.153
44:00.3	Audit log created		1.15.14	
44:00.3	Audit log rolled			
44:00.9	Camera connected to Axon Dock X630020W7	84	0	55.153
44:02.9	Audit log created	83	0 1.15.14	55.153
44:02.9	Audit log rolled	83	0	55.153
44:02.0	Audit log created	100	0 1.15.14	55.153
44:02.0	Audit log created	100	0 1.15.14	55.152
44:02.0	Audit log created	100	0 1.15.14	55.152
44:02.1	Audit log created	100	0 1.15.14	55.152
44:02.1	Audit log created	100	0 1.15.14	55.154
44:02.1	Audit log created	100	0 1.15.14	55.159
44:02.1	Audit log created	100	0 1.15.14	55.159
44:02.1	Audit log created	100	0 1.15.14	55.159
44:02.1	Audit log created	100	0 1.15.14	55.159
44:02.1	Audit log created	100	0 1.15.14	55.158

44:02.2	Audit log created	100	0 1.15.14	55.159
42:06.0	Device disconnected from charger	98	0	55.159
42:06.0	Camera disconnected from Axon Dock X630020W7	98	0	55.159
42:06.1	Audio recording disabled due to video buffering default			
42:23.8	Power button pressed			
42:26.8	Device powered off using button	100	0	55.16
42:27.2	Power button released			
13:49.0	Audit log created		1.15.14	
13:49.1	Device powered on using button	100	0	55.159
13:51.1	Audio recording disabled due to video buffering default			
13:49.0	Audit log created	92	0 1.15.14	55.158
13:49.0	Audit log created	86	0 1.15.14	55.157
13:49.0	Audit log created	80	0 1.15.14	55.155
13:49.0	Audit log created	74	0 1.15.14	55.154
13:49.1	Audit log created	68	0 1.15.14	55.153
02:38.4	Power button pressed			
02:41.4	Device powered off using button	63	0	55.152
02:42.1	Power button released			
55:44.9	Audit log created		1.15.14	
55:45.0	Device powered on using button	63	0	55.154
55:46.9	Audio recording disabled due to video buffering default			
55:57.5	Audio recording disabled due to video buffering default			
56:07.3	Audio recording disabled due to video buffering default			
56:19.1	Audio recording disabled due to video buffering default			
56:22.6	Device restarting due to device error	63	0	55.153
56:28.3	Device restarting due to device error	63	0	55.153
57:01.1	Device restarted due to device error	63	0	55.152
57:03.1	Audio recording disabled due to video buffering default			
16:12.4	Power button pressed			
16:15.4	Device powered off using button	61	0	55.152
16:15.9	Power button released			
17:51.1	Device powered on using button	61	0	55.151
17:53.0	Audio recording disabled due to video buffering default			
55:44.0	Audit log created	56	0 1.15.14	55.15
09:36.4	Camera connected to Axon Dock X630020W7	54	0	55.15
09:36.5	Audit log created	54	0 1.15.14	55.15
09:36.5	Audit log rolled	54	0	55.15
09:37.1	Device connected to charger	54	0	55.15
09:36.0	Audit log created	83	0 1.15.14	55.15
09:36.0	Audit log created	100	0 1.15.14	55.149
09:36.0	Audit log created	100	0 1.15.14	55.148
09:36.1	Audit log created	100	0 1.15.14	55.148
09:36.1	Audit log created	100	0 1.15.14	55.148
09:36.1	Audit log created	100	0 1.15.14	55.148
09:36.1	Audit log created	100	0 1.15.14	55.147
59:13.0	Device disconnected from charger	98	0	55.147
59:13.1	Camera disconnected from Axon Dock X630020W7	98	0	55.147

59:25.0	Power button pressed			
59:28.0	Device powered off using button	100	0	55.147
59:28.4	Power button released			
09:34.0	Audit log created		1.15.14	
09:34.1	Device powered on using button	100	0	55.147
09:36.2	Audio recording disabled due to video buffering default			
51:15.1	Camera connected to Axon Dock X62001V12	94	0	55.163
51:15.1	Audit log created	94	0 1.15.14	55.145
51:15.1	Audit log rolled	94	0	55.145
51:16.1	Device connected to charger	94	0	55.146
51:58.0	Date/Time synced to 08/17/2021 08:51:58.01 PM from 08/17/2021 08:51:45.10 PM			
51:58.4	Audit log successfully uploaded			
51:58.6	Audit log successfully uploaded and deleted from device	94	0	55.163
52:04.8	Audit log successfully uploaded			
52:05.0	Audit log successfully uploaded and deleted from device	94	0	55.163
52:45.1	Audit log successfully uploaded			
52:45.3	Audit log successfully uploaded and deleted from device	95	0	55.163
53:12.5	Audit log successfully uploaded			
53:12.7	Audit log successfully uploaded and deleted from device	95	0	55.163
53:38.9	Audit log successfully uploaded			
53:39.0	Audit log successfully uploaded and deleted from device	95	0	55.163
54:06.4	Audit log successfully uploaded			
54:06.6	Audit log successfully uploaded and deleted from device	95	0	55.163
54:13.7	Audit log successfully uploaded			
54:13.9	Audit log successfully uploaded and deleted from device	95	0	55.163
54:35.0	Audit log successfully uploaded			
54:35.2	Audit log successfully uploaded and deleted from device	95	0	55.163
54:47.3	Audit log successfully uploaded			
54:47.5	Audit log successfully uploaded and deleted from device	95	0	55.163
54:56.7	Audit log successfully uploaded			
54:56.8	Audit log successfully uploaded and deleted from device	95	0	55.163
55:12.0	Audit log successfully uploaded			
55:12.2	Audit log successfully uploaded and deleted from device	96	0	55.163
55:39.4	Audit log successfully uploaded			
55:39.6	Audit log successfully uploaded and deleted from device	96	0	55.163
55:41.8	Audit log successfully uploaded			
55:42.0	Audit log successfully uploaded and deleted from device	96	0	55.163
55:42.1	Audit log successfully uploaded			
55:42.3	Audit log successfully uploaded and deleted from device	96	0	55.163
56:09.5	Audit log successfully uploaded			
56:09.7	Audit log successfully uploaded and deleted from device	96	0	55.163
56:17.9	Audit log successfully uploaded			
56:18.0	Audit log successfully uploaded and deleted from device	96	0	55.163
56:42.2	Audit log successfully uploaded			
56:42.4	Audit log successfully uploaded and deleted from device	96	0	55.163
57:03.8	Audit log successfully uploaded			
57:04.0	Audit log successfully uploaded and deleted from device	96	0	55.163

57:18.3	Audit log successfully uploaded			
57:18.5	Audit log successfully uploaded and deleted from device	96	0	55.163
57:28.6	Audit log successfully uploaded			
57:28.8	Audit log successfully uploaded and deleted from device	96	0	55.163
57:37.1	Audit log successfully uploaded			
57:37.2	Audit log successfully uploaded and deleted from device	96	0	55.163
57:52.4	Audit log successfully uploaded			
57:52.6	Audit log successfully uploaded and deleted from device	96	0	55.163
58:07.8	Audit log successfully uploaded			
58:07.9	Audit log successfully uploaded and deleted from device	96	0	55.163
58:11.1	Audit log successfully uploaded			
58:11.3	Audit log successfully uploaded and deleted from device	96	0	55.163
58:27.5	Audit log successfully uploaded			
58:27.7	Audit log successfully uploaded and deleted from device	96	0	55.163
58:41.9	Audit log successfully uploaded			
58:42.1	Audit log successfully uploaded and deleted from device	96	0	55.163
58:42.2	Audit log successfully uploaded			
58:42.4	Audit log successfully uploaded and deleted from device	96	0	55.163
58:49.6	Audit log successfully uploaded			
58:49.8	Audit log successfully uploaded and deleted from device	96	0	55.163
59:16.0	Audit log successfully uploaded			
59:16.2	Audit log successfully uploaded and deleted from device	96	0	55.163
59:34.3	Audit log successfully uploaded			
59:34.5	Audit log successfully uploaded and deleted from device	96	0	55.163
59:39.7	Audit log successfully uploaded			
59:39.9	Audit log successfully uploaded and deleted from device	96	0	55.163
00:00.1	Audit log successfully uploaded			
00:00.2	Audit log successfully uploaded and deleted from device	97	0	55.163
00:06.4	Audit log successfully uploaded			
00:06.6	Audit log successfully uploaded and deleted from device	97	0	55.163
00:13.7	Audit log successfully uploaded			
00:13.9	Audit log successfully uploaded and deleted from device	97	0	55.163
00:42.1	Audit log successfully uploaded			
00:42.3	Audit log successfully uploaded and deleted from device	97	0	55.163
01:09.5	Audit log successfully uploaded			
01:09.7	Audit log successfully uploaded and deleted from device	97	0	55.163
01:38.8	Audit log successfully uploaded			
01:39.0	Audit log successfully uploaded and deleted from device	97	0	55.163
02:07.3	Audit log successfully uploaded			
02:07.5	Audit log successfully uploaded and deleted from device	97	0	55.163
02:29.8	Audit log successfully uploaded			
02:30.0	Audit log successfully uploaded and deleted from device	97	0	55.163
02:32.1	Audit log successfully uploaded			
02:32.3	Audit log successfully uploaded and deleted from device	97	0	55.163
02:57.5	Audit log successfully uploaded			
02:57.7	Audit log successfully uploaded and deleted from device	97	0	55.163
02:57.9	Audit log successfully uploaded			

02:58.1 Audit log successfully uploaded and deleted from device	97	0	55.163
03:14.3 Audit log successfully uploaded			
03:14.5 Audit log successfully uploaded and deleted from device	97	0	55.163
03:21.7 Audit log successfully uploaded			
03:21.9 Audit log successfully uploaded and deleted from device	97	0	55.163
03:40.0 Audit log successfully uploaded			
03:40.2 Audit log successfully uploaded and deleted from device	97	0	55.163
03:44.4 Audit log successfully uploaded			
03:44.6 Audit log successfully uploaded and deleted from device	97	0	55.163
04:13.7 Audit log successfully uploaded			
04:13.9 Audit log successfully uploaded and deleted from device	97	0	55.163
04:42.1 Audit log successfully uploaded			
04:42.2 Audit log successfully uploaded and deleted from device	97	0	55.163
04:56.5 Audit log successfully uploaded			
04:56.7 Audit log successfully uploaded and deleted from device	97	0	55.163
05:11.8 Audit log successfully uploaded			
05:12.0 Audit log successfully uploaded and deleted from device	97	0	55.163
05:35.1 Audit log successfully uploaded			
05:35.3 Audit log successfully uploaded and deleted from device	97	0	55.163
05:56.5 Audit log successfully uploaded			
05:56.7 Audit log successfully uploaded and deleted from device	97	0	55.163
06:06.0 Audit log successfully uploaded			
06:06.2 Audit log successfully uploaded and deleted from device	97	0	55.163
06:09.3 Audit log successfully uploaded			
06:09.5 Audit log successfully uploaded and deleted from device	97	0	55.163
06:11.7 Audit log successfully uploaded			
06:11.9 Audit log successfully uploaded and deleted from device	97	0	55.163
06:25.1 Audit log successfully uploaded			
06:25.3 Audit log successfully uploaded and deleted from device	97	0	55.163
06:40.5 Audit log successfully uploaded			
06:40.7 Audit log successfully uploaded and deleted from device	97	0	55.163
06:49.9 Audit log successfully uploaded			
06:50.1 Audit log successfully uploaded and deleted from device	97	0	55.163
07:11.3 Audit log successfully uploaded			
07:11.5 Audit log successfully uploaded and deleted from device	98	0	55.163
07:31.7 Audit log successfully uploaded			
07:31.9 Audit log successfully uploaded and deleted from device	98	0	55.163
07:37.0 Audit log successfully uploaded			
07:37.2 Audit log successfully uploaded and deleted from device	98	0	55.163
07:39.7 Audit log successfully uploaded			
07:39.9 Audit log successfully uploaded and deleted from device	98	0	55.163
07:45.0 Audit log successfully uploaded			
07:45.2 Audit log successfully uploaded and deleted from device	98	0	55.163
08:14.4 Audit log successfully uploaded			
08:14.6 Audit log successfully uploaded and deleted from device	98	0	55.163
08:26.8 Audit log successfully uploaded			
08:27.1 Audit log successfully uploaded and deleted from device	98	0	55.163

08:43.3	Audit log successfully uploaded			
08:43.5	Audit log successfully uploaded and deleted from device	98	0	55.163
09:08.7	Audit log successfully uploaded			
09:08.9	Audit log successfully uploaded and deleted from device	98	0	55.163
09:24.0	Audit log successfully uploaded			
09:24.2	Audit log successfully uploaded and deleted from device	98	0	55.163
09:42.3	Audit log successfully uploaded			
09:42.4	Audit log successfully uploaded and deleted from device	98	0	55.163
10:08.6	Audit log successfully uploaded			
10:08.8	Audit log successfully uploaded and deleted from device	98	0	55.163
10:37.0	Audit log successfully uploaded			
10:37.2	Audit log successfully uploaded and deleted from device	98	0	55.163
10:52.5	Audit log successfully uploaded			
10:52.7	Audit log successfully uploaded and deleted from device	98	0	55.163
10:56.8	Audit log successfully uploaded			
10:57.0	Audit log successfully uploaded and deleted from device	98	0	55.163
11:08.2	Audit log successfully uploaded			
11:08.5	Audit log successfully uploaded and deleted from device	98	0	55.163
11:28.6	Audit log successfully uploaded			
11:28.8	Audit log successfully uploaded and deleted from device	98	0	55.163
11:46.9	Audit log successfully uploaded			
11:47.1	Audit log successfully uploaded and deleted from device	98	0	55.163
12:04.2	Audit log successfully uploaded			
12:04.4	Audit log successfully uploaded and deleted from device	98	0	55.163
12:29.6	Audit log successfully uploaded			
12:29.8	Audit log successfully uploaded and deleted from device	98	0	55.163
12:58.9	Audit log successfully uploaded			
12:59.1	Audit log successfully uploaded and deleted from device	98	0	55.163
13:19.3	Audit log successfully uploaded			
13:19.5	Audit log successfully uploaded and deleted from device	99	0	55.163
13:39.7	Audit log successfully uploaded			
13:39.9	Audit log successfully uploaded and deleted from device	99	0	55.163
13:46.0	Audit log successfully uploaded			
13:46.2	Audit log successfully uploaded and deleted from device	99	0	55.163
14:08.4	Audit log successfully uploaded			
14:08.5	Audit log successfully uploaded and deleted from device	99	0	55.163
14:25.7	Audit log successfully uploaded			
14:25.9	Audit log successfully uploaded and deleted from device	99	0	55.163
14:53.1	Audit log successfully uploaded			
14:53.3	Audit log successfully uploaded and deleted from device	99	0	55.163
14:57.4	Audit log successfully uploaded			
14:57.6	Audit log successfully uploaded and deleted from device	99	0	55.163
15:20.8	Audit log successfully uploaded			
15:21.0	Audit log successfully uploaded and deleted from device	99	0	55.163
15:36.2	Audit log successfully uploaded			
15:36.4	Audit log successfully uploaded and deleted from device	99	0	55.163
15:52.6	Audit log successfully uploaded			

15:52.7	Audit log successfully uploaded and deleted from device	99	0	55.163
15:55.9	Audit log successfully uploaded			
15:56.1	Audit log successfully uploaded and deleted from device	99	0	55.163
16:18.3	Audit log successfully uploaded			
16:18.4	Audit log successfully uploaded and deleted from device	99	0	55.163
16:39.6	Audit log successfully uploaded			
16:39.8	Audit log successfully uploaded and deleted from device	99	0	55.163
16:55.9	Audit log successfully uploaded			
16:56.1	Audit log successfully uploaded and deleted from device	99	0	55.163
17:15.3	Audit log successfully uploaded			
17:15.5	Audit log successfully uploaded and deleted from device	99	0	55.163
17:36.6	Audit log successfully uploaded			
17:36.8	Audit log successfully uploaded and deleted from device	99	0	55.163
17:43.9	Audit log successfully uploaded			
17:44.1	Audit log successfully uploaded and deleted from device	99	0	55.163
18:00.3	Audit log successfully uploaded			
18:00.5	Audit log successfully uploaded and deleted from device	99	0	55.163
18:10.6	Audit log successfully uploaded			
18:10.8	Audit log successfully uploaded and deleted from device	99	0	55.163
18:34.0	Audit log successfully uploaded			
18:34.2	Audit log successfully uploaded and deleted from device	99	0	55.163
18:57.3	Audit log successfully uploaded			
18:57.5	Audit log successfully uploaded and deleted from device	99	0	55.163
19:21.6	Audit log successfully uploaded			
19:21.8	Audit log successfully uploaded and deleted from device	99	0	55.163
19:51.0	Audit log successfully uploaded			
19:51.2	Audit log successfully uploaded and deleted from device	99	0	55.163
20:13.4	Audit log successfully uploaded			
20:13.5	Audit log successfully uploaded and deleted from device	99	0	55.163
20:33.7	Audit log successfully uploaded			
20:33.9	Audit log successfully uploaded and deleted from device	99	0	55.163
20:51.0	Audit log successfully uploaded			
20:51.2	Audit log successfully uploaded and deleted from device	99	0	55.163
21:17.3	Audit log successfully uploaded			
21:17.5	Audit log successfully uploaded and deleted from device	99	0	55.163
21:28.6	Audit log successfully uploaded			
21:28.8	Audit log successfully uploaded and deleted from device	99	0	55.163
21:58.0	Date/Time synced to 08/17/2021 09:21:58.01 PM from 08/17/2021 09:21:58.03 PM			
51:27.5	Audit log created	100	0 1.15.14	55.165
51:58.0	Date/Time synced to 08/17/2021 09:51:58.02 PM from 08/17/2021 09:51:57.91 PM			
21:58.0	Date/Time synced to 08/17/2021 10:21:58.01 PM from 08/17/2021 10:21:57.91 PM			
32:56.6	Camera disconnected from Axon Dock X62001V12	100	0	55.17
32:56.6	Device disconnected from charger	100	0	55.17
35:29.4	Event button pressed			
35:29.5	Event button released			
35:29.6	Event button pressed			
35:29.6	Audio recording enabled due to video recording default			

35:29.7	Event button released			
35:29.8	Recording started due to button press	100	0	55.172 6f82d8d2d50442a48331d141a9e1f400
42:03.1	Event button pressed			
42:03.3	Event button released			
42:03.4	Event button pressed			
42:03.6	Event button released			
42:13.0	Event button pressed			
42:16.0	Recording stopped due to button press	97	1	54.897 6f82d8d2d50442a48331d141a9e1f400
42:16.7	Event button released			
42:16.8	Audio recording disabled due to video buffering default			
51:27.5	Audit log created	96	1 1.15.14	54.896
51:27.5	Audit log created	90	1 1.15.14	54.894
51:27.5	Audit log created	84	1 1.15.14	54.893
42:28.4	Axon application connected to device			
42:47.3	Axon application connected to device			
43:24.7	Categories 'Disorderly Person' added to video metadata using Axon applicator			6f82d8d2d50442a48331d141a9e1f400
43:24.7	Title changed in video metadata from 'Axon Body 3 Video 2021-08-17 2235 X6033271L' to 'Sig. 23 N6' using Axon applicator			6f82d8d2d50442a48331d141a9e1f400
43:44.6	Axon application disconnected from device			
51:27.5	Audit log created	78	1 1.15.14	54.891
51:27.5	Audit log created	73	1 1.15.14	54.89
51:27.5	Audit log created	66	1 1.15.14	54.889
51:27.5	Audit log created	60	1 1.15.14	54.887
39:15.9	Camera connected to Axon Dock X62001V12	54	1	54.89
39:15.9	Audit log created	54	1 1.15.14	54.886
39:15.9	Audit log rolled	54	1	54.886
39:16.6	Device connected to charger	54	1	54.886
39:29.3	Video upload started when camera was docked			6f82d8d2d50442a48331d141a9e1f400
39:35.5	Audit log successfully uploaded			
39:35.7	Audit log successfully uploaded and deleted from device	54	1	54.891
39:46.0	Date/Time synced to 08/18/2021 05:39:46.01 AM from 08/18/2021 05:39:45.92 AM			
39:55.8	Audit log successfully uploaded			
39:56.0	Audit log successfully uploaded and deleted from device	55	1	54.89
40:05.7	Audit log successfully uploaded			
40:05.9	Audit log successfully uploaded and deleted from device	55	1	54.89
40:13.1	Audit log successfully uploaded			
40:13.2	Audit log successfully uploaded and deleted from device	55	1	54.89
40:42.4	Audit log successfully uploaded			
40:42.6	Audit log successfully uploaded and deleted from device	55	1	54.89
40:46.7	Audit log successfully uploaded			
40:46.9	Audit log successfully uploaded and deleted from device	55	1	54.89
40:48.1	Video successfully uploaded from device when dockec			6f82d8d2d50442a48331d141a9e1f400
40:48.4	Video deleted from device when docked	55	0	55.163 6f82d8d2d50442a48331d141a9e1f400
40:48.4	Audit log created	55	0 1.15.14	55.164
40:48.4	Audit log rolled	55	0	55.164
40:48.5	Audit log created	55	0 1.15.14	55.164
40:48.5	Audit log rolled	55	0	55.164
41:16.1	Audit log successfully uploaded			

41:16.3	Audit log successfully uploaded and deleted from device	55	0	55.163
41:27.4	Audit log successfully uploaded			
41:27.6	Audit log successfully uploaded and deleted from device	55	0	55.163
41:27.8	Audit log successfully uploaded			
41:28.0	Audit log successfully uploaded and deleted from device	55	0	55.163
09:47.0	Date/Time synced to 08/18/2021 06:09:47.01 AM from 08/18/2021 06:09:46.03 AM			
35:53.5	Audit log successfully uploaded			
35:53.7	Audit log successfully uploaded and deleted from device	82	0	55.163
36:06.1	Audit log successfully uploaded			
36:06.3	Audit log successfully uploaded and deleted from device	82	0	55.163
39:47.0	Date/Time synced to 08/18/2021 06:39:47.01 AM from 08/18/2021 06:39:46.91 AM			
40:48.9	Audit log created	84	0 1.15.14	55.163
49:04.5	Device disconnected from charger	87	0	55.163
49:05.5	Device connected to charger	87	0	55.163
49:39.9	Audit log successfully uploaded			
49:40.1	Audit log successfully uploaded and deleted from device	87	0	55.163
09:46.0	Date/Time synced to 08/18/2021 07:09:46.01 AM from 08/18/2021 07:09:46.91 AM			
39:47.0	Date/Time synced to 08/18/2021 07:39:47.01 AM from 08/18/2021 07:39:45.93 AM			
40:48.9	Audit log created	100	0 1.15.14	55.164
54:05.8	Audit log successfully uploaded			
54:06.0	Audit log successfully uploaded and deleted from device	100	0	55.165
09:47.0	Date/Time synced to 08/18/2021 08:09:47.01 AM from 08/18/2021 08:09:46.91 AM			
39:46.0	Date/Time synced to 08/18/2021 08:39:46.01 AM from 08/18/2021 08:39:46.92 AM			
40:47.9	Audit log created	100	0 1.15.14	55.165
09:46.0	Date/Time synced to 08/18/2021 09:09:46.01 AM from 08/18/2021 09:09:45.92 AM			
36:03.8	Audit log successfully uploaded			
36:04.0	Audit log successfully uploaded and deleted from device	100	0	55.165
39:47.0	Date/Time synced to 08/18/2021 09:39:47.01 AM from 08/18/2021 09:39:45.93 AM			
40:48.9	Audit log created	100	0 1.15.14	55.165
09:46.0	Date/Time synced to 08/18/2021 10:09:46.01 AM from 08/18/2021 10:09:46.91 AM			
25:40.2	Audit log successfully uploaded			
25:40.4	Audit log successfully uploaded and deleted from device	100	0	55.165
39:47.0	Date/Time synced to 08/18/2021 10:39:47.01 AM from 08/18/2021 10:39:45.92 AM			
40:48.9	Audit log created	100	0 1.15.14	55.165
09:47.0	Date/Time synced to 08/18/2021 11:09:47.01 AM from 08/18/2021 11:09:46.91 AM			
19:39.7	Audit log successfully uploaded			
19:39.9	Audit log successfully uploaded and deleted from device	100	0	55.165
39:46.0	Date/Time synced to 08/18/2021 11:39:46.01 AM from 08/18/2021 11:39:46.91 AM			
40:47.9	Audit log created	100	0 1.15.14	55.165
09:46.0	Date/Time synced to 08/18/2021 12:09:46.01 PM from 08/18/2021 12:09:45.93 PM			
19:53.7	Audit log successfully uploaded			
19:53.9	Audit log successfully uploaded and deleted from device	100	0	55.165
39:46.0	Date/Time synced to 08/18/2021 12:39:46.01 PM from 08/18/2021 12:39:45.91 PM			
40:47.9	Audit log created	100	0 1.15.14	55.165
09:46.0	Date/Time synced to 08/18/2021 01:09:46.01 PM from 08/18/2021 01:09:45.91 PM			
23:48.8	Audit log successfully uploaded			
23:49.0	Audit log successfully uploaded and deleted from device	100	0	55.165

39:46.0 Date/Time synced to 08/18/2021 01:39:46.01 PM from 08/18/2021 01:39:45.92 PM			
40:47.9 Audit log created	100	0 1.15.14	55.165
09:46.0 Date/Time synced to 08/18/2021 02:09:46.01 PM from 08/18/2021 02:09:45.92 PM			
11:44.1 Audit log successfully uploaded			
11:44.3 Audit log successfully uploaded and deleted from device	100	0	55.165
39:46.0 Date/Time synced to 08/18/2021 02:39:46.02 PM from 08/18/2021 02:39:45.93 PM			
40:47.9 Audit log created	100	0 1.15.14	55.165
09:46.0 Date/Time synced to 08/18/2021 03:09:46.01 PM from 08/18/2021 03:09:45.92 PM			
15:36.6 Audit log successfully uploaded			
15:36.8 Audit log successfully uploaded and deleted from device	100	0	55.165
39:46.0 Date/Time synced to 08/18/2021 03:39:46.01 PM from 08/18/2021 03:39:45.93 PM			
40:48.0 Audit log created	100	0 1.15.14	55.164
06:20.5 Audit log successfully uploaded			
06:20.7 Audit log successfully uploaded and deleted from device	100	0	55.165
09:46.0 Date/Time synced to 08/18/2021 04:09:46.01 PM from 08/18/2021 04:09:45.93 PM			
39:46.0 Date/Time synced to 08/18/2021 04:39:46.01 PM from 08/18/2021 04:39:45.92 PM			
40:47.9 Audit log created	100	0 1.15.14	55.164
52:21.2 Audit log successfully uploaded			
52:21.4 Audit log successfully uploaded and deleted from device	100	0	55.164
09:46.0 Date/Time synced to 08/18/2021 05:09:46.01 PM from 08/18/2021 05:09:45.92 PM			
39:46.0 Date/Time synced to 08/18/2021 05:39:46.01 PM from 08/18/2021 05:39:45.92 PM			
40:48.0 Audit log created	100	0 1.15.14	55.164
50:14.3 Audit log successfully uploaded			
50:14.5 Audit log successfully uploaded and deleted from device	100	0	55.164
09:46.0 Date/Time synced to 08/18/2021 06:09:46.01 PM from 08/18/2021 06:09:45.91 PM			
39:46.0 Date/Time synced to 08/18/2021 06:39:46.01 PM from 08/18/2021 06:39:45.93 PM			
40:48.0 Audit log created	100	0 1.15.14	55.165
47:30.8 Audit log successfully uploaded			
47:31.0 Audit log successfully uploaded and deleted from device	100	0	55.165
09:46.0 Date/Time synced to 08/18/2021 07:09:46.01 PM from 08/18/2021 07:09:45.91 PM			
39:46.0 Date/Time synced to 08/18/2021 07:39:46.01 PM from 08/18/2021 07:39:45.92 PM			
40:48.0 Audit log created	100	0 1.15.14	55.17
52:37.5 Device disconnected from charger	100	0	55.169
52:37.5 Camera disconnected from Axon Dock X62001V12	100	0	55.174
40:48.0 Audit log created	94	0 1.15.14	55.173
40:48.0 Audit log created	87	0 1.15.14	55.172
40:48.0 Audit log created	81	0 1.15.14	55.17
40:48.0 Audit log created	75	0 1.15.14	55.169
40:48.0 Audit log created	69	0 1.15.14	55.168
39:33.2 Event button pressed			
39:33.3 Event button released			
39:33.4 Event button pressed			
39:33.4 Audio recording enabled due to video recording default			
39:33.5 Event button released			
39:33.5 Recording started due to button press	63	1	55.166 9ef7bf1867274ec388b6c28af049a8c8
40:48.0 Audit log created	63	1 1.15.14	55.067
41:47.5 Event button pressed			

41:47.7	Event button released				
41:47.8	Event button pressed				
41:48.0	Event button released				
41:49.6	Event button pressed				
41:52.6	Recording stopped due to button press	63	1	55.033	9ef7bf1867274ec388b6c28af049a8c8
41:53.3	Audio recording disabled due to video buffering default				
41:53.8	Event button released				
44:14.9	Axon application connected to device				
44:49.4	Title changed in video metadata from 'Axon Body 3 Video 2021-08-19 0139 X6033271L' to 'Sig. 31 N6' using Axon applicator				9ef7bf1867274ec388b6c28af049a8c8
44:49.4	Categories 'Sleeper' added to video metadata using Axon applicator				9ef7bf1867274ec388b6c28af049a8c8
45:05.2	Axon application disconnected from device				
45:33.7	Camera connected to Axon Dock X62001V12	63	1	55.035	
45:33.7	Audit log rolled	62	1	55.032	
45:33.7	Audit log created	62	1 1.15.14	55.032	
45:34.5	Device connected to charger	62	1	55.032	
45:49.8	Video upload started when camera was docked				9ef7bf1867274ec388b6c28af049a8c8
46:04.0	Date/Time synced to 08/19/2021 01:46:04.01 AM from 08/19/2021 01:46:03.69 AM				
46:06.2	Audit log successfully uploaded				
46:06.4	Audit log successfully uploaded and deleted from device	63	1	55.035	
46:14.1	Audit log successfully uploaded				
46:14.4	Audit log successfully uploaded and deleted from device	63	1	55.035	
46:28.2	Video successfully uploaded from device when docked				9ef7bf1867274ec388b6c28af049a8c8
46:28.5	Video deleted from device when docked	63	0	55.168	9ef7bf1867274ec388b6c28af049a8c8
46:28.6	Audit log rolled	63	0	55.168	
46:28.6	Audit log created	63	0 1.15.14	55.168	
46:28.6	Audit log rolled	63	0	55.168	
46:28.6	Audit log created	63	0 1.15.14	55.168	
46:43.5	Audit log successfully uploaded				
46:43.7	Audit log successfully uploaded and deleted from device	63	0	55.168	
47:11.8	Audit log successfully uploaded				
47:12.0	Audit log successfully uploaded and deleted from device	63	0	55.168	
47:24.1	Audit log successfully uploaded				
47:24.3	Audit log successfully uploaded and deleted from device	63	0	55.168	
47:44.4	Audit log successfully uploaded				
47:44.6	Audit log successfully uploaded and deleted from device	63	0	55.168	
48:11.7	Audit log successfully uploaded				
48:12.0	Audit log successfully uploaded and deleted from device	63	0	55.168	
48:19.1	Audit log successfully uploaded				
48:19.3	Audit log successfully uploaded and deleted from device	63	0	55.168	
07:00.3	Select button pressed				
07:00.4	Select button released				
07:00.7	Camera disconnected from Axon Dock X62001V12	72	0	55.168	
07:00.8	Device disconnected from charger	72	0	55.171	
46:28.0	Audit log created	68	0 1.15.14	55.171	
46:28.0	Audit log created	61	0 1.15.14	55.169	
46:28.1	Audit log created	54	0 1.15.14	55.168	
46:28.1	Audit log created	46	0 1.15.14	55.167	

36:05.5	Volume down button pressed			
36:05.6	Volume down button released			
36:05.8	Volume changed to low from medium using button			
36:09.1	Select button pressed			
36:09.2	Select button released			
36:10.5	Select button pressed			
36:10.6	Select button released			
36:11.0	Volume up button pressed			
36:11.2	Volume up button released			
36:11.4	Volume up button pressed			
36:11.6	Volume up button released			
36:11.7	Volume changed to medium from low using button			
36:15.7	Camera connected to Axon Dock X630020W7	41	0	55.166
36:15.7	Audit log rolled	41	0	55.166
36:15.7	Audit log created	41	0 1.15.14	55.166
36:16.7	Device connected to charger	41	0	55.166
36:15.0	Audit log created	70	0 1.15.14	55.166
36:15.0	Audit log created	96	0 1.15.14	55.166
36:15.0	Audit log created	100	0 1.15.14	55.165
36:15.0	Audit log created	100	0 1.15.14	55.165
36:15.0	Audit log created	100	0 1.15.14	55.165
36:15.0	Audit log created	100	0 1.15.14	55.165
36:15.0	Audit log created	100	0 1.15.14	55.164
36:15.0	Audit log created	100	0 1.15.14	55.164
36:15.0	Audit log created	100	0 1.15.14	55.164
36:15.0	Audit log created	100	0 1.15.14	55.164
36:15.0	Audit log created	100	0 1.15.14	55.164
36:15.1	Audit log created	100	0 1.15.14	55.163
36:15.1	Audit log created	100	0 1.15.14	55.163
36:15.1	Audit log created	100	0 1.15.14	55.163
46:34.7	Device disconnected from charger	100	0	55.163
46:34.7	Camera disconnected from Axon Dock X630020W7	100	0	55.166
46:50.2	Power button pressed			
46:53.2	Device powered off using button	100	0	55.166
46:53.7	Power button released			
59:39.1	Audit log created		1.15.14	
59:39.2	Device powered on using button	100	0	55.165
59:41.2	Audio recording disabled due to video buffering default			
53:31.1	Audio recording enabled due to video recording default			
53:31.2	Recording started due to Axon Signal Sidearm activation	93	1	55.163 a2cc71f11c7849bea7a2299d886ab8ed
56:42.4	Event button pressed			
56:44.9	Event button released			
56:47.1	Event button pressed			
56:50.1	Recording stopped due to button press	92	1	54.998 a2cc71f11c7849bea7a2299d886ab8ed
56:50.6	Event button released			
56:51.1	Audio recording disabled due to video buffering default			
59:39.1	Audit log created	92	1 1.15.14	54.997
13:13.3	Power button pressed			
13:16.3	Device powered off using button	91	1	54.997

13:16.7	Power button released			
12:11.0	Audit log created		1.15.14	
12:11.1	Device powered on using button	90	1	54.997
12:12.9	Audio recording disabled due to video buffering default			
12:28.0	Axon application connected to device			
12:39.0	Audio recording enabled due to video recording default			
12:39.2	Recording started due to Axon Signal Sidearm activation	90	2	54.996 66ac0e07065f4938b63e3d09d47a47ff
12:51.9	Event button pressed			
12:54.9	Recording stopped due to button press	90	2	54.975 66ac0e07065f4938b63e3d09d47a47ff
12:55.4	Event button released			
12:55.8	Audio recording disabled due to video buffering default			
14:30.0	Title changed in video metadata from 'Axon Body 3 Video 2021-08-19 2053 X6033271L' to 'Sig. 70 N6 Civic Center Deck' using Axon applicator			a2cc71f11c7849bea7a2299d886ab8ed
14:30.0	Categories 'Loitering' added to video metadata using Axon applicator			a2cc71f11c7849bea7a2299d886ab8ed
15:16.7	Categories 'Accidental Recording' added to video metadata using Axon applicator			66ac0e07065f4938b63e3d09d47a47ff
15:16.7	Title changed in video metadata from 'Axon Body 3 Video 2021-08-19 2312 X6033271L' to 'Accidental Recording' using Axon applicator			66ac0e07065f4938b63e3d09d47a47ff
15:55.9	Camera connected to Axon Dock X62001V12	90	2	54.983
15:55.9	Axon application disconnected from device			
15:55.9	Audit log rolled	90	2	54.974
15:55.9	Audit log created	90	2	1.15.14 54.974
15:56.1	Device connected to charger	90	2	54.975
16:13.1	Video upload started when camera was docked			a2cc71f11c7849bea7a2299d886ab8ed
16:27.0	Date/Time synced to 08/19/2021 11:16:27.01 PM from 08/19/2021 11:16:25.90 PM			
16:42.1	Audit log successfully uploaded			
16:42.3	Audit log successfully uploaded and deleted from device	90	2	54.983
16:54.6	Audit log successfully uploaded			
16:54.8	Audit log successfully uploaded and deleted from device	91	2	54.983
17:19.9	Audit log successfully uploaded			
17:20.1	Audit log successfully uploaded and deleted from device	91	2	54.983
17:36.3	Audit log successfully uploaded			
17:36.5	Audit log successfully uploaded and deleted from device	91	2	54.983
18:02.0	Audit log successfully uploaded			
18:02.2	Audit log successfully uploaded and deleted from device	91	2	54.983
18:23.4	Audit log successfully uploaded			
18:23.6	Audit log successfully uploaded and deleted from device	91	2	54.982
18:37.8	Audit log successfully uploaded			
18:38.0	Audit log successfully uploaded and deleted from device	91	2	54.982
19:05.1	Audit log successfully uploaded			
19:05.3	Audit log successfully uploaded and deleted from device	92	2	54.982
19:31.5	Audit log successfully uploaded			
19:31.7	Audit log successfully uploaded and deleted from device	92	2	54.982
19:32.8	Audit log successfully uploaded			
19:33.0	Audit log successfully uploaded and deleted from device	92	2	54.982
19:35.2	Audit log successfully uploaded			
19:35.4	Audit log successfully uploaded and deleted from device	92	2	54.982
19:38.5	Audit log successfully uploaded			
19:38.7	Audit log successfully uploaded and deleted from device	92	2	54.982
19:42.8	Audit log successfully uploaded			

19:43.0	Audit log successfully uploaded and deleted from device	92	2	54.982	
20:12.2	Audit log successfully uploaded				
20:12.4	Audit log successfully uploaded and deleted from device	92	2	54.982	
20:19.6	Audit log successfully uploaded				
20:19.8	Audit log successfully uploaded and deleted from device	92	2	54.982	
20:24.0	Audit log successfully uploaded				
20:24.2	Audit log successfully uploaded and deleted from device	92	2	54.982	
20:52.3	Audit log successfully uploaded				
20:52.5	Audit log successfully uploaded and deleted from device	92	2	54.982	
21:09.8	Audit log successfully uploaded				
21:10.0	Audit log successfully uploaded and deleted from device	92	2	54.982	
21:34.2	Audit log successfully uploaded				
21:34.4	Audit log successfully uploaded and deleted from device	92	2	54.982	
21:58.5	Audit log successfully uploaded				
21:58.7	Audit log successfully uploaded and deleted from device	93	2	54.982	
22:02.2	Select button pressed				
22:02.4	Select button released				
22:02.9	Camera disconnected from Axon Dock X62001V12	93	2	54.983	
22:03.9	Device disconnected from charger	93	2	54.982	
22:05.7	Camera connected to Axon Dock X62001V12	93	2	54.984	
22:05.8	Audit log rolled	93	2	54.982	
22:05.8	Audit log created	93	2 1.15.14	54.983	
22:06.9	Device connected to charger	93	2	54.983	
22:36.0	Date/Time synced to 08/19/2021 11:22:36.01 PM from 08/19/2021 11:22:35.79 PM				
28:33.0	Camera disconnected from Axon Dock X62001V12	95	2	54.983	
28:33.0	Device disconnected from charger	95	2	54.983	
28:34.9	Camera connected to Axon Dock X62001V12	95	2	54.984	
28:35.0	Audit log created	95	2 1.15.14	54.983	
28:35.0	Audit log rolled	95	2	54.983	
28:35.0	Device connected to charger	95	2	54.983	
29:04.1	Audit log successfully uploaded				
29:04.3	Audit log successfully uploaded and deleted from device	95	2	54.984	
29:05.0	Date/Time synced to 08/19/2021 11:29:05.01 PM from 08/19/2021 11:29:04.98 PM				
29:29.1	Audit log successfully uploaded				
29:29.3	Audit log successfully uploaded and deleted from device	95	2	54.984	
29:30.5	Audit log successfully uploaded				
29:30.7	Audit log successfully uploaded and deleted from device	95	2	54.984	
29:55.9	Audit log successfully uploaded				
29:56.1	Audit log successfully uploaded and deleted from device	95	2	54.983	
29:57.2	Audit log successfully uploaded				
29:57.4	Audit log successfully uploaded and deleted from device	95	2	54.983	
35:52.3	Video successfully uploaded from device when dockec				a2cc71f11c7849bea7a2299d886ab8ed
35:52.6	Video deleted from device when docked	97	1	55.149	a2cc71f11c7849bea7a2299d886ab8ed
35:52.6	Audit log created	97	1 1.15.14	55.149	
35:52.6	Audit log rolled	97	1	55.149	
35:52.8	Video upload started when camera was docked				66ac0e07065f4938b63e3d09d47a47ff
35:58.9	Video successfully uploaded from device when dockec				66ac0e07065f4938b63e3d09d47a47ff

35:59.1 Video deleted from device when docked	97	0	55.171 66ac0e07065f4938b63e3d09d47a47ff
35:59.1 Audit log created	97	0 1.15.14	55.171
35:59.1 Audit log rolled	97	0	55.171
35:59.2 Audit log rolled	97	0	55.171
35:59.2 Audit log created	97	0 1.15.14	55.171
41:49.0 Device disconnected from charger	98	0	55.171
41:49.1 Camera disconnected from Axon Dock X62001V12	98	0	55.171
42:06.4 Volume up button pressed			
42:06.6 Volume up button released			
42:06.6 Volume changed to high from medium using button			
42:10.4 Volume down button pressed			
42:10.6 Volume down button released			
42:10.7 Volume changed to medium from high using button			
35:59.0 Audit log created	91	0 1.15.14	55.169
35:59.0 Audit log created	85	0 1.15.14	55.168
37:52.7 Event button pressed			
37:52.9 Event button released			
37:52.9 Event button pressed			
37:53.0 Audio recording enabled due to video recording default			
37:53.0 Event button released			
37:53.1 Recording started due to button press	85	1	55.168 7fa1ce9bb97d465a88331d09a508e9f3
39:36.9 Event button pressed			
39:39.9 Recording stopped due to button press	84	1	55.051 7fa1ce9bb97d465a88331d09a508e9f3
39:40.4 Event button released			
39:40.8 Audio recording disabled due to video buffering default			
41:51.7 Axon application connected to device			
43:06.5 Title changed in video metadata from 'Axon Body 3 Video 2021-08-20 0137 X6033271L' to 'Sig. 31, 70 N6' using Axon applicator			7fa1ce9bb97d465a88331d09a508e9f3
43:06.5 Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			7fa1ce9bb97d465a88331d09a508e9f3
43:24.6 Axon application disconnected from device			
03:47.0 Camera connected to Axon Dock X62001V12	82	1	55.051
03:47.0 Audit log rolled	82	1	55.05
03:47.0 Audit log created	82	1 1.15.14	55.05
03:48.0 Device connected to charger	82	1	55.05
04:01.9 Video upload started when camera was docked			7fa1ce9bb97d465a88331d09a508e9f3
04:17.0 Date/Time synced to 08/20/2021 02:04:17.01 AM from 08/20/2021 02:04:17.01 AM			
04:17.1 Audit log successfully uploaded			
04:17.1 Audit log successfully uploaded and deleted from device	82	1	55.051
04:36.6 Video successfully uploaded from device when docked			7fa1ce9bb97d465a88331d09a508e9f3
04:36.9 Video deleted from device when docked	82	0	55.168 7fa1ce9bb97d465a88331d09a508e9f3
04:36.9 Audit log rolled	82	0	55.168
04:36.9 Audit log created	82	0 1.15.14	55.168
04:36.9 Audit log created	82	0 1.15.14	55.168
04:36.9 Audit log rolled	82	0	55.168
04:39.3 Audit log successfully uploaded			
04:39.5 Audit log successfully uploaded and deleted from device	82	0	55.168
04:56.6 Audit log successfully uploaded			
04:56.8 Audit log successfully uploaded and deleted from device	82	0	55.168

53:40.0 Audit log created	100	1 1.15.14	55.104
53:40.0 Audit log created	100	1 1.15.14	55.104
53:40.0 Audit log created	100	1 1.15.14	55.103
02:57.0 Device disconnected from charger	98	1	55.104
02:57.5 Camera disconnected from Axon Dock X630020W7	98	1	55.104
02:57.6 Audio recording disabled due to video buffering default			
03:09.0 Power button pressed			
03:12.0 Device powered off using button	100	1	55.106
03:12.5 Power button released			
27:36.9 Audit log created		1.15.14	
27:37.0 Device powered on due to charger connection	97	1	55.106
27:37.3 Device connected to charger			
27:37.3 Camera connected to Axon Dock X630020W7	97	1	55.106
27:37.3 Audit log rolled			
27:37.3 Audit log created		1.15.14	
27:38.0 Camera connected to Axon Dock X630020W7	97	1	55.106
27:39.9 Audit log created	97	1 1.15.14	55.106
27:39.9 Audit log rolled	97	1	55.106
27:39.0 Audit log created	97	1 1.15.14	55.105
35:51.6 Volume down button pressed			
35:51.7 Volume down button released			
35:52.0 Device disconnected from charger	97	1	55.105
35:52.4 Camera disconnected from Axon Dock X630020W7	97	1	55.105
35:52.6 Audio recording disabled due to video buffering default			
27:39.0 Audit log created	92	1 1.15.14	55.104
27:39.0 Audit log created	86	1 1.15.14	55.102
27:39.0 Audit log created	80	1 1.15.14	55.101
27:39.0 Audit log created	75	1 1.15.14	55.1
27:39.0 Audit log created	69	1 1.15.14	55.098
27:39.0 Audit log created	62	1 1.15.14	55.097
27:39.0 Audit log created	56	1 1.15.14	55.095
27:39.1 Audit log created	49	1 1.15.14	55.094
24:06.3 Camera connected to Axon Dock X62001W9H	43	1	55.103
24:06.3 Audit log created	43	1 1.15.14	55.093
24:06.3 Audit log rolled	43	1	55.093
24:07.0 Device connected to charger	43	1	55.094
24:30.9 Video upload started when camera was docked			0d7b2d459a1d436ab29cab0ba22bd440
24:39.0 Date/Time synced to 08/24/2021 12:24:39.02 AM from 08/24/2021 12:24:36.32 AM			
24:51.5 Video successfully uploaded from device when dockec			0d7b2d459a1d436ab29cab0ba22bd440
24:51.7 Video deleted from device when docked	43	0	55.164 0d7b2d459a1d436ab29cab0ba22bd440
24:51.8 Audit log created	43	0 1.15.14	55.164
24:51.8 Audit log rolled	43	0	55.164
24:51.8 Audit log rolled	43	0	55.164
24:51.8 Audit log created	43	0 1.15.14	55.164
24:55.0 Audit log successfully uploaded			
24:55.2 Audit log successfully uploaded and deleted from device	43	0	55.164
25:20.4 Audit log successfully uploaded			

25:20.6 Audit log successfully uploaded and deleted from device	44	0	55.164
25:36.8 Audit log successfully uploaded			
25:37.0 Audit log successfully uploaded and deleted from device	44	0	55.164
26:05.2 Audit log successfully uploaded			
26:05.4 Audit log successfully uploaded and deleted from device	44	0	55.164
26:22.6 Audit log successfully uploaded			
26:22.8 Audit log successfully uploaded and deleted from device	44	0	55.164
26:32.9 Audit log successfully uploaded			
26:33.1 Audit log successfully uploaded and deleted from device	44	0	55.164
26:53.3 Audit log successfully uploaded			
26:53.5 Audit log successfully uploaded and deleted from device	44	0	55.164
27:07.6 Audit log successfully uploaded			
27:07.8 Audit log successfully uploaded and deleted from device	44	0	55.164
27:09.0 Audit log successfully uploaded			
27:09.2 Audit log successfully uploaded and deleted from device	44	0	55.164
27:18.3 Audit log successfully uploaded			
27:18.5 Audit log successfully uploaded and deleted from device	44	0	55.164
27:39.6 Audit log successfully uploaded			
27:39.8 Audit log successfully uploaded and deleted from device	45	0	55.164
27:42.9 Audit log successfully uploaded			
27:43.1 Audit log successfully uploaded and deleted from device	45	0	55.164
28:05.3 Audit log successfully uploaded			
28:05.5 Audit log successfully uploaded and deleted from device	45	0	55.164
28:16.6 Audit log successfully uploaded			
28:16.8 Audit log successfully uploaded and deleted from device	45	0	55.164
28:40.9 Audit log successfully uploaded			
28:41.1 Audit log successfully uploaded and deleted from device	45	0	55.164
28:55.3 Audit log successfully uploaded			
28:55.5 Audit log successfully uploaded and deleted from device	45	0	55.164
28:59.6 Audit log successfully uploaded			
28:59.7 Audit log successfully uploaded and deleted from device	45	0	55.164
29:04.9 Audit log successfully uploaded			
29:05.0 Audit log successfully uploaded and deleted from device	45	0	55.164
29:14.2 Audit log successfully uploaded			
29:14.4 Audit log successfully uploaded and deleted from device	46	0	55.164
29:38.6 Audit log successfully uploaded			
29:38.7 Audit log successfully uploaded and deleted from device	46	0	55.164
30:00.8 Audit log successfully uploaded			
30:01.0 Audit log successfully uploaded and deleted from device	46	0	55.164
30:06.2 Audit log successfully uploaded			
30:06.4 Audit log successfully uploaded and deleted from device	46	0	55.164
30:06.7 Audit log successfully uploaded			
30:06.9 Audit log successfully uploaded and deleted from device	46	0	55.164
30:19.0 Audit log successfully uploaded			
30:19.2 Audit log successfully uploaded and deleted from device	46	0	55.164
30:26.3 Audit log successfully uploaded			
30:26.5 Audit log successfully uploaded and deleted from device	46	0	55.164

30:34.7	Audit log successfully uploaded			
30:34.9	Audit log successfully uploaded and deleted from device	46	0	55.164
30:48.0	Audit log successfully uploaded			
30:48.2	Audit log successfully uploaded and deleted from device	46	0	55.164
31:01.3	Audit log successfully uploaded			
31:01.5	Audit log successfully uploaded and deleted from device	46	0	55.164
37:53.6	Select button pressed			
37:53.8	Select button released			
37:53.8	Camera disconnected from Axon Dock X62001W9H	49	0	55.164
37:54.5	Device disconnected from charger	49	0	55.17
24:51.0	Audit log created	45	0 1.15.14	55.169
22:56.6	Camera connected to Axon Dock X630020W7	39	0	55.168
22:56.6	Audit log created	39	0 1.15.14	55.167
22:56.6	Audit log rolled	39	0	55.167
22:57.5	Device connected to charger	39	0	55.168
22:56.0	Audit log created	67	0 1.15.14	55.172
22:56.0	Audit log created	94	0 1.15.14	55.171
22:56.0	Audit log created	100	0 1.15.14	55.17
22:56.0	Audit log created	100	0 1.15.14	55.17
22:56.0	Audit log created	100	0 1.15.14	55.171
22:56.0	Audit log created	100	0 1.15.14	55.17
22:56.1	Audit log created	100	0 1.15.14	55.17
22:56.1	Audit log created	100	0 1.15.14	55.17
22:56.1	Audit log created	100	0 1.15.14	55.17
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.1	Audit log created	100	0 1.15.14	55.169
22:56.2	Audit log created	100	0 1.15.14	55.169
42:26.1	Volume down button pressed			
42:26.2	Volume down button released			
42:26.5	Device disconnected from charger	100	0	55.168
42:27.0	Camera disconnected from Axon Dock X630020W7	100	0	55.168
43:18.9	Power button pressed			
43:21.9	Device powered off using button	100	0	55.169
43:22.4	Power button released			
21:02.9	Audit log created		1.15.14	
21:03.0	Device powered on using button	100	0	55.169
21:04.8	Audio recording disabled due to video buffering default			
21:02.9	Audit log created	92	0 1.15.14	55.167
21:02.9	Audit log created	86	0 1.15.14	55.166
12:26.8	Event button pressed			
12:27.0	Event button released			
12:27.0	Event button pressed			
12:27.1	Audio recording enabled due to video recording default			

12:27.2	Event button released			
12:27.3	Recording started due to button press	81	0	55.165 caaa93d27393429eb092777a3f8b02f7
21:02.9	Audit log created	80	1 1.15.14	54.833
27:47.8	Event button pressed			
27:50.8	Recording stopped due to button press	78	1	54.618 caaa93d27393429eb092777a3f8b02f7
27:51.7	Audio recording disabled due to video buffering default			
27:52.2	Event button released			
32:15.2	Axon application connected to device			
33:27.8	Title changed in video metadata from 'Axon Body 3 Video 2021-08-24 2312 X6033271L' to 'Sig. 38A N2' using Axon application			caaa93d27393429eb092777a3f8b02f7
33:27.8	Categories 'Alcohol/Drug' added to video metadata using Axon application			caaa93d27393429eb092777a3f8b02f7
33:40.8	Axon application disconnected from device			
21:02.9	Audit log created	73	1 1.15.14	54.614
21:02.9	Audit log created	67	1 1.15.14	54.612
40:02.1	Event button pressed			
40:02.3	Event button released			
40:02.4	Event button pressed			
40:02.4	Audio recording enabled due to video recording default			
40:02.5	Event button released			
40:02.6	Recording started due to button press	65	2	54.612 07a83c5f275c4592a17838c22c6b6123
53:06.5	Event button pressed			
53:09.6	Recording stopped due to button press	63	2	54.135 07a83c5f275c4592a17838c22c6b6123
53:10.4	Audio recording disabled due to video buffering default			
53:10.5	Event button released			
21:03.1	Audit log created	60	2 1.15.14	54.135
43:00.1	Event button pressed			
43:00.4	Event button released			
43:01.5	Event button pressed			
43:01.6	Event button released			
43:01.7	Event button pressed			
43:01.8	Audio recording enabled due to video recording default			
43:01.9	Event button released			
43:01.9	Recording started due to button press	58	3	54.134 e0ba971f74ff42d3844afb003288587f
49:11.4	Event button pressed			
49:14.5	Recording stopped due to button press	56	3	53.877 e0ba971f74ff42d3844afb003288587f
49:14.9	Event button released			
49:15.3	Audio recording disabled due to video buffering default			
50:57.9	Event button pressed			
50:58.1	Event button released			
50:58.1	Event button pressed			
50:58.2	Audio recording enabled due to video recording default			
50:58.3	Event button released			
50:58.3	Recording started due to button press	56	4	53.875 f0e23077da244e00b829cafe2cf8bf99
54:17.5	Event button pressed			
54:20.5	Recording stopped due to button press	55	4	53.717 f0e23077da244e00b829cafe2cf8bf99
54:21.3	Audio recording disabled due to video buffering default			
54:21.3	Event button released			
21:03.1	Audit log created	52	4 1.15.14	53.715

40:42.7	Axon application connected to device				
41:17.7	Video played back using Axon application				07a83c5f275c4592a17838c22c6b6123
42:14.8	Title changed in video metadata from 'Axon Body 3 Video 2021-08-25 0140 X6033271L' to 'Sig. 31/70/23 N2' using Axon applicator				07a83c5f275c4592a17838c22c6b6123
42:14.8	Categories 'Sleeper', 'Explosive Device Found', 'Disorderly Person', 'Loitering' added to video metadata using Axon applicator				07a83c5f275c4592a17838c22c6b6123
43:06.8	Title changed in video metadata from 'Axon Body 3 Video 2021-08-25 0243 X6033271L' to 'Sig. 31 N3' using Axon applicator				e0ba971f74ff42d3844afb003288587f
43:06.8	Categories 'Sleeper' added to video metadata using Axon applicator				e0ba971f74ff42d3844afb003288587f
43:30.2	Categories 'Sleeper' added to video metadata using Axon applicator				f0e23077da244e00b829cafe2cf8bf99
43:30.2	Title changed in video metadata from 'Axon Body 3 Video 2021-08-25 0250 X6033271L' to 'Sig. 31 N3' using Axon applicator				f0e23077da244e00b829cafe2cf8bf99
43:43.4	Axon application disconnected from device				
44:33.0	Camera connected to Axon Dock X62001V12	49	4		53.731
44:33.1	Audit log rolled	49	4		53.714
44:33.1	Audit log created	49	4	1.15.14	53.714
44:34.0	Device connected to charger	49	4		53.714
44:59.9	Video upload started when camera was docked				caaa93d27393429eb092777a3f8b02f7
45:04.0	Date/Time synced to 08/25/2021 03:45:04.03 AM from 08/25/2021 03:45:03.18 AM				
45:05.5	Audit log successfully uploaded				
45:05.6	Audit log successfully uploaded and deleted from device	49	4		53.731
45:17.5	Audit log successfully uploaded				
45:17.7	Audit log successfully uploaded and deleted from device	49	4		53.731
45:40.8	Audit log successfully uploaded				
45:41.0	Audit log successfully uploaded and deleted from device	49	4		53.731
45:41.2	Audit log successfully uploaded				
45:41.4	Audit log successfully uploaded and deleted from device	49	4		53.731
45:42.5	Audit log successfully uploaded				
45:42.7	Audit log successfully uploaded and deleted from device	49	4		53.731
45:47.8	Audit log successfully uploaded				
45:48.0	Audit log successfully uploaded and deleted from device	49	4		53.731
45:58.2	Audit log successfully uploaded				
45:58.3	Audit log successfully uploaded and deleted from device	49	4		53.731
46:21.6	Audit log successfully uploaded				
46:21.8	Audit log successfully uploaded and deleted from device	50	4		53.73
46:34.0	Audit log successfully uploaded				
46:34.2	Audit log successfully uploaded and deleted from device	50	4		53.73
46:41.3	Audit log successfully uploaded				
46:41.5	Audit log successfully uploaded and deleted from device	50	4		53.73
47:08.4	Audit log successfully uploaded				
47:08.5	Audit log successfully uploaded and deleted from device	50	4		53.73
47:19.9	Video successfully uploaded from device when docked				caaa93d27393429eb092777a3f8b02f7
47:20.2	Video deleted from device when docked	50	3		54.273 caaa93d27393429eb092777a3f8b02f7
47:20.4	Audit log rolled	50	3		54.273
47:20.4	Audit log created	50	3	1.15.14	54.273
47:20.7	Video upload started when camera was docked				07a83c5f275c4592a17838c22c6b6123
47:35.7	Audit log successfully uploaded				
47:35.9	Audit log successfully uploaded and deleted from device	50	3		54.273
47:52.0	Audit log successfully uploaded				
47:52.2	Audit log successfully uploaded and deleted from device	50	3		54.273
47:56.3	Audit log successfully uploaded				

47:56.5	Audit log successfully uploaded and deleted from device	50	3	54.273
48:19.6	Audit log successfully uploaded			
48:19.8	Audit log successfully uploaded and deleted from device	51	3	54.273
48:20.1	Audit log successfully uploaded			
48:20.2	Audit log successfully uploaded and deleted from device	51	3	54.273
48:24.4	Audit log successfully uploaded			
48:24.6	Audit log successfully uploaded and deleted from device	51	3	54.273
48:32.8	Audit log successfully uploaded			
48:33.0	Audit log successfully uploaded and deleted from device	51	3	54.273
48:54.1	Audit log successfully uploaded			
48:54.3	Audit log successfully uploaded and deleted from device	51	3	54.273
48:56.5	Audit log successfully uploaded			
48:56.7	Audit log successfully uploaded and deleted from device	51	3	54.273
49:20.8	Audit log successfully uploaded			
49:21.0	Audit log successfully uploaded and deleted from device	51	3	54.273
49:29.2	Audit log successfully uploaded			
49:29.3	Audit log successfully uploaded and deleted from device	51	3	54.272
49:36.6	Video successfully uploaded from device when dockec			07a83c5f275c4592a17838c22c6b6123
49:37.0	Video deleted from device when docked	51	2	54.746 07a83c5f275c4592a17838c22c6b6123
49:37.0	Audit log rolled	51	2	54.748
49:37.0	Audit log created	51	2 1.15.14	54.748
49:37.2	Video upload started when camera was docked			e0ba971f74ff42d3844afb003288587f
49:45.4	Audit log successfully uploaded			
49:45.6	Audit log successfully uploaded and deleted from device	51	2	54.748
49:51.8	Audit log successfully uploaded			
49:52.0	Audit log successfully uploaded and deleted from device	51	2	54.748
50:15.2	Audit log successfully uploaded			
50:15.3	Audit log successfully uploaded and deleted from device	51	2	54.748
50:16.5	Audit log successfully uploaded			
50:16.7	Audit log successfully uploaded and deleted from device	51	2	54.748
50:19.8	Audit log successfully uploaded			
50:20.0	Audit log successfully uploaded and deleted from device	51	2	54.748
50:40.1	Audit log successfully uploaded			
50:40.3	Audit log successfully uploaded and deleted from device	51	2	54.747
50:41.1	Video successfully uploaded from device when dockec			e0ba971f74ff42d3844afb003288587f
50:41.4	Video deleted from device when docked	51	1	55.004 e0ba971f74ff42d3844afb003288587f
50:41.5	Audit log rolled	51	1	55.004
50:41.5	Audit log created	51	1 1.15.14	55.004
50:41.7	Video upload started when camera was docked			f0e23077da244e00b829cafe2cf8bf99
51:02.4	Audit log successfully uploaded			
51:02.6	Audit log successfully uploaded and deleted from device	52	1	55.004
51:21.2	Video successfully uploaded from device when dockec			f0e23077da244e00b829cafe2cf8bf99
51:21.5	Video deleted from device when docked	52	0	55.162 f0e23077da244e00b829cafe2cf8bf99
51:21.6	Audit log created	52	0 1.15.14	55.162
51:21.6	Audit log rolled	52	0	55.162
51:21.6	Audit log rolled	52	0	55.162
51:21.6	Audit log created	52	0 1.15.14	55.162

51:36.6 Device disconnected from charger	52	0	55.162
51:36.7 Camera disconnected from Axon Dock X62001V12	52	0	55.163
51:21.0 Audit log created	46	0 1.15.14	55.167
51:21.0 Audit log created	40	0 1.15.14	55.165
11:04.8 Camera connected to Axon Dock X630020W7	38	0	55.165
11:04.9 Audit log created	38	0 1.15.14	55.165
11:04.9 Audit log rolled	38	0	55.165
11:05.6 Device connected to charger	38	0	55.165
11:04.0 Audit log created	66	0 1.15.14	55.164
11:04.0 Audit log created	92	0 1.15.14	55.164
11:04.0 Audit log created	100	0 1.15.14	55.163
11:04.0 Audit log created	100	0 1.15.14	55.163
11:04.0 Audit log created	100	0 1.15.14	55.162
11:04.0 Audit log created	100	0 1.15.14	55.162
11:04.1 Audit log created	100	0 1.15.14	55.162
11:04.1 Audit log created	100	0 1.15.14	55.162
11:04.1 Audit log created	100	0 1.15.14	55.161
11:04.1 Audit log created	100	0 1.15.14	55.162
11:04.1 Audit log created	100	0 1.15.14	55.163
11:04.1 Audit log created	100	0 1.15.14	55.163
11:04.1 Audit log created	100	0 1.15.14	55.163
36:41.5 Camera disconnected from Axon Dock X630020W7	100	0	55.162
36:41.5 Device disconnected from charger	100	0	55.164
11:04.1 Audit log created	96	0 1.15.14	55.163
28:37.7 Event button pressed			
28:37.9 Event button released			
28:37.9 Event button pressed			
28:37.9 Audio recording enabled due to video recording default			
28:38.0 Event button released			
28:38.1 Recording started due to button press	94	1	55.162 3212ea15ee824ec686a7987f4bbb5d58
36:09.5 Event button pressed			
36:12.5 Recording stopped due to button press	92	1	54.863 3212ea15ee824ec686a7987f4bbb5d58
36:13.2 Audio recording disabled due to video buffering default			
36:13.6 Event button released			
11:04.1 Audit log created	89	1 1.15.14	54.861
05:07.3 Axon application connected to device			
05:54.7 Title changed in video metadata from 'Axon Body 3 Video 2021-08-25 2028 X6033271L' to 'Sig. 57 N6' using Axon applicator			3212ea15ee824ec686a7987f4bbb5d58
05:54.7 Categories 'Loud Radio' added to video metadata using Axon applicator			3212ea15ee824ec686a7987f4bbb5d58
06:08.0 Axon application disconnected from device			
11:04.1 Audit log created	83	1 1.15.14	54.859
11:04.1 Audit log created	77	1 1.15.14	54.858
11:04.1 Audit log created	71	1 1.15.14	54.857
22:08.9 Volume up button pressed			
22:08.9 Volume up button released			
22:09.1 Volume changed to high from medium using button			
22:13.2 Volume down button pressed			
22:13.4 Volume down button released			

22:13.6	Volume changed to medium from high using button				
22:16.9	Camera connected to Axon Dock X62001V12	71	1	54.864	
22:16.9	Audit log created	71	1 1.15.14	54.856	
22:16.9	Audit log rolled	71	1	54.856	
22:18.5	Device connected to charger	71	1	54.856	
22:34.6	Video upload started when camera was docked				3212ea15ee824ec686a7987f4bbb5d58
22:37.3	Audit log successfully uploaded				
22:37.5	Audit log successfully uploaded and deleted from device	71	1	54.864	
22:47.0	Date/Time synced to 08/26/2021 12:22:47.01 AM from 08/26/2021 12:22:46.91 AM				
22:57.9	Audit log successfully uploaded				
22:58.1	Audit log successfully uploaded and deleted from device	71	1	54.864	
23:26.2	Audit log successfully uploaded				
23:26.4	Audit log successfully uploaded and deleted from device	71	1	54.864	
23:31.6	Audit log successfully uploaded				
23:31.7	Audit log successfully uploaded and deleted from device	71	1	54.864	
23:44.8	Audit log successfully uploaded				
23:45.0	Audit log successfully uploaded and deleted from device	71	1	54.864	
23:55.1	Audit log successfully uploaded				
23:55.3	Audit log successfully uploaded and deleted from device	71	1	54.864	
23:57.1	Video successfully uploaded from device when docked				3212ea15ee824ec686a7987f4bbb5d58
23:57.4	Video deleted from device when docked	71	0	55.162	3212ea15ee824ec686a7987f4bbb5d58
23:57.5	Audit log rolled	71	0	55.164	
23:57.5	Audit log created	71	0 1.15.14	55.164	
23:57.6	Audit log created	71	0 1.15.14	55.164	
23:57.6	Audit log rolled	71	0	55.164	
24:06.5	Audit log successfully uploaded				
24:06.7	Audit log successfully uploaded and deleted from device	71	0	55.164	
24:31.8	Audit log successfully uploaded				
24:32.0	Audit log successfully uploaded and deleted from device	71	0	55.164	
24:37.2	Audit log successfully uploaded				
24:37.5	Audit log successfully uploaded and deleted from device	71	0	55.164	
25:04.6	Audit log successfully uploaded				
25:04.8	Audit log successfully uploaded and deleted from device	72	0	55.164	
25:30.9	Audit log successfully uploaded				
25:31.1	Audit log successfully uploaded and deleted from device	72	0	55.164	
25:33.3	Audit log successfully uploaded				
25:33.5	Audit log successfully uploaded and deleted from device	72	0	55.164	
25:45.6	Audit log successfully uploaded				
25:45.8	Audit log successfully uploaded and deleted from device	72	0	55.164	
25:58.9	Audit log successfully uploaded				
25:59.1	Audit log successfully uploaded and deleted from device	72	0	55.164	
26:21.3	Audit log successfully uploaded				
26:21.5	Audit log successfully uploaded and deleted from device	72	0	55.164	
26:41.6	Audit log successfully uploaded				
26:41.8	Audit log successfully uploaded and deleted from device	73	0	55.164	
27:08.9	Audit log successfully uploaded				
27:09.1	Audit log successfully uploaded and deleted from device	73	0	55.164	

27:13.3	Audit log successfully uploaded			
27:13.5	Audit log successfully uploaded and deleted from device	73	0	55.164
27:18.6	Audit log successfully uploaded			
27:18.8	Audit log successfully uploaded and deleted from device	73	0	55.164
27:42.0	Audit log successfully uploaded			
27:42.2	Audit log successfully uploaded and deleted from device	73	0	55.163
27:51.3	Audit log successfully uploaded			
27:51.6	Audit log successfully uploaded and deleted from device	73	0	55.163
28:14.7	Audit log successfully uploaded			
28:14.9	Audit log successfully uploaded and deleted from device	73	0	55.163
28:42.0	Audit log successfully uploaded			
28:42.2	Audit log successfully uploaded and deleted from device	73	0	55.163
28:56.4	Audit log successfully uploaded			
28:56.6	Audit log successfully uploaded and deleted from device	74	0	55.163
29:02.7	Audit log successfully uploaded			
29:02.8	Audit log successfully uploaded and deleted from device	74	0	55.163
29:08.0	Audit log successfully uploaded			
29:08.2	Audit log successfully uploaded and deleted from device	74	0	55.163
29:36.3	Audit log successfully uploaded			
29:36.5	Audit log successfully uploaded and deleted from device	74	0	55.163
40:55.5	Device disconnected from charger	80	0	55.165
40:56.1	Camera disconnected from Axon Dock X62001V12	80	0	55.168
23:57.0	Audit log created	74	0 1.15.14	55.167
23:57.0	Audit log created	67	0 1.15.14	55.166
24:33.1	Audio recording enabled due to video recording default			
24:33.3	Recording started due to Axon Signal Sidearm activation	67	1	55.165 6de9d9fceb6e4878ad92d5a423c6b7d5
24:35.9	Event button pressed			
24:38.9	Recording stopped due to button press	67	1	55.153 6de9d9fceb6e4878ad92d5a423c6b7d5
24:39.6	Event button released			
24:39.9	Audio recording disabled due to video buffering default			
08:23.0	Power button pressed			
08:26.1	Device powered off using button	63	1	55.101
08:26.6	Power button released			
01:21.0	Audit log created		1.15.14	
01:21.1	Device powered on using button	63	1	55.101
01:23.2	Audio recording disabled due to video buffering default			
01:37.4	Axon application connected to device			
02:32.1	Title changed in video metadata from 'Axon Body 3 Video 2021-08-26 0224 X6033271L' to 'Accidental Recording' using Axon applicator			6de9d9fceb6e4878ad92d5a423c6b7d5
02:32.1	Categories 'Accidental Recording' added to video metadata using Axon applicator			6de9d9fceb6e4878ad92d5a423c6b7d5
02:45.3	Axon application disconnected from device			
02:55.8	Camera connected to Axon Dock X62001V12	63	1	55.103
02:55.8	Audit log rolled	62	1	55.101
02:55.8	Audit log created	62	1 1.15.14	55.101
02:56.1	Device connected to charger	62	1	55.101
03:08.8	Video upload started when camera was docked			6de9d9fceb6e4878ad92d5a423c6b7d5
03:09.7	Audit log successfully uploaded			
03:09.9	Audit log successfully uploaded and deleted from device	62	1	55.103

03:23.0	Audit log successfully uploaded			
03:23.1	Audit log successfully uploaded and deleted from device	63	1	55.103
03:23.9	Audit log successfully uploaded			
03:24.1	Audit log successfully uploaded and deleted from device	63	1	55.103
03:27.0	Date/Time synced to 08/26/2021 04:03:27.01 AM from 08/26/2021 04:03:25.92 AM			
03:27.4	Video successfully uploaded from device when dockec			6de9d9fceb6e4878ad92d5a423c6b7d5
03:27.7	Video deleted from device when docked	63	0	55.167 6de9d9fceb6e4878ad92d5a423c6b7d5
03:27.7	Audit log created	63	0 1.15.14	55.167
03:27.7	Audit log rolled	63	0	55.167
03:27.7	Audit log created	63	0 1.15.14	55.167
03:27.7	Audit log rolled	63	0	55.167
03:33.2	Audit log successfully uploaded			
03:33.4	Audit log successfully uploaded and deleted from device	63	0	55.167
03:41.6	Audit log successfully uploaded			
03:41.9	Audit log successfully uploaded and deleted from device	63	0	55.167
03:51.1	Audit log successfully uploaded			
03:51.3	Audit log successfully uploaded and deleted from device	63	0	55.167
11:28.9	Camera disconnected from Axon Dock X62001V12	66	0	55.167
11:28.9	Device disconnected from charger	66	0	55.167
03:27.0	Audit log created	61	0 1.15.14	55.166
03:27.0	Audit log created	53	0 1.15.14	55.164
27:48.8	Volume up button pressed			
27:48.8	Volume up button released			
27:48.9	Volume changed to high from medium using button			
27:52.0	Volume down button pressed			
27:52.3	Volume down button released			
27:52.4	Volume changed to medium from high using button			
27:55.9	Camera connected to Axon Dock X630020W7	50	0	55.166
27:56.0	Audit log rolled	50	0	55.164
27:56.0	Audit log created	50	0 1.15.14	55.166
27:56.9	Device connected to charger	50	0	55.166
27:55.0	Audit log created	79	0 1.15.14	55.165
27:55.0	Audit log created	100	0 1.15.14	55.164
27:55.0	Audit log created	100	0 1.15.14	55.164
27:55.0	Audit log created	100	0 1.15.14	55.164
27:55.0	Audit log created	100	0 1.15.14	55.163
27:55.0	Audit log created	100	0 1.15.14	55.163
27:55.0	Audit log created	100	0 1.15.14	55.163
27:55.0	Audit log created	100	0 1.15.14	55.163
27:55.0	Audit log created	100	0 1.15.14	55.163
27:55.1	Audit log created	100	0 1.15.14	55.162
27:55.1	Audit log created	100	0 1.15.14	55.162
27:55.1	Audit log created	100	0 1.15.14	55.162
27:55.1	Audit log created	100	0 1.15.14	55.162
27:55.1	Audit log created	100	0 1.15.14	55.162
30:53.9	Camera disconnected from Axon Dock X630020W7	100	0	55.163
30:53.9	Device disconnected from charger	100	0	55.163
27:55.1	Audit log created	93	0 1.15.14	55.163

27:55.1 Audit log created	87	0 1.15.14	55.162
27:55.1 Audit log created	82	0 1.15.14	55.161
27:55.1 Audit log created	76	0 1.15.14	55.159
27:55.1 Audit log created	70	0 1.15.14	55.158
27:55.1 Audit log created	63	0 1.15.14	55.156
47:39.4 Event button pressed			
47:39.5 Event button released			
47:39.6 Event button pressed			
47:39.6 Audio recording enabled due to video recording default			
47:39.7 Event button released			
47:39.8 Recording started due to button press	62	0	55.156 bcb391de261b468ebe3dac00dfada8bb
54:26.0 Event button pressed			
54:29.0 Recording stopped due to button press	61	1	54.882 bcb391de261b468ebe3dac00dfada8bb
54:29.8 Audio recording disabled due to video buffering default			
54:30.1 Event button released			
59:48.1 Event button pressed			
59:48.2 Event button released			
59:48.3 Event button pressed			
59:48.3 Audio recording enabled due to video recording default			
59:48.4 Event button released			
59:48.5 Recording started due to button press	60	2	54.88 377cfebbbad8474a9b6f0d6afd436117
07:12.5 Event button pressed			
07:15.5 Recording stopped due to button press	58	2	54.583 377cfebbbad8474a9b6f0d6afd436117
07:16.1 Event button released			
07:16.3 Audio recording disabled due to video buffering default			
27:55.1 Audit log created	56	2 1.15.14	54.582
33:50.5 Axon application connected to device			
34:19.2 Video played back using Axon application			bcb391de261b468ebe3dac00dfada8bb
35:00.3 Title changed in video metadata from 'Axon Body 3 Video 2021-08-27 0147 X6033271L' to 'Sig. 31/70 N2' using Axon applicator			bcb391de261b468ebe3dac00dfada8bb
35:00.3 Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			bcb391de261b468ebe3dac00dfada8bb
35:55.4 Title changed in video metadata from 'Axon Body 3 Video 2021-08-27 0159 X6033271L' to 'Sig. 31/70 N4' using Axon applicator			377cfebbbad8474a9b6f0d6afd436117
35:55.4 Categories 'Sleeper', 'Loitering' added to video metadata using Axon applicator			377cfebbbad8474a9b6f0d6afd436117
36:02.4 Axon application disconnected from device			
39:10.6 Camera connected to Axon Dock X62001V12	54	2	54.592
39:10.6 Audit log rolled	54	2	54.581
39:10.6 Audit log created	54	2 1.15.14	54.581
39:11.9 Device connected to charger	54	2	54.583
39:30.9 Video upload started when camera was docked			bcb391de261b468ebe3dac00dfada8bb
39:41.0 Date/Time synced to 08/27/2021 02:39:41.03 AM from 08/27/2021 02:39:40.65 AM			
39:52.1 Audit log successfully uploaded			
39:52.2 Audit log successfully uploaded and deleted from device	54	2	54.592
40:02.4 Audit log successfully uploaded			
40:02.5 Audit log successfully uploaded and deleted from device	55	2	54.592
40:13.7 Audit log successfully uploaded			
40:13.8 Audit log successfully uploaded and deleted from device	55	2	54.591
40:37.9 Audit log successfully uploaded			
40:38.1 Audit log successfully uploaded and deleted from device	55	2	54.591

40:43.3 Video successfully uploaded from device when dockec				bcb391de261b468ebe3dac00dfada8bb
40:43.6 Video deleted from device when docked	55	1	54.866	bcb391de261b468ebe3dac00dfada8bb
40:43.7 Audit log rolled	55	1	54.866	
40:43.7 Audit log created	55	1 1.15.14	54.866	
40:43.9 Video upload started when camera was docked				377cfebbbad8474a9b6f0d6afd436117
41:02.3 Audit log successfully uploaded				
41:02.5 Audit log successfully uploaded and deleted from device	55	1	54.866	
41:25.6 Audit log successfully uploaded				
41:25.7 Audit log successfully uploaded and deleted from device	55	1	54.866	
41:54.8 Audit log successfully uploaded				
41:55.0 Audit log successfully uploaded and deleted from device	56	1	54.866	
41:56.8 Video successfully uploaded from device when dockec				377cfebbbad8474a9b6f0d6afd436117
41:57.2 Video deleted from device when docked	56	0	55.161	377cfebbbad8474a9b6f0d6afd436117
41:57.2 Audit log rolled	56	0	55.162	
41:57.2 Audit log created	56	0 1.15.14	55.162	
41:57.3 Audit log created	56	0 1.15.14	55.162	
41:57.3 Audit log rolled	56	0	55.162	
42:08.2 Audit log successfully uploaded				
42:08.4 Audit log successfully uploaded and deleted from device	56	0	55.162	
42:10.5 Audit log successfully uploaded				
42:10.7 Audit log successfully uploaded and deleted from device	56	0	55.162	
42:28.8 Audit log successfully uploaded				
42:29.0 Audit log successfully uploaded and deleted from device	56	0	55.162	
42:57.2 Audit log successfully uploaded				
42:57.4 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:06.5 Audit log successfully uploaded				
43:06.6 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:09.8 Audit log successfully uploaded				
43:10.1 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:27.2 Audit log successfully uploaded				
43:27.4 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:37.5 Audit log successfully uploaded				
43:37.7 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:50.8 Audit log successfully uploaded				
43:51.0 Audit log successfully uploaded and deleted from device	56	0	55.162	
43:59.1 Audit log successfully uploaded				
43:59.3 Audit log successfully uploaded and deleted from device	56	0	55.162	
44:04.5 Audit log successfully uploaded				
44:04.7 Audit log successfully uploaded and deleted from device	56	0	55.162	
44:20.8 Audit log successfully uploaded				
44:20.9 Audit log successfully uploaded and deleted from device	56	0	55.162	
44:22.0 Audit log successfully uploaded				
44:22.2 Audit log successfully uploaded and deleted from device	56	0	55.162	
44:27.3 Audit log successfully uploaded				
44:27.6 Audit log successfully uploaded and deleted from device	56	0	55.162	
44:53.7 Audit log successfully uploaded				
44:53.9 Audit log successfully uploaded and deleted from device	57	0	55.162	

45:17.0	Audit log successfully uploaded			
45:17.2	Audit log successfully uploaded and deleted from device	57	0	55.162
45:22.3	Audit log successfully uploaded			
45:22.5	Audit log successfully uploaded and deleted from device	57	0	55.162
45:22.6	Audit log successfully uploaded			
45:22.8	Audit log successfully uploaded and deleted from device	57	0	55.162
45:31.9	Audit log successfully uploaded			
45:32.1	Audit log successfully uploaded and deleted from device	57	0	55.162
54:25.1	Camera disconnected from Axon Dock X62001V12	61	0	55.162
54:25.1	Device disconnected from charger	61	0	55.167
41:57.0	Audit log created	57	0 1.15.14	55.166
41:57.0	Audit log created	49	0 1.15.14	55.164
41:57.0	Audit log created	43	0 1.15.14	55.163
34:41.7	Camera connected to Axon Dock X630020W7	38	0	55.162
34:41.7	Audit log created	38	0 1.15.14	55.162
34:41.7	Audit log rolled	38	0	55.162
34:43.1	Device connected to charger	38	0	55.162
34:41.0	Audit log created	66	0 1.15.14	55.161
34:41.0	Audit log created	92	0 1.15.14	55.161
34:41.0	Audit log created	100	0 1.15.14	55.16
34:41.0	Audit log created	100	0 1.15.14	55.16
34:41.0	Audit log created	100	0 1.15.14	55.16
34:41.0	Audit log created	100	0 1.15.14	55.159
34:41.0	Audit log created	100	0 1.15.14	55.159
37:16.1	Camera disconnected from Axon Dock X630020W7	98	0	55.159
37:16.2	Device disconnected from charger	98	0	55.159
37:30.3	Power button pressed			
37:33.4	Device powered off using button	100	0	55.161
37:33.7	Power button released			
46:44.0	Audit log created		1.15.14	
46:44.1	Device powered on using button	100	0	55.16
46:46.1	Audio recording disabled due to video buffering default			
13:19.2	Power button pressed			
13:21.7	Power button released			
13:22.8	Power button pressed			
13:25.8	Device powered off using button	96	0	55.16
13:26.4	Power button released			
55:24.2	Audit log created		1.15.14	
55:24.3	Device powered on using button	96	0	55.159
55:27.4	Audio recording disabled due to video buffering default			
55:24.2	Audit log created	89	0 1.15.14	55.158
55:24.2	Audit log created	84	0 1.15.14	55.157
15:08.4	Power button pressed			
15:11.4	Device powered off using button	82	0	55.156
15:12.0	Power button released			
19:36.1	Audit log created		1.15.14	
19:36.2	Device powered on due to charger connection	82	0	55.156

19:36.4 Device connected to charger			
19:36.4 Camera connected to Axon Dock X630020W7	82	0	55.156
19:36.4 Audit log created		1.15.14	
19:36.4 Audit log rolled			
19:37.2 Camera connected to Axon Dock X630020W7	82	0	55.156
19:39.1 Audit log rolled	82	0	55.156
19:39.1 Audit log created	82	0 1.15.14	55.156
19:39.0 Audit log created	100	0 1.15.14	55.155
19:39.0 Audit log created	100	0 1.15.14	55.155
19:39.0 Audit log created	100	0 1.15.14	55.155
19:39.0 Audit log created	100	0 1.15.14	55.154
19:39.0 Audit log created	100	0 1.15.14	55.155
19:39.0 Audit log created	100	0 1.15.14	55.162
19:39.0 Audit log created	100	0 1.15.14	55.164
19:39.0 Audit log created	100	0 1.15.14	55.164
19:39.0 Audit log created	100	0 1.15.14	55.164
31:12.2 Device disconnected from charger	100	0	55.164
31:12.2 Camera disconnected from Axon Dock X630020W7	100	0	55.164
31:12.3 Audio recording disabled due to video buffering default			
31:14.8 Camera connected to Axon Dock X630020W7	100	0	55.165
31:14.8 Audit log created	100	0 1.15.14	55.165
31:14.8 Audit log rolled	100	0	55.165
31:15.2 Device connected to charger	100	0	55.165
31:14.0 Audit log created	100	0 1.15.14	55.165
31:14.0 Audit log created	100	0 1.15.14	55.165
31:14.0 Audit log created	100	0 1.15.14	55.165
12:49.2 Device disconnected from charger	100	0	55.165
12:49.3 Camera disconnected from Axon Dock X630020W7	100	0	55.165
31:14.0 Audit log created	97	0 1.15.14	55.165
31:14.0 Audit log created	91	0 1.15.14	55.163
51:02.1 Select button pressed			
51:02.2 Select button released			
51:14.2 Programmable button pressed			
51:14.5 Programmable button released			
31:14.0 Audit log created	85	0 1.15.14	55.162
31:14.0 Audit log created	79	0 1.15.14	55.16
31:14.1 Audit log created	73	0 1.15.14	55.159
31:14.1 Audit log created	67	0 1.15.14	55.158
45:32.1 Power button pressed			
45:35.1 Device powered off using button	65	0	55.157
45:35.6 Power button released			
36:19.9 Audit log created		1.15.14	
36:20.1 Device powered on using button	65	0	55.16
36:22.1 Audio recording disabled due to video buffering default			
42:51.3 Power button pressed			
42:52.2 Power button released			
42:53.4 Power button pressed			

42:56.4 Device powered off using button	65	0	55.16
42:56.8 Power button released			
43:46.2 Device powered on using button	65	0	55.159
43:48.3 Audio recording disabled due to video buffering default			
25:04.5 Power button pressed			
25:07.5 Device powered off using button	61	0	55.158
25:08.1 Power button released			
33:48.9 Audit log created		1.15.14	
33:49.0 Device powered on due to charger connection	61	0	55.158
33:49.3 Device connected to charger			
33:49.3 Camera connected to Axon Dock X630020W7	61	0	55.157
33:49.3 Audit log rolled			
33:49.3 Audit log created		1.15.14	
33:50.0 Camera connected to Axon Dock X630020W7	61	0	55.157
33:51.9 Audit log created	61	0 1.15.14	55.158
33:51.9 Audit log rolled	61	0	55.158
33:51.0 Audit log created	89	0 1.15.14	55.157
33:51.0 Audit log created	100	0 1.15.14	55.156
33:51.0 Audit log created	100	0 1.15.14	55.156
33:51.0 Audit log created	100	0 1.15.14	55.156
33:51.0 Audit log created	100	0 1.15.14	55.155
33:51.0 Audit log created	100	0 1.15.14	55.155
33:51.0 Audit log created	100	0 1.15.14	55.155
33:51.0 Audit log created	100	0 1.15.14	55.155
33:51.1 Audit log created	100	0 1.15.14	55.155
33:51.1 Audit log created	100	0 1.15.14	55.154
33:51.1 Audit log created	100	0 1.15.14	55.157
33:51.1 Audit log created	100	0 1.15.14	55.156
33:51.1 Audit log created	100	0 1.15.14	55.158
57:13.0 Device disconnected from charger	98	0	55.158
57:13.3 Camera disconnected from Axon Dock X630020W7	98	0	55.158
57:13.4 Audio recording disabled due to video buffering default			
57:37.2 Power button pressed			
57:40.2 Device powered off using button	100	0	55.158
57:40.7 Power button released			
09:34.0 Audit log created		1.15.14	
09:34.1 Device powered on using button	100	0	55.157
09:36.2 Audio recording disabled due to video buffering default			
31:55.0 Event button pressed			
31:55.1 Event button released			
31:55.2 Event button pressed			
31:55.3 Audio recording enabled due to video recording default			
31:55.3 Event button released			
31:55.5 Recording started due to button press	97	0	55.156 6fd8de1b4b744a3881c3725218848dca
32:49.5 Event button pressed			
32:52.6 Recording stopped due to button press	97	1	55.066 6fd8de1b4b744a3881c3725218848dca
32:52.6 Event button released			
32:53.3 Audio recording disabled due to video buffering default			

32:58.2 Event button pressed			
33:00.1 Event button released			
33:00.4 Event button pressed			
33:00.5 Event button released			
33:00.6 Event button pressed			
33:00.6 Audio recording enabled due to video recording default			
33:00.7 Event button released			
33:00.7 Recording started due to button press	97	2	55.065 5ea11a0085ab478eb3b5c56820be12f1
34:38.0 Event button pressed			
34:41.0 Recording stopped due to button press	96	2	55.01 5ea11a0085ab478eb3b5c56820be12f1
34:41.6 Event button released			
34:41.8 Audio recording disabled due to video buffering default			
36:09.7 Event button pressed			
36:09.7 Event button released			
36:09.8 Event button pressed			
36:09.8 Audio recording enabled due to video recording default			
36:09.9 Event button released			
36:10.0 Recording started due to button press	96	3	55.009 82edb796496547719a0b87e8cfe5e096
37:37.7 Event button pressed			
37:40.7 Recording stopped due to button press	96	3	54.917 82edb796496547719a0b87e8cfe5e096
37:41.2 Event button released			
37:41.3 Audio recording disabled due to video buffering default			
38:19.0 Event button pressed			
38:19.1 Event button released			
38:19.2 Event button pressed			
38:19.3 Audio recording enabled due to video recording default			
38:19.3 Event button released			
38:19.4 Recording started due to button press	96	4	54.916 16f44e681edc42c38315a983890fdc2d
47:33.3 Event button pressed			
47:36.3 Recording stopped due to button press	94	4	54.605 16f44e681edc42c38315a983890fdc2d
47:37.2 Audio recording disabled due to video buffering default			
47:38.0 Event button released			
49:34.9 Event button pressed			
49:35.7 Event button released			
49:35.9 Event button pressed			
49:36.0 Event button released			
49:37.3 Event button pressed			
49:37.4 Event button released			
49:37.5 Event button pressed			
49:37.5 Audio recording enabled due to video recording default			
49:37.7 Event button released			
49:37.7 Recording started due to button press	93	5	54.603 9f3301be39de423499ea8025d62fa1df
49:51.0 Event button pressed			
49:51.2 Event button released			
49:51.3 Event button pressed			
49:57.9 Event button released			
49:58.4 Event button pressed			

50:01.4 Recording stopped due to button press	93	5	54.549 9f3301be39de423499ea8025d62fa1df
50:01.9 Event button released			
50:02.3 Audio recording disabled due to video buffering default			
50:10.3 Event button pressed			
50:10.5 Event button released			
50:10.6 Event button pressed			
50:10.6 Audio recording enabled due to video recording default			
50:10.7 Event button released			
50:10.7 Recording started due to button press	93	5	54.533 0f6f698872a84ad8bce79e97844826d2
50:25.1 Event button pressed			
50:28.1 Recording stopped due to button press	93	6	54.517 0f6f698872a84ad8bce79e97844826d2
50:28.6 Event button released			
50:28.8 Audio recording disabled due to video buffering default			
50:49.1 Event button pressed			
50:49.3 Event button released			
50:49.4 Event button pressed			
50:49.4 Audio recording enabled due to video recording default			
50:49.5 Recording started due to button press	93	7	54.516 729c6c0580584261a0e73c181ccd98b7
50:49.6 Event button released			
51:04.1 Event button pressed			
51:07.1 Recording stopped due to button press	93	7	54.497 729c6c0580584261a0e73c181ccd98b7
51:07.6 Event button released			
51:07.9 Audio recording disabled due to video buffering default			
51:13.2 Event button pressed			
51:13.3 Event button released			
51:13.4 Event button pressed			
51:13.4 Audio recording enabled due to video recording default			
51:13.5 Event button released			
51:13.6 Recording started due to button press	93	8	54.496 85116a4ca70e437d827698cf9d0cb6e9
51:29.5 Event button pressed			
51:32.5 Recording stopped due to button press	93	8	54.484 85116a4ca70e437d827698cf9d0cb6e9
51:33.1 Event button released			
51:33.3 Audio recording disabled due to video buffering default			
51:36.3 Event button pressed			
51:36.7 Event button released			
51:36.9 Event button pressed			
51:36.9 Audio recording enabled due to video recording default			
51:37.0 Event button released			
51:37.0 Event button pressed			
51:37.0 Recording started due to button press	93	9	54.483 2a711e1e20bf4686bef17942da70dc72
51:37.1 Event button released			
51:50.1 Event button pressed			
51:53.1 Recording stopped due to button press	93	9	54.473 2a711e1e20bf4686bef17942da70dc72
51:53.6 Event button released			
51:54.1 Audio recording disabled due to video buffering default			
52:00.5 Event button pressed			
52:00.7 Event button released			

52:00.8	Event button pressed			
52:00.8	Audio recording enabled due to video recording default			
52:00.9	Event button released			
52:00.9	Recording started due to button press	93	10	54.473 65ba696db3274ef181a6b2b21135cdf3
52:17.0	Event button pressed			
52:20.0	Recording stopped due to button press	93	10	54.459 65ba696db3274ef181a6b2b21135cdf3
52:20.5	Event button released			
52:20.7	Audio recording disabled due to video buffering default			
52:25.3	Event button pressed			
52:25.5	Event button released			
52:25.6	Event button pressed			
52:25.6	Audio recording enabled due to video recording default			
52:25.7	Event button released			
52:25.7	Recording started due to button press	93	11	54.459 2d035c9bdb5948c2a85d4d8c2e205d1a
53:04.3	Event button pressed			
53:07.3	Recording stopped due to button press	92	11	54.435 2d035c9bdb5948c2a85d4d8c2e205d1a
53:08.0	Audio recording disabled due to video buffering default			
53:09.0	Event button released			
04:09.0	Axon application connected to device			
04:29.2	Axon application connected to device			
07:30.1	Video played back using Axon application			6fd8de1b4b744a3881c3725218848dca
07:57.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1631 X6033271L' to 'Sig. 15 NE8' using Axon applicator			6fd8de1b4b744a3881c3725218848dca
07:57.1	Categories 'Customer Assist' added to video metadata using Axon applicator			6fd8de1b4b744a3881c3725218848dca
09:34.0	Audit log created	91	11 1.15.14	54.432
11:07.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1633 X6033271L' to 'Sig. 75 NE8' using Axon applicator			5ea11a0085ab478eb3b5c56820be12f1
11:07.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			5ea11a0085ab478eb3b5c56820be12f1
15:08.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1636 X6033271L' to 'Sig 65e NE10' using Axon applicator			82edb796496547719a0b87e8cfe5e096
15:08.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			82edb796496547719a0b87e8cfe5e096
16:00.2	Video played back using Axon application			16f44e681edc42c38315a983890fdc2d
17:19.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1638 X6033271L' to 'Sig. 65 NE10 Backing Up 3610' using Axon applicatio			16f44e681edc42c38315a983890fdc2d
18:24.1	Title changed in video metadata from 'Sig 65e NE10' to 'Sig. 75 NE8 Lots + BUS LOOP' using Axon applicator			82edb796496547719a0b87e8cfe5e096
20:26.7	Event button pressed			
20:26.9	Event button released			
20:27.0	Event button pressed			
20:27.0	Audio recording enabled due to video recording default			
20:27.1	Event button released			
20:27.2	Recording started due to button press	89	12	54.431 331434c74164479a96c697bcf2604301
28:56.1	Event button pressed			
28:59.2	Recording stopped due to button press	88	12	54.103 331434c74164479a96c697bcf2604301
28:59.9	Audio recording disabled due to video buffering default			
29:00.4	Event button released			
33:42.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1649 X6033271L' to 'Sig. 75s NE10 Car 142' using Axon applicator			9f3301be39de423499ea8025d62fa1df
33:42.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			9f3301be39de423499ea8025d62fa1df
34:10.7	Video played back using Axon application			0f6f698872a84ad8bce79e97844826d2
35:11.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1650 X6033271L' to 'Sig. 75s NE10 Car 141' using Axon applicator			0f6f698872a84ad8bce79e97844826d2
35:11.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			0f6f698872a84ad8bce79e97844826d2
36:07.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1650 X6033271L' to 'Sig. 75s NE10 Car' using Axon applicator			729c6c0580584261a0e73c181ccd98b7

36:07.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				729c6c0580584261a0e73c181ccd98b7
36:15.2	Video played back using Axon application				729c6c0580584261a0e73c181ccd98b7
36:52.7	Title changed in video metadata from 'Sig. 75s NE10 Car' to 'Sig. 75s NE10 Car 290' using Axon application				729c6c0580584261a0e73c181ccd98b7
37:23.0	Video played back using Axon application				85116a4ca70e437d827698cf9d0cb6e9
38:04.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1651 X6033271L' to 'Sig. 75s NE10 Car 289' using Axon applicator				85116a4ca70e437d827698cf9d0cb6e9
38:04.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				85116a4ca70e437d827698cf9d0cb6e9
39:03.1	Video played back using Axon application				2a711e1e20bf4686bef17942da70dc72
39:53.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1651 X6033271L' to 'Sig. 75s NE10 Car 224' using Axon applicator				2a711e1e20bf4686bef17942da70dc72
39:53.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				2a711e1e20bf4686bef17942da70dc72
40:23.6	Video played back using Axon application				65ba696db3274ef181a6b2b21135cdf3
41:55.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1652 X6033271L' to 'Sig. 75s NE10 Car 223' using Axon applicator				65ba696db3274ef181a6b2b21135cdf3
41:55.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				65ba696db3274ef181a6b2b21135cdf3
42:45.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1652 X6033271L' to 'Sig.75 NE10 Platform' using Axon applicator				2d035c9bdb5948c2a85d4d8c2e205d1a
42:45.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				2d035c9bdb5948c2a85d4d8c2e205d1a
43:43.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1720 X6033271L' to 'Sig. 65e NE10 Backing Up 3610' using Axon applicator				331434c74164479a96c697bcf2604301
43:43.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				331434c74164479a96c697bcf2604301
44:15.7	Event button pressed				
44:16.3	Event button released				
44:16.4	Event button pressed				
44:16.5	Audio recording enabled due to video recording default				
44:16.6	Event button released				
44:16.6	Recording started due to button press	86	13	54.1	fd7c34ae1c1c4f4797140bbe55e9d418
44:16.6	Event button pressed				
44:16.8	Event button released				
44:37.6	Event button pressed				
44:40.6	Recording stopped due to button press	86	13	54.046	fd7c34ae1c1c4f4797140bbe55e9d418
44:41.1	Event button released				
44:41.3	Audio recording disabled due to video buffering default				
45:01.6	Event button pressed				
45:02.0	Event button released				
45:02.1	Event button pressed				
45:02.2	Audio recording enabled due to video recording default				
45:02.3	Event button released				
45:02.3	Recording started due to button press	86	14	54.027	219548e5195f40f2809a4be202f1357a
45:17.2	Event button pressed				
45:20.2	Recording stopped due to button press	86	14	54.007	219548e5195f40f2809a4be202f1357a
45:20.7	Event button released				
45:21.1	Audio recording disabled due to video buffering default				
45:32.0	Event button pressed				
45:32.1	Event button released				
45:32.2	Event button pressed				
45:32.3	Audio recording enabled due to video recording default				
45:32.3	Event button released				
45:32.4	Recording started due to button press	86	15	54.007	6e72b15c37ce4341a6596dec7ab3922a
45:46.9	Event button pressed				
45:49.9	Recording stopped due to button press	86	15	53.992	6e72b15c37ce4341a6596dec7ab3922a
45:50.5	Event button released				

45:50.7	Audio recording disabled due to video buffering default			
45:58.1	Event button pressed			
46:00.6	Event button released			
46:01.3	Event button pressed			
46:01.4	Event button released			
46:01.5	Event button pressed			
46:01.5	Audio recording enabled due to video recording default			
46:01.6	Event button released			
46:01.6	Recording started due to button press	86	16	53.991 7faae75360e6465783a85287e2fb6227
46:15.0	Event button pressed			
46:18.0	Recording stopped due to button press	85	16	53.978 7faae75360e6465783a85287e2fb6227
46:18.4	Event button released			
46:18.9	Audio recording disabled due to video buffering default			
46:30.5	Event button pressed			
46:30.7	Event button released			
46:30.7	Event button pressed			
46:30.8	Audio recording enabled due to video recording default			
46:30.8	Event button released			
46:30.9	Recording started due to button press	85	17	53.977 83e489cc3c204819a5881692440c2499
46:48.2	Event button pressed			
46:51.2	Recording stopped due to button press	85	17	53.961 83e489cc3c204819a5881692440c2499
46:51.7	Event button released			
46:52.1	Audio recording disabled due to video buffering default			
46:55.1	Event button pressed			
46:55.3	Event button released			
46:55.4	Event button pressed			
46:55.4	Audio recording enabled due to video recording default			
46:55.5	Event button released			
46:55.5	Recording started due to button press	85	18	53.96 f9c2be91f63d456f9c85e534d8fa4a9b
47:12.9	Event button pressed			
47:15.9	Recording stopped due to button press	85	18	53.948 f9c2be91f63d456f9c85e534d8fa4a9b
47:16.4	Event button released			
47:16.7	Audio recording disabled due to video buffering default			
47:35.3	Event button pressed			
47:35.4	Event button released			
47:35.5	Event button pressed			
47:35.5	Audio recording enabled due to video recording default			
47:35.7	Event button released			
47:35.7	Recording started due to button press	85	19	53.947 cd44da9235ac4ec2b1dad540b1380866
48:48.2	Event button pressed			
48:48.3	Event button released			
48:48.4	Event button pressed			
48:48.5	Event button released			
48:54.4	Event button pressed			
48:57.4	Recording stopped due to button press	85	19	53.895 cd44da9235ac4ec2b1dad540b1380866
48:58.0	Event button released			
48:58.3	Audio recording disabled due to video buffering default			

49:14.2	Event button pressed			
49:14.3	Event button released			
49:14.4	Event button pressed			
49:14.4	Audio recording enabled due to video recording default			
49:14.5	Event button released			
49:14.6	Recording started due to button press	85	20	53.894 fb3343fd17d24e3a817a7e121d2982f5
59:37.0	Event button pressed			
59:40.0	Recording stopped due to button press	83	20	53.557 fb3343fd17d24e3a817a7e121d2982f5
59:40.5	Event button released			
59:40.8	Audio recording disabled due to video buffering default			
01:29.1	Event button pressed			
01:29.3	Event button released			
01:29.3	Event button pressed			
01:29.4	Audio recording enabled due to video recording default			
01:29.5	Event button released			
01:29.5	Recording started due to button press	83	21	53.555 668377f9af2042a28832ae7aa85f938c
09:34.1	Audit log created	82	21 1.15.14	53.244
18:05.4	Event button pressed			
18:08.4	Recording stopped due to button press	80	21	52.973 668377f9af2042a28832ae7aa85f938c
18:08.9	Event button released			
18:09.3	Audio recording disabled due to video buffering default			
34:05.2	Event button pressed			
34:05.2	Event button released			
34:05.3	Event button pressed			
34:05.3	Audio recording enabled due to video recording default			
34:05.4	Event button released			
34:05.5	Recording started due to button press	79	22	52.97 0cff589f24714e54ae94a278e688fb00
38:23.7	Event button pressed			
38:26.7	Recording stopped due to button press	78	22	52.772 0cff589f24714e54ae94a278e688fb00
38:27.2	Event button released			
38:27.4	Audio recording disabled due to video buffering default			
03:15.9	Event button pressed			
03:16.0	Event button released			
03:16.1	Event button pressed			
03:16.1	Audio recording enabled due to video recording default			
03:16.2	Event button released			
03:16.2	Recording started due to button press	75	23	52.77 71ffa0c5c86443989378f2589e51e361
09:34.2	Audit log created	74	23 1.15.14	52.512
13:18.3	Event button pressed			
13:18.4	Event button released			
13:18.5	Event button pressed			
13:18.7	Event button released			
13:18.9	Event button pressed			
13:22.0	Recording stopped due to button press	74	23	52.393 71ffa0c5c86443989378f2589e51e361
13:22.6	Event button released			
13:22.8	Audio recording disabled due to video buffering default			
13:27.0	Event button pressed			

13:31.0	Event button released			
13:31.8	Event button pressed			
13:32.0	Event button released			
13:32.1	Event button pressed			
13:32.1	Audio recording enabled due to video recording default			
13:32.2	Event button released			
13:32.2	Recording started due to button press	73	24	52.391 f3dbe9299fc84d7b90abd5cad16b41a9
14:58.8	Event button pressed			
15:01.9	Recording stopped due to button press	73	24	52.339 f3dbe9299fc84d7b90abd5cad16b41a9
15:02.5	Event button released			
15:02.7	Audio recording disabled due to video buffering default			
15:35.8	Event button pressed			
15:35.9	Event button released			
15:36.0	Event button pressed			
15:36.0	Audio recording enabled due to video recording default			
15:36.1	Event button released			
15:36.1	Recording started due to button press	73	25	52.338 cb29a36c4f70412d87a3ad3e250734ca
16:01.4	Event button pressed			
16:04.4	Recording stopped due to button press	73	25	52.307 cb29a36c4f70412d87a3ad3e250734ca
16:05.1	Event button released			
16:05.2	Audio recording disabled due to video buffering default			
16:30.8	Event button pressed			
16:31.5	Event button released			
16:31.6	Event button pressed			
16:31.7	Event button released			
16:31.8	Event button pressed			
16:31.8	Audio recording enabled due to video recording default			
16:31.9	Event button released			
16:31.9	Recording started due to button press	73	26	52.306 de4dca4434ec400697d3d2ef38cc1cc9
17:40.2	Event button pressed			
17:43.2	Recording stopped due to button press	73	26	52.256 de4dca4434ec400697d3d2ef38cc1cc9
17:43.7	Event button released			
17:44.0	Audio recording disabled due to video buffering default			
20:09.8	Video played back using Axon application			fd7c34ae1c1c4f4797140bbe55e9d418
21:30.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1744 X6033271L' to '75s NE10 Train 303 Car 698' using Axon applicator			fd7c34ae1c1c4f4797140bbe55e9d418
21:30.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			fd7c34ae1c1c4f4797140bbe55e9d418
24:15.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1745 X6033271L' to '75s NE10 Train 303 Car 697' using Axon applicator			219548e5195f40f2809a4be202f1357a
24:15.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			219548e5195f40f2809a4be202f1357a
24:59.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1745 X6033271L' to '75s NE10 Train 303 Car 684' using Axon applicator			6e72b15c37ce4341a6596dec7ab3922a
24:59.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			6e72b15c37ce4341a6596dec7ab3922a
25:55.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			7faae75360e6465783a85287e2fb6227
26:14.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1746 X6033271L' to '75s NE10 Train 303 Car 683' using Axon applicator			7faae75360e6465783a85287e2fb6227
26:38.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1746 X6033271L' to '75s NE10 Train 303 Car 156' using Axon applicator			83e489cc3c204819a5881692440c2499
26:38.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			83e489cc3c204819a5881692440c2499
27:05.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1746 X6033271L' to '75s NE10 Train 303 Car 155' using Axon applicator			f9c2be91f63d456f9c85e534d8fa4a9b
27:05.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			f9c2be91f63d456f9c85e534d8fa4a9b
27:28.8	Video played back using Axon application			cd44da9235ac4ec2b1dad540b1380866

29:04.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1747 X6033271L' to '75 NE10 Platform + Concourse' using Axon applicati	cd44da9235ac4ec2b1dad540b1380866
29:04.1 Categories 'Miscellaneous' added to video metadata using Axon applicator	cd44da9235ac4ec2b1dad540b1380866
30:07.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1749 X6033271L' to '65s NE10 Platform Backing 3610' using Axon applica	fb3343fd17d24e3a817a7e121d2982f5
30:07.7 Categories 'Smoking/Eating' added to video metadata using Axon applicator	fb3343fd17d24e3a817a7e121d2982f5
30:36.7 Categories 'Smoking/Eating' added to video metadata using Axon applicator	16f44e681edc42c38315a983890fdc2d
30:59.9 Categories 'Miscellaneous' removed from video metadata using Axon applicator	331434c74164479a96c697bcf2604301
31:06.4 Categories 'Smoking/Eating' added to video metadata using Axon applicator	331434c74164479a96c697bcf2604301
32:18.4 Categories 'Wanted Person Located' added to video metadata using Axon applicator	668377f9af2042a28832ae7aa85f938c
32:18.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1801 X6033271L' to 'Sig. 83 NE10' using Axon applicator	668377f9af2042a28832ae7aa85f938c
33:06.1 Title changed in video metadata from 'Sig. 83 NE10' to 'Sig. 83 Out Of Dallas-TX NE10' using Axon applicator	668377f9af2042a28832ae7aa85f938c
33:21.8 Title changed in video metadata from 'Sig. 83 Out Of Dallas-TX NE10' to 'Sig. 83 NE10 Out Of Dallas-TX' using Axon applicator	668377f9af2042a28832ae7aa85f938c
34:22.3 Categories 'Person Detained', 'Wanted Person Located', 'Wagon Call' added to video metadata using Axon applicator	0cff589f24714e54ae94a278e688fb00
34:22.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1834 X6033271L' to 'Sig 83 NE10' using Axon applicator	0cff589f24714e54ae94a278e688fb00
35:38.3 Categories 'Miscellaneous' added to video metadata using Axon applicator	de4dca4434ec400697d3d2ef38cc1cc9
35:38.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1916 X6033271L' to 'Sig. 9 Escalator 1 NE8' using Axon applicator	de4dca4434ec400697d3d2ef38cc1cc9
36:51.4 Categories 'Miscellaneous' added to video metadata using Axon applicator	cb29a36c4f70412d87a3ad3e250734ca
36:51.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1915 X6033271L' to '75s NE8 Bus 1551 R47' using Axon applicator	cb29a36c4f70412d87a3ad3e250734ca
37:05.4 Title changed in video metadata from '75s NE8 Bus 1551 R47' to '75s NE8 Bus 1551 Route 47' using Axon applicator	cb29a36c4f70412d87a3ad3e250734ca
37:11.0 Video played back using Axon application	cb29a36c4f70412d87a3ad3e250734ca
38:30.1 Categories 'Disorderly Person' added to video metadata using Axon applicator	71ffa0c5c86443989378f2589e51e361
38:30.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1903 X6033271L' to 'Sig 23 NE8 Platform' using Axon applicator	71ffa0c5c86443989378f2589e51e361
39:08.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 1913 X6033271L' to '75 NE 8 Concourse + Bus Loop' using Axon applicati	f3dbe9299fc84d7b90abd5cad16b41a9
54:42.8 Axon application disconnected from device	
09:30.6 Event button pressed	
09:30.8 Event button released	
09:30.9 Event button pressed	
09:30.9 Audio recording enabled due to video recording default	
09:31.0 Event button released	
09:31.0 Recording started due to button press	67 27 52.252 f3381f9cd828435aa8dd0e3e5203610b
09:34.2 Audit log created	67 27 1.15.14 52.245
11:11.7 Event button pressed	
11:14.7 Recording stopped due to button press	66 27 52.137 f3381f9cd828435aa8dd0e3e5203610b
11:15.4 Event button released	
11:15.5 Audio recording disabled due to video buffering default	
19:01.6 Axon application connected to device	
19:35.8 Categories 'Customer Assist' added to video metadata using Axon applicator	f3381f9cd828435aa8dd0e3e5203610b
19:35.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2009 X6033271L' to 'Sig. 15 NE10' using Axon applicator	f3381f9cd828435aa8dd0e3e5203610b
21:06.6 Title changed in video metadata from 'Sig. 9 Escalator 1 NE8' to 'Sig. 75 + 9 Escalator 1 NE8' using Axon applicator	de4dca4434ec400697d3d2ef38cc1cc9
22:25.0 Axon application disconnected from device	
24:19.6 Event button pressed	
24:19.7 Event button released	
24:19.7 Event button pressed	
24:19.8 Audio recording enabled due to video recording default	
24:19.9 Event button released	
24:20.0 Recording started due to button press	65 28 52.135 230c14a9e14846419cc17badbb4cedf5
25:03.4 Event button pressed	
25:06.4 Recording stopped due to button press	65 28 52.051 230c14a9e14846419cc17badbb4cedf5

25:06.9	Event button released			
25:07.1	Audio recording disabled due to video buffering default			
25:30.7	Event button pressed			
25:30.9	Event button released			
25:31.0	Event button pressed			
25:31.0	Audio recording enabled due to video recording default			
25:31.0	Event button released			
25:31.2	Recording started due to button press	65	29	52.05 2845d5345dc845bbbb676cd7347b7793
25:53.0	Event button pressed			
25:56.0	Recording stopped due to button press	65	29	52.025 2845d5345dc845bbbb676cd7347b7793
25:56.5	Event button released			
25:56.8	Audio recording disabled due to video buffering default			
26:03.6	Event button pressed			
26:04.1	Event button released			
26:04.1	Event button pressed			
26:04.2	Audio recording enabled due to video recording default			
26:04.3	Recording started due to button press	65	30	52.025 0a5966a2e75b45fe96ae21ee1ae7ba72
26:04.4	Event button released			
26:19.7	Event button pressed			
26:22.7	Recording stopped due to button press	65	30	52.012 0a5966a2e75b45fe96ae21ee1ae7ba72
26:23.2	Event button released			
26:23.6	Audio recording disabled due to video buffering default			
26:33.6	Event button pressed			
26:33.7	Event button released			
26:33.8	Event button pressed			
26:33.9	Audio recording enabled due to video recording default			
26:33.9	Event button released			
26:34.0	Recording started due to button press	65	31	52.011 b65f693892f44d21a90016939617cf75
26:55.8	Event button pressed			
26:58.8	Recording stopped due to button press	65	31	51.993 b65f693892f44d21a90016939617cf75
26:59.3	Event button released			
26:59.5	Audio recording disabled due to video buffering default			
27:07.9	Event button pressed			
27:08.0	Event button released			
27:08.1	Event button pressed			
27:08.2	Audio recording enabled due to video recording default			
27:08.3	Recording started due to button press	65	32	51.992 16112e7d851e4b079dbbca1f9b21047e
27:08.3	Event button released			
27:22.7	Event button pressed			
27:25.7	Recording stopped due to button press	64	32	51.979 16112e7d851e4b079dbbca1f9b21047e
27:26.1	Event button released			
27:26.4	Audio recording disabled due to video buffering default			
27:33.3	Event button pressed			
27:33.4	Event button released			
27:33.5	Event button pressed			
27:33.5	Audio recording enabled due to video recording default			
27:33.6	Event button released			

27:33.7	Recording started due to button press	64	33	51.979	b6ffdf44b0f34dffa309998e6ba9c10f
27:46.8	Event button pressed				
27:49.8	Recording stopped due to button press	64	33	51.967	b6ffdf44b0f34dffa309998e6ba9c10f
27:50.2	Event button released				
27:50.5	Audio recording disabled due to video buffering default				
28:00.5	Event button pressed				
28:00.5	Event button released				
28:00.8	Event button pressed				
28:00.8	Audio recording enabled due to video recording default				
28:00.9	Event button released				
28:00.9	Recording started due to button press	64	34	51.966	c0e7cc7e83a548ddade21cb3b2ef80c5
28:15.9	Event button pressed				
28:18.9	Recording stopped due to button press	64	34	51.952	c0e7cc7e83a548ddade21cb3b2ef80c5
28:19.7	Audio recording disabled due to video buffering default				
28:19.8	Event button released				
28:33.6	Event button pressed				
28:34.0	Event button released				
28:34.1	Event button pressed				
28:34.1	Audio recording enabled due to video recording default				
28:34.2	Event button released				
28:34.2	Event button pressed				
28:34.2	Recording started due to button press	64	35	51.952	328855abe31f4a53a612c58792812d52
28:34.3	Event button released				
30:07.8	Event button pressed				
30:10.9	Recording stopped due to button press	64	35	51.894	328855abe31f4a53a612c58792812d52
30:11.3	Event button released				
30:11.7	Audio recording disabled due to video buffering default				
32:36.5	Axon application connected to device				
33:01.8	Video played back using Axon application				230c14a9e14846419cc17badbb4cedf5
33:30.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				230c14a9e14846419cc17badbb4cedf5
33:30.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2024 X6033271L' to 'Sig. 75 NE10 Platform' using Axon applicator				230c14a9e14846419cc17badbb4cedf5
34:18.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				2845d5345dc845bbbb676cd7347b7793
34:18.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2025 X6033271L' to '75s NE10 Train 301 Car 116' using Axon applicator				2845d5345dc845bbbb676cd7347b7793
34:58.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				0a5966a2e75b45fe96ae21ee1ae7ba72
34:58.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2026 X6033271L' to '75s NE10 Train 301 Car 115' using Axon applicator				0a5966a2e75b45fe96ae21ee1ae7ba72
35:32.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				b65f693892f44d21a90016939617cf75
35:32.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2026 X6033271L' to '75s NE10 Train 301 Car 305' using Axon applicator				b65f693892f44d21a90016939617cf75
36:15.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				16112e7d851e4b079dbbca1f9b21047e
36:15.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2027 X6033271L' to '75s NE10 Train 301 Car 306' using Axon applicator				16112e7d851e4b079dbbca1f9b21047e
37:01.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				b6ffdf44b0f34dffa309998e6ba9c10f
37:01.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2027 X6033271L' to '75s NE10 Train 301 Car 194' using Axon applicator				b6ffdf44b0f34dffa309998e6ba9c10f
37:41.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				c0e7cc7e83a548ddade21cb3b2ef80c5
37:41.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2028 X6033271L' to '75s NE10 Train 301 193' using Axon applicator				c0e7cc7e83a548ddade21cb3b2ef80c5
38:09.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				328855abe31f4a53a612c58792812d52
38:09.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2028 X6033271L' to '75 NE10 Platform' using Axon applicator				328855abe31f4a53a612c58792812d52
43:21.9	Axon application disconnected from device				
44:02.8	Event button pressed				

44:02.9	Event button released			
44:03.0	Event button pressed			
44:03.1	Event button released			
44:03.1	Audio recording enabled due to video recording default			
44:03.3	Recording started due to button press	63	36	51.891 92df770cb192477b8cc11ad27061666d
44:23.6	Event button pressed			
44:26.7	Recording stopped due to button press	62	36	51.839 92df770cb192477b8cc11ad27061666d
44:27.1	Event button released			
44:27.4	Audio recording disabled due to video buffering default			
44:36.9	Event button pressed			
44:37.1	Event button released			
44:37.2	Event button pressed			
44:37.2	Audio recording enabled due to video recording default			
44:37.2	Event button released			
44:37.3	Recording started due to button press	62	37	51.822 e76e204d442d4153bcff0e6654b9af37
44:50.9	Event button pressed			
44:53.9	Recording stopped due to button press	62	37	51.805 e76e204d442d4153bcff0e6654b9af37
44:54.5	Event button released			
44:54.8	Audio recording disabled due to video buffering default			
45:03.4	Event button pressed			
45:03.6	Event button released			
45:03.6	Event button pressed			
45:03.6	Audio recording enabled due to video recording default			
45:03.7	Event button released			
45:03.8	Recording started due to button press	62	38	51.804 496aad2c9d46459dbee0c984ec5196eb
45:18.1	Event button pressed			
45:21.1	Recording stopped due to button press	62	38	51.791 496aad2c9d46459dbee0c984ec5196eb
45:21.7	Event button released			
45:22.0	Audio recording disabled due to video buffering default			
45:39.4	Event button pressed			
45:42.3	Event button released			
45:43.0	Event button pressed			
45:43.2	Event button released			
45:43.3	Event button pressed			
45:43.3	Audio recording enabled due to video recording default			
45:43.3	Event button released			
45:43.4	Recording started due to button press	62	39	51.79 40ce9f1b11a042c68b06f98195e678b5
45:54.0	Event button pressed			
45:57.0	Recording stopped due to button press	62	39	51.773 40ce9f1b11a042c68b06f98195e678b5
45:57.5	Event button released			
45:58.0	Audio recording disabled due to video buffering default			
46:09.1	Event button pressed			
46:09.2	Event button released			
46:09.3	Event button pressed			
46:09.3	Audio recording enabled due to video recording default			
46:09.4	Event button released			
46:09.4	Recording started due to button press	62	40	51.772 85cd4714ce3f4ab79fbeda44726e6f77

46:23.3	Event button pressed				
46:26.3	Recording stopped due to button press	62	40	51.758	85cd4714ce3f4ab79fbeda44726e6f77
46:26.8	Event button released				
46:27.1	Audio recording disabled due to video buffering default				
46:44.6	Event button pressed				
46:44.7	Event button released				
46:44.8	Event button pressed				
46:44.9	Audio recording enabled due to video recording default				
46:44.9	Event button released				
46:45.0	Recording started due to button press	62	41	51.757	2f50e67db69c40b481281a4ddde9aa95
46:59.8	Event button pressed				
47:02.8	Recording stopped due to button press	62	41	51.739	2f50e67db69c40b481281a4ddde9aa95
47:03.5	Audio recording disabled due to video buffering default				
47:03.8	Event button released				
47:17.2	Event button pressed				
47:17.4	Event button released				
47:17.4	Event button pressed				
47:17.4	Audio recording enabled due to video recording default				
47:17.5	Event button released				
47:17.6	Recording started due to button press	62	42	51.739	ed64344eb83c421bb740367385805286
49:01.2	Event button pressed				
49:04.2	Recording stopped due to button press	61	42	51.676	ed64344eb83c421bb740367385805286
49:04.7	Event button released				
49:05.2	Audio recording disabled due to video buffering default				
50:10.2	Axon application connected to device				
51:06.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				92df770cb192477b8cc11ad27061666d
51:06.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2044 X6033271L' to '75s NE10 Train 302 Car 107' using Axon applicator				92df770cb192477b8cc11ad27061666d
51:54.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				e76e204d442d4153bcff0e6654b9af37
51:54.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2044 X6033271L' to '75s NE10 Train 302 Car 108' using Axon applicator				e76e204d442d4153bcff0e6654b9af37
52:35.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				496aad2c9d46459dbec0c984ec5196eb
52:35.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2045 X6033271L' to '75s NE10 Train 302 Car 148' using Axon applicator				496aad2c9d46459dbec0c984ec5196eb
53:17.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				40ce9f1b11a042c68b06f98195e678b5
53:17.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2045 X6033271L' to '75s NE10 Train 302 Car 147' using Axon applicator				40ce9f1b11a042c68b06f98195e678b5
54:21.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				85cd4714ce3f4ab79fbeda44726e6f77
54:21.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2046 X6033271L' to '75s NE10 Train 302 Car 266' using Axon applicator				85cd4714ce3f4ab79fbeda44726e6f77
54:58.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				2f50e67db69c40b481281a4ddde9aa95
54:58.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2046 X6033271L' to '75s NE10 Train 302 Car 265' using Axon applicator				2f50e67db69c40b481281a4ddde9aa95
55:33.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				ed64344eb83c421bb740367385805286
55:33.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2047 X6033271L' to 'Sig. 75 NE10 Platform' using Axon applicator				ed64344eb83c421bb740367385805286
59:37.5	Axon application disconnected from device				
01:24.5	Event button pressed				
01:24.6	Event button released				
01:24.7	Event button pressed				
01:24.7	Audio recording enabled due to video recording default				
01:24.8	Event button released				
01:24.9	Recording started due to button press	61	43	51.674	c886ee0a92334310adc5f2956ea0c131
02:06.8	Event button pressed				

02:09.8 Recording stopped due to button press	60	43	51.59 c886ee0a92334310adc5f2956ea0c131
02:10.2 Event button released			
02:10.5 Audio recording disabled due to video buffering default			
02:27.2 Event button pressed			
02:27.4 Event button released			
02:27.4 Event button pressed			
02:27.4 Audio recording enabled due to video recording default			
02:27.5 Event button released			
02:27.5 Recording started due to button press	60	44	51.59 5ee0983d915b49a583c449da771d3dcb
02:46.8 Event button pressed			
02:46.9 Event button released			
02:47.0 Event button pressed			
02:47.1 Event button released			
03:00.1 Event button pressed			
03:03.1 Recording stopped due to button press	60	44	51.563 5ee0983d915b49a583c449da771d3dcb
03:03.7 Event button released			
03:04.0 Audio recording disabled due to video buffering default			
07:20.5 Event button pressed			
07:20.6 Event button released			
07:20.7 Event button pressed			
07:20.7 Audio recording enabled due to video recording default			
07:20.8 Event button released			
07:20.9 Recording started due to button press	59	45	51.562 659e5211e8394e9a97968ec705a86b78
08:27.9 Event button pressed			
08:30.9 Recording stopped due to button press	59	45	51.465 659e5211e8394e9a97968ec705a86b78
08:31.4 Event button released			
08:31.7 Audio recording disabled due to video buffering default			
08:44.0 Event button pressed			
08:44.1 Event button released			
08:44.2 Event button pressed			
08:44.3 Audio recording enabled due to video recording default			
08:44.3 Event button released			
08:44.4 Recording started due to button press	59	46	51.464 f7aa09cea13144f6973823c392a41a94
09:03.9 Event button pressed			
09:06.9 Recording stopped due to button press	59	46	51.446 f7aa09cea13144f6973823c392a41a94
09:07.3 Event button released			
09:07.7 Audio recording disabled due to video buffering default			
09:19.1 Event button pressed			
09:19.3 Event button released			
09:19.3 Event button pressed			
09:19.3 Audio recording enabled due to video recording default			
09:19.4 Event button released			
09:19.5 Recording started due to button press	59	47	51.445 5091709c34174751b0cc02ab2dddece6
09:34.2 Audit log created	59	47 1.15.14	51.432
10:03.4 Event button pressed			
10:06.4 Recording stopped due to button press	59	47	51.415 5091709c34174751b0cc02ab2dddece6
10:06.8 Event button released			

10:07.2 Audio recording disabled due to video buffering default			
10:12.0 Event button pressed			
10:12.1 Event button released			
10:12.2 Event button pressed			
10:12.2 Audio recording enabled due to video recording default			
10:12.3 Event button released			
10:12.4 Recording started due to button press	59	48	51.414 8f672c599f9142fca6857e2ca1eac549
10:21.6 Event button pressed			
10:24.6 Recording stopped due to button press	59	48	51.406 8f672c599f9142fca6857e2ca1eac549
10:25.0 Event button released			
10:25.4 Audio recording disabled due to video buffering default			
12:28.0 Event button pressed			
12:28.1 Event button released			
12:28.1 Event button pressed			
12:28.2 Audio recording enabled due to video recording default			
12:28.2 Event button released			
12:28.4 Recording started due to button press	59	49	51.405 a8b3ba703b924a1cbc06352632e0be31
14:06.7 Event button pressed			
14:09.7 Recording stopped due to button press	58	49	51.292 a8b3ba703b924a1cbc06352632e0be31
14:10.1 Event button released			
14:10.7 Audio recording disabled due to video buffering default			
19:13.8 Event button pressed			
19:13.9 Event button released			
19:13.9 Event button pressed			
19:14.0 Audio recording enabled due to video recording default			
19:14.0 Event button released			
19:14.1 Recording started due to button press	58	50	51.291 347a4fc4adae433480a5be26c098fdf9
19:59.9 Event button pressed			
20:00.2 Event button released			
20:00.2 Event button pressed			
20:04.7 Event button released			
20:05.0 Event button pressed			
20:08.0 Recording stopped due to button press	57	50	51.202 347a4fc4adae433480a5be26c098fdf9
20:08.5 Event button released			
20:08.7 Audio recording disabled due to video buffering default			
20:50.6 Event button pressed			
20:50.7 Event button released			
20:50.8 Event button pressed			
20:50.8 Audio recording enabled due to video recording default			
20:50.9 Event button released			
20:50.9 Recording started due to button press	57	51	51.201 df5d17c4aa32492d809a450b15b574e3
22:40.4 Event button pressed			
22:43.4 Recording stopped due to button press	57	51	51.121 df5d17c4aa32492d809a450b15b574e3
22:43.9 Event button released			
22:44.2 Audio recording disabled due to video buffering default			
24:38.0 Event button pressed			
24:38.1 Event button released			

24:38.3	Event button pressed			
24:38.3	Audio recording enabled due to video recording default			
24:38.4	Event button released			
24:38.4	Recording started due to button press	56	52	51.12 d77b05b7eaa94009aab31119f02568db
24:54.3	Event button pressed			
24:57.3	Recording stopped due to button press	56	52	51.078 d77b05b7eaa94009aab31119f02568db
24:58.0	Event button released			
24:58.2	Audio recording disabled due to video buffering default			
25:15.2	Event button pressed			
25:15.3	Event button released			
25:15.4	Event button pressed			
25:15.4	Audio recording enabled due to video recording default			
25:15.5	Event button released			
25:15.6	Recording started due to button press	56	53	51.052 d569103709b543a99dd7c3c4586e1c9c
25:29.0	Event button pressed			
25:32.0	Recording stopped due to button press	56	53	51.036 d569103709b543a99dd7c3c4586e1c9c
25:32.5	Event button released			
25:32.8	Audio recording disabled due to video buffering default			
25:52.1	Event button pressed			
25:52.2	Event button released			
25:52.3	Event button pressed			
25:52.3	Audio recording enabled due to video recording default			
25:52.4	Event button released			
25:52.5	Recording started due to button press	56	54	51.035 7d86389417514eedbbf3a92da85f76de
26:08.0	Event button pressed			
26:11.0	Recording stopped due to button press	56	54	51.015 7d86389417514eedbbf3a92da85f76de
26:11.4	Event button released			
26:11.8	Audio recording disabled due to video buffering default			
26:35.9	Event button pressed			
26:38.3	Event button released			
26:38.6	Event button pressed			
26:38.7	Event button released			
26:38.7	Event button pressed			
26:38.7	Audio recording enabled due to video recording default			
26:38.8	Event button released			
26:38.9	Recording started due to button press	56	55	51.015 31ce1a17258c4cc6b13d746ee535fba2
26:51.4	Event button pressed			
26:54.4	Recording stopped due to button press	56	55	50.993 31ce1a17258c4cc6b13d746ee535fba2
26:55.0	Event button released			
26:55.3	Audio recording disabled due to video buffering default			
27:08.9	Event button pressed			
27:09.6	Event button released			
27:10.7	Event button pressed			
27:10.8	Event button released			
27:11.0	Event button pressed			
27:11.0	Audio recording enabled due to video recording default			
27:11.2	Event button released			

27:11.2	Recording started due to button press	56	56	50.993	1d6dcf55bb0a466686595cf26b141ec1
27:11.2	Event button pressed				
27:11.3	Event button released				
27:24.9	Event button pressed				
27:27.9	Recording stopped due to button press	56	56	50.977	1d6dcf55bb0a466686595cf26b141ec1
27:28.4	Event button released				
27:28.8	Audio recording disabled due to video buffering default				
27:49.0	Event button pressed				
27:49.2	Event button released				
27:49.3	Event button pressed				
27:49.3	Audio recording enabled due to video recording default				
27:49.3	Event button released				
27:49.4	Recording started due to button press	56	57	50.976	810ba4455d324d39bda49b80d900c450
28:04.6	Event button pressed				
28:07.6	Recording stopped due to button press	56	57	50.956	810ba4455d324d39bda49b80d900c450
28:08.2	Event button released				
28:08.3	Audio recording disabled due to video buffering default				
28:23.8	Event button pressed				
28:24.0	Event button released				
28:24.0	Event button pressed				
28:24.0	Audio recording enabled due to video recording default				
28:24.1	Event button released				
28:24.2	Recording started due to button press	56	58	50.956	e34cd2136240425c9f9981780ae89778
30:07.0	Event button pressed				
30:10.0	Recording stopped due to button press	55	58	50.892	e34cd2136240425c9f9981780ae89778
30:10.5	Event button released				
30:10.7	Audio recording disabled due to video buffering default				
31:27.5	Axon application connected to device				
32:13.6	Video played back using Axon application				c886ee0a92334310adc5f2956ea0c131
33:04.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				c886ee0a92334310adc5f2956ea0c131
33:04.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2101 X6033271L' to 'Sig. 75 NE10 Concourse' using Axon applicator				c886ee0a92334310adc5f2956ea0c131
34:25.5	Video played back using Axon application				5ee0983d915b49a583c449da771d3dcb
35:16.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				5ee0983d915b49a583c449da771d3dcb
35:16.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2102 X6033271L' to 'Sig. 75 NE10 Bus Loop' using Axon applicator				5ee0983d915b49a583c449da771d3dcb
35:53.2	Video played back using Axon application				659e5211e8394e9a97968ec705a86b78
37:06.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				659e5211e8394e9a97968ec705a86b78
37:06.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2107 X6033271L' to 'Sig. 75 NE9 Parking Lots' using Axon applicator				659e5211e8394e9a97968ec705a86b78
38:11.4	Categories 'Customer Assist' added to video metadata using Axon applicator				f7aa09cea13144f6973823c392a41a94
38:11.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2108 X6033271L' to 'Sig. 15 NE9 Faregates' using Axon applicator				f7aa09cea13144f6973823c392a41a94
38:57.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				5091709c34174751b0cc02ab2dddece6
38:57.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2109 X6033271L' to 'Sig. 75 NE9 Concourse' using Axon applicator				5091709c34174751b0cc02ab2dddece6
39:42.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				8f672c599f9142fca6857e2ca1eac549
39:42.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2110 X6033271L' to 'Sig. 75 NE9 Bus Loop' using Axon applicator				8f672c599f9142fca6857e2ca1eac549
40:20.2	Video played back using Axon application				a8b3ba703b924a1cbc06352632e0be31
41:22.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				a8b3ba703b924a1cbc06352632e0be31
41:22.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2112 X6033271L' to 'Sig. 75 NE9 Parking Lots' using Axon applicator				a8b3ba703b924a1cbc06352632e0be31
42:16.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				347a4fc4adae433480a5be26c098fdf9

42:16.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2119 X6033271L' to 'Sig. 75 NE10 Bus Loop' using Axon applicator			347a4fc4adae433480a5be26c098fdf9
42:57.3	Video played back using Axon application			df5d17c4aa32492d809a450b15b574e3
43:51.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			df5d17c4aa32492d809a450b15b574e3
43:51.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2120 X6033271L' to 'Sig. 75 NE10 Platform' using Axon applicator			df5d17c4aa32492d809a450b15b574e3
44:36.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			d77b05b7eaa94009aab31119f02568db
44:36.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2124 X6033271L' to '75s NE10 Train 304 Car 692' using Axon applicator			d77b05b7eaa94009aab31119f02568db
46:48.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			d569103709b543a99dd7c3c4586e1c9c
46:48.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2125 X6033271L' to '75s NE10 Train 304 Car 691' using Axon applicator			d569103709b543a99dd7c3c4586e1c9c
47:30.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			7d86389417514eedbbf3a92da85f76de
47:30.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2125 X6033271L' to '75s NE10 Train 304 Car 701' using Axon applicator			7d86389417514eedbbf3a92da85f76de
48:00.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2126 X6033271L' to '75s NE10 Train 304 Car 701' using Axon applicator			31ce1a17258c4cc6b13d746ee535fba2
48:06.9	Title changed in video metadata from '75s NE10 Train 304 Car 701' to '75s NE10 Train 304 Car 702' using Axon applicator			31ce1a17258c4cc6b13d746ee535fba2
48:14.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			31ce1a17258c4cc6b13d746ee535fba2
48:53.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			1d6dcf55bb0a466686595cf26b141ec1
48:53.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2127 X6033271L' to '75s NE10 Train 304 Car 314' using Axon applicator			1d6dcf55bb0a466686595cf26b141ec1
49:25.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			810ba4455d324d39bda49b80d900c450
49:25.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2127 X6033271L' to 'Sig. 75 NE10 Platform' using Axon applicator			810ba4455d324d39bda49b80d900c450
09:34.2	Audit log created	50	58 1.15.14	50.888
15:51.6	Axon application disconnected from device			
21:57.1	Axon application connected to device			
22:43.0	Title changed in video metadata from 'Sig. 75 NE10 Platform' to '75s NE10 Train 304 Car 313' using Axon applicator			810ba4455d324d39bda49b80d900c450
23:09.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			e34cd2136240425c9f9981780ae89778
23:09.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-01 2128 X6033271L' to 'Sig. 75 NE10 Platform' using Axon applicator			e34cd2136240425c9f9981780ae89778
23:55.7	Axon application disconnected from device			
09:34.3	Audit log created	43	58 1.15.14	50.887
26:07.6	Volume up button pressed			
26:07.6	Volume up button released			
26:07.9	Volume changed to high from medium using button			
26:11.9	Volume down button pressed			
26:12.1	Volume down button released			
26:12.2	Volume changed to medium from high using button			
26:16.0	Audit log created	42	58 1.15.14	50.886
26:16.0	Audit log rolled	42	58	50.886
26:16.1	Camera connected to Axon Dock X62001W9H	42	58	50.926
26:17.1	Device connected to charger	42	58	50.886
26:32.3	Video upload started when camera was docked			6fd8de1b4b744a3881c3725218848dca
26:52.0	Date/Time synced to 09/01/2021 11:26:52.02 PM from 09/01/2021 11:26:46.17 PM			
27:05.3	Video successfully uploaded from device when dockec			6fd8de1b4b744a3881c3725218848dca
27:05.6	Video deleted from device when docked	42	57	51.016 6fd8de1b4b744a3881c3725218848dca
27:05.6	Audit log created	42	57 1.15.14	51.017
27:05.6	Audit log rolled	42	57	51.017
27:05.8	Video upload started when camera was docked			5ea11a0085ab478eb3b5c56820be12f1
27:16.8	Audit log successfully uploaded			
27:17.0	Audit log successfully uploaded and deleted from device	42	57	51.016
27:21.6	Video successfully uploaded from device when dockec			5ea11a0085ab478eb3b5c56820be12f1
27:21.8	Video deleted from device when docked	42	56	51.073 5ea11a0085ab478eb3b5c56820be12f1
27:21.8	Audit log created	42	56 1.15.14	51.073

27:21.8 Audit log rolled	42	56	51.073	
27:22.0 Video upload started when camera was docked				82edb796496547719a0b87e8cfe5e096
27:40.1 Audit log successfully uploaded				
27:40.3 Audit log successfully uploaded and deleted from device	42	56	51.073	
27:50.3 Video successfully uploaded from device when dockec				82edb796496547719a0b87e8cfe5e096
27:50.5 Video deleted from device when docked	42	55	51.165	82edb796496547719a0b87e8cfe5e096
27:50.6 Audit log rolled	42	55	51.165	
27:50.6 Audit log created	42	55 1.15.14	51.165	
27:50.9 Video upload started when camera was docked				16f44e681edc42c38315a983890fdc2d
27:55.4 Audit log successfully uploaded				
27:55.6 Audit log successfully uploaded and deleted from device	42	55	51.165	
27:56.7 Audit log successfully uploaded				
27:56.9 Audit log successfully uploaded and deleted from device	42	55	51.165	
28:24.0 Audit log successfully uploaded				
28:24.2 Audit log successfully uploaded and deleted from device	42	55	51.165	
28:38.3 Audit log successfully uploaded				
28:38.5 Audit log successfully uploaded and deleted from device	42	55	51.165	
28:42.6 Audit log successfully uploaded				
28:42.8 Audit log successfully uploaded and deleted from device	42	55	51.165	
29:05.9 Audit log successfully uploaded				
29:06.1 Audit log successfully uploaded and deleted from device	43	55	51.165	
29:21.5 Video successfully uploaded from device when dockec				16f44e681edc42c38315a983890fdc2d
29:21.8 Video deleted from device when docked	43	54	51.475	16f44e681edc42c38315a983890fdc2d
29:21.9 Audit log rolled	43	54	51.476	
29:21.9 Audit log created	43	54 1.15.14	51.476	
29:22.2 Video upload started when camera was docked				9f3301be39de423499ea8025d62fa1df
29:31.2 Audit log successfully uploaded				
29:31.4 Audit log successfully uploaded and deleted from device	43	54	51.475	
29:41.5 Audit log successfully uploaded				
29:41.7 Audit log successfully uploaded and deleted from device	43	54	51.475	
29:43.6 Video successfully uploaded from device when dockec				9f3301be39de423499ea8025d62fa1df
29:43.8 Video deleted from device when docked	43	53	51.548	9f3301be39de423499ea8025d62fa1df
29:43.8 Audit log created	43	53 1.15.14	51.549	
29:43.8 Audit log rolled	43	53	51.549	
29:44.4 Video upload started when camera was docked				0f6f698872a84ad8bce79e97844826d2
29:48.6 Video successfully uploaded from device when dockec				0f6f698872a84ad8bce79e97844826d2
29:48.9 Video deleted from device when docked	43	52	51.562	0f6f698872a84ad8bce79e97844826d2
29:48.9 Audit log created	43	52 1.15.14	51.562	
29:48.9 Audit log rolled	43	52	51.562	
29:49.1 Video upload started when camera was docked				729c6c0580584261a0e73c181ccd98b7
29:56.2 Video successfully uploaded from device when dockec				729c6c0580584261a0e73c181ccd98b7
29:56.4 Video deleted from device when docked	43	51	51.582	729c6c0580584261a0e73c181ccd98b7
29:56.5 Audit log rolled	43	51	51.582	
29:56.5 Audit log created	43	51 1.15.14	51.582	
29:56.6 Video upload started when camera was docked				85116a4ca70e437d827698cf9d0cb6e9
29:56.9 Audit log successfully uploaded				
29:57.1 Audit log successfully uploaded and deleted from device	43	51	51.582	

30:01.0	Video successfully uploaded from device when dockec			85116a4ca70e437d827698cf9d0cb6e9
30:01.2	Video deleted from device when docked	43	50	51.595 85116a4ca70e437d827698cf9d0cb6e9
30:01.2	Audit log created	43	50 1.15.14	51.595
30:01.2	Audit log rolled	43	50	51.595
30:01.4	Video upload started when camera was docked			2a711e1e20bf4686bef17942da70dc72
30:05.1	Video successfully uploaded from device when dockec			2a711e1e20bf4686bef17942da70dc72
30:05.3	Video deleted from device when docked	43	49	51.605 2a711e1e20bf4686bef17942da70dc72
30:05.3	Audit log rolled	43	49	51.606
30:05.3	Audit log created	43	49 1.15.14	51.606
30:05.5	Video upload started when camera was docked			65ba696db3274ef181a6b2b21135cdf3
30:11.6	Video successfully uploaded from device when dockec			65ba696db3274ef181a6b2b21135cdf3
30:11.8	Video deleted from device when docked	43	48	51.619 65ba696db3274ef181a6b2b21135cdf3
30:11.9	Audit log created	43	48 1.15.14	51.619
30:11.9	Audit log rolled	43	48	51.619
30:12.1	Video upload started when camera was docked			2d035c9bdb5948c2a85d4d8c2e205d1a
30:24.2	Audit log successfully uploaded			
30:24.4	Audit log successfully uploaded and deleted from device	43	48	51.619
30:27.4	Video successfully uploaded from device when dockec			2d035c9bdb5948c2a85d4d8c2e205d1a
30:27.7	Video deleted from device when docked	43	47	51.644 2d035c9bdb5948c2a85d4d8c2e205d1a
30:27.8	Audit log created	43	47 1.15.14	51.644
30:27.8	Audit log rolled	43	47	51.644
30:28.0	Video upload started when camera was docked			331434c74164479a96c697bcf2604301
30:35.5	Audit log successfully uploaded			
30:35.7	Audit log successfully uploaded and deleted from device	43	47	51.644
31:02.5	Audit log successfully uploaded			
31:02.7	Audit log successfully uploaded and deleted from device	44	47	51.644
31:28.8	Audit log successfully uploaded			
31:29.0	Audit log successfully uploaded and deleted from device	44	47	51.644
31:36.2	Audit log successfully uploaded			
31:36.4	Audit log successfully uploaded and deleted from device	44	47	51.644
32:00.5	Audit log successfully uploaded			
32:00.7	Audit log successfully uploaded and deleted from device	44	47	51.644
32:09.8	Audit log successfully uploaded			
32:10.0	Audit log successfully uploaded and deleted from device	44	47	51.644
32:39.2	Audit log successfully uploaded			
32:39.3	Audit log successfully uploaded and deleted from device	44	47	51.644
32:57.5	Audit log successfully uploaded			
32:57.7	Audit log successfully uploaded and deleted from device	44	47	51.644
33:04.9	Audit log successfully uploaded			
33:05.0	Audit log successfully uploaded and deleted from device	44	47	51.644
33:13.2	Audit log successfully uploaded			
33:13.4	Audit log successfully uploaded and deleted from device	45	47	51.644
33:23.5	Audit log successfully uploaded			
33:23.7	Audit log successfully uploaded and deleted from device	45	47	51.643
33:37.8	Audit log successfully uploaded			
33:38.0	Audit log successfully uploaded and deleted from device	45	47	51.643
34:01.3	Audit log successfully uploaded			

34:01.4	Audit log successfully uploaded and deleted from device	45	47	51.643
34:26.5	Audit log successfully uploaded			
34:26.7	Audit log successfully uploaded and deleted from device	45	47	51.643
34:44.9	Audit log successfully uploaded			
34:45.1	Audit log successfully uploaded and deleted from device	45	47	51.643
34:54.5	Video successfully uploaded from device when dockec			331434c74164479a96c697bcf2604301
34:54.8	Video deleted from device when docked	46	46	51.972 331434c74164479a96c697bcf2604301
34:54.9	Audit log rolled	46	46	51.972
34:54.9	Audit log created	46	46 1.15.14	51.972
34:55.2	Video upload started when camera was docked			fd7c34ae1c1c4f4797140bbe55e9d418
35:03.2	Audit log successfully uploaded			
35:03.5	Audit log successfully uploaded and deleted from device	46	46	51.972
35:32.6	Audit log successfully uploaded			
35:32.8	Audit log successfully uploaded and deleted from device	46	46	51.972
35:49.0	Audit log successfully uploaded			
35:49.1	Audit log successfully uploaded and deleted from device	46	46	51.972
35:58.3	Audit log successfully uploaded			
35:58.4	Audit log successfully uploaded and deleted from device	46	46	51.972
36:03.1	Video successfully uploaded from device when dockec			fd7c34ae1c1c4f4797140bbe55e9d418
36:03.4	Video deleted from device when docked	46	45	52.045 fd7c34ae1c1c4f4797140bbe55e9d418
36:03.4	Audit log rolled	46	45	52.049
36:03.4	Audit log created	46	45 1.15.14	52.049
36:03.7	Video upload started when camera was docked			219548e5195f40f2809a4be202f1357a
36:13.6	Audit log successfully uploaded			
36:13.8	Audit log successfully uploaded and deleted from device	46	45	52.049
36:23.9	Video successfully uploaded from device when dockec			219548e5195f40f2809a4be202f1357a
36:24.1	Video deleted from device when docked	46	44	52.069 219548e5195f40f2809a4be202f1357a
36:24.2	Audit log rolled	46	44	52.069
36:24.2	Audit log created	46	44 1.15.14	52.069
36:24.5	Video upload started when camera was docked			6e72b15c37ce4341a6596dec7ab3922a
36:25.9	Audit log successfully uploaded			
36:26.1	Audit log successfully uploaded and deleted from device	46	44	52.069
36:30.3	Audit log successfully uploaded			
36:30.4	Audit log successfully uploaded and deleted from device	46	44	52.069
36:39.6	Video successfully uploaded from device when dockec			6e72b15c37ce4341a6596dec7ab3922a
36:39.8	Video deleted from device when docked	46	43	52.084 6e72b15c37ce4341a6596dec7ab3922a
36:39.9	Audit log created	46	43 1.15.14	52.084
36:39.9	Audit log rolled	46	43	52.084
36:40.1	Video upload started when camera was docked			7faae75360e6465783a85287e2fb6227
36:44.6	Audit log successfully uploaded			
36:44.8	Audit log successfully uploaded and deleted from device	46	43	52.084
36:55.6	Video successfully uploaded from device when dockec			7faae75360e6465783a85287e2fb6227
36:55.8	Video deleted from device when docked	46	42	52.098 7faae75360e6465783a85287e2fb6227
36:55.9	Audit log rolled	46	42	52.1
36:55.9	Audit log created	46	42 1.15.14	52.1
36:56.1	Video upload started when camera was docked			83e489cc3c204819a5881692440c2499
37:11.0	Audit log successfully uploaded			

37:11.2	Audit log successfully uploaded and deleted from device	46	42	52.1	
37:16.3	Video successfully uploaded from device when dockec				83e489cc3c204819a5881692440c2499
37:16.5	Video deleted from device when docked	46	41	52.117	83e489cc3c204819a5881692440c2499
37:16.5	Audit log rolled	46	41	52.117	
37:16.5	Audit log created	46	41	1.15.14	52.117
37:16.8	Video upload started when camera was docked				f9c2be91f63d456f9c85e534d8fa4a9b
37:18.3	Audit log successfully uploaded				
37:18.5	Audit log successfully uploaded and deleted from device	46	41	52.117	
37:27.8	Video successfully uploaded from device when dockec				f9c2be91f63d456f9c85e534d8fa4a9b
37:28.0	Video deleted from device when docked	47	40	52.129	f9c2be91f63d456f9c85e534d8fa4a9b
37:28.1	Audit log rolled	47	40	52.13	
37:28.1	Audit log created	47	40	1.15.14	52.13
37:28.2	Video upload started when camera was docked				cd44da9235ac4ec2b1dad540b1380866
37:38.6	Audit log successfully uploaded				
37:38.8	Audit log successfully uploaded and deleted from device	47	40	52.13	
38:08.0	Audit log successfully uploaded				
38:08.2	Audit log successfully uploaded and deleted from device	47	40	52.13	
38:21.0	Video successfully uploaded from device when dockec				cd44da9235ac4ec2b1dad540b1380866
38:21.2	Video deleted from device when docked	47	39	52.182	cd44da9235ac4ec2b1dad540b1380866
38:21.2	Audit log rolled	47	39	52.183	
38:21.2	Audit log created	47	39	1.15.14	52.183
38:21.7	Video upload started when camera was docked				fb3343fd17d24e3a817a7e121d2982f5
38:36.3	Audit log successfully uploaded				
38:36.5	Audit log successfully uploaded and deleted from device	47	39	52.183	
38:56.6	Audit log successfully uploaded				
38:56.8	Audit log successfully uploaded and deleted from device	47	39	52.183	
39:19.9	Audit log successfully uploaded				
39:20.1	Audit log successfully uploaded and deleted from device	47	39	52.183	
39:24.4	Audit log successfully uploaded				
39:24.6	Audit log successfully uploaded and deleted from device	47	39	52.183	
39:53.7	Audit log successfully uploaded				
39:53.9	Audit log successfully uploaded and deleted from device	47	39	52.183	
40:16.0	Audit log successfully uploaded				
40:16.4	Audit log successfully uploaded and deleted from device	48	39	52.183	
40:34.6	Audit log successfully uploaded				
40:34.8	Audit log successfully uploaded and deleted from device	48	39	52.183	
41:02.3	Audit log successfully uploaded				
41:02.5	Audit log successfully uploaded and deleted from device	48	39	52.182	
41:18.6	Audit log successfully uploaded				
41:18.8	Audit log successfully uploaded and deleted from device	48	39	52.182	
41:48.0	Audit log successfully uploaded				
41:48.2	Audit log successfully uploaded and deleted from device	49	39	52.182	
41:57.3	Audit log successfully uploaded				
41:57.5	Audit log successfully uploaded and deleted from device	49	39	52.182	
42:26.7	Audit log successfully uploaded				
42:26.9	Audit log successfully uploaded and deleted from device	49	39	52.182	
42:56.0	Audit log successfully uploaded				

42:56.2	Audit log successfully uploaded and deleted from device	49	39	52.182	
42:59.9	Video successfully uploaded from device when dockec				fb3343fd17d24e3a817a7e121d2982f5
43:00.3	Video deleted from device when docked	49	38	52.518	fb3343fd17d24e3a817a7e121d2982f5
43:00.3	Audit log created	49	38	1.15.14	52.519
43:00.3	Audit log rolled	49	38		52.519
43:00.6	Video upload started when camera was docked				668377f9af2042a28832ae7aa85f938c
43:23.3	Audit log successfully uploaded				
43:23.5	Audit log successfully uploaded and deleted from device	49	38		52.519
43:34.6	Audit log successfully uploaded				
43:34.8	Audit log successfully uploaded and deleted from device	49	38		52.519
43:44.9	Audit log successfully uploaded				
43:45.1	Audit log successfully uploaded and deleted from device	49	38		52.519
44:00.2	Audit log successfully uploaded				
44:00.3	Audit log successfully uploaded and deleted from device	49	38		52.519
44:19.5	Audit log successfully uploaded				
44:19.7	Audit log successfully uploaded and deleted from device	50	38		52.519
44:43.9	Audit log successfully uploaded				
44:44.1	Audit log successfully uploaded and deleted from device	50	38		52.518
45:09.2	Audit log successfully uploaded				
45:09.4	Audit log successfully uploaded and deleted from device	50	38		52.518
45:34.5	Audit log successfully uploaded				
45:34.8	Audit log successfully uploaded and deleted from device	50	38		52.518
45:47.9	Audit log successfully uploaded				
45:48.1	Audit log successfully uploaded and deleted from device	50	38		52.518
46:05.3	Audit log successfully uploaded				
46:05.4	Audit log successfully uploaded and deleted from device	51	38		52.518
46:12.2	Video successfully uploaded from device when dockec				668377f9af2042a28832ae7aa85f938c
46:12.6	Audit log successfully uploaded				
46:12.6	Video deleted from device when docked	51	37	53.098	668377f9af2042a28832ae7aa85f938c
46:12.7	Audit log created	51	37	1.15.14	53.098
46:12.7	Audit log rolled	51	37		53.098
46:12.8	Audit log successfully uploaded and deleted from device	51	37		53.098
46:12.9	Video upload started when camera was docked				0cff589f24714e54ae94a278e688fb00
46:39.9	Audit log successfully uploaded				
46:40.1	Audit log successfully uploaded and deleted from device	51	37		53.098
46:41.2	Audit log successfully uploaded				
46:41.4	Audit log successfully uploaded and deleted from device	51	37		53.098
47:12.0	Video successfully uploaded from device when dockec				0cff589f24714e54ae94a278e688fb00
47:12.2	Video deleted from device when docked	51	36	53.295	0cff589f24714e54ae94a278e688fb00
47:12.3	Audit log created	51	36	1.15.14	53.296
47:12.3	Audit log rolled	51	36		53.296
47:12.5	Video upload started when camera was docked				71ffa0c5c86443989378f2589e51e361
48:56.0	Video successfully uploaded from device when dockec				71ffa0c5c86443989378f2589e51e361
48:56.2	Video deleted from device when docked	52	35	53.673	71ffa0c5c86443989378f2589e51e361
48:56.3	Audit log rolled	52	35		53.673
48:56.3	Audit log created	52	35	1.15.14	53.673
48:56.5	Video upload started when camera was docked				f3dbe9299fc84d7b90abd5cad16b41a9

49:12.6	Video successfully uploaded from device when dockec				f3dbe9299fc84d7b90abd5cad16b41a9
49:12.8	Video deleted from device when docked	52	34	53.725	f3dbe9299fc84d7b90abd5cad16b41a9
49:12.9	Audit log created	52	34	1.15.14	53.726
49:12.9	Audit log rolled	52	34		53.726
49:13.1	Video upload started when camera was docked				cb29a36c4f70412d87a3ad3e250734ca
49:22.5	Video successfully uploaded from device when dockec				cb29a36c4f70412d87a3ad3e250734ca
49:22.7	Video deleted from device when docked	52	33	53.757	cb29a36c4f70412d87a3ad3e250734ca
49:22.7	Audit log created	52	33	1.15.14	53.758
49:22.7	Audit log rolled	52	33		53.758
49:22.9	Video upload started when camera was docked				de4dca4434ec400697d3d2ef38cc1cc9
49:40.0	Video successfully uploaded from device when dockec				de4dca4434ec400697d3d2ef38cc1cc9
49:40.2	Video deleted from device when docked	52	32	53.809	de4dca4434ec400697d3d2ef38cc1cc9
49:40.2	Audit log rolled	52	32		53.81
49:40.2	Audit log created	52	32	1.15.14	53.81
49:40.4	Video upload started when camera was docked				f3381f9cd828435aa8dd0e3e5203610b
50:12.4	Video successfully uploaded from device when dockec				f3381f9cd828435aa8dd0e3e5203610b
50:12.7	Video deleted from device when docked	53	31	53.925	f3381f9cd828435aa8dd0e3e5203610b
50:12.7	Audit log created	53	31	1.15.14	53.925
50:12.7	Audit log rolled	53	31		53.925
50:13.0	Video upload started when camera was docked				230c14a9e14846419cc17badbb4cedf5
50:37.1	Video successfully uploaded from device when dockec				230c14a9e14846419cc17badbb4cedf5
50:37.3	Video deleted from device when docked	53	30	54.01	230c14a9e14846419cc17badbb4cedf5
50:37.3	Audit log created	53	30	1.15.14	54.01
50:37.3	Audit log rolled	53	30		54.01
50:37.5	Video upload started when camera was docked				2845d5345dc845bbbb676cd7347b7793
50:46.5	Video successfully uploaded from device when dockec				2845d5345dc845bbbb676cd7347b7793
50:46.7	Video deleted from device when docked	53	29	54.035	2845d5345dc845bbbb676cd7347b7793
50:46.8	Audit log created	53	29	1.15.14	54.035
50:46.8	Audit log rolled	53	29		54.035
50:47.1	Video upload started when camera was docked				0a5966a2e75b45fe96ae21ee1ae7ba72
50:51.5	Video successfully uploaded from device when dockec				0a5966a2e75b45fe96ae21ee1ae7ba72
50:51.7	Video deleted from device when docked	53	28	54.049	0a5966a2e75b45fe96ae21ee1ae7ba72
50:51.8	Audit log created	53	28	1.15.14	54.049
50:51.8	Audit log rolled	53	28		54.049
50:52.0	Video upload started when camera was docked				b65f693892f44d21a90016939617cf75
51:02.4	Video successfully uploaded from device when dockec				b65f693892f44d21a90016939617cf75
51:02.7	Video deleted from device when docked	53	27	54.067	b65f693892f44d21a90016939617cf75
51:02.7	Audit log rolled	53	27		54.067
51:02.7	Audit log created	53	27	1.15.14	54.067
51:02.9	Video upload started when camera was docked				16112e7d851e4b079dbbca1f9b21047e
51:07.2	Video successfully uploaded from device when dockec				16112e7d851e4b079dbbca1f9b21047e
51:07.4	Video deleted from device when docked	53	26	54.081	16112e7d851e4b079dbbca1f9b21047e
51:07.4	Audit log created	53	26	1.15.14	54.081
51:07.4	Audit log rolled	53	26		54.081
51:07.6	Video upload started when camera was docked				b6ffdf44b0f34dffa309998e6ba9c10f
51:12.0	Video successfully uploaded from device when dockec				b6ffdf44b0f34dffa309998e6ba9c10f
51:12.2	Video deleted from device when docked	53	25	54.093	b6ffdf44b0f34dffa309998e6ba9c10f

51:12.2	Audit log created	53	25	1.15.14	54.093	
51:12.3	Audit log rolled	53	25		54.093	
51:12.5	Video upload started when camera was docked					c0e7cc7e83a548ddade21cb3b2ef80c5
51:17.9	Video successfully uploaded from device when docked					c0e7cc7e83a548ddade21cb3b2ef80c5
51:18.2	Video deleted from device when docked	53	24		54.108	c0e7cc7e83a548ddade21cb3b2ef80c5
51:18.2	Audit log created	53	24	1.15.14	54.108	
51:18.2	Audit log rolled	53	24		54.108	
51:18.5	Video upload started when camera was docked					328855abe31f4a53a612c58792812d52
51:35.5	Video successfully uploaded from device when docked					328855abe31f4a53a612c58792812d52
51:35.7	Video deleted from device when docked	53	23		54.166	328855abe31f4a53a612c58792812d52
51:35.8	Audit log rolled	53	23		54.166	
51:35.8	Audit log created	53	23	1.15.14	54.166	
51:36.0	Video upload started when camera was docked					92df770cb192477b8cc11ad27061666d
51:56.0	Video successfully uploaded from device when docked					92df770cb192477b8cc11ad27061666d
51:56.3	Video deleted from device when docked	53	22		54.239	92df770cb192477b8cc11ad27061666d
51:56.3	Audit log created	53	22	1.15.14	54.239	
51:56.3	Audit log rolled	53	22		54.239	
51:56.6	Video upload started when camera was docked					e76e204d442d4153bcff0e6654b9af37
52:00.8	Video successfully uploaded from device when docked					e76e204d442d4153bcff0e6654b9af37
52:01.0	Video deleted from device when docked	53	21		54.253	e76e204d442d4153bcff0e6654b9af37
52:01.1	Audit log created	53	21	1.15.14	54.253	
52:01.1	Audit log rolled	53	21		54.253	
52:01.3	Video upload started when camera was docked					496aad2c9d46459dbee0c984ec5196eb
52:06.0	Video successfully uploaded from device when docked					496aad2c9d46459dbee0c984ec5196eb
52:06.2	Video deleted from device when docked	53	20		54.267	496aad2c9d46459dbee0c984ec5196eb
52:06.2	Audit log rolled	53	20		54.267	
52:06.2	Audit log created	53	20	1.15.14	54.267	
52:06.4	Video upload started when camera was docked					40ce9f1b11a042c68b06f98195e678b5
52:12.4	Video successfully uploaded from device when docked					40ce9f1b11a042c68b06f98195e678b5
52:12.6	Video deleted from device when docked	53	19		54.285	40ce9f1b11a042c68b06f98195e678b5
52:12.7	Audit log created	53	19	1.15.14	54.285	
52:12.7	Audit log rolled	53	19		54.285	
52:13.1	Video upload started when camera was docked					85cd4714ce3f4ab79fbeda44726e6f77
52:17.7	Video successfully uploaded from device when docked					85cd4714ce3f4ab79fbeda44726e6f77
52:17.9	Video deleted from device when docked	53	18		54.3	85cd4714ce3f4ab79fbeda44726e6f77
52:18.0	Audit log created	53	18	1.15.14	54.3	
52:18.0	Audit log rolled	53	18		54.3	
52:18.2	Video upload started when camera was docked					2f50e67db69c40b481281a4ddde9aa95
52:23.7	Video successfully uploaded from device when docked					2f50e67db69c40b481281a4ddde9aa95
52:23.9	Video deleted from device when docked	53	17		54.318	2f50e67db69c40b481281a4ddde9aa95
52:23.9	Audit log rolled	53	17		54.318	
52:23.9	Audit log created	53	17	1.15.14	54.318	
52:24.2	Video upload started when camera was docked					ed64344eb83c421bb740367385805286
52:43.1	Video successfully uploaded from device when docked					ed64344eb83c421bb740367385805286
52:43.3	Video deleted from device when docked	54	16		54.381	ed64344eb83c421bb740367385805286
52:43.4	Audit log created	54	16	1.15.14	54.383	
52:43.4	Audit log rolled	54	16		54.383	

52:43.6	Video upload started when camera was docked				c886ee0a92334310adc5f2956ea0c131
53:09.1	Video successfully uploaded from device when docked				c886ee0a92334310adc5f2956ea0c131
53:09.4	Video deleted from device when docked	54	15	54.467	c886ee0a92334310adc5f2956ea0c131
53:09.4	Audit log created	54	15	1.15.14	54.469
53:09.4	Audit log rolled	54	15		54.469
53:09.6	Video upload started when camera was docked				5ee0983d915b49a583c449da771d3dcb
53:18.4	Video successfully uploaded from device when docked				5ee0983d915b49a583c449da771d3dcb
53:18.6	Video deleted from device when docked	54	14	54.496	5ee0983d915b49a583c449da771d3dcb
53:18.6	Audit log created	54	14	1.15.14	54.496
53:18.7	Audit log rolled	54	14		54.496
53:18.8	Video upload started when camera was docked				659e5211e8394e9a97968ec705a86b78
53:46.1	Video successfully uploaded from device when docked				659e5211e8394e9a97968ec705a86b78
53:46.3	Video deleted from device when docked	54	13	54.593	659e5211e8394e9a97968ec705a86b78
53:46.4	Audit log created	54	13	1.15.14	54.593
53:46.4	Audit log rolled	54	13		54.593
53:46.6	Video upload started when camera was docked				f7aa09cea13144f6973823c392a41a94
53:51.9	Video successfully uploaded from device when docked				f7aa09cea13144f6973823c392a41a94
53:52.2	Video deleted from device when docked	54	12	54.611	f7aa09cea13144f6973823c392a41a94
53:52.2	Audit log rolled	54	12		54.612
53:52.2	Audit log created	54	12	1.15.14	54.612
53:52.5	Video upload started when camera was docked				5091709c34174751b0cc02ab2dddece6
54:01.8	Video successfully uploaded from device when docked				5091709c34174751b0cc02ab2dddece6
54:02.0	Video deleted from device when docked	54	11	54.642	5091709c34174751b0cc02ab2dddece6
54:02.1	Audit log rolled	54	11		54.643
54:02.1	Audit log created	54	11	1.15.14	54.643
54:02.3	Video upload started when camera was docked				8f672c599f9142fca6857e2ca1eac549
54:06.3	Video successfully uploaded from device when docked				8f672c599f9142fca6857e2ca1eac549
54:06.5	Video deleted from device when docked	54	10	54.652	8f672c599f9142fca6857e2ca1eac549
54:06.5	Audit log rolled	54	10		54.652
54:06.5	Audit log created	54	10	1.15.14	54.652
54:06.7	Video upload started when camera was docked				a8b3ba703b924a1cbc06352632e0be31
54:41.1	Video successfully uploaded from device when docked				a8b3ba703b924a1cbc06352632e0be31
54:41.4	Video deleted from device when docked	54	9	54.766	a8b3ba703b924a1cbc06352632e0be31
54:41.4	Audit log rolled	54	9		54.766
54:41.4	Audit log created	54	9	1.15.14	54.766
54:41.6	Video upload started when camera was docked				347a4fc4adae433480a5be26c098fdf9
55:07.4	Video successfully uploaded from device when docked				347a4fc4adae433480a5be26c098fdf9
55:07.6	Video deleted from device when docked	55	8	54.855	347a4fc4adae433480a5be26c098fdf9
55:07.7	Audit log created	55	8	1.15.14	54.855
55:07.7	Audit log rolled	55	8		54.855
55:07.9	Video upload started when camera was docked				df5d17c4aa32492d809a450b15b574e3
55:30.5	Video successfully uploaded from device when docked				df5d17c4aa32492d809a450b15b574e3
55:30.8	Video deleted from device when docked	55	7	54.935	df5d17c4aa32492d809a450b15b574e3
55:30.8	Audit log created	55	7	1.15.14	54.936
55:30.8	Audit log rolled	55	7		54.936
55:31.0	Video upload started when camera was docked				d77b05b7eaa94009aab31119f02568db
55:50.8	Video successfully uploaded from device when docked				d77b05b7eaa94009aab31119f02568db

55:51.1 Video deleted from device when docked	55	6	55.003 d77b05b7eaa94009aab31119f02568db
55:51.1 Audit log created	55	6 1.15.14	55.003
55:51.1 Audit log rolled	55	6	55.003
55:51.4 Video upload started when camera was docked			d569103709b543a99dd7c3c4586e1c9c
55:57.6 Video successfully uploaded from device when docked			d569103709b543a99dd7c3c4586e1c9c
55:57.8 Video deleted from device when docked	55	5	55.02 d569103709b543a99dd7c3c4586e1c9c
55:57.9 Audit log created	55	5 1.15.14	55.021
55:57.9 Audit log rolled	55	5	55.021
55:58.1 Video upload started when camera was docked			7d86389417514eedbbf3a92da85f76de
56:04.4 Video successfully uploaded from device when docked			7d86389417514eedbbf3a92da85f76de
56:04.7 Video deleted from device when docked	55	4	55.04 7d86389417514eedbbf3a92da85f76de
56:04.7 Audit log created	55	4 1.15.14	55.04
56:04.7 Audit log rolled	55	4	55.041
56:04.9 Video upload started when camera was docked			31ce1a17258c4cc6b13d746ee535fba2
56:11.3 Video successfully uploaded from device when docked			31ce1a17258c4cc6b13d746ee535fba2
56:11.5 Video deleted from device when docked	55	3	55.062 31ce1a17258c4cc6b13d746ee535fba2
56:11.6 Audit log created	55	3 1.15.14	55.062
56:11.6 Audit log rolled	55	3	55.062
56:11.8 Video upload started when camera was docked			1d6dcf55bb0a466686595cf26b141ec1
56:16.7 Video successfully uploaded from device when docked			1d6dcf55bb0a466686595cf26b141ec1
56:17.0 Video deleted from device when docked	55	2	55.079 1d6dcf55bb0a466686595cf26b141ec1
56:17.0 Audit log created	55	2 1.15.14	55.079
56:17.0 Audit log rolled	55	2	55.079
56:17.2 Video upload started when camera was docked			810ba4455d324d39bda49b80d900c450
56:23.4 Video successfully uploaded from device when docked			810ba4455d324d39bda49b80d900c450
56:23.6 Video deleted from device when docked	55	1	55.099 810ba4455d324d39bda49b80d900c450
56:23.7 Audit log created	55	1 1.15.14	55.108
56:23.7 Audit log rolled	55	1	55.108
56:23.9 Video upload started when camera was docked			e34cd2136240425c9f9981780ae89778
56:40.9 Video successfully uploaded from device when docked			e34cd2136240425c9f9981780ae89778
56:41.2 Video deleted from device when docked	55	0	55.171 e34cd2136240425c9f9981780ae89778
56:41.2 Audit log created	55	0 1.15.14	55.177
56:41.2 Audit log rolled	55	0	55.177
56:41.3 Audit log created	55	0 1.15.14	55.177
56:41.3 Audit log rolled	55	0	55.177
56:53.0 Date/Time synced to 09/01/2021 11:56:53.01 PM from 09/01/2021 11:56:52.04 PM			
58:04.4 Device disconnected from charger	56	0	55.177
58:04.6 Camera disconnected from Axon Dock X62001W9H	56	0	55.178
56:41.8 Audit log created	49	0 1.15.14	55.19
56:41.8 Audit log created	43	0 1.15.14	55.189
25:07.4 Camera connected to Axon Dock X630020W7	40	0	55.196
25:07.5 Audit log created	40	0 1.15.14	55.196
25:07.5 Audit log rolled	40	0	55.196
25:08.4 Device connected to charger	40	0	55.196
25:07.0 Audit log created	68	0 1.15.14	55.195
25:07.0 Audit log created	94	0 1.15.14	55.195
25:07.0 Audit log created	100	0 1.15.14	55.194

25:07.0	Audit log created	100	0	1.15.14	55.193
25:07.0	Audit log created	100	0	1.15.14	55.193
25:07.0	Audit log created	100	0	1.15.14	55.193
25:07.1	Audit log created	100	0	1.15.14	55.192
25:07.1	Audit log created	100	0	1.15.14	55.192
25:07.1	Audit log created	100	0	1.15.14	55.191
25:07.1	Audit log created	100	0	1.15.14	55.191
25:07.1	Audit log created	100	0	1.15.14	55.191
25:07.1	Audit log created	100	0	1.15.14	55.19
25:07.1	Audit log created	100	0	1.15.14	55.19
44:21.4	Device disconnected from charger	98	0		55.19
44:21.9	Camera disconnected from Axon Dock X630020W7	100	0		55.19
44:34.8	Power button pressed				
44:37.9	Device powered off using button	100	0		55.191
44:38.5	Power button released				
44:50.0	Audit log created			1.15.14	
44:50.1	Device powered on using button	100	0		55.19
44:52.0	Audio recording disabled due to video buffering default				
45:13.1	Event button pressed				
45:13.2	Event button released				
45:13.3	Event button pressed				
45:13.3	Audio recording enabled due to video recording default				
45:13.3	Event button released				
45:13.5	Recording started due to button press	100	1		55.19 f1429bb76c46459fa77db564e37a5624
45:29.5	Event button pressed				
45:29.6	Event button released				
45:29.7	Event button pressed				
45:29.8	Event button released				
45:31.2	Event button pressed				
45:34.2	Recording stopped due to button press	100	1		55.169 f1429bb76c46459fa77db564e37a5624
45:34.7	Event button released				
45:35.0	Audio recording disabled due to video buffering default				
46:24.5	Event button pressed				
46:24.7	Event button released				
46:24.7	Event button pressed				
46:24.7	Audio recording enabled due to video recording default				
46:24.8	Event button released				
46:24.9	Recording started due to button press	99	2		55.168 4db02fb44cec4b5cb572bda893bbf7f0
46:36.1	Event button pressed				
46:39.1	Recording stopped due to button press	99	2		55.137 4db02fb44cec4b5cb572bda893bbf7f0
46:39.7	Event button released				
46:40.0	Audio recording disabled due to video buffering default				
48:30.5	Power button pressed				
48:33.6	Device powered off using button	99	2		55.135
48:33.9	Power button released				
50:36.2	Device powered on using button	99	2		55.135
50:39.2	Audio recording disabled due to video buffering default				
50:43.6	Event button pressed				

50:43.7	Event button released			
50:43.8	Event button pressed			
50:43.8	Audio recording enabled due to video recording default			
50:43.9	Event button released			
50:44.0	Recording started due to button press	99	3	55.134 4674768963724d4a91cf4be05215d7c2
51:18.2	Event button pressed			
51:21.3	Recording stopped due to button press	99	3	55.113 4674768963724d4a91cf4be05215d7c2
51:21.7	Event button released			
51:22.2	Audio recording disabled due to video buffering default			
52:29.4	Event button pressed			
52:29.6	Event button released			
52:29.7	Event button pressed			
52:29.7	Audio recording enabled due to video recording default			
52:29.8	Event button released			
52:29.9	Recording started due to button press	99	4	55.112 adf09fa4b12745349bae04fa52d1d50a
53:09.3	Event button pressed			
53:12.3	Recording stopped due to button press	98	4	55.056 adf09fa4b12745349bae04fa52d1d50a
53:12.6	Event button released			
53:13.1	Audio recording disabled due to video buffering default			
53:18.4	Event button pressed			
53:18.6	Event button released			
53:18.7	Event button pressed			
53:18.7	Audio recording enabled due to video recording default			
53:18.8	Event button released			
53:18.8	Recording started due to button press	98	4	55.056 032322b11151459a97310bf113b451c5
53:51.5	Event button pressed			
53:54.5	Recording stopped due to button press	98	5	55.034 032322b11151459a97310bf113b451c5
53:55.0	Event button released			
53:55.2	Audio recording disabled due to video buffering default			
54:23.4	Event button pressed			
54:23.5	Event button released			
54:23.6	Event button pressed			
54:23.6	Audio recording enabled due to video recording default			
54:23.7	Event button released			
54:23.8	Recording started due to button press	98	6	55.034 e11d265f66734b159b605c38cbd0ea1e
55:05.1	Event button pressed			
55:08.1	Recording stopped due to button press	98	6	54.996 e11d265f66734b159b605c38cbd0ea1e
55:08.8	Event button released			
55:09.0	Audio recording disabled due to video buffering default			
57:15.0	Event button pressed			
57:15.1	Event button released			
57:15.2	Event button pressed			
57:15.3	Audio recording enabled due to video recording default			
57:15.3	Event button released			
57:15.4	Recording started due to button press	97	7	54.995 a3cb0dd78c4d4b5481aac9f696200bf6
58:24.0	Event button pressed			
58:27.0	Recording stopped due to button press	97	7	54.898 a3cb0dd78c4d4b5481aac9f696200bf6

58:27.5	Event button released			
58:27.9	Audio recording disabled due to video buffering default			
08:57.7	Event button pressed			
08:57.9	Event button released			
08:57.9	Event button pressed			
08:58.0	Audio recording enabled due to video recording default			
08:58.0	Event button released			
08:58.1	Recording started due to button press	96	8	54.896 346d0a282dc0467d8328bbb63cb85874
09:24.9	Event button pressed			
09:27.9	Recording stopped due to button press	96	8	54.83 346d0a282dc0467d8328bbb63cb85874
09:28.3	Event button released			
09:28.7	Audio recording disabled due to video buffering default			
09:35.8	Event button pressed			
09:35.9	Event button released			
09:36.0	Event button pressed			
09:36.0	Audio recording enabled due to video recording default			
09:36.1	Event button released			
09:36.1	Recording started due to button press	96	9	54.82 d26a3f94d1724de5983c49101e5cb665
09:56.4	Event button pressed			
09:59.4	Recording stopped due to button press	96	9	54.805 d26a3f94d1724de5983c49101e5cb665
09:59.8	Event button released			
10:00.2	Audio recording disabled due to video buffering default			
10:09.9	Event button pressed			
10:10.1	Event button released			
10:10.2	Event button pressed			
10:10.3	Event button released			
10:10.3	Audio recording enabled due to video recording default			
10:10.4	Recording started due to button press	96	10	54.804 99212c772a18466c8e75d2f5a2057af9
12:40.2	Event button pressed			
12:43.2	Recording stopped due to button press	95	10	54.719 99212c772a18466c8e75d2f5a2057af9
12:43.6	Event button released			
12:43.9	Audio recording disabled due to video buffering default			
25:54.8	Event button pressed			
25:55.0	Event button released			
25:55.1	Event button pressed			
25:55.1	Audio recording enabled due to video recording default			
25:55.2	Event button released			
25:55.2	Recording started due to button press	94	11	54.717 bcba6b6ed0fa4ff48f5d8b270678b817
26:05.5	Event button pressed			
26:08.5	Recording stopped due to button press	94	11	54.687 bcba6b6ed0fa4ff48f5d8b270678b817
26:08.9	Event button released			
26:09.3	Audio recording disabled due to video buffering default			
26:32.4	Event button pressed			
26:32.5	Event button released			
26:32.6	Event button pressed			
26:32.7	Audio recording enabled due to video recording default			
26:32.7	Event button released			

26:32.8 Recording started due to button press	94	12	54.65 342f44ceeabc409f9c01d2a62a4b7b97
27:22.8 Event button pressed			
27:25.8 Recording stopped due to button press	93	12	54.61 342f44ceeabc409f9c01d2a62a4b7b97
27:26.6 Event button released			
27:26.7 Audio recording disabled due to video buffering default			
28:02.2 Event button pressed			
28:02.3 Event button released			
28:02.4 Event button pressed			
28:02.4 Audio recording enabled due to video recording default			
28:02.5 Event button released			
28:02.6 Recording started due to button press	93	13	54.61 a8f295a0136442728652d4b9b10a1395
28:20.3 Event button pressed			
28:23.3 Recording stopped due to button press	93	13	54.581 a8f295a0136442728652d4b9b10a1395
28:23.8 Event button released			
28:24.1 Audio recording disabled due to video buffering default			
29:02.9 Event button pressed			
29:03.0 Event button released			
29:03.1 Event button pressed			
29:03.1 Audio recording enabled due to video recording default			
29:03.1 Event button released			
29:03.2 Recording started due to button press	93	14	54.58 108c929fa6724916b6144856ff15ef5a
29:25.5 Event button pressed			
29:28.5 Recording stopped due to button press	93	14	54.548 108c929fa6724916b6144856ff15ef5a
29:29.0 Event button released			
29:29.4 Audio recording disabled due to video buffering default			
38:36.9 Event button pressed			
38:37.1 Event button released			
38:37.1 Event button pressed			
38:37.2 Audio recording enabled due to video recording default			
38:37.3 Event button released			
38:37.3 Recording started due to button press	92	15	54.547 8ec27cb5d8954c28a3a3f10600499ffc
39:17.4 Event button pressed			
39:20.4 Recording stopped due to button press	92	15	54.464 8ec27cb5d8954c28a3a3f10600499ffc
39:20.9 Event button released			
39:21.2 Audio recording disabled due to video buffering default			
42:56.2 Event button pressed			
42:56.4 Event button released			
42:56.5 Event button pressed			
42:56.5 Audio recording enabled due to video recording default			
42:56.6 Event button released			
42:56.6 Recording started due to button press	91	16	54.464 62df219cedbd483c9429aa6563bc3316
43:10.2 Event button pressed			
43:10.4 Event button released			
43:10.5 Event button pressed			
43:10.6 Event button released			
43:11.0 Event button pressed			
43:14.0 Recording stopped due to button press	91	16	54.424 62df219cedbd483c9429aa6563bc3316

43:14.5 Event button released			
43:14.7 Audio recording disabled due to video buffering default			
43:20.5 Event button pressed			
43:20.7 Event button released			
43:20.8 Event button pressed			
43:20.8 Audio recording enabled due to video recording default			
43:20.9 Recording started due to button press	91	17	54.41 bce15b59d3d74765858e2ccc0a80588e
43:21.0 Event button released			
44:47.7 Event button pressed			
44:49.1 Audit log created	91	17 1.15.14	54.344
44:50.7 Recording stopped due to button press	91	17	54.343 bce15b59d3d74765858e2ccc0a80588e
44:51.1 Event button released			
44:51.4 Audio recording disabled due to video buffering default			
45:05.1 Event button pressed			
45:05.2 Event button released			
45:05.3 Event button pressed			
45:05.4 Audio recording enabled due to video recording default			
45:05.4 Event button released			
45:05.5 Recording started due to button press	91	18	54.342 5f51b63097ab49d281311c190211b862
46:07.9 Event button pressed			
46:10.9 Recording stopped due to button press	91	18	54.301 5f51b63097ab49d281311c190211b862
46:11.4 Event button released			
46:11.8 Audio recording disabled due to video buffering default			
46:21.2 Event button pressed			
46:21.4 Event button released			
46:21.5 Event button pressed			
46:21.6 Audio recording enabled due to video recording default			
46:21.6 Event button released			
46:21.7 Recording started due to button press	91	19	54.3 ddd05f7049d849a1b4ae188febced5ec
46:30.0 Event button pressed			
46:30.2 Event button released			
46:30.3 Event button pressed			
46:30.4 Event button released			
46:31.4 Event button pressed			
46:34.4 Recording stopped due to button press	90	19	54.289 ddd05f7049d849a1b4ae188febced5ec
46:35.0 Event button released			
46:35.2 Audio recording disabled due to video buffering default			
46:44.3 Event button pressed			
46:44.5 Event button released			
46:44.6 Event button pressed			
46:44.7 Audio recording enabled due to video recording default			
46:44.8 Recording started due to button press	90	20	54.289 1a2aa47ecdb340d2956d5185474b972d
46:44.8 Event button released			
46:51.7 Event button pressed			
46:54.7 Recording stopped due to button press	90	20	54.279 1a2aa47ecdb340d2956d5185474b972d
46:55.1 Event button released			
46:55.5 Audio recording disabled due to video buffering default			

47:04.2 Event button pressed			
47:04.4 Event button released			
47:04.5 Event button pressed			
47:04.6 Audio recording enabled due to video recording default			
47:04.6 Event button released			
47:04.7 Recording started due to button press	90	21	54.278 591abd9135404bf9a9802083a10efabd
47:14.3 Event button pressed			
47:17.3 Recording stopped due to button press	90	21	54.268 591abd9135404bf9a9802083a10efabd
47:17.8 Event button released			
47:18.0 Audio recording disabled due to video buffering default			
47:20.3 Event button pressed			
47:20.5 Event button released			
47:20.6 Event button pressed			
47:20.6 Audio recording enabled due to video recording default			
47:20.7 Event button released			
47:20.7 Recording started due to button press	90	22	54.267 171547cef65a45249a86fc7e2e12d2bf
47:48.7 Event button pressed			
47:51.7 Recording stopped due to button press	90	22	54.25 171547cef65a45249a86fc7e2e12d2bf
47:52.3 Event button released			
47:52.5 Audio recording disabled due to video buffering default			
48:13.2 Event button pressed			
48:13.4 Event button released			
48:13.5 Event button pressed			
48:13.5 Audio recording enabled due to video recording default			
48:13.6 Event button released			
48:13.6 Recording started due to button press	90	23	54.249 a64bec06d6f348cebb7698f3752cc144
49:04.9 Event button pressed			
49:07.9 Recording stopped due to button press	90	23	54.21 a64bec06d6f348cebb7698f3752cc144
49:08.4 Event button released			
49:08.6 Audio recording disabled due to video buffering default			
50:03.1 Event button pressed			
50:03.3 Event button released			
50:03.3 Event button pressed			
50:03.4 Audio recording enabled due to video recording default			
50:03.4 Event button released			
50:03.5 Recording started due to button press	90	24	54.209 d8b1e8a15ad04649a14f915b01b6c5aa
50:19.8 Event button pressed			
50:22.8 Recording stopped due to button press	90	24	54.172 d8b1e8a15ad04649a14f915b01b6c5aa
50:23.3 Event button released			
50:23.8 Audio recording disabled due to video buffering default			
50:36.1 Event button pressed			
50:36.3 Event button released			
50:36.4 Event button pressed			
50:36.4 Audio recording enabled due to video recording default			
50:36.5 Event button released			
50:36.5 Recording started due to button press	90	25	54.171 3554ee6cb08044ab9dc5754cda9a4e6e
50:51.4 Event button pressed			

50:54.4 Recording stopped due to button press	90	25	54.156 3554ee6cb08044ab9dc5754cda9a4e6e
50:55.0 Event button released			
50:55.2 Audio recording disabled due to video buffering default			
51:11.1 Event button pressed			
51:11.2 Event button released			
51:11.3 Event button pressed			
51:11.3 Audio recording enabled due to video recording default			
51:11.4 Event button released			
51:11.5 Recording started due to button press	90	26	54.155 bf485dedaf7c4833b4d9c936f3e69df1
51:25.2 Event button pressed			
51:28.2 Recording stopped due to button press	90	26	54.139 bf485dedaf7c4833b4d9c936f3e69df1
51:28.8 Event button released			
51:29.2 Audio recording disabled due to video buffering default			
51:47.0 Event button pressed			
51:47.1 Event button released			
51:47.2 Event button pressed			
51:47.3 Audio recording enabled due to video recording default			
51:47.3 Event button released			
51:47.4 Recording started due to button press	90	27	54.138 2bc90ae32e3b425b9c8bda468a08c5cf
52:12.6 Event button pressed			
52:12.8 Event button released			
52:12.8 Event button pressed			
52:12.9 Event button released			
52:39.8 Event button pressed			
52:42.8 Recording stopped due to button press	90	27	54.1 2bc90ae32e3b425b9c8bda468a08c5cf
52:43.6 Event button released			
52:43.8 Audio recording disabled due to video buffering default			
52:59.3 Event button pressed			
53:02.8 Event button released			
53:03.0 Event button pressed			
53:03.1 Event button released			
53:03.2 Event button pressed			
53:03.2 Audio recording enabled due to video recording default			
53:03.3 Event button released			
53:03.3 Recording started due to button press	90	28	54.099 2c25f6f8dc764d79b56f242542eaf095
53:22.9 Event button pressed			
53:25.9 Recording stopped due to button press	89	28	54.078 2c25f6f8dc764d79b56f242542eaf095
53:26.6 Event button released			
53:26.8 Audio recording disabled due to video buffering default			
53:42.5 Event button pressed			
53:42.6 Event button released			
53:42.7 Event button pressed			
53:42.7 Audio recording enabled due to video recording default			
53:42.8 Event button released			
53:42.9 Recording started due to button press	89	28	54.077 0c8ed000d768494c8ffad12a563a0969
53:51.2 Event button pressed			
53:54.2 Recording stopped due to button press	89	29	54.064 0c8ed000d768494c8ffad12a563a0969

53:54.9 Audio recording disabled due to video buffering default			
53:55.3 Event button released			
54:45.3 Event button pressed			
54:45.4 Event button released			
54:45.5 Event button pressed			
54:45.5 Audio recording enabled due to video recording default			
54:45.6 Event button released			
54:45.7 Recording started due to button press	89	30	54.063 e58dabb721ca4bafae6d7f14b0f7590f
55:07.1 Event button pressed			
55:10.1 Recording stopped due to button press	89	30	54.025 e58dabb721ca4bafae6d7f14b0f7590f
55:10.7 Event button released			
55:10.8 Audio recording disabled due to video buffering default			
55:13.6 Event button pressed			
55:13.8 Event button released			
55:13.8 Event button pressed			
55:13.9 Audio recording enabled due to video recording default			
55:13.9 Event button released			
55:14.0 Recording started due to button press	89	31	54.024 f2702d0fa9bf48edac368473a50bfe12
55:36.9 Event button pressed			
55:39.9 Recording stopped due to button press	89	31	54.01 f2702d0fa9bf48edac368473a50bfe12
55:40.6 Event button released			
55:40.7 Audio recording disabled due to video buffering default			
55:44.6 Event button pressed			
55:44.7 Event button released			
55:44.8 Event button pressed			
55:44.8 Audio recording enabled due to video recording default			
55:44.9 Event button released			
55:45.0 Recording started due to button press	89	32	54.009 0ecf6cbb98b84ba5bdd7796a586e36c6
56:11.1 Event button pressed			
56:14.1 Recording stopped due to button press	89	32	53.992 0ecf6cbb98b84ba5bdd7796a586e36c6
56:14.5 Event button released			
56:14.9 Audio recording disabled due to video buffering default			
56:47.1 Event button pressed			
56:47.3 Event button released			
56:47.4 Event button pressed			
56:47.4 Audio recording enabled due to video recording default			
56:47.5 Event button released			
56:47.5 Recording started due to button press	89	33	53.991 25e5e97fec8d4f66b7e18d30465aca03
58:09.1 Event button pressed			
58:12.1 Recording stopped due to button press	89	33	53.931 25e5e97fec8d4f66b7e18d30465aca03
58:12.5 Event button released			
58:13.0 Audio recording disabled due to video buffering default			
01:02.5 Axon application connected to device			
03:01.8 Event button pressed			
03:02.0 Event button released			
03:03.3 Event button pressed			
03:03.4 Event button released			

03:03.5	Event button pressed			
03:03.5	Audio recording enabled due to video recording default			
03:03.6	Event button released			
03:03.6	Recording started due to button press	88	34	53.929 d1f302806291428d9fabe350e9097fe5
03:32.1	Event button pressed			
03:35.1	Recording stopped due to button press	88	34	53.86 d1f302806291428d9fabe350e9097fe5
03:35.6	Event button released			
03:35.8	Audio recording disabled due to video buffering default			
03:49.1	Event button pressed			
03:49.2	Event button released			
03:49.3	Event button pressed			
03:49.3	Audio recording enabled due to video recording default			
03:49.4	Event button released			
03:49.4	Recording started due to button press	88	35	53.851 0893bb2797064eb2ac04075b4e89decb
04:02.5	Event button pressed			
04:05.5	Recording stopped due to button press	88	35	53.836 0893bb2797064eb2ac04075b4e89decb
04:06.0	Event button released			
04:06.3	Audio recording disabled due to video buffering default			
04:24.4	Event button pressed			
04:24.5	Event button released			
04:24.6	Event button pressed			
04:24.6	Audio recording enabled due to video recording default			
04:24.7	Event button released			
04:24.7	Recording started due to button press	88	35	53.835 3c52f567c9644e028439d4b6b942d0b4
04:42.9	Event button pressed			
04:45.9	Recording stopped due to button press	88	36	53.815 3c52f567c9644e028439d4b6b942d0b4
04:46.4	Event button released			
04:46.8	Audio recording disabled due to video buffering default			
05:01.8	Event button pressed			
05:02.0	Event button released			
05:02.1	Event button pressed			
05:02.1	Audio recording enabled due to video recording default			
05:02.1	Event button released			
05:02.2	Recording started due to button press	88	37	53.814 e62c165aae824949b475d7e09e10a407
05:17.5	Event button pressed			
05:20.5	Recording stopped due to button press	88	37	53.797 e62c165aae824949b475d7e09e10a407
05:21.0	Event button released			
05:21.2	Audio recording disabled due to video buffering default			
05:38.0	Event button pressed			
05:38.2	Event button released			
05:38.2	Event button pressed			
05:38.2	Audio recording enabled due to video recording default			
05:38.3	Event button released			
05:38.4	Recording started due to button press	87	38	53.796 e2fbc22b2ac3409988f72967d78d6cd9
05:54.0	Event button pressed			
05:57.1	Recording stopped due to button press	87	38	53.778 e2fbc22b2ac3409988f72967d78d6cd9
05:57.6	Event button released			

05:58.0	Audio recording disabled due to video buffering default			
06:11.9	Event button pressed			
06:12.1	Event button released			
06:12.1	Event button pressed			
06:12.2	Audio recording enabled due to video recording default			
06:12.2	Event button released			
06:12.3	Recording started due to button press	87	38	53.778 7f94747f2b794986968699046db1081f
06:24.1	Event button pressed			
06:27.1	Recording stopped due to button press	87	39	53.763 7f94747f2b794986968699046db1081f
06:27.9	Audio recording disabled due to video buffering default			
06:28.0	Event button released			
06:30.3	Event button pressed			
06:30.5	Event button released			
06:30.6	Event button pressed			
06:30.6	Audio recording enabled due to video recording default			
06:30.7	Event button released			
06:30.7	Recording started due to button press	87	40	53.762 bb7798af92244b84832e771b5adc6f9a
08:08.0	Event button pressed			
08:11.0	Recording stopped due to button press	87	40	53.708 bb7798af92244b84832e771b5adc6f9a
08:11.4	Event button released			
08:11.9	Audio recording disabled due to video buffering default			
12:05.2	Video played back using Axon application			d8b1e8a15ad04649a14f915b01b6c5aa
12:15.4	Video played back using Axon application			3554ee6cb08044ab9dc5754cda9a4e6e
13:13.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1750 X6033271L' to '75s NE10 Train 303 Car132' using Axon applicator			3554ee6cb08044ab9dc5754cda9a4e6e
13:13.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			3554ee6cb08044ab9dc5754cda9a4e6e
13:35.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1750 X6033271L' to '75s NE10 Train 303 Car 131' using Axon applicator			d8b1e8a15ad04649a14f915b01b6c5aa
13:43.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			d8b1e8a15ad04649a14f915b01b6c5aa
15:32.6	Event button pressed			
15:32.7	Event button released			
15:32.8	Event button pressed			
15:32.8	Audio recording enabled due to video recording default			
15:32.8	Event button released			
15:33.0	Recording started due to button press	86	41	53.704 792e73b22d094628800f61c5e828e7c9
15:48.9	Event button pressed			
15:49.0	Event button released			
15:49.1	Event button pressed			
15:49.2	Event button released			
15:56.3	Event button pressed			
15:59.3	Recording stopped due to button press	86	41	53.644 792e73b22d094628800f61c5e828e7c9
16:00.1	Audio recording disabled due to video buffering default			
16:00.4	Event button released			
16:16.6	Event button pressed			
16:16.7	Event button released			
16:16.8	Event button pressed			
16:16.8	Audio recording enabled due to video recording default			
16:16.9	Event button released			
16:16.9	Recording started due to button press	86	42	53.629 4051506d35d3498a8246747b96ca523f

16:28.3 Event button pressed			
16:31.3 Recording stopped due to button press	86	42	53.613 4051506d35d3498a8246747b96ca523f
16:31.8 Event button released			
16:32.0 Audio recording disabled due to video buffering default			
16:46.5 Event button pressed			
16:46.6 Event button released			
16:46.7 Event button pressed			
16:46.8 Audio recording enabled due to video recording default			
16:46.8 Event button released			
16:46.9 Recording started due to button press	86	43	53.613 033a5faa49e14209886be53832f5f882
16:58.3 Event button pressed			
17:01.3 Recording stopped due to button press	86	43	53.598 033a5faa49e14209886be53832f5f882
17:02.2 Audio recording disabled due to video buffering default			
17:02.2 Event button released			
17:19.4 Event button pressed			
17:19.5 Event button released			
17:19.6 Event button pressed			
17:19.6 Audio recording enabled due to video recording default			
17:19.7 Event button released			
17:19.7 Recording started due to button press	86	44	53.597 c95dad872ad943baba126a73f4e7b29e
17:27.2 Event button pressed			
17:30.2 Recording stopped due to button press	86	44	53.584 c95dad872ad943baba126a73f4e7b29e
17:30.5 Event button released			
17:31.1 Audio recording disabled due to video buffering default			
17:34.2 Event button pressed			
17:34.3 Event button released			
17:34.4 Event button pressed			
17:34.4 Audio recording enabled due to video recording default			
17:34.5 Event button released			
17:34.5 Recording started due to button press	86	45	53.583 8616ce3215e642e0afc13b4fad28d88d
17:48.7 Event button pressed			
17:51.7 Recording stopped due to button press	86	45	53.573 8616ce3215e642e0afc13b4fad28d88d
17:52.2 Event button released			
17:52.4 Audio recording disabled due to video buffering default			
18:17.0 Event button pressed			
18:17.2 Event button released			
18:17.2 Event button pressed			
18:17.3 Audio recording enabled due to video recording default			
18:17.3 Event button released			
18:17.4 Recording started due to button press	86	46	53.572 d33f17c07253453eb2570242559b48f7
18:27.5 Event button pressed			
18:30.5 Recording stopped due to button press	86	46	53.553 d33f17c07253453eb2570242559b48f7
18:31.2 Event button released			
18:31.3 Audio recording disabled due to video buffering default			
18:47.7 Event button pressed			
18:48.6 Event button released			
18:48.8 Event button pressed			

18:48.9	Event button released				
18:48.9	Event button pressed				
18:49.0	Audio recording enabled due to video recording default				
18:49.0	Event button released				
18:49.1	Recording started due to button press	86	47	53.552	8bfcb562b5ae4b2bb620c0a72652d876
19:01.3	Event button pressed				
19:04.3	Recording stopped due to button press	85	47	53.536	8bfcb562b5ae4b2bb620c0a72652d876
19:04.8	Event button released				
19:05.2	Audio recording disabled due to video buffering default				
19:09.4	Event button pressed				
19:09.6	Event button released				
19:09.7	Event button pressed				
19:09.7	Audio recording enabled due to video recording default				
19:09.7	Event button released				
19:09.9	Recording started due to button press	85	48	53.535	127db577ed804b5f998a5039c3349d5e
20:43.4	Event button pressed				
20:46.4	Recording stopped due to button press	85	48	53.482	127db577ed804b5f998a5039c3349d5e
20:46.9	Event button released				
20:47.3	Audio recording disabled due to video buffering default				
23:35.1	Video played back using Axon application				d1f302806291428d9fabe350e9097fe5
24:27.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1803 X6033271L' to '75s NE10 Train 304 Car 607' using Axon applicator				d1f302806291428d9fabe350e9097fe5
24:27.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				d1f302806291428d9fabe350e9097fe5
25:16.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1803 X6033271L' to '75s NE10 Train 304 Car 608' using Axon applicator				0893bb2797064eb2ac04075b4e89decb
25:16.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				0893bb2797064eb2ac04075b4e89decb
26:12.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1804 X6033271L' to '75s NE10 Train 304 Car 299' using Axon applicator				3c52f567c9644e028439d4b6b942d0b4
26:12.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				3c52f567c9644e028439d4b6b942d0b4
26:52.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1805 X6033271L' to '75s NE10 Train 304 Car 300' using Axon applicator				e2fbc22b2ac3409988f72967d78d6cd9
26:52.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				e2fbc22b2ac3409988f72967d78d6cd9
27:09.4	Title changed in video metadata from '75s NE10 Train 304 Car 300' to '75s NE10 Train 304 Car 292' using Axon applicator				e2fbc22b2ac3409988f72967d78d6cd9
27:40.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1805 X6033271L' to '75s NE10 Train 304 Car 300' using Axon applicator				e62c165aae824949b475d7e09e10a407
27:40.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				e62c165aae824949b475d7e09e10a407
28:03.3	Video played back using Axon application				7f94747f2b794986968699046db1081f
28:36.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1806 X6033271L' to '75s NE10 Train 304 Car 291' using Axon applicator				7f94747f2b794986968699046db1081f
29:17.9	Video played back using Axon application				bb7798af92244b84832e771b5adc6f9a
29:54.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1806 X6033271L' to '75 NE10 Platform' using Axon applicator				bb7798af92244b84832e771b5adc6f9a
29:54.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				bb7798af92244b84832e771b5adc6f9a
30:14.6	Video played back using Axon application				792e73b22d094628800f61c5e828e7c9
30:48.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1815 X6033271L' to '75s NE10 Train 305 Car 217' using Axon applicator				792e73b22d094628800f61c5e828e7c9
30:48.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				792e73b22d094628800f61c5e828e7c9
31:34.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1816 X6033271L' to '75s NE10 Train 305 Car 218' using Axon applicator				4051506d35d3498a8246747b96ca523f
31:34.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				4051506d35d3498a8246747b96ca523f
32:16.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1816 X6033271L' to '75s NE10 Train 305 Car 261' using Axon applicator				033a5faa49e14209886be53832f5f882
33:09.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1817 X6033271L' to '15 NE10 Platform' using Axon applicator				c95dad872ad943baba126a73f4e7b29e
33:09.1	Categories 'Customer Assist' added to video metadata using Axon applicator				c95dad872ad943baba126a73f4e7b29e
33:45.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1817 X6033271L' to '75s NE10 Train 305 Car 262' using Axon applicator				8616ce3215e642e0afc13b4fad28d88d
33:45.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				8616ce3215e642e0afc13b4fad28d88d
34:43.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1818 X6033271L' to '75s NE10 Train 305 Car 129' using Axon applicator				d33f17c07253453eb2570242559b48f7

34:43.9 Categories 'Miscellaneous' added to video metadata using Axon applicator				d33f17c07253453eb2570242559b48f7
35:12.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1818 X6033271L' to '75s NE10 Train 305 Car 130' using Axon applicator				8bfc562b5ae4b2bb620c0a72652d876
35:12.6 Categories 'Miscellaneous' added to video metadata using Axon applicator				8bfc562b5ae4b2bb620c0a72652d876
35:48.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1819 X6033271L' to '75 NE10 Platform' using Axon applicator				127db577ed804b5f998a5039c3349d5e
35:48.4 Categories 'Miscellaneous' added to video metadata using Axon applicator				127db577ed804b5f998a5039c3349d5e
36:10.3 Categories 'Miscellaneous' added to video metadata using Axon applicator				7f94747f2b794986968699046db1081f
36:47.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1756 X6033271L' to '75 NE10 Platform' using Axon applicator				25e5e97fec8d4f66b7e18d30465aca03
36:47.9 Categories 'Miscellaneous' added to video metadata using Axon applicator				25e5e97fec8d4f66b7e18d30465aca03
37:07.6 Video played back using Axon application				0ecf6cbb98b84ba5bdd7796a586e36c6
37:42.5 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1755 X6033271L' to '75 Bus Loop NE10' using Axon applicator				0ecf6cbb98b84ba5bdd7796a586e36c6
37:42.5 Categories 'Miscellaneous' added to video metadata using Axon applicator				0ecf6cbb98b84ba5bdd7796a586e36c6
38:30.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1755 X6033271L' to '75 Concourse NE10' using Axon applicator				f2702d0fa9bf48edac368473a50bfe12
38:30.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				f2702d0fa9bf48edac368473a50bfe12
38:46.0 Title changed in video metadata from '75 Concourse NE10' to '75 NE10 Concourse' using Axon applicator				f2702d0fa9bf48edac368473a50bfe12
39:06.1 Title changed in video metadata from '75 Bus Loop NE10' to '75 NE10 Bus Loop' using Axon applicator				0ecf6cbb98b84ba5bdd7796a586e36c6
40:31.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1754 X6033271L' to '75 NE10 Concourse' using Axon applicator				e58dabb721ca4bafae6d7f14b0f7590f
40:31.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				e58dabb721ca4bafae6d7f14b0f7590f
41:26.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1753 X6033271L' to '75s NE10 Train 305 Car 131' using Axon applicator				0c8ed000d768494c8ffad12a563a0969
41:26.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				0c8ed000d768494c8ffad12a563a0969
41:39.2 Title changed in video metadata from '75s NE10 Train 305 Car 131' to '75s NE10 Train 305 Car 275' using Axon applicator				0c8ed000d768494c8ffad12a563a0969
42:13.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1753 X6033271L' to '75s NE10 Train 303 Car 276' using Axon applicator				2c25f6f8dc764d79b56f242542eaf095
42:13.4 Categories 'Miscellaneous' added to video metadata using Axon applicator				2c25f6f8dc764d79b56f242542eaf095
42:28.3 Title changed in video metadata from '75s NE10 Train 305 Car 275' to '75s NE10 Train 303 Car 275' using Axon applicator				0c8ed000d768494c8ffad12a563a0969
43:04.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1751 X6033271L' to '75s NE10 Train 303 Car 177' using Axon applicator				2bc90ae32e3b425b9c8bda468a08c5cf
43:04.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				2bc90ae32e3b425b9c8bda468a08c5cf
43:36.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1751 X6033271L' to '75s NE10 Train 303 Car 178' using Axon applicator				bf485dedaf7c4833b4d9c936f3e69df1
43:36.8 Categories 'Miscellaneous' added to video metadata using Axon applicator				bf485dedaf7c4833b4d9c936f3e69df1
44:20.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1748 X6033271L' to '75 NE10 Platform' using Axon applicator				a64bec06d6f348cebb7698f3752cc144
44:20.3 Categories 'Miscellaneous' added to video metadata using Axon applicator				a64bec06d6f348cebb7698f3752cc144
44:49.1 Audit log created	83	48 1.15.14	53.479	
45:02.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1747 X6033271L' to '75 NE10 Concourse' using Axon applicator				171547cef65a45249a86fc7e2e12d2bf
45:02.2 Categories 'Miscellaneous' added to video metadata using Axon applicator				171547cef65a45249a86fc7e2e12d2bf
45:54.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1747 X6033271L' to '15 NE10 Restroom' using Axon applicator				591abd9135404bf9a9802083a10efabd
45:54.3 Categories 'Customer Assist' added to video metadata using Axon applicator				591abd9135404bf9a9802083a10efabd
46:23.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1746 X6033271L' to '15 NE10 Restroom' using Axon applicator				1a2aa47ecdb340d2956d5185474b972d
46:23.0 Categories 'Customer Assist' added to video metadata using Axon applicator				1a2aa47ecdb340d2956d5185474b972d
46:54.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1746 X6033271L' to '15 NE10 Restroom' using Axon applicator				ddd05f7049d849a1b4ae188febced5ec
46:54.1 Categories 'Customer Assist' added to video metadata using Axon applicator				ddd05f7049d849a1b4ae188febced5ec
47:35.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1745 X6033271L' to '75 NE10 Bus Loop' using Axon applicator				5f51b63097ab49d281311c190211b862
47:35.3 Categories 'Miscellaneous' added to video metadata using Axon applicator				5f51b63097ab49d281311c190211b862
48:26.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1743 X6033271L' to '75 NE10 Parking Lot' using Axon applicator				bce15b59d3d74765858e2ccc0a80588e
48:26.4 Categories 'Miscellaneous' added to video metadata using Axon applicator				bce15b59d3d74765858e2ccc0a80588e
49:43.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1645 X6033271L' to '75 NE10 Bus Loop' using Axon applicator				f1429bb76c46459fa77db564e37a5624
49:43.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				f1429bb76c46459fa77db564e37a5624
50:04.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1646 X6033271L' to '75 NE10 Concourse' using Axon applicator				4db02fb44cecb4b5cb572bda893bbf7f0
50:04.3 Categories 'Miscellaneous' added to video metadata using Axon applicator				4db02fb44cecb4b5cb572bda893bbf7f0
50:33.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1650 X6033271L' to '75 NE10 Bus Loop' using Axon applicator				4674768963724d4a91cf4be05215d7c2

50:33.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				4674768963724d4a91cf4be05215d7c2
53:09.3	Title changed in video metadata from '75 NE10 Bus Loop' to '23 NE8' using Axon applicator				4674768963724d4a91cf4be05215d7c2
53:09.3	Categories 'Disorderly Person' added to video metadata using Axon applicator				4674768963724d4a91cf4be05215d7c2
53:09.3	Categories 'Miscellaneous' removed from video metadata using Axon applicator				4674768963724d4a91cf4be05215d7c2
53:41.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1652 X6033271L' to '75 NE10 Bus Loop' using Axon applicator				adf09fa4b12745349bae04fa52d1d50a
53:41.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				adf09fa4b12745349bae04fa52d1d50a
54:50.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1653 X6033271L' to '75 NE10 Concourse' using Axon applicator				032322b11151459a97310bf113b451c5
54:50.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				032322b11151459a97310bf113b451c5
55:09.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1654 X6033271L' to '75 NE10 Platform' using Axon applicator				e11d265f66734b159b605c38cbd0ea1e
55:09.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				e11d265f66734b159b605c38cbd0ea1e
55:45.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1657 X6033271L' to '75 NE10 Platform' using Axon applicator				a3cb0dd78c4d4b5481aac9f696200bf6
55:45.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				a3cb0dd78c4d4b5481aac9f696200bf6
56:15.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1708 X6033271L' to '75 NE10 Concourse' using Axon applicator				346d0a282dc0467d8328bbb63cb85874
56:15.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				346d0a282dc0467d8328bbb63cb85874
56:46.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1709 X6033271L' to '75 NE10 Bus Loop' using Axon applicator				d26a3f94d1724de5983c49101e5cb665
56:46.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				d26a3f94d1724de5983c49101e5cb665
57:30.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1710 X6033271L' to '23 NE8' using Axon applicator				99212c772a18466c8e75d2f5a2057af9
57:30.6	Categories 'Disorderly Person' added to video metadata using Axon applicator				99212c772a18466c8e75d2f5a2057af9
58:03.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1725 X6033271L' to '75 NE8 Lot' using Axon applicator				bcba6b6ed0fa4ff48f5d8b270678b817
58:03.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				bcba6b6ed0fa4ff48f5d8b270678b817
58:40.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1726 X6033271L' to '23 NE8 Concourse' using Axon applicator				342f44ceeabc409f9c01d2a62a4b7b97
58:40.6	Categories 'Disorderly Person' added to video metadata using Axon applicator				342f44ceeabc409f9c01d2a62a4b7b97
59:04.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1728 X6033271L' to '75 NE8 Concourse' using Axon applicator				a8f295a0136442728652d4b9b10a1395
59:04.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				a8f295a0136442728652d4b9b10a1395
59:40.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1729 X6033271L' to '75 NE8 Parking Lot' using Axon applicator				108c929fa6724916b6144856ff15ef5a
59:40.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				108c929fa6724916b6144856ff15ef5a
00:22.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1738 X6033271L' to '75 NE9 Parking Lots' using Axon applicator				8ec27cb5d8954c28a3a3f10600499ffc
00:22.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				8ec27cb5d8954c28a3a3f10600499ffc
01:08.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 1742 X6033271L' to '75 NE10 Parking Lots' using Axon applicator				62df219cedbd483c9429aa6563bc3316
01:08.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				62df219cedbd483c9429aa6563bc3316
02:13.4	Categories 'Customer Assist' added to video metadata using Axon applicator				171547cef65a45249a86fc7e2e12d2bf
02:13.4	Categories 'Miscellaneous' removed from video metadata using Axon applicator				171547cef65a45249a86fc7e2e12d2bf
02:24.6	Title changed in video metadata from '75 NE10 Concourse' to '15 NE10 Restroom' using Axon applicator				171547cef65a45249a86fc7e2e12d2bf
21:09.6	Title changed in video metadata from '23 NE8' to '75 NE10 Bus Loop' using Axon applicator				4674768963724d4a91cf4be05215d7c2
21:09.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				4674768963724d4a91cf4be05215d7c2
21:09.6	Categories 'Disorderly Person' removed from video metadata using Axon applicator				4674768963724d4a91cf4be05215d7c2
32:31.2	Title changed in video metadata from '75 NE10 Parking Lot' to '75 NE10 Parking Lot + Bus Loop' using Axon applicator				bce15b59d3d74765858e2ccc0a80588e
33:57.5	Title changed in video metadata from '75 NE10 Parking Lot + Bus Loop' to '75 NE10 Parking Lot 2 + Bus Loop' using Axon applicator				bce15b59d3d74765858e2ccc0a80588e
34:09.2	Title changed in video metadata from '75 NE10 Parking Lots' to '75 NE10 Parking Lot 3' using Axon applicator				62df219cedbd483c9429aa6563bc3316
44:49.1	Audit log created	75	48 1.15.14	53.477	
17:24.5	Axon application disconnected from device				
17:48.6	Axon application connected to device				
18:41.6	Axon application disconnected from device				
44:49.2	Audit log created	68	48 1.15.14	53.475	
47:30.3	Event button pressed				
47:30.3	Event button released				
47:30.4	Event button pressed				

47:30.4	Audio recording enabled due to video recording default				
47:30.5	Event button released				
47:30.6	Recording started due to button press	68	49	53.474	709907a59de149b28cf3b730e2e0160c
47:54.5	Event button pressed				
47:54.6	Event button released				
47:54.7	Event button pressed				
47:54.8	Event button released				
47:56.5	Event button pressed				
47:59.6	Recording stopped due to button press	67	49	53.411	709907a59de149b28cf3b730e2e0160c
48:00.0	Event button released				
48:00.3	Audio recording disabled due to video buffering default				
55:41.7	Axon application connected to device				
56:18.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-02 2047 X6033271L' to 'Sig. 15 NE10 Restroom' using Axon applicator				709907a59de149b28cf3b730e2e0160c
56:18.6	Categories 'Customer Assist' added to video metadata using Axon applicator				709907a59de149b28cf3b730e2e0160c
57:13.2	Axon application disconnected from device				
44:49.2	Audit log created	60	49 1.15.14	53.397	
46:59.0	Power button pressed				
47:02.2	Device powered off using button	60	49	53.397	
47:02.6	Power button released				
03:09.2	Audit log created		1.15.14		
03:09.3	Device powered on using button	61	49	53.404	
03:11.3	Audio recording disabled due to video buffering default				
16:10.6	Axon application connected to device				
29:18.5	Axon application disconnected from device				
03:09.2	Audit log created	52	49 1.15.14	53.403	
03:09.2	Audit log created	45	49 1.15.14	53.401	
46:38.2	Event button pressed				
46:38.3	Event button released				
46:38.4	Event button pressed				
46:38.4	Audio recording enabled due to video recording default				
46:38.5	Event button released				
46:38.6	Recording started due to button press	40	50	53.4	d132640e42784690bb4336607752ef08
49:28.5	Event button pressed				
49:31.5	Recording stopped due to button press	39	50	53.248	d132640e42784690bb4336607752ef08
49:32.3	Audio recording disabled due to video buffering default				
49:32.5	Event button released				
49:35.1	Event button pressed				
49:35.3	Event button released				
49:35.4	Event button pressed				
49:35.4	Audio recording enabled due to video recording default				
49:35.5	Event button released				
49:35.5	Recording started due to button press	39	51	53.247	03527056f44c4c82aba82cfb0bae68d5
51:47.7	Event button pressed				
51:50.7	Recording stopped due to button press	39	51	53.175	03527056f44c4c82aba82cfb0bae68d5
51:51.3	Event button released				
51:51.5	Audio recording disabled due to video buffering default				
52:09.6	Axon application connected to device				

52:47.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-03 0146 X6033271L' to 'NE10 Detail' using Axon applicati			d132640e42784690bb4336607752ef08
52:47.8	Categories 'Sleeper' added to video metadata using Axon applicati			d132640e42784690bb4336607752ef08
53:57.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-03 0149 X6033271L' to 'NE10 Detail' using Axon applicati			03527056f44c4c82aba82cfb0bae68d5
53:57.8	Categories 'Sleeper' added to video metadata using Axon applicati			03527056f44c4c82aba82cfb0bae68d5
03:09.2	Audit log created	38	51 1.15.14	53.173
09:39.1	Axon application disconnected from device			
09:58.5	Volume up button pressed			
09:58.5	Volume up button released			
09:58.6	Volume changed to high from medium using button			
10:04.2	Volume down button pressed			
10:04.4	Volume down button released			
10:04.5	Volume changed to medium from high using button			
10:10.5	Camera connected to Axon Dock X62001W9H	37	51	53.193
10:10.5	Audit log rolled	37	51	53.173
10:10.5	Audit log created	37	51 1.15.14	53.173
10:11.3	Device connected to charger	37	51	53.173
10:30.4	Video upload started when camera was docked			f1429bb76c46459fa77db564e37a5624
10:40.4	Audit log successfully uploaded			
10:40.6	Audit log successfully uploaded and deleted from device	37	51	53.193
10:42.0	Date/Time synced to 09/03/2021 02:10:42.01 AM from 09/03/2021 02:10:40.52 AM			
10:42.9	Video successfully uploaded from device when dockec			f1429bb76c46459fa77db564e37a5624
10:43.2	Video deleted from device when docked	37	50	53.214 f1429bb76c46459fa77db564e37a5624
10:43.2	Audit log created	37	50 1.15.14	53.214
10:43.2	Audit log rolled	37	50	53.214
10:43.5	Video upload started when camera was docked			4db02fb44cec4b5cb572bda893bbf7f0
11:02.4	Audit log successfully uploaded			
11:02.6	Audit log successfully uploaded and deleted from device	38	50	53.215
11:08.5	Video successfully uploaded from device when dockec			4db02fb44cec4b5cb572bda893bbf7f0
11:08.7	Video deleted from device when docked	38	49	53.247 4db02fb44cec4b5cb572bda893bbf7f0
11:08.7	Audit log created	38	49 1.15.14	53.247
11:08.7	Audit log rolled	38	49	53.247
11:08.9	Video upload started when camera was docked			4674768963724d4a91cf4be05215d7c2
11:11.7	Audit log successfully uploaded			
11:11.9	Audit log successfully uploaded and deleted from device	38	49	53.247
11:19.1	Audit log successfully uploaded			
11:19.3	Audit log successfully uploaded and deleted from device	38	49	53.247
11:21.9	Video successfully uploaded from device when dockec			4674768963724d4a91cf4be05215d7c2
11:22.1	Video deleted from device when docked	38	48	53.269 4674768963724d4a91cf4be05215d7c2
11:22.2	Audit log created	38	48 1.15.14	53.269
11:22.2	Audit log rolled	38	48	53.269
11:22.5	Video upload started when camera was docked			adf09fa4b12745349bae04fa52d1d50a
11:30.4	Audit log successfully uploaded			
11:30.6	Audit log successfully uploaded and deleted from device	38	48	53.269
11:30.7	Audit log successfully uploaded			
11:30.9	Audit log successfully uploaded and deleted from device	38	48	53.269
11:52.0	Audit log successfully uploaded			
11:52.2	Audit log successfully uploaded and deleted from device	38	48	53.269

11:59.3	Audit log successfully uploaded			
11:59.5	Audit log successfully uploaded and deleted from device	38	48	53.269
12:09.2	Video successfully uploaded from device when dockec			adf09fa4b12745349bae04fa52d1d50a
12:09.4	Video deleted from device when docked	38	47	53.325 adf09fa4b12745349bae04fa52d1d50a
12:09.4	Audit log created	38	47 1.15.14	53.325
12:09.4	Audit log rolled	38	47	53.325
12:09.7	Video upload started when camera was docked			032322b11151459a97310bf113b451c5
12:25.6	Audit log successfully uploaded			
12:25.8	Audit log successfully uploaded and deleted from device	39	47	53.325
12:27.7	Video successfully uploaded from device when dockec			032322b11151459a97310bf113b451c5
12:27.9	Video deleted from device when docked	39	46	53.346 032322b11151459a97310bf113b451c5
12:28.0	Audit log created	39	46 1.15.14	53.346
12:28.0	Audit log rolled	39	46	53.346
12:28.2	Video upload started when camera was docked			e11d265f66734b159b605c38cbd0ea1e
12:30.9	Audit log successfully uploaded			
12:31.1	Audit log successfully uploaded and deleted from device	39	46	53.346
12:54.2	Audit log successfully uploaded			
12:54.4	Audit log successfully uploaded and deleted from device	39	46	53.346
12:56.4	Video successfully uploaded from device when dockec			e11d265f66734b159b605c38cbd0ea1e
12:56.6	Video deleted from device when docked	39	45	53.384 e11d265f66734b159b605c38cbd0ea1e
12:56.7	Audit log created	39	45 1.15.14	53.384
12:56.7	Audit log rolled	39	45	53.384
12:56.8	Video upload started when camera was docked			a3cb0dd78c4d4b5481aac9f696200bf6
12:57.5	Audit log successfully uploaded			
12:57.7	Audit log successfully uploaded and deleted from device	39	45	53.384
13:11.8	Audit log successfully uploaded			
13:12.0	Audit log successfully uploaded and deleted from device	39	45	53.384
13:27.2	Audit log successfully uploaded			
13:27.4	Audit log successfully uploaded and deleted from device	39	45	53.384
13:39.6	Audit log successfully uploaded			
13:39.8	Audit log successfully uploaded and deleted from device	39	45	53.384
13:56.9	Audit log successfully uploaded			
13:57.3	Audit log successfully uploaded and deleted from device	39	45	53.384
13:59.5	Video successfully uploaded from device when dockec			a3cb0dd78c4d4b5481aac9f696200bf6
13:59.7	Video deleted from device when docked	39	44	53.482 a3cb0dd78c4d4b5481aac9f696200bf6
13:59.8	Audit log rolled	39	44	53.482
13:59.8	Audit log created	39	44 1.15.14	53.482
14:00.0	Video upload started when camera was docked			346d0a282dc0467d8328bbb63cb85874
14:06.4	Audit log successfully uploaded			
14:06.6	Audit log successfully uploaded and deleted from device	39	44	53.482
14:17.7	Audit log successfully uploaded			
14:17.9	Audit log successfully uploaded and deleted from device	39	44	53.482
14:34.0	Audit log successfully uploaded			
14:34.2	Audit log successfully uploaded and deleted from device	39	44	53.482
14:42.4	Audit log successfully uploaded			
14:42.6	Audit log successfully uploaded and deleted from device	39	44	53.482
14:47.1	Video successfully uploaded from device when dockec			346d0a282dc0467d8328bbb63cb85874

14:47.3 Video deleted from device when docked	39	43	53.558	346d0a282dc0467d8328bbb63cb85874
14:47.4 Audit log created	39	43 1.15.14	53.558	
14:47.4 Audit log rolled	39	43	53.558	
14:47.6 Video upload started when camera was docked				d26a3f94d1724de5983c49101e5cb665
14:59.0 Video successfully uploaded from device when docked				d26a3f94d1724de5983c49101e5cb665
14:59.2 Video deleted from device when docked	40	42	53.574	d26a3f94d1724de5983c49101e5cb665
14:59.3 Audit log created	40	42 1.15.14	53.574	
14:59.3 Audit log rolled	40	42	53.574	
14:59.5 Video upload started when camera was docked				99212c772a18466c8e75d2f5a2057af9
15:08.7 Audit log successfully uploaded				
15:08.8 Audit log successfully uploaded and deleted from device	40	42	53.574	
15:25.0 Audit log successfully uploaded				
15:25.2 Audit log successfully uploaded and deleted from device	40	42	53.574	
15:31.3 Audit log successfully uploaded				
15:31.4 Audit log successfully uploaded and deleted from device	40	42	53.574	
15:34.6 Audit log successfully uploaded				
15:34.8 Audit log successfully uploaded and deleted from device	40	42	53.574	
16:01.9 Video successfully uploaded from device when docked				99212c772a18466c8e75d2f5a2057af9
16:02.2 Video deleted from device when docked	40	41	53.659	99212c772a18466c8e75d2f5a2057af9
16:02.2 Audit log rolled	40	41	53.66	
16:02.2 Audit log created	40	41 1.15.14	53.66	
16:02.5 Video upload started when camera was docked				bcba6b6ed0fa4ff48f5d8b270678b817
16:02.9 Audit log successfully uploaded				
16:03.1 Audit log successfully uploaded and deleted from device	40	41	53.659	
16:13.2 Audit log successfully uploaded				
16:13.4 Audit log successfully uploaded and deleted from device	40	41	53.659	
16:15.6 Audit log successfully uploaded				
16:15.8 Audit log successfully uploaded and deleted from device	40	41	53.659	
16:22.0 Audit log successfully uploaded				
16:22.2 Audit log successfully uploaded and deleted from device	40	41	53.659	
16:36.3 Audit log successfully uploaded				
16:36.5 Audit log successfully uploaded and deleted from device	41	41	53.659	
16:53.7 Video successfully uploaded from device when docked				bcba6b6ed0fa4ff48f5d8b270678b817
16:53.8 Video deleted from device when docked	41	40	53.727	bcba6b6ed0fa4ff48f5d8b270678b817
16:53.9 Audit log rolled	41	40	53.727	
16:53.9 Audit log created	41	40 1.15.14	53.727	
16:54.2 Video upload started when camera was docked				342f44ceeabc409f9c01d2a62a4b7b97
17:05.4 Audit log successfully uploaded				
17:05.5 Audit log successfully uploaded and deleted from device	41	40	53.727	
17:08.6 Audit log successfully uploaded				
17:08.8 Audit log successfully uploaded and deleted from device	41	40	53.727	
17:14.0 Audit log successfully uploaded				
17:14.1 Audit log successfully uploaded and deleted from device	41	40	53.727	
17:18.3 Audit log successfully uploaded				
17:18.5 Audit log successfully uploaded and deleted from device	41	40	53.727	
17:23.7 Video successfully uploaded from device when docked				342f44ceeabc409f9c01d2a62a4b7b97
17:23.9 Video deleted from device when docked	41	39	53.766	342f44ceeabc409f9c01d2a62a4b7b97

17:24.0	Audit log rolled	41	39	53.766	
17:24.0	Audit log created	41	39 1.15.14	53.766	
17:24.1	Video upload started when camera was docked				a8f295a0136442728652d4b9b10a1395
17:33.6	Audit log successfully uploaded				
17:33.8	Audit log successfully uploaded and deleted from device	41	39	53.766	
17:48.7	Video successfully uploaded from device when docked				a8f295a0136442728652d4b9b10a1395
17:48.9	Video deleted from device when docked	41	38	53.795	a8f295a0136442728652d4b9b10a1395
17:48.9	Audit log rolled	41	38	53.795	
17:48.9	Audit log created	41	38 1.15.14	53.795	
17:49.1	Video upload started when camera was docked				108c929fa6724916b6144856ff15ef5a
18:00.0	Audit log successfully uploaded				
18:00.1	Audit log successfully uploaded and deleted from device	41	38	53.795	
18:16.3	Video successfully uploaded from device when docked				108c929fa6724916b6144856ff15ef5a
18:16.4	Video deleted from device when docked	41	37	53.828	108c929fa6724916b6144856ff15ef5a
18:16.5	Audit log created	41	37 1.15.14	53.828	
18:16.5	Audit log rolled	41	37	53.828	
18:16.7	Video upload started when camera was docked				8ec27cb5d8954c28a3a3f10600499ffc
18:18.3	Audit log successfully uploaded				
18:18.5	Audit log successfully uploaded and deleted from device	41	37	53.828	
18:34.6	Audit log successfully uploaded				
18:34.8	Audit log successfully uploaded and deleted from device	41	37	53.828	
18:56.0	Audit log successfully uploaded				
18:56.2	Audit log successfully uploaded and deleted from device	41	37	53.828	
19:07.3	Audit log successfully uploaded				
19:07.5	Audit log successfully uploaded and deleted from device	42	37	53.828	
19:20.1	Video successfully uploaded from device when docked				8ec27cb5d8954c28a3a3f10600499ffc
19:20.3	Video deleted from device when docked	42	36	53.911	8ec27cb5d8954c28a3a3f10600499ffc
19:20.3	Audit log rolled	42	36	53.911	
19:20.3	Audit log created	42	36 1.15.14	53.911	
19:20.6	Video upload started when camera was docked				62df219cedbd483c9429aa6563bc3316
19:20.6	Audit log successfully uploaded				
19:20.8	Audit log successfully uploaded and deleted from device	42	36	53.911	
19:48.0	Audit log successfully uploaded				
19:48.1	Audit log successfully uploaded and deleted from device	42	36	53.911	
20:07.9	Video successfully uploaded from device when docked				62df219cedbd483c9429aa6563bc3316
20:08.1	Video deleted from device when docked	42	35	53.981	62df219cedbd483c9429aa6563bc3316
20:08.2	Audit log created	42	35 1.15.14	53.981	
20:08.2	Audit log rolled	42	35	53.981	
20:08.5	Video upload started when camera was docked				bce15b59d3d74765858e2ccc0a80588e
20:15.3	Audit log successfully uploaded				
20:15.4	Audit log successfully uploaded and deleted from device	42	35	53.981	
20:26.6	Audit log successfully uploaded				
20:26.6	Video successfully uploaded from device when docked				bce15b59d3d74765858e2ccc0a80588e
20:26.8	Audit log successfully uploaded and deleted from device	42	35	53.981	
20:26.8	Video deleted from device when docked	42	34	54.031	bce15b59d3d74765858e2ccc0a80588e
20:26.9	Audit log created	42	34 1.15.14	54.031	
20:26.9	Audit log rolled	42	34	54.031	

20:27.1	Video upload started when camera was docked			5f51b63097ab49d281311c190211b862
20:39.1	Video successfully uploaded from device when docked			5f51b63097ab49d281311c190211b862
20:39.3	Video deleted from device when docked	42	33	54.072 5f51b63097ab49d281311c190211b862
20:39.3	Audit log created	42	33 1.15.14	54.072
20:39.3	Audit log rolled	42	33	54.072
20:39.5	Video upload started when camera was docked			ddd05f7049d849a1b4ae188febced5ec
20:40.9	Audit log successfully uploaded			
20:41.1	Audit log successfully uploaded and deleted from device	42	33	54.072
20:43.2	Video successfully uploaded from device when docked			ddd05f7049d849a1b4ae188febced5ec
20:43.5	Video deleted from device when docked	42	32	54.084 ddd05f7049d849a1b4ae188febced5ec
20:43.5	Audit log created	42	32 1.15.14	54.084
20:43.5	Audit log rolled	42	32	54.084
20:43.7	Video upload started when camera was docked			1a2aa47ecdb340d2956d5185474b972d
20:48.1	Video successfully uploaded from device when docked			1a2aa47ecdb340d2956d5185474b972d
20:48.3	Video deleted from device when docked	42	31	54.094 1a2aa47ecdb340d2956d5185474b972d
20:48.4	Audit log created	42	31 1.15.14	54.094
20:48.4	Audit log rolled	42	31	54.094
20:48.5	Video upload started when camera was docked			591abd9135404bf9a9802083a10efabd
20:52.5	Video successfully uploaded from device when docked			591abd9135404bf9a9802083a10efabd
20:52.7	Video deleted from device when docked	42	30	54.105 591abd9135404bf9a9802083a10efabd
20:52.8	Audit log created	42	30 1.15.14	54.105
20:52.8	Audit log rolled	42	30	54.105
20:53.0	Video upload started when camera was docked			171547cef65a45249a86fc7e2e12d2bf
20:58.4	Video successfully uploaded from device when docked			171547cef65a45249a86fc7e2e12d2bf
20:58.5	Video deleted from device when docked	42	29	54.123 171547cef65a45249a86fc7e2e12d2bf
20:58.6	Audit log created	42	29 1.15.14	54.123
20:58.6	Audit log rolled	42	29	54.123
20:58.8	Video upload started when camera was docked			a64bec06d6f348cebb7698f3752cc144
21:03.2	Audit log successfully uploaded			
21:03.4	Audit log successfully uploaded and deleted from device	42	29	54.123
21:08.5	Audit log successfully uploaded			
21:08.7	Audit log successfully uploaded and deleted from device	42	29	54.123
21:11.0	Video successfully uploaded from device when docked			a64bec06d6f348cebb7698f3752cc144
21:11.2	Video deleted from device when docked	42	28	54.162 a64bec06d6f348cebb7698f3752cc144
21:11.2	Audit log rolled	42	28	54.162
21:11.2	Audit log created	42	28 1.15.14	54.162
21:11.4	Video upload started when camera was docked			d8b1e8a15ad04649a14f915b01b6c5aa
21:23.7	Video successfully uploaded from device when docked			d8b1e8a15ad04649a14f915b01b6c5aa
21:23.9	Video deleted from device when docked	42	27	54.2 d8b1e8a15ad04649a14f915b01b6c5aa
21:23.9	Audit log created	42	27 1.15.14	54.2
21:23.9	Audit log rolled	42	27	54.2
21:24.1	Video upload started when camera was docked			3554ee6cb08044ab9dc5754cda9a4e6e
21:29.1	Video successfully uploaded from device when docked			3554ee6cb08044ab9dc5754cda9a4e6e
21:29.3	Video deleted from device when docked	43	26	54.215 3554ee6cb08044ab9dc5754cda9a4e6e
21:29.4	Audit log rolled	43	26	54.215
21:29.4	Audit log created	43	26 1.15.14	54.215
21:29.7	Video upload started when camera was docked			bf485dedaf7c4833b4d9c936f3e69df1

21:35.0	Video successfully uploaded from device when dockec				bf485dedaf7c4833b4d9c936f3e69df1
21:35.2	Video deleted from device when docked	43	25	54.232	bf485dedaf7c4833b4d9c936f3e69df1
21:35.3	Audit log rolled	43	25	54.232	
21:35.3	Audit log created	43	25 1.15.14	54.232	
21:35.5	Video upload started when camera was docked				2bc90ae32e3b425b9c8bda468a08c5cf
21:35.9	Audit log successfully uploaded				
21:36.1	Audit log successfully uploaded and deleted from device	43	25	54.232	
21:44.2	Audit log successfully uploaded				
21:44.4	Audit log successfully uploaded and deleted from device	43	25	54.232	
21:46.8	Video successfully uploaded from device when dockec				2bc90ae32e3b425b9c8bda468a08c5cf
21:47.0	Video deleted from device when docked	43	24	54.27	2bc90ae32e3b425b9c8bda468a08c5cf
21:47.1	Audit log rolled	43	24	54.27	
21:47.1	Audit log created	43	24 1.15.14	54.27	
21:47.3	Video upload started when camera was docked				2c25f6f8dc764d79b56f242542eaf095
21:50.5	Audit log successfully uploaded				
21:50.7	Audit log successfully uploaded and deleted from device	43	24	54.27	
21:50.8	Audit log successfully uploaded				
21:51.0	Audit log successfully uploaded and deleted from device	43	24	54.27	
21:53.5	Video successfully uploaded from device when dockec				2c25f6f8dc764d79b56f242542eaf095
21:53.7	Video deleted from device when docked	43	23	54.292	2c25f6f8dc764d79b56f242542eaf095
21:53.8	Audit log created	43	23 1.15.14	54.292	
21:53.8	Audit log rolled	43	23	54.292	
21:53.9	Video upload started when camera was docked				0c8ed000d768494c8ffad12a563a0969
21:54.1	Audit log successfully uploaded				
21:54.2	Audit log successfully uploaded and deleted from device	43	23	54.292	
21:58.8	Video successfully uploaded from device when dockec				0c8ed000d768494c8ffad12a563a0969
21:59.0	Video deleted from device when docked	43	22	54.306	0c8ed000d768494c8ffad12a563a0969
21:59.0	Audit log rolled	43	22	54.306	
21:59.0	Audit log created	43	22 1.15.14	54.306	
21:59.2	Video upload started when camera was docked				e58dabb721ca4bafae6d7f14b0f7590f
22:10.3	Video successfully uploaded from device when dockec				e58dabb721ca4bafae6d7f14b0f7590f
22:10.5	Video deleted from device when docked	43	21	54.345	e58dabb721ca4bafae6d7f14b0f7590f
22:10.5	Audit log created	43	21 1.15.14	54.345	
22:10.5	Audit log rolled	43	21	54.345	
22:10.7	Video upload started when camera was docked				f2702d0fa9bf48edac368473a50bfe12
22:12.3	Audit log successfully uploaded				
22:12.5	Audit log successfully uploaded and deleted from device	43	21	54.345	
22:13.7	Audit log successfully uploaded				
22:13.9	Audit log successfully uploaded and deleted from device	43	21	54.345	
22:15.9	Video successfully uploaded from device when dockec				f2702d0fa9bf48edac368473a50bfe12
22:16.0	Video deleted from device when docked	43	20	54.36	f2702d0fa9bf48edac368473a50bfe12
22:16.1	Audit log created	43	20 1.15.14	54.36	
22:16.1	Audit log rolled	43	20	54.36	
22:16.3	Video upload started when camera was docked				0ecf6cbb98b84ba5bdd7796a586e36c6
22:21.7	Video successfully uploaded from device when dockec				0ecf6cbb98b84ba5bdd7796a586e36c6
22:21.9	Video deleted from device when docked	43	19	54.377	0ecf6cbb98b84ba5bdd7796a586e36c6
22:21.9	Audit log created	43	19 1.15.14	54.377	

22:22.0	Audit log rolled	43	19	54.377	
22:22.1	Video upload started when camera was docked				25e5e97fec8d4f66b7e18d30465aca03
22:40.0	Video successfully uploaded from device when docked				25e5e97fec8d4f66b7e18d30465aca03
22:40.3	Video deleted from device when docked	43	18	54.438	25e5e97fec8d4f66b7e18d30465aca03
22:40.3	Audit log created	43	18	1.15.14	54.438
22:40.3	Audit log rolled	43	18		54.438
22:40.5	Video upload started when camera was docked				d1f302806291428d9fabe350e9097fe5
22:43.1	Audit log successfully uploaded				
22:43.2	Audit log successfully uploaded and deleted from device	43	18		54.438
23:02.1	Video successfully uploaded from device when docked				d1f302806291428d9fabe350e9097fe5
23:02.3	Video deleted from device when docked	43	17	54.515	d1f302806291428d9fabe350e9097fe5
23:02.4	Audit log rolled	43	17		54.515
23:02.4	Audit log created	43	17	1.15.14	54.515
23:02.6	Video upload started when camera was docked				0893bb2797064eb2ac04075b4e89decb
23:04.4	Audit log successfully uploaded				
23:04.6	Audit log successfully uploaded and deleted from device	43	17		54.515
23:07.0	Video successfully uploaded from device when docked				0893bb2797064eb2ac04075b4e89decb
23:07.1	Video deleted from device when docked	44	16	54.53	0893bb2797064eb2ac04075b4e89decb
23:07.2	Audit log created	44	16	1.15.14	54.53
23:07.2	Audit log rolled	44	16		54.53
23:07.4	Video upload started when camera was docked				3c52f567c9644e028439d4b6b942d0b4
23:12.7	Audit log successfully uploaded				
23:12.8	Audit log successfully uploaded and deleted from device	44	16		54.53
23:13.7	Video successfully uploaded from device when docked				3c52f567c9644e028439d4b6b942d0b4
23:13.9	Video deleted from device when docked	44	15	54.55	3c52f567c9644e028439d4b6b942d0b4
23:13.9	Audit log rolled	44	15		54.55
23:13.9	Audit log created	44	15	1.15.14	54.55
23:14.1	Video upload started when camera was docked				e62c165aae824949b475d7e09e10a407
23:19.0	Audit log successfully uploaded				
23:19.1	Audit log successfully uploaded and deleted from device	44	15		54.55
23:19.5	Video successfully uploaded from device when docked				e62c165aae824949b475d7e09e10a407
23:19.7	Video deleted from device when docked	44	14	54.568	e62c165aae824949b475d7e09e10a407
23:19.8	Audit log created	44	14	1.15.14	54.568
23:19.8	Audit log rolled	44	14		54.568
23:19.9	Video upload started when camera was docked				e2fbc22b2ac3409988f72967d78d6cd9
23:26.9	Video successfully uploaded from device when docked				e2fbc22b2ac3409988f72967d78d6cd9
23:27.1	Video deleted from device when docked	44	13	54.586	e2fbc22b2ac3409988f72967d78d6cd9
23:27.1	Audit log rolled	44	13		54.586
23:27.1	Audit log created	44	13	1.15.14	54.586
23:27.3	Video upload started when camera was docked				7f94747f2b794986968699046db1081f
23:31.9	Video successfully uploaded from device when docked				7f94747f2b794986968699046db1081f
23:32.1	Video deleted from device when docked	44	12	54.601	7f94747f2b794986968699046db1081f
23:32.2	Audit log created	44	12	1.15.14	54.601
23:32.2	Audit log rolled	44	12		54.601
23:32.4	Video upload started when camera was docked				bb7798af92244b84832e771b5adc6f9a
23:33.2	Audit log successfully uploaded				
23:33.4	Audit log successfully uploaded and deleted from device	44	12		54.601

23:35.5	Audit log successfully uploaded				
23:35.7	Audit log successfully uploaded and deleted from device	44	12	54.601	
23:47.6	Video successfully uploaded from device when docked				bb7798af92244b84832e771b5adc6f9a
23:47.8	Audit log successfully uploaded				
23:47.9	Video deleted from device when docked	44	11	54.655	bb7798af92244b84832e771b5adc6f9a
23:47.9	Audit log created	44	11	1.15.14	54.655
23:47.9	Audit log rolled	44	11		54.655
23:48.0	Audit log successfully uploaded and deleted from device	44	11		54.655
23:48.2	Video upload started when camera was docked				792e73b22d094628800f61c5e828e7c9
23:58.2	Audit log successfully uploaded				
23:58.3	Audit log successfully uploaded and deleted from device	44	11	54.655	
24:09.6	Video successfully uploaded from device when docked				792e73b22d094628800f61c5e828e7c9
24:09.8	Video deleted from device when docked	44	10	54.729	792e73b22d094628800f61c5e828e7c9
24:09.9	Audit log rolled	44	10		54.729
24:09.9	Audit log created	44	10	1.15.14	54.729
24:10.1	Video upload started when camera was docked				4051506d35d3498a8246747b96ca523f
24:15.1	Video successfully uploaded from device when docked				4051506d35d3498a8246747b96ca523f
24:15.3	Video deleted from device when docked	44	9	54.745	4051506d35d3498a8246747b96ca523f
24:15.3	Audit log created	44	9	1.15.14	54.745
24:15.3	Audit log rolled	44	9		54.745
24:15.5	Video upload started when camera was docked				033a5faa49e14209886be53832f5f882
24:20.0	Video successfully uploaded from device when docked				033a5faa49e14209886be53832f5f882
24:20.2	Video deleted from device when docked	44	8	54.76	033a5faa49e14209886be53832f5f882
24:20.2	Audit log rolled	44	8		54.76
24:20.2	Audit log created	44	8	1.15.14	54.76
24:20.5	Video upload started when camera was docked				c95dad872ad943baba126a73f4e7b29e
24:24.8	Video successfully uploaded from device when docked				c95dad872ad943baba126a73f4e7b29e
24:25.0	Video deleted from device when docked	44	7	54.774	c95dad872ad943baba126a73f4e7b29e
24:25.1	Audit log rolled	44	7		54.774
24:25.1	Audit log created	44	7	1.15.14	54.774
24:25.3	Video upload started when camera was docked				8616ce3215e642e0afc13b4fad28d88d
24:26.4	Audit log successfully uploaded				
24:26.6	Audit log successfully uploaded and deleted from device	44	7	54.774	
24:28.8	Video successfully uploaded from device when docked				8616ce3215e642e0afc13b4fad28d88d
24:29.0	Video deleted from device when docked	44	6	54.785	8616ce3215e642e0afc13b4fad28d88d
24:29.1	Audit log created	44	6	1.15.14	54.786
24:29.1	Audit log rolled	44	6		54.786
24:29.3	Video upload started when camera was docked				d33f17c07253453eb2570242559b48f7
24:35.2	Video successfully uploaded from device when docked				d33f17c07253453eb2570242559b48f7
24:35.4	Video deleted from device when docked	44	5	54.805	d33f17c07253453eb2570242559b48f7
24:35.5	Audit log created	44	5	1.15.14	54.806
24:35.5	Audit log rolled	44	5		54.806
24:35.7	Video upload started when camera was docked				8bfc562b5ae4b2bb620c0a72652d876
24:41.2	Video successfully uploaded from device when docked				8bfc562b5ae4b2bb620c0a72652d876
24:41.4	Video deleted from device when docked	44	4	54.823	8bfc562b5ae4b2bb620c0a72652d876
24:41.4	Audit log created	44	4	1.15.14	54.823
24:41.4	Audit log rolled	44	4		54.823

24:41.6 Video upload started when camera was docked				127db577ed804b5f998a5039c3349d5e
24:49.7 Audit log successfully uploaded				
24:49.8 Audit log successfully uploaded and deleted from device	44	4	54.823	
24:56.9 Video successfully uploaded from device when docked				127db577ed804b5f998a5039c3349d5e
24:57.1 Video deleted from device when docked	44	3	54.876	127db577ed804b5f998a5039c3349d5e
24:57.2 Audit log rolled	44	3	54.876	
24:57.2 Audit log created	44	3	1.15.14	54.876
24:57.5 Video upload started when camera was docked				709907a59de149b28cf3b730e2e0160c
25:15.9 Audit log successfully uploaded				
25:16.1 Audit log successfully uploaded and deleted from device	44	3	54.876	
25:18.3 Video successfully uploaded from device when docked				709907a59de149b28cf3b730e2e0160c
25:18.5 Video deleted from device when docked	44	2	54.952	709907a59de149b28cf3b730e2e0160c
25:18.5 Audit log rolled	44	2	54.952	
25:18.5 Audit log created	44	2	1.15.14	54.952
25:18.7 Video upload started when camera was docked				d132640e42784690bb4336607752ef08
25:35.3 Audit log successfully uploaded				
25:35.5 Audit log successfully uploaded and deleted from device	45	2	54.952	
25:51.6 Audit log successfully uploaded				
25:51.8 Audit log successfully uploaded and deleted from device	45	2	54.952	
25:58.9 Video successfully uploaded from device when docked				d132640e42784690bb4336607752ef08
25:59.1 Video deleted from device when docked	45	1	55.103	d132640e42784690bb4336607752ef08
25:59.2 Audit log rolled	45	1	55.104	
25:59.2 Audit log created	45	1	1.15.14	55.104
25:59.4 Video upload started when camera was docked				03527056f44c4c82aba82cfb0bae68d5
26:06.0 Audit log successfully uploaded				
26:06.1 Audit log successfully uploaded and deleted from device	45	1	55.104	
26:16.3 Audit log successfully uploaded				
26:16.4 Audit log successfully uploaded and deleted from device	45	1	55.104	
26:17.9 Video successfully uploaded from device when docked				03527056f44c4c82aba82cfb0bae68d5
26:18.2 Video deleted from device when docked	45	0	55.176	03527056f44c4c82aba82cfb0bae68d5
26:18.2 Audit log created	45	0	1.15.14	55.176
26:18.2 Audit log rolled	45	0		55.176
26:18.3 Audit log rolled	45	0		55.176
26:18.3 Audit log created	45	0	1.15.14	55.176
26:21.1 Select button pressed				
26:21.5 Select button released				
26:21.6 Device disconnected from charger	45	0	55.176	
26:22.0 Camera disconnected from Axon Dock X62001W9H	45	0	55.178	
26:28.3 Programmable button pressed				
26:28.3 Programmable button released				
31:51.0 Power button pressed				
31:54.0 Device powered off using button	44	0	55.18	
31:54.8 Power button released				
44:54.1 Device powered on due to charger connection	45	0	55.18	
44:54.3 Device connected to charger				
44:54.3 Camera connected to Axon Dock X630020W7	45	0	55.18	
44:54.4 Audit log created			1.15.14	

44:54.4	Audit log rolled			
44:55.0	Camera connected to Axon Dock X630020W7	45	0	55.18
44:56.9	Audit log created	45	0 1.15.14	55.18
44:56.9	Audit log rolled	45	0	55.18
44:56.0	Audit log created	73	0 1.15.14	55.179
44:56.0	Audit log created	97	0 1.15.14	55.179
44:56.0	Audit log created	100	0 1.15.14	55.178
44:56.0	Audit log created	100	0 1.15.14	55.178
44:56.1	Audit log created	100	0 1.15.14	55.185
44:56.1	Audit log created	100	0 1.15.14	55.189
44:56.1	Audit log created	100	0 1.15.14	55.193
44:56.1	Audit log created	100	0 1.15.14	55.193
44:56.1	Audit log created	100	0 1.15.14	55.192
44:56.1	Audit log created	100	0 1.15.14	55.192
44:56.1	Audit log created	100	0 1.15.14	55.191
44:56.1	Audit log created	100	0 1.15.14	55.191
44:56.1	Audit log created	100	0 1.15.14	55.191
44:56.2	Audit log created	100	0 1.15.14	55.19
44:56.2	Audit log created	100	0 1.15.14	55.19
44:56.2	Audit log created	100	0 1.15.14	55.189
44:56.2	Audit log created	100	0 1.15.14	55.189
44:56.2	Audit log created	100	0 1.15.14	55.188
44:56.2	Audit log created	100	0 1.15.14	55.188
44:56.2	Audit log created	100	0 1.15.14	55.187
44:56.2	Audit log created	100	0 1.15.14	55.187
44:56.2	Audit log created	100	0 1.15.14	55.187
44:56.3	Audit log created	100	0 1.15.14	55.186
44:56.3	Audit log created	100	0 1.15.14	55.186
44:56.3	Audit log created	100	0 1.15.14	55.185
44:56.3	Audit log created	100	0 1.15.14	55.185
44:56.3	Audit log created	100	0 1.15.14	55.184
44:56.3	Audit log created	100	0 1.15.14	55.184
44:56.3	Audit log created	100	0 1.15.14	55.183
44:56.3	Audit log created	100	0 1.15.14	55.183
44:56.4	Audit log created	100	0 1.15.14	55.182
44:56.4	Audit log created	100	0 1.15.14	55.182
44:56.4	Audit log created	100	0 1.15.14	55.181
44:56.4	Audit log created	100	0 1.15.14	55.181
44:56.4	Audit log created	100	0 1.15.14	55.18
42:30.0	Camera disconnected from Axon Dock X630020W7	100	0	55.18
42:30.1	Device disconnected from charger	100	0	55.18
42:30.2	Audio recording disabled due to video buffering default			
42:46.3	Power button pressed			
42:49.3	Device powered off using button	100	0	55.18
42:49.7	Power button released			
29:31.9	Audit log created		1.15.14	

29:32.1 Device powered on due to charger connection	97	0	55.179
29:32.3 Device connected to charger			
29:32.3 Camera connected to Axon Dock X630020W7	97	0	55.179
29:32.3 Audit log rolled			
29:32.3 Audit log created		1.15.14	
29:33.0 Camera connected to Axon Dock X630020W7	97	0	55.179
29:35.0 Audit log rolled	97	0	55.179
29:35.0 Audit log created	97	0 1.15.14	55.179
29:34.0 Audit log created	97	0 1.15.14	55.178
29:34.0 Audit log created	97	0 1.15.14	55.178
29:34.0 Audit log created	97	0 1.15.14	55.177
29:34.1 Audit log created	97	0 1.15.14	55.177
29:34.1 Audit log created	97	0 1.15.14	55.177
29:34.1 Audit log created	97	0 1.15.14	55.176
29:34.1 Audit log created	97	0 1.15.14	55.176
29:34.1 Audit log created	97	0 1.15.14	55.175
29:34.1 Audit log created	97	0 1.15.14	55.175
29:34.1 Audit log created	97	0 1.15.14	55.174
29:34.2 Audit log created	97	0 1.15.14	55.174
29:34.2 Audit log created	97	0 1.15.14	55.173
29:34.2 Audit log created	97	0 1.15.14	55.173
29:34.2 Audit log created	97	0 1.15.14	55.172
29:34.2 Audit log created	97	0 1.15.14	55.172
42:29.0 Device disconnected from charger	97	0	55.172
42:29.5 Camera disconnected from Axon Dock X630020W7	97	0	55.172
42:29.7 Audio recording disabled due to video buffering default			
42:37.5 Volume down button pressed			
42:38.8 Volume down button released			
42:39.3 Volume changed to low from medium using button			
42:39.4 Volume up button pressed			
42:39.7 Volume up button released			
42:39.8 Volume changed to medium from low using button			
42:46.4 Power button pressed			
42:48.5 Power button released			
42:50.2 Volume up button pressed			
42:50.4 Volume up button released			
42:50.5 Volume changed to high from medium using button			
42:52.3 Volume down button pressed			
42:52.6 Volume down button released			
42:52.7 Volume changed to medium from high using button			
42:53.5 Power button pressed			
42:54.6 Power button released			
42:55.2 Power button pressed			
42:58.2 Device powered off using button	97	0	55.172
42:58.7 Power button released			
44:40.0 Audit log created		1.15.14	
44:40.1 Device powered on due to charger connection	96	0	55.171

44:40.3 Device connected to charger			
44:40.4 Camera connected to Axon Dock X630020W7	96	0	55.171
44:40.4 Audit log created		1.15.14	
44:40.4 Audit log rolled			
44:41.1 Camera connected to Axon Dock X630020W7	96	0	55.171
44:43.0 Audit log rolled	96	0	55.171
44:43.0 Audit log created	96	0 1.15.14	55.171
44:43.0 Audit log created	100	0 1.15.14	55.17
44:43.0 Audit log created	100	0 1.15.14	55.17
44:43.0 Audit log created	100	0 1.15.14	55.17
44:43.0 Audit log created	100	0 1.15.14	55.169
44:43.1 Audit log created	100	0 1.15.14	55.169
44:43.1 Audit log created	100	0 1.15.14	55.169
44:43.1 Audit log created	100	0 1.15.14	55.169
44:43.1 Audit log created	100	0 1.15.14	55.169
44:43.1 Audit log created	100	0 1.15.14	55.168
44:43.1 Audit log created	100	0 1.15.14	55.168
44:43.1 Audit log created	100	0 1.15.14	55.168
44:43.1 Audit log created	100	0 1.15.14	55.168
44:43.1 Audit log created	100	0 1.15.14	55.167
44:43.1 Audit log created	100	0 1.15.14	55.167
44:43.1 Audit log created	100	0 1.15.14	55.167
44:43.1 Audit log created	100	0 1.15.14	55.167
44:43.2 Audit log created	100	0 1.15.14	55.166
41:27.1 Camera disconnected from Axon Dock X630020W7	100	0	55.166
41:27.1 Device disconnected from charger	100	0	55.166
41:27.2 Audio recording disabled due to video buffering default			
41:44.0 Power button pressed			
41:47.0 Device powered off using button	100	0	55.166
41:47.5 Power button released			
42:25.9 Audit log created		1.15.14	
42:26.0 Device powered on using button	100	0	55.165
42:27.9 Audio recording disabled due to video buffering default			
42:31.7 Event button pressed			
42:31.7 Event button released			
42:31.8 Event button pressed			
42:31.8 Audio recording enabled due to video recording default			
42:31.9 Event button released			
42:32.0 Recording started due to button press	100	0	55.165 607dc4df8cfd45f8a06fefcdc29522c5
50:09.9 Event button pressed			
50:10.1 Event button released			
50:11.0 Event button pressed			
50:14.0 Recording stopped due to button press	97	1	54.919 607dc4df8cfd45f8a06fefcdc29522c5
50:14.6 Event button released			
50:14.8 Audio recording disabled due to video buffering default			
50:21.7 Event button pressed			
50:21.9 Event button released			
50:21.9 Event button pressed			

50:21.9	Audio recording enabled due to video recording default			
50:22.0	Event button released			
50:22.1	Recording started due to button press	97	2	54.918 6d8ec5dc45fd4ca5a02a33b0063c7e47
52:53.2	Event button pressed			
52:56.2	Recording stopped due to button press	97	2	54.833 6d8ec5dc45fd4ca5a02a33b0063c7e47
52:56.7	Event button released			
52:57.1	Audio recording disabled due to video buffering default			
58:40.5	Event button pressed			
58:40.6	Event button released			
58:40.7	Event button pressed			
58:40.7	Audio recording enabled due to video recording default			
58:40.7	Event button released			
58:40.9	Recording started due to button press	96	3	54.832 173f0d5a91d248158f1802681ab331b6
58:58.9	Event button pressed			
58:59.1	Event button released			
58:59.2	Event button pressed			
58:59.3	Event button released			
59:00.8	Event button pressed			
59:03.8	Recording stopped due to button press	96	3	54.779 173f0d5a91d248158f1802681ab331b6
59:04.5	Audio recording disabled due to video buffering default			
59:04.7	Event button released			
01:47.8	Event button pressed			
01:48.0	Event button released			
01:48.0	Event button pressed			
01:48.1	Audio recording enabled due to video recording default			
01:48.1	Event button released			
01:48.2	Recording started due to button press	96	3	54.759 515e50f3c86e40959d90077edc61baac
01:56.7	Event button pressed			
01:59.7	Recording stopped due to button press	96	4	54.733 515e50f3c86e40959d90077edc61baac
02:00.5	Event button released			
02:00.5	Audio recording disabled due to video buffering default			
06:41.5	Event button pressed			
06:41.6	Event button released			
06:41.6	Event button pressed			
06:41.7	Audio recording enabled due to video recording default			
06:41.8	Event button released			
06:41.8	Recording started due to button press	95	5	54.692 a2fafd46bf764e1db9043babe590b481
06:52.8	Event button pressed			
06:55.8	Recording stopped due to button press	95	5	54.66 a2fafd46bf764e1db9043babe590b481
06:56.3	Event button released			
06:56.5	Audio recording disabled due to video buffering default			
07:07.6	Event button pressed			
07:07.7	Event button released			
07:07.8	Event button pressed			
07:07.8	Audio recording enabled due to video recording default			
07:07.9	Event button released			
07:07.9	Recording started due to button press	95	6	54.639 17fb1b3532374bd3a0c33fbc7caf4f19

07:21.5	Event button pressed			
07:24.5	Recording stopped due to button press	95	6	54.61 17fb1b3532374bd3a0c33bc7caf4f19
07:24.9	Event button released			
07:25.2	Audio recording disabled due to video buffering default			
07:34.3	Event button pressed			
07:34.4	Event button released			
07:34.5	Event button pressed			
07:34.5	Audio recording enabled due to video recording default			
07:34.6	Event button released			
07:34.6	Recording started due to button press	95	7	54.609 c3e6765221ad436d925dff06e5c6cf91
08:06.4	Event button pressed			
08:09.4	Recording stopped due to button press	95	7	54.586 c3e6765221ad436d925dff06e5c6cf91
08:09.8	Event button released			
08:10.3	Audio recording disabled due to video buffering default			
08:16.5	Event button pressed			
08:16.7	Event button released			
08:16.7	Event button pressed			
08:16.7	Audio recording enabled due to video recording default			
08:16.8	Event button released			
08:16.8	Recording started due to button press	95	8	54.586 c9489162e3b2405981303c6ef2298bf7
08:27.1	Event button pressed			
08:30.1	Recording stopped due to button press	95	8	54.576 c9489162e3b2405981303c6ef2298bf7
08:31.1	Audio recording disabled due to video buffering default			
08:31.5	Event button released			
08:54.0	Event button pressed			
08:54.1	Event button released			
08:54.1	Event button pressed			
08:54.1	Audio recording enabled due to video recording default			
08:54.2	Event button released			
08:54.3	Recording started due to button press	95	9	54.575 b7e9cee514124d87a9db0d4d674d55ae
09:13.4	Event button pressed			
09:16.4	Recording stopped due to button press	94	9	54.552 b7e9cee514124d87a9db0d4d674d55ae
09:17.1	Audio recording disabled due to video buffering default			
09:17.3	Event button released			
09:24.1	Event button pressed			
09:24.2	Event button released			
09:24.3	Event button pressed			
09:24.3	Audio recording enabled due to video recording default			
09:24.4	Event button released			
09:24.5	Recording started due to button press	94	10	54.552 34eb81bd098145bca0a1fb7f754835a8
09:53.5	Event button pressed			
09:56.5	Recording stopped due to button press	94	10	54.531 34eb81bd098145bca0a1fb7f754835a8
09:57.0	Event button released			
09:57.4	Audio recording disabled due to video buffering default			
10:24.6	Event button pressed			
10:24.7	Event button released			
10:24.8	Event button pressed			

10:24.8 Audio recording enabled due to video recording default			
10:24.8 Event button released			
10:24.9 Recording started due to button press	94	11	54.531 6ee3c7c70f7147dc8a2a0faafc669cd3
10:44.1 Event button pressed			
10:47.1 Recording stopped due to button press	94	11	54.506 6ee3c7c70f7147dc8a2a0faafc669cd3
10:47.6 Event button released			
10:48.0 Audio recording disabled due to video buffering default			
10:52.9 Event button pressed			
10:53.0 Event button released			
10:53.1 Event button pressed			
10:53.1 Audio recording enabled due to video recording default			
10:53.2 Event button released			
10:53.2 Recording started due to button press	94	12	54.505 f8683976c5a1485f86d3e33c4665712c
11:01.0 Event button pressed			
11:04.0 Recording stopped due to button press	94	12	54.497 f8683976c5a1485f86d3e33c4665712c
11:04.4 Event button released			
11:04.7 Audio recording disabled due to video buffering default			
11:07.2 Event button pressed			
11:07.4 Event button released			
11:07.4 Event button pressed			
11:07.5 Audio recording enabled due to video recording default			
11:07.5 Event button released			
11:07.6 Recording started due to button press	94	13	54.496 e67a8b09307d45e495923e8aa7d5f57b
11:20.4 Event button pressed			
11:23.4 Recording stopped due to button press	94	13	54.487 e67a8b09307d45e495923e8aa7d5f57b
11:24.0 Event button released			
11:24.3 Audio recording disabled due to video buffering default			
14:50.5 Event button pressed			
14:50.6 Event button released			
14:50.7 Event button pressed			
14:50.7 Audio recording enabled due to video recording default			
14:50.8 Event button released			
14:50.9 Recording started due to button press	94	14	54.486 4d751c5396b14e72844d1a44c48cd381
15:04.7 Event button pressed			
15:07.7 Recording stopped due to button press	94	14	54.449 4d751c5396b14e72844d1a44c48cd381
15:08.3 Event button released			
15:08.5 Audio recording disabled due to video buffering default			
15:14.6 Event button pressed			
15:14.7 Event button released			
15:14.8 Event button pressed			
15:14.9 Audio recording enabled due to video recording default			
15:14.9 Event button released			
15:15.0 Recording started due to button press	94	15	54.435 5218723471f34abab307350ea1f5b3f6
15:32.1 Event button pressed			
15:32.3 Event button released			
15:32.5 Event button pressed			
15:38.3 Event button released			

15:38.6	Event button pressed			
15:41.6	Recording stopped due to button press	94	15	54.4 5218723471f34abab307350ea1f5b3f6
15:42.2	Event button released			
15:42.4	Audio recording disabled due to video buffering default			
15:45.0	Event button pressed			
15:45.1	Event button released			
15:45.2	Event button pressed			
15:45.2	Audio recording enabled due to video recording default			
15:45.3	Event button released			
15:45.4	Recording started due to button press	94	16	54.399 088b0ee003d74ce89275fd5b4352aaef
16:02.8	Event button pressed			
16:05.8	Recording stopped due to button press	93	16	54.388 088b0ee003d74ce89275fd5b4352aaef
16:06.7	Audio recording disabled due to video buffering default			
16:08.8	Event button released			
20:47.4	Event button pressed			
20:47.6	Event button released			
20:47.7	Event button pressed			
20:47.7	Audio recording enabled due to video recording default			
20:47.8	Event button released			
20:47.9	Recording started due to button press	93	17	54.387 b0551e1403e24a889a371bbd7b53a9b0
21:01.4	Event button pressed			
21:04.4	Recording stopped due to button press	93	17	54.35 b0551e1403e24a889a371bbd7b53a9b0
21:05.0	Event button released			
21:05.4	Audio recording disabled due to video buffering default			
21:44.7	Event button pressed			
21:44.9	Event button released			
21:45.0	Event button pressed			
21:45.0	Audio recording enabled due to video recording default			
21:45.1	Event button released			
21:45.1	Recording started due to button press	93	18	54.318 243f27744e6d4a2bbbae5883c939ba62
22:47.1	Event button pressed			
22:50.1	Recording stopped due to button press	92	18	54.264 243f27744e6d4a2bbbae5883c939ba62
22:50.7	Event button released			
22:50.9	Audio recording disabled due to video buffering default			
23:09.2	Event button pressed			
23:09.4	Event button released			
23:09.4	Event button pressed			
23:09.5	Audio recording enabled due to video recording default			
23:09.6	Event button released			
23:09.6	Recording started due to button press	92	19	54.263 0c6b6e9ad1ae40af9e03e187a9a04bbe
23:24.3	Event button pressed			
23:27.3	Recording stopped due to button press	92	19	54.245 0c6b6e9ad1ae40af9e03e187a9a04bbe
23:27.8	Event button released			
23:28.1	Audio recording disabled due to video buffering default			
23:37.9	Event button pressed			
23:38.1	Event button released			
23:38.2	Event button pressed			

23:38.2 Audio recording enabled due to video recording default			
23:38.3 Event button released			
23:38.3 Recording started due to button press	92	20	54.244 8709b834dcb14308a8c4ba9dd9fb37d8
23:53.7 Event button pressed			
23:56.7 Recording stopped due to button press	92	20	54.23 8709b834dcb14308a8c4ba9dd9fb37d8
23:57.4 Audio recording disabled due to video buffering default			
23:57.9 Event button released			
24:17.4 Event button pressed			
24:17.5 Event button released			
24:17.6 Event button pressed			
24:17.6 Audio recording enabled due to video recording default			
24:17.7 Event button released			
24:17.7 Recording started due to button press	92	21	54.229 35242359641e4ebc8e1a8982b1b4b409
24:29.1 Event button pressed			
24:32.1 Recording stopped due to button press	92	21	54.211 35242359641e4ebc8e1a8982b1b4b409
24:32.9 Event button released			
24:32.9 Audio recording disabled due to video buffering default			
25:04.1 Event button pressed			
25:04.4 Event button released			
25:04.4 Event button pressed			
25:04.5 Audio recording enabled due to video recording default			
25:04.5 Event button released			
25:04.6 Recording started due to button press	92	22	54.211 91ad756ced3048e98c642cca412233b0
25:27.0 Event button pressed			
25:30.0 Recording stopped due to button press	92	22	54.182 91ad756ced3048e98c642cca412233b0
25:30.6 Event button released			
25:30.9 Audio recording disabled due to video buffering default			
26:06.1 Event button pressed			
26:06.3 Event button released			
26:06.3 Event button pressed			
26:06.3 Audio recording enabled due to video recording default			
26:06.4 Event button released			
26:06.5 Recording started due to button press	92	23	54.181 d80e2a0df5284f8c88e901e54ef3c0de
26:13.8 Event button pressed			
26:16.8 Recording stopped due to button press	92	23	54.159 d80e2a0df5284f8c88e901e54ef3c0de
26:17.5 Audio recording disabled due to video buffering default			
26:17.9 Event button released			
27:15.4 Event button pressed			
27:15.5 Event button released			
27:15.6 Event button pressed			
27:15.6 Audio recording enabled due to video recording default			
27:15.6 Event button released			
27:15.8 Recording started due to button press	92	24	54.158 364dad5633224c5e98f0ddeb9f160865
27:57.8 Event button pressed			
28:00.8 Recording stopped due to button press	92	24	54.105 364dad5633224c5e98f0ddeb9f160865
28:01.7 Audio recording disabled due to video buffering default			
28:01.8 Event button released			

32:00.6 Event button pressed			
32:00.7 Event button released			
32:00.8 Event button pressed			
32:00.8 Audio recording enabled due to video recording default			
32:00.9 Event button released			
32:00.9 Recording started due to button press	91	24	54.104 ffb4bea87d2c4fe4ae826c4640527f67
32:24.5 Event button pressed			
32:27.5 Recording stopped due to button press	91	25	54.045 ffb4bea87d2c4fe4ae826c4640527f67
32:28.0 Event button released			
32:28.3 Audio recording disabled due to video buffering default			
32:31.0 Event button pressed			
32:31.1 Event button released			
32:31.1 Event button pressed			
32:31.1 Audio recording enabled due to video recording default			
32:31.2 Event button released			
32:31.3 Recording started due to button press	91	26	54.038 04227c9fc05e4e7e936f927b95be158d
32:40.4 Event button pressed			
32:41.9 Event button released			
32:44.8 Event button pressed			
32:47.8 Recording stopped due to button press	91	26	54.019 04227c9fc05e4e7e936f927b95be158d
32:48.2 Event button released			
32:48.6 Audio recording disabled due to video buffering default			
32:59.8 Event button pressed			
32:59.9 Event button released			
33:00.0 Event button pressed			
33:00.0 Audio recording enabled due to video recording default			
33:00.1 Event button released			
33:00.1 Recording started due to button press	91	27	54.019 e0828b47fd1c441db40510e7e31c5f89
33:15.9 Event button pressed			
33:18.9 Recording stopped due to button press	91	27	54.003 e0828b47fd1c441db40510e7e31c5f89
33:19.4 Event button released			
33:19.8 Audio recording disabled due to video buffering default			
36:20.6 Event button pressed			
36:20.7 Event button released			
36:20.7 Event button pressed			
36:20.8 Audio recording enabled due to video recording default			
36:20.8 Event button released			
36:21.0 Recording started due to button press	90	27	54.003 9d04cd011cca4bf2bd80652f6aa7e3e1
36:33.7 Event button pressed			
36:36.7 Recording stopped due to button press	90	28	53.968 9d04cd011cca4bf2bd80652f6aa7e3e1
36:37.1 Event button released			
36:37.4 Audio recording disabled due to video buffering default			
36:39.4 Event button pressed			
36:39.6 Event button released			
36:39.6 Event button pressed			
36:39.6 Audio recording enabled due to video recording default			
36:39.7 Event button released			

36:39.8 Recording started due to button press	90	29	53.961 93621ad560294a3ea85f29b83a4e790d
36:45.9 Event button pressed			
36:48.9 Recording stopped due to button press	90	29	53.936 93621ad560294a3ea85f29b83a4e790d
36:49.5 Event button released			
36:52.2 Event button pressed			
36:52.3 Event button released			
36:52.4 Event button pressed			
36:52.4 Event button released			
36:52.7 Audio recording disabled due to video buffering default			
36:54.7 Event button pressed			
36:54.8 Event button released			
36:54.8 Event button pressed			
36:54.9 Audio recording enabled due to video recording default			
36:54.9 Event button released			
36:55.0 Recording started due to button press	90	30	53.928 b591834db0024662b619ca6f558c174f
37:22.2 Event button pressed			
37:22.3 Event button released			
37:22.8 Event button pressed			
37:23.0 Event button released			
37:23.8 Event button pressed			
37:26.8 Recording stopped due to button press	90	30	53.91 b591834db0024662b619ca6f558c174f
37:27.5 Event button released			
37:27.5 Audio recording disabled due to video buffering default			
37:29.3 Event button pressed			
37:29.4 Event button released			
37:29.4 Event button pressed			
37:29.5 Audio recording enabled due to video recording default			
37:29.5 Event button released			
37:29.6 Recording started due to button press	90	31	53.91 c7408287eb894f2da2005d8c24270b9f
37:56.6 Event button pressed			
37:59.6 Recording stopped due to button press	90	31	53.893 c7408287eb894f2da2005d8c24270b9f
38:00.0 Event button released			
38:00.3 Audio recording disabled due to video buffering default			
38:05.0 Event button pressed			
38:05.1 Event button released			
38:05.2 Event button pressed			
38:05.2 Audio recording enabled due to video recording default			
38:05.3 Event button released			
38:05.3 Recording started due to button press	90	32	53.892 0143bbb0b5ed4d709194a3537bb5f4bb
40:30.1 Event button pressed			
40:33.1 Recording stopped due to button press	90	32	53.812 0143bbb0b5ed4d709194a3537bb5f4bb
40:33.6 Event button released			
40:34.0 Audio recording disabled due to video buffering default			
41:23.3 Event button pressed			
41:23.5 Event button released			
41:23.5 Event button pressed			
41:23.5 Audio recording enabled due to video recording default			

41:23.6	Event button released			
41:23.7	Recording started due to button press	89	33	53.811 899e36983bc14f93ab2d24c43b9a0bf3
41:37.2	Event button pressed			
41:40.2	Recording stopped due to button press	89	33	53.778 899e36983bc14f93ab2d24c43b9a0bf3
41:41.1	Audio recording disabled due to video buffering default			
41:41.2	Event button released			
42:26.0	Audit log created	89	33 1.15.14	53.778
42:30.5	Event button pressed			
42:30.7	Event button released			
42:30.7	Event button pressed			
42:30.8	Audio recording enabled due to video recording default			
42:30.8	Event button released			
42:30.9	Recording started due to button press	89	34	53.777 c9d13a3740184469a69c2b1968d6ad8a
42:57.5	Event button pressed			
42:57.6	Event button released			
42:57.8	Event button pressed			
43:05.7	Event button released			
43:06.3	Event button pressed			
43:08.9	Event button released			
43:09.3	Event button pressed			
43:12.2	Event button released			
43:12.8	Event button pressed			
43:15.4	Event button released			
43:17.2	Event button pressed			
43:20.2	Recording stopped due to button press	89	34	53.727 c9d13a3740184469a69c2b1968d6ad8a
43:20.8	Event button released			
43:21.0	Audio recording disabled due to video buffering default			
43:37.5	Event button pressed			
43:37.6	Event button released			
43:37.7	Event button pressed			
43:37.7	Audio recording enabled due to video recording default			
43:37.7	Event button released			
43:37.8	Recording started due to button press	89	35	53.726 2dca2add8bfe4841bbd8365475bb4f16
43:50.9	Event button pressed			
43:53.9	Recording stopped due to button press	89	35	53.709 2dca2add8bfe4841bbd8365475bb4f16
43:54.6	Event button released			
43:54.9	Audio recording disabled due to video buffering default			
44:08.2	Event button pressed			
44:08.3	Event button released			
44:08.4	Event button pressed			
44:08.4	Audio recording enabled due to video recording default			
44:08.5	Event button released			
44:08.5	Recording started due to button press	89	36	53.709 a8b31b7b679045159b19ecd6dbf2453b
44:35.5	Event button pressed			
44:38.6	Recording stopped due to button press	89	36	53.686 a8b31b7b679045159b19ecd6dbf2453b
44:39.3	Event button released			
44:39.3	Audio recording disabled due to video buffering default			

44:55.5 Event button pressed			
44:59.8 Event button released			
45:00.4 Event button pressed			
45:00.5 Event button released			
45:00.5 Event button pressed			
45:00.6 Audio recording enabled due to video recording default			
45:00.6 Event button released			
45:00.7 Recording started due to button press	89	37	53.686 875ef3aa2532480383b544037e96e670
45:22.7 Event button pressed			
45:25.7 Recording stopped due to button press	89	37	53.662 875ef3aa2532480383b544037e96e670
45:26.2 Event button released			
45:26.6 Audio recording disabled due to video buffering default			
45:29.1 Event button pressed			
45:29.2 Event button released			
45:29.3 Event button pressed			
45:29.3 Audio recording enabled due to video recording default			
45:29.4 Event button released			
45:29.4 Recording started due to button press	89	38	53.662 470f7d3264fe47ddb85cad660df73697
45:42.0 Event button pressed			
45:45.0 Recording stopped due to button press	89	38	53.652 470f7d3264fe47ddb85cad660df73697
45:45.6 Event button released			
45:46.0 Audio recording disabled due to video buffering default			
45:58.0 Event button pressed			
45:58.1 Event button released			
45:58.1 Event button pressed			
45:58.2 Audio recording enabled due to video recording default			
45:58.3 Event button released			
45:58.3 Recording started due to button press	89	39	53.652 6ce937cafb5642eab2a18720de149228
46:10.6 Event button pressed			
46:13.6 Recording stopped due to button press	89	39	53.638 6ce937cafb5642eab2a18720de149228
46:14.0 Event button released			
46:14.3 Audio recording disabled due to video buffering default			
46:27.5 Event button pressed			
46:27.7 Event button released			
46:27.7 Event button pressed			
46:27.7 Audio recording enabled due to video recording default			
46:27.8 Event button released			
46:27.9 Recording started due to button press	89	40	53.637 53426cef23a54432ad756226a3e5ac2a
46:41.6 Event button pressed			
46:44.6 Recording stopped due to button press	89	40	53.622 53426cef23a54432ad756226a3e5ac2a
46:45.3 Audio recording disabled due to video buffering default			
46:45.4 Event button released			
46:54.5 Event button pressed			
46:54.6 Event button released			
46:54.7 Event button pressed			
46:54.7 Audio recording enabled due to video recording default			
46:54.8 Event button released			

46:54.8 Recording started due to button press	89	41	53.622 331d41288ea743d29407c3f9eaebc3e7
47:26.2 Event button pressed			
47:29.2 Recording stopped due to button press	89	41	53.599 331d41288ea743d29407c3f9eaebc3e7
47:30.0 Event button released			
47:30.2 Audio recording disabled due to video buffering default			
47:35.3 Event button pressed			
47:35.4 Event button released			
47:35.4 Event button pressed			
47:35.4 Audio recording enabled due to video recording default			
47:35.5 Event button released			
47:35.6 Recording started due to button press	89	42	53.598 0270a4f17eff48749beb07276c0d9fb9
48:23.8 Event button pressed			
48:26.8 Recording stopped due to button press	88	42	53.569 0270a4f17eff48749beb07276c0d9fb9
48:27.3 Event button released			
48:27.5 Audio recording disabled due to video buffering default			
48:32.9 Event button pressed			
48:33.0 Event button released			
48:33.0 Event button pressed			
48:33.1 Audio recording enabled due to video recording default			
48:33.1 Event button released			
48:33.2 Recording started due to button press	88	43	53.568 67b8e5006886452bb48c1426029e49e8
49:16.5 Event button pressed			
49:19.6 Recording stopped due to button press	88	43	53.541 67b8e5006886452bb48c1426029e49e8
49:20.1 Event button released			
49:20.3 Audio recording disabled due to video buffering default			
50:06.1 Event button pressed			
50:06.2 Event button released			
50:06.3 Event button pressed			
50:06.3 Audio recording enabled due to video recording default			
50:06.3 Event button released			
50:06.4 Recording started due to button press	88	44	53.541 044bdb5905e9426a99a4b79eacc0f3e9
50:32.7 Event button pressed			
50:35.7 Recording stopped due to button press	88	44	53.503 044bdb5905e9426a99a4b79eacc0f3e9
50:36.3 Event button released			
50:36.6 Audio recording disabled due to video buffering default			
50:48.0 Event button pressed			
50:48.1 Event button released			
50:48.1 Event button pressed			
50:48.2 Audio recording enabled due to video recording default			
50:48.2 Event button released			
50:48.3 Recording started due to button press	88	45	53.502 ed765c95ace248c9b03fcd1a1eb0b5c1
51:00.6 Event button pressed			
51:03.6 Recording stopped due to button press	88	45	53.488 ed765c95ace248c9b03fcd1a1eb0b5c1
51:04.1 Event button released			
51:04.3 Audio recording disabled due to video buffering default			
51:07.1 Event button pressed			
51:07.2 Event button released			

51:07.4	Event button pressed			
51:07.4	Audio recording enabled due to video recording default			
51:07.5	Event button released			
51:07.5	Recording started due to button press	88	46	53.488 6e374b467d14425c82c8a7c32bbdb720
51:30.5	Event button pressed			
51:33.5	Recording stopped due to button press	88	46	53.473 6e374b467d14425c82c8a7c32bbdb720
51:34.0	Event button released			
51:34.2	Audio recording disabled due to video buffering default			
51:44.1	Event button pressed			
51:44.2	Event button released			
51:44.3	Event button pressed			
51:44.3	Audio recording enabled due to video recording default			
51:44.4	Event button released			
51:44.4	Recording started due to button press	88	47	53.472 2a0706b95aa941eb97eb629d8d6188f0
52:32.4	Event button pressed			
52:35.4	Recording stopped due to button press	87	47	53.441 2a0706b95aa941eb97eb629d8d6188f0
52:35.9	Event button released			
52:36.3	Audio recording disabled due to video buffering default			
54:40.0	Axon application connected to device			
55:44.4	Video played back using Axon application			2a0706b95aa941eb97eb629d8d6188f0
56:20.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1751 X6033271L' to 'Sig. 75' using Axon applicator			2a0706b95aa941eb97eb629d8d6188f0
56:20.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			2a0706b95aa941eb97eb629d8d6188f0
57:04.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1751 X6033271L' to 'Signal 75' using Axon applicator			6e374b467d14425c82c8a7c32bbdb720
57:04.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			6e374b467d14425c82c8a7c32bbdb720
57:33.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1750 X6033271L' to 'Signal 75' using Axon applicator			ed765c95ace248c9b03fcd1a1eb0b5c1
57:33.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			ed765c95ace248c9b03fcd1a1eb0b5c1
58:04.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1750 X6033271L' to 'Signal 75' using Axon applicator			044bdb5905e9426a99a4b79eacc0f3e9
58:04.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			044bdb5905e9426a99a4b79eacc0f3e9
59:38.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1748 X6033271L' to 'Signal 75' using Axon applicator			67b8e5006886452bb48c1426029e49e8
59:38.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			67b8e5006886452bb48c1426029e49e8
00:07.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1747 X6033271L' to 'Signal 75' using Axon applicator			0270a4f17eff48749beb07276c0d9fb9
00:07.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			0270a4f17eff48749beb07276c0d9fb9
00:25.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1746 X6033271L' to 'Signal 75' using Axon applicator			331d41288ea743d29407c3f9eaebc3e7
00:25.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			331d41288ea743d29407c3f9eaebc3e7
00:46.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1746 X6033271L' to 'Signal 75' using Axon applicator			53426cef23a54432ad756226a3e5ac2a
00:46.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			53426cef23a54432ad756226a3e5ac2a
01:23.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1745 X6033271L' to 'Signal 75' using Axon applicator			6ce937cafb5642eab2a18720de149228
01:23.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			6ce937cafb5642eab2a18720de149228
01:43.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1745 X6033271L' to 'Signal 75' using Axon applicator			470f7d3264fe47ddb85cad660df73697
01:43.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			470f7d3264fe47ddb85cad660df73697
02:08.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1745 X6033271L' to 'Signal 75' using Axon applicator			875ef3aa2532480383b544037e96e670
02:08.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			875ef3aa2532480383b544037e96e670
02:59.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1744 X6033271L' to 'Signal 75' using Axon applicator			a8b31b7b679045159b19ecd6dbf2453b
02:59.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			a8b31b7b679045159b19ecd6dbf2453b
03:20.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1743 X6033271L' to 'Signal 75' using Axon applicator			2dca2add8bfe4841bbd8365475bb4f16
03:20.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			2dca2add8bfe4841bbd8365475bb4f16
05:38.5	Event button pressed			

05:38.6	Event button released			
05:38.6	Event button pressed			
05:38.7	Audio recording enabled due to video recording default			
05:38.7	Event button released			
05:38.8	Recording started due to button press	86	48	53.434 84a4dbc3896146a1b38ab0913eee0ca6
06:22.1	Event button pressed			
06:25.1	Recording stopped due to button press	86	48	53.349 84a4dbc3896146a1b38ab0913eee0ca6
06:25.6	Event button released			
06:26.0	Audio recording disabled due to video buffering default			
06:36.8	Event button pressed			
06:37.1	Event button released			
06:38.5	Event button pressed			
06:38.7	Event button released			
06:39.3	Event button pressed			
06:39.4	Event button released			
06:39.5	Event button pressed			
06:39.5	Audio recording enabled due to video recording default			
06:39.6	Event button released			
06:39.6	Recording started due to button press	86	49	53.348 26e21dd2953d43e896256833de2aae1e
07:00.1	Event button pressed			
07:03.1	Recording stopped due to button press	86	49	53.329 26e21dd2953d43e896256833de2aae1e
07:03.6	Event button released			
07:04.0	Audio recording disabled due to video buffering default			
07:07.4	Event button pressed			
07:07.6	Event button released			
07:07.6	Event button pressed			
07:07.6	Audio recording enabled due to video recording default			
07:07.7	Event button released			
07:07.8	Recording started due to button press	86	50	53.329 e5f8c99dfc4644939ed0d488b97bf70d
13:24.4	Event button pressed			
13:27.4	Recording stopped due to button press	85	50	53.128 e5f8c99dfc4644939ed0d488b97bf70d
13:27.9	Event button released			
13:28.2	Audio recording disabled due to video buffering default			
17:22.7	Event button pressed			
17:22.8	Event button released			
17:22.9	Event button pressed			
17:22.9	Audio recording enabled due to video recording default			
17:22.9	Event button released			
17:23.0	Recording started due to button press	84	51	53.126 f53f02de15d045da965b59dfa42102ad
18:47.1	Event button pressed			
18:50.1	Recording stopped due to button press	84	51	53.02 f53f02de15d045da965b59dfa42102ad
18:50.9	Audio recording disabled due to video buffering default			
18:51.0	Event button released			
27:14.8	Event button pressed			
27:14.9	Event button released			
27:15.0	Event button pressed			
27:15.0	Audio recording enabled due to video recording default			

27:15.1	Event button released				
27:15.2	Recording started due to button press	83	52	53.019	37b14b8b753b42fa80ba2d76a8df3ade
31:11.9	Event button pressed				
31:14.9	Recording stopped due to button press	82	52	52.832	37b14b8b753b42fa80ba2d76a8df3ade
31:15.7	Event button released				
31:15.8	Audio recording disabled due to video buffering default				
42:26.1	Audit log created	82	52	1.15.14	52.831
05:49.4	Event button pressed				
05:49.5	Event button released				
05:49.5	Event button pressed				
05:49.6	Audio recording enabled due to video recording default				
05:49.6	Event button released				
05:49.7	Recording started due to button press	79	53	52.83	ff04ac5df6c94803a24b38e8bb45a99e
06:42.5	Event button pressed				
06:42.7	Event button released				
06:42.8	Event button pressed				
06:42.9	Event button released				
06:44.6	Event button pressed				
06:47.6	Recording stopped due to button press	79	53	52.739	ff04ac5df6c94803a24b38e8bb45a99e
06:48.0	Event button released				
06:48.3	Audio recording disabled due to video buffering default				
07:38.5	Event button pressed				
07:38.7	Event button released				
07:38.7	Event button pressed				
07:38.7	Audio recording enabled due to video recording default				
07:38.8	Event button released				
07:38.9	Recording started due to button press	79	54	52.738	e228786e614f4cce84af14b179767471
08:50.8	Event button pressed				
08:53.8	Recording stopped due to button press	78	54	52.674	e228786e614f4cce84af14b179767471
08:54.8	Event button released				
08:54.8	Audio recording disabled due to video buffering default				
15:09.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1742 X6033271L' to 'Signal 75' using Axon applicator				c9d13a3740184469a69c2b1968d6ad8a
15:09.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				c9d13a3740184469a69c2b1968d6ad8a
15:27.1	Video played back using Axon application				899e36983bc14f93ab2d24c43b9a0bf3
16:20.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1741 X6033271L' to 'Signal 75' using Axon applicator				899e36983bc14f93ab2d24c43b9a0bf3
16:20.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				899e36983bc14f93ab2d24c43b9a0bf3
17:29.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1738 X6033271L' to 'Signal 75 Backing 3610' using Axon applicator				0143bbb0b5ed4d709194a3537bb5f4bb
17:29.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				0143bbb0b5ed4d709194a3537bb5f4bb
17:50.7	Title changed in video metadata from 'Signal 75 Backing 3610' to 'Signal 75' using Axon applicator				0143bbb0b5ed4d709194a3537bb5f4bb
18:10.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1737 X6033271L' to 'Signal 75' using Axon applicator				c7408287eb894f2da2005d8c24270b9f
18:10.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				c7408287eb894f2da2005d8c24270b9f
18:31.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1736 X6033271L' to 'Signal 75' using Axon applicator				b591834db0024662b619ca6f558c174f
18:31.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				b591834db0024662b619ca6f558c174f
18:56.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1736 X6033271L' to 'Signal 75' using Axon applicator				93621ad560294a3ea85f29b83a4e790d
18:56.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				93621ad560294a3ea85f29b83a4e790d
19:16.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1736 X6033271L' to 'Signal' using Axon applicator				9d04cd011cca4bf2bd80652f6aa7e3e1
19:16.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				9d04cd011cca4bf2bd80652f6aa7e3e1

19:41.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1733 X6033271L' to 'Signal 75' using Axon applicator			e0828b47fd1c441db40510e7e31c5f89
19:41.8 Categories 'Miscellaneous' added to video metadata using Axon applicator			e0828b47fd1c441db40510e7e31c5f89
20:06.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1732 X6033271L' to 'Signal 75' using Axon applicator			04227c9fc05e4e7e936f927b95be158d
20:06.9 Categories 'Miscellaneous' added to video metadata using Axon applicator			04227c9fc05e4e7e936f927b95be158d
20:24.5 Title changed in video metadata from 'Signal' to 'Signal 75' using Axon applicator			9d04cd011cca4bf2bd80652f6aa7e3e1
21:19.5 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1732 X6033271L' to 'Signal 75' using Axon applicator			ffb4bea87d2c4fe4ae826c4640527f67
21:19.5 Categories 'Miscellaneous' added to video metadata using Axon applicator			ffb4bea87d2c4fe4ae826c4640527f67
21:51.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1727 X6033271L' to 'Signal 75' using Axon applicator			364dad5633224c5e98f0ddeb9f160865
21:51.8 Categories 'Miscellaneous' added to video metadata using Axon applicator			364dad5633224c5e98f0ddeb9f160865
22:09.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1726 X6033271L' to 'Signal 75' using Axon applicator			d80e2a0df5284f8c88e901e54ef3c0de
22:09.7 Categories 'Miscellaneous' added to video metadata using Axon applicator			d80e2a0df5284f8c88e901e54ef3c0de
22:31.5 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1725 X6033271L' to 'Signal 75' using Axon applicator			91ad756ced3048e98c642cca412233b0
22:31.5 Categories 'Miscellaneous' added to video metadata using Axon applicator			91ad756ced3048e98c642cca412233b0
22:49.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1724 X6033271L' to 'Signal 75' using Axon applicator			35242359641e4ebc8e1a8982b1b4b409
22:49.2 Categories 'Miscellaneous' added to video metadata using Axon applicator			35242359641e4ebc8e1a8982b1b4b409
23:06.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1723 X6033271L' to 'Signal 75' using Axon applicator			8709b834dcb14308a8c4ba9dd9fb37d8
23:06.7 Categories 'Miscellaneous' added to video metadata using Axon applicator			8709b834dcb14308a8c4ba9dd9fb37d8
23:32.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1723 X6033271L' to 'Signal 75' using Axon applicator			0c6b6e9ad1ae40af9e03e187a9a04bbe
23:32.3 Categories 'Miscellaneous' added to video metadata using Axon applicator			0c6b6e9ad1ae40af9e03e187a9a04bbe
23:52.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1721 X6033271L' to 'Signal 75' using Axon applicator			243f27744e6d4a2bbbae5883c939ba62
23:52.9 Categories 'Miscellaneous' added to video metadata using Axon applicator			243f27744e6d4a2bbbae5883c939ba62
24:31.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1720 X6033271L' to 'Signal 75' using Axon applicator			b0551e1403e24a889a371bbd7b53a9b0
24:31.0 Categories 'Miscellaneous' added to video metadata using Axon applicator			b0551e1403e24a889a371bbd7b53a9b0
25:46.0 Event button pressed			
25:46.1 Event button released			
25:46.2 Event button pressed			
25:46.2 Audio recording enabled due to video recording default			
25:46.3 Event button released			
25:46.4 Recording started due to button press	77	55	52.672 aad916d1f540491b8bbf1085237a1e4d
26:52.3 Event button pressed			
26:55.3 Recording stopped due to button press	77	55	52.576 aad916d1f540491b8bbf1085237a1e4d
26:55.9 Event button released			
26:56.3 Audio recording disabled due to video buffering default			
30:08.9 Event button pressed			
30:09.1 Event button released			
30:09.1 Event button pressed			
30:09.1 Audio recording enabled due to video recording default			
30:09.3 Event button released			
30:09.3 Recording started due to button press	76	56	52.575 81f0b91cf8124570be871c4b13725dbd
30:45.5 Event button pressed			
30:48.5 Recording stopped due to button press	76	56	52.494 81f0b91cf8124570be871c4b13725dbd
30:49.1 Event button released			
30:49.3 Audio recording disabled due to video buffering default			
31:14.9 Event button pressed			
31:15.1 Event button released			
31:15.1 Event button pressed			
31:15.1 Audio recording enabled due to video recording default			

31:15.2	Event button released			
31:15.3	Recording started due to button press	76	57	52.493 87371a8c72814d4ba71b074f082c7080
31:34.4	Event button pressed			
31:37.4	Recording stopped due to button press	76	57	52.469 87371a8c72814d4ba71b074f082c7080
31:37.9	Event button released			
31:38.2	Audio recording disabled due to video buffering default			
32:13.0	Event button pressed			
32:13.1	Event button released			
32:13.2	Event button pressed			
32:13.2	Audio recording enabled due to video recording default			
32:13.3	Event button released			
32:13.4	Recording started due to button press	76	58	52.468 2211099e137a45a3bcaa5474e43ee034
34:05.5	Event button pressed			
34:08.5	Recording stopped due to button press	75	58	52.39 2211099e137a45a3bcaa5474e43ee034
34:09.0	Event button released			
34:09.3	Audio recording disabled due to video buffering default			
34:52.7	Event button pressed			
34:53.0	Event button released			
34:53.3	Event button pressed			
34:53.3	Audio recording enabled due to video recording default			
34:53.4	Event button released			
34:53.4	Recording started due to button press	75	59	52.389 d06236b72e40458fa9226947543c
34:53.5	Event button pressed			
34:53.6	Event button released			
35:21.4	Event button pressed			
35:24.4	Recording stopped due to button press	75	59	52.351 d06236b72e40458fa9226947543c
35:25.0	Event button released			
35:25.2	Audio recording disabled due to video buffering default			
39:58.5	Event button pressed			
39:58.6	Event button released			
39:58.7	Event button pressed			
39:58.7	Audio recording enabled due to video recording default			
39:58.8	Event button released			
39:58.9	Recording started due to button press	75	60	52.35 157e0a707e5e441cae1b6758ac91a682
40:14.2	Event button pressed			
40:17.2	Recording stopped due to button press	75	60	52.309 157e0a707e5e441cae1b6758ac91a682
40:17.6	Event button released			
40:18.1	Audio recording disabled due to video buffering default			
41:05.9	Event button pressed			
41:06.0	Event button released			
41:06.1	Event button pressed			
41:06.1	Audio recording enabled due to video recording default			
41:06.2	Event button released			
41:06.3	Recording started due to button press	75	61	52.28 75bc2d0c14cd4d09a9c2ac2c7455a212
42:26.1	Audit log created	74	61 1.15.14	52.214
42:43.0	Event button pressed			
42:46.0	Recording stopped due to button press	74	61	52.203 75bc2d0c14cd4d09a9c2ac2c7455a212

42:46.5	Event button released			
42:46.8	Audio recording disabled due to video buffering default			
43:08.8	Event button pressed			
43:08.9	Event button released			
43:09.0	Event button pressed			
43:09.0	Audio recording enabled due to video recording default			
43:09.1	Event button released			
43:09.2	Recording started due to button press	74	62	52.203 72867dc0e2e94332b86202d9e0290c5e
43:42.0	Event button pressed			
43:45.0	Recording stopped due to button press	74	62	52.173 72867dc0e2e94332b86202d9e0290c5e
43:45.5	Event button released			
43:45.8	Audio recording disabled due to video buffering default			
44:16.3	Event button pressed			
44:16.4	Event button released			
44:16.5	Event button pressed			
44:16.5	Audio recording enabled due to video recording default			
44:16.6	Event button released			
44:16.7	Recording started due to button press	74	63	52.172 5ddd1639671d4f109ab68cf59db8a4f1
44:36.9	Event button pressed			
44:39.9	Recording stopped due to button press	74	63	52.145 5ddd1639671d4f109ab68cf59db8a4f1
44:40.4	Event button released			
44:40.7	Audio recording disabled due to video buffering default			
48:02.4	Event button pressed			
48:02.6	Event button released			
48:02.7	Event button pressed			
48:02.7	Audio recording enabled due to video recording default			
48:02.8	Event button released			
48:02.8	Recording started due to button press	73	64	52.144 447753abe4b846fbb3d4f4bbc2aca785
48:07.6	Event button pressed			
48:10.6	Recording stopped due to button press	73	64	52.127 447753abe4b846fbb3d4f4bbc2aca785
48:11.3	Audio recording disabled due to video buffering default			
48:12.0	Event button released			
48:15.9	Event button pressed			
48:16.0	Event button released			
48:16.1	Event button pressed			
48:16.1	Audio recording enabled due to video recording default			
48:16.2	Event button released			
48:16.3	Recording started due to button press	73	65	52.115 e07a5c34fd5c4326a1eb370fd8455b8f
49:26.7	Event button pressed			
49:29.7	Recording stopped due to button press	73	65	52.038 e07a5c34fd5c4326a1eb370fd8455b8f
49:30.4	Audio recording disabled due to video buffering default			
49:30.5	Event button released			
52:41.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1715 X6033271L' to 'Signal 75' using Axon applicator			088b0ee003d74ce89275fd5b4352aaef
52:41.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			088b0ee003d74ce89275fd5b4352aaef
53:03.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1715 X6033271L' to 'Signal 75' using Axon applicator			5218723471f34abab307350ea1f5b3f6
53:03.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			5218723471f34abab307350ea1f5b3f6
53:22.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1714 X6033271L' to 'Signal 75' using Axon applicator			4d751c5396b14e72844d1a44c48cd381

53:22.4 Categories 'Miscellaneous' added to video metadata using Axon applicator
53:41.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1711 X6033271L' to 'Signal 75' using Axon applicator
53:41.7 Categories 'Miscellaneous' added to video metadata using Axon applicator
54:01.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1710 X6033271L' to 'Signal 75' using Axon applicator
54:01.7 Categories 'Miscellaneous' added to video metadata using Axon applicator
54:27.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1710 X6033271L' to 'Signal 75' using Axon applicator
54:27.3 Categories 'Miscellaneous' added to video metadata using Axon applicator
54:52.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1709 X6033271L' to 'Signal 75' using Axon applicator
54:52.7 Categories 'Miscellaneous' added to video metadata using Axon applicator
55:20.5 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1708 X6033271L' to 'Signal 75' using Axon applicator
55:20.5 Categories 'Miscellaneous' added to video metadata using Axon applicator
55:38.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1708 X6033271L' to 'Signal 75' using Axon applicator
55:38.3 Categories 'Miscellaneous' added to video metadata using Axon applicator
55:58.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1707 X6033271L' to 'Signal 75' using Axon applicator
55:58.7 Categories 'Miscellaneous' added to video metadata using Axon applicator
56:15.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1707 X6033271L' to 'Signal 75' using Axon applicator
56:15.6 Categories 'Miscellaneous' added to video metadata using Axon applicator
56:31.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1706 X6033271L' to 'Signal 75' using Axon applicator
56:31.1 Categories 'Miscellaneous' added to video metadata using Axon applicator
56:46.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1701 X6033271L' to 'Signal 75' using Axon applicator
56:46.6 Categories 'Miscellaneous' added to video metadata using Axon applicator
57:13.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1658 X6033271L' to 'Signal 75' using Axon applicator
57:13.3 Categories 'Miscellaneous' added to video metadata using Axon applicator
57:29.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1650 X6033271L' to 'Signal 75' using Axon applicator
57:29.0 Categories 'Miscellaneous' added to video metadata using Axon applicator
57:57.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1642 X6033271L' to 'Signal 75' using Axon applicator
57:57.7 Categories 'Miscellaneous' added to video metadata using Axon applicator
58:05.5 Video played back using Axon application
01:08.8 Title changed in video metadata from 'Signal 75' to 'Accidental Recording' using Axon applicator
01:08.8 Categories 'Accidental Recording' added to video metadata using Axon applicator
01:08.8 Categories 'Miscellaneous' removed from video metadata using Axon applicator
02:31.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1805 X6033271L' to 'Signal 75' using Axon applicator
02:31.2 Categories 'Miscellaneous' added to video metadata using Axon applicator
02:49.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1806 X6033271L' to 'Signal 75' using Axon applicator
02:49.2 Categories 'Miscellaneous' added to video metadata using Axon applicator
03:10.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1807 X6033271L' to 'Signal 75' using Axon applicator
03:10.2 Categories 'Miscellaneous' added to video metadata using Axon applicator
03:52.5 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1817 X6033271L' to 'Signal 75' using Axon applicator
03:52.5 Categories 'Miscellaneous' added to video metadata using Axon applicator
04:14.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1827 X6033271L' to 'Signal 75' using Axon applicator
04:14.9 Categories 'Miscellaneous' added to video metadata using Axon applicator
04:34.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1905 X6033271L' to 'Signal 75' using Axon applicator
04:34.4 Categories 'Miscellaneous' added to video metadata using Axon applicator
04:57.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1907 X6033271L' to 'Sig' using Axon applicator
04:57.3 Categories 'Miscellaneous' added to video metadata using Axon applicator
05:08.6 Title changed in video metadata from 'Sig' to 'Signal 75' using Axon application
05:37.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1925 X6033271L' to 'Signal 75' using Axon applicator

4d751c5396b14e72844d1a44c48cd381
e67a8b09307d45e495923e8aa7d5f57b
e67a8b09307d45e495923e8aa7d5f57b
f8683976c5a1485f86d3e33c4665712c
f8683976c5a1485f86d3e33c4665712c
6ee3c7c70f7147dc8a2a0faafc669cd3
6ee3c7c70f7147dc8a2a0faafc669cd3
34eb81bd098145bca0a1fb7f754835a8
34eb81bd098145bca0a1fb7f754835a8
b7e9cee514124d87a9db0d4d674d55ae
b7e9cee514124d87a9db0d4d674d55ae
c9489162e3b2405981303c6ef2298bf7
c9489162e3b2405981303c6ef2298bf7
c3e6765221ad436d925dff06e5c6cf91
c3e6765221ad436d925dff06e5c6cf91
17fb1b3532374bd3a0c33bc7caf4f19
17fb1b3532374bd3a0c33bc7caf4f19
a2fafd46bf764e1db9043babe590b481
a2fafd46bf764e1db9043babe590b481
515e50f3c86e40959d90077edc61baac
515e50f3c86e40959d90077edc61baac
173f0d5a91d248158f1802681ab331b6
173f0d5a91d248158f1802681ab331b6
6d8ec5dc45fd4ca5a02a33b0063c7e47
6d8ec5dc45fd4ca5a02a33b0063c7e47
607dc4df8cfd45f8a06fefcdc29522c5
607dc4df8cfd45f8a06fefcdc29522c5
607dc4df8cfd45f8a06fefcdc29522c5
607dc4df8cfd45f8a06fefcdc29522c5
607dc4df8cfd45f8a06fefcdc29522c5
607dc4df8cfd45f8a06fefcdc29522c5
84a4dbc3896146a1b38ab0913eee0ca6
84a4dbc3896146a1b38ab0913eee0ca6
26e21dd2953d43e896256833de2aae1e
26e21dd2953d43e896256833de2aae1e
e5f8c99dfc4644939ed0d488b97bf70d
e5f8c99dfc4644939ed0d488b97bf70d
f53f02de15d045da965b59dfa42102ad
f53f02de15d045da965b59dfa42102ad
37b14b8b753b42fa80ba2d76a8df3ade
37b14b8b753b42fa80ba2d76a8df3ade
ff04ac5df6c94803a24b38e8bb45a99e
ff04ac5df6c94803a24b38e8bb45a99e
e228786e614f4cce84af14b179767471
e228786e614f4cce84af14b179767471
e228786e614f4cce84af14b179767471
e228786e614f4cce84af14b179767471
aad916d1f540491b8bbf1085237a1e4d

05:37.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				aad916d1f540491b8bbf1085237a1e4d
05:58.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1930 X6033271L' to 'Signal 75' using Axon applicator				81f0b91cf8124570be871c4b13725dbd
05:58.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				81f0b91cf8124570be871c4b13725dbd
06:15.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1931 X6033271L' to 'Signal 75' using Axon applicator				87371a8c72814d4ba71b074f082c7080
06:15.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				87371a8c72814d4ba71b074f082c7080
06:33.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1932 X6033271L' to 'Signal 75' using Axon applicator				2211099e137a45a3bcaa5474e43ee034
06:33.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				2211099e137a45a3bcaa5474e43ee034
06:52.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1934 X6033271L' to 'Signal 75' using Axon applicator				d06236b72e40458fa9ff79226947543c
06:52.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				d06236b72e40458fa9ff79226947543c
07:13.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1939 X6033271L' to 'Signal 75' using Axon applicator				157e0a707e5e441cae1b6758ac91a682
07:13.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				157e0a707e5e441cae1b6758ac91a682
07:27.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1941 X6033271L' to 'Signal 75' using Axon applicator				75bc2d0c14cd4d09a9c2ac2c7455a212
07:32.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				75bc2d0c14cd4d09a9c2ac2c7455a212
07:54.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1943 X6033271L' to 'Signal 75' using Axon applicator				72867dc0e2e94332b86202d9e0290c5e
07:54.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				72867dc0e2e94332b86202d9e0290c5e
08:14.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1944 X6033271L' to 'Signal 75' using Axon applicator				5ddd1639671d4f109ab68cf59db8a4f1
08:14.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				5ddd1639671d4f109ab68cf59db8a4f1
08:35.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1948 X6033271L' to 'Signal' using Axon applicator				447753abe4b846fbb3d4f4bbc2aca785
08:35.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				447753abe4b846fbb3d4f4bbc2aca785
08:42.1	Title changed in video metadata from 'Signal' to 'Signal 75' using Axon applicator				447753abe4b846fbb3d4f4bbc2aca785
09:00.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-06 1948 X6033271L' to 'Signal 75' using Axon applicator				e07a5c34fd5c4326a1eb370fd8455b8f
09:00.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				e07a5c34fd5c4326a1eb370fd8455b8f
09:18.1	Axon application disconnected from device				
42:26.2	Audit log created	68	65 1.15.14	52.034	
42:26.2	Audit log created	62	65 1.15.14	52.033	
42:26.2	Audit log created	55	65 1.15.14	52.031	
33:43.7	Camera connected to Axon Dock X62001W9H	49	65	52.066	
33:43.9	Audit log created	49	65 1.15.14	52.03	
33:43.9	Audit log rolled	49	65	52.03	
33:44.0	Device connected to charger	49	65	52.03	
33:57.9	Video upload started when camera was docked				607dc4df8cfd45f8a06fefcdc29522c5
34:13.8	Audit log successfully uploaded				
34:13.9	Audit log successfully uploaded and deleted from device	49	65	52.066	
34:15.0	Date/Time synced to 09/06/2021 11:34:15.02 PM from 09/06/2021 11:34:13.92 PM				
34:40.9	Audit log successfully uploaded				
34:41.1	Audit log successfully uploaded and deleted from device	49	65	52.066	
34:59.2	Audit log successfully uploaded				
34:59.4	Audit log successfully uploaded and deleted from device	49	65	52.066	
35:04.3	Video successfully uploaded from device when docked				607dc4df8cfd45f8a06fefcdc29522c5
35:04.6	Video deleted from device when docked	49	64	52.31	607dc4df8cfd45f8a06fefcdc29522c5
35:04.7	Audit log created	49	64 1.15.14	52.311	
35:04.7	Audit log rolled	49	64	52.311	
35:04.9	Video upload started when camera was docked				6d8ec5dc45fd4ca5a02a33b0063c7e47
35:07.6	Audit log successfully uploaded				
35:07.7	Audit log successfully uploaded and deleted from device	49	64	52.311	
35:22.9	Audit log successfully uploaded				
35:23.1	Audit log successfully uploaded and deleted from device	49	64	52.311	

35:30.9	Video successfully uploaded from device when dockec			6d8ec5dc45fd4ca5a02a33b0063c7e47
35:31.1	Video deleted from device when docked	49	63	52.395 6d8ec5dc45fd4ca5a02a33b0063c7e47
35:31.2	Audit log created	49	63 1.15.14	52.395
35:31.2	Audit log rolled	49	63	52.395
35:31.4	Video upload started when camera was docked			173f0d5a91d248158f1802681ab331b6
35:51.2	Audit log successfully uploaded			
35:51.3	Audit log successfully uploaded and deleted from device	49	63	52.395
35:52.8	Video successfully uploaded from device when dockec			173f0d5a91d248158f1802681ab331b6
35:53.0	Video deleted from device when docked	49	62	52.468 173f0d5a91d248158f1802681ab331b6
35:53.1	Audit log rolled	49	62	52.468
35:53.1	Audit log created	49	62 1.15.14	52.468
35:53.3	Video upload started when camera was docked			515e50f3c86e40959d90077edc61baac
35:54.5	Audit log successfully uploaded			
35:54.6	Audit log successfully uploaded and deleted from device	49	62	52.468
36:02.5	Audit log successfully uploaded			
36:02.7	Audit log successfully uploaded and deleted from device	49	62	52.468
36:09.8	Audit log successfully uploaded			
36:10.0	Audit log successfully uploaded and deleted from device	50	62	52.468
36:12.5	Video successfully uploaded from device when dockec			515e50f3c86e40959d90077edc61baac
36:12.8	Video deleted from device when docked	50	61	52.534 515e50f3c86e40959d90077edc61baac
36:12.9	Audit log created	50	61 1.15.14	52.535
36:12.9	Audit log rolled	50	61	52.535
36:13.1	Video upload started when camera was docked			a2fafd46bf764e1db9043babe590b481
36:29.1	Audit log successfully uploaded			
36:29.3	Audit log successfully uploaded and deleted from device	50	61	52.535
36:32.5	Video successfully uploaded from device when dockec			a2fafd46bf764e1db9043babe590b481
36:32.8	Video deleted from device when docked	50	60	52.603 a2fafd46bf764e1db9043babe590b481
36:32.8	Audit log rolled	50	60	52.603
36:32.8	Audit log created	50	60 1.15.14	52.603
36:33.1	Video upload started when camera was docked			17fb1b3532374bd3a0c33fbc7caf4f19
36:37.5	Video successfully uploaded from device when dockec			17fb1b3532374bd3a0c33fbc7caf4f19
36:37.7	Video deleted from device when docked	50	59	52.617 17fb1b3532374bd3a0c33fbc7caf4f19
36:37.8	Audit log created	50	59 1.15.14	52.617
36:37.8	Audit log rolled	50	59	52.617
36:38.0	Video upload started when camera was docked			c3e6765221ad436d925dff06e5c6cf91
36:41.4	Audit log successfully uploaded			
36:41.6	Audit log successfully uploaded and deleted from device	50	59	52.617
36:44.6	Video successfully uploaded from device when dockec			c3e6765221ad436d925dff06e5c6cf91
36:44.7	Audit log successfully uploaded			
36:44.9	Video deleted from device when docked	50	58	52.64 c3e6765221ad436d925dff06e5c6cf91
36:44.9	Audit log created	50	58 1.15.14	52.64
36:44.9	Audit log rolled	50	58	52.64
36:45.0	Audit log successfully uploaded and deleted from device	50	58	52.64
36:45.1	Video upload started when camera was docked			c9489162e3b2405981303c6ef2298bf7
36:48.5	Video successfully uploaded from device when dockec			c9489162e3b2405981303c6ef2298bf7
36:48.6	Video deleted from device when docked	50	57	52.651 c9489162e3b2405981303c6ef2298bf7
36:48.7	Audit log rolled	50	57	52.651

36:48.7	Audit log created	50	57	1.15.14	52.651	
36:49.0	Video upload started when camera was docked					b7e9cee514124d87a9db0d4d674d55ae
36:56.6	Video successfully uploaded from device when docked					b7e9cee514124d87a9db0d4d674d55ae
36:56.8	Video deleted from device when docked	50	56		52.674	b7e9cee514124d87a9db0d4d674d55ae
36:56.9	Audit log rolled	50	56		52.674	
36:56.9	Audit log created	50	56	1.15.14	52.674	
36:57.0	Video upload started when camera was docked					34eb81bd098145bca0a1fb7f754835a8
37:03.7	Video successfully uploaded from device when docked					34eb81bd098145bca0a1fb7f754835a8
37:03.9	Video deleted from device when docked	50	55		52.695	34eb81bd098145bca0a1fb7f754835a8
37:04.0	Audit log created	50	55	1.15.14	52.695	
37:04.0	Audit log rolled	50	55		52.695	
37:04.2	Video upload started when camera was docked					6ee3c7c70f7147dc8a2a0faafc669cd3
37:10.1	Audit log successfully uploaded					
37:10.2	Audit log successfully uploaded and deleted from device	50	55		52.695	
37:12.4	Video successfully uploaded from device when docked					6ee3c7c70f7147dc8a2a0faafc669cd3
37:12.7	Video deleted from device when docked	50	54		52.721	6ee3c7c70f7147dc8a2a0faafc669cd3
37:12.7	Audit log created	50	54	1.15.14	52.721	
37:12.7	Audit log rolled	50	54		52.721	
37:12.9	Video upload started when camera was docked					f8683976c5a1485f86d3e33c4665712c
37:16.2	Video successfully uploaded from device when docked					f8683976c5a1485f86d3e33c4665712c
37:16.4	Video deleted from device when docked	50	53		52.729	f8683976c5a1485f86d3e33c4665712c
37:16.5	Audit log rolled	50	53		52.729	
37:16.5	Audit log created	50	53	1.15.14	52.729	
37:16.7	Video upload started when camera was docked					e67a8b09307d45e495923e8aa7d5f57b
37:19.9	Video successfully uploaded from device when docked					e67a8b09307d45e495923e8aa7d5f57b
37:20.1	Video deleted from device when docked	50	52		52.739	e67a8b09307d45e495923e8aa7d5f57b
37:20.1	Audit log created	50	52	1.15.14	52.739	
37:20.1	Audit log rolled	50	52		52.739	
37:20.4	Video upload started when camera was docked					4d751c5396b14e72844d1a44c48cd381
37:35.3	Audit log successfully uploaded					
37:35.5	Audit log successfully uploaded and deleted from device	50	52		52.739	
37:40.3	Video successfully uploaded from device when docked					4d751c5396b14e72844d1a44c48cd381
37:40.5	Video deleted from device when docked	50	51		52.809	4d751c5396b14e72844d1a44c48cd381
37:40.5	Audit log rolled	50	51		52.809	
37:40.5	Audit log created	50	51	1.15.14	52.809	
37:40.7	Video upload started when camera was docked					5218723471f34abab307350ea1f5b3f6
37:46.2	Video successfully uploaded from device when docked					5218723471f34abab307350ea1f5b3f6
37:46.4	Video deleted from device when docked	50	50		52.826	5218723471f34abab307350ea1f5b3f6
37:46.5	Audit log created	50	50	1.15.14	52.826	
37:46.5	Audit log rolled	50	50		52.826	
37:46.7	Video upload started when camera was docked					088b0ee003d74ce89275fd5b4352aaef
37:48.7	Audit log successfully uploaded					
37:48.8	Audit log successfully uploaded and deleted from device	50	50		52.826	
37:50.8	Video successfully uploaded from device when docked					088b0ee003d74ce89275fd5b4352aaef
37:51.0	Video deleted from device when docked	50	49		52.838	088b0ee003d74ce89275fd5b4352aaef
37:51.0	Audit log rolled	50	49		52.838	
37:51.0	Audit log created	50	49	1.15.14	52.838	

37:51.3	Video upload started when camera was docked				b0551e1403e24a889a371bbd7b53a9b0
38:05.0	Audit log successfully uploaded				
38:05.2	Audit log successfully uploaded and deleted from device	51	49	52.838	
38:11.3	Video successfully uploaded from device when docked				b0551e1403e24a889a371bbd7b53a9b0
38:11.5	Video deleted from device when docked	51	48	52.907	b0551e1403e24a889a371bbd7b53a9b0
38:11.6	Audit log rolled	51	48	52.907	
38:11.6	Audit log created	51	48	1.15.14	52.907
38:11.7	Video upload started when camera was docked				243f27744e6d4a2bbbbae5883c939ba62
38:21.3	Audit log successfully uploaded				
38:21.4	Audit log successfully uploaded and deleted from device	51	48	52.907	
38:26.4	Video successfully uploaded from device when docked				243f27744e6d4a2bbbbae5883c939ba62
38:26.7	Video deleted from device when docked	51	47	52.962	243f27744e6d4a2bbbbae5883c939ba62
38:26.7	Audit log created	51	47	1.15.14	52.962
38:26.7	Audit log rolled	51	47	52.962	
38:27.1	Video upload started when camera was docked				0c6b6e9ad1ae40af9e03e187a9a04bbe
38:32.6	Video successfully uploaded from device when docked				0c6b6e9ad1ae40af9e03e187a9a04bbe
38:32.8	Video deleted from device when docked	51	46	52.98	0c6b6e9ad1ae40af9e03e187a9a04bbe
38:32.9	Audit log created	51	46	1.15.14	52.981
38:32.9	Audit log rolled	51	46	52.981	
38:33.1	Video upload started when camera was docked				8709b834dcb14308a8c4ba9dd9fb37d8
38:37.7	Video successfully uploaded from device when docked				8709b834dcb14308a8c4ba9dd9fb37d8
38:37.9	Video deleted from device when docked	51	45	52.995	8709b834dcb14308a8c4ba9dd9fb37d8
38:38.0	Audit log rolled	51	45	52.996	
38:38.0	Audit log created	51	45	1.15.14	52.996
38:38.2	Video upload started when camera was docked				35242359641e4ebc8e1a8982b1b4b409
38:43.5	Video successfully uploaded from device when docked				35242359641e4ebc8e1a8982b1b4b409
38:43.7	Video deleted from device when docked	51	44	53.013	35242359641e4ebc8e1a8982b1b4b409
38:43.8	Audit log created	51	44	1.15.14	53.014
38:43.8	Audit log rolled	51	44	53.014	
38:44.0	Video upload started when camera was docked				91ad756ced3048e98c642cca412233b0
38:44.6	Audit log successfully uploaded				
38:44.7	Audit log successfully uploaded and deleted from device	51	44	53.014	
38:46.9	Audit log successfully uploaded				
38:47.0	Audit log successfully uploaded and deleted from device	51	44	53.014	
38:52.6	Video successfully uploaded from device when docked				91ad756ced3048e98c642cca412233b0
38:52.6	Audit log successfully uploaded				
38:52.8	Audit log successfully uploaded and deleted from device	51	43	53.043	
38:52.8	Video deleted from device when docked	51	43	53.043	91ad756ced3048e98c642cca412233b0
38:52.9	Audit log rolled	51	43	53.043	
38:52.9	Audit log created	51	43	1.15.14	53.043
38:52.9	Audit log successfully uploaded				
38:53.1	Video upload started when camera was docked				d80e2a0df5284f8c88e901e54ef3c0de
38:53.1	Audit log successfully uploaded and deleted from device	51	43	53.043	
38:59.8	Video successfully uploaded from device when docked				d80e2a0df5284f8c88e901e54ef3c0de
39:00.0	Video deleted from device when docked	51	42	53.067	d80e2a0df5284f8c88e901e54ef3c0de
39:00.0	Audit log rolled	51	42	53.067	
39:00.0	Audit log created	51	42	1.15.14	53.067

39:00.2 Video upload started when camera was docked				364dad5633224c5e98f0ddeb9f160865
39:15.0 Video successfully uploaded from device when dockec				364dad5633224c5e98f0ddeb9f160865
39:15.3 Video deleted from device when docked	51	41	53.119	364dad5633224c5e98f0ddeb9f160865
39:15.3 Audit log created	51	41 1.15.14	53.12	
39:15.3 Audit log rolled	51	41	53.12	
39:15.5 Video upload started when camera was docked				ffb4bea87d2c4fe4ae826c4640527f67
39:21.2 Audit log successfully uploaded				
39:21.4 Audit log successfully uploaded and deleted from device	51	41	53.12	
39:21.6 Audit log successfully uploaded				
39:21.8 Audit log successfully uploaded and deleted from device	51	41	53.12	
39:21.9 Audit log successfully uploaded				
39:22.1 Audit log successfully uploaded and deleted from device	51	41	53.12	
39:36.7 Video successfully uploaded from device when dockec				ffb4bea87d2c4fe4ae826c4640527f67
39:36.9 Video deleted from device when docked	51	40	53.194	ffb4bea87d2c4fe4ae826c4640527f67
39:37.0 Audit log created	51	40 1.15.14	53.194	
39:37.0 Audit log rolled	51	40	53.194	
39:37.3 Video upload started when camera was docked				04227c9fc05e4e7e936f927b95be158d
39:41.0 Video successfully uploaded from device when dockec				04227c9fc05e4e7e936f927b95be158d
39:41.3 Video deleted from device when docked	51	39	53.204	04227c9fc05e4e7e936f927b95be158d
39:41.3 Audit log rolled	51	39	53.205	
39:41.3 Audit log created	51	39 1.15.14	53.205	
39:41.5 Video upload started when camera was docked				e0828b47fd1c441db40510e7e31c5f89
39:46.1 Video successfully uploaded from device when dockec				e0828b47fd1c441db40510e7e31c5f89
39:46.3 Video deleted from device when docked	51	38	53.22	e0828b47fd1c441db40510e7e31c5f89
39:46.4 Audit log rolled	51	38	53.221	
39:46.4 Audit log created	51	38 1.15.14	53.221	
39:46.6 Video upload started when camera was docked				9d04cd011cca4bf2bd80652f6aa7e3e1
39:47.2 Audit log successfully uploaded				
39:47.4 Audit log successfully uploaded and deleted from device	51	38	53.22	
40:07.6 Video successfully uploaded from device when dockec				9d04cd011cca4bf2bd80652f6aa7e3e1
40:07.8 Video deleted from device when docked	51	37	53.289	9d04cd011cca4bf2bd80652f6aa7e3e1
40:07.9 Audit log rolled	51	37	53.289	
40:07.9 Audit log created	51	37 1.15.14	53.289	
40:08.1 Video upload started when camera was docked				93621ad560294a3ea85f29b83a4e790d
40:08.5 Audit log successfully uploaded				
40:08.7 Audit log successfully uploaded and deleted from device	51	37	53.289	
40:10.3 Video successfully uploaded from device when dockec				93621ad560294a3ea85f29b83a4e790d
40:10.5 Video deleted from device when docked	51	36	53.295	93621ad560294a3ea85f29b83a4e790d
40:10.6 Audit log created	51	36 1.15.14	53.295	
40:10.6 Audit log rolled	51	36	53.295	
40:10.9 Video upload started when camera was docked				b591834db0024662b619ca6f558c174f
40:12.8 Audit log successfully uploaded				
40:13.0 Audit log successfully uploaded and deleted from device	51	36	53.295	
40:16.7 Video successfully uploaded from device when dockec				b591834db0024662b619ca6f558c174f
40:16.9 Video deleted from device when docked	51	35	53.313	b591834db0024662b619ca6f558c174f
40:17.0 Audit log created	51	35 1.15.14	53.313	
40:17.0 Audit log rolled	51	35	53.313	

40:17.2	Video upload started when camera was docked			c7408287eb894f2da2005d8c24270b9f
40:22.4	Video successfully uploaded from device when docked			c7408287eb894f2da2005d8c24270b9f
40:22.6	Video deleted from device when docked	51	34	53.33 c7408287eb894f2da2005d8c24270b9f
40:22.6	Audit log created	51	34 1.15.14	53.33
40:22.6	Audit log rolled	51	34	53.33
40:22.9	Video upload started when camera was docked			0143bbb0b5ed4d709194a3537bb5f4bb
40:40.2	Audit log successfully uploaded			
40:40.4	Audit log successfully uploaded and deleted from device	52	34	53.33
40:44.9	Video successfully uploaded from device when docked			0143bbb0b5ed4d709194a3537bb5f4bb
40:45.1	Video deleted from device when docked	52	33	53.41 0143bbb0b5ed4d709194a3537bb5f4bb
40:45.2	Audit log rolled	52	33	53.41
40:45.2	Audit log created	52	33 1.15.14	53.41
40:45.4	Video upload started when camera was docked			899e36983bc14f93ab2d24c43b9a0bf3
40:54.5	Audit log successfully uploaded			
40:54.7	Audit log successfully uploaded and deleted from device	52	33	53.41
40:55.1	Video successfully uploaded from device when docked			899e36983bc14f93ab2d24c43b9a0bf3
40:55.4	Video deleted from device when docked	52	32	53.444 899e36983bc14f93ab2d24c43b9a0bf3
40:55.5	Audit log created	52	32 1.15.14	53.444
40:55.5	Audit log rolled	52	32	53.444
40:55.6	Video upload started when camera was docked			c9d13a3740184469a69c2b1968d6ad8a
41:06.9	Audit log successfully uploaded			
41:07.1	Audit log successfully uploaded and deleted from device	52	32	53.444
41:10.5	Video successfully uploaded from device when docked			c9d13a3740184469a69c2b1968d6ad8a
41:10.7	Video deleted from device when docked	52	31	53.495 c9d13a3740184469a69c2b1968d6ad8a
41:10.8	Audit log created	52	31 1.15.14	53.495
41:10.8	Audit log rolled	52	31	53.495
41:11.0	Video upload started when camera was docked			2dca2add8bfe4841bbd8365475bb4f16
41:15.9	Video successfully uploaded from device when docked			2dca2add8bfe4841bbd8365475bb4f16
41:16.1	Video deleted from device when docked	52	30	53.512 2dca2add8bfe4841bbd8365475bb4f16
41:16.2	Audit log rolled	52	30	53.512
41:16.2	Audit log created	52	30 1.15.14	53.512
41:16.4	Video upload started when camera was docked			a8b31b7b679045159b19ecd6dbf2453b
41:22.9	Video successfully uploaded from device when docked			a8b31b7b679045159b19ecd6dbf2453b
41:23.0	Video deleted from device when docked	52	29	53.535 a8b31b7b679045159b19ecd6dbf2453b
41:23.1	Audit log rolled	52	29	53.535
41:23.1	Audit log created	52	29 1.15.14	53.535
41:23.3	Video upload started when camera was docked			875ef3aa2532480383b544037e96e670
41:31.0	Video successfully uploaded from device when docked			875ef3aa2532480383b544037e96e670
41:31.2	Video deleted from device when docked	52	28	53.559 875ef3aa2532480383b544037e96e670
41:31.2	Audit log created	52	28 1.15.14	53.559
41:31.2	Audit log rolled	52	28	53.559
41:31.5	Video upload started when camera was docked			470f7d3264fe47ddb85cad660df73697
41:32.2	Audit log successfully uploaded			
41:32.4	Audit log successfully uploaded and deleted from device	52	28	53.559
41:35.0	Video successfully uploaded from device when docked			470f7d3264fe47ddb85cad660df73697
41:35.2	Video deleted from device when docked	52	27	53.569 470f7d3264fe47ddb85cad660df73697
41:35.3	Audit log rolled	52	27	53.569

41:35.3	Audit log created	52	27	1.15.14	53.569	
41:35.5	Video upload started when camera was docked					6ce937cafb5642eab2a18720de149228
41:39.9	Video successfully uploaded from device when docked					6ce937cafb5642eab2a18720de149228
41:40.1	Video deleted from device when docked	52	26		53.583	6ce937cafb5642eab2a18720de149228
41:40.2	Audit log created	52	26	1.15.14	53.584	
41:40.2	Audit log rolled	52	26		53.584	
41:40.4	Video upload started when camera was docked					53426cef23a54432ad756226a3e5ac2a
41:45.4	Video successfully uploaded from device when docked					53426cef23a54432ad756226a3e5ac2a
41:45.6	Video deleted from device when docked	52	25		53.599	53426cef23a54432ad756226a3e5ac2a
41:45.6	Audit log created	52	25	1.15.14	53.599	
41:45.6	Audit log rolled	52	25		53.599	
41:45.9	Video upload started when camera was docked					331d41288ea743d29407c3f9eabc3e7
41:50.5	Audit log successfully uploaded					
41:50.7	Audit log successfully uploaded and deleted from device	52	25		53.599	
41:53.2	Video successfully uploaded from device when docked					331d41288ea743d29407c3f9eabc3e7
41:53.4	Video deleted from device when docked	52	24		53.622	331d41288ea743d29407c3f9eabc3e7
41:53.5	Audit log created	52	24	1.15.14	53.622	
41:53.5	Audit log rolled	52	24		53.622	
41:53.7	Video upload started when camera was docked					0270a4f17eff48749beb07276c0d9fb9
42:02.2	Video successfully uploaded from device when docked					0270a4f17eff48749beb07276c0d9fb9
42:02.5	Video deleted from device when docked	52	23		53.652	0270a4f17eff48749beb07276c0d9fb9
42:02.6	Audit log rolled	52	23		53.652	
42:02.6	Audit log created	52	23	1.15.14	53.652	
42:02.7	Video upload started when camera was docked					67b8e5006886452bb48c1426029e49e8
42:10.7	Video successfully uploaded from device when docked					67b8e5006886452bb48c1426029e49e8
42:10.9	Video deleted from device when docked	53	22		53.679	67b8e5006886452bb48c1426029e49e8
42:11.0	Audit log created	53	22	1.15.14	53.679	
42:11.0	Audit log rolled	53	22		53.679	
42:11.1	Video upload started when camera was docked					044bdb5905e9426a99a4b79eacc0f3e9
42:12.8	Audit log successfully uploaded					
42:13.0	Audit log successfully uploaded and deleted from device	53	22		53.679	
42:19.2	Audit log successfully uploaded					
42:19.3	Audit log successfully uploaded and deleted from device	53	22		53.679	
42:20.4	Audit log successfully uploaded					
42:20.6	Audit log successfully uploaded and deleted from device	53	22		53.679	
42:22.9	Video successfully uploaded from device when docked					044bdb5905e9426a99a4b79eacc0f3e9
42:23.2	Video deleted from device when docked	53	21		53.718	044bdb5905e9426a99a4b79eacc0f3e9
42:23.2	Audit log created	53	21	1.15.14	53.718	
42:23.2	Audit log rolled	53	21		53.718	
42:23.5	Video upload started when camera was docked					ed765c95ace248c9b03fcd1a1eb0b5c1
42:23.7	Audit log successfully uploaded					
42:23.9	Audit log successfully uploaded and deleted from device	53	21		53.718	
42:28.5	Video successfully uploaded from device when docked					ed765c95ace248c9b03fcd1a1eb0b5c1
42:28.7	Video deleted from device when docked	53	20		53.732	ed765c95ace248c9b03fcd1a1eb0b5c1
42:28.8	Audit log created	53	20	1.15.14	53.732	
42:28.8	Audit log rolled	53	20		53.732	
42:29.0	Video upload started when camera was docked					6e374b467d14425c82c8a7c32bbdb720

42:33.5	Video successfully uploaded from device when dockec				6e374b467d14425c82c8a7c32bbdb720
42:33.7	Video deleted from device when docked	53	19	53.747	6e374b467d14425c82c8a7c32bbdb720
42:33.8	Audit log created	53	19	1.15.14	53.747
42:33.8	Audit log rolled	53	19		53.747
42:34.0	Video upload started when camera was docked				2a0706b95aa941eb97eb629d8d6188f0
42:35.0	Audit log successfully uploaded				
42:35.2	Audit log successfully uploaded and deleted from device	53	19		53.747
42:36.3	Audit log successfully uploaded				
42:36.5	Audit log successfully uploaded and deleted from device	53	19		53.747
42:43.3	Video successfully uploaded from device when dockec				2a0706b95aa941eb97eb629d8d6188f0
42:43.5	Video deleted from device when docked	53	18	53.779	2a0706b95aa941eb97eb629d8d6188f0
42:43.6	Audit log created	53	18	1.15.14	53.779
42:43.6	Audit log rolled	53	18		53.779
42:43.8	Video upload started when camera was docked				84a4dbc3896146a1b38ab0913eee0ca6
42:49.7	Audit log successfully uploaded				
42:49.9	Audit log successfully uploaded and deleted from device	53	18		53.779
43:07.7	Video successfully uploaded from device when dockec				84a4dbc3896146a1b38ab0913eee0ca6
43:07.9	Video deleted from device when docked	53	17		53.864
43:08.0	Audit log created	53	17	1.15.14	53.864
43:08.0	Audit log rolled	53	17		53.864
43:08.2	Video upload started when camera was docked				26e21dd2953d43e896256833de2aae1e
43:13.0	Audit log successfully uploaded				
43:13.2	Audit log successfully uploaded and deleted from device	53	17		53.864
43:13.7	Video successfully uploaded from device when dockec				26e21dd2953d43e896256833de2aae1e
43:13.9	Video deleted from device when docked	53	16		53.883
43:14.0	Audit log created	53	16	1.15.14	53.884
43:14.0	Audit log rolled	53	16		53.884
43:14.1	Video upload started when camera was docked				e5f8c99dfc4644939ed0d488b97bf70d
43:25.4	Audit log successfully uploaded				
43:25.5	Audit log successfully uploaded and deleted from device	53	16		53.884
43:25.7	Audit log successfully uploaded				
43:25.9	Audit log successfully uploaded and deleted from device	53	16		53.884
43:36.0	Audit log successfully uploaded				
43:36.1	Audit log successfully uploaded and deleted from device	53	16		53.884
43:42.3	Audit log successfully uploaded				
43:42.4	Audit log successfully uploaded and deleted from device	53	16		53.884
43:56.6	Audit log successfully uploaded				
43:56.7	Audit log successfully uploaded and deleted from device	53	16		53.884
44:08.8	Video successfully uploaded from device when dockec				e5f8c99dfc4644939ed0d488b97bf70d
44:09.0	Video deleted from device when docked	53	15	54.084	e5f8c99dfc4644939ed0d488b97bf70d
44:09.0	Audit log rolled	53	15		54.084
44:09.0	Audit log created	53	15	1.15.14	54.084
44:09.3	Video upload started when camera was docked				f53f02de15d045da965b59dfa42102ad
44:18.9	Audit log successfully uploaded				
44:19.0	Audit log successfully uploaded and deleted from device	53	15		54.084
44:38.1	Video successfully uploaded from device when dockec				f53f02de15d045da965b59dfa42102ad
44:38.3	Video deleted from device when docked	54	14	54.19	f53f02de15d045da965b59dfa42102ad

44:38.4	Audit log created	54	14	1.15.14	54.191	
44:38.4	Audit log rolled	54	14		54.191	
44:38.6	Video upload started when camera was docked					37b14b8b753b42fa80ba2d76a8df3ade
44:48.1	Audit log successfully uploaded					
44:48.3	Audit log successfully uploaded and deleted from device	54	14		54.19	
45:11.4	Audit log successfully uploaded					
45:11.6	Audit log successfully uploaded and deleted from device	54	14		54.19	
45:27.7	Audit log successfully uploaded					
45:27.9	Audit log successfully uploaded and deleted from device	54	14		54.19	
45:30.7	Video successfully uploaded from device when dockec					37b14b8b753b42fa80ba2d76a8df3ade
45:31.0	Video deleted from device when docked	54	13		54.376	37b14b8b753b42fa80ba2d76a8df3ade
45:31.1	Audit log rolled	54	13		54.377	
45:31.1	Audit log created	54	13	1.15.14	54.377	
45:31.2	Video upload started when camera was docked					ff04ac5df6c94803a24b38e8bb45a99e
45:56.8	Video successfully uploaded from device when dockec					ff04ac5df6c94803a24b38e8bb45a99e
45:57.0	Audit log successfully uploaded					
45:57.0	Video deleted from device when docked	54	12		54.468	ff04ac5df6c94803a24b38e8bb45a99e
45:57.1	Audit log created	54	12	1.15.14	54.468	
45:57.1	Audit log rolled	54	12		54.468	
45:57.2	Audit log successfully uploaded and deleted from device	54	12		54.468	
45:57.2	Video upload started when camera was docked					e228786e614f4cce84af14b179767471
46:03.3	Audit log successfully uploaded					
46:03.5	Audit log successfully uploaded and deleted from device	54	12		54.468	
46:09.6	Audit log successfully uploaded					
46:09.8	Audit log successfully uploaded and deleted from device	54	12		54.468	
46:15.9	Video successfully uploaded from device when dockec					e228786e614f4cce84af14b179767471
46:16.2	Video deleted from device when docked	54	11		54.532	e228786e614f4cce84af14b179767471
46:16.3	Audit log created	54	11	1.15.14	54.533	
46:16.3	Audit log rolled	54	11		54.533	
46:16.4	Video upload started when camera was docked					aad916d1f540491b8bbf1085237a1e4d
46:29.0	Audit log successfully uploaded					
46:29.1	Audit log successfully uploaded and deleted from device	54	11		54.532	
46:39.3	Audit log successfully uploaded					
46:39.4	Audit log successfully uploaded and deleted from device	54	11		54.532	
46:43.3	Video successfully uploaded from device when dockec					aad916d1f540491b8bbf1085237a1e4d
46:43.6	Video deleted from device when docked	54	10		54.629	aad916d1f540491b8bbf1085237a1e4d
46:43.6	Audit log rolled	54	10		54.629	
46:43.6	Audit log created	54	10	1.15.14	54.629	
46:43.8	Video upload started when camera was docked					81f0b91cf8124570be871c4b13725dbd
46:47.6	Audit log successfully uploaded					
46:47.8	Audit log successfully uploaded and deleted from device	54	10		54.629	
47:05.7	Video successfully uploaded from device when dockec					81f0b91cf8124570be871c4b13725dbd
47:05.9	Video deleted from device when docked	55	9		54.71	81f0b91cf8124570be871c4b13725dbd
47:06.0	Audit log created	55	9	1.15.14	54.711	
47:06.0	Audit log rolled	55	9		54.711	
47:06.2	Video upload started when camera was docked					87371a8c72814d4ba71b074f082c7080
47:06.9	Audit log successfully uploaded					

47:07.0	Audit log successfully uploaded and deleted from device	55	9	54.711	
47:13.5	Video successfully uploaded from device when dockec				87371a8c72814d4ba71b074f082c7080
47:13.7	Video deleted from device when docked	55	8	54.735	87371a8c72814d4ba71b074f082c7080
47:13.7	Audit log created	55	8 1.15.14	54.736	
47:13.8	Audit log rolled	55	8	54.736	
47:13.9	Video upload started when camera was docked				2211099e137a45a3bcaa5474e43ee034
47:15.2	Audit log successfully uploaded				
47:15.3	Audit log successfully uploaded and deleted from device	55	8	54.736	
47:15.5	Audit log successfully uploaded				
47:15.7	Audit log successfully uploaded and deleted from device	55	8	54.736	
47:27.8	Audit log successfully uploaded				
47:27.9	Audit log successfully uploaded and deleted from device	55	8	54.736	
47:34.4	Video successfully uploaded from device when dockec				2211099e137a45a3bcaa5474e43ee034
47:34.6	Video deleted from device when docked	55	7	54.814	2211099e137a45a3bcaa5474e43ee034
47:34.7	Audit log rolled	55	7	54.824	
47:34.7	Audit log created	55	7 1.15.14	54.824	
47:34.9	Video upload started when camera was docked				d06236b72e40458fa9ff79226947543c
47:41.1	Audit log successfully uploaded				
47:41.2	Audit log successfully uploaded and deleted from device	55	7	54.824	
47:46.6	Video successfully uploaded from device when dockec				d06236b72e40458fa9ff79226947543c
47:46.8	Video deleted from device when docked	55	6	54.863	d06236b72e40458fa9ff79226947543c
47:46.9	Audit log created	55	6 1.15.14	54.869	
47:46.9	Audit log rolled	55	6	54.869	
47:47.1	Video upload started when camera was docked				157e0a707e5e441cae1b6758ac91a682
47:51.3	Audit log successfully uploaded				
47:51.5	Audit log successfully uploaded and deleted from device	55	6	54.869	
47:52.6	Audit log successfully uploaded				
47:52.8	Audit log successfully uploaded and deleted from device	55	6	54.869	
48:06.5	Video successfully uploaded from device when dockec				157e0a707e5e441cae1b6758ac91a682
48:06.7	Video deleted from device when docked	55	5	54.939	157e0a707e5e441cae1b6758ac91a682
48:06.8	Audit log created	55	5 1.15.14	54.941	
48:06.8	Audit log rolled	55	5	54.941	
48:07.0	Video upload started when camera was docked				75bc2d0c14cd4d09a9c2ac2c7455a212
48:12.0	Audit log successfully uploaded				
48:12.2	Audit log successfully uploaded and deleted from device	55	5	54.941	
48:24.3	Audit log successfully uploaded				
48:24.4	Audit log successfully uploaded and deleted from device	55	5	54.941	
48:26.8	Video successfully uploaded from device when dockec				75bc2d0c14cd4d09a9c2ac2c7455a212
48:27.1	Video deleted from device when docked	55	4	55.017	75bc2d0c14cd4d09a9c2ac2c7455a212
48:27.2	Audit log rolled	55	4	55.018	
48:27.2	Audit log created	55	4 1.15.14	55.018	
48:27.4	Video upload started when camera was docked				72867dc0e2e94332b86202d9e0290c5e
48:33.6	Audit log successfully uploaded				
48:33.8	Audit log successfully uploaded and deleted from device	55	4	55.018	
48:36.1	Video successfully uploaded from device when dockec				72867dc0e2e94332b86202d9e0290c5e
48:36.3	Video deleted from device when docked	55	3	55.048	72867dc0e2e94332b86202d9e0290c5e
48:36.3	Audit log created	55	3 1.15.14	55.048	

48:36.3	Audit log rolled	55	3	55.048
48:36.5	Video upload started when camera was docked			5ddd1639671d4f109ab68cf59db8a4f1
48:41.9	Audit log successfully uploaded			
48:42.0	Audit log successfully uploaded and deleted from device	55	3	55.048
48:44.4	Video successfully uploaded from device when dockec			5ddd1639671d4f109ab68cf59db8a4f1
48:44.7	Video deleted from device when docked	56	2	55.075 5ddd1639671d4f109ab68cf59db8a4f1
48:44.7	Audit log created	56	2 1.15.14	55.075
48:44.7	Audit log rolled	56	2	55.075
48:44.9	Video upload started when camera was docked			447753abe4b846fbb3d4f4bbc2aca785
48:55.2	Audit log successfully uploaded			
48:55.4	Audit log successfully uploaded and deleted from device	56	2	55.075
49:02.8	Video successfully uploaded from device when dockec			447753abe4b846fbb3d4f4bbc2aca785
49:03.0	Video deleted from device when docked	56	1	55.14 447753abe4b846fbb3d4f4bbc2aca785
49:03.1	Audit log created	56	1 1.15.14	55.14
49:03.1	Audit log rolled	56	1	55.14
49:03.3	Video upload started when camera was docked			e07a5c34fd5c4326a1eb370fd8455b8f
49:08.5	Audit log successfully uploaded			
49:08.7	Audit log successfully uploaded and deleted from device	56	1	55.14
49:13.8	Video successfully uploaded from device when dockec			e07a5c34fd5c4326a1eb370fd8455b8f
49:14.0	Video deleted from device when docked	56	0	55.181 e07a5c34fd5c4326a1eb370fd8455b8f
49:14.1	Audit log created	56	0 1.15.14	55.181
49:14.1	Audit log rolled	56	0	55.181
49:14.2	Audit log created	56	0 1.15.14	55.181
49:14.2	Audit log rolled	56	0	55.181
49:31.9	Audit log successfully uploaded			
49:32.1	Audit log successfully uploaded and deleted from device	56	0	55.181
49:47.3	Audit log successfully uploaded			
49:47.5	Audit log successfully uploaded and deleted from device	56	0	55.181
50:13.8	Audit log successfully uploaded			
50:14.0	Audit log successfully uploaded and deleted from device	56	0	55.181
50:29.1	Audit log successfully uploaded			
50:29.3	Audit log successfully uploaded and deleted from device	56	0	55.181
50:53.4	Audit log successfully uploaded			
50:53.6	Audit log successfully uploaded and deleted from device	56	0	55.181
51:14.8	Audit log successfully uploaded			
51:15.0	Audit log successfully uploaded and deleted from device	57	0	55.181
51:43.1	Audit log successfully uploaded			
51:43.3	Audit log successfully uploaded and deleted from device	57	0	55.181
51:52.5	Audit log successfully uploaded			
51:52.7	Audit log successfully uploaded and deleted from device	57	0	55.181
52:02.8	Audit log successfully uploaded			
52:03.1	Audit log successfully uploaded and deleted from device	57	0	55.181
52:32.3	Audit log successfully uploaded			
52:32.5	Audit log successfully uploaded and deleted from device	57	0	55.181
52:35.6	Audit log successfully uploaded			
52:35.7	Audit log successfully uploaded and deleted from device	57	0	55.181
53:03.9	Audit log successfully uploaded			

53:04.1	Audit log successfully uploaded and deleted from device	58	0	55.181
53:27.3	Audit log successfully uploaded			
53:27.5	Audit log successfully uploaded and deleted from device	58	0	55.181
53:28.6	Audit log successfully uploaded			
53:28.8	Audit log successfully uploaded and deleted from device	58	0	55.181
53:51.0	Audit log successfully uploaded			
53:51.2	Audit log successfully uploaded and deleted from device	58	0	55.181
54:14.4	Audit log successfully uploaded			
54:14.6	Audit log successfully uploaded and deleted from device	58	0	55.181
54:14.7	Audit log successfully uploaded			
54:14.9	Audit log successfully uploaded and deleted from device	58	0	55.181
54:18.0	Audit log successfully uploaded			
54:18.2	Audit log successfully uploaded and deleted from device	58	0	55.181
54:33.3	Audit log successfully uploaded			
54:33.5	Audit log successfully uploaded and deleted from device	58	0	55.181
54:43.7	Audit log successfully uploaded			
54:43.9	Audit log successfully uploaded and deleted from device	58	0	55.181
54:45.1	Audit log successfully uploaded			
54:45.3	Audit log successfully uploaded and deleted from device	58	0	55.181
55:14.4	Audit log successfully uploaded			
55:14.6	Audit log successfully uploaded and deleted from device	59	0	55.181
55:21.8	Audit log successfully uploaded			
55:22.0	Audit log successfully uploaded and deleted from device	59	0	55.181
55:43.2	Audit log successfully uploaded			
55:43.3	Audit log successfully uploaded and deleted from device	59	0	55.181
56:04.5	Audit log successfully uploaded			
56:04.7	Audit log successfully uploaded and deleted from device	59	0	55.181
56:12.8	Audit log successfully uploaded			
56:13.0	Audit log successfully uploaded and deleted from device	59	0	55.181
56:23.2	Audit log successfully uploaded			
56:23.4	Audit log successfully uploaded and deleted from device	59	0	55.181
56:40.5	Audit log successfully uploaded			
56:40.7	Audit log successfully uploaded and deleted from device	59	0	55.181
56:45.8	Audit log successfully uploaded			
56:45.9	Audit log successfully uploaded and deleted from device	59	0	55.181
57:14.1	Audit log successfully uploaded			
57:14.3	Audit log successfully uploaded and deleted from device	60	0	55.181
57:19.4	Audit log successfully uploaded			
57:19.6	Audit log successfully uploaded and deleted from device	60	0	55.181
57:29.8	Audit log successfully uploaded			
57:30.0	Audit log successfully uploaded and deleted from device	60	0	55.181
57:52.1	Audit log successfully uploaded			
57:52.3	Audit log successfully uploaded and deleted from device	60	0	55.181
58:16.4	Audit log successfully uploaded			
58:16.6	Audit log successfully uploaded and deleted from device	60	0	55.181
58:18.7	Audit log successfully uploaded			
58:18.9	Audit log successfully uploaded and deleted from device	60	0	55.181

58:31.1	Audit log successfully uploaded			
58:31.3	Audit log successfully uploaded and deleted from device	60	0	55.181
58:51.4	Audit log successfully uploaded			
58:51.6	Audit log successfully uploaded and deleted from device	61	0	55.181
59:15.7	Audit log successfully uploaded			
59:15.9	Audit log successfully uploaded and deleted from device	61	0	55.181
59:31.0	Audit log successfully uploaded			
59:31.2	Audit log successfully uploaded and deleted from device	61	0	55.181
59:50.3	Audit log successfully uploaded			
59:50.5	Audit log successfully uploaded and deleted from device	61	0	55.181
00:05.6	Audit log successfully uploaded			
00:05.8	Audit log successfully uploaded and deleted from device	61	0	55.181
00:14.0	Audit log successfully uploaded			
00:14.2	Audit log successfully uploaded and deleted from device	61	0	55.18
00:36.3	Audit log successfully uploaded			
00:36.5	Audit log successfully uploaded and deleted from device	61	0	55.18
00:54.7	Audit log successfully uploaded			
00:54.9	Audit log successfully uploaded and deleted from device	61	0	55.18
01:19.1	Audit log successfully uploaded			
01:19.2	Audit log successfully uploaded and deleted from device	62	0	55.18
01:43.4	Audit log successfully uploaded			
01:43.6	Audit log successfully uploaded and deleted from device	62	0	55.18
01:59.7	Audit log successfully uploaded			
01:59.9	Audit log successfully uploaded and deleted from device	62	0	55.18
02:14.1	Audit log successfully uploaded			
02:14.3	Audit log successfully uploaded and deleted from device	62	0	55.18
02:38.5	Audit log successfully uploaded			
02:38.7	Audit log successfully uploaded and deleted from device	63	0	55.18
03:07.9	Audit log successfully uploaded			
03:08.1	Audit log successfully uploaded and deleted from device	63	0	55.18
03:10.2	Audit log successfully uploaded			
03:10.4	Audit log successfully uploaded and deleted from device	63	0	55.18
03:12.5	Audit log successfully uploaded			
03:12.7	Audit log successfully uploaded and deleted from device	63	0	55.18
03:28.9	Audit log successfully uploaded			
03:29.1	Audit log successfully uploaded and deleted from device	63	0	55.18
03:34.3	Audit log successfully uploaded			
03:34.5	Audit log successfully uploaded and deleted from device	63	0	55.18
03:57.6	Audit log successfully uploaded			
03:57.8	Audit log successfully uploaded and deleted from device	63	0	55.18
04:15.0	Date/Time synced to 09/07/2021 12:04:15.01 AM from 09/07/2021 12:04:15.04 AM			
04:21.8	Audit log successfully uploaded			
04:22.0	Audit log successfully uploaded and deleted from device	63	0	55.18
04:51.1	Audit log successfully uploaded			
04:51.3	Audit log successfully uploaded and deleted from device	63	0	55.18
04:53.4	Audit log successfully uploaded			
04:53.6	Audit log successfully uploaded and deleted from device	64	0	55.18

05:03.8	Audit log successfully uploaded			
05:03.9	Audit log successfully uploaded and deleted from device	64	0	55.18
05:11.1	Audit log successfully uploaded			
05:11.3	Audit log successfully uploaded and deleted from device	64	0	55.18
05:20.5	Audit log successfully uploaded			
05:20.7	Audit log successfully uploaded and deleted from device	64	0	55.18
05:23.8	Audit log successfully uploaded			
05:24.0	Audit log successfully uploaded and deleted from device	64	0	55.18
05:37.1	Audit log successfully uploaded			
05:37.2	Audit log successfully uploaded and deleted from device	64	0	55.18
05:56.4	Audit log successfully uploaded			
05:56.6	Audit log successfully uploaded and deleted from device	64	0	55.18
06:09.7	Audit log successfully uploaded			
06:09.9	Audit log successfully uploaded and deleted from device	64	0	55.18
06:21.0	Audit log successfully uploaded			
06:21.2	Audit log successfully uploaded and deleted from device	64	0	55.18
06:33.3	Audit log successfully uploaded			
06:33.5	Audit log successfully uploaded and deleted from device	65	0	55.18
06:49.7	Audit log successfully uploaded			
06:49.9	Audit log successfully uploaded and deleted from device	65	0	55.18
06:50.0	Audit log successfully uploaded			
06:50.2	Audit log successfully uploaded and deleted from device	65	0	55.18
07:16.4	Audit log successfully uploaded			
07:16.5	Audit log successfully uploaded and deleted from device	65	0	55.18
07:29.7	Audit log successfully uploaded			
07:29.9	Audit log successfully uploaded and deleted from device	65	0	55.18
07:42.1	Audit log successfully uploaded			
07:42.3	Audit log successfully uploaded and deleted from device	65	0	55.18
08:03.5	Audit log successfully uploaded			
08:03.7	Audit log successfully uploaded and deleted from device	65	0	55.18
08:04.8	Audit log successfully uploaded			
08:05.0	Audit log successfully uploaded and deleted from device	65	0	55.18
08:24.2	Audit log successfully uploaded			
08:24.3	Audit log successfully uploaded and deleted from device	65	0	55.18
08:48.5	Audit log successfully uploaded			
08:48.7	Audit log successfully uploaded and deleted from device	65	0	55.18
09:07.9	Audit log successfully uploaded			
09:08.0	Audit log successfully uploaded and deleted from device	66	0	55.18
09:12.3	Audit log successfully uploaded			
09:12.5	Audit log successfully uploaded and deleted from device	66	0	55.18
09:37.6	Audit log successfully uploaded			
09:37.8	Audit log successfully uploaded and deleted from device	66	0	55.18
09:46.1	Audit log successfully uploaded			
09:46.3	Audit log successfully uploaded and deleted from device	66	0	55.18
09:55.4	Audit log successfully uploaded			
09:55.6	Audit log successfully uploaded and deleted from device	66	0	55.18
10:06.8	Audit log successfully uploaded			

10:07.0	Audit log successfully uploaded and deleted from device	66	0	55.18	
10:25.1	Audit log successfully uploaded				
10:25.3	Audit log successfully uploaded and deleted from device	66	0	55.18	
10:51.4	Audit log successfully uploaded				
10:51.6	Audit log successfully uploaded and deleted from device	66	0	55.18	
31:37.7	Device disconnected from charger	77	0	55.184	
31:37.7	Camera disconnected from Axon Dock X62001W9H	77	0	55.184	
31:49.2	Volume up button pressed				
31:49.5	Volume up button released				
31:49.5	Volume changed to high from medium using button				
31:51.8	Volume down button pressed				
31:51.9	Volume down button released				
31:52.0	Volume changed to medium from high using button				
47:37.1	Event button pressed				
47:37.1	Event button released				
47:37.2	Event button pressed				
47:37.2	Audio recording enabled due to video recording default				
47:37.3	Event button released				
47:37.3	Recording started due to button press	75	1	55.197	8c8bc169c5a6494f9d056052801ad0d5
47:37.3	Event button pressed				
47:37.4	Event button released				
47:42.9	Event button pressed				
47:45.9	Recording stopped due to button press	75	1	55.178	8c8bc169c5a6494f9d056052801ad0d5
47:46.5	Event button released				
47:46.8	Audio recording disabled due to video buffering default				
48:16.2	Axon application connected to device				
48:35.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 0047 X6033271L' to 'Accidental Recording' using Axon applicator				8c8bc169c5a6494f9d056052801ad0d5
48:35.4	Categories 'Accidental Recording' added to video metadata using Axon applicator				8c8bc169c5a6494f9d056052801ad0d5
48:48.2	Axon application disconnected from device				
49:13.9	Audit log created	75	1	55.132	1.15.14
55:08.3	Event button pressed				
55:08.4	Event button released				
55:08.5	Event button pressed				
55:08.5	Audio recording enabled due to video recording default				
55:08.6	Event button released				
55:08.7	Recording started due to button press	74	2	55.131	29f5da8eaf0d423389b1b3766e2922e2
59:45.2	Event button pressed				
59:48.2	Recording stopped due to button press	73	2	54.923	29f5da8eaf0d423389b1b3766e2922e2
59:48.8	Event button released				
59:49.0	Audio recording disabled due to video buffering default				
59:58.4	Event button pressed				
59:58.6	Event button released				
59:58.6	Event button pressed				
59:58.7	Audio recording enabled due to video recording default				
59:58.7	Event button released				
59:58.8	Recording started due to button press	73	3	54.922	47c4c18b28fc4e63814ddb58d2562070
00:25.7	Event button pressed				

00:26.8	Event button released			
01:52.0	Event button pressed			
01:55.0	Recording stopped due to button press	73	3	54.856 47c4c18b28fc4e63814ddb58d2562070
01:55.9	Event button released			
01:56.0	Audio recording disabled due to video buffering default			
42:28.7	Axon application connected to device			
42:50.5	Categories 'Accidental Recording' removed from video metadata using Axon applicator			8c8bc169c5a6494f9d056052801ad0d5
42:59.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			8c8bc169c5a6494f9d056052801ad0d5
43:06.3	Title changed in video metadata from 'Accidental Recording' to 'Signal 75' using Axon applicator			8c8bc169c5a6494f9d056052801ad0d5
43:42.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 0055 X6033271L' to 'Signal 75' using Axon applicator			29f5da8eaf0d423389b1b3766e2922e2
43:42.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			29f5da8eaf0d423389b1b3766e2922e2
44:07.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 0059 X6033271L' to 'Signal 75' using Axon applicator			47c4c18b28fc4e63814ddb58d2562070
44:07.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			47c4c18b28fc4e63814ddb58d2562070
44:28.9	Axon application disconnected from device			
49:13.9	Audit log created	67	3 1.15.14	54.854
28:29.9	Camera connected to Axon Dock X630020W7	63	3	54.853
28:30.0	Audit log rolled	63	3	54.853
28:30.0	Audit log created	63	3 1.15.14	54.853
28:30.7	Device connected to charger	63	3	54.853
28:30.0	Audit log created	91	3 1.15.14	54.852
28:30.0	Audit log created	100	3 1.15.14	54.852
28:30.0	Audit log created	100	3 1.15.14	54.851
28:30.1	Audit log created	100	3 1.15.14	54.851
28:30.1	Audit log created	100	3 1.15.14	54.85
28:30.1	Audit log created	100	3 1.15.14	54.85
28:30.1	Audit log created	100	3 1.15.14	54.849
28:30.1	Audit log created	100	3 1.15.14	54.849
28:30.1	Audit log created	100	3 1.15.14	54.848
28:30.1	Audit log created	100	3 1.15.14	54.848
28:30.1	Audit log created	100	3 1.15.14	54.847
28:30.2	Audit log created	100	3 1.15.14	54.847
50:12.7	Device disconnected from charger	98	3	54.847
50:13.3	Camera disconnected from Axon Dock X630020W7	100	3	54.847
50:29.3	Power button pressed			
50:32.4	Device powered off using button	100	3	54.848
50:32.9	Power button released			
30:48.0	Audit log created		1.15.14	
30:48.1	Device powered on using button	100	3	54.847
30:50.1	Audio recording disabled due to video buffering default			
30:55.0	Event button pressed			
30:55.0	Event button released			
30:55.1	Event button pressed			
30:55.1	Audio recording enabled due to video recording default			
30:55.2	Event button released			
30:55.3	Recording started due to button press	100	4	54.847 c5a3af972e024939af12e3111b425a8d
31:27.0	Event button pressed			
31:27.2	Event button released			

31:27.3	Event button pressed			
31:27.4	Event button released			
31:29.8	Event button pressed			
31:32.8	Recording stopped due to button press	100	4	54.826 c5a3af972e024939af12e3111b425a8d
31:33.2	Event button released			
31:33.5	Audio recording disabled due to video buffering default			
31:41.7	Event button pressed			
31:41.8	Event button released			
31:41.9	Event button pressed			
31:41.9	Audio recording enabled due to video recording default			
31:42.0	Event button released			
31:42.0	Recording started due to button press	100	5	54.825 d6ff816e32a6451397a34b713c61ddc1
32:33.8	Event button pressed			
32:36.8	Recording stopped due to button press	99	5	54.792 d6ff816e32a6451397a34b713c61ddc1
32:37.2	Event button released			
32:37.6	Audio recording disabled due to video buffering default			
33:40.6	Event button pressed			
33:40.7	Event button released			
33:40.7	Event button pressed			
33:40.8	Audio recording enabled due to video recording default			
33:40.8	Event button released			
33:40.9	Recording started due to button press	99	6	54.792 50a02c087ae04cd6af740c073d71ba51
34:05.5	Event button pressed			
34:08.5	Recording stopped due to button press	99	6	54.746 50a02c087ae04cd6af740c073d71ba51
34:08.9	Event button released			
34:09.3	Audio recording disabled due to video buffering default			
36:47.7	Event button pressed			
36:47.8	Event button released			
36:47.8	Event button pressed			
36:47.9	Audio recording enabled due to video recording default			
36:47.9	Event button released			
36:48.0	Recording started due to button press	99	7	54.745 5f9e0b97ea0344869273d0a0f6848ecc
37:26.3	Event button pressed			
37:29.3	Recording stopped due to button press	98	7	54.663 5f9e0b97ea0344869273d0a0f6848ecc
37:29.7	Event button released			
37:30.0	Audio recording disabled due to video buffering default			
37:50.9	Event button pressed			
37:51.0	Event button released			
37:51.1	Event button pressed			
37:51.2	Audio recording enabled due to video recording default			
37:51.2	Event button released			
37:51.3	Recording started due to button press	98	8	54.662 f456848697eb4695b500065c98ff4124
38:39.7	Event button pressed			
38:42.7	Recording stopped due to button press	98	8	54.625 f456848697eb4695b500065c98ff4124
38:43.3	Event button released			
38:43.4	Audio recording disabled due to video buffering default			
39:01.3	Event button pressed			

39:01.4	Event button released			
39:01.4	Event button pressed			
39:01.5	Audio recording enabled due to video recording default			
39:01.5	Event button released			
39:01.6	Recording started due to button press	98	9	54.624 d752b6a3760049ae8fdee56abe081106
39:52.3	Event button pressed			
39:55.3	Recording stopped due to button press	97	9	54.587 d752b6a3760049ae8fdee56abe081106
39:55.8	Event button released			
39:56.1	Audio recording disabled due to video buffering default			
49:50.6	Event button pressed			
49:50.8	Event button released			
49:50.9	Event button pressed			
49:50.9	Audio recording enabled due to video recording default			
49:51.0	Event button released			
49:51.1	Recording started due to button press	96	10	54.586 86e0661f81184c599895260e8b1d9c32
50:28.1	Event button pressed			
50:28.2	Event button released			
50:28.3	Event button pressed			
50:28.4	Event button released			
50:28.9	Event button pressed			
50:31.9	Recording stopped due to button press	96	10	54.505 86e0661f81184c599895260e8b1d9c32
50:32.3	Event button released			
50:32.7	Audio recording disabled due to video buffering default			
51:13.5	Event button pressed			
51:13.6	Event button released			
51:13.7	Event button pressed			
51:13.7	Audio recording enabled due to video recording default			
51:13.8	Event button released			
51:13.8	Recording started due to button press	96	11	54.504 8bf55c23a3344398aeae00f26ea725d6
52:08.3	Event button pressed			
52:11.3	Recording stopped due to button press	96	11	54.453 8bf55c23a3344398aeae00f26ea725d6
52:11.8	Event button released			
52:12.0	Audio recording disabled due to video buffering default			
52:15.6	Event button pressed			
52:15.7	Event button released			
52:15.7	Event button pressed			
52:15.8	Audio recording enabled due to video recording default			
52:15.8	Event button released			
52:15.9	Recording started due to button press	96	12	54.452 246ee58c35bc4b1291b45fa3e3a55798
52:55.6	Event button pressed			
52:58.6	Recording stopped due to button press	96	12	54.429 246ee58c35bc4b1291b45fa3e3a55798
52:59.1	Event button released			
52:59.4	Audio recording disabled due to video buffering default			
59:04.5	Event button pressed			
59:04.7	Event button released			
59:04.8	Event button pressed			
59:04.8	Audio recording enabled due to video recording default			

59:05.0 Recording started due to button press	95	13	54.428 160733f992ce4957bd1bc32fa68cecaf
59:05.1 Event button released			
00:25.3 Event button pressed			
00:28.3 Recording stopped due to button press	94	13	54.324 160733f992ce4957bd1bc32fa68cecaf
00:29.0 Event button released			
00:29.3 Audio recording disabled due to video buffering default			
00:33.4 Event button pressed			
00:33.6 Event button released			
00:33.6 Event button pressed			
00:33.7 Audio recording enabled due to video recording default			
00:33.8 Event button released			
00:33.8 Recording started due to button press	94	14	54.323 67b66c75ad1a41f280398ae1728c565c
01:36.0 Event button pressed			
01:39.0 Recording stopped due to button press	94	14	54.288 67b66c75ad1a41f280398ae1728c565c
01:39.5 Event button released			
01:39.8 Audio recording disabled due to video buffering default			
02:08.7 Event button pressed			
02:08.8 Event button released			
02:08.9 Event button pressed			
02:08.9 Audio recording enabled due to video recording default			
02:09.0 Event button released			
02:09.1 Recording started due to button press	94	15	54.287 70c96cd13ff54312b4876fd28dd698a8
02:31.5 Event button pressed			
02:34.5 Recording stopped due to button press	94	15	54.259 70c96cd13ff54312b4876fd28dd698a8
02:34.9 Event button released			
02:35.2 Audio recording disabled due to video buffering default			
06:13.4 Event button pressed			
06:13.6 Event button released			
06:13.6 Event button pressed			
06:13.7 Audio recording enabled due to video recording default			
06:13.7 Event button released			
06:13.8 Recording started due to button press	94	16	54.258 c955164e5b674474baba56d531bf8788
09:04.2 Event button pressed			
09:07.2 Recording stopped due to button press	93	16	54.107 c955164e5b674474baba56d531bf8788
09:08.0 Audio recording disabled due to video buffering default			
09:08.1 Event button released			
11:49.7 Event button pressed			
11:49.9 Event button released			
11:49.9 Event button pressed			
11:49.9 Audio recording enabled due to video recording default			
11:50.0 Event button released			
11:50.1 Recording started due to button press	93	17	54.106 99d486e69a9f42c2894bfcd2997436df
12:44.0 Event button pressed			
12:47.0 Recording stopped due to button press	93	17	54.016 99d486e69a9f42c2894bfcd2997436df
12:47.5 Event button released			
12:48.0 Audio recording disabled due to video buffering default			
14:02.4 Axon application connected to device			

15:07.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1711 X6033271L' to 'Signal 75' using Axon applicator			99d486e69a9f42c2894bfcd2997436df
15:07.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			99d486e69a9f42c2894bfcd2997436df
15:31.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1706 X6033271L' to 'Signal 75' using Axon applicator			c955164e5b674474baba56d531bf8788
15:31.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			c955164e5b674474baba56d531bf8788
15:55.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1702 X6033271L' to 'Signal 75' using Axon applicator			70c96cd13ff54312b4876fd28dd698a8
15:55.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			70c96cd13ff54312b4876fd28dd698a8
16:32.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1700 X6033271L' to 'Signal 75' using Axon applicator			67b66c75ad1a41f280398ae1728c565c
16:32.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			67b66c75ad1a41f280398ae1728c565c
17:02.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1659 X6033271L' to 'Signal 75' using Axon applicator			160733f992ce4957bd1bc32fa68cecaf
17:02.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			160733f992ce4957bd1bc32fa68cecaf
17:22.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1652 X6033271L' to 'Signal 75' using Axon applicator			246ee58c35bc4b1291b45fa3e3a55798
17:22.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			246ee58c35bc4b1291b45fa3e3a55798
17:36.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1651 X6033271L' to 'Signal 75' using Axon applicator			8bf55c23a3344398aeae00f26ea725d6
17:36.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			8bf55c23a3344398aeae00f26ea725d6
17:54.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1649 X6033271L' to 'Signal 75' using Axon applicator			86e0661f81184c599895260e8b1d9c32
17:54.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			86e0661f81184c599895260e8b1d9c32
18:11.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1639 X6033271L' to 'Signal 75' using Axon applicator			d752b6a3760049ae8fdee56abe081106
18:11.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			d752b6a3760049ae8fdee56abe081106
18:25.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1637 X6033271L' to 'Signal 75' using Axon applicator			f456848697eb4695b500065c98ff4124
18:25.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			f456848697eb4695b500065c98ff4124
18:44.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1636 X6033271L' to 'Signal 75' using Axon applicator			5f9e0b97ea0344869273d0a0f6848ecc
18:44.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			5f9e0b97ea0344869273d0a0f6848ecc
19:04.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1633 X6033271L' to 'Signal 75' using Axon applicator			50a02c087ae04cd6af740c073d71ba51
19:04.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			50a02c087ae04cd6af740c073d71ba51
19:27.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1631 X6033271L' to 'Signal 75' using Axon applicator			d6ff816e32a6451397a34b713c61ddc1
19:27.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			d6ff816e32a6451397a34b713c61ddc1
19:58.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1630 X6033271L' to 'Signal 75' using Axon applicator			c5a3af972e024939af12e3111b425a8d
19:58.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			c5a3af972e024939af12e3111b425a8d
20:45.1	Event button pressed			
20:45.1	Event button released			
20:45.2	Event button pressed			
20:45.3	Audio recording enabled due to video recording default			
20:45.3	Event button released			
20:45.4	Recording started due to button press	92	18	54.013 9fc43b17f6a24097ba31b0dec58c8534
23:38.4	Event button pressed			
23:41.4	Recording stopped due to button press	91	18	53.861 9fc43b17f6a24097ba31b0dec58c8534
23:42.2	Audio recording disabled due to video buffering default			
23:42.4	Event button released			
28:01.8	Event button pressed			
28:02.0	Event button released			
28:02.0	Event button pressed			
28:02.0	Audio recording enabled due to video recording default			
28:02.2	Event button released			
28:02.2	Recording started due to button press	91	19	53.859 07ecab3af47d4b3ab18932272960625b
29:00.5	Event button pressed			
29:03.5	Recording stopped due to button press	90	19	53.767 07ecab3af47d4b3ab18932272960625b
29:04.0	Event button released			

29:04.2 Audio recording disabled due to video buffering default			
29:24.3 Event button pressed			
29:24.5 Event button released			
29:24.5 Event button pressed			
29:24.6 Audio recording enabled due to video recording default			
29:24.6 Event button released			
29:24.7 Recording started due to button press	90	20	53.766 157fd6fa35f24f298d937ce9ca89891d
30:24.0 Event button pressed			
30:27.0 Recording stopped due to button press	90	20	53.723 157fd6fa35f24f298d937ce9ca89891d
30:27.7 Event button released			
30:27.9 Audio recording disabled due to video buffering default			
30:48.1 Audit log created	90	20 1.15.14	53.722
31:10.4 Event button pressed			
31:10.5 Event button released			
31:10.5 Event button pressed			
31:10.6 Audio recording enabled due to video recording default			
31:10.6 Event button released			
31:10.7 Recording started due to button press	90	21	53.722 a2e17861034a47d5b68f2a3809abd98b
32:29.1 Event button pressed			
32:32.1 Recording stopped due to button press	90	21	53.658 a2e17861034a47d5b68f2a3809abd98b
32:32.7 Event button released			
32:32.8 Audio recording disabled due to video buffering default			
32:46.7 Event button pressed			
32:46.8 Event button released			
32:46.9 Event button pressed			
32:46.9 Audio recording enabled due to video recording default			
32:47.0 Event button released			
32:47.0 Recording started due to button press	90	22	53.657 8dec2abdf77d499d9d5444c924b64c9c
32:57.4 Event button pressed			
33:00.0 Event button released			
33:01.0 Event button pressed			
33:04.0 Recording stopped due to button press	90	22	53.642 8dec2abdf77d499d9d5444c924b64c9c
33:04.5 Event button released			
33:05.0 Audio recording disabled due to video buffering default			
33:07.8 Event button pressed			
33:07.9 Event button released			
33:08.0 Event button pressed			
33:08.0 Audio recording enabled due to video recording default			
33:08.1 Event button released			
33:08.1 Recording started due to button press	90	23	53.641 b9b3e26ac5884509bf4fb7065bf4dfea
33:22.9 Event button pressed			
33:25.9 Recording stopped due to button press	90	23	53.63 b9b3e26ac5884509bf4fb7065bf4dfea
33:26.5 Event button released			
33:26.8 Audio recording disabled due to video buffering default			
36:27.6 Event button pressed			
36:27.7 Event button released			
36:27.8 Event button pressed			

36:27.9	Audio recording enabled due to video recording default			
36:28.0	Event button released			
36:28.0	Recording started due to button press	89	24	53.629 0adc4c5a8c764e838521f3b28c3c4c8c
36:46.4	Event button pressed			
36:49.5	Recording stopped due to button press	89	24	53.58 0adc4c5a8c764e838521f3b28c3c4c8c
36:49.9	Event button released			
36:50.3	Audio recording disabled due to video buffering default			
36:52.3	Event button pressed			
36:52.4	Event button released			
36:52.5	Event button pressed			
36:52.5	Audio recording enabled due to video recording default			
36:52.6	Event button released			
36:52.6	Recording started due to button press	89	25	53.573 825c7f12d4f14c05ad36f6167b665de3
37:41.8	Event button pressed			
37:44.8	Recording stopped due to button press	89	25	53.529 825c7f12d4f14c05ad36f6167b665de3
37:45.4	Event button released			
37:45.7	Audio recording disabled due to video buffering default			
37:58.8	Event button pressed			
37:59.0	Event button released			
37:59.0	Event button pressed			
37:59.0	Audio recording enabled due to video recording default			
37:59.1	Event button released			
37:59.2	Recording started due to button press	89	26	53.528 3f707c3b50ca474d90ee80aa4aafdfa0
38:31.3	Event button pressed			
38:34.3	Recording stopped due to button press	89	26	53.503 3f707c3b50ca474d90ee80aa4aafdfa0
38:34.8	Event button released			
38:35.3	Audio recording disabled due to video buffering default			
38:43.3	Event button pressed			
38:43.4	Event button released			
38:43.5	Event button pressed			
38:43.5	Audio recording enabled due to video recording default			
38:43.6	Event button released			
38:43.7	Recording started due to button press	89	27	53.503 fb50db32bf46445293fb26ba02db1060
39:16.1	Event button pressed			
39:19.1	Recording stopped due to button press	89	27	53.48 fb50db32bf46445293fb26ba02db1060
39:19.6	Event button released			
39:19.8	Audio recording disabled due to video buffering default			
39:25.0	Event button pressed			
39:25.1	Event button released			
39:25.2	Event button pressed			
39:25.2	Audio recording enabled due to video recording default			
39:25.3	Event button released			
39:25.3	Recording started due to button press	89	28	53.48 a905d8b9ce0a4bab8cc241be3b13d631
40:39.8	Event button pressed			
40:42.8	Recording stopped due to button press	89	28	53.436 a905d8b9ce0a4bab8cc241be3b13d631
40:43.4	Event button released			
40:43.8	Audio recording disabled due to video buffering default			

41:41.7	Event button pressed			
41:41.8	Event button released			
41:41.9	Event button pressed			
41:41.9	Audio recording enabled due to video recording default			
41:42.0	Event button released			
41:42.1	Recording started due to button press	89	29	53.436 f157d93a683c4a73be0988a3fcb1c1f7
42:27.5	Event button pressed			
42:30.5	Recording stopped due to button press	88	29	53.381 f157d93a683c4a73be0988a3fcb1c1f7
42:30.9	Event button released			
42:31.2	Audio recording disabled due to video buffering default			
44:04.5	Event button pressed			
44:04.6	Event button released			
44:04.6	Event button pressed			
44:04.7	Audio recording enabled due to video recording default			
44:04.7	Event button released			
44:04.8	Recording started due to button press	88	30	53.38 e89bea022ec5479b993070fabd6d8a0e
44:34.7	Event button pressed			
44:37.7	Recording stopped due to button press	88	30	53.316 e89bea022ec5479b993070fabd6d8a0e
44:38.1	Event button released			
44:38.4	Audio recording disabled due to video buffering default			
44:40.7	Event button pressed			
44:40.8	Event button released			
44:40.8	Event button pressed			
44:40.8	Audio recording enabled due to video recording default			
44:40.9	Event button released			
44:41.0	Recording started due to button press	88	31	53.315 31943603961f4b6e9218a5bcffe799d5
45:08.1	Event button pressed			
45:11.1	Recording stopped due to button press	88	31	53.299 31943603961f4b6e9218a5bcffe799d5
45:11.7	Event button released			
45:12.0	Audio recording disabled due to video buffering default			
45:16.8	Event button pressed			
45:16.9	Event button released			
45:17.0	Event button pressed			
45:17.0	Audio recording enabled due to video recording default			
45:17.1	Event button released			
45:17.1	Recording started due to button press	88	32	53.298 95f7bb40f7d34e8088f4a1203b21be36
46:04.5	Event button pressed			
46:07.5	Recording stopped due to button press	88	32	53.269 95f7bb40f7d34e8088f4a1203b21be36
46:08.2	Audio recording disabled due to video buffering default			
46:08.2	Event button released			
46:45.4	Event button pressed			
46:45.6	Event button released			
46:45.6	Event button pressed			
46:45.7	Audio recording enabled due to video recording default			
46:45.7	Event button released			
46:45.8	Recording started due to button press	87	33	53.268 78d72be316314849aa797aac21f60d0f
47:42.7	Event button pressed			

47:45.7 Recording stopped due to button press	87	33	53.218 78d72be316314849aa797aac21f60d0f
47:46.2 Event button released			
47:46.5 Audio recording disabled due to video buffering default			
48:25.8 Event button pressed			
48:25.9 Event button released			
48:25.9 Event button pressed			
48:25.9 Audio recording enabled due to video recording default			
48:26.0 Event button released			
48:26.1 Recording started due to button press	87	34	53.218 45d157ef3a404829ba4be5870d5574a3
49:56.7 Event button pressed			
49:59.7 Recording stopped due to button press	87	34	53.149 45d157ef3a404829ba4be5870d5574a3
50:00.2 Event button released			
50:00.4 Audio recording disabled due to video buffering default			
50:36.4 Event button pressed			
50:36.5 Event button released			
50:36.5 Event button pressed			
50:36.5 Audio recording enabled due to video recording default			
50:36.6 Event button released			
50:36.7 Recording started due to button press	87	35	53.148 113da213298b47dc956a7c63779d13cb
50:36.7 Event button pressed			
50:36.7 Event button released			
51:26.6 Event button pressed			
51:29.6 Recording stopped due to button press	87	35	53.103 113da213298b47dc956a7c63779d13cb
51:30.1 Event button released			
51:30.3 Audio recording disabled due to video buffering default			
52:35.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1750 X6033271L' to 'Signal 75' using Axon applicator			113da213298b47dc956a7c63779d13cb
52:35.4 Categories 'Miscellaneous' added to video metadata using Axon applicator			113da213298b47dc956a7c63779d13cb
53:02.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1748 X6033271L' to 'Signal 75' using Axon applicator			45d157ef3a404829ba4be5870d5574a3
53:02.3 Categories 'Miscellaneous' added to video metadata using Axon applicator			45d157ef3a404829ba4be5870d5574a3
53:32.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1746 X6033271L' to 'Signal 75' using Axon applicator			78d72be316314849aa797aac21f60d0f
53:32.8 Categories 'Miscellaneous' added to video metadata using Axon applicator			78d72be316314849aa797aac21f60d0f
53:54.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1745 X6033271L' to 'Signal 75' using Axon applicator			95f7bb40f7d34e8088f4a1203b21be36
53:54.6 Categories 'Miscellaneous' added to video metadata using Axon applicator			95f7bb40f7d34e8088f4a1203b21be36
54:23.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1744 X6033271L' to 'Signal 75' using Axon applicator			31943603961f4b6e9218a5bcffe799d5
54:23.4 Categories 'Miscellaneous' added to video metadata using Axon applicator			31943603961f4b6e9218a5bcffe799d5
54:44.1 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1744 X6033271L' to 'Signal 75' using Axon applicator			e89bea022ec5479b993070fabd6d8a0e
54:44.1 Categories 'Miscellaneous' added to video metadata using Axon applicator			e89bea022ec5479b993070fabd6d8a0e
55:09.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1741 X6033271L' to 'Signal 75' using Axon applicator			f157d93a683c4a73be0988a3fcb1c1f7
55:09.3 Categories 'Miscellaneous' added to video metadata using Axon applicator			f157d93a683c4a73be0988a3fcb1c1f7
55:32.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1739 X6033271L' to 'Signal 75' using Axon applicator			a905d8b9ce0a4bab8cc241be3b13d631
55:32.9 Categories 'Miscellaneous' added to video metadata using Axon applicator			a905d8b9ce0a4bab8cc241be3b13d631
55:48.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1738 X6033271L' to 'Signal 75' using Axon applicator			fb50db32bf46445293fb26ba02db1060
55:48.2 Categories 'Miscellaneous' added to video metadata using Axon applicator			fb50db32bf46445293fb26ba02db1060
56:06.6 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1737 X6033271L' to 'Signal 75' using Axon applicator			3f707c3b50ca474d90ee80aa4aafdfa0
56:06.6 Categories 'Miscellaneous' added to video metadata using Axon applicator			3f707c3b50ca474d90ee80aa4aafdfa0
56:25.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1736 X6033271L' to 'Signal 75' using Axon applicator			825c7f12d4f14c05ad36f6167b665de3
56:25.4 Categories 'Miscellaneous' added to video metadata using Axon applicator			825c7f12d4f14c05ad36f6167b665de3

56:56.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1736 X6033271L' to 'Signal 75' using Axon applicator				0adc4c5a8c764e838521f3b28c3c4c8c
56:56.9 Categories 'Miscellaneous' added to video metadata using Axon applicator				0adc4c5a8c764e838521f3b28c3c4c8c
57:13.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1733 X6033271L' to 'Signal 75' using Axon applicator				b9b3e26ac5884509bf4fb7065bf4dfea
57:13.9 Categories 'Miscellaneous' added to video metadata using Axon applicator				b9b3e26ac5884509bf4fb7065bf4dfea
57:30.2 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1732 X6033271L' to 'Signal 75' using Axon applicator				8dec2abdf77d499d9d5444c924b64c9c
57:30.2 Categories 'Miscellaneous' added to video metadata using Axon applicator				8dec2abdf77d499d9d5444c924b64c9c
57:47.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1731 X6033271L' to 'Signal 75' using Axon applicator				a2e17861034a47d5b68f2a3809abd98b
57:47.0 Categories 'Miscellaneous' added to video metadata using Axon applicator				a2e17861034a47d5b68f2a3809abd98b
58:05.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1729 X6033271L' to 'Signal 75' using Axon applicator				157fd6fa35f24f298d937ce9ca89891d
58:05.0 Categories 'Miscellaneous' added to video metadata using Axon applicator				157fd6fa35f24f298d937ce9ca89891d
58:27.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1728 X6033271L' to 'Signal 75' using Axon applicator				07ecab3af47d4b3ab18932272960625b
58:27.8 Categories 'Miscellaneous' added to video metadata using Axon applicator				07ecab3af47d4b3ab18932272960625b
58:43.3 Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1720 X6033271L' to 'Signal 75' using Axon applicator				9fc43b17f6a24097ba31b0dec58c8534
58:43.3 Categories 'Miscellaneous' added to video metadata using Axon applicator				9fc43b17f6a24097ba31b0dec58c8534
06:36.6 Axon application disconnected from device				
13:29.9 Event button pressed				
13:30.0 Event button released				
13:30.1 Event button pressed				
13:30.1 Audio recording enabled due to video recording default				
13:30.1 Event button released				
13:30.2 Recording started due to button press	85	36		53.1 2d13ce4750074b1cb7a71aff69d73486
15:47.4 Event button pressed				
15:47.7 Event button released				
15:48.5 Event button pressed				
15:48.7 Event button released				
15:48.7 Event button pressed				
15:48.9 Event button released				
15:51.9 Event button pressed				
15:54.9 Recording stopped due to button press	84	36		52.964 2d13ce4750074b1cb7a71aff69d73486
15:55.4 Event button released				
15:55.6 Audio recording disabled due to video buffering default				
15:57.7 Event button pressed				
15:57.9 Event button released				
15:57.9 Event button pressed				
15:57.9 Audio recording enabled due to video recording default				
15:58.0 Event button released				
15:58.0 Recording started due to button press	84	37		52.963 dd9138493d5b494890ed33d11beeb2a
16:24.5 Event button pressed				
16:24.7 Event button released				
16:24.8 Event button pressed				
16:24.9 Event button released				
16:26.5 Event button pressed				
16:29.5 Recording stopped due to button press	84	37		52.946 dd9138493d5b494890ed33d11beeb2a
16:30.0 Event button released				
16:30.3 Audio recording disabled due to video buffering default				
30:48.1 Audit log created	83	37 1.15.14		52.945
41:17.1 Event button pressed				

41:17.2	Event button released			
41:17.3	Event button pressed			
41:17.4	Audio recording enabled due to video recording default			
41:17.4	Event button released			
41:17.5	Recording started due to button press	82	38	52.945 672654394e0e4377848e3c70f1b61399
56:18.0	Event button pressed			
56:21.0	Recording stopped due to button press	79	38	52.412 672654394e0e4377848e3c70f1b61399
56:21.6	Event button released			
56:21.9	Audio recording disabled due to video buffering default			
23:50.0	Event button pressed			
23:50.0	Event button released			
23:50.0	Event button pressed			
23:50.0	Audio recording enabled due to video recording default			
23:50.1	Event button released			
23:50.2	Recording started due to button press	77	39	52.409 7c1f56f3291c446ea7315773aa6d1c4c
24:15.1	Event button pressed			
24:18.1	Recording stopped due to button press	77	39	52.345 7c1f56f3291c446ea7315773aa6d1c4c
24:18.7	Event button released			
24:19.0	Audio recording disabled due to video buffering default			
24:23.6	Event button pressed			
24:23.7	Event button released			
24:23.8	Event button pressed			
24:23.8	Audio recording enabled due to video recording default			
24:23.9	Event button released			
24:24.0	Recording started due to button press	77	40	52.335 ee986bff62e449f88eef91d9851804d3
24:43.8	Event button pressed			
24:46.8	Recording stopped due to button press	77	40	52.319 ee986bff62e449f88eef91d9851804d3
24:47.3	Event button released			
24:47.6	Audio recording disabled due to video buffering default			
30:48.1	Audit log created	76	40 1.15.14	52.318
31:01.8	Event button pressed			
31:01.9	Event button released			
31:02.0	Event button pressed			
31:02.0	Audio recording enabled due to video recording default			
31:02.0	Event button released			
31:02.2	Recording started due to button press	76	41	52.318 5f7966f066fb4a619969713ba23a7906
31:45.4	Event button pressed			
31:48.4	Recording stopped due to button press	76	41	52.234 5f7966f066fb4a619969713ba23a7906
31:49.2	Audio recording disabled due to video buffering default			
31:49.5	Event button released			
32:26.0	Event button pressed			
32:26.2	Event button released			
32:26.2	Event button pressed			
32:26.3	Audio recording enabled due to video recording default			
32:26.3	Event button released			
32:26.4	Recording started due to button press	76	42	52.233 5c4e4ce05ec14e92853e2f74cc5922ad
33:18.1	Event button pressed			

33:21.1 Recording stopped due to button press	75	42	52.186 5c4e4ce05ec14e92853e2f74cc5922ad
33:21.6 Event button released			
33:22.1 Audio recording disabled due to video buffering default			
33:34.3 Power button pressed			
33:37.8 Device powered off using button	75	42	52.185
33:38.1 Power button released			
34:39.2 Device powered on using button	75	42	52.189
34:42.0 Audio recording disabled due to video buffering default			
34:46.4 Event button pressed			
34:46.5 Event button released			
34:46.6 Event button pressed			
34:46.6 Audio recording enabled due to video recording default			
34:46.6 Event button released			
34:46.8 Recording started due to button press	75	43	52.189 47aecb6a5ec440eea4793945d379104e
35:23.7 Event button pressed			
35:26.7 Recording stopped due to button press	75	43	52.166 47aecb6a5ec440eea4793945d379104e
35:27.1 Event button released			
35:27.4 Audio recording disabled due to video buffering default			
35:30.5 Event button pressed			
35:30.7 Event button released			
35:30.7 Event button pressed			
35:30.7 Audio recording enabled due to video recording default			
35:30.8 Event button released			
35:30.9 Recording started due to button press	75	44	52.165 f3882d1938654a239f708e9c2eb003e6
35:47.6 Event button pressed			
35:50.7 Recording stopped due to button press	75	44	52.154 f3882d1938654a239f708e9c2eb003e6
35:51.1 Event button released			
35:51.4 Audio recording disabled due to video buffering default			
36:03.8 Event button pressed			
36:04.0 Event button released			
36:04.0 Event button pressed			
36:04.1 Audio recording enabled due to video recording default			
36:04.1 Event button released			
36:04.2 Recording started due to button press	75	45	52.153 bb110b17c8414a18912123d21fba34cc
36:24.2 Event button pressed			
36:27.2 Recording stopped due to button press	75	45	52.135 bb110b17c8414a18912123d21fba34cc
36:27.8 Event button released			
36:28.2 Audio recording disabled due to video buffering default			
37:17.0 Event button pressed			
37:17.2 Event button released			
37:17.2 Event button pressed			
37:17.2 Audio recording enabled due to video recording default			
37:17.3 Event button released			
37:17.4 Recording started due to button press	75	46	52.134 b3c625cbea254adc90b01ab582f57703
37:55.2 Event button pressed			
37:58.2 Recording stopped due to button press	75	46	52.088 b3c625cbea254adc90b01ab582f57703
37:58.6 Event button released			

37:59.0	Audio recording disabled due to video buffering default			
38:14.3	Event button pressed			
38:14.4	Event button released			
38:14.5	Event button pressed			
38:14.5	Audio recording enabled due to video recording default			
38:14.6	Event button released			
38:14.7	Recording started due to button press	75	47	52.087 7b6d14dbb6d44ea88cfc18d94638f38d
39:14.0	Event button pressed			
39:17.0	Recording stopped due to button press	75	47	52.047 7b6d14dbb6d44ea88cfc18d94638f38d
39:17.5	Event button released			
39:17.9	Audio recording disabled due to video buffering default			
39:21.2	Event button pressed			
39:21.3	Event button released			
39:21.4	Event button pressed			
39:21.4	Audio recording enabled due to video recording default			
39:21.5	Event button released			
39:21.5	Recording started due to button press	75	48	52.046 3a74ef8bb4d5456694dfa373e026db61
39:56.2	Event button pressed			
39:59.3	Recording stopped due to button press	74	48	52.025 3a74ef8bb4d5456694dfa373e026db61
39:59.7	Event button released			
40:00.2	Audio recording disabled due to video buffering default			
41:49.1	Axon application connected to device			
42:34.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1813 X6033271L' to 'Signal 75' using Axon applicator			2d13ce4750074b1cb7a71aff69d73486
42:34.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			2d13ce4750074b1cb7a71aff69d73486
43:03.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1815 X6033271L' to 'Signal 75' using Axon applicator			dd9138493d5b4948906ed33d11beeb2a
43:03.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			dd9138493d5b4948906ed33d11beeb2a
43:43.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1939 X6033271L' to 'Signal 75' using Axon applicator			3a74ef8bb4d5456694dfa373e026db61
43:43.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			3a74ef8bb4d5456694dfa373e026db61
44:03.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1938 X6033271L' to 'Signal 75' using Axon applicator			7b6d14dbb6d44ea88cfc18d94638f38d
44:03.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			7b6d14dbb6d44ea88cfc18d94638f38d
44:20.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1937 X6033271L' to 'Signal 75' using Axon applicator			b3c625cbea254adc90b01ab582f57703
44:20.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			b3c625cbea254adc90b01ab582f57703
44:45.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1936 X6033271L' to 'Signal 75' using Axon applicator			bb110b17c8414a18912123d21fba34cc
44:45.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			bb110b17c8414a18912123d21fba34cc
45:09.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1935 X6033271L' to 'Signal 75' using Axon applicator			f3882d1938654a239f708e9c2eb003e6
45:09.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			f3882d1938654a239f708e9c2eb003e6
45:32.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1934 X6033271L' to 'Signal 75' using Axon applicator			47aecb6a5ec440eea4793945d379104e
45:32.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			47aecb6a5ec440eea4793945d379104e
47:32.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1932 X6033271L' to 'Signal 75' using Axon applicator			5c4e4ce05ec14e92853e2f74cc5922ad
47:32.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			5c4e4ce05ec14e92853e2f74cc5922ad
48:10.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1931 X6033271L' to 'Signal 75' using Axon applicator			5f7966f066fb4a619969713ba23a7906
48:10.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			5f7966f066fb4a619969713ba23a7906
48:47.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1924 X6033271L' to 'Signal 75' using Axon applicator			ee986bff62e449f88eef91d9851804d3
48:47.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			ee986bff62e449f88eef91d9851804d3
49:04.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1923 X6033271L' to 'Signal 75' using Axon applicator			7c1f56f3291c446ea7315773aa6d1c4c
49:04.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			7c1f56f3291c446ea7315773aa6d1c4c
49:22.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 1841 X6033271L' to 'Signal 75' using Axon applicator			672654394e0e4377848e3c70f1b61399

49:22.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			672654394e0e4377848e3c70f1b61399
49:41.4	Video played back using Axon application			672654394e0e4377848e3c70f1b61399
53:09.2	Video played back using Axon application			672654394e0e4377848e3c70f1b61399
53:57.9	Video played back using Axon application			672654394e0e4377848e3c70f1b61399
57:49.4	Title changed in video metadata from 'Signal 75' to 'Signal 43 Bus 2495 Route 126 Bl. 3' using Axon applicator			672654394e0e4377848e3c70f1b61399
57:49.4	Categories 'Auto Accident' added to video metadata using Axon applicator			672654394e0e4377848e3c70f1b61399
57:49.4	Categories 'Miscellaneous' removed from video metadata using Axon applicator			672654394e0e4377848e3c70f1b61399
03:31.8	Video played back using Axon application			99d486e69a9f42c2894bfcd2997436df
05:33.9	Video played back using Axon application			8c8bc169c5a6494f9d056052801ad0d5
10:25.2	Title changed in video metadata from 'Signal 75' to 'Signal 90/35, Code 23 By 3610' using Axon applicator			47c4c18b28fc4e63814ddb58d2562070
10:25.2	Categories 'Arrest', 'Criminal Trespass' added to video metadata using Axon applicator			47c4c18b28fc4e63814ddb58d2562070
10:25.2	Categories 'Miscellaneous' removed from video metadata using Axon applicator			47c4c18b28fc4e63814ddb58d2562070
14:55.8	Video played back using Axon application			d752b6a3760049ae8fdee56abe081106
16:01.2	Video played back using Axon application			86e0661f81184c599895260e8b1d9c32
16:48.0	Video played back using Axon application			8bf55c23a3344398aeae00f26ea725d6
18:15.1	Video played back using Axon application			67b66c75ad1a41f280398ae1728c565c
19:50.4	Video played back using Axon application			9fc43b17f6a24097ba31b0dec58c8534
20:08.8	Video played back using Axon application			07ecab3af47d4b3ab18932272960625b
21:30.6	Video played back using Axon application			0adc4c5a8c764e838521f3b28c3c4c8c
22:56.9	Video played back using Axon application			3f707c3b50ca474d90ee80aa4aafdfa0
26:18.6	Video played back using Axon application			113da213298b47dc956a7c63779d13cb
27:15.9	Video played back using Axon application			2d13ce4750074b1cb7a71aff69d73486
29:19.1	Video played back using Axon application			7c1f56f3291c446ea7315773aa6d1c4c
30:48.0	Audit log created	68	48 1.15.14	52.018
30:48.3	Video played back using Axon application			5f7966f066fb4a619969713ba23a7906
32:34.9	Video played back using Axon application			7b6d14dbb6d44ea88cfc18d94638f38d
33:20.1	Axon application disconnected from device			
30:48.1	Audit log created	62	48 1.15.14	52.017
23:53.7	Event button pressed			
23:53.8	Event button released			
23:53.9	Event button pressed			
23:54.0	Audio recording enabled due to video recording default			
23:54.0	Event button released			
23:54.1	Recording started due to button press	56	48	52.015 27003ad535c34f28879a1512e1b963cd
24:58.9	Event button pressed			
25:01.9	Recording stopped due to button press	56	49	51.919 27003ad535c34f28879a1512e1b963cd
25:02.4	Event button released			
25:02.7	Audio recording disabled due to video buffering default			
30:08.9	Event button pressed			
30:09.1	Event button released			
30:09.1	Event button pressed			
30:09.2	Audio recording enabled due to video recording default			
30:09.3	Event button released			
30:09.3	Recording started due to button press	55	50	51.918 6630d84236154f5b88a52739b35afde0
30:48.1	Audit log created	55	50 1.15.14	51.838
31:56.3	Event button pressed			
31:59.3	Recording stopped due to button press	54	50	51.8 6630d84236154f5b88a52739b35afde0

31:59.7	Event button released			
32:00.0	Audio recording disabled due to video buffering default			
32:03.6	Event button pressed			
32:03.8	Event button released			
32:03.8	Event button pressed			
32:03.9	Audio recording enabled due to video recording default			
32:04.0	Event button released			
32:04.0	Recording started due to button press	54	50	51.799 1e9c193cfcb84457bc2b065594e16357
32:20.0	Event button pressed			
32:23.0	Recording stopped due to button press	54	51	51.788 1e9c193cfcb84457bc2b065594e16357
32:23.5	Event button released			
32:23.8	Audio recording disabled due to video buffering default			
33:28.3	Event button pressed			
33:28.5	Event button released			
33:28.5	Event button pressed			
33:28.6	Audio recording enabled due to video recording default			
33:28.6	Event button released			
33:28.7	Recording started due to button press	54	52	51.787 19d21d29f53d4dc59234a9862da4a4ca
33:41.4	Event button pressed			
33:44.4	Recording stopped due to button press	54	52	51.752 19d21d29f53d4dc59234a9862da4a4ca
33:44.9	Event button released			
33:45.3	Audio recording disabled due to video buffering default			
33:50.9	Event button pressed			
33:51.0	Event button released			
33:51.1	Event button pressed			
33:51.1	Audio recording enabled due to video recording default			
33:51.2	Event button released			
33:51.2	Recording started due to button press	54	53	51.746 8f1369a1e41d43c2902f396d65d91f2a
34:15.5	Event button pressed			
34:18.5	Recording stopped due to button press	54	53	51.729 8f1369a1e41d43c2902f396d65d91f2a
34:19.0	Event button released			
34:19.3	Audio recording disabled due to video buffering default			
29:49.2	Volume up button pressed			
29:49.3	Volume up button released			
29:49.5	Volume changed to high from medium using button			
30:48.1	Audit log created	47	53 1.15.14	51.727
30:55.4	Axon application connected to device			
31:29.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 2230 X6033271L' to 'Signal 75' using Axon application			6630d84236154f5b88a52739b35afde0
31:29.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			6630d84236154f5b88a52739b35afde0
32:15.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 2223 X6033271L' to 'Signal 75' using Axon applicator			27003ad535c34f28879a1512e1b963cd
32:15.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			27003ad535c34f28879a1512e1b963cd
33:05.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 2232 X6033271L' to 'Signal 75' using Axon application			1e9c193cfcb84457bc2b065594e16357
33:05.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			1e9c193cfcb84457bc2b065594e16357
33:48.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 2233 X6033271L' to 'Signal 75' using Axon application			19d21d29f53d4dc59234a9862da4a4ca
33:48.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			19d21d29f53d4dc59234a9862da4a4ca
35:42.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-07 2233 X6033271L' to 'Signal 75' using Axon application			8f1369a1e41d43c2902f396d65d91f2a
35:42.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			8f1369a1e41d43c2902f396d65d91f2a

36:05.2 Camera connected to Axon Dock X62001W9H	47	53	51.747
36:05.2 Axon application disconnected from device			
36:05.2 Audit log created	47	53 1.15.14	51.726
36:05.3 Audit log rolled	47	53	51.726
36:06.2 Device connected to charger	47	53	51.726
36:19.5 Video upload started when camera was docked			8c8bc169c5a6494f9d056052801ad0d5
36:37.0 Date/Time synced to 09/07/2021 11:36:37.04 PM from 09/07/2021 11:36:35.27 PM			
36:39.8 Video successfully uploaded from device when docked			8c8bc169c5a6494f9d056052801ad0d5
36:40.0 Video deleted from device when docked	47	52	51.812 8c8bc169c5a6494f9d056052801ad0d5
36:40.0 Audit log created	47	52 1.15.14	51.812
36:40.1 Audit log rolled	47	52	51.812
36:40.4 Video upload started when camera was docked			29f5da8eaf0d423389b1b3766e2922e2
37:01.0 Audit log successfully uploaded			
37:01.1 Audit log successfully uploaded and deleted from device	47	52	51.812
37:17.3 Audit log successfully uploaded			
37:17.5 Audit log successfully uploaded and deleted from device	47	52	51.812
37:38.6 Audit log successfully uploaded			
37:38.8 Audit log successfully uploaded and deleted from device	47	52	51.812
37:39.9 Video successfully uploaded from device when docked			29f5da8eaf0d423389b1b3766e2922e2
37:40.3 Video deleted from device when docked	47	51	52.02 29f5da8eaf0d423389b1b3766e2922e2
37:40.3 Audit log rolled	47	51	52.02
37:40.3 Audit log created	47	51 1.15.14	52.02
37:40.7 Video upload started when camera was docked			47c4c18b28fc4e63814ddb58d2562070
37:56.9 Audit log successfully uploaded			
37:57.2 Audit log successfully uploaded and deleted from device	48	51	52.02
38:00.4 Video successfully uploaded from device when docked			47c4c18b28fc4e63814ddb58d2562070
38:00.6 Video deleted from device when docked	48	50	52.086 47c4c18b28fc4e63814ddb58d2562070
38:00.6 Audit log rolled	48	50	52.086
38:00.6 Audit log created	48	50 1.15.14	52.086
38:01.0 Video upload started when camera was docked			c5a3af972e024939af12e3111b425a8d
38:07.6 Video successfully uploaded from device when docked			c5a3af972e024939af12e3111b425a8d
38:07.8 Video deleted from device when docked	48	49	52.108 c5a3af972e024939af12e3111b425a8d
38:07.9 Audit log created	48	49 1.15.14	52.108
38:07.9 Audit log rolled	48	49	52.108
38:08.1 Video upload started when camera was docked			d6ff816e32a6451397a34b713c61ddc1
38:14.4 Audit log successfully uploaded			
38:14.6 Audit log successfully uploaded and deleted from device	48	49	52.108
38:17.5 Video successfully uploaded from device when docked			d6ff816e32a6451397a34b713c61ddc1
38:17.7 Video deleted from device when docked	48	48	52.141 d6ff816e32a6451397a34b713c61ddc1
38:17.7 Audit log rolled	48	48	52.141
38:17.7 Audit log created	48	48 1.15.14	52.141
38:18.1 Video upload started when camera was docked			50a02c087ae04cd6af740c073d71ba51
38:31.1 Video successfully uploaded from device when docked			50a02c087ae04cd6af740c073d71ba51
38:31.3 Video deleted from device when docked	48	47	52.187 50a02c087ae04cd6af740c073d71ba51
38:31.4 Audit log created	48	47 1.15.14	52.187
38:31.4 Audit log rolled	48	47	52.187
38:31.6 Video upload started when camera was docked			5f9e0b97ea0344869273d0a0f6848ecc

38:39.7	Audit log successfully uploaded			
38:39.9	Audit log successfully uploaded and deleted from device	48	47	52.187
38:54.0	Audit log successfully uploaded			
38:54.2	Audit log successfully uploaded and deleted from device	48	47	52.187
38:55.7	Video successfully uploaded from device when dockec			5f9e0b97ea0344869273d0a0f6848ecc
38:55.9	Video deleted from device when docked	48	46	52.269 5f9e0b97ea0344869273d0a0f6848ecc
38:56.0	Audit log rolled	48	46	52.269
38:56.0	Audit log created	48	46 1.15.14	52.269
38:56.2	Video upload started when camera was docked			f456848697eb4695b500065c98ff4124
39:02.3	Audit log successfully uploaded			
39:02.4	Audit log successfully uploaded and deleted from device	48	46	52.269
39:07.6	Video successfully uploaded from device when dockec			f456848697eb4695b500065c98ff4124
39:07.8	Video deleted from device when docked	48	45	52.307 f456848697eb4695b500065c98ff4124
39:07.9	Audit log created	48	45 1.15.14	52.307
39:07.9	Audit log rolled	48	45	52.307
39:08.1	Video upload started when camera was docked			d752b6a3760049ae8fdee56abe081106
39:16.6	Audit log successfully uploaded			
39:16.8	Audit log successfully uploaded and deleted from device	48	45	52.307
39:19.0	Video successfully uploaded from device when dockec			d752b6a3760049ae8fdee56abe081106
39:19.2	Video deleted from device when docked	48	44	52.344 d752b6a3760049ae8fdee56abe081106
39:19.2	Audit log rolled	48	44	52.344
39:19.2	Audit log created	48	44 1.15.14	52.344
39:19.5	Video upload started when camera was docked			86e0661f81184c599895260e8b1d9c32
39:23.9	Audit log successfully uploaded			
39:24.1	Audit log successfully uploaded and deleted from device	48	44	52.344
39:26.3	Audit log successfully uploaded			
39:26.6	Audit log successfully uploaded and deleted from device	48	44	52.344
39:43.6	Video successfully uploaded from device when dockec			86e0661f81184c599895260e8b1d9c32
39:43.7	Video deleted from device when docked	49	43	52.426 86e0661f81184c599895260e8b1d9c32
39:43.8	Audit log successfully uploaded			
39:43.8	Audit log rolled	49	43	52.426
39:43.8	Audit log created	49	43 1.15.14	52.426
39:44.0	Audit log successfully uploaded and deleted from device	49	43	52.426
39:44.0	Video upload started when camera was docked			8bf55c23a3344398aeae00f26ea725d6
39:49.1	Audit log successfully uploaded			
39:49.3	Audit log successfully uploaded and deleted from device	49	43	52.426
39:56.5	Audit log successfully uploaded			
39:56.7	Audit log successfully uploaded and deleted from device	49	43	52.426
39:57.8	Audit log successfully uploaded			
39:58.1	Audit log successfully uploaded and deleted from device	49	43	52.426
39:59.2	Video successfully uploaded from device when dockec			8bf55c23a3344398aeae00f26ea725d6
39:59.4	Video deleted from device when docked	49	42	52.477 8bf55c23a3344398aeae00f26ea725d6
39:59.5	Audit log rolled	49	42	52.477
39:59.5	Audit log created	49	42 1.15.14	52.477
39:59.7	Video upload started when camera was docked			246ee58c35bc4b1291b45fa3e3a55798
40:07.5	Video successfully uploaded from device when dockec			246ee58c35bc4b1291b45fa3e3a55798
40:07.8	Video deleted from device when docked	49	41	52.501 246ee58c35bc4b1291b45fa3e3a55798

40:07.8	Audit log created	49	41 1.15.14	52.501	
40:07.8	Audit log rolled	49	41	52.501	
40:08.0	Video upload started when camera was docked				160733f992ce4957bd1bc32fa68cecaf
40:14.2	Audit log successfully uploaded				
40:14.4	Audit log successfully uploaded and deleted from device	49	41	52.501	
40:14.5	Audit log successfully uploaded				
40:14.7	Audit log successfully uploaded and deleted from device	49	41	52.501	
40:20.8	Audit log successfully uploaded				
40:21.0	Audit log successfully uploaded and deleted from device	49	41	52.501	
40:34.1	Audit log successfully uploaded				
40:34.4	Audit log successfully uploaded and deleted from device	49	41	52.501	
40:38.7	Video successfully uploaded from device when docked				160733f992ce4957bd1bc32fa68cecaf
40:38.9	Video deleted from device when docked	49	40	52.605	160733f992ce4957bd1bc32fa68cecaf
40:38.9	Audit log rolled	49	40	52.605	
40:38.9	Audit log created	49	40 1.15.14	52.605	
40:39.2	Video upload started when camera was docked				67b66c75ad1a41f280398ae1728c565c
40:50.6	Video successfully uploaded from device when docked				67b66c75ad1a41f280398ae1728c565c
40:50.8	Video deleted from device when docked	49	39	52.641	67b66c75ad1a41f280398ae1728c565c
40:50.9	Audit log rolled	49	39	52.641	
40:50.9	Audit log created	49	39 1.15.14	52.641	
40:51.1	Video upload started when camera was docked				70c96cd13ff54312b4876fd28dd698a8
40:54.5	Audit log successfully uploaded				
40:54.6	Audit log successfully uploaded and deleted from device	49	39	52.641	
41:00.1	Video successfully uploaded from device when docked				70c96cd13ff54312b4876fd28dd698a8
41:00.3	Video deleted from device when docked	49	38	52.669	70c96cd13ff54312b4876fd28dd698a8
41:00.4	Audit log rolled	49	38	52.669	
41:00.4	Audit log created	49	38 1.15.14	52.669	
41:00.7	Video upload started when camera was docked				c955164e5b674474baba56d531bf8788
41:22.8	Audit log successfully uploaded				
41:22.9	Audit log successfully uploaded and deleted from device	49	38	52.669	
41:42.1	Audit log successfully uploaded				
41:42.3	Audit log successfully uploaded and deleted from device	49	38	52.669	
41:43.1	Video successfully uploaded from device when docked				c955164e5b674474baba56d531bf8788
41:43.4	Video deleted from device when docked	49	37	52.82	c955164e5b674474baba56d531bf8788
41:43.5	Audit log rolled	49	37	52.82	
41:43.5	Audit log created	49	37 1.15.14	52.82	
41:43.7	Video upload started when camera was docked				99d486e69a9f42c2894bfcd2997436df
41:57.4	Audit log successfully uploaded				
41:57.6	Audit log successfully uploaded and deleted from device	49	37	52.82	
42:07.7	Audit log successfully uploaded				
42:08.0	Audit log successfully uploaded and deleted from device	49	37	52.82	
42:10.3	Video successfully uploaded from device when docked				99d486e69a9f42c2894bfcd2997436df
42:10.5	Video deleted from device when docked	49	36	52.91	99d486e69a9f42c2894bfcd2997436df
42:10.6	Audit log rolled	49	36	52.91	
42:10.6	Audit log created	49	36 1.15.14	52.91	
42:11.0	Video upload started when camera was docked				9fc43b17f6a24097ba31b0dec58c8534
42:23.1	Audit log successfully uploaded				

42:23.2	Audit log successfully uploaded and deleted from device	50	36	52.91	
42:47.4	Audit log successfully uploaded				
42:47.6	Audit log successfully uploaded and deleted from device	50	36	52.91	
42:53.2	Video successfully uploaded from device when dockec				9fc43b17f6a24097ba31b0dec58c8534
42:53.4	Video deleted from device when docked	50	35	53.063	9fc43b17f6a24097ba31b0dec58c8534
42:53.5	Audit log rolled	50	35	53.063	
42:53.5	Audit log created	50	35	53.063	
42:53.7	Video upload started when camera was docked				07ecab3af47d4b3ab18932272960625b
43:06.7	Audit log successfully uploaded				
43:06.9	Audit log successfully uploaded and deleted from device	50	35	53.062	
43:10.0	Audit log successfully uploaded				
43:10.2	Audit log successfully uploaded and deleted from device	50	35	53.062	
43:18.0	Video successfully uploaded from device when dockec				07ecab3af47d4b3ab18932272960625b
43:18.2	Video deleted from device when docked	50	34	53.155	07ecab3af47d4b3ab18932272960625b
43:18.3	Audit log created	50	34	53.155	
43:18.3	Audit log rolled	50	34	53.155	
43:18.7	Video upload started when camera was docked				157fd6fa35f24f298d937ce9ca89891d
43:19.3	Audit log successfully uploaded				
43:19.5	Audit log successfully uploaded and deleted from device	50	34	53.155	
43:31.2	Video successfully uploaded from device when dockec				157fd6fa35f24f298d937ce9ca89891d
43:31.4	Video deleted from device when docked	50	33	53.198	157fd6fa35f24f298d937ce9ca89891d
43:31.4	Audit log created	50	33	53.198	
43:31.4	Audit log rolled	50	33	53.198	
43:31.7	Video upload started when camera was docked				a2e17861034a47d5b68f2a3809abd98b
43:35.6	Audit log successfully uploaded				
43:35.8	Audit log successfully uploaded and deleted from device	50	33	53.198	
43:37.9	Audit log successfully uploaded				
43:38.1	Audit log successfully uploaded and deleted from device	50	33	53.198	
43:50.8	Video successfully uploaded from device when dockec				a2e17861034a47d5b68f2a3809abd98b
43:51.0	Video deleted from device when docked	50	32	53.262	a2e17861034a47d5b68f2a3809abd98b
43:51.1	Audit log created	50	32	53.262	
43:51.1	Audit log rolled	50	32	53.262	
43:51.4	Video upload started when camera was docked				8dec2abdf77d499d9d5444c924b64c9c
43:56.3	Video successfully uploaded from device when dockec				8dec2abdf77d499d9d5444c924b64c9c
43:56.5	Video deleted from device when docked	50	31	53.278	8dec2abdf77d499d9d5444c924b64c9c
43:56.6	Audit log created	50	31	53.278	
43:56.6	Audit log rolled	50	31	53.278	
43:56.8	Video upload started when camera was docked				b9b3e26ac5884509bf4fb7065bf4dfea
44:00.9	Video successfully uploaded from device when dockec				b9b3e26ac5884509bf4fb7065bf4dfea
44:01.1	Video deleted from device when docked	50	30	53.289	b9b3e26ac5884509bf4fb7065bf4dfea
44:01.1	Audit log rolled	50	30	53.289	
44:01.1	Audit log created	50	30	53.289	
44:01.3	Video upload started when camera was docked				0adc4c5a8c764e838521f3b28c3c4c8c
44:07.3	Audit log successfully uploaded				
44:07.5	Audit log successfully uploaded and deleted from device	51	30	53.289	
44:21.0	Video successfully uploaded from device when dockec				0adc4c5a8c764e838521f3b28c3c4c8c
44:21.2	Video deleted from device when docked	51	29	53.361	0adc4c5a8c764e838521f3b28c3c4c8c

44:21.3	Audit log rolled	51	29	53.361	
44:21.3	Audit log created	51	29 1.15.14	53.361	
44:21.7	Video upload started when camera was docked				825c7f12d4f14c05ad36f6167b665de3
44:30.2	Video successfully uploaded from device when dockec				825c7f12d4f14c05ad36f6167b665de3
44:30.4	Video deleted from device when docked	51	28	53.389	825c7f12d4f14c05ad36f6167b665de3
44:30.4	Audit log created	51	28 1.15.14	53.389	
44:30.4	Audit log rolled	51	28	53.389	
44:30.6	Audit log successfully uploaded				
44:30.7	Video upload started when camera was docked				3f707c3b50ca474d90ee80aa4aafdfa0
44:30.8	Audit log successfully uploaded and deleted from device	51	28	53.389	
44:37.6	Video successfully uploaded from device when dockec				3f707c3b50ca474d90ee80aa4aafdfa0
44:37.8	Video deleted from device when docked	51	27	53.414	3f707c3b50ca474d90ee80aa4aafdfa0
44:37.8	Audit log rolled	51	27	53.414	
44:37.8	Audit log created	51	27 1.15.14	53.414	
44:38.0	Video upload started when camera was docked				fb50db32bf46445293fb26ba02db1060
44:44.8	Video successfully uploaded from device when dockec				fb50db32bf46445293fb26ba02db1060
44:45.1	Video deleted from device when docked	51	26	53.437	fb50db32bf46445293fb26ba02db1060
44:45.1	Audit log rolled	51	26	53.437	
44:45.1	Audit log created	51	26 1.15.14	53.437	
44:45.3	Video upload started when camera was docked				a905d8b9ce0a4bab8cc241be3b13d631
44:56.9	Audit log successfully uploaded				
44:57.1	Audit log successfully uploaded and deleted from device	51	26	53.437	
44:58.4	Video successfully uploaded from device when dockec				a905d8b9ce0a4bab8cc241be3b13d631
44:58.6	Video deleted from device when docked	51	25	53.48	a905d8b9ce0a4bab8cc241be3b13d631
44:58.7	Audit log rolled	51	25	53.481	
44:58.7	Audit log created	51	25 1.15.14	53.481	
44:58.8	Video upload started when camera was docked				f157d93a683c4a73be0988a3fcb1c1f7
45:14.8	Video successfully uploaded from device when dockec				f157d93a683c4a73be0988a3fcb1c1f7
45:15.0	Video deleted from device when docked	51	24	53.535	f157d93a683c4a73be0988a3fcb1c1f7
45:15.0	Audit log rolled	51	24	53.535	
45:15.0	Audit log created	51	24 1.15.14	53.535	
45:15.2	Video upload started when camera was docked				e89bea022ec5479b993070fabd6d8a0e
45:22.3	Audit log successfully uploaded				
45:22.4	Audit log successfully uploaded and deleted from device	51	24	53.535	
45:33.0	Video successfully uploaded from device when dockec				e89bea022ec5479b993070fabd6d8a0e
45:33.2	Video deleted from device when docked	51	23	53.6	e89bea022ec5479b993070fabd6d8a0e
45:33.3	Audit log rolled	51	23	53.6	
45:33.3	Audit log created	51	23 1.15.14	53.6	
45:33.5	Video upload started when camera was docked				31943603961f4b6e9218a5bcffe799d5
45:38.4	Video successfully uploaded from device when dockec				31943603961f4b6e9218a5bcffe799d5
45:38.6	Video deleted from device when docked	51	22	53.617	31943603961f4b6e9218a5bcffe799d5
45:38.7	Audit log rolled	51	22	53.617	
45:38.7	Audit log created	51	22 1.15.14	53.617	
45:38.8	Video upload started when camera was docked				95f7bb40f7d34e8088f4a1203b21be36
45:47.6	Audit log successfully uploaded				
45:47.8	Audit log successfully uploaded and deleted from device	51	22	53.617	
45:47.8	Video successfully uploaded from device when dockec				95f7bb40f7d34e8088f4a1203b21be36

45:48.0 Video deleted from device when docked	51	21	53.646	95f7bb40f7d34e8088f4a1203b21be36
45:48.1 Audit log rolled	51	21	53.646	
45:48.1 Audit log created	51	21 1.15.14	53.646	
45:48.3 Video upload started when camera was docked				78d72be316314849aa797aac21f60d0f
46:02.8 Video successfully uploaded from device when docked				78d72be316314849aa797aac21f60d0f
46:02.9 Audit log successfully uploaded				
46:03.0 Video deleted from device when docked	51	20	53.696	78d72be316314849aa797aac21f60d0f
46:03.1 Audit log created	51	20 1.15.14	53.696	
46:03.1 Audit log rolled	51	20	53.696	
46:03.1 Audit log successfully uploaded and deleted from device	51	20	53.696	
46:03.3 Video upload started when camera was docked				45d157ef3a404829ba4be5870d5574a3
46:22.3 Video successfully uploaded from device when docked				45d157ef3a404829ba4be5870d5574a3
46:22.5 Video deleted from device when docked	51	19	53.765	45d157ef3a404829ba4be5870d5574a3
46:22.6 Audit log rolled	51	19	53.765	
46:22.6 Audit log created	51	19 1.15.14	53.765	
46:22.8 Video upload started when camera was docked				113da213298b47dc956a7c63779d13cb
46:25.2 Audit log successfully uploaded				
46:25.4 Audit log successfully uploaded and deleted from device	51	19	53.765	
46:28.5 Audit log successfully uploaded				
46:28.7 Audit log successfully uploaded and deleted from device	51	19	53.765	
46:35.2 Video successfully uploaded from device when docked				113da213298b47dc956a7c63779d13cb
46:35.3 Video deleted from device when docked	51	18	53.811	113da213298b47dc956a7c63779d13cb
46:35.4 Audit log rolled	51	18	53.811	
46:35.4 Audit log created	51	18 1.15.14	53.811	
46:35.6 Video upload started when camera was docked				2d13ce4750074b1cb7a71aff69d73486
46:53.9 Audit log successfully uploaded				
46:54.0 Audit log successfully uploaded and deleted from device	52	18	53.811	
47:07.5 Audit log successfully uploaded				
47:07.6 Audit log successfully uploaded and deleted from device	52	18	53.811	
47:12.3 Video successfully uploaded from device when docked				2d13ce4750074b1cb7a71aff69d73486
47:12.5 Video deleted from device when docked	52	17	53.947	2d13ce4750074b1cb7a71aff69d73486
47:12.6 Audit log rolled	52	17	53.947	
47:12.6 Audit log created	52	17 1.15.14	53.947	
47:12.8 Video upload started when camera was docked				dd9138493d5b4948906ed33d11beeb2a
47:17.7 Audit log successfully uploaded				
47:17.9 Audit log successfully uploaded and deleted from device	52	17	53.947	
47:18.4 Video successfully uploaded from device when docked				dd9138493d5b4948906ed33d11beeb2a
47:18.5 Video deleted from device when docked	52	16	53.965	dd9138493d5b4948906ed33d11beeb2a
47:18.6 Audit log rolled	52	16	53.965	
47:18.6 Audit log created	52	16 1.15.14	53.965	
47:18.8 Video upload started when camera was docked				672654394e0e4377848e3c70f1b61399
47:38.0 Audit log successfully uploaded				
47:38.2 Audit log successfully uploaded and deleted from device	52	16	53.965	
48:05.3 Audit log successfully uploaded				
48:05.5 Audit log successfully uploaded and deleted from device	52	16	53.965	
48:28.6 Audit log successfully uploaded				
48:28.8 Audit log successfully uploaded and deleted from device	53	16	53.965	

48:32.0	Audit log successfully uploaded			
48:32.2	Audit log successfully uploaded and deleted from device	53	16	53.965
48:42.3	Audit log successfully uploaded			
48:42.5	Audit log successfully uploaded and deleted from device	53	16	53.965
49:01.7	Audit log successfully uploaded			
49:01.9	Audit log successfully uploaded and deleted from device	53	16	53.965
49:09.1	Audit log successfully uploaded			
49:09.2	Audit log successfully uploaded and deleted from device	53	16	53.965
49:31.3	Audit log successfully uploaded			
49:31.5	Audit log successfully uploaded and deleted from device	53	16	53.965
49:40.6	Audit log successfully uploaded			
49:40.8	Audit log successfully uploaded and deleted from device	53	16	53.965
49:49.3	Video successfully uploaded from device when dockec			672654394e0e4377848e3c70f1b61399
49:49.7	Video deleted from device when docked	53	15	54.498 672654394e0e4377848e3c70f1b61399
49:49.7	Audit log created	53	15 1.15.14	54.498
49:49.7	Audit log rolled	53	15	54.498
49:49.9	Audit log successfully uploaded			
49:50.1	Audit log successfully uploaded and deleted from device	53	15	54.498
49:50.3	Video upload started when camera was docked			7c1f56f3291c446ea7315773aa6d1c4c
49:59.3	Audit log successfully uploaded			
49:59.5	Audit log successfully uploaded and deleted from device	53	15	54.498
50:11.3	Video successfully uploaded from device when dockec			7c1f56f3291c446ea7315773aa6d1c4c
50:11.6	Video deleted from device when docked	53	14	54.573 7c1f56f3291c446ea7315773aa6d1c4c
50:11.6	Audit log rolled	53	14	54.573
50:11.6	Audit log created	53	14 1.15.14	54.573
50:11.9	Video upload started when camera was docked			ee986bff62e449f88eef91d9851804d3
50:14.7	Audit log successfully uploaded			
50:14.9	Audit log successfully uploaded and deleted from device	53	14	54.573
50:16.9	Video successfully uploaded from device when dockec			ee986bff62e449f88eef91d9851804d3
50:17.2	Video deleted from device when docked	53	13	54.588 ee986bff62e449f88eef91d9851804d3
50:17.2	Audit log rolled	53	13	54.588
50:17.2	Audit log created	53	13 1.15.14	54.588
50:17.6	Video upload started when camera was docked			5f7966f066fb4a619969713ba23a7906
50:35.1	Audit log successfully uploaded			
50:35.3	Audit log successfully uploaded and deleted from device	53	13	54.588
50:42.0	Video successfully uploaded from device when dockec			5f7966f066fb4a619969713ba23a7906
50:42.2	Video deleted from device when docked	53	12	54.673 5f7966f066fb4a619969713ba23a7906
50:42.3	Audit log created	53	12 1.15.14	54.673
50:42.3	Audit log rolled	53	12	54.673
50:42.5	Video upload started when camera was docked			5c4e4ce05ec14e92853e2f74cc5922ad
50:47.4	Audit log successfully uploaded			
50:47.6	Audit log successfully uploaded and deleted from device	53	12	54.673
50:55.7	Video successfully uploaded from device when dockec			5c4e4ce05ec14e92853e2f74cc5922ad
50:55.9	Video deleted from device when docked	54	11	54.72 5c4e4ce05ec14e92853e2f74cc5922ad
50:56.0	Audit log rolled	54	11	54.72
50:56.0	Audit log created	54	11 1.15.14	54.72
50:56.2	Video upload started when camera was docked			47aecb6a5ec440eea4793945d379104e

50:56.7	Audit log successfully uploaded				
50:56.9	Audit log successfully uploaded and deleted from device	54	11	54.72	
51:04.2	Video successfully uploaded from device when docked				47aecb6a5ec440eea4793945d379104e
51:04.4	Video deleted from device when docked	54	10	54.743	47aecb6a5ec440eea4793945d379104e
51:04.5	Audit log rolled	54	10	54.743	
51:04.5	Audit log created	54	10	1.15.14	54.743
51:05.0	Video upload started when camera was docked				f3882d1938654a239f708e9c2eb003e6
51:09.1	Video successfully uploaded from device when docked				f3882d1938654a239f708e9c2eb003e6
51:09.3	Video deleted from device when docked	54	9	54.755	f3882d1938654a239f708e9c2eb003e6
51:09.3	Audit log created	54	9	1.15.14	54.756
51:09.3	Audit log rolled	54	9		54.756
51:09.5	Video upload started when camera was docked				bb110b17c8414a18912123d21fba34cc
51:15.0	Video successfully uploaded from device when docked				bb110b17c8414a18912123d21fba34cc
51:15.2	Video deleted from device when docked	54	8	54.774	bb110b17c8414a18912123d21fba34cc
51:15.2	Audit log created	54	8	1.15.14	54.776
51:15.2	Audit log rolled	54	8		54.776
51:15.4	Video upload started when camera was docked				b3c625cbea254adc90b01ab582f57703
51:20.0	Audit log successfully uploaded				
51:20.2	Audit log successfully uploaded and deleted from device	54	8	54.776	
51:29.0	Video successfully uploaded from device when docked				b3c625cbea254adc90b01ab582f57703
51:29.3	Video deleted from device when docked	54	7	54.822	b3c625cbea254adc90b01ab582f57703
51:29.3	Audit log rolled	54	7		54.823
51:29.3	Audit log created	54	7	1.15.14	54.823
51:29.5	Video upload started when camera was docked				7b6d14dbb6d44ea88cfc18d94638f38d
51:40.9	Video successfully uploaded from device when docked				7b6d14dbb6d44ea88cfc18d94638f38d
51:41.1	Video deleted from device when docked	54	6	54.863	7b6d14dbb6d44ea88cfc18d94638f38d
51:41.2	Audit log rolled	54	6		54.864
51:41.2	Audit log created	54	6	1.15.14	54.864
51:41.3	Video upload started when camera was docked				3a74ef8bb4d5456694dfa373e026db61
51:48.4	Video successfully uploaded from device when docked				3a74ef8bb4d5456694dfa373e026db61
51:48.6	Video deleted from device when docked	54	5	54.885	3a74ef8bb4d5456694dfa373e026db61
51:48.7	Audit log rolled	54	5		54.885
51:48.7	Audit log created	54	5	1.15.14	54.885
51:48.9	Video upload started when camera was docked				27003ad535c34f28879a1512e1b963cd
51:49.5	Audit log successfully uploaded				
51:49.7	Audit log successfully uploaded and deleted from device	54	5	54.885	
51:59.0	Audit log successfully uploaded				
51:59.2	Audit log successfully uploaded and deleted from device	54	5	54.885	
52:14.4	Video successfully uploaded from device when docked				27003ad535c34f28879a1512e1b963cd
52:14.7	Video deleted from device when docked	54	4	54.982	27003ad535c34f28879a1512e1b963cd
52:14.7	Audit log rolled	54	4		54.982
52:14.7	Audit log created	54	4	1.15.14	54.982
52:14.9	Video upload started when camera was docked				6630d84236154f5b88a52739b35afde0
52:24.3	Audit log successfully uploaded				
52:24.4	Audit log successfully uploaded and deleted from device	54	4	54.982	
52:37.5	Audit log successfully uploaded				
52:37.7	Audit log successfully uploaded and deleted from device	54	4	54.982	

52:43.9	Audit log successfully uploaded			
52:44.1	Audit log successfully uploaded and deleted from device	54	4	54.982
52:44.2	Audit log successfully uploaded			
52:44.5	Audit log successfully uploaded and deleted from device	54	4	54.982
52:48.0	Video successfully uploaded from device when dockec			6630d84236154f5b88a52739b35afde0
52:48.3	Video deleted from device when docked	54	3	55.1 6630d84236154f5b88a52739b35afde0
52:48.4	Audit log rolled	54	3	55.1
52:48.4	Audit log created	54	3 1.15.14	55.1
52:48.6	Video upload started when camera was docked			1e9c193cfcb84457bc2b065594e16357
52:49.9	Audit log successfully uploaded			
52:50.1	Audit log successfully uploaded and deleted from device	54	3	55.1
52:53.0	Video successfully uploaded from device when dockec			1e9c193cfcb84457bc2b065594e16357
52:53.2	Video deleted from device when docked	54	2	55.112 1e9c193cfcb84457bc2b065594e16357
52:53.2	Audit log created	54	2 1.15.14	55.112
52:53.2	Audit log rolled	54	2	55.112
52:53.4	Video upload started when camera was docked			19d21d29f53d4dc59234a9862da4a4ca
53:04.1	Video successfully uploaded from device when dockec			19d21d29f53d4dc59234a9862da4a4ca
53:04.4	Video deleted from device when docked	54	1	55.153 19d21d29f53d4dc59234a9862da4a4ca
53:04.4	Audit log rolled	54	1	55.153
53:04.4	Audit log created	54	1 1.15.14	55.153
53:04.6	Video upload started when camera was docked			8f1369a1e41d43c2902f396d65d91f2a
53:10.7	Video successfully uploaded from device when dockec			8f1369a1e41d43c2902f396d65d91f2a
53:10.9	Video deleted from device when docked	54	0	55.171 8f1369a1e41d43c2902f396d65d91f2a
53:11.0	Audit log created	54	0 1.15.14	55.171
53:11.0	Audit log rolled	54	0	55.171
53:11.0	Audit log rolled	54	0	55.171
53:11.0	Audit log created	54	0 1.15.14	55.171
53:16.2	Audit log successfully uploaded			
53:16.4	Audit log successfully uploaded and deleted from device	55	0	55.171
53:27.6	Audit log successfully uploaded			
53:27.8	Audit log successfully uploaded and deleted from device	55	0	55.171
53:35.0	Audit log successfully uploaded			
53:35.1	Audit log successfully uploaded and deleted from device	55	0	55.171
53:59.2	Audit log successfully uploaded			
53:59.5	Audit log successfully uploaded and deleted from device	55	0	55.171
53:59.6	Audit log successfully uploaded			
53:59.8	Audit log successfully uploaded and deleted from device	55	0	55.171
54:19.0	Audit log successfully uploaded			
54:19.1	Audit log successfully uploaded and deleted from device	55	0	55.171
54:20.3	Audit log successfully uploaded			
54:20.5	Audit log successfully uploaded and deleted from device	55	0	55.171
54:45.7	Audit log successfully uploaded			
54:45.8	Audit log successfully uploaded and deleted from device	55	0	55.171
55:10.0	Audit log successfully uploaded			
55:10.2	Audit log successfully uploaded and deleted from device	56	0	55.171
55:39.4	Audit log successfully uploaded			
55:39.6	Audit log successfully uploaded and deleted from device	56	0	55.171

55:55.8	Audit log successfully uploaded			
55:56.0	Audit log successfully uploaded and deleted from device	56	0	55.171
56:25.2	Audit log successfully uploaded			
56:25.4	Audit log successfully uploaded and deleted from device	56	0	55.171
56:49.6	Audit log successfully uploaded			
56:49.8	Audit log successfully uploaded and deleted from device	56	0	55.171
57:16.0	Audit log successfully uploaded			
57:16.2	Audit log successfully uploaded and deleted from device	57	0	55.171
57:38.3	Audit log successfully uploaded			
57:38.5	Audit log successfully uploaded and deleted from device	57	0	55.171
58:05.7	Audit log successfully uploaded			
58:05.9	Audit log successfully uploaded and deleted from device	57	0	55.171
58:23.1	Audit log successfully uploaded			
58:23.3	Audit log successfully uploaded and deleted from device	57	0	55.171
58:32.5	Audit log successfully uploaded			
58:32.7	Audit log successfully uploaded and deleted from device	57	0	55.171
58:42.9	Audit log successfully uploaded			
58:43.1	Audit log successfully uploaded and deleted from device	57	0	55.171
58:57.6	Device disconnected from charger	58	0	55.177
58:57.6	Camera disconnected from Axon Dock X62001W9H	58	0	55.177
59:00.9	Camera connected to Axon Dock X62001W9H	58	0	55.179
59:01.0	Audit log created	58	0 1.15.14	55.179
59:01.0	Audit log rolled	58	0	55.179
59:01.6	Device connected to charger	58	0	55.179
59:22.6	Audit log successfully uploaded			
59:22.8	Audit log successfully uploaded and deleted from device	58	0	55.179
59:31.0	Date/Time synced to 09/07/2021 11:59:31.03 PM from 09/07/2021 11:59:30.91 PM			
59:53.2	Audit log successfully uploaded			
59:53.5	Audit log successfully uploaded and deleted from device	58	0	55.179
00:17.6	Audit log successfully uploaded			
00:17.7	Audit log successfully uploaded and deleted from device	58	0	55.179
00:31.9	Audit log successfully uploaded			
00:32.1	Audit log successfully uploaded and deleted from device	58	0	55.179
00:36.2	Audit log successfully uploaded			
00:36.4	Audit log successfully uploaded and deleted from device	58	0	55.179
00:38.5	Audit log successfully uploaded			
00:38.7	Audit log successfully uploaded and deleted from device	58	0	55.179
00:56.9	Audit log successfully uploaded			
00:57.1	Audit log successfully uploaded and deleted from device	58	0	55.179
01:07.3	Audit log successfully uploaded			
01:07.5	Audit log successfully uploaded and deleted from device	59	0	55.18
01:25.7	Audit log successfully uploaded			
01:25.8	Audit log successfully uploaded and deleted from device	59	0	55.18
01:37.0	Audit log successfully uploaded			
01:37.2	Audit log successfully uploaded and deleted from device	59	0	55.18
01:50.3	Audit log successfully uploaded			
01:50.6	Audit log successfully uploaded and deleted from device	59	0	55.18

02:04.7	Audit log successfully uploaded			
02:04.9	Audit log successfully uploaded and deleted from device	59	0	55.179
02:18.0	Audit log successfully uploaded			
02:18.2	Audit log successfully uploaded and deleted from device	59	0	55.179
02:42.3	Audit log successfully uploaded			
02:42.5	Audit log successfully uploaded and deleted from device	59	0	55.179
03:06.9	Audit log successfully uploaded			
03:07.2	Audit log successfully uploaded and deleted from device	59	0	55.179
03:23.3	Audit log successfully uploaded			
03:23.5	Audit log successfully uploaded and deleted from device	60	0	55.179
03:46.6	Audit log successfully uploaded			
03:46.8	Audit log successfully uploaded and deleted from device	60	0	55.179
04:10.9	Audit log successfully uploaded			
04:11.1	Audit log successfully uploaded and deleted from device	60	0	55.179
04:39.3	Audit log successfully uploaded			
04:39.5	Audit log successfully uploaded and deleted from device	60	0	55.179
05:07.6	Audit log successfully uploaded			
05:07.8	Audit log successfully uploaded and deleted from device	61	0	55.179
05:12.0	Audit log successfully uploaded			
05:12.2	Audit log successfully uploaded and deleted from device	61	0	55.179
05:25.3	Audit log successfully uploaded			
05:25.5	Audit log successfully uploaded and deleted from device	61	0	55.179
05:48.7	Audit log successfully uploaded			
05:48.9	Audit log successfully uploaded and deleted from device	61	0	55.179
05:55.1	Audit log successfully uploaded			
05:55.3	Audit log successfully uploaded and deleted from device	61	0	55.179
06:21.4	Audit log successfully uploaded			
06:21.6	Audit log successfully uploaded and deleted from device	61	0	55.179
06:25.8	Audit log successfully uploaded			
06:26.0	Audit log successfully uploaded and deleted from device	61	0	55.179
06:51.2	Audit log successfully uploaded			
06:51.4	Audit log successfully uploaded and deleted from device	61	0	55.179
06:53.5	Audit log successfully uploaded			
06:53.7	Audit log successfully uploaded and deleted from device	61	0	55.179
06:57.3	Audit log successfully uploaded			
06:57.5	Audit log successfully uploaded and deleted from device	61	0	55.179
07:12.6	Audit log successfully uploaded			
07:12.8	Audit log successfully uploaded and deleted from device	62	0	55.179
07:12.9	Audit log successfully uploaded			
07:13.1	Audit log successfully uploaded and deleted from device	62	0	55.179
07:17.3	Audit log successfully uploaded			
07:17.4	Audit log successfully uploaded and deleted from device	62	0	55.179
07:26.6	Audit log successfully uploaded			
07:26.8	Audit log successfully uploaded and deleted from device	62	0	55.179
07:50.9	Audit log successfully uploaded			
07:51.0	Audit log successfully uploaded and deleted from device	62	0	55.179
08:10.2	Audit log successfully uploaded			

08:10.4 Audit log successfully uploaded and deleted from device	62	0	55.179
08:22.5 Audit log successfully uploaded			
08:22.7 Audit log successfully uploaded and deleted from device	62	0	55.179
08:22.8 Audit log successfully uploaded			
08:23.0 Audit log successfully uploaded and deleted from device	62	0	55.179
08:52.1 Audit log successfully uploaded			
08:52.3 Audit log successfully uploaded and deleted from device	63	0	55.179
09:00.4 Audit log successfully uploaded			
09:00.6 Audit log successfully uploaded and deleted from device	63	0	55.179
09:10.8 Audit log successfully uploaded			
09:11.0 Audit log successfully uploaded and deleted from device	63	0	55.179
09:19.1 Audit log successfully uploaded			
09:19.3 Audit log successfully uploaded and deleted from device	63	0	55.179
09:27.4 Audit log successfully uploaded			
09:27.6 Audit log successfully uploaded and deleted from device	63	0	55.179
09:48.7 Audit log successfully uploaded			
09:48.9 Audit log successfully uploaded and deleted from device	63	0	55.179
10:13.0 Audit log successfully uploaded			
10:13.2 Audit log successfully uploaded and deleted from device	63	0	55.179
10:21.4 Audit log successfully uploaded			
10:21.6 Audit log successfully uploaded and deleted from device	63	0	55.179
10:23.7 Audit log successfully uploaded			
10:23.9 Audit log successfully uploaded and deleted from device	63	0	55.179
10:45.1 Audit log successfully uploaded			
10:45.3 Audit log successfully uploaded and deleted from device	63	0	55.179
10:57.4 Audit log successfully uploaded			
10:57.5 Audit log successfully uploaded and deleted from device	64	0	55.179
11:19.7 Audit log successfully uploaded			
11:19.9 Audit log successfully uploaded and deleted from device	64	0	55.179
11:48.1 Audit log successfully uploaded			
11:48.2 Audit log successfully uploaded and deleted from device	64	0	55.179
12:08.4 Audit log successfully uploaded			
12:08.6 Audit log successfully uploaded and deleted from device	64	0	55.179
12:21.7 Audit log successfully uploaded			
12:21.9 Audit log successfully uploaded and deleted from device	64	0	55.179
12:46.1 Audit log successfully uploaded			
12:46.2 Audit log successfully uploaded and deleted from device	65	0	55.179
13:07.4 Audit log successfully uploaded			
13:07.6 Audit log successfully uploaded and deleted from device	65	0	55.179
13:10.7 Audit log successfully uploaded			
13:10.9 Audit log successfully uploaded and deleted from device	65	0	55.179
13:29.1 Audit log successfully uploaded			
13:29.3 Audit log successfully uploaded and deleted from device	65	0	55.179
13:42.4 Audit log successfully uploaded			
13:42.6 Audit log successfully uploaded and deleted from device	65	0	55.179
13:47.8 Audit log successfully uploaded			
13:48.0 Audit log successfully uploaded and deleted from device	65	0	55.179

13:57.1	Audit log successfully uploaded			
13:57.2	Audit log successfully uploaded and deleted from device	65	0	55.179
14:23.3	Audit log successfully uploaded			
14:23.5	Audit log successfully uploaded and deleted from device	65	0	55.179
14:41.7	Audit log successfully uploaded			
14:41.9	Audit log successfully uploaded and deleted from device	65	0	55.179
29:31.0	Date/Time synced to 09/08/2021 12:29:31.01 AM from 09/08/2021 12:29:31.05 AM			
33:32.4	Device disconnected from charger	75	0	55.179
33:32.5	Camera disconnected from Axon Dock X62001W9H	75	0	55.179
58:59.9	Audit log created	72	0 1.15.14	55.179
58:59.9	Audit log created	65	0 1.15.14	55.177
06:17.6	Power button pressed			
06:17.7	Power button released			
06:17.7	Power button pressed			
06:17.8	Power button released			
06:23.2	Audit log rolled	64	0	55.177
06:23.2	Audit log created	64	0 1.15.14	55.177
06:23.3	Camera connected to Axon Dock X630020W7	64	0	55.177
06:23.4	Device connected to charger	64	0	55.177
06:23.0	Audit log created	92	0 1.15.14	55.176
06:23.0	Audit log created	100	0 1.15.14	55.184
06:23.0	Audit log created	100	0 1.15.14	55.188
06:23.0	Audit log created	100	0 1.15.14	55.191
06:23.1	Audit log created	100	0 1.15.14	55.191
06:23.1	Audit log created	100	0 1.15.14	55.19
06:23.1	Audit log created	100	0 1.15.14	55.19
06:23.1	Audit log created	100	0 1.15.14	55.189
06:23.1	Audit log created	100	0 1.15.14	55.189
06:23.1	Audit log created	100	0 1.15.14	55.188
06:23.1	Audit log created	100	0 1.15.14	55.188
06:23.1	Audit log created	100	0 1.15.14	55.187
10:22.5	Device disconnected from charger	98	0	55.187
10:22.8	Camera disconnected from Axon Dock X630020W7	100	0	55.187
10:45.1	Power button pressed			
10:48.2	Device powered off using button	100	0	55.188
10:48.6	Power button released			
08:56.0	Audit log created		1.15.14	
08:56.1	Device powered on using button	100	0	55.187
08:58.0	Audio recording disabled due to video buffering default			
09:01.0	Event button pressed			
09:01.2	Event button released			
09:01.2	Event button pressed			
09:01.2	Audio recording enabled due to video recording default			
09:01.3	Event button released			
09:01.4	Recording started due to button press	100	1	55.187 c16e0ac5dbcb4d49ae75235ae057100f
09:45.9	Event button pressed			
09:48.9	Recording stopped due to button press	99	1	55.161 c16e0ac5dbcb4d49ae75235ae057100f

09:49.3 Event button released			
09:49.8 Audio recording disabled due to video buffering default			
08:56.0 Audit log created	92	1 1.15.14	55.159
13:20.5 Event button pressed			
13:20.6 Event button released			
13:20.8 Event button pressed			
13:20.8 Audio recording enabled due to video recording default			
13:20.8 Event button released			
13:21.0 Recording started due to button press	92	1	55.159 defc3363c8bb487ba86af2f6ef96ce09
13:26.4 Volume up button pressed			
13:26.6 Volume up button released			
13:26.7 Volume changed to very high from high using button			
13:30.7 Select button pressed			
13:30.9 Select button released			
13:31.0 Select button pressed			
13:31.1 Select button released			
13:33.1 Volume down button pressed			
13:33.3 Volume down button released			
13:33.4 Volume changed to high from very high using button			
13:33.7 Volume down button pressed			
13:33.9 Volume down button released			
13:34.0 Volume changed to medium from high using button			
13:56.5 Event button pressed			
13:59.5 Recording stopped due to button press	92	2	55.078 defc3363c8bb487ba86af2f6ef96ce09
13:59.9 Event button released			
14:00.4 Audio recording disabled due to video buffering default			
14:38.7 Power button pressed			
14:41.8 Device powered off using button	92	2	55.078
14:42.1 Power button released			
17:04.2 Device powered on using button	92	2	55.078
17:07.0 Audio recording disabled due to video buffering default			
17:13.0 Event button pressed			
17:13.1 Event button released			
17:13.2 Event button pressed			
17:13.3 Audio recording enabled due to video recording default			
17:13.3 Event button released			
17:13.4 Recording started due to button press	92	3	55.077 5d05a44510fc4649a4f0125500cb3009
17:31.3 Event button pressed			
17:34.3 Recording stopped due to button press	92	3	55.064 5d05a44510fc4649a4f0125500cb3009
17:34.8 Event button released			
17:35.1 Audio recording disabled due to video buffering default			
17:51.7 Event button pressed			
17:51.8 Event button released			
17:51.9 Event button pressed			
17:51.9 Audio recording enabled due to video recording default			
17:52.0 Event button released			
17:52.0 Recording started due to button press	92	4	55.063 f95501e945e34cbb835b6cf28485c220

18:05.9	Event button pressed			
18:08.9	Recording stopped due to button press	91	4	55.046 f95501e945e34cbb835b6cf28485c220
18:09.3	Event button released			
18:09.7	Audio recording disabled due to video buffering default			
44:42.9	Event button pressed			
44:43.0	Event button released			
44:43.1	Event button pressed			
44:43.1	Audio recording enabled due to video recording default			
44:43.2	Event button released			
44:43.3	Recording started due to button press	89	5	55.045 3a4e2669ffc4430cbf407939835fc157
45:30.4	Event button pressed			
45:33.4	Recording stopped due to button press	89	5	54.958 3a4e2669ffc4430cbf407939835fc157
45:33.9	Event button released			
45:34.3	Audio recording disabled due to video buffering default			
46:13.3	Event button pressed			
46:13.5	Event button released			
46:13.5	Event button pressed			
46:13.5	Audio recording enabled due to video recording default			
46:13.6	Event button released			
46:13.7	Recording started due to button press	89	6	54.957 2d84275293e845239b1c03302c1c5729
46:34.4	Event button pressed			
46:37.4	Recording stopped due to button press	89	6	54.926 2d84275293e845239b1c03302c1c5729
46:37.9	Event button released			
46:38.2	Audio recording disabled due to video buffering default			
48:34.1	Event button pressed			
48:34.2	Event button released			
48:34.2	Event button pressed			
48:34.3	Audio recording enabled due to video recording default			
48:34.3	Event button released			
48:34.4	Recording started due to button press	88	7	54.925 f8de1a7baa1c403c9ae6d1825a7b593c
48:51.5	Event button pressed			
48:54.5	Recording stopped due to button press	88	7	54.879 f8de1a7baa1c403c9ae6d1825a7b593c
48:54.9	Event button released			
48:55.3	Audio recording disabled due to video buffering default			
48:57.6	Event button pressed			
48:57.7	Event button released			
48:57.8	Event button pressed			
48:57.8	Audio recording enabled due to video recording default			
48:57.9	Event button released			
48:57.9	Recording started due to button press	88	8	54.872 7bc3b4e750a144229218150f680e15c7
49:15.5	Event button pressed			
49:18.5	Recording stopped due to button press	88	8	54.844 7bc3b4e750a144229218150f680e15c7
49:19.0	Event button released			
49:19.3	Audio recording disabled due to video buffering default			
50:15.8	Axon application connected to device			
53:01.5	Video played back using Axon application			defc3363c8bb487ba86af2f6ef96ce09
53:59.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			defc3363c8bb487ba86af2f6ef96ce09

53:59.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1713 X6033271L' to 'Signal 75' using Axon applicator				defc3363c8bb487ba86af2f6ef96ce09
54:16.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1609 X6033271L' to 'Signal 75' using Axon applicator				c16e0ac5dbcb4d49ae75235ae057100f
54:16.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				c16e0ac5dbcb4d49ae75235ae057100f
55:05.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				5d05a44510fc4649a4f0125500cb3009
55:05.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1717 X6033271L' to 'Signal 75' using Axon applicator				5d05a44510fc4649a4f0125500cb3009
55:38.9	Video played back using Axon application				f95501e945e34cbb835b6cf28485c220
56:17.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1717 X6033271L' to 'Signal 75' using Axon applicator				f95501e945e34cbb835b6cf28485c220
56:17.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				f95501e945e34cbb835b6cf28485c220
56:55.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1744 X6033271L' to 'Signal 75' using Axon applicator				3a4e2669ffc4430cbf407939835fc157
56:55.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				3a4e2669ffc4430cbf407939835fc157
57:06.4	Video played back using Axon application				3a4e2669ffc4430cbf407939835fc157
57:42.7	Video played back using Axon application				2d84275293e845239b1c03302c1c5729
58:14.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1746 X6033271L' to 'Signal 75' using Axon applicator				2d84275293e845239b1c03302c1c5729
58:14.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				2d84275293e845239b1c03302c1c5729
58:51.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1748 X6033271L' to 'Signal 75' using Axon applicator				f8de1a7baa1c403c9ae6d1825a7b593c
58:51.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				f8de1a7baa1c403c9ae6d1825a7b593c
59:18.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1748 X6033271L' to 'Signal 75' using Axon applicator				7bc3b4e750a144229218150f680e15c7
59:18.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				7bc3b4e750a144229218150f680e15c7
07:48.3	Event button pressed				
07:48.4	Event button released				
07:48.5	Event button pressed				
07:48.6	Audio recording enabled due to video recording default				
07:48.6	Event button released				
07:48.7	Recording started due to button press	86	9	54.841	a876772eb2bd42f4956d0e4626467116
08:28.9	Event button pressed				
08:31.9	Recording stopped due to button press	86	9	54.758	a876772eb2bd42f4956d0e4626467116
08:32.5	Event button released				
08:32.6	Audio recording disabled due to video buffering default				
08:56.1	Audit log created	86	9 1.15.14	54.758	
25:09.7	Event button pressed				
25:09.7	Event button released				
25:09.8	Event button pressed				
25:09.9	Audio recording enabled due to video recording default				
25:09.9	Event button released				
25:10.0	Recording started due to button press	84	10	54.757	877fa66ebac547f786f66d2dd36a0cfe
25:53.0	Event button pressed				
25:53.0	Event button released				
25:53.3	Event button pressed				
26:01.8	Event button released				
26:02.1	Event button pressed				
26:04.0	Event button released				
26:04.5	Event button pressed				
26:05.8	Event button released				
26:06.2	Event button pressed				
26:09.2	Recording stopped due to button press	84	10	54.665	877fa66ebac547f786f66d2dd36a0cfe
26:09.4	Event button released				
26:10.1	Audio recording disabled due to video buffering default				

28:28.7 Event button pressed			
28:28.8 Event button released			
28:28.9 Event button pressed			
28:28.9 Audio recording enabled due to video recording default			
28:29.0 Event button released			
28:29.0 Recording started due to button press	84	11	54.665 367813c473dc47499e94eafc048f0f40
28:45.8 Event button pressed			
28:46.3 Event button released			
28:58.5 Event button pressed			
29:01.5 Recording stopped due to button press	84	11	54.595 367813c473dc47499e94eafc048f0f40
29:02.4 Audio recording disabled due to video buffering default			
29:02.7 Event button released			
32:30.8 Event button pressed			
32:31.0 Event button released			
32:31.0 Event button pressed			
32:31.1 Audio recording enabled due to video recording default			
32:31.2 Event button released			
32:31.3 Recording started due to button press	83	12	54.586 b0824d7529864b0ab3a0c8fae7b5bdda
32:41.5 Event button pressed			
32:43.1 Event button released			
32:44.6 Event button pressed			
32:47.6 Recording stopped due to button press	83	12	54.55 b0824d7529864b0ab3a0c8fae7b5bdda
32:48.2 Event button released			
32:48.4 Audio recording disabled due to video buffering default			
33:31.8 Event button pressed			
33:31.9 Event button released			
33:32.0 Event button pressed			
33:32.1 Audio recording enabled due to video recording default			
33:32.1 Event button released			
33:32.2 Recording started due to button press	83	13	54.517 85392a1f1e2243c4a993dd5be3134b42
34:26.6 Event button pressed			
34:29.6 Recording stopped due to button press	83	13	54.465 85392a1f1e2243c4a993dd5be3134b42
34:30.1 Event button released			
34:30.4 Audio recording disabled due to video buffering default			
34:56.7 Event button pressed			
34:56.8 Event button released			
34:56.9 Event button pressed			
34:56.9 Audio recording enabled due to video recording default			
34:57.0 Event button released			
34:57.1 Recording started due to button press	83	14	54.464 1742f34486ce42e1bdb25a8341b20442
35:39.2 Event button pressed			
35:42.2 Recording stopped due to button press	82	14	54.427 1742f34486ce42e1bdb25a8341b20442
35:42.9 Event button released			
35:43.0 Audio recording disabled due to video buffering default			
39:24.8 Event button pressed			
39:24.9 Event button released			
39:24.9 Event button pressed			

39:25.0	Audio recording enabled due to video recording default			
39:25.0	Event button released			
39:25.1	Recording started due to button press	82	15	54.427 b373be575e6048dba16499fa520a6710
39:38.4	Event button pressed			
39:41.4	Recording stopped due to button press	82	15	54.39 b373be575e6048dba16499fa520a6710
39:41.8	Event button released			
39:42.3	Audio recording disabled due to video buffering default			
43:56.2	Event button pressed			
43:56.4	Event button released			
43:56.4	Event button pressed			
43:56.5	Audio recording enabled due to video recording default			
43:56.5	Event button released			
43:56.6	Recording started due to button press	82	16	54.357 a9dab46cead64f6f85f6c23d7207faf7
44:31.8	Event button pressed			
44:34.8	Recording stopped due to button press	81	16	54.277 a9dab46cead64f6f85f6c23d7207faf7
44:35.4	Event button released			
44:35.7	Audio recording disabled due to video buffering default			
55:42.8	Event button pressed			
55:42.9	Event button released			
55:42.9	Event button pressed			
55:43.0	Audio recording enabled due to video recording default			
55:43.1	Event button released			
55:43.1	Recording started due to button press	80	17	54.276 a9fc6671bcde4641aba8d33303319ace
56:48.3	Event button pressed			
56:51.3	Recording stopped due to button press	80	17	54.18 a9fc6671bcde4641aba8d33303319ace
56:52.1	Audio recording disabled due to video buffering default			
56:52.1	Event button released			
58:24.3	Event button pressed			
58:24.5	Event button released			
58:24.5	Event button pressed			
58:24.5	Audio recording enabled due to video recording default			
58:24.6	Event button released			
58:24.7	Recording started due to button press	80	18	54.179 4f8bd35d1fd542c788647c913197a4cd
58:35.8	Event button pressed			
58:38.8	Recording stopped due to button press	80	18	54.147 4f8bd35d1fd542c788647c913197a4cd
58:39.4	Event button released			
58:39.6	Audio recording disabled due to video buffering default			
02:44.9	Video played back using Axon application			a876772eb2bd42f4956d0e4626467116
03:40.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1807 X6033271L' to 'Signal 75' using Axon applicator			a876772eb2bd42f4956d0e4626467116
03:40.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			a876772eb2bd42f4956d0e4626467116
05:10.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1825 X6033271L' to 'Signal 75' using Axon applicator			877fa66ebac547f786f66d2dd36a0cfe
05:10.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			877fa66ebac547f786f66d2dd36a0cfe
05:23.5	Video played back using Axon application			877fa66ebac547f786f66d2dd36a0cfe
06:16.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1828 X6033271L' to 'Signal 75' using Axon applicator			367813c473dc47499e94eafc048f0f40
06:16.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			367813c473dc47499e94eafc048f0f40
06:19.6	Video played back using Axon application			367813c473dc47499e94eafc048f0f40
07:38.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			85392a1f1e2243c4a993dd5be3134b42

07:38.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1833 X6033271L' to 'Signal 75' using Axon applicator				85392a1f1e2243c4a993dd5be3134b42
08:00.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				b0824d7529864b0ab3a0c8fae7b5bdda
08:00.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1832 X6033271L' to 'Signal 75' using Axon applicator				b0824d7529864b0ab3a0c8fae7b5bdda
08:25.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				1742f34486ce42e1bdb25a8341b20442
08:25.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1834 X6033271L' to 'Signal 75' using Axon applicator				1742f34486ce42e1bdb25a8341b20442
08:56.1	Audit log created	79	18	1.15.14	54.123
09:05.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				b373be575e6048dba16499fa520a6710
09:05.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1839 X6033271L' to 'Signal 75' using Axon applicator				b373be575e6048dba16499fa520a6710
10:38.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				a9dab46cead64f6f85f6c23d7207faf7
10:38.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1843 X6033271L' to 'Signal 75' using Axon applicator				a9dab46cead64f6f85f6c23d7207faf7
10:45.0	Video played back using Axon application				a9dab46cead64f6f85f6c23d7207faf7
11:48.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				a9fc6671bcde4641aba8d33303319ace
11:48.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1855 X6033271L' to 'Signal 75' using Axon applicator				a9fc6671bcde4641aba8d33303319ace
12:35.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				4f8bd35d1fd542c788647c913197a4cd
12:35.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 1858 X6033271L' to 'Signal 75' using Axon applicator				4f8bd35d1fd542c788647c913197a4cd
30:36.3	Axon application disconnected from device				
08:56.1	Audit log created	73	18	1.15.14	54.121
36:44.4	Power button pressed				
36:47.5	Device powered off using button	71	18		54.12
36:47.9	Power button released				
38:31.2	Device powered on using button	71	18		54.124
38:34.2	Audio recording disabled due to video buffering default				
40:48.4	Event button pressed				
40:48.5	Event button released				
40:48.6	Event button pressed				
40:48.6	Audio recording enabled due to video recording default				
40:48.7	Event button released				
40:48.8	Recording started due to button press	70	19		54.123 a8e28ab36c8d4ed98231725e3ca51f43
48:26.5	Event button pressed				
48:29.5	Recording stopped due to button press	68	19		53.82 a8e28ab36c8d4ed98231725e3ca51f43
48:30.1	Event button released				
48:30.3	Audio recording disabled due to video buffering default				
55:08.3	Event button pressed				
55:08.5	Event button released				
55:08.5	Event button pressed				
55:08.6	Audio recording enabled due to video recording default				
55:08.6	Event button released				
55:08.7	Recording started due to button press	68	19		53.818 a1ea06ca628445a3a5bc6a9da2ea4db8
56:42.7	Event button pressed				
56:45.7	Recording stopped due to button press	67	20		53.706 a1ea06ca628445a3a5bc6a9da2ea4db8
56:46.4	Audio recording disabled due to video buffering default				
56:46.6	Event button released				
08:56.0	Audit log created	66	20	1.15.14	53.705
03:24.3	Event button pressed				
03:24.4	Event button released				
03:24.5	Event button pressed				
03:24.5	Audio recording enabled due to video recording default				

03:24.6	Event button released			
03:24.6	Recording started due to button press	61	21	53.704 06e2d1ce4bb5419280ae12e9c8bb22f0
03:56.4	Event button pressed			
03:59.4	Recording stopped due to button press	61	21	53.628 06e2d1ce4bb5419280ae12e9c8bb22f0
03:59.9	Event button released			
04:00.3	Audio recording disabled due to video buffering default			
04:04.7	Event button pressed			
04:04.8	Event button released			
04:04.8	Event button pressed			
04:04.8	Audio recording enabled due to video recording default			
04:04.9	Event button released			
04:05.0	Recording started due to button press	61	22	53.625 12b3d79cfa0148a782032014a72872e8
06:04.3	Event button pressed			
06:05.5	Event button released			
06:17.9	Event button pressed			
06:20.9	Recording stopped due to button press	60	22	53.551 12b3d79cfa0148a782032014a72872e8
06:21.4	Event button released			
06:21.9	Audio recording disabled due to video buffering default			
06:23.6	Event button pressed			
06:23.8	Event button released			
06:23.9	Event button pressed			
06:23.9	Audio recording enabled due to video recording default			
06:24.0	Event button released			
06:24.0	Recording started due to button press	60	23	53.551 b302fa8eb2f24a88831101d8cce9370c
06:54.0	Event button pressed			
06:57.0	Recording stopped due to button press	60	23	53.532 b302fa8eb2f24a88831101d8cce9370c
06:57.6	Event button released			
06:57.8	Audio recording disabled due to video buffering default			
08:56.0	Audit log created	60	23 1.15.14	53.532
04:59.6	Axon application connected to device			
07:18.7	Video played back using Axon application			a8e28ab36c8d4ed98231725e3ca51f43
08:38.8	Categories 'Ambulance Call' added to video metadata using Axon applicator			a8e28ab36c8d4ed98231725e3ca51f43
08:38.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 2040 X6033271L' to 'Signal 47/24 She Went Code 8' using Axon applicator			a8e28ab36c8d4ed98231725e3ca51f43
08:56.0	Audit log created	53	23 1.15.14	53.53
11:55.4	Categories 'Ambulance Call', 'Demented Person' added to video metadata using Axon applicator			a1ea06ca628445a3a5bc6a9da2ea4db8
11:55.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 2055 X6033271L' to 'Signal 47/24 She Went Code 8' using Axon applicator			a1ea06ca628445a3a5bc6a9da2ea4db8
12:12.5	Categories 'Demented Person' added to video metadata using Axon applicator			a8e28ab36c8d4ed98231725e3ca51f43
12:45.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			06e2d1ce4bb5419280ae12e9c8bb22f0
12:45.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 2203 X6033271L' to 'Signal 75' using Axon applicator			06e2d1ce4bb5419280ae12e9c8bb22f0
13:09.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			12b3d79cfa0148a782032014a72872e8
13:09.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 2204 X6033271L' to 'Signal 75' using Axon applicator			12b3d79cfa0148a782032014a72872e8
13:18.0	Video played back using Axon application			12b3d79cfa0148a782032014a72872e8
13:41.2	Categories 'Customer Assist' added to video metadata using Axon applicator			12b3d79cfa0148a782032014a72872e8
13:41.2	Categories 'Miscellaneous' removed from video metadata using Axon applicator			12b3d79cfa0148a782032014a72872e8
13:41.2	Title changed in video metadata from 'Signal 75' to 'Signal 15' using Axon application			12b3d79cfa0148a782032014a72872e8
14:02.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			b302fa8eb2f24a88831101d8cce9370c
14:02.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-08 2206 X6033271L' to 'Signal 75' using Axon applicator			b302fa8eb2f24a88831101d8cce9370c

14:33.3	Axon application disconnected from device			
36:23.9	Volume up button pressed			
36:24.0	Volume up button released			
36:24.1	Volume changed to high from medium using button			
36:26.9	Volume down button pressed			
36:27.2	Volume down button released			
36:27.3	Volume changed to medium from high using button			
36:38.4	Camera connected to Axon Dock X62001V12	49	22	53.57
36:38.5	Audit log created	49	23 1.15.14	53.529
36:38.5	Audit log rolled	49	23	53.529
36:39.2	Device connected to charger	49	23	53.529
36:57.9	Video upload started when camera was docked			c16e0ac5dbcb4d49ae75235ae057100f
37:05.8	Video successfully uploaded from device when dockec			c16e0ac5dbcb4d49ae75235ae057100f
37:06.1	Video deleted from device when docked	49	22	53.571 c16e0ac5dbcb4d49ae75235ae057100f
37:06.1	Audit log created	49	22 1.15.14	53.571
37:06.1	Audit log rolled	49	22	53.571
37:06.3	Video upload started when camera was docked			defc3363c8bb487ba86af2f6ef96ce09
37:16.0	Date/Time synced to 09/08/2021 11:37:16.01 PM from 09/08/2021 11:37:08.41 PM			
37:24.8	Video upload started when camera was docked			5d05a44510fc4649a4f0125500cb3009
37:33.7	Audit log successfully uploaded			
37:33.9	Audit log successfully uploaded and deleted from device	49	22	53.57
37:35.2	Video upload started when camera was docked			f95501e945e34cbb835b6cf28485c220
37:37.0	Audit log successfully uploaded			
37:37.2	Audit log successfully uploaded and deleted from device	49	22	53.57
37:49.3	Audit log successfully uploaded			
37:49.5	Audit log successfully uploaded and deleted from device	49	22	53.57
38:10.6	Audit log successfully uploaded			
38:10.8	Audit log successfully uploaded and deleted from device	50	22	53.57
38:15.0	Audit log successfully uploaded			
38:15.3	Audit log successfully uploaded and deleted from device	50	22	53.57
38:29.4	Audit log successfully uploaded			
38:29.6	Audit log successfully uploaded and deleted from device	50	22	53.57
38:47.8	Audit log successfully uploaded			
38:47.9	Audit log successfully uploaded and deleted from device	50	22	53.57
38:56.2	Video successfully uploaded from device when dockec			f95501e945e34cbb835b6cf28485c220
38:56.4	Video deleted from device when docked	50	21	53.588 f95501e945e34cbb835b6cf28485c220
38:56.5	Audit log rolled	50	21	53.588
38:56.5	Audit log created	50	21 1.15.14	53.588
38:56.9	Video upload started when camera was docked			3a4e2669ffc4430cbf407939835fc157
39:04.4	Audit log successfully uploaded			
39:04.6	Audit log successfully uploaded and deleted from device	50	21	53.588
39:20.7	Audit log successfully uploaded			
39:20.8	Audit log successfully uploaded and deleted from device	50	21	53.588
39:21.5	Video successfully uploaded from device when dockec			3a4e2669ffc4430cbf407939835fc157
39:21.7	Video deleted from device when docked	50	20	53.675 3a4e2669ffc4430cbf407939835fc157
39:21.8	Audit log created	50	20 1.15.14	53.675
39:21.8	Audit log rolled	50	20	53.675

39:22.0	Video upload started when camera was docked				2d84275293e845239b1c03302c1c5729
39:24.0	Audit log successfully uploaded				
39:24.2	Audit log successfully uploaded and deleted from device	50	20	53.675	
39:31.7	Video successfully uploaded from device when docked				2d84275293e845239b1c03302c1c5729
39:31.9	Video deleted from device when docked	50	19	53.707	2d84275293e845239b1c03302c1c5729
39:31.9	Audit log rolled	50	19	53.707	
39:31.9	Audit log created	50	19	1.15.14	53.707
39:32.1	Video upload started when camera was docked				f8de1a7baa1c403c9ae6d1825a7b593c
39:38.3	Audit log successfully uploaded				
39:38.5	Audit log successfully uploaded and deleted from device	50	19	53.707	
39:38.6	Audit log successfully uploaded				
39:38.8	Audit log successfully uploaded and deleted from device	50	19	53.707	
39:53.6	Video successfully uploaded from device when docked				f8de1a7baa1c403c9ae6d1825a7b593c
39:53.8	Video deleted from device when docked	51	18	53.776	f8de1a7baa1c403c9ae6d1825a7b593c
39:53.8	Audit log rolled	51	18	53.776	
39:53.8	Audit log created	51	18	1.15.14	53.776
39:54.1	Video upload started when camera was docked				7bc3b4e750a144229218150f680e15c7
39:58.1	Video successfully uploaded from device when docked				7bc3b4e750a144229218150f680e15c7
39:58.3	Video deleted from device when docked	51	17	53.788	7bc3b4e750a144229218150f680e15c7
39:58.3	Audit log created	51	17	1.15.14	53.788
39:58.3	Audit log rolled	51	17	53.788	
39:58.6	Video upload started when camera was docked				a876772eb2bd42f4956d0e4626467116
40:00.9	Audit log successfully uploaded				
40:01.1	Audit log successfully uploaded and deleted from device	51	17	53.788	
40:24.1	Video successfully uploaded from device when docked				a876772eb2bd42f4956d0e4626467116
40:24.3	Video deleted from device when docked	51	16	53.871	a876772eb2bd42f4956d0e4626467116
40:24.3	Audit log created	51	16	1.15.14	53.871
40:24.3	Audit log rolled	51	16	53.871	
40:24.5	Video upload started when camera was docked				877fa66ebac547f786f66d2dd36a0cfe
40:27.2	Audit log successfully uploaded				
40:27.4	Audit log successfully uploaded and deleted from device	51	16	53.871	
40:38.5	Audit log successfully uploaded				
40:38.8	Audit log successfully uploaded and deleted from device	51	16	53.871	
40:51.2	Video successfully uploaded from device when docked				877fa66ebac547f786f66d2dd36a0cfe
40:51.5	Video deleted from device when docked	51	15	53.963	877fa66ebac547f786f66d2dd36a0cfe
40:51.5	Audit log created	51	15	1.15.14	53.963
40:51.5	Audit log rolled	51	15	53.963	
40:51.7	Video upload started when camera was docked				367813c473dc47499e94eafc048f0f40
41:07.2	Audit log successfully uploaded				
41:07.4	Audit log successfully uploaded and deleted from device	51	15	53.963	
41:11.6	Audit log successfully uploaded				
41:11.8	Audit log successfully uploaded and deleted from device	51	15	53.963	
41:13.9	Audit log successfully uploaded				
41:14.1	Audit log successfully uploaded and deleted from device	51	15	53.963	
41:14.9	Video successfully uploaded from device when docked				367813c473dc47499e94eafc048f0f40
41:15.1	Video deleted from device when docked	51	14	54.041	367813c473dc47499e94eafc048f0f40
41:15.2	Audit log rolled	51	14	54.041	

41:15.2	Audit log created	51	14	1.15.14	54.041	
41:15.4	Video upload started when camera was docked					b0824d7529864b0ab3a0c8fae7b5bdda
41:30.2	Audit log successfully uploaded					
41:30.4	Audit log successfully uploaded and deleted from device	51	14		54.041	
41:34.9	Video successfully uploaded from device when dockec					b0824d7529864b0ab3a0c8fae7b5bdda
41:35.2	Video deleted from device when docked	51	13		54.11	b0824d7529864b0ab3a0c8fae7b5bdda
41:35.3	Audit log rolled	51	13		54.11	
41:35.3	Audit log created	51	13	1.15.14	54.11	
41:35.5	Video upload started when camera was docked					85392a1f1e2243c4a993dd5be3134b42
41:41.6	Audit log successfully uploaded					
41:41.8	Audit log successfully uploaded and deleted from device	51	13		54.11	
41:50.7	Video successfully uploaded from device when dockec					85392a1f1e2243c4a993dd5be3134b42
41:51.0	Video deleted from device when docked	51	12		54.162	85392a1f1e2243c4a993dd5be3134b42
41:51.0	Audit log created	51	12	1.15.14	54.162	
41:51.0	Audit log rolled	51	12		54.162	
41:51.4	Video upload started when camera was docked					1742f34486ce42e1bdb25a8341b20442
42:02.5	Video successfully uploaded from device when dockec					1742f34486ce42e1bdb25a8341b20442
42:02.7	Video deleted from device when docked	51	11		54.199	1742f34486ce42e1bdb25a8341b20442
42:02.7	Audit log rolled	51	11		54.199	
42:02.7	Audit log created	51	11	1.15.14	54.199	
42:02.9	Audit log successfully uploaded					
42:03.0	Video upload started when camera was docked					b373be575e6048dba16499fa520a6710
42:03.1	Audit log successfully uploaded and deleted from device	51	11		54.199	
42:21.2	Audit log successfully uploaded					
42:21.4	Audit log successfully uploaded and deleted from device	52	11		54.199	
42:22.5	Video successfully uploaded from device when dockec					b373be575e6048dba16499fa520a6710
42:22.8	Video deleted from device when docked	52	10		54.268	b373be575e6048dba16499fa520a6710
42:22.8	Audit log created	52	10	1.15.14	54.268	
42:22.8	Audit log rolled	52	10		54.268	
42:23.0	Video upload started when camera was docked					a9dab46cead64f6f85f6c23d7207faf7
42:43.6	Audit log successfully uploaded					
42:43.8	Audit log successfully uploaded and deleted from device	52	10		54.268	
42:46.6	Video successfully uploaded from device when dockec					a9dab46cead64f6f85f6c23d7207faf7
42:46.8	Video deleted from device when docked	52	9		54.348	a9dab46cead64f6f85f6c23d7207faf7
42:46.8	Audit log created	52	9	1.15.14	54.348	
42:46.8	Audit log rolled	52	9		54.348	
42:47.1	Video upload started when camera was docked					a9fc6671bcde4641aba8d33303319ace
43:05.1	Audit log successfully uploaded					
43:05.3	Audit log successfully uploaded and deleted from device	52	9		54.348	
43:15.6	Video successfully uploaded from device when dockec					a9fc6671bcde4641aba8d33303319ace
43:15.8	Video deleted from device when docked	52	8		54.445	a9fc6671bcde4641aba8d33303319ace
43:15.9	Audit log rolled	52	8		54.445	
43:15.9	Audit log created	52	8	1.15.14	54.445	
43:16.2	Video upload started when camera was docked					4f8bd35d1fd542c788647c913197a4cd
43:31.8	Video successfully uploaded from device when dockec					4f8bd35d1fd542c788647c913197a4cd
43:31.9	Video deleted from device when docked	52	7		54.498	4f8bd35d1fd542c788647c913197a4cd
43:32.0	Audit log created	52	7	1.15.14	54.499	

43:32.0	Audit log rolled	52	7	54.499	
43:32.2	Video upload started when camera was docked				a8e28ab36c8d4ed98231725e3ca51f43
44:50.9	Video successfully uploaded from device when docked				a8e28ab36c8d4ed98231725e3ca51f43
44:51.2	Video deleted from device when docked	53	6	54.8	a8e28ab36c8d4ed98231725e3ca51f43
44:51.3	Audit log created	53	6	1.15.14	54.8
44:51.3	Audit log rolled	53	6		54.8
44:51.6	Video upload started when camera was docked				a1ea06ca628445a3a5bc6a9da2ea4db8
45:22.4	Video successfully uploaded from device when docked				a1ea06ca628445a3a5bc6a9da2ea4db8
45:22.7	Video deleted from device when docked	53	5	54.912	a1ea06ca628445a3a5bc6a9da2ea4db8
45:22.8	Audit log created	53	5	1.15.14	54.912
45:22.8	Audit log rolled	53	5		54.912
45:23.0	Video upload started when camera was docked				06e2d1ce4bb5419280ae12e9c8bb22f0
45:45.5	Video successfully uploaded from device when docked				06e2d1ce4bb5419280ae12e9c8bb22f0
45:45.8	Video deleted from device when docked	53	4	54.991	06e2d1ce4bb5419280ae12e9c8bb22f0
45:45.9	Audit log created	53	4	1.15.14	54.991
45:45.9	Audit log rolled	53	4		54.991
45:46.1	Video upload started when camera was docked				12b3d79cfa0148a782032014a72872e8
46:07.6	Video successfully uploaded from device when docked				12b3d79cfa0148a782032014a72872e8
46:07.8	Video deleted from device when docked	53	3	55.064	12b3d79cfa0148a782032014a72872e8
46:07.9	Audit log rolled	53	3		55.064
46:07.9	Audit log created	53	3	1.15.14	55.064
46:08.1	Video upload started when camera was docked				b302fa8eb2f24a88831101d8cce9370c
46:13.8	Video successfully uploaded from device when docked				b302fa8eb2f24a88831101d8cce9370c
46:14.1	Video deleted from device when docked	53	2	55.083	b302fa8eb2f24a88831101d8cce9370c
46:14.1	Audit log created	53	2	1.15.14	55.083
46:14.1	Audit log rolled	53	2		55.083
46:18.5	Video successfully uploaded from device when docked				5d05a44510fc4649a4f0125500cb3009
46:18.7	Video deleted from device when docked	53	1	55.097	5d05a44510fc4649a4f0125500cb3009
46:18.8	Audit log rolled	53	1		55.097
46:18.8	Audit log created	53	1	1.15.14	55.097
46:36.9	Video successfully uploaded from device when docked				defc3363c8bb487ba86af2f6ef96ce09
46:37.2	Video deleted from device when docked	54	0	55.178	defc3363c8bb487ba86af2f6ef96ce09
46:37.2	Audit log created	54	0	1.15.14	55.178
46:37.2	Audit log rolled	54	0		55.178
46:37.3	Audit log rolled	54	0		55.178
46:37.3	Audit log created	54	0	1.15.14	55.178
07:16.0	Date/Time synced to 09/09/2021 12:07:16.01 AM from 09/09/2021 12:07:16.03 AM				
37:16.0	Date/Time synced to 09/09/2021 12:37:16.01 AM from 09/09/2021 12:37:15.90 AM				
46:36.9	Audit log created	83	0	1.15.14	55.183
51:57.4	Camera disconnected from Axon Dock X62001V12	85	0		55.183
51:57.5	Device disconnected from charger	85	0		55.185
46:36.9	Audit log created	78	0	1.15.14	55.185
18:10.9	Camera connected to Axon Dock X630020W7	75	0		55.184
18:10.9	Audit log created	74	0	1.15.14	55.184
18:10.9	Audit log rolled	74	0		55.184
18:11.5	Device connected to charger	74	0		55.184
18:10.0	Audit log created	98	0	1.15.14	55.183

18:10.0	Audit log created	100	0	1.15.14	55.182
18:10.0	Audit log created	100	0	1.15.14	55.182
18:10.0	Audit log created	100	0	1.15.14	55.182
18:10.0	Audit log created	100	0	1.15.14	55.181
18:10.0	Audit log created	100	0	1.15.14	55.181
18:10.0	Audit log created	100	0	1.15.14	55.18
18:10.1	Audit log created	100	0	1.15.14	55.18
18:10.1	Audit log created	100	0	1.15.14	55.179
18:10.1	Audit log created	100	0	1.15.14	55.179
18:10.1	Audit log created	100	0	1.15.14	55.178
18:10.1	Audit log created	100	0	1.15.14	55.178
04:04.5	Device disconnected from charger	99	0		55.177
04:04.9	Camera disconnected from Axon Dock X630020W7	99	0		55.177
04:09.1	Programmable button pressed				
04:09.1	Programmable button released				
18:10.1	Audit log created	98	0	1.15.14	55.178
18:10.1	Audit log created	91	0	1.15.14	55.176
38:16.7	Power button pressed				
38:19.8	Device powered off using button	89	0		55.176
38:20.3	Power button released				
42:04.3	Device powered on using button	89	0		55.175
42:07.3	Audio recording disabled due to video buffering default				
45:33.5	Event button pressed				
45:33.6	Event button released				
45:33.7	Event button pressed				
45:33.8	Audio recording enabled due to video recording default				
45:33.8	Event button released				
45:34.0	Recording started due to button press	89	1		55.176 d39fb12827c84a3886878ea331bbe913
48:19.1	Event button pressed				
48:22.1	Recording stopped due to button press	88	1		55.027 d39fb12827c84a3886878ea331bbe913
48:22.6	Event button released				
48:22.9	Audio recording disabled due to video buffering default				
53:58.4	Event button pressed				
53:58.5	Event button released				
53:58.6	Event button pressed				
53:58.6	Audio recording enabled due to video recording default				
53:58.7	Event button released				
53:58.7	Recording started due to button press	87	2		55.026 932260d382c04b7fbbb517e8c4f25208
54:09.5	Event button pressed				
54:12.5	Recording stopped due to button press	87	2		54.994 932260d382c04b7fbbb517e8c4f25208
54:13.0	Event button released				
54:13.4	Audio recording disabled due to video buffering default				
54:16.8	Event button pressed				
54:16.9	Event button released				
54:16.9	Event button pressed				
54:17.0	Audio recording enabled due to video recording default				
54:17.0	Event button released				

54:17.1 Recording started due to button press	87	3	54.983 d46b29978b3d4ff0bb79f3b0589cc62f
54:23.7 Event button pressed			
54:26.7 Recording stopped due to button press	87	3	54.956 d46b29978b3d4ff0bb79f3b0589cc62f
54:27.1 Event button released			
54:29.1 Audio recording disabled due to video buffering default			
59:29.3 Event button pressed			
59:29.4 Event button released			
59:29.4 Event button pressed			
59:29.5 Audio recording enabled due to video recording default			
59:29.5 Event button released			
59:29.6 Recording started due to button press	87	4	54.951 8a38db0180a84117bcf89ad7f031bf70
59:38.0 Event button pressed			
59:41.0 Recording stopped due to button press	87	4	54.925 8a38db0180a84117bcf89ad7f031bf70
59:41.3 Event button released			
59:41.9 Audio recording disabled due to video buffering default			
59:43.0 Event button pressed			
59:43.1 Event button released			
59:43.2 Event button pressed			
59:43.2 Audio recording enabled due to video recording default			
59:43.3 Event button released			
59:43.3 Recording started due to button press	87	5	54.92 63a1226d3d00422b8e192c34def9054d
00:23.3 Event button pressed			
00:23.4 Event button released			
00:23.5 Event button pressed			
00:23.6 Event button released			
00:24.1 Event button pressed			
00:27.1 Recording stopped due to button press	86	5	54.861 63a1226d3d00422b8e192c34def9054d
00:27.4 Event button released			
00:27.9 Audio recording disabled due to video buffering default			
01:30.7 Event button pressed			
01:30.9 Event button released			
01:30.9 Event button pressed			
01:31.0 Audio recording enabled due to video recording default			
01:31.0 Event button released			
01:31.1 Recording started due to button press	86	6	54.86 fcf76ae364704294a4b3e0b2c7d8f4ae
01:49.9 Event button pressed			
01:52.9 Recording stopped due to button press	86	6	54.817 fcf76ae364704294a4b3e0b2c7d8f4ae
01:53.3 Event button released			
01:53.8 Audio recording disabled due to video buffering default			
02:10.0 Event button pressed			
02:10.1 Event button released			
02:10.1 Event button pressed			
02:10.1 Audio recording enabled due to video recording default			
02:10.2 Event button released			
02:10.3 Recording started due to button press	86	7	54.816 6ba9d24b10e34059a21db104af56d67f
02:53.7 Event button pressed			
02:56.7 Recording stopped due to button press	86	7	54.784 6ba9d24b10e34059a21db104af56d67f

02:57.2	Event button released			
02:57.4	Audio recording disabled due to video buffering default			
09:40.7	Event button pressed			
09:40.8	Event button released			
09:40.9	Event button pressed			
09:40.9	Audio recording enabled due to video recording default			
09:40.9	Event button released			
09:41.0	Recording started due to button press	85	8	54.783 94883be5995a42bd81afdcc4f281cf4a
10:11.1	Event button pressed			
10:14.1	Recording stopped due to button press	85	8	54.711 94883be5995a42bd81afdcc4f281cf4a
10:14.5	Event button released			
10:15.0	Audio recording disabled due to video buffering default			
10:54.8	Event button pressed			
10:55.0	Event button released			
10:55.1	Event button pressed			
10:55.1	Audio recording enabled due to video recording default			
10:55.2	Event button released			
10:55.2	Recording started due to button press	85	9	54.705 17ea099ca0b948aa9772b65918fede0c
11:05.2	Event button pressed			
11:07.6	Event button released			
11:09.0	Event button pressed			
11:12.0	Recording stopped due to button press	85	9	54.676 17ea099ca0b948aa9772b65918fede0c
11:12.5	Event button released			
11:12.9	Audio recording disabled due to video buffering default			
11:14.9	Event button pressed			
11:15.1	Event button released			
11:15.2	Event button pressed			
11:15.2	Audio recording enabled due to video recording default			
11:15.3	Event button released			
11:15.3	Recording started due to button press	85	10	54.676 e40a80acee9b43ff9a59fc877edbcfab
11:27.4	Event button pressed			
11:30.4	Recording stopped due to button press	85	10	54.667 e40a80acee9b43ff9a59fc877edbcfab
11:31.2	Audio recording disabled due to video buffering default			
11:31.8	Event button released			
11:45.4	Event button pressed			
11:45.6	Event button released			
11:45.6	Event button pressed			
11:45.6	Audio recording enabled due to video recording default			
11:45.7	Event button released			
11:45.7	Recording started due to button press	85	11	54.666 f6ca9fc4d8324391a690cb666c1580be
11:58.4	Event button pressed			
12:01.4	Recording stopped due to button press	85	11	54.651 f6ca9fc4d8324391a690cb666c1580be
12:01.9	Event button released			
12:02.3	Audio recording disabled due to video buffering default			
12:13.0	Event button pressed			
12:13.1	Event button released			
12:13.2	Event button pressed			

12:13.2 Audio recording enabled due to video recording default			
12:13.3 Event button released			
12:13.4 Recording started due to button press	85	12	54.651 25e9d7c1339f4438b9682e90608b291f
12:23.9 Event button pressed			
12:26.9 Recording stopped due to button press	85	12	54.638 25e9d7c1339f4438b9682e90608b291f
12:27.3 Event button released			
12:27.7 Audio recording disabled due to video buffering default			
12:58.8 Event button pressed			
12:59.1 Event button released			
12:59.2 Event button pressed			
12:59.3 Audio recording enabled due to video recording default			
12:59.4 Event button released			
12:59.4 Recording started due to button press	85	13	54.638 14b7b96a524f4a70b6a3f425c83e8721
13:08.7 Event button pressed			
13:11.7 Recording stopped due to button press	85	13	54.616 14b7b96a524f4a70b6a3f425c83e8721
13:12.2 Event button released			
13:12.5 Audio recording disabled due to video buffering default			
13:15.7 Event button pressed			
13:15.9 Event button released			
13:15.9 Event button pressed			
13:15.9 Audio recording enabled due to video recording default			
13:16.0 Event button released			
13:16.0 Recording started due to button press	85	14	54.615 818aa00ab7a04e879b37c4ef0cd28153
13:36.2 Event button pressed			
13:39.2 Recording stopped due to button press	85	14	54.601 818aa00ab7a04e879b37c4ef0cd28153
13:39.7 Event button released			
13:40.1 Audio recording disabled due to video buffering default			
13:45.6 Event button pressed			
13:45.7 Event button released			
13:45.7 Event button pressed			
13:45.8 Audio recording enabled due to video recording default			
13:45.8 Event button released			
13:45.9 Recording started due to button press	85	15	54.601 751dfbbfccbe40698127974950bf6ac4
14:03.9 Event button pressed			
14:06.9 Recording stopped due to button press	84	15	54.587 751dfbbfccbe40698127974950bf6ac4
14:07.4 Event button released			
14:07.8 Audio recording disabled due to video buffering default			
14:10.7 Event button pressed			
14:10.9 Event button released			
14:11.0 Event button pressed			
14:11.0 Audio recording enabled due to video recording default			
14:11.1 Event button released			
14:11.1 Recording started due to button press	84	16	54.587 fa8c6f737a52406e8592a789d3e86f1c
14:31.3 Event button pressed			
14:34.3 Recording stopped due to button press	84	16	54.573 fa8c6f737a52406e8592a789d3e86f1c
14:34.8 Event button released			
14:35.2 Audio recording disabled due to video buffering default			

15:08.3 Event button pressed			
15:08.5 Event button released			
15:08.5 Event button pressed			
15:08.6 Audio recording enabled due to video recording default			
15:08.6 Event button released			
15:08.7 Recording started due to button press	84	17	54.572 de19c0dc29c24e6b899ec244d53a5b79
15:28.4 Event button pressed			
15:31.4 Recording stopped due to button press	84	17	54.544 de19c0dc29c24e6b899ec244d53a5b79
15:32.0 Event button released			
15:32.3 Audio recording disabled due to video buffering default			
15:34.3 Event button pressed			
15:34.4 Event button released			
15:34.5 Event button pressed			
15:34.5 Audio recording enabled due to video recording default			
15:34.6 Event button released			
15:34.6 Recording started due to button press	84	18	54.543 e6305d1416cb4147b0d25ef285a1cf6d
15:47.0 Event button pressed			
15:50.0 Recording stopped due to button press	84	18	54.535 e6305d1416cb4147b0d25ef285a1cf6d
15:50.4 Event button released			
15:50.9 Audio recording disabled due to video buffering default			
17:11.3 Event button pressed			
17:11.4 Event button released			
17:11.5 Event button pressed			
17:11.5 Audio recording enabled due to video recording default			
17:11.6 Event button released			
17:11.7 Recording started due to button press	84	19	54.534 741e734a6b9c4295b1a494a9c4fd2940
18:10.1 Audit log created	84	19 1.15.14	54.463
18:14.3 Event button pressed			
18:17.3 Recording stopped due to button press	84	19	54.459 741e734a6b9c4295b1a494a9c4fd2940
18:17.7 Event button released			
18:18.2 Audio recording disabled due to video buffering default			
20:43.4 Event button pressed			
20:43.6 Event button released			
20:43.7 Event button pressed			
20:43.7 Audio recording enabled due to video recording default			
20:43.8 Event button released			
20:43.9 Recording started due to button press	84	20	54.458 615955ef0679429aae0e40b11e71e10a
21:04.5 Event button pressed			
21:07.5 Recording stopped due to button press	84	20	54.405 615955ef0679429aae0e40b11e71e10a
21:08.0 Event button released			
21:08.3 Audio recording disabled due to video buffering default			
21:18.6 Event button pressed			
21:18.8 Event button released			
21:18.8 Event button pressed			
21:18.8 Audio recording enabled due to video recording default			
21:18.9 Event button released			
21:19.0 Recording started due to button press	84	21	54.387 0ce2da4e83a043c48d7d467f210766fa

21:35.9 Event button pressed			
21:39.0 Recording stopped due to button press	83	21	54.37 0ce2da4e83a043c48d7d467f210766fa
21:39.4 Event button released			
21:39.8 Audio recording disabled due to video buffering default			
21:54.9 Event button pressed			
21:55.1 Event button released			
21:55.1 Event button pressed			
21:55.1 Audio recording enabled due to video recording default			
21:55.2 Event button released			
21:55.2 Recording started due to button press	83	22	54.369 db1772e269e34d3296b86f4810cad86
22:07.0 Event button pressed			
22:10.0 Recording stopped due to button press	83	22	54.354 db1772e269e34d3296b86f4810cad86
22:10.7 Event button released			
22:10.9 Audio recording disabled due to video buffering default			
22:27.7 Event button pressed			
22:27.8 Event button released			
22:27.9 Event button pressed			
22:27.9 Audio recording enabled due to video recording default			
22:28.0 Event button released			
22:28.1 Recording started due to button press	83	23	54.353 74012fa195904f6dbc26d6196697897e
22:39.7 Event button pressed			
22:42.7 Recording stopped due to button press	83	23	54.337 74012fa195904f6dbc26d6196697897e
22:43.1 Event button released			
22:43.4 Audio recording disabled due to video buffering default			
23:00.0 Event button pressed			
23:00.1 Event button released			
23:00.2 Event button pressed			
23:00.2 Audio recording enabled due to video recording default			
23:00.3 Event button released			
23:00.3 Recording started due to button press	83	24	54.337 b8613f52acab413d99e956e203c012c7
23:17.0 Event button pressed			
23:20.0 Recording stopped due to button press	83	24	54.318 b8613f52acab413d99e956e203c012c7
23:20.4 Event button released			
23:20.7 Audio recording disabled due to video buffering default			
23:29.1 Event button pressed			
23:29.4 Event button released			
23:30.2 Event button pressed			
23:30.4 Event button released			
23:30.4 Event button pressed			
23:30.4 Audio recording enabled due to video recording default			
23:30.5 Event button released			
23:30.6 Recording started due to button press	83	25	54.318 58e6896651744bc9b2d7325c01d29480
23:40.3 Event button pressed			
23:43.3 Recording stopped due to button press	83	25	54.307 58e6896651744bc9b2d7325c01d29480
23:44.0 Event button released			
23:44.0 Audio recording disabled due to video buffering default			
23:46.2 Event button pressed			

23:46.3	Event button released			
23:46.4	Event button pressed			
23:46.4	Audio recording enabled due to video recording default			
23:46.5	Event button released			
23:46.5	Recording started due to button press	83	26	54.307 80e1f3db6afa40ee845d3769f6983786
24:13.5	Event button pressed			
24:16.5	Recording stopped due to button press	83	26	54.29 80e1f3db6afa40ee845d3769f6983786
24:17.0	Event button released			
24:17.2	Audio recording disabled due to video buffering default			
24:21.7	Event button pressed			
24:21.9	Event button released			
24:21.9	Event button pressed			
24:21.9	Audio recording enabled due to video recording default			
24:22.0	Event button released			
24:22.1	Recording started due to button press	83	27	54.289 8076ee10f69045d3bf091ba173a56168
25:04.3	Event button pressed			
25:07.3	Recording stopped due to button press	83	27	54.263 8076ee10f69045d3bf091ba173a56168
25:07.7	Event button released			
25:08.1	Audio recording disabled due to video buffering default			
25:11.2	Event button pressed			
25:11.3	Event button released			
25:11.4	Event button pressed			
25:11.4	Audio recording enabled due to video recording default			
25:11.5	Event button released			
25:11.5	Recording started due to button press	83	28	54.263 31509206b3ff4fe68d774ed9f0dd181d
26:14.5	Event button pressed			
26:17.5	Recording stopped due to button press	82	28	54.227 31509206b3ff4fe68d774ed9f0dd181d
26:18.0	Event button released			
26:18.2	Audio recording disabled due to video buffering default			
26:31.7	Event button pressed			
26:31.8	Event button released			
26:31.9	Event button pressed			
26:31.9	Audio recording enabled due to video recording default			
26:32.0	Event button released			
26:32.0	Recording started due to button press	82	28	54.226 d51a4dc6cefa4d65be3454b371fea9c1
27:14.6	Event button pressed			
27:17.6	Recording stopped due to button press	82	29	54.196 d51a4dc6cefa4d65be3454b371fea9c1
27:18.1	Event button released			
27:18.4	Audio recording disabled due to video buffering default			
27:28.4	Event button pressed			
27:28.6	Event button released			
27:28.6	Event button pressed			
27:28.6	Audio recording enabled due to video recording default			
27:28.7	Event button released			
27:28.8	Recording started due to button press	82	30	54.195 a3808e4dd436491eb71613baece6311a
27:43.2	Event button pressed			
27:46.2	Recording stopped due to button press	82	30	54.181 a3808e4dd436491eb71613baece6311a

27:46.8	Event button released			
27:47.0	Audio recording disabled due to video buffering default			
28:03.9	Event button pressed			
28:04.1	Event button released			
28:04.1	Event button pressed			
28:04.2	Audio recording enabled due to video recording default			
28:04.3	Event button released			
28:04.3	Recording started due to button press	82	31	54.181 c04f284eaae348d29b243e5a332a17ab
28:35.7	Event button pressed			
28:38.7	Recording stopped due to button press	82	31	54.154 c04f284eaae348d29b243e5a332a17ab
28:39.1	Event button released			
28:39.7	Audio recording disabled due to video buffering default			
29:34.1	Power button pressed			
29:34.8	Power button released			
29:39.9	Power button pressed			
29:43.0	Device powered off using button	82	31	54.154
29:43.4	Power button released			
38:03.1	Device powered on using button	82	31	54.153
38:04.9	Audio recording disabled due to video buffering default			
18:10.0	Audit log created	78	31 1.15.14	54.152
18:10.0	Audit log created	72	31 1.15.14	54.151
29:42.9	Event button pressed			
29:43.0	Event button released			
29:43.1	Event button pressed			
29:43.1	Audio recording enabled due to video recording default			
29:43.2	Event button released			
29:43.3	Recording started due to button press	71	32	54.15 bf2ad987e302443b93dad714195f5b57
30:00.7	Event button pressed			
30:03.7	Recording stopped due to button press	71	32	54.105 bf2ad987e302443b93dad714195f5b57
30:04.1	Event button released			
30:04.5	Audio recording disabled due to video buffering default			
30:09.4	Event button pressed			
30:09.5	Event button released			
30:09.6	Event button pressed			
30:09.6	Audio recording enabled due to video recording default			
30:09.7	Event button released			
30:09.7	Recording started due to button press	71	33	54.092 f32319f7dbb340f180a069ebecca886
30:31.3	Event button pressed			
30:34.3	Recording stopped due to button press	71	33	54.064 f32319f7dbb340f180a069ebecca886
30:34.7	Event button released			
30:35.1	Audio recording disabled due to video buffering default			
45:22.4	Axon application connected to device			
56:18.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1645 X6033271L' to 'Signal 15' using Axon applicator			d39fb12827c84a3886878ea331bbe913
56:18.6	Categories 'Customer Assist' added to video metadata using Axon applicator			d39fb12827c84a3886878ea331bbe913
57:08.7	Video played back using Axon application			932260d382c04b7fbbb517e8c4f25208
58:06.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1653 X6033271L' to 'Signal 75' using Axon applicator			932260d382c04b7fbbb517e8c4f25208
58:06.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			932260d382c04b7fbbb517e8c4f25208

58:43.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1654 X6033271L' to 'Signal 75' using Axon applicator			d46b29978b3d4ff0bb79f3b0589cc62f
58:43.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			d46b29978b3d4ff0bb79f3b0589cc62f
00:58.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1659 X6033271L' to 'Signal 75' using Axon applicator			8a38db0180a84117bcf89ad7f031bf70
00:58.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			8a38db0180a84117bcf89ad7f031bf70
01:30.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1659 X6033271L' to 'Signal 75' using Axon applicator			63a1226d3d00422b8e192c34def9054d
01:30.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			63a1226d3d00422b8e192c34def9054d
01:48.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1701 X6033271L' to 'Signal 75' using Axon applicator			fcf76ae364704294a4b3e0b2c7d8f4ae
01:48.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			fcf76ae364704294a4b3e0b2c7d8f4ae
02:11.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1702 X6033271L' to 'Signal 75' using Axon applicator			6ba9d24b10e34059a21db104af56d67f
02:11.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			6ba9d24b10e34059a21db104af56d67f
02:28.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1709 X6033271L' to 'Signal 75' using Axon applicator			94883be5995a42bd81afdcc4f281cf4a
02:28.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			94883be5995a42bd81afdcc4f281cf4a
02:44.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1710 X6033271L' to 'Signal 75' using Axon applicator			17ea099ca0b948aa9772b65918fede0c
02:44.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			17ea099ca0b948aa9772b65918fede0c
03:23.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1711 X6033271L' to 'Signal 75' using Axon applicator			e40a80acee9b43ff9a59fc877edbcfab
03:23.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			e40a80acee9b43ff9a59fc877edbcfab
03:53.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1711 X6033271L' to 'Signal 75' using Axon applicator			f6ca9fc4d8324391a690cb666c1580be
03:53.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			f6ca9fc4d8324391a690cb666c1580be
04:19.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1712 X6033271L' to 'Signal 75' using Axon applicator			25e9d7c1339f4438b9682e90608b291f
04:19.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			25e9d7c1339f4438b9682e90608b291f
04:40.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1712 X6033271L' to 'Signal 75' using Axon applicator			14b7b96a524f4a70b6a3f425c83e8721
04:40.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			14b7b96a524f4a70b6a3f425c83e8721
05:04.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1713 X6033271L' to 'Signal 75' using Axon applicator			818aa00ab7a04e879b37c4ef0cd28153
05:04.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			818aa00ab7a04e879b37c4ef0cd28153
05:23.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1713 X6033271L' to 'Signal 15' using Axon applicator			751dfbbfccbe40698127974950bf6ac4
05:23.2	Categories 'Customer Assist' added to video metadata using Axon applicator			751dfbbfccbe40698127974950bf6ac4
05:46.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1714 X6033271L' to 'Signal 15' using Axon applicator			fa8c6f737a52406e8592a789d3e86f1c
05:46.3	Categories 'Customer Assist' added to video metadata using Axon applicator			fa8c6f737a52406e8592a789d3e86f1c
06:08.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1715 X6033271L' to 'Signal 75' using Axon applicator			de19c0dc29c24e6b899ec244d53a5b79
06:08.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			de19c0dc29c24e6b899ec244d53a5b79
06:22.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1715 X6033271L' to 'Signal 15' using Axon applicator			e6305d1416cb4147b0d25ef285a1cf6d
06:22.4	Categories 'Customer Assist' added to video metadata using Axon applicator			e6305d1416cb4147b0d25ef285a1cf6d
06:40.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1717 X6033271L' to 'Signal 75' using Axon applicator			741e734a6b9c4295b1a494a9c4fd2940
06:40.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			741e734a6b9c4295b1a494a9c4fd2940
07:05.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1720 X6033271L' to 'Signal 75' using Axon applicator			615955ef0679429aae0e40b11e71e10a
07:05.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			615955ef0679429aae0e40b11e71e10a
07:42.9	Event button pressed			
07:43.0	Event button released			
07:43.1	Event button pressed			
07:43.1	Audio recording enabled due to video recording default			
07:43.2	Event button released			
07:43.2	Recording started due to button press	66	34	54.057 a6ba0725f8e44365af1062f00e746393
07:55.2	Event button pressed			
07:58.2	Recording stopped due to button press	66	34	54.023 a6ba0725f8e44365af1062f00e746393
07:58.6	Event button released			
07:59.0	Audio recording disabled due to video buffering default			
09:26.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1721 X6033271L' to 'Signal 75' using Axon applicator			Oce2da4e83a043c48d7d467f210766fa

09:26.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				Oce2da4e83a043c48d7d467f210766fa
11:21.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1721 X6033271L' to 'Signal 75' using Axon applicator				db1772e269e34d3296b86f4810cadc86
11:21.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				db1772e269e34d3296b86f4810cadc86
12:29.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1722 X6033271L' to 'Signal 75' using Axon applicator				74012fa195904f6dbc26d6196697897e
12:29.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				74012fa195904f6dbc26d6196697897e
14:45.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				b8613f52acab413d99e956e203c012c7
15:00.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1723 X6033271L' to 'Signal 75' using Axon applicator				b8613f52acab413d99e956e203c012c7
18:10.0	Audit log created	65	34	1.15.14	53.988
18:42.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1723 X6033271L' to 'Signal 75' using Axon applicator				58e6896651744bc9b2d7325c01d29480
18:42.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				58e6896651744bc9b2d7325c01d29480
19:01.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1723 X6033271L' to 'Signal 75' using Axon applicator				80e1f3db6afa40ee845d3769f6983786
19:01.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				80e1f3db6afa40ee845d3769f6983786
19:21.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1724 X6033271L' to 'Signal 75' using Axon applicator				8076ee10f69045d3bf091ba173a56168
19:21.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				8076ee10f69045d3bf091ba173a56168
19:40.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1725 X6033271L' to 'Signal 15' using Axon applicator				31509206b3ff4fe68d774ed9f0dd181d
19:40.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				31509206b3ff4fe68d774ed9f0dd181d
20:05.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1726 X6033271L' to 'Signal' using Axon applicator				d51a4dc6cefa4d65be3454b371fea9c1
20:05.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				d51a4dc6cefa4d65be3454b371fea9c1
20:17.9	Title changed in video metadata from 'Signal' to 'Signal 75' using Axon applicator				d51a4dc6cefa4d65be3454b371fea9c1
20:34.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1727 X6033271L' to 'Signal 75' using Axon applicator				a3808e4dd436491eb71613baece6311a
20:34.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				a3808e4dd436491eb71613baece6311a
20:59.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1728 X6033271L' to 'Signal 75' using Axon applicator				c04f284eae348d29b243e5a332a17ab
20:59.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				c04f284eae348d29b243e5a332a17ab
21:16.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1929 X6033271L' to 'Signal 75' using Axon applicator				bf2ad987e302443b93dad714195f5b57
21:16.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				bf2ad987e302443b93dad714195f5b57
21:31.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 1930 X6033271L' to 'Signal 75' using Axon applicator				f32319f7dbb340f180a069beacca886
21:31.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				f32319f7dbb340f180a069beacca886
21:50.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2007 X6033271L' to 'Signal 75' using Axon applicator				a6ba0725f8e44365af1062f00e746393
21:50.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				a6ba0725f8e44365af1062f00e746393
26:19.3	Event button pressed				
26:19.4	Event button released				
26:19.5	Event button pressed				
26:19.5	Audio recording enabled due to video recording default				
26:19.5	Event button released				
26:19.6	Recording started due to button press	64	35		53.987 eb2d3aab582348c0b534f310c9da388c
26:59.5	Event button pressed				
27:02.5	Recording stopped due to button press	64	35		53.905 eb2d3aab582348c0b534f310c9da388c
27:03.0	Event button released				
27:03.2	Audio recording disabled due to video buffering default				
27:09.8	Event button pressed				
27:09.9	Event button released				
27:09.9	Event button pressed				
27:09.9	Audio recording enabled due to video recording default				
27:10.0	Event button released				
27:10.1	Recording started due to button press	64	36		53.904 e68b5f0ecc6d4d3fbf4d480af90156ad
27:32.9	Event button pressed				
27:35.9	Recording stopped due to button press	64	36		53.887 e68b5f0ecc6d4d3fbf4d480af90156ad

27:36.3	Event button released			
27:36.7	Audio recording disabled due to video buffering default			
32:28.8	Event button pressed			
32:29.0	Event button released			
32:29.0	Event button pressed			
32:29.1	Audio recording enabled due to video recording default			
32:29.2	Event button released			
32:29.2	Recording started due to button press	63	37	53.886 3a71e83dc36249e088d1e3a98acae95e
33:01.9	Event button pressed			
33:04.9	Recording stopped due to button press	63	37	53.809 3a71e83dc36249e088d1e3a98acae95e
33:05.4	Event button released			
33:05.8	Audio recording disabled due to video buffering default			
36:37.1	Event button pressed			
36:37.3	Event button released			
36:37.4	Event button pressed			
36:37.4	Audio recording enabled due to video recording default			
36:37.5	Event button released			
36:37.5	Recording started due to button press	63	38	53.807 d320c32270d1404b8e035531680d5f8b
40:19.0	Event button pressed			
40:22.0	Recording stopped due to button press	62	38	53.629 d320c32270d1404b8e035531680d5f8b
40:22.6	Event button released			
40:23.0	Audio recording disabled due to video buffering default			
40:52.7	Event button pressed			
40:52.9	Event button released			
40:52.9	Event button pressed			
40:53.0	Audio recording enabled due to video recording default			
40:53.0	Event button released			
40:53.1	Recording started due to button press	62	39	53.628 e5ff3a895d2b4577a85a9ce68eee2faa
40:58.4	Event button pressed			
41:01.4	Recording stopped due to button press	62	39	53.61 e5ff3a895d2b4577a85a9ce68eee2faa
41:01.7	Event button released			
41:02.2	Audio recording disabled due to video buffering default			
45:31.2	Video played back using Axon application			eb2d3aab582348c0b534f310c9da388c
47:06.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2026 X6033271L' to 'Signal 75' using Axon applicator			eb2d3aab582348c0b534f310c9da388c
47:06.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			eb2d3aab582348c0b534f310c9da388c
47:30.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2027 X6033271L' to 'Signal 75' using Axon applicator			e68b5f0ecc6d4d3fbf4d480af90156ad
47:30.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			e68b5f0ecc6d4d3fbf4d480af90156ad
47:55.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2032 X6033271L' to 'Signal 75' using Axon applicator			3a71e83dc36249e088d1e3a98acae95e
47:55.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			3a71e83dc36249e088d1e3a98acae95e
48:24.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2036 X6033271L' to 'Signal 75' using Axon applicator			d320c32270d1404b8e035531680d5f8b
48:24.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			d320c32270d1404b8e035531680d5f8b
48:58.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2040 X6033271L' to 'Signal 75' using Axon applicator			e5ff3a895d2b4577a85a9ce68eee2faa
48:58.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			e5ff3a895d2b4577a85a9ce68eee2faa
49:17.0	Video played back using Axon application			e5ff3a895d2b4577a85a9ce68eee2faa
50:41.4	Title changed in video metadata from 'Signal 75' to 'Signal 15' using Axon application			e5ff3a895d2b4577a85a9ce68eee2faa
50:41.4	Categories 'Customer Assist' added to video metadata using Axon applicator			e5ff3a895d2b4577a85a9ce68eee2faa
50:41.4	Categories 'Miscellaneous' removed from video metadata using Axon applicator			e5ff3a895d2b4577a85a9ce68eee2faa

50:59.0	Video played back using Axon application				3a71e83dc36249e088d1e3a98acae95e
51:46.3	Title changed in video metadata from 'Signal 75' to 'Signal 15' using Axon application				3a71e83dc36249e088d1e3a98acae95e
51:46.3	Categories 'Customer Assist' added to video metadata using Axon applicator				3a71e83dc36249e088d1e3a98acae95e
51:46.3	Categories 'Miscellaneous' removed from video metadata using Axon applicator				3a71e83dc36249e088d1e3a98acae95e
58:23.1	Event button pressed				
58:23.3	Event button released				
58:23.4	Event button pressed				
58:23.4	Audio recording enabled due to video recording default				
58:23.5	Event button released				
58:23.5	Recording started due to button press	60	40	53.607	b8a017e67add4652a841cdee0412fc30
58:42.3	Event button pressed				
58:45.3	Recording stopped due to button press	60	40	53.557	b8a017e67add4652a841cdee0412fc30
58:45.9	Event button released				
58:46.2	Audio recording disabled due to video buffering default				
59:15.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2058 X6033271L' to 'Signal 15' using Axon applicator				b8a017e67add4652a841cdee0412fc30
59:15.9	Categories 'Customer Assist' added to video metadata using Axon applicator				b8a017e67add4652a841cdee0412fc30
59:38.8	Event button pressed				
59:38.9	Event button released				
59:38.9	Event button pressed				
59:39.0	Audio recording enabled due to video recording default				
59:39.0	Event button released				
59:39.1	Recording started due to button press	60	41	53.535	3ad9969cef7242fd8faba4230d707201
00:10.8	Event button pressed				
00:13.8	Recording stopped due to button press	60	41	53.49	3ad9969cef7242fd8faba4230d707201
00:14.3	Event button released				
00:14.7	Audio recording disabled due to video buffering default				
03:50.1	Event button pressed				
03:50.2	Event button released				
03:50.4	Event button pressed				
03:50.4	Audio recording enabled due to video recording default				
03:50.5	Event button released				
03:50.5	Recording started due to button press	59	42	53.49	30a3f3f861294fe2902c790e0e52e9f1
04:02.4	Event button pressed				
04:05.4	Recording stopped due to button press	59	42	53.455	30a3f3f861294fe2902c790e0e52e9f1
04:05.9	Event button released				
04:06.3	Audio recording disabled due to video buffering default				
18:10.0	Audit log created	58	42	1.15.14	53.421
21:05.9	Video played back using Axon application				63a1226d3d00422b8e192c34def9054d
29:07.9	Video played back using Axon application				14b7b96a524f4a70b6a3f425c83e8721
29:50.2	Video played back using Axon application				818aa00ab7a04e879b37c4ef0cd28153
46:50.0	Video played back using Axon application				3ad9969cef7242fd8faba4230d707201
47:20.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2059 X6033271L' to 'Signal 15' using Axon applicator				3ad9969cef7242fd8faba4230d707201
47:20.7	Categories 'Customer Assist' added to video metadata using Axon applicator				3ad9969cef7242fd8faba4230d707201
47:37.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-09 2103 X6033271L' to 'Signal 15' using Axon applicator				30a3f3f861294fe2902c790e0e52e9f1
47:37.8	Categories 'Customer Assist' added to video metadata using Axon applicator				30a3f3f861294fe2902c790e0e52e9f1
18:10.0	Audit log created	49	42	1.15.14	53.418
19:23.4	Axon application disconnected from device				

18:10.0 Audit log created	43	42 1.15.14	53.417
18:10.1 Audit log created	37	42 1.15.14	53.415
31:47.0 Volume up button pressed			
31:47.1 Volume up button released			
31:47.4 Volume changed to high from medium using button			
31:53.0 Volume down button pressed			
31:53.2 Volume down button released			
31:53.3 Volume changed to medium from high using button			
31:59.3 Camera connected to Axon Dock X62001W9H	36	42	53.431
31:59.3 Audit log rolled	35	42	53.415
31:59.3 Audit log created	35	42 1.15.14	53.415
32:00.1 Device connected to charger	35	42	53.415
32:15.0 Video upload started when camera was docked			d39fb12827c84a3886878ea331bbe913
32:24.6 Audit log successfully uploaded			
32:24.8 Audit log successfully uploaded and deleted from device	36	42	53.431
32:30.0 Date/Time synced to 09/10/2021 12:32:30.02 AM from 09/10/2021 12:32:29.39 AM			
32:40.2 Audit log successfully uploaded			
32:40.4 Audit log successfully uploaded and deleted from device	36	42	53.431
32:43.0 Audit log successfully uploaded			
32:43.2 Audit log successfully uploaded and deleted from device	36	42	53.431
32:59.6 Video successfully uploaded from device when dockec			d39fb12827c84a3886878ea331bbe913
32:59.9 Video deleted from device when docked	36	41	53.579 d39fb12827c84a3886878ea331bbe913
32:59.9 Audit log created	36	41 1.15.14	53.579
32:59.9 Audit log rolled	36	41	53.579
33:00.2 Video upload started when camera was docked			932260d382c04b7fbbb517e8c4f25208
33:09.4 Audit log successfully uploaded			
33:09.5 Audit log successfully uploaded and deleted from device	36	41	53.579
33:20.1 Video successfully uploaded from device when dockec			932260d382c04b7fbbb517e8c4f25208
33:20.3 Video deleted from device when docked	36	40	53.647 932260d382c04b7fbbb517e8c4f25208
33:20.3 Audit log created	36	40 1.15.14	53.647
33:20.3 Audit log rolled	36	40	53.647
33:20.6 Video upload started when camera was docked			d46b29978b3d4ff0bb79f3b0589cc62f
33:23.1 Video successfully uploaded from device when dockec			d46b29978b3d4ff0bb79f3b0589cc62f
33:23.3 Video deleted from device when docked	36	39	53.654 d46b29978b3d4ff0bb79f3b0589cc62f
33:23.4 Audit log rolled	36	39	53.654
33:23.4 Audit log created	36	39 1.15.14	53.654
33:23.6 Video upload started when camera was docked			8a38db0180a84117bcf89ad7f031bf70
33:29.7 Audit log successfully uploaded			
33:29.9 Audit log successfully uploaded and deleted from device	36	39	53.654
33:37.0 Audit log successfully uploaded			
33:37.2 Audit log successfully uploaded and deleted from device	36	39	53.654
33:42.2 Video successfully uploaded from device when dockec			8a38db0180a84117bcf89ad7f031bf70
33:42.4 Video deleted from device when docked	36	38	53.721 8a38db0180a84117bcf89ad7f031bf70
33:42.5 Audit log created	36	38 1.15.14	53.722
33:42.5 Audit log rolled	36	38	53.722
33:42.7 Video upload started when camera was docked			63a1226d3d00422b8e192c34def9054d
33:49.2 Video successfully uploaded from device when dockec			63a1226d3d00422b8e192c34def9054d

33:49.3	Video deleted from device when docked	36	37	53.746	63a1226d3d00422b8e192c34def9054d
33:49.4	Audit log created	36	37 1.15.14	53.746	
33:49.4	Audit log rolled	36	37	53.746	
33:49.6	Video upload started when camera was docked				fcf76ae364704294a4b3e0b2c7d8f4ae
33:55.3	Audit log successfully uploaded				
33:55.5	Audit log successfully uploaded and deleted from device	36	37	53.746	
34:01.5	Video successfully uploaded from device when docked				fcf76ae364704294a4b3e0b2c7d8f4ae
34:01.7	Video deleted from device when docked	36	36	53.789	fcf76ae364704294a4b3e0b2c7d8f4ae
34:01.7	Audit log rolled	36	36	53.79	
34:01.7	Audit log created	36	36 1.15.14	53.79	
34:02.0	Video upload started when camera was docked				6ba9d24b10e34059a21db104af56d67f
34:11.3	Video successfully uploaded from device when docked				6ba9d24b10e34059a21db104af56d67f
34:11.5	Video deleted from device when docked	37	35	53.822	6ba9d24b10e34059a21db104af56d67f
34:11.6	Audit log created	37	35 1.15.14	53.823	
34:11.6	Audit log rolled	37	35	53.823	
34:11.8	Video upload started when camera was docked				94883be5995a42bd81afdcc4f281cf4a
34:24.6	Audit log successfully uploaded				
34:24.7	Audit log successfully uploaded and deleted from device	37	35	53.823	
34:27.9	Audit log successfully uploaded				
34:28.1	Audit log successfully uploaded and deleted from device	37	35	53.823	
34:31.3	Audit log successfully uploaded				
34:31.5	Audit log successfully uploaded and deleted from device	37	35	53.823	
34:34.8	Video successfully uploaded from device when docked				94883be5995a42bd81afdcc4f281cf4a
34:35.0	Video deleted from device when docked	37	34	53.901	94883be5995a42bd81afdcc4f281cf4a
34:35.0	Audit log created	37	34 1.15.14	53.901	
34:35.0	Audit log rolled	37	34	53.901	
34:35.2	Video upload started when camera was docked				17ea099ca0b948aa9772b65918fede0c
34:37.6	Audit log successfully uploaded				
34:37.8	Audit log successfully uploaded and deleted from device	37	34	53.901	
34:44.4	Video successfully uploaded from device when docked				17ea099ca0b948aa9772b65918fede0c
34:44.6	Video deleted from device when docked	37	33	53.93	17ea099ca0b948aa9772b65918fede0c
34:44.6	Audit log created	37	33 1.15.14	53.93	
34:44.6	Audit log rolled	37	33	53.93	
34:44.9	Video upload started when camera was docked				e40a80acee9b43ff9a59fc877edbcfab
34:47.9	Audit log successfully uploaded				
34:48.1	Audit log successfully uploaded and deleted from device	37	33	53.93	
34:48.8	Video successfully uploaded from device when docked				e40a80acee9b43ff9a59fc877edbcfab
34:49.0	Video deleted from device when docked	37	32	53.939	e40a80acee9b43ff9a59fc877edbcfab
34:49.1	Audit log rolled	37	32	53.94	
34:49.1	Audit log created	37	32 1.15.14	53.94	
34:49.3	Video upload started when camera was docked				f6ca9fc4d8324391a690cb666c1580be
34:51.3	Audit log successfully uploaded				
34:51.5	Audit log successfully uploaded and deleted from device	37	32	53.939	
34:54.1	Video successfully uploaded from device when docked				f6ca9fc4d8324391a690cb666c1580be
34:54.3	Video deleted from device when docked	37	31	53.955	f6ca9fc4d8324391a690cb666c1580be
34:54.4	Audit log rolled	37	31	53.955	
34:54.4	Audit log created	37	31 1.15.14	53.955	

34:54.6	Video upload started when camera was docked			25e9d7c1339f4438b9682e90608b291f
35:04.7	Video successfully uploaded from device when docked			25e9d7c1339f4438b9682e90608b291f
35:04.9	Video deleted from device when docked	37	30	53.968 25e9d7c1339f4438b9682e90608b291f
35:05.0	Audit log created	37	30 1.15.14	53.968
35:05.0	Audit log rolled	37	30	53.968
35:05.3	Video upload started when camera was docked			14b7b96a524f4a70b6a3f425c83e8721
35:08.6	Audit log successfully uploaded			
35:08.8	Audit log successfully uploaded and deleted from device	37	30	53.968
35:12.2	Video successfully uploaded from device when docked			14b7b96a524f4a70b6a3f425c83e8721
35:12.5	Video deleted from device when docked	37	29	53.99 14b7b96a524f4a70b6a3f425c83e8721
35:12.6	Audit log rolled	37	29	53.991
35:12.6	Audit log created	37	29 1.15.14	53.991
35:13.0	Video upload started when camera was docked			818aa00ab7a04e879b37c4ef0cd28153
35:18.8	Video successfully uploaded from device when docked			818aa00ab7a04e879b37c4ef0cd28153
35:19.0	Video deleted from device when docked	37	28	54.005 818aa00ab7a04e879b37c4ef0cd28153
35:19.0	Audit log rolled	37	28	54.005
35:19.0	Audit log created	37	28 1.15.14	54.005
35:19.2	Video upload started when camera was docked			751dfbbfccbe40698127974950bf6ac4
35:21.9	Audit log successfully uploaded			
35:22.1	Audit log successfully uploaded and deleted from device	37	28	54.005
35:24.3	Video successfully uploaded from device when docked			751dfbbfccbe40698127974950bf6ac4
35:24.5	Video deleted from device when docked	37	27	54.019 751dfbbfccbe40698127974950bf6ac4
35:24.6	Audit log created	37	27 1.15.14	54.019
35:24.6	Audit log rolled	37	27	54.019
35:24.8	Video upload started when camera was docked			fa8c6f737a52406e8592a789d3e86f1c
35:30.8	Video successfully uploaded from device when docked			fa8c6f737a52406e8592a789d3e86f1c
35:31.0	Video deleted from device when docked	37	26	54.033 fa8c6f737a52406e8592a789d3e86f1c
35:31.1	Audit log created	37	26 1.15.14	54.033
35:31.1	Audit log rolled	37	26	54.033
35:31.3	Video upload started when camera was docked			de19c0dc29c24e6b899ec244d53a5b79
35:39.8	Video successfully uploaded from device when docked			de19c0dc29c24e6b899ec244d53a5b79
35:40.0	Video deleted from device when docked	37	25	54.062 de19c0dc29c24e6b899ec244d53a5b79
35:40.1	Audit log rolled	37	25	54.067
35:40.1	Audit log created	37	25 1.15.14	54.067
35:40.3	Audit log successfully uploaded			
35:40.3	Video upload started when camera was docked			e6305d1416cb4147b0d25ef285a1cf6d
35:40.6	Audit log successfully uploaded and deleted from device	37	25	54.067
35:44.2	Video successfully uploaded from device when docked			e6305d1416cb4147b0d25ef285a1cf6d
35:44.5	Video deleted from device when docked	37	24	54.077 e6305d1416cb4147b0d25ef285a1cf6d
35:44.6	Audit log rolled	37	24	54.077
35:44.6	Audit log created	37	24 1.15.14	54.077
35:44.8	Video upload started when camera was docked			741e734a6b9c4295b1a494a9c4fd2940
35:45.7	Audit log successfully uploaded			
35:45.9	Audit log successfully uploaded and deleted from device	37	24	54.077
35:50.0	Audit log successfully uploaded			
35:50.2	Audit log successfully uploaded and deleted from device	37	24	54.077
36:07.2	Video successfully uploaded from device when docked			741e734a6b9c4295b1a494a9c4fd2940

36:07.4 Video deleted from device when docked	37	23	54.152	741e734a6b9c4295b1a494a9c4fd2940
36:07.5 Audit log rolled	37	23	54.157	
36:07.5 Audit log created	37	23 1.15.14	54.157	
36:07.7 Video upload started when camera was docked				615955ef0679429aae0e40b11e71e10a
36:11.3 Audit log successfully uploaded				
36:11.5 Audit log successfully uploaded and deleted from device	37	23	54.157	
36:29.4 Video successfully uploaded from device when docked				615955ef0679429aae0e40b11e71e10a
36:29.7 Video deleted from device when docked	37	22	54.23	615955ef0679429aae0e40b11e71e10a
36:29.7 Audit log rolled	37	22	54.23	
36:29.7 Audit log created	37	22 1.15.14	54.23	
36:30.0 Video upload started when camera was docked				Oce2da4e83a043c48d7d467f210766fa
36:35.0 Video successfully uploaded from device when docked				Oce2da4e83a043c48d7d467f210766fa
36:35.2 Video deleted from device when docked	37	21	54.246	Oce2da4e83a043c48d7d467f210766fa
36:35.2 Audit log created	37	21 1.15.14	54.246	
36:35.2 Audit log rolled	37	21	54.246	
36:35.4 Video upload started when camera was docked				db1772e269e34d3296b86f4810cad86
36:37.6 Audit log successfully uploaded				
36:37.8 Audit log successfully uploaded and deleted from device	37	21	54.246	
36:40.2 Video successfully uploaded from device when docked				db1772e269e34d3296b86f4810cad86
36:40.3 Video deleted from device when docked	38	20	54.261	db1772e269e34d3296b86f4810cad86
36:40.4 Audit log rolled	38	20	54.261	
36:40.4 Audit log created	38	20 1.15.14	54.261	
36:40.6 Video upload started when camera was docked				74012fa195904f6dbc26d6196697897e
36:45.7 Video successfully uploaded from device when docked				74012fa195904f6dbc26d6196697897e
36:45.9 Video deleted from device when docked	38	19	54.277	74012fa195904f6dbc26d6196697897e
36:46.0 Audit log created	38	19 1.15.14	54.278	
36:46.0 Audit log rolled	38	19	54.278	
36:46.2 Video upload started when camera was docked				b8613f52acab413d99e956e203c012c7
36:51.8 Video successfully uploaded from device when docked				b8613f52acab413d99e956e203c012c7
36:52.0 Video deleted from device when docked	38	18	54.296	b8613f52acab413d99e956e203c012c7
36:52.0 Audit log created	38	18 1.15.14	54.296	
36:52.0 Audit log rolled	38	18	54.296	
36:52.3 Video upload started when camera was docked				58e6896651744bc9b2d7325c01d29480
36:56.0 Video successfully uploaded from device when docked				58e6896651744bc9b2d7325c01d29480
36:56.2 Video deleted from device when docked	38	17	54.307	58e6896651744bc9b2d7325c01d29480
36:56.2 Audit log created	38	17 1.15.14	54.307	
36:56.2 Audit log rolled	38	17	54.307	
36:56.4 Video upload started when camera was docked				80e1f3db6afa40ee845d3769f6983786
37:02.7 Video successfully uploaded from device when docked				80e1f3db6afa40ee845d3769f6983786
37:02.9 Video deleted from device when docked	38	16	54.324	80e1f3db6afa40ee845d3769f6983786
37:02.9 Audit log rolled	38	16	54.324	
37:02.9 Audit log created	38	16 1.15.14	54.324	
37:03.3 Video upload started when camera was docked				8076ee10f69045d3bf091ba173a56168
37:04.9 Audit log successfully uploaded				
37:05.1 Audit log successfully uploaded and deleted from device	38	16	54.324	
37:12.0 Video successfully uploaded from device when docked				8076ee10f69045d3bf091ba173a56168
37:12.2 Video deleted from device when docked	38	15	54.35	8076ee10f69045d3bf091ba173a56168

37:12.2 Audit log created	38	15 1.15.14	54.35	
37:12.2 Audit log rolled	38	15	54.35	
37:12.5 Video upload started when camera was docked				31509206b3ff4fe68d774ed9f0dd181d
37:18.3 Audit log successfully uploaded				
37:18.6 Audit log successfully uploaded and deleted from device	38	15	54.35	
37:22.9 Video successfully uploaded from device when docked				31509206b3ff4fe68d774ed9f0dd181d
37:23.1 Video deleted from device when docked	38	14	54.387	31509206b3ff4fe68d774ed9f0dd181d
37:23.1 Audit log created	38	14 1.15.14	54.387	
37:23.1 Audit log rolled	38	14	54.387	
37:23.3 Video upload started when camera was docked				d51a4dc6cefa4d65be3454b371fea9c1
37:24.7 Audit log successfully uploaded				
37:24.8 Audit log successfully uploaded and deleted from device	38	14	54.387	
37:32.3 Video successfully uploaded from device when docked				d51a4dc6cefa4d65be3454b371fea9c1
37:32.5 Video deleted from device when docked	38	13	54.417	d51a4dc6cefa4d65be3454b371fea9c1
37:32.6 Audit log created	38	13 1.15.14	54.417	
37:32.6 Audit log rolled	38	13	54.417	
37:32.8 Video upload started when camera was docked				a3808e4dd436491eb71613baece6311a
37:37.4 Video successfully uploaded from device when docked				a3808e4dd436491eb71613baece6311a
37:37.5 Video deleted from device when docked	38	12	54.432	a3808e4dd436491eb71613baece6311a
37:37.6 Audit log created	38	12 1.15.14	54.432	
37:37.6 Audit log rolled	38	12	54.432	
37:37.8 Video upload started when camera was docked				c04f284eae348d29b243e5a332a17ab
37:38.0 Audit log successfully uploaded				
37:38.2 Audit log successfully uploaded and deleted from device	38	12	54.432	
37:45.5 Video successfully uploaded from device when docked				c04f284eae348d29b243e5a332a17ab
37:45.8 Video deleted from device when docked	38	11	54.458	c04f284eae348d29b243e5a332a17ab
37:45.8 Audit log created	38	11 1.15.14	54.458	
37:45.8 Audit log rolled	38	11	54.458	
37:46.1 Video upload started when camera was docked				bf2ad987e302443b93dad714195f5b57
38:06.3 Audit log successfully uploaded				
38:06.5 Audit log successfully uploaded and deleted from device	38	11	54.458	
38:08.8 Video successfully uploaded from device when docked				bf2ad987e302443b93dad714195f5b57
38:09.0 Video deleted from device when docked	38	10	54.529	bf2ad987e302443b93dad714195f5b57
38:09.1 Audit log rolled	38	10	54.529	
38:09.1 Audit log created	38	10 1.15.14	54.529	
38:09.4 Video upload started when camera was docked				f32319f7dbb340f180a069ebecca886
38:14.7 Video successfully uploaded from device when docked				f32319f7dbb340f180a069ebecca886
38:14.9 Video deleted from device when docked	38	9	54.545	f32319f7dbb340f180a069ebecca886
38:15.0 Audit log rolled	38	9	54.545	
38:15.0 Audit log created	38	9 1.15.14	54.545	
38:15.2 Video upload started when camera was docked				a6ba0725f8e44365af1062f00e746393
38:16.6 Audit log successfully uploaded				
38:16.8 Audit log successfully uploaded and deleted from device	38	9	54.545	
38:21.9 Audit log successfully uploaded				
38:22.1 Audit log successfully uploaded and deleted from device	39	9	54.545	
38:35.7 Video successfully uploaded from device when docked				a6ba0725f8e44365af1062f00e746393
38:35.9 Video deleted from device when docked	39	8	54.613	a6ba0725f8e44365af1062f00e746393

38:36.0	Audit log rolled	39	8	54.613	
38:36.0	Audit log created	39	8 1.15.14	54.613	
38:36.2	Video upload started when camera was docked				eb2d3aab582348c0b534f310c9da388c
38:44.3	Audit log successfully uploaded				
38:44.5	Audit log successfully uploaded and deleted from device	39	8	54.613	
38:56.6	Audit log successfully uploaded				
38:56.8	Audit log successfully uploaded and deleted from device	39	8	54.613	
38:58.3	Video successfully uploaded from device when docked				eb2d3aab582348c0b534f310c9da388c
38:58.5	Video deleted from device when docked	39	7	54.696	eb2d3aab582348c0b534f310c9da388c
38:58.6	Audit log created	39	7 1.15.14	54.697	
38:58.6	Audit log rolled	39	7	54.697	
38:58.9	Video upload started when camera was docked				e68b5f0ecc6d4d3fbf4d480af90156ad
39:04.0	Video successfully uploaded from device when docked				e68b5f0ecc6d4d3fbf4d480af90156ad
39:04.2	Video deleted from device when docked	39	6	54.713	e68b5f0ecc6d4d3fbf4d480af90156ad
39:04.3	Audit log rolled	39	6	54.713	
39:04.3	Audit log created	39	6 1.15.14	54.713	
39:04.5	Video upload started when camera was docked				3a71e83dc36249e088d1e3a98acae95e
39:18.9	Audit log successfully uploaded				
39:19.1	Audit log successfully uploaded and deleted from device	39	6	54.713	
39:27.3	Video successfully uploaded from device when docked				3a71e83dc36249e088d1e3a98acae95e
39:27.6	Video deleted from device when docked	39	5	54.793	3a71e83dc36249e088d1e3a98acae95e
39:27.6	Audit log created	39	5 1.15.14	54.793	
39:27.6	Audit log rolled	39	5	54.793	
39:27.9	Video upload started when camera was docked				d320c32270d1404b8e035531680d5f8b
39:39.2	Audit log successfully uploaded				
39:39.4	Audit log successfully uploaded and deleted from device	39	5	54.793	
40:03.5	Audit log successfully uploaded				
40:03.7	Audit log successfully uploaded and deleted from device	39	5	54.793	
40:17.4	Video successfully uploaded from device when docked				d320c32270d1404b8e035531680d5f8b
40:17.7	Video deleted from device when docked	39	4	54.971	d320c32270d1404b8e035531680d5f8b
40:17.7	Audit log rolled	39	4	54.971	
40:17.7	Audit log created	39	4 1.15.14	54.971	
40:18.0	Video upload started when camera was docked				e5ff3a895d2b4577a85a9ce68eee2faa
40:21.8	Audit log successfully uploaded				
40:22.0	Audit log successfully uploaded and deleted from device	39	4	54.971	
40:23.6	Video successfully uploaded from device when docked				e5ff3a895d2b4577a85a9ce68eee2faa
40:23.8	Video deleted from device when docked	39	3	54.99	e5ff3a895d2b4577a85a9ce68eee2faa
40:23.8	Audit log created	39	3 1.15.14	54.99	
40:23.8	Audit log rolled	39	3	54.99	
40:24.0	Video upload started when camera was docked				b8a017e67add4652a841cdee0412fc30
40:46.3	Video successfully uploaded from device when docked				b8a017e67add4652a841cdee0412fc30
40:46.6	Video deleted from device when docked	39	2	55.062	b8a017e67add4652a841cdee0412fc30
40:46.6	Audit log created	39	2 1.15.14	55.062	
40:46.6	Audit log rolled	39	2	55.062	
40:46.9	Video upload started when camera was docked				3ad9969cef7242fd8faba4230d707201
40:50.2	Audit log successfully uploaded				
40:50.3	Audit log successfully uploaded and deleted from device	39	2	55.062	

40:58.5	Audit log successfully uploaded			
40:58.7	Audit log successfully uploaded and deleted from device	40	2	55.062
40:59.5	Video successfully uploaded from device when docked			3ad9969cef7242fd8faba4230d707201
40:59.7	Video deleted from device when docked	40	1	55.107 3ad9969cef7242fd8faba4230d707201
40:59.8	Audit log created	40	1 1.15.14	55.107
40:59.8	Audit log rolled	40	1	55.107
41:00.0	Video upload started when camera was docked			30a3f3f861294fe2902c790e0e52e9f1
41:07.8	Audit log successfully uploaded			
41:08.0	Audit log successfully uploaded and deleted from device	40	1	55.107
41:17.1	Audit log successfully uploaded			
41:17.3	Audit log successfully uploaded and deleted from device	40	1	55.107
41:19.6	Video successfully uploaded from device when docked			30a3f3f861294fe2902c790e0e52e9f1
41:19.7	Video deleted from device when docked	40	0	55.175 30a3f3f861294fe2902c790e0e52e9f1
41:19.8	Audit log rolled	40	0	55.175
41:19.8	Audit log created	40	0 1.15.14	55.175
41:19.8	Audit log rolled	40	0	55.175
41:19.8	Audit log created	40	0 1.15.14	55.175
41:30.5	Audit log successfully uploaded			
41:30.7	Audit log successfully uploaded and deleted from device	40	0	55.175
41:40.9	Audit log successfully uploaded			
41:41.0	Audit log successfully uploaded and deleted from device	40	0	55.175
41:59.2	Audit log successfully uploaded			
41:59.4	Audit log successfully uploaded and deleted from device	40	0	55.175
42:02.5	Audit log successfully uploaded			
42:02.7	Audit log successfully uploaded and deleted from device	40	0	55.175
42:02.9	Audit log successfully uploaded			
42:03.1	Audit log successfully uploaded and deleted from device	40	0	55.175
42:12.2	Audit log successfully uploaded			
42:12.4	Audit log successfully uploaded and deleted from device	40	0	55.175
42:30.6	Audit log successfully uploaded			
42:30.7	Audit log successfully uploaded and deleted from device	40	0	55.175
42:35.0	Audit log successfully uploaded			
42:35.2	Audit log successfully uploaded and deleted from device	41	0	55.175
42:54.3	Audit log successfully uploaded			
42:54.5	Audit log successfully uploaded and deleted from device	41	0	55.175
43:23.6	Audit log successfully uploaded			
43:23.8	Audit log successfully uploaded and deleted from device	41	0	55.175
43:42.0	Audit log successfully uploaded			
43:42.1	Audit log successfully uploaded and deleted from device	41	0	55.175
43:55.3	Audit log successfully uploaded			
43:55.5	Audit log successfully uploaded and deleted from device	41	0	55.175
44:00.7	Audit log successfully uploaded			
44:00.9	Audit log successfully uploaded and deleted from device	41	0	55.175
48:58.4	Device disconnected from charger	43	0	55.175
48:59.4	Device connected to charger	43	0	55.176
49:26.9	Audit log successfully uploaded			
49:27.1	Audit log successfully uploaded and deleted from device	44	0	55.176

49:30.2	Audit log successfully uploaded			
49:30.4	Audit log successfully uploaded and deleted from device	44	0	55.176
49:57.5	Audit log successfully uploaded			
49:57.7	Audit log successfully uploaded and deleted from device	44	0	55.176
50:02.9	Audit log successfully uploaded			
50:03.1	Audit log successfully uploaded and deleted from device	44	0	55.176
50:25.2	Audit log successfully uploaded			
50:25.4	Audit log successfully uploaded and deleted from device	44	0	55.176
50:34.5	Audit log successfully uploaded			
50:34.7	Audit log successfully uploaded and deleted from device	44	0	55.176
50:57.9	Audit log successfully uploaded			
50:58.1	Audit log successfully uploaded and deleted from device	44	0	55.176
51:08.2	Audit log successfully uploaded			
51:08.4	Audit log successfully uploaded and deleted from device	44	0	55.176
51:19.5	Audit log successfully uploaded			
51:19.7	Audit log successfully uploaded and deleted from device	44	0	55.176
51:47.8	Audit log successfully uploaded			
51:48.0	Audit log successfully uploaded and deleted from device	45	0	55.176
51:49.1	Audit log successfully uploaded			
51:49.3	Audit log successfully uploaded and deleted from device	45	0	55.176
52:10.5	Audit log successfully uploaded			
52:10.7	Audit log successfully uploaded and deleted from device	45	0	55.176
52:26.8	Audit log successfully uploaded			
52:27.0	Audit log successfully uploaded and deleted from device	45	0	55.176
52:36.2	Audit log successfully uploaded			
52:36.4	Audit log successfully uploaded and deleted from device	45	0	55.176
53:01.6	Audit log successfully uploaded			
53:01.8	Audit log successfully uploaded and deleted from device	45	0	55.176
53:26.4	Audit log successfully uploaded			
53:26.6	Audit log successfully uploaded and deleted from device	46	0	55.176
53:54.7	Audit log successfully uploaded			
53:54.9	Audit log successfully uploaded and deleted from device	46	0	55.176
53:58.0	Audit log successfully uploaded			
53:58.2	Audit log successfully uploaded and deleted from device	46	0	55.176
54:25.3	Audit log successfully uploaded			
54:25.5	Audit log successfully uploaded and deleted from device	46	0	55.176
54:37.6	Audit log successfully uploaded			
54:37.8	Audit log successfully uploaded and deleted from device	46	0	55.176
54:51.9	Audit log successfully uploaded			
54:52.1	Audit log successfully uploaded and deleted from device	46	0	55.176
54:52.2	Audit log successfully uploaded			
54:52.4	Audit log successfully uploaded and deleted from device	46	0	55.176
55:17.5	Audit log successfully uploaded			
55:17.7	Audit log successfully uploaded and deleted from device	46	0	55.176
55:33.8	Audit log successfully uploaded			
55:34.0	Audit log successfully uploaded and deleted from device	46	0	55.176
55:49.1	Audit log successfully uploaded			

55:49.3 Audit log successfully uploaded and deleted from device	46	0	55.176
56:16.5 Audit log successfully uploaded			
56:16.6 Audit log successfully uploaded and deleted from device	47	0	55.176
56:36.8 Audit log successfully uploaded			
56:36.9 Audit log successfully uploaded and deleted from device	47	0	55.176
56:44.0 Audit log successfully uploaded			
56:44.3 Audit log successfully uploaded and deleted from device	47	0	55.176
56:48.4 Audit log successfully uploaded			
56:48.6 Audit log successfully uploaded and deleted from device	47	0	55.176
57:05.7 Audit log successfully uploaded			
57:05.9 Audit log successfully uploaded and deleted from device	47	0	55.176
57:25.1 Audit log successfully uploaded			
57:25.3 Audit log successfully uploaded and deleted from device	47	0	55.176
57:50.4 Audit log successfully uploaded			
57:50.6 Audit log successfully uploaded and deleted from device	47	0	55.176
58:07.7 Audit log successfully uploaded			
58:07.9 Audit log successfully uploaded and deleted from device	47	0	55.176
58:23.0 Audit log successfully uploaded			
58:23.2 Audit log successfully uploaded and deleted from device	47	0	55.176
58:51.4 Device disconnected from charger	48	0	55.176
58:51.4 Camera disconnected from Axon Dock X62001W9H	48	0	55.176
08:45.4 Power button pressed			
08:48.4 Device powered off using button	47	0	55.185
08:48.9 Power button released			
41:16.0 Device powered on due to charger connection	47	0	55.185
41:16.2 Device connected to charger			
41:16.3 Camera connected to Axon Dock X630020W7	47	0	55.185
41:16.3 Audit log created		1.15.14	
41:16.3 Audit log rolled			
41:17.0 Camera connected to Axon Dock X630020W7	47	0	55.185
41:18.9 Audit log created	47	0 1.15.14	55.185
41:18.9 Audit log rolled	47	0	55.185
41:18.0 Audit log created	75	0 1.15.14	55.185
41:18.0 Audit log created	98	0 1.15.14	55.184
41:18.0 Audit log created	100	0 1.15.14	55.184
41:18.0 Audit log created	100	0 1.15.14	55.184
41:18.0 Audit log created	100	0 1.15.14	55.183
41:18.0 Audit log created	100	0 1.15.14	55.183
41:18.0 Audit log created	100	0 1.15.14	55.183
41:18.1 Audit log created	100	0 1.15.14	55.183
41:18.1 Audit log created	100	0 1.15.14	55.182
41:18.1 Audit log created	100	0 1.15.14	55.182
41:18.1 Audit log created	100	0 1.15.14	55.182
41:18.1 Audit log created	100	0 1.15.14	55.182
41:18.1 Audit log created	100	0 1.15.14	55.181
41:18.1 Audit log created	100	0 1.15.14	55.187
41:18.1 Audit log created	100	0 1.15.14	55.188

41:18.1 Audit log created	100	0 1.15.14	55.192
41:18.1 Audit log created	100	0 1.15.14	55.191
41:18.1 Audit log created	100	0 1.15.14	55.191
41:18.2 Audit log created	100	0 1.15.14	55.19
41:18.2 Audit log created	100	0 1.15.14	55.19
41:18.2 Audit log created	100	0 1.15.14	55.19
41:18.2 Audit log created	100	0 1.15.14	55.189
41:18.2 Audit log created	100	0 1.15.14	55.189
41:18.2 Audit log created	100	0 1.15.14	55.188
41:18.2 Audit log created	100	0 1.15.14	55.188
41:18.2 Audit log created	100	0 1.15.14	55.187
41:18.2 Audit log created	100	0 1.15.14	55.187
41:18.2 Audit log created	100	0 1.15.14	55.186
41:18.2 Audit log created	100	0 1.15.14	55.186
41:18.2 Audit log created	100	0 1.15.14	55.185
41:18.3 Audit log created	100	0 1.15.14	55.185
41:18.3 Audit log created	100	0 1.15.14	55.185
41:18.3 Audit log created	100	0 1.15.14	55.184
41:18.3 Audit log created	100	0 1.15.14	55.183
41:18.3 Audit log created	100	0 1.15.14	55.183
41:18.3 Audit log created	100	0 1.15.14	55.183
41:18.3 Audit log created	100	0 1.15.14	55.182
47:04.0 Device disconnected from charger	99	0	55.182
47:04.4 Camera disconnected from Axon Dock X630020W7	100	0	55.182
47:04.5 Audio recording disabled due to video buffering default			
41:18.3 Audit log created	93	0 1.15.14	55.181
41:18.3 Audit log created	87	0 1.15.14	55.179
00:36.4 Event button pressed			
00:36.5 Event button released			
00:36.6 Event button pressed			
00:36.6 Audio recording enabled due to video recording default			
00:36.7 Event button released			
00:36.9 Recording started due to button press	85	0	55.179 83c88402b9b74007a7d96261c488766a
00:49.4 Event button pressed			
00:52.4 Recording stopped due to button press	85	1	55.144 83c88402b9b74007a7d96261c488766a
00:52.8 Event button released			
00:53.4 Audio recording disabled due to video buffering default			
01:18.5 Event button pressed			
01:18.6 Event button released			
01:18.7 Event button pressed			
01:18.7 Audio recording enabled due to video recording default			
01:18.8 Event button released			
01:18.8 Recording started due to button press	85	2	55.11 12adc7fb68ee473b8398b81ccab55708
03:22.7 Event button pressed			
03:25.7 Recording stopped due to button press	84	2	55.031 12adc7fb68ee473b8398b81ccab55708
03:26.3 Event button released			
03:26.5 Audio recording disabled due to video buffering default			

04:04.3	Event button pressed				
04:04.4	Event button released				
04:04.5	Event button pressed				
04:04.5	Audio recording enabled due to video recording default				
04:04.6	Event button released				
04:04.6	Recording started due to button press	84	3	55.03	d56cd424dac0430c9eaac35d5a3d04fd
04:28.1	Event button pressed				
04:31.1	Recording stopped due to button press	84	3	54.997	d56cd424dac0430c9eaac35d5a3d04fd
04:32.0	Audio recording disabled due to video buffering default				
04:32.6	Event button released				
08:19.3	Axon application connected to device				
09:06.3	Axon application connected to device				
10:43.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-11 1700 X6033271L' to 'Signal 75 Bus Loop E8' using Axon applicator				83c88402b9b74007a7d96261c488766a
10:43.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				83c88402b9b74007a7d96261c488766a
12:12.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-11 1701 X6033271L' to 'Signal 75 Bus Loop E8' using Axon applicator				12adc7fb68ee473b8398b81ccab55708
12:12.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				12adc7fb68ee473b8398b81ccab55708
14:21.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-11 1704 X6033271L' to 'Signal 75 Bus 7079, Route 115, BL. 2' using Axon applicator				d56cd424dac0430c9eaac35d5a3d04fd
14:21.5	Categories 'Miscellaneous' added to video metadata using Axon applicator				d56cd424dac0430c9eaac35d5a3d04fd
25:40.7	Axon application disconnected from device				
41:18.3	Audit log created	81	3	1.15.14	54.995
50:19.2	Event button pressed				
50:19.3	Event button released				
50:19.4	Event button pressed				
50:19.4	Audio recording enabled due to video recording default				
50:19.5	Event button released				
50:19.5	Recording started due to button press	80	4	54.995	ca017d2aecba42e687d30e2d59c02e7a
51:28.3	Event button pressed				
51:31.3	Recording stopped due to button press	80	4	54.897	ca017d2aecba42e687d30e2d59c02e7a
51:31.8	Event button released				
51:32.1	Audio recording disabled due to video buffering default				
41:18.3	Audit log created	75	4	1.15.14	54.895
44:49.5	Event button pressed				
44:49.7	Event button released				
44:49.7	Event button pressed				
44:49.7	Audio recording enabled due to video recording default				
44:49.8	Event button released				
44:49.9	Recording started due to button press	75	5	54.895	989cf5c4841c4e88a7b534966158785a
44:52.6	Event button pressed				
44:55.6	Recording stopped due to button press	75	5	54.882	989cf5c4841c4e88a7b534966158785a
44:56.3	Audio recording disabled due to video buffering default				
44:56.3	Event button released				
45:42.3	Axon application connected to device				
46:49.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-11 1750 X6033271L' to 'Signal 75 Bus' using Axon applicator				ca017d2aecba42e687d30e2d59c02e7a
46:49.9	Categories 'Miscellaneous' added to video metadata using Axon applicator				ca017d2aecba42e687d30e2d59c02e7a
47:16.1	Video played back using Axon application				ca017d2aecba42e687d30e2d59c02e7a
47:58.5	Categories 'Miscellaneous' removed from video metadata using Axon applicator				ca017d2aecba42e687d30e2d59c02e7a
48:22.1	Title changed in video metadata from 'Signal 75 Bus' to 'Signal 75/31 Bus' using Axon applicator				ca017d2aecba42e687d30e2d59c02e7a

48:22.1 Categories 'Sleeper' added to video metadata using Axon applicator

ca017d2aecba42e687d30e2d59c02e7a

48:38.5 Axon application disconnected from device

26:32.9 Volume up button pressed

26:33.1 Volume up button released

26:33.2 Volume changed to high from medium using button

26:38.8 Volume down button pressed

26:39.0 Volume down button released

26:39.1 Volume changed to medium from high using button

26:42.8 Camera connected to Axon Dock X630020W7

71 5 54.83

26:42.9 Audit log rolled

70 5 54.83

26:42.9 Audit log created

70 5 1.15.14 54.83

26:44.0 Device connected to charger

70 5 54.83

26:42.0 Audit log created

97 5 1.15.14 54.829

26:42.0 Audit log created

100 5 1.15.14 54.829

26:42.0 Audit log created

100 5 1.15.14 54.828

26:42.0 Audit log created

100 5 1.15.14 54.828

26:42.0 Audit log created

100 5 1.15.14 54.827

26:42.1 Audit log created

100 5 1.15.14 54.827

26:42.1 Audit log created

100 5 1.15.14 54.826

26:42.1 Audit log created

100 5 1.15.14 54.826

26:42.1 Audit log created

100 5 1.15.14 54.825

26:42.1 Audit log created

100 5 1.15.14 54.825

26:42.1 Audit log created

100 5 1.15.14 54.825

41:13.5 Select button pressed

41:13.7 Select button released

41:14.0 Device disconnected from charger

98 5 54.824

41:14.6 Camera disconnected from Axon Dock X630020W7

100 5 54.824

23:25.0 Select button pressed

23:25.0 Select button released

23:29.9 Camera connected to Axon Dock X630020W7

95 5 54.827

23:30.0 Audit log rolled

94 5 54.827

23:30.0 Audit log created

94 5 1.15.14 54.827

23:30.0 Device connected to charger

94 5 54.827

24:52.3 Device restarting due to device error

95 5 54.827

25:31.1 Device restarted due to device error

95 5 54.826

25:32.1 Camera connected to Axon Dock

96 5 54.826

25:33.9 Audit log rolled

95 5 54.826

25:33.9 Audit log created

95 5 1.15.14 54.826

25:54.0 Device connected to charger

95 5 54.826

26:29.1 Camera disconnected from Axon Dock

96 5 54.826

26:29.1 Device disconnected from charger

96 5 54.826

26:29.1 Audio recording disabled due to video buffering default

26:31.7 Camera connected to Axon Dock X62001VOK

96 5 54.841

26:31.8 Audit log rolled

96 5 54.826

26:31.8 Audit log created

96 5 1.15.14 54.826

26:32.1 Device connected to charger

96 5 54.826

26:52.9 Video upload started when camera was docked

83c88402b9b74007a7d96261c488766a

27:00.7	Audit log successfully uploaded			
27:00.9	Audit log successfully uploaded and deleted from device	96	5	54.841
27:03.0	Date/Time synced to 09/12/2021 07:27:03.01 AM from 09/12/2021 07:27:01.72 AM			
27:07.1	Audit log successfully uploaded			
27:07.3	Audit log successfully uploaded and deleted from device	96	5	54.839
27:14.0	Video successfully uploaded from device when dockec			83c88402b9b74007a7d96261c488766a
27:14.2	Video deleted from device when docked	96	4	54.905 83c88402b9b74007a7d96261c488766a
27:14.3	Audit log created	96	4 1.15.14	54.905
27:14.3	Audit log rolled	96	4	54.905
27:14.5	Video upload started when camera was docked			12adc7fb68ee473b8398b81ccab55708
27:31.5	Audit log successfully uploaded			
27:31.7	Audit log successfully uploaded and deleted from device	96	4	54.895
27:38.4	Video successfully uploaded from device when dockec			12adc7fb68ee473b8398b81ccab55708
27:38.6	Video deleted from device when docked	96	3	54.972 12adc7fb68ee473b8398b81ccab55708
27:38.7	Audit log rolled	96	3	54.972
27:38.7	Audit log created	96	3 1.15.14	54.972
27:38.8	Video upload started when camera was docked			d56cd424dac0430c9eaac35d5a3d04fd
27:40.9	Audit log successfully uploaded			
27:41.1	Audit log successfully uploaded and deleted from device	96	3	54.971
27:48.9	Video successfully uploaded from device when dockec			d56cd424dac0430c9eaac35d5a3d04fd
27:49.1	Video deleted from device when docked	96	2	55.001 d56cd424dac0430c9eaac35d5a3d04fd
27:49.2	Audit log created	96	2 1.15.14	55.001
27:49.2	Audit log rolled	96	2	55.001
27:49.4	Video upload started when camera was docked			ca017d2aecba42e687d30e2d59c02e7a
27:53.3	Audit log successfully uploaded			
27:53.5	Audit log successfully uploaded and deleted from device	96	2	54.999
28:15.7	Audit log successfully uploaded			
28:15.9	Audit log successfully uploaded and deleted from device	96	2	54.997
28:17.8	Video successfully uploaded from device when dockec			ca017d2aecba42e687d30e2d59c02e7a
28:18.1	Video deleted from device when docked	96	1	55.095 ca017d2aecba42e687d30e2d59c02e7a
28:18.2	Audit log rolled	96	1	55.095
28:18.2	Audit log created	96	1 1.15.14	55.095
28:18.3	Video upload started when camera was docked			989cf5c4841c4e88a7b534966158785a
28:37.5	Video successfully uploaded from device when dockec			989cf5c4841c4e88a7b534966158785a
28:37.7	Video deleted from device when docked	96	0	55.159 989cf5c4841c4e88a7b534966158785a
28:37.8	Audit log created	96	0 1.15.14	55.159
28:37.8	Audit log rolled	96	0	55.159
28:37.8	Audit log rolled	96	0	55.159
28:37.8	Audit log created	96	0 1.15.14	55.159
28:44.1	Audit log successfully uploaded			
28:44.3	Audit log successfully uploaded and deleted from device	96	0	55.159
28:51.4	Audit log successfully uploaded			
28:51.6	Audit log successfully uploaded and deleted from device	96	0	55.159
29:04.8	Audit log successfully uploaded			
29:04.9	Audit log successfully uploaded and deleted from device	96	0	55.159
29:33.1	Audit log successfully uploaded			
29:33.3	Audit log successfully uploaded and deleted from device	96	0	55.159

30:02.6	Audit log successfully uploaded			
30:02.9	Audit log successfully uploaded and deleted from device	96	0	55.159
30:11.0	Audit log successfully uploaded			
30:11.2	Audit log successfully uploaded and deleted from device	96	0	55.159
30:28.4	Audit log successfully uploaded			
30:28.6	Audit log successfully uploaded and deleted from device	96	0	55.159
30:55.9	Audit log successfully uploaded			
30:56.0	Audit log successfully uploaded and deleted from device	96	0	55.159
31:19.2	Audit log successfully uploaded			
31:19.4	Audit log successfully uploaded and deleted from device	97	0	55.159
31:45.6	Audit log successfully uploaded			
31:45.8	Audit log successfully uploaded and deleted from device	97	0	55.159
32:00.0	Audit log successfully uploaded			
32:00.2	Audit log successfully uploaded and deleted from device	97	0	55.159
32:09.4	Audit log successfully uploaded			
32:09.6	Audit log successfully uploaded and deleted from device	97	0	55.159
32:13.7	Audit log successfully uploaded			
32:13.9	Audit log successfully uploaded and deleted from device	97	0	55.159
32:24.1	Audit log successfully uploaded			
32:24.3	Audit log successfully uploaded and deleted from device	97	0	55.159
32:39.4	Audit log successfully uploaded			
32:39.6	Audit log successfully uploaded and deleted from device	97	0	55.159
32:49.8	Audit log successfully uploaded			
32:50.0	Audit log successfully uploaded and deleted from device	97	0	55.159
33:17.2	Audit log successfully uploaded			
33:17.4	Audit log successfully uploaded and deleted from device	97	0	55.159
33:25.5	Audit log successfully uploaded			
33:25.7	Audit log successfully uploaded and deleted from device	97	0	55.159
33:29.9	Audit log successfully uploaded			
33:30.1	Audit log successfully uploaded and deleted from device	97	0	55.159
33:44.3	Audit log successfully uploaded			
33:44.4	Audit log successfully uploaded and deleted from device	97	0	55.159
34:03.6	Audit log successfully uploaded			
34:03.8	Audit log successfully uploaded and deleted from device	97	0	55.159
34:08.9	Audit log successfully uploaded			
34:09.1	Audit log successfully uploaded and deleted from device	97	0	55.159
34:20.3	Audit log successfully uploaded			
34:20.5	Audit log successfully uploaded and deleted from device	97	0	55.159
34:35.6	Audit log successfully uploaded			
34:35.8	Audit log successfully uploaded and deleted from device	97	0	55.159
34:50.0	Audit log successfully uploaded			
34:50.2	Audit log successfully uploaded and deleted from device	97	0	55.159
35:03.0	Camera disconnected from Axon Dock X62001V0K	97	0	55.159
35:03.1	Device disconnected from charger	97	0	55.159
28:37.0	Audit log created	91	0 1.15.14	55.157
28:37.0	Audit log created	85	0 1.15.14	55.156
28:37.0	Audit log created	79	0 1.15.14	55.155

12:16.2	Volume up button pressed			
12:16.6	Volume up button released			
12:16.7	Volume up button pressed			
12:16.7	Volume up button released			
12:16.8	Volume changed to high from medium using button			
12:16.8	Volume up button pressed			
12:16.9	Volume up button released			
12:17.1	Volume changed to very high from high using button			
12:20.3	Volume down button pressed			
12:20.5	Volume down button released			
12:20.6	Volume changed to high from very high using button			
12:21.2	Volume down button pressed			
12:21.4	Volume down button released			
12:21.5	Volume changed to medium from high using button			
12:23.7	Camera connected to Axon Dock X630020W7	75	0	55.153
12:23.7	Audit log created	75	0 1.15.14	55.154
12:23.7	Audit log rolled	75	0	55.154
12:25.1	Device connected to charger	75	0	55.154
12:23.0	Audit log created	98	0 1.15.14	55.153
12:23.0	Audit log created	100	0 1.15.14	55.153
12:23.0	Audit log created	100	0 1.15.14	55.152
03:28.0	Device disconnected from charger	98	0	55.152
03:28.7	Camera disconnected from Axon Dock X630020W7	98	0	55.152
12:23.0	Audit log created	99	0 1.15.14	55.154
12:23.0	Audit log created	92	0 1.15.14	55.153
12:23.1	Audit log created	85	0 1.15.14	55.152
12:23.1	Audit log created	79	0 1.15.14	55.15
12:23.1	Audit log created	73	0 1.15.14	55.149
16:57.9	Volume up button pressed			
16:58.0	Volume up button released			
16:58.1	Volume changed to high from medium using button			
17:01.7	Volume down button pressed			
17:01.9	Volume down button released			
17:02.0	Volume changed to medium from high using button			
17:06.6	Camera connected to Axon Dock X630020W7	73	0	55.149
17:06.6	Audit log rolled	73	0	55.148
17:06.6	Audit log created	73	0 1.15.14	55.149
17:07.0	Device connected to charger	73	0	55.149
17:06.0	Audit log created	97	0 1.15.14	55.148
17:06.0	Audit log created	100	0 1.15.14	55.148
17:06.0	Audit log created	100	0 1.15.14	55.147
17:06.0	Audit log created	100	0 1.15.14	55.147
17:06.1	Audit log created	100	0 1.15.14	55.147
17:06.1	Audit log created	100	0 1.15.14	55.147
17:06.1	Audit log created	100	0 1.15.14	55.146
17:06.1	Audit log created	100	0 1.15.14	55.146
17:06.1	Audit log created	100	0 1.15.14	55.146

17:06.1	Audit log created	100	0	1.15.14	55.146
17:06.1	Audit log created	100	0	1.15.14	55.145
17:06.1	Audit log created	100	0	1.15.14	55.145
17:06.1	Audit log created	100	0	1.15.14	55.145
17:06.2	Audit log created	100	0	1.15.14	55.145
17:06.2	Audit log created	100	0	1.15.14	55.144
17:06.2	Audit log created	100	0	1.15.14	55.144
17:06.2	Audit log created	100	0	1.15.14	55.144
17:06.2	Audit log created	100	0	1.15.14	55.143
17:06.2	Audit log created	100	0	1.15.14	55.143
47:23.0	Device disconnected from charger	99	0		55.143
47:23.4	Camera disconnected from Axon Dock X630020W7	100	0		55.143
47:41.3	Power button pressed				
47:44.3	Device powered off using button	100	0		55.145
47:44.8	Power button released				
07:50.1	Audit log created			1.15.14	
07:50.2	Device powered on using button	100	0		55.145
07:53.2	Audio recording disabled due to video buffering default				
51:07.2	Event button pressed				
51:07.3	Event button released				
51:07.4	Event button pressed				
51:07.5	Audio recording enabled due to video recording default				
51:07.5	Event button released				
51:07.7	Recording started due to button press	94	0		55.143 a3457c011a0e4cddaa8ec09381117e39
51:19.0	Event button pressed				
51:22.1	Recording stopped due to button press	94	1		55.111 a3457c011a0e4cddaa8ec09381117e39
51:22.5	Event button released				
51:23.0	Audio recording disabled due to video buffering default				
57:45.1	Event button pressed				
57:45.3	Event button released				
57:45.4	Event button pressed				
57:45.4	Audio recording enabled due to video recording default				
57:45.5	Event button released				
57:45.5	Recording started due to button press	93	2		55.075 d87d94bc91f543d5b8d09311989520e6
58:40.9	Event button pressed				
58:44.0	Recording stopped due to button press	93	2		54.984 d87d94bc91f543d5b8d09311989520e6
58:44.4	Event button released				
58:44.8	Audio recording disabled due to video buffering default				
59:04.3	Event button pressed				
59:04.5	Event button released				
59:04.5	Event button pressed				
59:04.5	Audio recording enabled due to video recording default				
59:04.6	Event button released				
59:04.7	Recording started due to button press	93	3		54.983 5e55b7f084764cf685adb5d85689be00
01:59.3	Event button pressed				
02:02.3	Recording stopped due to button press	92	3		54.88 5e55b7f084764cf685adb5d85689be00
02:03.1	Event button released				

02:03.2	Audio recording disabled due to video buffering default			
04:49.1	Event button pressed			
04:49.3	Event button released			
04:49.3	Event button pressed			
04:49.3	Audio recording enabled due to video recording default			
04:49.4	Event button released			
04:49.5	Recording started due to button press	92	4	54.879 78964023989d46ad9952a359804c09dd
04:57.9	Event button pressed			
05:00.9	Recording stopped due to button press	92	4	54.853 78964023989d46ad9952a359804c09dd
05:01.3	Event button released			
05:01.8	Audio recording disabled due to video buffering default			
05:15.6	Event button pressed			
05:15.7	Event button released			
05:15.8	Event button pressed			
05:15.8	Audio recording enabled due to video recording default			
05:15.9	Event button released			
05:16.0	Recording started due to button press	92	5	54.827 9ae982dd8ae041d59f605dfc67ddc7bc
05:23.9	Event button pressed			
05:26.9	Recording stopped due to button press	92	5	54.8 9ae982dd8ae041d59f605dfc67ddc7bc
05:27.4	Event button released			
05:27.6	Audio recording disabled due to video buffering default			
05:41.5	Event button pressed			
05:41.7	Event button released			
05:41.7	Event button pressed			
05:41.8	Audio recording enabled due to video recording default			
05:41.8	Event button released			
05:41.9	Recording started due to button press	92	6	54.799 2489331ef72e40a6b6a0cf555747c65a
05:49.2	Event button pressed			
05:52.2	Recording stopped due to button press	92	6	54.787 2489331ef72e40a6b6a0cf555747c65a
05:52.7	Event button released			
05:53.0	Audio recording disabled due to video buffering default			
06:12.9	Event button pressed			
06:13.0	Event button released			
06:13.1	Event button pressed			
06:13.1	Audio recording enabled due to video recording default			
06:13.2	Event button released			
06:13.3	Recording started due to button press	92	7	54.787 8c3666de2c334932ac9b217705c0dcd7
06:21.6	Event button pressed			
06:24.6	Recording stopped due to button press	92	7	54.771 8c3666de2c334932ac9b217705c0dcd7
06:25.1	Event button released			
06:25.4	Audio recording disabled due to video buffering default			
06:38.1	Event button pressed			
06:38.2	Event button released			
06:38.3	Event button pressed			
06:38.3	Audio recording enabled due to video recording default			
06:38.4	Event button released			
06:38.5	Recording started due to button press	92	8	54.77 9169619963074a9e8acacd0868801a5b

06:45.4 Event button pressed			
06:48.4 Recording stopped due to button press	92	8	54.759 9169619963074a9e8acacd0868801a5b
06:48.9 Event button released			
06:49.2 Audio recording disabled due to video buffering default			
07:02.1 Event button pressed			
07:02.3 Event button released			
07:02.4 Event button pressed			
07:02.4 Audio recording enabled due to video recording default			
07:02.5 Event button released			
07:02.5 Recording started due to button press	92	9	54.758 06858bde02b14c4da0084391f74278c8
07:41.4 Event button pressed			
07:41.7 Event button released			
07:42.8 Event button pressed			
07:45.8 Recording stopped due to button press	91	9	54.729 06858bde02b14c4da0084391f74278c8
07:46.3 Event button released			
07:46.7 Audio recording disabled due to video buffering default			
07:49.9 Event button pressed			
07:50.0 Event button released			
07:50.0 Event button pressed			
07:50.1 Audio recording enabled due to video recording default			
07:50.1 Audit log created	91	9 1.15.14	54.729
07:50.1 Event button released			
07:50.2 Recording started due to button press	91	10	54.728 46af30fc084344ccab574dfda9d656d8
08:20.0 Event button pressed			
08:20.1 Event button released			
08:20.2 Event button pressed			
08:20.3 Event button released			
08:25.6 Event button pressed			
08:28.6 Recording stopped due to button press	91	10	54.707 46af30fc084344ccab574dfda9d656d8
08:29.3 Event button released			
08:29.3 Audio recording disabled due to video buffering default			
08:31.2 Event button pressed			
08:31.4 Event button released			
08:31.4 Event button pressed			
08:31.4 Audio recording enabled due to video recording default			
08:31.5 Event button released			
08:31.6 Recording started due to button press	91	11	54.706 3779e27598344e039d6184a5c7bc3018
08:57.6 Event button pressed			
09:00.7 Recording stopped due to button press	91	11	54.69 3779e27598344e039d6184a5c7bc3018
09:01.1 Event button released			
09:01.4 Audio recording disabled due to video buffering default			
07:50.1 Audit log created	85	11 1.15.14	54.688
26:25.6 Event button pressed			
26:25.9 Event button released			
26:26.1 Event button pressed			
26:26.2 Audio recording enabled due to video recording default			
26:26.2 Event button released			

26:26.3 Recording started due to button press	84	12	54.688 131d4f4abf9e4c06ad1f7fcc49cd2fd4
26:43.2 Event button pressed			
26:46.3 Recording stopped due to button press	84	12	54.642 131d4f4abf9e4c06ad1f7fcc49cd2fd4
26:46.7 Event button released			
26:47.0 Audio recording disabled due to video buffering default			
29:09.8 Event button pressed			
29:09.9 Event button released			
29:10.0 Event button pressed			
29:10.1 Audio recording enabled due to video recording default			
29:10.1 Event button released			
29:10.2 Recording started due to button press	83	13	54.617 8a5025d095834ef188caeaeb0e570e98
31:26.3 Event button pressed			
31:29.3 Recording stopped due to button press	83	13	54.483 8a5025d095834ef188caeaeb0e570e98
31:29.8 Event button released			
31:30.1 Audio recording disabled due to video buffering default			
32:52.2 Event button pressed			
32:52.3 Event button released			
32:52.4 Event button pressed			
32:52.5 Audio recording enabled due to video recording default			
32:52.5 Event button released			
32:52.6 Recording started due to button press	82	14	54.482 cc0109f919004d0390e49d5db57a3ddc
33:35.2 Event button pressed			
33:38.3 Recording stopped due to button press	82	14	54.417 cc0109f919004d0390e49d5db57a3ddc
33:38.7 Event button released			
33:39.0 Audio recording disabled due to video buffering default			
34:12.8 Event button pressed			
34:12.9 Event button released			
34:13.0 Event button pressed			
34:13.0 Audio recording enabled due to video recording default			
34:13.0 Event button released			
34:13.1 Recording started due to button press	82	15	54.416 bacd2d771e6e43f9a80d82d3b0f0c8ee
34:42.2 Event button pressed			
34:45.2 Recording stopped due to button press	82	15	54.383 bacd2d771e6e43f9a80d82d3b0f0c8ee
34:45.9 Event button released			
34:46.0 Audio recording disabled due to video buffering default			
07:50.1 Audit log created	79	15 1.15.14	54.381
44:12.5 Event button pressed			
44:12.6 Event button released			
44:12.7 Event button pressed			
44:12.7 Audio recording enabled due to video recording default			
44:12.8 Event button released			
44:12.9 Recording started due to button press	75	15	54.38 346f0f5e5f6c4da98fe4b47373a84b9e
47:07.0 Event button pressed			
47:10.0 Recording stopped due to button press	75	16	54.226 346f0f5e5f6c4da98fe4b47373a84b9e
47:10.9 Audio recording disabled due to video buffering default			
47:11.1 Event button released			
47:36.4 Event button pressed			

47:36.5	Event button released			
47:36.6	Event button pressed			
47:36.6	Audio recording enabled due to video recording default			
47:36.7	Event button released			
47:36.8	Recording started due to button press	75	17	54.225 1f8d3f2cf179491390ef93f8b3eedf4c
48:38.8	Event button pressed			
48:41.8	Recording stopped due to button press	74	17	54.179 1f8d3f2cf179491390ef93f8b3eedf4c
48:42.2	Event button released			
48:42.7	Audio recording disabled due to video buffering default			
48:44.6	Event button pressed			
48:44.7	Event button released			
48:44.8	Event button pressed			
48:44.8	Audio recording enabled due to video recording default			
48:44.9	Event button released			
48:45.0	Recording started due to button press	74	18	54.178 b8a1c1c11c4340acbd0b6c32fc06aac7
49:26.4	Event button pressed			
49:29.4	Recording stopped due to button press	74	18	54.154 b8a1c1c11c4340acbd0b6c32fc06aac7
49:29.9	Event button released			
49:30.3	Audio recording disabled due to video buffering default			
50:25.4	Event button pressed			
50:25.5	Event button released			
50:25.6	Event button pressed			
50:25.6	Audio recording enabled due to video recording default			
50:25.7	Event button released			
50:25.8	Recording started due to button press	74	19	54.153 84d3df588f5941e691f17e01b0ee72f1
50:36.6	Event button pressed			
50:36.8	Event button released			
50:36.8	Event button pressed			
50:37.0	Event button released			
50:37.2	Event button pressed			
50:40.2	Recording stopped due to button press	74	19	54.121 84d3df588f5941e691f17e01b0ee72f1
50:40.7	Event button released			
50:41.0	Audio recording disabled due to video buffering default			
50:43.9	Event button pressed			
50:44.1	Event button released			
50:44.1	Event button pressed			
50:44.1	Audio recording enabled due to video recording default			
50:44.2	Event button released			
50:44.2	Recording started due to button press	74	20	54.117 cff31ba56fc8443bacebe292a957ec62
51:20.0	Event button pressed			
51:22.7	Event button released			
51:24.8	Event button pressed			
51:27.8	Recording stopped due to button press	74	20	54.093 cff31ba56fc8443bacebe292a957ec62
51:28.6	Audio recording disabled due to video buffering default			
51:28.8	Event button released			
51:31.5	Event button pressed			
51:31.7	Event button released			

51:33.0 Event button pressed			
51:33.1 Event button released			
51:33.2 Event button pressed			
51:33.2 Audio recording enabled due to video recording default			
51:33.2 Event button released			
51:33.4 Recording started due to button press	74	21	54.093 03f1f58765a845da936ed9c50e3d8a18
51:54.8 Event button pressed			
51:57.8 Recording stopped due to button press	74	21	54.078 03f1f58765a845da936ed9c50e3d8a18
51:58.3 Event button released			
51:58.5 Audio recording disabled due to video buffering default			
52:14.4 Event button pressed			
52:14.6 Event button released			
52:14.7 Event button pressed			
52:14.7 Audio recording enabled due to video recording default			
52:14.8 Event button released			
52:14.8 Recording started due to button press	74	22	54.077 9044f18a029c4cb5ae7c6188d109e9fd
53:53.5 Event button pressed			
53:56.5 Recording stopped due to button press	73	22	54.016 9044f18a029c4cb5ae7c6188d109e9fd
53:56.9 Event button released			
53:57.4 Audio recording disabled due to video buffering default			
54:06.6 Event button pressed			
54:06.8 Event button released			
54:06.8 Event button pressed			
54:06.9 Audio recording enabled due to video recording default			
54:07.0 Event button released			
54:07.0 Recording started due to button press	73	22	54.015 5b67f22c000845d08ea0e6ad5d96b4d7
54:29.4 Event button pressed			
54:32.4 Recording stopped due to button press	73	23	53.997 5b67f22c000845d08ea0e6ad5d96b4d7
54:33.0 Event button released			
54:33.3 Audio recording disabled due to video buffering default			
01:38.6 Event button pressed			
01:38.8 Event button released			
01:38.8 Event button pressed			
01:38.8 Audio recording enabled due to video recording default			
01:38.9 Event button released			
01:39.0 Recording started due to button press	73	24	53.996 7d00c93c33914f698df6fb608099bdba
01:54.9 Event button pressed			
01:57.9 Recording stopped due to button press	73	24	53.954 7d00c93c33914f698df6fb608099bdba
01:58.4 Event button released			
01:58.8 Audio recording disabled due to video buffering default			
02:01.3 Event button pressed			
02:01.4 Event button released			
02:01.5 Event button pressed			
02:01.5 Audio recording enabled due to video recording default			
02:01.6 Event button released			
02:01.6 Recording started due to button press	73	25	53.945 6c9babaced6f4e7bab4aef4c4a932784
02:14.5 Event button pressed			

02:17.5 Recording stopped due to button press	73	25	53.917 6c9babaced6f4e7bab4aef4c4a932784
02:18.0 Event button released			
02:18.3 Audio recording disabled due to video buffering default			
07:50.2 Audit log created	72	25 1.15.14	53.916
26:39.1 Event button pressed			
26:39.3 Event button released			
26:39.3 Event button pressed			
26:39.4 Audio recording enabled due to video recording default			
26:39.4 Event button released			
26:39.5 Recording started due to button press	70	26	53.915 b89040eccc874cefab6318a10fa8154f
27:07.1 Event button pressed			
27:10.1 Recording stopped due to button press	70	26	53.849 b89040eccc874cefab6318a10fa8154f
27:10.6 Event button released			
27:10.9 Audio recording disabled due to video buffering default			
33:12.6 Event button pressed			
33:12.8 Event button released			
33:12.8 Event button pressed			
33:12.9 Audio recording enabled due to video recording default			
33:12.9 Event button released			
33:13.0 Recording started due to button press	70	27	53.838 3f30a2c8e1984f33ac9457a4f3a47ae9
33:26.3 Event button pressed			
33:29.3 Recording stopped due to button press	70	27	53.802 3f30a2c8e1984f33ac9457a4f3a47ae9
33:29.7 Event button released			
33:30.2 Audio recording disabled due to video buffering default			
33:52.2 Event button pressed			
33:52.3 Event button released			
33:52.4 Event button pressed			
33:52.4 Audio recording enabled due to video recording default			
33:52.5 Event button released			
33:52.5 Recording started due to button press	70	28	53.769 40553252fbaa489e8f37accf054a52b9
34:00.8 Event button pressed			
34:03.8 Recording stopped due to button press	70	28	53.752 40553252fbaa489e8f37accf054a52b9
34:04.2 Event button released			
34:04.7 Audio recording disabled due to video buffering default			
07:50.2 Audit log created	66	28 1.15.14	53.751
07:50.2 Audit log created	59	28 1.15.14	53.75
07:50.2 Audit log created	52	28 1.15.14	53.748
32:04.9 Event button pressed			
32:05.0 Event button released			
32:05.1 Event button pressed			
32:05.1 Audio recording enabled due to video recording default			
32:05.2 Event button released			
32:05.3 Recording started due to button press	49	29	53.747 70daad29d6e2439cbb704f32a56da6fb
32:18.5 Event button pressed			
32:21.5 Recording stopped due to button press	49	29	53.711 70daad29d6e2439cbb704f32a56da6fb
32:22.0 Event button released			
32:22.2 Audio recording disabled due to video buffering default			

32:24.1	Event button pressed			
32:24.2	Event button released			
32:24.3	Event button pressed			
32:24.3	Audio recording enabled due to video recording default			
32:24.4	Event button released			
32:24.5	Recording started due to button press	49	30	53.704 4ec25324fde34569b127cdb493d37d03
32:36.3	Event button pressed			
32:39.4	Recording stopped due to button press	49	30	53.67 4ec25324fde34569b127cdb493d37d03
32:39.9	Event button released			
32:40.2	Audio recording disabled due to video buffering default			
33:26.7	Event button pressed			
33:26.9	Event button released			
33:26.9	Event button pressed			
33:27.0	Audio recording enabled due to video recording default			
33:27.1	Event button released			
33:27.1	Recording started due to button press	49	31	53.669 849ef888c2c84272810551fff5cdd8a0
33:41.7	Event button pressed			
33:44.8	Recording stopped due to button press	49	31	53.636 849ef888c2c84272810551fff5cdd8a0
33:45.2	Event button released			
33:45.5	Audio recording disabled due to video buffering default			
34:12.0	Event button pressed			
34:12.1	Event button released			
34:12.2	Event button pressed			
34:12.2	Audio recording enabled due to video recording default			
34:12.3	Event button released			
34:12.4	Recording started due to button press	49	32	53.636 68e3e3f997d144aeac27d1a198e92198
34:19.2	Event button pressed			
34:22.2	Recording stopped due to button press	49	32	53.618 68e3e3f997d144aeac27d1a198e92198
34:22.6	Event button released			
34:23.0	Audio recording disabled due to video buffering default			
34:26.2	Event button pressed			
34:26.3	Event button released			
34:26.3	Event button pressed			
34:26.4	Audio recording enabled due to video recording default			
34:26.4	Event button released			
34:26.5	Recording started due to button press	49	33	53.617 d5411e87764a4c8889723d98fe1989a5
37:27.3	Event button pressed			
37:30.3	Recording stopped due to button press	48	33	53.518 d5411e87764a4c8889723d98fe1989a5
37:30.9	Event button released			
37:31.2	Audio recording disabled due to video buffering default			
37:35.3	Event button pressed			
37:35.4	Event button released			
37:35.4	Event button pressed			
37:35.5	Audio recording enabled due to video recording default			
37:35.5	Event button released			
37:35.6	Recording started due to button press	48	34	53.518 f9e510ce9b4a4e778de597eb043a03c8
37:57.6	Event button pressed			

38:00.6	Recording stopped due to button press	48	34	53.502	f9e510ce9b4a4e778de597eb043a03c8
38:01.2	Event button released				
38:01.4	Audio recording disabled due to video buffering default				
38:05.8	Event button pressed				
38:05.9	Event button released				
38:05.9	Event button pressed				
38:05.9	Audio recording enabled due to video recording default				
38:06.0	Event button released				
38:06.1	Recording started due to button press	48	35	53.502	9679730d6c024cf08d80c4955b4efe56
38:16.8	Event button pressed				
38:19.8	Recording stopped due to button press	48	35	53.493	9679730d6c024cf08d80c4955b4efe56
38:20.2	Event button released				
38:20.7	Audio recording disabled due to video buffering default				
50:59.0	Axon application connected to device				
51:54.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1651 X6033271L' to 'Signal 75' using Axon applicator				a3457c011a0e4cddaa8ec09381117e39
51:54.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				a3457c011a0e4cddaa8ec09381117e39
52:20.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1657 X6033271L' to 'Signal 75' using Axon application				d87d94bc91f543d5b8d09311989520e6
52:20.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				d87d94bc91f543d5b8d09311989520e6
52:40.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1659 X6033271L' to 'Signal 75' using Axon applicator				5e55b7f084764cf685adb5d85689be00
52:40.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				5e55b7f084764cf685adb5d85689be00
53:00.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1704 X6033271L' to 'Signal 75' using Axon application				78964023989d46ad9952a359804c09dd
53:00.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				78964023989d46ad9952a359804c09dd
53:30.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1705 X6033271L' to 'Signal 75' using Axon applicator				9ae982dd8ae041d59f605dfc67ddc7bc
53:30.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				9ae982dd8ae041d59f605dfc67ddc7bc
53:52.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1705 X6033271L' to 'Signal 75' using Axon application				2489331ef72e40a6b6a0cf555747c65a
53:52.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				2489331ef72e40a6b6a0cf555747c65a
55:02.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1706 X6033271L' to 'Signal 75' using Axon application				8c3666de2c334932ac9b217705c0dcd7
55:02.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				8c3666de2c334932ac9b217705c0dcd7
55:16.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1706 X6033271L' to 'Signal 75' using Axon application				9169619963074a9e8acacd0868801a5b
55:16.8	Categories 'Miscellaneous' added to video metadata using Axon applicator				9169619963074a9e8acacd0868801a5b
55:38.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1707 X6033271L' to 'Signal 75' using Axon application				06858bde02b14c4da0084391f74278c8
55:38.3	Categories 'Miscellaneous' added to video metadata using Axon applicator				06858bde02b14c4da0084391f74278c8
55:58.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1707 X6033271L' to 'Signal 75' using Axon application				46af30fc084344ccab574dfda9d656d8
55:58.2	Categories 'Miscellaneous' added to video metadata using Axon applicator				46af30fc084344ccab574dfda9d656d8
56:23.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1708 X6033271L' to 'Signal 75' using Axon application				3779e27598344e039d6184a5c7bc3018
56:23.0	Categories 'Miscellaneous' added to video metadata using Axon applicator				3779e27598344e039d6184a5c7bc3018
56:39.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1826 X6033271L' to 'Signal 75' using Axon application				131d4f4abf9e4c06ad1f7fcc49cd2fd4
56:39.6	Categories 'Miscellaneous' added to video metadata using Axon applicator				131d4f4abf9e4c06ad1f7fcc49cd2fd4
57:26.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1829 X6033271L' to 'Signal 75' using Axon application				8a5025d095834ef188caeaeb0e570e98
57:26.1	Categories 'Miscellaneous' added to video metadata using Axon applicator				8a5025d095834ef188caeaeb0e570e98
57:44.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1832 X6033271L' to 'Signal 75' using Axon application				cc0109f919004d0390e49d5db57a3ddc
57:44.7	Categories 'Miscellaneous' added to video metadata using Axon applicator				cc0109f919004d0390e49d5db57a3ddc
59:10.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1834 X6033271L' to 'Signal 75' using Axon application				bacd2d771e6e43f9a80d82d3b0f0c8ee
59:10.4	Categories 'Miscellaneous' added to video metadata using Axon applicator				bacd2d771e6e43f9a80d82d3b0f0c8ee
01:15.6	Axon application disconnected from device				
02:05.0	Axon application connected to device				
02:47.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1944 X6033271L' to 'Signal 75' using Axon application				346f0f5e5f6c4da98fe4b47373a84b9e

02:47.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			346f0f5e5f6c4da98fe4b47373a84b9e
03:12.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1947 X6033271L' to 'Signal 75' using Axon applicator			1f8d3f2cf179491390ef93f8b3eedf4c
03:12.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			1f8d3f2cf179491390ef93f8b3eedf4c
03:28.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1948 X6033271L' to 'Signal 75' using Axon applicator			b8a1c1c11c4340acbd0b6c32fc06aac7
03:28.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			b8a1c1c11c4340acbd0b6c32fc06aac7
03:56.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1950 X6033271L' to 'Signal 75' using Axon applicator			84d3df588f5941e691f17e01b0ee72f1
03:56.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			84d3df588f5941e691f17e01b0ee72f1
04:13.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1950 X6033271L' to 'Signal 75' using Axon applicator			cff31ba56fc8443bacebe292a957ec62
04:13.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			cff31ba56fc8443bacebe292a957ec62
04:29.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1951 X6033271L' to 'Signal 75' using Axon applicator			03f1f58765a845da936ed9c50e3d8a18
04:29.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			03f1f58765a845da936ed9c50e3d8a18
04:45.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1952 X6033271L' to 'Signal 75' using Axon applicator			9044f18a029c4cb5ae7c6188d109e9fd
04:45.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			9044f18a029c4cb5ae7c6188d109e9fd
04:59.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 1954 X6033271L' to 'Signal 75' using Axon applicator			5b67f22c000845d08ea0e6ad5d96b4d7
04:59.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			5b67f22c000845d08ea0e6ad5d96b4d7
05:18.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2001 X6033271L' to 'Signal 75' using Axon applicator			7d00c93c33914f698df6b608099bdba
05:18.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			7d00c93c33914f698df6b608099bdba
05:37.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2002 X6033271L' to 'Signal 75' using Axon applicator			6c9babaced6f4e7bab4aef4c4a932784
05:37.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			6c9babaced6f4e7bab4aef4c4a932784
05:54.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2026 X6033271L' to 'Signal 75' using Axon applicator			b89040eccc874cefab6318a10fa8154f
05:54.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			b89040eccc874cefab6318a10fa8154f
06:11.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2033 X6033271L' to 'Signal 75' using Axon applicator			3f30a2c8e1984f33ac9457a4f3a47ae9
06:11.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			3f30a2c8e1984f33ac9457a4f3a47ae9
06:26.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2033 X6033271L' to 'Signal 75' using Axon applicator			40553252fbaa489e8f37accf054a52b9
06:26.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			40553252fbaa489e8f37accf054a52b9
06:58.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2332 X6033271L' to 'Signal 75' using Axon applicator			70daad29d6e2439cbb704f32a56da6fb
06:58.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			70daad29d6e2439cbb704f32a56da6fb
07:16.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2332 X6033271L' to 'Signal 75' using Axon applicator			4ec25324fde34569b127cdb493d37d03
07:16.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			4ec25324fde34569b127cdb493d37d03
07:33.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2333 X6033271L' to 'Signal 75' using Axon applicator			849ef888c2c84272810551fff5cdd8a0
07:33.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			849ef888c2c84272810551fff5cdd8a0
07:50.3	Audit log created	45	35 1.15.14	53.486
07:51.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2334 X6033271L' to 'Signal 75' using Axon applicator			68e3e3f997d144aeac27d1a198e92198
07:51.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			68e3e3f997d144aeac27d1a198e92198
08:17.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2334 X6033271L' to 'Signal 75' using Axon applicator			d5411e87764a4c8889723d98fe1989a5
08:17.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			d5411e87764a4c8889723d98fe1989a5
08:41.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2337 X6033271L' to 'Signal 75' using Axon applicator			f9e510ce9b4a4e778de597eb043a03c8
08:41.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			f9e510ce9b4a4e778de597eb043a03c8
08:58.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-13 2338 X6033271L' to 'Signal 75' using Axon applicator			9679730d6c024cf08d80c4955b4efe56
08:58.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			9679730d6c024cf08d80c4955b4efe56
09:36.9	Axon application disconnected from device			
09:51.5	Volume up button pressed			
09:51.7	Volume up button released			
09:51.9	Volume changed to high from medium using button			
09:56.3	Audit log rolled	44	35	53.486
09:56.3	Audit log created	44	35 1.15.14	53.486
09:56.3	Camera connected to Axon Dock X62001W9H	45	35	53.507

09:56.3 Device connected to charger	44	35	53.486	
09:57.4 Volume down button pressed				
09:57.6 Volume down button released				
09:58.6 Volume down button pressed				
09:58.8 Volume down button released				
10:11.1 Video upload started when camera was docked				a3457c011a0e4cddaa8ec09381117e39
10:28.0 Date/Time synced to 09/14/2021 12:10:28.02 AM from 09/14/2021 12:10:26.31 AM				
10:31.7 Video successfully uploaded from device when docked				a3457c011a0e4cddaa8ec09381117e39
10:32.0 Video deleted from device when docked	45	34	53.575	a3457c011a0e4cddaa8ec09381117e39
10:32.0 Audit log created	45	34 1.15.14	53.575	
10:32.1 Audit log rolled	45	34	53.575	
10:32.2 Video upload started when camera was docked				d87d94bc91f543d5b8d09311989520e6
10:48.7 Audit log successfully uploaded				
10:48.9 Audit log successfully uploaded and deleted from device	45	34	53.575	
10:58.0 Audit log successfully uploaded				
10:58.1 Video successfully uploaded from device when docked				d87d94bc91f543d5b8d09311989520e6
10:58.2 Audit log successfully uploaded and deleted from device	45	34	53.575	
10:58.3 Video deleted from device when docked	45	33	53.666	d87d94bc91f543d5b8d09311989520e6
10:58.4 Audit log rolled	45	33	53.666	
10:58.4 Audit log created	45	33 1.15.14	53.666	
10:58.6 Video upload started when camera was docked				5e55b7f084764cf685adb5d85689be00
11:13.3 Audit log successfully uploaded				
11:13.5 Audit log successfully uploaded and deleted from device	45	33	53.666	
11:30.0 Video successfully uploaded from device when docked				5e55b7f084764cf685adb5d85689be00
11:30.2 Video deleted from device when docked	45	32	53.769	5e55b7f084764cf685adb5d85689be00
11:30.3 Audit log created	45	32 1.15.14	53.769	
11:30.3 Audit log rolled	45	32	53.769	
11:30.4 Video upload started when camera was docked				78964023989d46ad9952a359804c09dd
11:36.6 Audit log successfully uploaded				
11:36.8 Audit log successfully uploaded and deleted from device	45	32	53.769	
11:45.0 Audit log successfully uploaded				
11:45.1 Audit log successfully uploaded and deleted from device	45	32	53.769	
11:47.2 Audit log successfully uploaded				
11:47.4 Audit log successfully uploaded and deleted from device	46	32	53.769	
11:48.8 Video successfully uploaded from device when docked				78964023989d46ad9952a359804c09dd
11:49.1 Video deleted from device when docked	46	31	53.835	78964023989d46ad9952a359804c09dd
11:49.2 Audit log created	46	31 1.15.14	53.835	
11:49.2 Audit log rolled	46	31	53.835	
11:49.5 Video upload started when camera was docked				9ae982dd8ae041d59f605dfc67ddc7bc
11:53.6 Video successfully uploaded from device when docked				9ae982dd8ae041d59f605dfc67ddc7bc
11:53.9 Video deleted from device when docked	46	30	53.848	9ae982dd8ae041d59f605dfc67ddc7bc
11:53.9 Audit log rolled	46	30	53.848	
11:53.9 Audit log created	46	30 1.15.14	53.848	
11:54.2 Video upload started when camera was docked				2489331ef72e40a6b6a0cf555747c65a
11:58.3 Video successfully uploaded from device when docked				2489331ef72e40a6b6a0cf555747c65a
11:58.5 Video deleted from device when docked	46	29	53.861	2489331ef72e40a6b6a0cf555747c65a
11:58.5 Audit log rolled	46	29	53.861	

11:58.5	Audit log created	46	29	1.15.14	53.861	
11:58.7	Video upload started when camera was docked					8c3666de2c334932ac9b217705c0dcd7
12:03.7	Video successfully uploaded from device when docked					8c3666de2c334932ac9b217705c0dcd7
12:04.0	Video deleted from device when docked	46	28		53.877	8c3666de2c334932ac9b217705c0dcd7
12:04.0	Audit log rolled	46	28		53.877	
12:04.0	Audit log created	46	28	1.15.14	53.877	
12:04.2	Video upload started when camera was docked					9169619963074a9e8acacd0868801a5b
12:04.5	Audit log successfully uploaded					
12:04.7	Audit log successfully uploaded and deleted from device	46	28		53.877	
12:08.4	Video successfully uploaded from device when docked					9169619963074a9e8acacd0868801a5b
12:08.6	Video deleted from device when docked	46	27		53.889	9169619963074a9e8acacd0868801a5b
12:08.7	Audit log rolled	46	27		53.889	
12:08.7	Audit log created	46	27	1.15.14	53.889	
12:08.8	Video upload started when camera was docked					06858bde02b14c4da0084391f74278c8
12:17.3	Video successfully uploaded from device when docked					06858bde02b14c4da0084391f74278c8
12:17.5	Video deleted from device when docked	46	26		53.919	06858bde02b14c4da0084391f74278c8
12:17.6	Audit log rolled	46	26		53.919	
12:17.6	Audit log created	46	26	1.15.14	53.919	
12:17.8	Video upload started when camera was docked					46af30fc084344ccab574dfda9d656d8
12:24.8	Video successfully uploaded from device when docked					46af30fc084344ccab574dfda9d656d8
12:25.0	Video deleted from device when docked	46	25		53.941	46af30fc084344ccab574dfda9d656d8
12:25.1	Audit log created	46	25	1.15.14	53.941	
12:25.1	Audit log rolled	46	25		53.941	
12:25.3	Video upload started when camera was docked					3779e27598344e039d6184a5c7bc3018
12:30.8	Video successfully uploaded from device when docked					3779e27598344e039d6184a5c7bc3018
12:31.0	Video deleted from device when docked	46	24		53.957	3779e27598344e039d6184a5c7bc3018
12:31.1	Audit log rolled	46	24		53.958	
12:31.1	Audit log created	46	24	1.15.14	53.958	
12:31.3	Video upload started when camera was docked					131d4f4abf9e4c06ad1f7fcc49cd2fd4
12:33.8	Audit log successfully uploaded					
12:34.0	Audit log successfully uploaded and deleted from device	46	24		53.958	
12:46.1	Audit log successfully uploaded					
12:46.3	Audit log successfully uploaded and deleted from device	46	24		53.958	
12:52.0	Video successfully uploaded from device when docked					131d4f4abf9e4c06ad1f7fcc49cd2fd4
12:52.3	Video deleted from device when docked	46	23		54.028	131d4f4abf9e4c06ad1f7fcc49cd2fd4
12:52.3	Audit log created	46	23	1.15.14	54.029	
12:52.3	Audit log rolled	46	23		54.029	
12:52.5	Video upload started when camera was docked					8a5025d095834ef188caeaeb0e570e98
12:57.4	Audit log successfully uploaded					
12:57.6	Audit log successfully uploaded and deleted from device	46	23		54.029	
13:12.7	Audit log successfully uploaded					
13:12.9	Audit log successfully uploaded and deleted from device	46	23		54.029	
13:28.0	Video successfully uploaded from device when docked					8a5025d095834ef188caeaeb0e570e98
13:28.3	Video deleted from device when docked	46	22		54.162	8a5025d095834ef188caeaeb0e570e98
13:28.3	Audit log created	46	22	1.15.14	54.162	
13:28.3	Audit log rolled	46	22		54.162	
13:28.5	Video upload started when camera was docked					cc0109f919004d0390e49d5db57a3ddc

13:34.0	Audit log successfully uploaded			
13:34.2	Audit log successfully uploaded and deleted from device	46	22	54.162
13:42.3	Audit log successfully uploaded			
13:42.5	Audit log successfully uploaded and deleted from device	46	22	54.162
13:47.1	Video successfully uploaded from device when dockec			cc0109f919004d0390e49d5db57a3ddc
13:47.3	Video deleted from device when docked	46	21	54.227 cc0109f919004d0390e49d5db57a3ddc
13:47.4	Audit log rolled	46	21	54.23
13:47.4	Audit log created	46	21 1.15.14	54.23
13:47.6	Video upload started when camera was docked			bacd2d771e6e43f9a80d82d3b0f0c8ee
13:48.6	Audit log successfully uploaded			
13:48.8	Audit log successfully uploaded and deleted from device	46	21	54.23
13:50.9	Audit log successfully uploaded			
13:51.0	Audit log successfully uploaded and deleted from device	46	21	54.23
13:57.3	Video successfully uploaded from device when dockec			bacd2d771e6e43f9a80d82d3b0f0c8ee
13:57.6	Video deleted from device when docked	46	20	54.264 bacd2d771e6e43f9a80d82d3b0f0c8ee
13:57.6	Audit log created	46	20 1.15.14	54.264
13:57.6	Audit log rolled	46	20	54.264
13:57.8	Video upload started when camera was docked			346f0f5e5f6c4da98fe4b47373a84b9e
14:04.2	Audit log successfully uploaded			
14:04.3	Audit log successfully uploaded and deleted from device	46	20	54.264
14:16.4	Audit log successfully uploaded			
14:16.6	Audit log successfully uploaded and deleted from device	46	20	54.264
14:37.7	Audit log successfully uploaded			
14:38.2	Audit log successfully uploaded and deleted from device	47	20	54.264
14:39.8	Video successfully uploaded from device when dockec			346f0f5e5f6c4da98fe4b47373a84b9e
14:40.1	Video deleted from device when docked	47	19	54.417 346f0f5e5f6c4da98fe4b47373a84b9e
14:40.2	Audit log created	47	19 1.15.14	54.418
14:40.2	Audit log rolled	47	19	54.418
14:40.4	Video upload started when camera was docked			1f8d3f2cf179491390ef93f8b3eedf4c
14:48.3	Audit log successfully uploaded			
14:48.5	Audit log successfully uploaded and deleted from device	47	19	54.418
14:54.3	Video successfully uploaded from device when dockec			1f8d3f2cf179491390ef93f8b3eedf4c
14:54.5	Video deleted from device when docked	47	18	54.465 1f8d3f2cf179491390ef93f8b3eedf4c
14:54.6	Audit log created	47	18 1.15.14	54.465
14:54.6	Audit log rolled	47	18	54.465
14:54.8	Video upload started when camera was docked			b8a1c1c11c4340acbd0b6c32fc06aac7
15:02.1	Video successfully uploaded from device when dockec			b8a1c1c11c4340acbd0b6c32fc06aac7
15:02.4	Video deleted from device when docked	47	17	54.489 b8a1c1c11c4340acbd0b6c32fc06aac7
15:02.5	Audit log created	47	17 1.15.14	54.49
15:02.5	Audit log rolled	47	17	54.49
15:02.6	Video upload started when camera was docked			84d3df588f5941e691f17e01b0ee72f1
15:04.6	Audit log successfully uploaded			
15:04.8	Audit log successfully uploaded and deleted from device	47	17	54.49
15:13.0	Video successfully uploaded from device when dockec			84d3df588f5941e691f17e01b0ee72f1
15:13.2	Video deleted from device when docked	47	16	54.525 84d3df588f5941e691f17e01b0ee72f1
15:13.2	Audit log rolled	47	16	54.525
15:13.2	Audit log created	47	16 1.15.14	54.525

15:13.5	Video upload started when camera was docked				cff31ba56fc8443bacebe292a957ec62
15:13.9	Audit log successfully uploaded				
15:14.1	Audit log successfully uploaded and deleted from device	47	16	54.525	
15:18.3	Audit log successfully uploaded				
15:18.4	Audit log successfully uploaded and deleted from device	47	16	54.525	
15:20.8	Video successfully uploaded from device when docked				cff31ba56fc8443bacebe292a957ec62
15:21.0	Video deleted from device when docked	47	15	54.55	cff31ba56fc8443bacebe292a957ec62
15:21.1	Audit log rolled	47	15	54.55	
15:21.1	Audit log created	47	15	54.55	1.15.14
15:21.3	Video upload started when camera was docked				03f1f58765a845da936ed9c50e3d8a18
15:26.3	Video successfully uploaded from device when docked				03f1f58765a845da936ed9c50e3d8a18
15:26.5	Video deleted from device when docked	47	14	54.565	03f1f58765a845da936ed9c50e3d8a18
15:26.6	Audit log created	47	14	54.565	1.15.14
15:26.6	Audit log rolled	47	14	54.565	
15:26.8	Video upload started when camera was docked				9044f18a029c4cb5ae7c6188d109e9fd
15:38.5	Audit log successfully uploaded				
15:38.7	Audit log successfully uploaded and deleted from device	47	14	54.565	
15:43.6	Video successfully uploaded from device when docked				9044f18a029c4cb5ae7c6188d109e9fd
15:43.8	Video deleted from device when docked	47	13	54.627	9044f18a029c4cb5ae7c6188d109e9fd
15:43.9	Audit log rolled	47	13	54.627	
15:43.9	Audit log created	47	13	54.627	1.15.14
15:44.0	Video upload started when camera was docked				5b67f22c000845d08ea0e6ad5d96b4d7
15:50.2	Video successfully uploaded from device when docked				5b67f22c000845d08ea0e6ad5d96b4d7
15:50.5	Video deleted from device when docked	47	12	54.645	5b67f22c000845d08ea0e6ad5d96b4d7
15:50.5	Audit log created	47	12	54.645	1.15.14
15:50.5	Audit log rolled	47	12	54.645	
15:50.8	Video upload started when camera was docked				7d00c93c33914f698df6fb608099bdba
15:53.8	Audit log successfully uploaded				
15:54.0	Audit log successfully uploaded and deleted from device	47	12	54.645	
16:09.9	Video successfully uploaded from device when docked				7d00c93c33914f698df6fb608099bdba
16:10.1	Video deleted from device when docked	47	11	54.715	7d00c93c33914f698df6fb608099bdba
16:10.2	Audit log created	47	11	54.716	1.15.14
16:10.2	Audit log rolled	47	11	54.716	
16:10.4	Video upload started when camera was docked				6c9babaced6f4e7bab4aef4c4a932784
16:12.1	Audit log successfully uploaded				
16:12.3	Audit log successfully uploaded and deleted from device	47	11	54.716	
16:14.1	Video successfully uploaded from device when docked				6c9babaced6f4e7bab4aef4c4a932784
16:14.3	Video deleted from device when docked	47	10	54.725	6c9babaced6f4e7bab4aef4c4a932784
16:14.4	Audit log created	47	10	54.725	1.15.14
16:14.4	Audit log rolled	47	10	54.725	
16:14.6	Video upload started when camera was docked				b89040ecc874cefab6318a10fa8154f
16:15.4	Audit log successfully uploaded				
16:15.6	Audit log successfully uploaded and deleted from device	47	10	54.725	
16:35.7	Video successfully uploaded from device when docked				b89040ecc874cefab6318a10fa8154f
16:35.9	Video deleted from device when docked	47	9	54.802	b89040ecc874cefab6318a10fa8154f
16:36.0	Audit log created	47	9	54.802	1.15.14
16:36.0	Audit log rolled	47	9	54.802	

16:36.4	Video upload started when camera was docked				3f30a2c8e1984f33ac9457a4f3a47ae9
16:43.7	Audit log successfully uploaded				
16:43.9	Audit log successfully uploaded and deleted from device	47	9	54.802	
16:56.0	Video successfully uploaded from device when docked				3f30a2c8e1984f33ac9457a4f3a47ae9
16:56.3	Video deleted from device when docked	47	8	54.872	3f30a2c8e1984f33ac9457a4f3a47ae9
16:56.4	Audit log rolled	47	8	54.872	
16:56.4	Audit log created	47	8	1.15.14	54.872
16:56.6	Video upload started when camera was docked				40553252fbaa489e8f37accf054a52b9
17:02.3	Video successfully uploaded from device when docked				40553252fbaa489e8f37accf054a52b9
17:02.5	Video deleted from device when docked	48	7	54.889	40553252fbaa489e8f37accf054a52b9
17:02.6	Audit log rolled	48	7	54.889	
17:02.6	Audit log created	48	7	1.15.14	54.889
17:02.9	Video upload started when camera was docked				70daad29d6e2439cbb704f32a56da6fb
17:08.0	Audit log successfully uploaded				
17:08.2	Audit log successfully uploaded and deleted from device	48	7	54.889	
17:20.4	Audit log successfully uploaded				
17:20.6	Audit log successfully uploaded and deleted from device	48	7	54.889	
17:21.8	Video successfully uploaded from device when docked				70daad29d6e2439cbb704f32a56da6fb
17:22.0	Video deleted from device when docked	48	6	54.958	70daad29d6e2439cbb704f32a56da6fb
17:22.1	Audit log created	48	6	1.15.14	54.958
17:22.1	Audit log rolled	48	6	54.958	
17:22.3	Video upload started when camera was docked				4ec25324fde34569b127cdb493d37d03
17:25.5	Video successfully uploaded from device when docked				4ec25324fde34569b127cdb493d37d03
17:26.0	Video deleted from device when docked	48	5	54.967	4ec25324fde34569b127cdb493d37d03
17:26.1	Audit log created	48	5	1.15.14	54.967
17:26.1	Audit log rolled	48	5	54.967	
17:26.3	Video upload started when camera was docked				849ef888c2c84272810551fff5cdd8a0
17:36.5	Video successfully uploaded from device when docked				849ef888c2c84272810551fff5cdd8a0
17:36.7	Video deleted from device when docked	48	4	55	849ef888c2c84272810551fff5cdd8a0
17:36.8	Audit log rolled	48	4	55	
17:36.8	Audit log created	48	4	1.15.14	55
17:37.0	Video upload started when camera was docked				68e3e3f997d144aeac27d1a198e92198
17:43.1	Video successfully uploaded from device when docked				68e3e3f997d144aeac27d1a198e92198
17:43.4	Video deleted from device when docked	48	3	55.019	68e3e3f997d144aeac27d1a198e92198
17:43.5	Audit log rolled	48	3	55.019	
17:43.5	Audit log created	48	3	1.15.14	55.019
17:43.7	Video upload started when camera was docked				d5411e87764a4c8889723d98fe1989a5
17:43.7	Audit log successfully uploaded				
17:43.9	Audit log successfully uploaded and deleted from device	48	3	55.019	
17:52.0	Audit log successfully uploaded				
17:52.2	Audit log successfully uploaded and deleted from device	48	3	55.019	
18:05.3	Audit log successfully uploaded				
18:05.4	Audit log successfully uploaded and deleted from device	48	3	55.019	
18:08.6	Video successfully uploaded from device when docked				d5411e87764a4c8889723d98fe1989a5
18:08.9	Video deleted from device when docked	48	2	55.117	d5411e87764a4c8889723d98fe1989a5
18:09.0	Audit log rolled	48	2	55.117	
18:09.0	Audit log created	48	2	1.15.14	55.117

18:09.2	Video upload started when camera was docked			f9e510ce9b4a4e778de597eb043a03c8
18:13.9	Video successfully uploaded from device when docked			f9e510ce9b4a4e778de597eb043a03c8
18:14.1	Video deleted from device when docked	48	1	55.132 f9e510ce9b4a4e778de597eb043a03c8
18:14.2	Audit log rolled	48	1	55.134
18:14.2	Audit log created	48	1 1.15.14	55.134
18:14.3	Video upload started when camera was docked			9679730d6c024cf08d80c4955b4efe56
18:26.6	Audit log successfully uploaded			
18:26.8	Audit log successfully uploaded and deleted from device	48	1	55.134
18:33.9	Audit log successfully uploaded			
18:34.1	Audit log successfully uploaded and deleted from device	48	1	55.134
18:46.3	Audit log successfully uploaded			
18:46.5	Audit log successfully uploaded and deleted from device	49	1	55.134
18:46.6	Audit log successfully uploaded			
18:46.8	Audit log successfully uploaded and deleted from device	49	1	55.134
18:46.9	Audit log successfully uploaded			
18:47.1	Audit log successfully uploaded and deleted from device	49	1	55.134
19:06.3	Audit log successfully uploaded			
19:06.4	Audit log successfully uploaded and deleted from device	49	1	55.134
19:21.6	Audit log successfully uploaded			
19:21.8	Audit log successfully uploaded and deleted from device	49	1	55.134
19:28.9	Audit log successfully uploaded			
19:29.1	Audit log successfully uploaded and deleted from device	49	1	55.134
19:36.2	Audit log successfully uploaded			
19:36.4	Audit log successfully uploaded and deleted from device	49	1	55.134
19:57.5	Audit log successfully uploaded			
19:57.7	Audit log successfully uploaded and deleted from device	49	1	55.134
20:08.9	Audit log successfully uploaded			
20:09.0	Audit log successfully uploaded and deleted from device	49	1	55.134
20:36.2	Audit log successfully uploaded			
20:36.4	Audit log successfully uploaded and deleted from device	49	1	55.134
20:37.5	Audit log successfully uploaded			
20:37.6	Audit log successfully uploaded and deleted from device	49	1	55.134
20:58.1	Video deleted from device when docked	49	0	55.143 9679730d6c024cf08d80c4955b4efe56
20:58.2	Audit log rolled	49	0	55.144
20:58.2	Audit log created	49	0 1.15.14	55.144
20:58.2	Audit log rolled	49	0	55.144
20:58.2	Audit log created	49	0 1.15.14	55.144
20:59.8	Audit log successfully uploaded			
21:00.0	Audit log successfully uploaded and deleted from device	49	0	55.144
21:05.1	Audit log successfully uploaded			
21:05.3	Audit log successfully uploaded and deleted from device	49	0	55.144
21:20.5	Audit log successfully uploaded			
21:20.7	Audit log successfully uploaded and deleted from device	50	0	55.143
21:23.8	Audit log successfully uploaded			
21:24.0	Audit log successfully uploaded and deleted from device	50	0	55.143
21:49.1	Audit log successfully uploaded			
21:49.3	Audit log successfully uploaded and deleted from device	50	0	55.143

22:00.5	Audit log successfully uploaded			
22:00.7	Audit log successfully uploaded and deleted from device	50	0	55.143
22:16.8	Audit log successfully uploaded			
22:17.0	Audit log successfully uploaded and deleted from device	50	0	55.143
22:30.1	Audit log successfully uploaded			
22:30.3	Audit log successfully uploaded and deleted from device	50	0	55.143
22:33.5	Audit log successfully uploaded			
22:33.7	Audit log successfully uploaded and deleted from device	50	0	55.143
22:35.8	Audit log successfully uploaded			
22:36.0	Audit log successfully uploaded and deleted from device	50	0	55.143
22:38.1	Audit log successfully uploaded			
22:38.3	Audit log successfully uploaded and deleted from device	50	0	55.143
22:51.5	Audit log successfully uploaded			
22:51.6	Audit log successfully uploaded and deleted from device	50	0	55.143
22:55.8	Audit log successfully uploaded			
22:56.0	Audit log successfully uploaded and deleted from device	50	0	55.143
23:19.2	Audit log successfully uploaded			
23:19.4	Audit log successfully uploaded and deleted from device	51	0	55.143
23:47.6	Audit log successfully uploaded			
23:47.7	Audit log successfully uploaded and deleted from device	51	0	55.143
24:13.9	Audit log successfully uploaded			
24:14.1	Audit log successfully uploaded and deleted from device	51	0	55.143
24:21.2	Audit log successfully uploaded			
24:21.4	Audit log successfully uploaded and deleted from device	51	0	55.143
24:29.6	Audit log successfully uploaded			
24:29.8	Audit log successfully uploaded and deleted from device	51	0	55.143
24:40.9	Audit log successfully uploaded			
24:41.1	Audit log successfully uploaded and deleted from device	51	0	55.143
24:54.2	Audit log successfully uploaded			
24:54.4	Audit log successfully uploaded and deleted from device	51	0	55.143
25:02.6	Audit log successfully uploaded			
25:02.8	Audit log successfully uploaded and deleted from device	51	0	55.143
25:31.9	Audit log successfully uploaded			
25:32.1	Audit log successfully uploaded and deleted from device	52	0	55.143
25:50.3	Audit log successfully uploaded			
25:50.5	Audit log successfully uploaded and deleted from device	52	0	55.143
25:56.6	Audit log successfully uploaded			
25:56.8	Audit log successfully uploaded and deleted from device	52	0	55.143
26:04.9	Audit log successfully uploaded			
26:05.1	Audit log successfully uploaded and deleted from device	52	0	55.143
26:27.3	Audit log successfully uploaded			
26:27.5	Audit log successfully uploaded and deleted from device	52	0	55.143
26:39.6	Audit log successfully uploaded			
26:39.8	Audit log successfully uploaded and deleted from device	52	0	55.143
26:53.0	Audit log successfully uploaded			
26:53.2	Audit log successfully uploaded and deleted from device	52	0	55.143
26:58.3	Audit log successfully uploaded			

26:58.5	Audit log successfully uploaded and deleted from device	52	0	55.143
27:05.6	Audit log successfully uploaded			
27:05.8	Audit log successfully uploaded and deleted from device	52	0	55.143
27:30.0	Audit log successfully uploaded			
27:30.1	Audit log successfully uploaded and deleted from device	53	0	55.143
27:38.3	Audit log successfully uploaded			
27:38.5	Audit log successfully uploaded and deleted from device	53	0	55.143
28:01.9	Audit log successfully uploaded			
28:02.0	Audit log successfully uploaded and deleted from device	53	0	55.143
28:16.1	Audit log successfully uploaded			
28:16.3	Audit log successfully uploaded and deleted from device	53	0	55.143
28:22.4	Audit log successfully uploaded			
28:22.7	Audit log successfully uploaded and deleted from device	53	0	55.143
28:37.8	Audit log successfully uploaded			
28:38.0	Audit log successfully uploaded and deleted from device	53	0	55.143
29:05.1	Audit log successfully uploaded			
29:05.3	Audit log successfully uploaded and deleted from device	53	0	55.143
29:33.4	Audit log successfully uploaded			
29:33.6	Audit log successfully uploaded and deleted from device	53	0	55.143
29:36.7	Audit log successfully uploaded			
29:36.9	Audit log successfully uploaded and deleted from device	54	0	55.143
40:28.0	Date/Time synced to 09/14/2021 12:40:28.01 AM from 09/14/2021 12:40:28.04 AM			
59:23.5	Device disconnected from charger	68	0	55.146
59:23.9	Camera disconnected from Axon Dock X62001W9H	68	0	55.147
59:27.7	Programmable button pressed			
59:27.8	Programmable button released			
20:57.9	Audit log created	66	0 1.15.14	55.155
20:57.9	Audit log created	60	0 1.15.14	55.154
31:27.7	Volume up button pressed			
31:27.8	Volume up button released			
31:27.8	Select button pressed			
31:27.8	Select button released			
31:27.9	Volume changed to very high from high using button			
31:32.0	Volume down button pressed			
31:32.2	Volume down button released			
31:32.3	Volume changed to high from very high using button			
31:33.5	Volume down button pressed			
31:33.8	Volume down button released			
31:33.9	Volume changed to medium from high using button			
31:35.9	Camera connected to Axon Dock X630020W7	59	0	55.154
31:35.9	Audit log created	59	0 1.15.14	55.154
31:35.9	Audit log rolled	59	0	55.153
31:36.5	Device connected to charger	59	0	55.154
31:35.0	Audit log created	87	0 1.15.14	55.153
31:35.0	Audit log created	100	0 1.15.14	55.152
31:35.0	Audit log created	100	0 1.15.14	55.153
31:35.0	Audit log created	100	0 1.15.14	55.153

31:35.0 Audit log created	100	0 1.15.14	55.153
31:35.0 Audit log created	100	0 1.15.14	55.153
31:35.0 Audit log created	100	0 1.15.14	55.153
31:35.0 Audit log created	100	0 1.15.14	55.152
31:35.1 Audit log created	100	0 1.15.14	55.152
31:35.1 Audit log created	100	0 1.15.14	55.152
31:35.1 Audit log created	100	0 1.15.14	55.152
31:35.1 Audit log created	100	0 1.15.14	55.151
28:55.5 Camera disconnected from Axon Dock X630020W7	98	0	55.151
28:55.5 Device disconnected from charger	98	0	55.152
31:35.1 Audit log created	99	0 1.15.14	55.152
31:35.1 Audit log created	92	0 1.15.14	55.15
58:39.6 Volume up button pressed			
58:39.7 Volume up button released			
58:39.8 Volume changed to high from medium using button			
58:41.5 Volume down button pressed			
58:41.7 Volume down button released			
58:41.8 Volume changed to medium from high using button			
58:45.6 Volume down button pressed			
58:45.8 Volume down button released			
58:46.0 Volume changed to low from medium using button			
58:46.7 Volume up button pressed			
58:46.9 Volume up button released			
58:47.0 Volume changed to medium from low using button			
58:48.9 Audit log created	89	0 1.15.14	55.15
58:48.9 Audit log rolled	89	0	55.15
58:50.5 Device connected to charger	89	0	55.15
58:59.2 Device disconnected from charger	89	0	55.15
58:59.3 Camera disconnected from Axon Dock X630020W7	89	0	55.151
58:48.0 Audit log created	84	0 1.15.14	55.149
58:48.0 Audit log created	78	0 1.15.14	55.148
27:20.5 Programmable button pressed			
27:20.6 Programmable button released			
27:21.0 Programmable button pressed			
27:21.0 Programmable button released			
58:48.0 Audit log created	72	0 1.15.14	55.146
56:20.4 Event button pressed			
56:20.6 Event button released			
56:20.7 Event button pressed			
56:20.7 Audio recording enabled due to video recording default			
56:20.8 Event button released			
56:20.9 Recording started due to button press	66	1	55.145 c11220e9637a42ad8c9a0d92ef0f6d26
56:33.4 Event button pressed			
56:36.4 Recording stopped due to button press	66	1	55.11 c11220e9637a42ad8c9a0d92ef0f6d26
56:37.0 Event button released			
56:37.3 Audio recording disabled due to video buffering default			
57:03.8 Event button pressed			

57:03.9	Event button released			
57:04.0	Event button pressed			
57:04.0	Audio recording enabled due to video recording default			
57:04.1	Event button released			
57:04.2	Recording started due to button press	65	2	55.076 3d3976b75c3d4fed97d464fa06bbf05b
57:31.1	Event button pressed			
57:34.1	Recording stopped due to button press	65	2	55.047 3d3976b75c3d4fed97d464fa06bbf05b
57:34.5	Event button released			
57:35.0	Audio recording disabled due to video buffering default			
58:48.0	Audit log created	65	2 1.15.14	55.047
58:48.0	Audit log created	59	2 1.15.14	55.045
02:07.8	Power button pressed			
02:10.8	Device powered off using button	59	2	55.045
02:11.3	Power button released			
03:38.1	Device powered on using button	59	2	55.047
03:39.9	Audio recording disabled due to video buffering default			
03:51.0	Event button pressed			
03:51.1	Event button released			
03:51.2	Event button pressed			
03:51.2	Audio recording enabled due to video recording default			
03:51.3	Event button released			
03:51.4	Recording started due to button press	59	3	55.047 70c4fb175f2e4740b365208a2f502fe5
04:00.0	Event button pressed			
04:03.0	Recording stopped due to button press	59	3	55.036 70c4fb175f2e4740b365208a2f502fe5
04:03.3	Event button released			
04:03.9	Audio recording disabled due to video buffering default			
04:09.9	Event button pressed			
04:10.0	Event button released			
04:10.1	Event button pressed			
04:10.1	Audio recording enabled due to video recording default			
04:10.2	Event button released			
04:10.2	Recording started due to button press	59	4	55.035 fc149a3fb0f04b53b9b46dba39458bcb
07:14.7	Event button pressed			
07:17.7	Recording stopped due to button press	58	4	54.933 fc149a3fb0f04b53b9b46dba39458bcb
07:18.2	Event button released			
07:18.4	Audio recording disabled due to video buffering default			
42:03.0	Event button pressed			
42:03.2	Event button released			
42:03.2	Event button pressed			
42:03.2	Audio recording enabled due to video recording default			
42:03.3	Event button released			
42:03.4	Recording started due to button press	53	5	54.931 0e63bb433f1e4ae38cbe9751d4497785
42:32.4	Event button pressed			
42:35.4	Recording stopped due to button press	53	5	54.86 0e63bb433f1e4ae38cbe9751d4497785
42:35.8	Event button released			
42:36.1	Audio recording disabled due to video buffering default			
43:04.1	Event button pressed			

43:04.3	Event button released			
43:04.3	Event button pressed			
43:04.4	Audio recording enabled due to video recording default			
43:04.4	Event button released			
43:04.5	Recording started due to button press	53	6	54.853 bda90832cea24c299b9375fe27ae3877
43:15.2	Event button pressed			
43:18.2	Recording stopped due to button press	53	6	54.832 bda90832cea24c299b9375fe27ae3877
43:18.6	Event button released			
43:19.1	Audio recording disabled due to video buffering default			
58:48.1	Audit log created	51	6 1.15.14	54.831
31:01.8	Event button pressed			
31:01.8	Event button released			
31:01.9	Event button pressed			
31:01.9	Audio recording enabled due to video recording default			
31:02.0	Event button released			
31:02.1	Recording started due to button press	47	7	54.83 fb068013de8d48f8a3f7861979c4201f
31:46.6	Event button pressed			
31:49.6	Recording stopped due to button press	47	7	54.745 fb068013de8d48f8a3f7861979c4201f
31:50.1	Event button released			
31:50.4	Audio recording disabled due to video buffering default			
31:52.6	Event button pressed			
31:52.7	Event button released			
31:52.8	Event button pressed			
31:52.8	Audio recording enabled due to video recording default			
31:52.9	Event button released			
31:52.9	Recording started due to button press	47	8	54.744 0d04944e35d6478092f9496eef3bc34e
32:30.8	Event button pressed			
32:33.8	Recording stopped due to button press	47	8	54.722 0d04944e35d6478092f9496eef3bc34e
32:34.4	Event button released			
32:34.7	Audio recording disabled due to video buffering default			
32:44.9	Event button pressed			
32:45.1	Event button released			
32:45.1	Event button pressed			
32:45.1	Audio recording enabled due to video recording default			
32:45.2	Event button released			
32:45.2	Recording started due to button press	47	9	54.721 9652ecfa84c742f5893b13e57fa1c8cf
33:12.3	Event button pressed			
33:15.4	Recording stopped due to button press	47	9	54.701 9652ecfa84c742f5893b13e57fa1c8cf
33:15.8	Event button released			
33:16.2	Audio recording disabled due to video buffering default			
33:26.3	Event button pressed			
33:26.5	Event button released			
33:26.5	Event button pressed			
33:26.6	Audio recording enabled due to video recording default			
33:26.7	Event button released			
33:26.7	Recording started due to button press	47	10	54.7 ed8ed56c3ec9417eb9fa02155109aff9
33:41.6	Event button pressed			

33:44.6 Recording stopped due to button press	47	10	54.686 ed8ed56c3ec9417eb9fa02155109aff9
33:45.1 Event button released			
33:45.4 Audio recording disabled due to video buffering default			
58:48.1 Audit log created	44	10 1.15.14	54.685
58:48.1 Audit log created	38	10 1.15.14	54.683
58:48.1 Audit log created	33	10 1.15.14	54.682
11:18.9 Event button pressed			
11:19.1 Event button released			
11:19.1 Event button pressed			
11:19.2 Audio recording enabled due to video recording default			
11:19.2 Event button released			
11:19.3 Recording started due to button press	32	11	54.681 5de746c87e5d4259a5eb93d045113ed8
16:46.9 Event button pressed			
16:50.0 Recording stopped due to button press	30	11	54.446 5de746c87e5d4259a5eb93d045113ed8
16:50.5 Event button released			
16:50.8 Audio recording disabled due to video buffering default			
23:28.9 Event button pressed			
23:29.1 Event button released			
23:29.2 Event button pressed			
23:29.2 Audio recording enabled due to video recording default			
23:29.3 Event button released			
23:29.3 Recording started due to button press	30	12	54.445 adc8179dca664675828fe8ff801d0fb2
24:03.0 Event button pressed			
24:06.0 Recording stopped due to button press	29	12	54.366 adc8179dca664675828fe8ff801d0fb2
24:06.6 Event button released			
24:06.9 Audio recording disabled due to video buffering default			
26:10.0 Event button pressed			
26:10.1 Event button released			
26:10.2 Event button pressed			
26:10.2 Audio recording enabled due to video recording default			
26:10.2 Event button released			
26:10.4 Recording started due to button press	29	13	54.364 17184a35cace4d1d8cd2e6f840b5b7cb
30:12.3 Event button pressed			
30:15.3 Recording stopped due to button press	29	13	54.174 17184a35cace4d1d8cd2e6f840b5b7cb
30:15.8 Event button released			
30:16.2 Audio recording disabled due to video buffering default			
30:48.3 Event button pressed			
30:48.4 Event button released			
30:48.4 Event button pressed			
30:48.5 Audio recording enabled due to video recording default			
30:48.6 Event button released			
30:48.7 Recording started due to button press	29	14	54.173 af032bd99f984202b0b2190294202e14
31:24.4 Event button pressed			
31:27.4 Recording stopped due to button press	28	14	54.136 af032bd99f984202b0b2190294202e14
31:27.8 Event button released			
31:28.3 Audio recording disabled due to video buffering default			
32:12.1 Event button pressed			

32:12.3	Event button released			
32:12.3	Event button pressed			
32:12.3	Audio recording enabled due to video recording default			
32:12.4	Event button released			
32:12.5	Recording started due to button press	28	15	54.136 cbbc14d802b84348a33aa924caa787ee
38:45.1	Event button pressed			
38:48.1	Recording stopped due to button press	27	15	53.904 cbbc14d802b84348a33aa924caa787ee
38:48.6	Event button released			
38:48.9	Audio recording disabled due to video buffering default			
53:52.8	Axon application connected to device			
55:26.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2056 X6033271L' to 'Signal 75' using Axon applicator			c11220e9637a42ad8c9a0d92ef0f6d26
55:26.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			c11220e9637a42ad8c9a0d92ef0f6d26
55:58.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2057 X6033271L' to 'Signal 75' using Axon applicator			3d3976b75c3d4fed97d464fa06bbf05b
55:58.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			3d3976b75c3d4fed97d464fa06bbf05b
56:26.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2203 X6033271L' to 'Signal 75' using Axon applicator			70c4fb175f2e4740b365208a2f502fe5
56:26.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			70c4fb175f2e4740b365208a2f502fe5
56:59.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2204 X6033271L' to 'Signal 75' using Axon applicator			fc149a3fb0f04b53b9b46dba39458bcb
56:59.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			fc149a3fb0f04b53b9b46dba39458bcb
57:17.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2242 X6033271L' to 'Signal 75' using Axon applicator			0e63bb433f1e4ae38cbe9751d4497785
57:17.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			0e63bb433f1e4ae38cbe9751d4497785
57:34.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2243 X6033271L' to 'Signal 75' using Axon applicator			bda90832cea24c299b9375fe27ae3877
57:34.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			bda90832cea24c299b9375fe27ae3877
58:00.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2331 X6033271L' to 'Signal 75' using Axon applicator			fb068013de8d48f8a3f7861979c4201f
58:00.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			fb068013de8d48f8a3f7861979c4201f
58:21.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2331 X6033271L' to 'Signal 75' using Axon applicator			0d04944e35d6478092f9496eef3bc34e
58:21.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			0d04944e35d6478092f9496eef3bc34e
58:48.1	Audit log created	25	15 1.15.14	53.9
08:45.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2332 X6033271L' to 'Signal 75' using Axon applicator			9652ecfa84c742f5893b13e57fa1c8cf
08:45.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			9652ecfa84c742f5893b13e57fa1c8cf
09:04.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-14 2333 X6033271L' to 'Signal 75' using Axon applicator			ed8ed56c3ec9417eb9fa02155109aff9
09:04.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			ed8ed56c3ec9417eb9fa02155109aff9
09:18.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 0211 X6033271L' to 'Signal 75' using Axon applicator			5de746c87e5d4259a5eb93d045113ed8
09:18.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			5de746c87e5d4259a5eb93d045113ed8
09:34.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 0223 X6033271L' to 'Signal 75' using Axon applicator			adc8179dca664675828fe8ff801d0fb2
09:34.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			adc8179dca664675828fe8ff801d0fb2
09:52.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 0226 X6033271L' to 'Signal 75' using Axon applicator			17184a35cace4d1d8cd2e6f840b5b7cb
09:52.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			17184a35cace4d1d8cd2e6f840b5b7cb
10:07.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 0230 X6033271L' to 'Signal 75' using Axon applicator			af032bd99f984202b0b2190294202e14
10:07.9	Categories 'Miscellaneous' added to video metadata using Axon applicator			af032bd99f984202b0b2190294202e14
10:26.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 0232 X6033271L' to 'Signal 75' using Axon applicator			cbbc14d802b84348a33aa924caa787ee
10:26.2	Categories 'Miscellaneous' added to video metadata using Axon applicator			cbbc14d802b84348a33aa924caa787ee
11:20.5	Axon application disconnected from device			
11:32.3	Camera connected to Axon Dock X62001V12	24	15	53.916
11:32.4	Audit log rolled	23	15	53.9
11:32.4	Audit log created	23	15 1.15.14	53.9
11:33.1	Device connected to charger	23	15	53.9
11:47.5	Video upload started when camera was docked			c11220e9637a42ad8c9a0d92ef0f6d26

11:58.9	Audit log successfully uploaded				
11:59.1	Audit log successfully uploaded and deleted from device	24	15	53.916	
12:03.0	Date/Time synced to 09/15/2021 03:12:03.03 AM from 09/15/2021 03:12:02.50 AM				
12:07.2	Video successfully uploaded from device when dockec				c11220e9637a42ad8c9a0d92ef0f6d26
12:07.4	Video deleted from device when docked	24	14	53.984	c11220e9637a42ad8c9a0d92ef0f6d26
12:07.5	Audit log rolled	24	14	53.985	
12:07.5	Audit log created	24	14	1.15.14	53.985
12:07.8	Video upload started when camera was docked				3d3976b75c3d4fed97d464fa06bbf05b
12:16.5	Video successfully uploaded from device when dockec				3d3976b75c3d4fed97d464fa06bbf05b
12:16.7	Video deleted from device when docked	24	13	54.014	3d3976b75c3d4fed97d464fa06bbf05b
12:16.8	Audit log created	24	13	1.15.14	54.014
12:16.8	Audit log rolled	24	13		54.014
12:17.1	Video upload started when camera was docked				70c4fb175f2e4740b365208a2f502fe5
12:20.8	Video successfully uploaded from device when dockec				70c4fb175f2e4740b365208a2f502fe5
12:21.0	Video deleted from device when docked	24	12	54.026	70c4fb175f2e4740b365208a2f502fe5
12:21.1	Audit log created	24	12	1.15.14	54.026
12:21.1	Audit log rolled	24	12		54.026
12:21.3	Video upload started when camera was docked				fc149a3fb0f04b53b9b46dba39458bcb
12:22.1	Audit log successfully uploaded				
12:22.3	Audit log successfully uploaded and deleted from device	24	12	54.026	
12:49.2	Video successfully uploaded from device when dockec				fc149a3fb0f04b53b9b46dba39458bcb
12:49.4	Audit log successfully uploaded				
12:49.5	Video deleted from device when docked	24	11	54.128	fc149a3fb0f04b53b9b46dba39458bcb
12:49.5	Audit log created	24	11	1.15.14	54.128
12:49.5	Audit log rolled	24	11		54.128
12:49.7	Audit log successfully uploaded and deleted from device	24	11		54.128
12:49.7	Video upload started when camera was docked				0e63bb433f1e4ae38cbe9751d4497785
13:06.9	Audit log successfully uploaded				
13:07.1	Audit log successfully uploaded and deleted from device	24	11	54.128	
13:10.2	Audit log successfully uploaded				
13:10.4	Audit log successfully uploaded and deleted from device	24	11	54.128	
13:11.5	Video successfully uploaded from device when dockec				0e63bb433f1e4ae38cbe9751d4497785
13:11.8	Video deleted from device when docked	24	10	54.206	0e63bb433f1e4ae38cbe9751d4497785
13:11.8	Audit log created	24	10	1.15.14	54.206
13:11.8	Audit log rolled	24	10		54.206
13:12.1	Video upload started when camera was docked				bda90832cea24c299b9375fe27ae3877
13:18.5	Video successfully uploaded from device when dockec				bda90832cea24c299b9375fe27ae3877
13:18.7	Video deleted from device when docked	24	9	54.227	bda90832cea24c299b9375fe27ae3877
13:18.8	Audit log created	24	9	1.15.14	54.234
13:18.8	Audit log rolled	24	9		54.234
13:19.0	Video upload started when camera was docked				fb068013de8d48f8a3f7861979c4201f
13:37.5	Audit log successfully uploaded				
13:37.7	Audit log successfully uploaded and deleted from device	24	9	54.234	
13:41.8	Video successfully uploaded from device when dockec				fb068013de8d48f8a3f7861979c4201f
13:42.1	Video deleted from device when docked	24	8	54.32	fb068013de8d48f8a3f7861979c4201f
13:42.1	Audit log created	24	8	1.15.14	54.324
13:42.1	Audit log rolled	24	8		54.324

13:42.3	Video upload started when camera was docked				0d04944e35d6478092f9496eef3bc34e
13:47.8	Audit log successfully uploaded				
13:48.0	Audit log successfully uploaded and deleted from device	24	8	54.324	
13:49.1	Video successfully uploaded from device when dockec				0d04944e35d6478092f9496eef3bc34e
13:49.4	Video deleted from device when docked	25	7	54.347	0d04944e35d6478092f9496eef3bc34e
13:49.4	Audit log created	25	7	54.347	1.15.14
13:49.4	Audit log rolled	25	7	54.347	
13:49.6	Video upload started when camera was docked				9652ecfa84c742f5893b13e57fa1c8cf
13:56.4	Video successfully uploaded from device when dockec				9652ecfa84c742f5893b13e57fa1c8cf
13:56.6	Video deleted from device when docked	25	6	54.368	9652ecfa84c742f5893b13e57fa1c8cf
13:56.7	Audit log rolled	25	6	54.368	
13:56.7	Audit log created	25	6	54.368	1.15.14
13:56.8	Video upload started when camera was docked				ed8ed56c3ec9417eb9fa02155109aff9
14:01.4	Video successfully uploaded from device when dockec				ed8ed56c3ec9417eb9fa02155109aff9
14:01.6	Video deleted from device when docked	25	5	54.383	ed8ed56c3ec9417eb9fa02155109aff9
14:01.6	Audit log rolled	25	5	54.383	
14:01.6	Audit log created	25	5	54.383	1.15.14
14:01.8	Video upload started when camera was docked				5de746c87e5d4259a5eb93d045113ed8
14:12.1	Audit log successfully uploaded				
14:12.3	Audit log successfully uploaded and deleted from device	25	5	54.383	
14:23.5	Audit log successfully uploaded				
14:23.7	Audit log successfully uploaded and deleted from device	25	5	54.383	
14:49.8	Audit log successfully uploaded				
14:49.9	Audit log successfully uploaded and deleted from device	25	5	54.383	
14:54.1	Audit log successfully uploaded				
14:54.2	Audit log successfully uploaded and deleted from device	25	5	54.383	
15:01.6	Video successfully uploaded from device when dockec				5de746c87e5d4259a5eb93d045113ed8
15:02.0	Video deleted from device when docked	25	4	54.617	5de746c87e5d4259a5eb93d045113ed8
15:02.0	Audit log rolled	25	4	54.617	
15:02.0	Audit log created	25	4	54.617	1.15.14
15:02.2	Video upload started when camera was docked				adc8179dca664675828fe8ff801d0fb2
15:16.3	Audit log successfully uploaded				
15:16.6	Audit log successfully uploaded and deleted from device	25	4	54.617	
15:23.6	Video successfully uploaded from device when dockec				adc8179dca664675828fe8ff801d0fb2
15:23.8	Video deleted from device when docked	25	3	54.697	adc8179dca664675828fe8ff801d0fb2
15:23.9	Audit log rolled	25	3	54.697	
15:23.9	Audit log created	25	3	54.697	1.15.14
15:24.1	Video upload started when camera was docked				17184a35cace4d1d8cd2e6f840b5b7cb
15:31.7	Audit log successfully uploaded				
15:31.9	Audit log successfully uploaded and deleted from device	25	3	54.697	
15:41.0	Audit log successfully uploaded				
15:41.2	Audit log successfully uploaded and deleted from device	25	3	54.697	
15:46.3	Audit log successfully uploaded				
15:46.5	Audit log successfully uploaded and deleted from device	25	3	54.697	
15:53.6	Audit log successfully uploaded				
15:53.7	Audit log successfully uploaded and deleted from device	25	3	54.697	
16:12.9	Video successfully uploaded from device when dockec				17184a35cace4d1d8cd2e6f840b5b7cb

16:13.2 Video deleted from device when docked	25	2	54.886	17184a35cace4d1d8cd2e6f840b5b7cb
16:13.2 Audit log rolled	25	2	54.886	
16:13.2 Audit log created	25	2	1.15.14	54.886
16:13.5 Video upload started when camera was docked				af032bd99f984202b0b2190294202e14
16:20.8 Audit log successfully uploaded				
16:21.0 Audit log successfully uploaded and deleted from device	25	2	54.886	
16:23.7 Video successfully uploaded from device when docked				af032bd99f984202b0b2190294202e14
16:23.9 Video deleted from device when docked	25	1	54.923	af032bd99f984202b0b2190294202e14
16:24.0 Audit log created	25	1	1.15.14	54.923
16:24.0 Audit log rolled	25	1	54.923	
16:24.1 Video upload started when camera was docked				cbbc14d802b84348a33aa924caa787ee
16:29.1 Audit log successfully uploaded				
16:29.3 Audit log successfully uploaded and deleted from device	25	1	54.923	
16:33.4 Audit log successfully uploaded				
16:33.6 Audit log successfully uploaded and deleted from device	25	1	54.923	
16:38.7 Audit log successfully uploaded				
16:38.9 Audit log successfully uploaded and deleted from device	25	1	54.923	
17:07.1 Audit log successfully uploaded				
17:07.3 Audit log successfully uploaded and deleted from device	26	1	54.923	
17:13.4 Audit log successfully uploaded				
17:13.6 Audit log successfully uploaded and deleted from device	26	1	54.923	
17:13.7 Audit log successfully uploaded				
17:13.9 Audit log successfully uploaded and deleted from device	26	1	54.923	
17:22.1 Video successfully uploaded from device when docked				cbbc14d802b84348a33aa924caa787ee
17:22.4 Video deleted from device when docked	26	0	55.153	cbbc14d802b84348a33aa924caa787ee
17:22.5 Audit log created	26	0	1.15.14	55.153
17:22.5 Audit log rolled	26	0	55.153	
17:22.6 Audit log rolled	26	0	55.153	
17:22.6 Audit log created	26	0	1.15.14	55.153
17:36.0 Audit log successfully uploaded				
17:36.3 Audit log successfully uploaded and deleted from device	26	0	55.153	
17:50.4 Audit log successfully uploaded				
17:50.7 Audit log successfully uploaded and deleted from device	26	0	55.153	
18:04.9 Audit log successfully uploaded				
18:05.0 Audit log successfully uploaded and deleted from device	26	0	55.153	
18:24.2 Audit log successfully uploaded				
18:24.5 Audit log successfully uploaded and deleted from device	26	0	55.153	
18:27.6 Audit log successfully uploaded				
18:27.8 Audit log successfully uploaded and deleted from device	26	0	55.153	
18:43.9 Audit log successfully uploaded				
18:44.1 Audit log successfully uploaded and deleted from device	27	0	55.153	
18:53.3 Audit log successfully uploaded				
18:53.5 Audit log successfully uploaded and deleted from device	27	0	55.153	
19:17.7 Audit log successfully uploaded				
19:17.9 Audit log successfully uploaded and deleted from device	27	0	55.153	
19:44.1 Audit log successfully uploaded				
19:44.3 Audit log successfully uploaded and deleted from device	27	0	55.153	

19:49.4	Audit log successfully uploaded			
19:49.7	Audit log successfully uploaded and deleted from device	27	0	55.153
19:58.8	Audit log successfully uploaded			
19:59.0	Audit log successfully uploaded and deleted from device	27	0	55.153
20:03.2	Audit log successfully uploaded			
20:03.4	Audit log successfully uploaded and deleted from device	27	0	55.152
20:19.6	Audit log successfully uploaded			
20:19.8	Audit log successfully uploaded and deleted from device	27	0	55.152
20:46.0	Audit log successfully uploaded			
20:46.1	Audit log successfully uploaded and deleted from device	27	0	55.152
20:51.3	Audit log successfully uploaded			
20:51.4	Audit log successfully uploaded and deleted from device	27	0	55.152
21:02.6	Audit log successfully uploaded			
21:02.8	Audit log successfully uploaded and deleted from device	27	0	55.152
21:16.9	Audit log successfully uploaded			
21:17.1	Audit log successfully uploaded and deleted from device	28	0	55.152
21:20.2	Audit log successfully uploaded			
21:20.4	Audit log successfully uploaded and deleted from device	28	0	55.152
21:27.5	Audit log successfully uploaded			
21:27.7	Audit log successfully uploaded and deleted from device	28	0	55.152
21:52.0	Audit log successfully uploaded			
21:52.2	Audit log successfully uploaded and deleted from device	28	0	55.152
22:19.3	Audit log successfully uploaded			
22:19.5	Audit log successfully uploaded and deleted from device	28	0	55.152
22:36.7	Audit log successfully uploaded			
22:36.9	Audit log successfully uploaded and deleted from device	28	0	55.152
22:47.0	Audit log successfully uploaded			
22:47.3	Audit log successfully uploaded and deleted from device	28	0	55.152
23:10.4	Audit log successfully uploaded			
23:10.6	Audit log successfully uploaded and deleted from device	29	0	55.152
23:38.8	Audit log successfully uploaded			
23:38.9	Audit log successfully uploaded and deleted from device	29	0	55.152
23:41.1	Audit log successfully uploaded			
23:41.2	Audit log successfully uploaded and deleted from device	29	0	55.152
23:46.4	Audit log successfully uploaded			
23:46.6	Audit log successfully uploaded and deleted from device	29	0	55.152
24:10.7	Audit log successfully uploaded			
24:10.9	Audit log successfully uploaded and deleted from device	29	0	55.152
24:19.1	Audit log successfully uploaded			
24:19.3	Audit log successfully uploaded and deleted from device	29	0	55.152
24:46.4	Audit log successfully uploaded			
24:46.6	Audit log successfully uploaded and deleted from device	29	0	55.152
24:46.7	Audit log successfully uploaded			
24:46.9	Audit log successfully uploaded and deleted from device	29	0	55.152
24:58.0	Audit log successfully uploaded			
24:58.1	Audit log successfully uploaded and deleted from device	29	0	55.152
25:02.5	Audit log successfully uploaded			

25:02.7 Audit log successfully uploaded and deleted from device	29	0	55.152
25:28.9 Audit log successfully uploaded			
25:29.1 Audit log successfully uploaded and deleted from device	29	0	55.152
25:46.3 Audit log successfully uploaded			
25:46.5 Audit log successfully uploaded and deleted from device	30	0	55.152
26:09.7 Audit log successfully uploaded			
26:09.9 Audit log successfully uploaded and deleted from device	30	0	55.152
26:27.0 Audit log successfully uploaded			
26:27.2 Audit log successfully uploaded and deleted from device	30	0	55.152
26:30.4 Audit log successfully uploaded			
26:30.6 Audit log successfully uploaded and deleted from device	30	0	55.152
26:34.7 Audit log successfully uploaded			
26:34.9 Audit log successfully uploaded and deleted from device	30	0	55.152
26:45.1 Audit log successfully uploaded			
26:45.3 Audit log successfully uploaded and deleted from device	30	0	55.152
27:14.5 Audit log successfully uploaded			
27:14.7 Audit log successfully uploaded and deleted from device	30	0	55.152
27:18.8 Audit log successfully uploaded			
27:19.0 Audit log successfully uploaded and deleted from device	30	0	55.152
27:48.1 Audit log successfully uploaded			
27:48.3 Audit log successfully uploaded and deleted from device	30	0	55.152
42:08.0 Date/Time synced to 09/15/2021 03:42:08.01 AM from 09/15/2021 03:42:03.05 AM			
42:50.7 Volume down button pressed			
42:50.7 Volume down button released			
42:51.1 Device disconnected from charger	37	0	55.154
42:51.2 Camera disconnected from Axon Dock X62001V12	37	0	55.154
17:21.9 Audit log created	35	0 1.15.14	55.158
17:21.9 Audit log created	29	0 1.15.14	55.157
17:21.9 Audit log created	22	0 1.15.14	55.156
19:11.2 Camera connected to Axon Dock X630020W7	22	0	55.155
19:11.2 Audit log rolled	22	0	55.156
19:11.2 Audit log created	22	0 1.15.14	55.156
19:12.2 Device connected to charger	22	0	55.155
19:11.0 Audit log created	49	0 1.15.14	55.155
19:11.0 Audit log created	75	0 1.15.14	55.154
19:11.0 Audit log created	98	0 1.15.14	55.153
19:11.0 Audit log created	100	0 1.15.14	55.152
19:11.0 Audit log created	100	0 1.15.14	55.151
19:11.0 Audit log created	100	0 1.15.14	55.151
19:11.0 Audit log created	100	0 1.15.14	55.15
19:11.1 Audit log created	100	0 1.15.14	55.15
19:11.1 Audit log created	100	0 1.15.14	55.15
19:11.1 Audit log created	100	0 1.15.14	55.149
19:11.1 Audit log created	100	0 1.15.14	55.149
19:11.1 Audit log created	100	0 1.15.14	55.148
52:09.1 Device disconnected from charger	98	0	55.148
52:09.2 Camera disconnected from Axon Dock X630020W7	98	0	55.148

19:11.1	Audit log created	96	0	1.15.14	55.149
19:11.1	Audit log created	90	0	1.15.14	55.147
19:11.1	Audit log created	84	0	1.15.14	55.146
19:11.1	Audit log created	78	0	1.15.14	55.145
23:54.3	Event button pressed				
23:54.4	Event button released				
23:54.5	Event button pressed				
23:54.5	Audio recording enabled due to video recording default				
23:54.5	Event button released				
23:54.6	Recording started due to button press	78	1		55.144 0527c021ccff4581a6571ce827d39424
54:36.1	Event button pressed				
54:39.1	Recording stopped due to button press	73	1		54.119 0527c021ccff4581a6571ce827d39424
54:39.7	Event button released				
54:40.0	Audio recording disabled due to video buffering default				
59:07.2	Axon application connected to device				
59:48.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-15 2223 X6033271L' to 'Signal 6 N6' using Axon applicator				0527c021ccff4581a6571ce827d39424
59:48.7	Categories 'Lost Property' added to video metadata using Axon applicator				0527c021ccff4581a6571ce827d39424
00:02.9	Axon application disconnected from device				
00:15.8	Camera connected to Axon Dock X62001V12	72	1		54.122
00:15.9	Audit log created	72	1	1.15.14	54.114
00:15.9	Audit log rolled	72	1		54.114
00:16.1	Device connected to charger	72	1		54.114
00:33.7	Video upload started when camera was docked				0527c021ccff4581a6571ce827d39424
00:42.5	Audit log successfully uploaded				
00:42.7	Audit log successfully uploaded and deleted from device	72	1		54.122
00:51.0	Date/Time synced to 09/15/2021 11:00:51.01 PM from 09/15/2021 11:00:50.90 PM				
00:52.9	Audit log successfully uploaded				
00:53.1	Audit log successfully uploaded and deleted from device	72	1		54.122
01:03.7	Audit log successfully uploaded				
01:03.9	Audit log successfully uploaded and deleted from device	73	1		54.122
01:28.0	Audit log successfully uploaded				
01:28.2	Audit log successfully uploaded and deleted from device	73	1		54.122
01:45.4	Audit log successfully uploaded				
01:45.5	Audit log successfully uploaded and deleted from device	73	1		54.122
01:48.7	Audit log successfully uploaded				
01:48.8	Audit log successfully uploaded and deleted from device	73	1		54.122
01:57.9	Audit log successfully uploaded				
01:58.1	Audit log successfully uploaded and deleted from device	73	1		54.122
02:13.3	Audit log successfully uploaded				
02:13.5	Audit log successfully uploaded and deleted from device	73	1		54.122
02:38.6	Audit log successfully uploaded				
02:38.8	Audit log successfully uploaded and deleted from device	73	1		54.122
02:56.9	Audit log successfully uploaded				
02:57.1	Audit log successfully uploaded and deleted from device	73	1		54.122
02:58.2	Audit log successfully uploaded				
02:58.4	Audit log successfully uploaded and deleted from device	73	1		54.122
03:08.5	Audit log successfully uploaded				

03:08.7	Audit log successfully uploaded and deleted from device	73	1	54.122
03:10.8	Audit log successfully uploaded			
03:11.0	Audit log successfully uploaded and deleted from device	73	1	54.122
03:17.1	Audit log successfully uploaded			
03:17.3	Audit log successfully uploaded and deleted from device	73	1	54.122
03:39.4	Audit log successfully uploaded			
03:39.6	Audit log successfully uploaded and deleted from device	74	1	54.122
04:02.6	Audit log successfully uploaded			
04:02.8	Audit log successfully uploaded and deleted from device	74	1	54.122
04:05.9	Audit log successfully uploaded			
04:06.1	Audit log successfully uploaded and deleted from device	74	1	54.122
04:15.2	Audit log successfully uploaded			
04:15.4	Audit log successfully uploaded and deleted from device	74	1	54.122
04:31.5	Audit log successfully uploaded			
04:31.7	Audit log successfully uploaded and deleted from device	74	1	54.122
04:43.8	Audit log successfully uploaded			
04:44.0	Audit log successfully uploaded and deleted from device	74	1	54.122
04:49.1	Audit log successfully uploaded			
04:49.3	Audit log successfully uploaded and deleted from device	74	1	54.122
05:09.9	Video successfully uploaded from device when docked			0527c021ccff4581a6571ce827d39424
05:10.4	Video deleted from device when docked	75	0	55.149 0527c021ccff4581a6571ce827d39424
05:10.5	Audit log created	75	0 1.15.14	55.149
05:10.5	Audit log rolled	75	0	55.149
05:10.6	Audit log created	75	0 1.15.14	55.149
05:10.6	Audit log rolled	75	0	55.149
05:16.4	Audit log successfully uploaded			
05:16.6	Audit log successfully uploaded and deleted from device	75	0	55.149
05:39.8	Audit log successfully uploaded			
05:40.0	Audit log successfully uploaded and deleted from device	75	0	55.149
06:00.2	Audit log successfully uploaded			
06:00.4	Audit log successfully uploaded and deleted from device	75	0	55.149
06:04.5	Audit log successfully uploaded			
06:04.7	Audit log successfully uploaded and deleted from device	75	0	55.149
06:13.9	Audit log successfully uploaded			
06:14.1	Audit log successfully uploaded and deleted from device	75	0	55.149
06:32.2	Audit log successfully uploaded			
06:32.4	Audit log successfully uploaded and deleted from device	75	0	55.148
06:35.5	Audit log successfully uploaded			
06:35.7	Audit log successfully uploaded and deleted from device	75	0	55.148
06:45.9	Audit log successfully uploaded			
06:46.1	Audit log successfully uploaded and deleted from device	75	0	55.148
06:52.3	Audit log successfully uploaded			
06:52.5	Audit log successfully uploaded and deleted from device	75	0	55.148
06:55.6	Audit log successfully uploaded			
06:55.8	Audit log successfully uploaded and deleted from device	75	0	55.148
07:20.9	Audit log successfully uploaded			
07:21.1	Audit log successfully uploaded and deleted from device	75	0	55.148

07:33.3	Audit log successfully uploaded			
07:33.5	Audit log successfully uploaded and deleted from device	75	0	55.148
07:33.6	Audit log successfully uploaded			
07:33.8	Audit log successfully uploaded and deleted from device	75	0	55.148
07:54.0	Audit log successfully uploaded			
07:54.2	Audit log successfully uploaded and deleted from device	76	0	55.148
07:57.3	Audit log successfully uploaded			
07:57.5	Audit log successfully uploaded and deleted from device	76	0	55.148
30:51.0	Date/Time synced to 09/15/2021 11:30:51.01 PM from 09/15/2021 11:30:51.03 PM			
43:06.1	Camera disconnected from Axon Dock X62001V12	92	0	55.149
43:06.1	Device disconnected from charger	92	0	55.149
05:09.8	Audit log created	89	0 1.15.14	55.152
05:09.9	Audit log created	82	0 1.15.14	55.151
05:09.9	Audit log created	76	0 1.15.14	55.149
50:44.9	Audio recording enabled due to video recording default			
50:45.1	Recording started due to Axon Signal Vehicle activation	71	0	55.148 393e732a9fd24a3a8cd7d2a1e48457ab
50:48.4	Event button pressed			
50:51.4	Recording stopped due to button press	71	1	55.134 393e732a9fd24a3a8cd7d2a1e48457ab
50:52.1	Event button released			
50:52.3	Audio recording disabled due to video buffering default			
05:09.9	Audit log created	70	1 1.15.14	55.084
05:09.9	Audit log created	63	1 1.15.14	55.082
28:56.9	Axon application connected to device			
29:17.0	Video played back using Axon application			393e732a9fd24a3a8cd7d2a1e48457ab
31:43.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-16 0250 X6033271L' to 'Accidental Recording' using Axon applicator			393e732a9fd24a3a8cd7d2a1e48457ab
31:43.9	Categories 'Accidental Recording' added to video metadata using Axon applicator			393e732a9fd24a3a8cd7d2a1e48457ab
32:07.2	Axon application disconnected from device			
05:09.9	Audit log created	56	1 1.15.14	55.081
05:09.9	Audit log created	49	1 1.15.14	55.079
46:59.8	Camera connected to Axon Dock X630020W7	45	1	55.078
46:59.8	Audit log created	45	1 1.15.14	55.078
46:59.8	Audit log rolled	45	1	55.078
47:01.0	Device connected to charger	45	1	55.078
46:59.0	Audit log created	74	1 1.15.14	55.077
46:59.0	Audit log created	97	1 1.15.14	55.076
46:59.0	Audit log created	100	1 1.15.14	55.076
46:59.1	Audit log created	100	1 1.15.14	55.075
46:59.1	Audit log created	100	1 1.15.14	55.075
46:59.1	Audit log created	100	1 1.15.14	55.074
46:59.1	Audit log created	100	1 1.15.14	55.074
46:59.1	Audit log created	100	1 1.15.14	55.073
46:59.1	Audit log created	100	1 1.15.14	55.073
46:59.1	Audit log created	100	1 1.15.14	55.074
46:59.1	Audit log created	100	1 1.15.14	55.073
46:59.1	Audit log created	100	1 1.15.14	55.073
24:03.0	Device disconnected from charger	98	1	55.073
24:03.5	Camera disconnected from Axon Dock X630020W7	98	1	55.073

46:59.1 Audit log created	97	1 1.15.14	55.077
46:59.1 Audit log created	90	1 1.15.14	55.076
53:50.8 Event button pressed			
53:51.2 Event button released			
53:52.7 Power button pressed			
53:56.0 Device powered off using button	89	1	55.076
53:56.4 Power button released			
38:35.0 Audit log created		1.15.14	
38:35.1 Device powered on using button	89	1	55.076
38:37.0 Audio recording disabled due to video buffering default			
38:35.0 Audit log created	84	1 1.15.14	55.074
38:35.0 Audit log created	78	1 1.15.14	55.073
38:11.0 Event button pressed			
38:11.1 Event button released			
38:11.1 Event button pressed			
38:11.2 Audio recording enabled due to video recording default			
38:11.3 Event button released			
38:11.4 Recording started due to button press	72	1	55.071 b36753babcab46b08c48d959cd332668
38:35.0 Audit log created	72	2 1.15.14	55.017
38:35.1 Event button pressed			
38:38.1 Recording stopped due to button press	72	2	55.01 b36753babcab46b08c48d959cd332668
38:38.5 Event button released			
38:39.0 Audio recording disabled due to video buffering default			
40:09.5 Event button pressed			
40:09.6 Event button released			
40:09.6 Event button pressed			
40:09.7 Audio recording enabled due to video recording default			
40:09.7 Event button released			
40:09.8 Recording started due to button press	71	3	54.996 777d4db07b55495485fc5803034cc3e9
44:04.8 Event button pressed			
44:07.8 Recording stopped due to button press	71	3	54.825 777d4db07b55495485fc5803034cc3e9
44:08.3 Event button released			
44:08.5 Audio recording disabled due to video buffering default			
50:29.0 Event button pressed			
50:29.1 Event button released			
50:29.2 Event button pressed			
50:29.2 Audio recording enabled due to video recording default			
50:29.3 Event button released			
50:29.3 Recording started due to button press	70	4	54.824 6e143985b5534235865027cf32467a8c
55:33.4 Event button pressed			
55:36.4 Recording stopped due to button press	69	4	54.6 6e143985b5534235865027cf32467a8c
55:37.1 Event button released			
55:37.3 Audio recording disabled due to video buffering default			
56:44.4 Event button pressed			
56:44.5 Event button released			
56:44.6 Event button pressed			
56:44.6 Audio recording enabled due to video recording default			

56:44.7	Event button released			
56:44.7	Recording started due to button press	69	5	54.599 b3d4adfc68645a9b57c4f4071a3ec45
56:56.7	Event button pressed			
56:59.7	Recording stopped due to button press	69	5	54.565 b3d4adfc68645a9b57c4f4071a3ec45
57:00.1	Event button released			
57:00.5	Audio recording disabled due to video buffering default			
03:25.5	Event button pressed			
03:25.7	Event button released			
03:25.8	Event button pressed			
03:25.8	Audio recording enabled due to video recording default			
03:25.8	Event button released			
03:25.9	Recording started due to button press	68	6	54.557 eae6ae8c03df4f4c9a4674396fc89af6
11:08.5	Event button pressed			
11:11.5	Recording stopped due to button press	66	6	54.25 eae6ae8c03df4f4c9a4674396fc89af6
11:11.9	Event button released			
11:12.4	Audio recording disabled due to video buffering default			
12:43.0	Event button pressed			
12:43.1	Event button released			
12:43.2	Event button pressed			
12:43.2	Audio recording enabled due to video recording default			
12:43.3	Event button released			
12:43.4	Recording started due to button press	66	7	54.248 ca604e3fdec54058a54c4b175568559b
13:48.2	Event button pressed			
13:51.2	Recording stopped due to button press	66	7	54.167 ca604e3fdec54058a54c4b175568559b
13:51.7	Event button released			
13:52.1	Audio recording disabled due to video buffering default			
14:03.0	Event button pressed			
14:03.2	Event button released			
14:03.2	Event button pressed			
14:03.3	Audio recording enabled due to video recording default			
14:03.3	Event button released			
14:03.4	Recording started due to button press	66	7	54.166 154a81cd24764944ab5ea114bc5cb42b
21:47.2	Event button pressed			
21:50.2	Recording stopped due to button press	64	8	53.914 154a81cd24764944ab5ea114bc5cb42b
21:50.9	Event button released			
21:51.1	Audio recording disabled due to video buffering default			
22:16.9	Event button pressed			
22:17.0	Event button released			
22:17.0	Event button pressed			
22:17.1	Audio recording enabled due to video recording default			
22:17.2	Event button released			
22:17.2	Recording started due to button press	64	9	53.912 1ef2c1e6ef0a4d5fbf783ebe6cf7768c
22:36.4	Event button pressed			
22:39.4	Recording stopped due to button press	64	9	53.888 1ef2c1e6ef0a4d5fbf783ebe6cf7768c
22:39.9	Event button released			
22:40.2	Audio recording disabled due to video buffering default			
28:35.5	Event button pressed			

28:35.7	Event button released			
28:35.7	Event button pressed			
28:35.8	Audio recording enabled due to video recording default			
28:35.9	Event button released			
28:35.9	Recording started due to button press	63	10	53.887 839ebd1c44be4c5b898fc1333d06ef3e
34:44.0	Event button pressed			
34:47.0	Recording stopped due to button press	62	10	53.63 839ebd1c44be4c5b898fc1333d06ef3e
34:47.5	Event button released			
34:47.9	Audio recording disabled due to video buffering default			
38:27.8	Axon application connected to device			
38:35.0	Audit log created	62	10 1.15.14	53.629
39:11.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0138 X6033271L' to 'Signal 75' using Axon applicator			b36753babcab46b08c48d959cd332668
39:11.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			b36753babcab46b08c48d959cd332668
39:32.0	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0140 X6033271L' to 'Signal 75' using Axon applicator			777d4db07b55495485fc5803034cc3e9
39:32.0	Categories 'Miscellaneous' added to video metadata using Axon applicator			777d4db07b55495485fc5803034cc3e9
39:48.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0150 X6033271L' to 'Signal 75' using Axon applicator			6e143985b5534235865027cf32467a8c
39:48.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			6e143985b5534235865027cf32467a8c
40:10.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0156 X6033271L' to 'Signal 75' using Axon applicator			b3d4adfc68645a9b57c4f4071a3ec45
40:10.4	Categories 'Miscellaneous' added to video metadata using Axon applicator			b3d4adfc68645a9b57c4f4071a3ec45
40:33.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0203 X6033271L' to 'Signal 75' using Axon applicator			eae6ae8c03df4f4c9a4674396fc89af6
40:33.8	Categories 'Miscellaneous' added to video metadata using Axon applicator			eae6ae8c03df4f4c9a4674396fc89af6
40:57.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0212 X6033271L' to 'Signal 75' using Axon applicator			ca604e3fdec54058a54c4b175568559b
40:57.3	Categories 'Miscellaneous' added to video metadata using Axon applicator			ca604e3fdec54058a54c4b175568559b
41:16.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0214 X6033271L' to 'Signal 75' using Axon applicator			154a81cd24764944ab5ea114bc5cb42b
41:16.7	Categories 'Miscellaneous' added to video metadata using Axon applicator			154a81cd24764944ab5ea114bc5cb42b
41:44.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0222 X6033271L' to 'Signal 75' using Axon applicator			1ef2c1e6ef0a4d5fbf783ebe6cf7768c
41:44.6	Categories 'Miscellaneous' added to video metadata using Axon applicator			1ef2c1e6ef0a4d5fbf783ebe6cf7768c
42:04.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-17 0228 X6033271L' to 'Signal 75' using Axon applicator			839ebd1c44be4c5b898fc1333d06ef3e
42:04.1	Categories 'Miscellaneous' added to video metadata using Axon applicator			839ebd1c44be4c5b898fc1333d06ef3e
42:36.7	Axon application disconnected from device			
59:42.7	Volume up button pressed			
59:43.0	Volume up button released			
59:43.0	Volume up button pressed			
59:43.1	Volume up button released			
59:43.2	Volume changed to high from medium using button			
59:43.4	Volume changed to very high from high using button			
59:45.7	Volume down button pressed			
59:45.9	Volume down button released			
59:46.0	Volume changed to high from very high using button			
59:47.0	Volume down button pressed			
59:47.2	Volume down button released			
59:47.3	Volume changed to medium from high using button			
59:54.8	Camera connected to Axon Dock X62001V12	60	10	53.644
59:54.8	Audit log created	60	10 1.15.14	53.627
59:54.8	Audit log rolled	60	10	53.627
59:56.1	Device connected to charger	60	10	53.627
00:18.9	Video upload started when camera was docked			393e732a9fd24a3a8cd7d2a1e48457ab

00:26.0	Date/Time synced to 09/17/2021 03:00:26.02 AM from 09/17/2021 03:00:24.91 AM				
00:37.3	Video successfully uploaded from device when dockec				393e732a9fd24a3a8cd7d2a1e48457ab
00:37.6	Video deleted from device when docked	61	9	53.708	393e732a9fd24a3a8cd7d2a1e48457ab
00:37.6	Audit log created	61	9 1.15.14	53.708	
00:37.6	Audit log rolled	61	9	53.708	
00:37.8	Video upload started when camera was docked				b36753babcab46b08c48d959cd332668
00:52.2	Audit log successfully uploaded				
00:52.4	Audit log successfully uploaded and deleted from device	61	9	53.708	
01:00.4	Video successfully uploaded from device when dockec				b36753babcab46b08c48d959cd332668
01:00.6	Audit log successfully uploaded				
01:00.6	Video deleted from device when docked	61	8	53.783	b36753babcab46b08c48d959cd332668
01:00.7	Audit log rolled	61	8	53.783	
01:00.7	Audit log created	61	8 1.15.14	53.783	
01:00.8	Audit log successfully uploaded and deleted from device	61	8	53.783	
01:00.9	Video upload started when camera was docked				777d4db07b55495485fc5803034cc3e9
01:17.9	Audit log successfully uploaded				
01:18.1	Audit log successfully uploaded and deleted from device	61	8	53.783	
01:40.2	Audit log successfully uploaded				
01:40.4	Audit log successfully uploaded and deleted from device	61	8	53.783	
01:49.0	Video successfully uploaded from device when dockec				777d4db07b55495485fc5803034cc3e9
01:49.3	Video deleted from device when docked	61	7	53.953	777d4db07b55495485fc5803034cc3e9
01:49.3	Audit log created	61	7 1.15.14	53.954	
01:49.3	Audit log rolled	61	7	53.954	
01:49.5	Video upload started when camera was docked				6e143985b5534235865027cf32467a8c
01:59.5	Audit log successfully uploaded				
01:59.7	Audit log successfully uploaded and deleted from device	61	7	53.954	
02:17.8	Audit log successfully uploaded				
02:18.0	Audit log successfully uploaded and deleted from device	61	7	53.953	
02:36.2	Audit log successfully uploaded				
02:36.4	Audit log successfully uploaded and deleted from device	61	7	53.953	
02:52.0	Video successfully uploaded from device when dockec				6e143985b5534235865027cf32467a8c
02:52.3	Video deleted from device when docked	61	6	54.176	6e143985b5534235865027cf32467a8c
02:52.3	Audit log rolled	61	6	54.176	
02:52.3	Audit log created	61	6 1.15.14	54.176	
02:52.5	Video upload started when camera was docked				b3d4adfc68645a9b57c4f4071a3ec45
02:55.5	Audit log successfully uploaded				
02:55.6	Audit log successfully uploaded and deleted from device	61	6	54.176	
03:05.5	Video successfully uploaded from device when dockec				b3d4adfc68645a9b57c4f4071a3ec45
03:05.7	Video deleted from device when docked	61	5	54.218	b3d4adfc68645a9b57c4f4071a3ec45
03:05.8	Audit log rolled	61	5	54.218	
03:05.8	Audit log created	61	5 1.15.14	54.218	
03:06.0	Video upload started when camera was docked				ea6ae8c03df4f4c9a4674396fc89af6
03:10.8	Audit log successfully uploaded				
03:10.9	Audit log successfully uploaded and deleted from device	61	5	54.218	
03:30.0	Audit log successfully uploaded				
03:30.2	Audit log successfully uploaded and deleted from device	62	5	54.218	
03:53.3	Audit log successfully uploaded				

03:53.5	Audit log successfully uploaded and deleted from device	62	5	54.218
04:02.3	Audit log successfully uploaded			
04:02.5	Audit log successfully uploaded and deleted from device	62	5	54.218
04:22.6	Audit log successfully uploaded			
04:22.8	Audit log successfully uploaded and deleted from device	62	5	54.218
04:28.1	Video successfully uploaded from device when dockec			eae6ae8c03df4f4c9a4674396fc89af6
04:28.4	Video deleted from device when docked	62	4	54.523 eae6ae8c03df4f4c9a4674396fc89af6
04:28.4	Audit log rolled	62	4	54.523
04:28.4	Audit log created	62	4 1.15.14	54.523
04:28.7	Video upload started when camera was docked			ca604e3fdec54058a54c4b175568559b
04:44.9	Audit log successfully uploaded			
04:45.1	Audit log successfully uploaded and deleted from device	62	4	54.523
04:50.8	Video successfully uploaded from device when dockec			ca604e3fdec54058a54c4b175568559b
04:51.0	Video deleted from device when docked	62	3	54.604 ca604e3fdec54058a54c4b175568559b
04:51.1	Audit log rolled	62	3	54.605
04:51.1	Audit log created	62	3 1.15.14	54.605
04:51.3	Video upload started when camera was docked			154a81cd24764944ab5ea114bc5cb42b
05:00.3	Audit log successfully uploaded			
05:00.4	Audit log successfully uploaded and deleted from device	63	3	54.605
05:23.6	Audit log successfully uploaded			
05:23.7	Audit log successfully uploaded and deleted from device	63	3	54.605
05:26.2	Audit log successfully uploaded			
05:26.3	Audit log successfully uploaded and deleted from device	63	3	54.605
05:53.5	Audit log successfully uploaded			
05:53.7	Audit log successfully uploaded and deleted from device	63	3	54.604
05:59.1	Video successfully uploaded from device when dockec			154a81cd24764944ab5ea114bc5cb42b
05:59.5	Video deleted from device when docked	63	2	54.855 154a81cd24764944ab5ea114bc5cb42b
05:59.5	Audit log rolled	63	2	54.856
05:59.5	Audit log created	63	2 1.15.14	54.856
05:59.7	Video upload started when camera was docked			1ef2c1e6ef0a4d5fbf783ebe6cf7768c
05:59.8	Audit log successfully uploaded			
06:00.0	Audit log successfully uploaded and deleted from device	63	2	54.856
06:06.9	Video successfully uploaded from device when dockec			1ef2c1e6ef0a4d5fbf783ebe6cf7768c
06:07.1	Video deleted from device when docked	63	1	54.881 1ef2c1e6ef0a4d5fbf783ebe6cf7768c
06:07.1	Audit log successfully uploaded			
06:07.2	Audit log rolled	63	1	54.882
06:07.2	Audit log created	63	1 1.15.14	54.882
06:07.3	Audit log successfully uploaded and deleted from device	63	1	54.882
06:07.4	Video upload started when camera was docked			839ebd1c44be4c5b898fc1333d06ef3e
06:22.6	Audit log successfully uploaded			
06:22.8	Audit log successfully uploaded and deleted from device	63	1	54.882
06:32.9	Audit log successfully uploaded			
06:33.0	Audit log successfully uploaded and deleted from device	63	1	54.882
06:50.3	Audit log successfully uploaded			
06:50.4	Audit log successfully uploaded and deleted from device	63	1	54.882
07:09.6	Audit log successfully uploaded			
07:09.7	Audit log successfully uploaded and deleted from device	63	1	54.882

07:18.3 Video successfully uploaded from device when dockec			839ebd1c44be4c5b898fc1333d06ef3e
07:18.7 Video deleted from device when docked	63	0	55.137 839ebd1c44be4c5b898fc1333d06ef3e
07:18.7 Audit log rolled	63	0	55.147
07:18.7 Audit log created	63	0 1.15.14	55.147
07:18.8 Audit log rolled	63	0	55.147
07:18.8 Audit log created	63	0 1.15.14	55.147
07:21.9 Audit log successfully uploaded			
07:22.1 Audit log successfully uploaded and deleted from device	63	0	55.147
07:30.2 Audit log successfully uploaded			
07:30.4 Audit log successfully uploaded and deleted from device	64	0	55.147
07:51.6 Audit log successfully uploaded			
07:51.8 Audit log successfully uploaded and deleted from device	64	0	55.146
08:06.9 Audit log successfully uploaded			
08:07.2 Audit log successfully uploaded and deleted from device	64	0	55.146
08:31.3 Audit log successfully uploaded			
08:31.6 Audit log successfully uploaded and deleted from device	64	0	55.146
08:35.7 Audit log successfully uploaded			
08:35.9 Audit log successfully uploaded and deleted from device	64	0	55.146
08:55.0 Audit log successfully uploaded			
08:55.2 Audit log successfully uploaded and deleted from device	64	0	55.146
12:22.8 Camera disconnected from Axon Dock X62001V12	66	0	55.147
12:22.8 Device disconnected from charger	66	0	55.147
07:18.0 Audit log created	61	0 1.15.14	55.15
07:18.0 Audit log created	53	0 1.15.14	55.148
48:22.0 Event button pressed			
48:23.3 Event button released			
07:18.0 Audit log created	46	0 1.15.14	55.147
37:40.3 Volume up button pressed			
37:40.5 Volume up button released			
37:40.6 Volume changed to high from medium using button			
37:43.0 Volume down button pressed			
37:43.2 Volume down button released			
37:43.3 Volume changed to medium from high using button			
37:46.6 Audit log created	43	0 1.15.14	55.146
37:46.6 Audit log rolled	43	0	55.146
37:46.6 Camera connected to Axon Dock X630020W7	43	0	55.146
37:47.8 Device connected to charger	43	0	55.146
37:46.0 Audit log created	71	0 1.15.14	55.146
37:46.0 Audit log created	97	0 1.15.14	55.145
37:46.0 Audit log created	100	0 1.15.14	55.144
37:46.0 Audit log created	100	0 1.15.14	55.143
37:46.0 Audit log created	100	0 1.15.14	55.142
37:46.0 Audit log created	100	0 1.15.14	55.142
37:46.1 Audit log created	100	0 1.15.14	55.141
37:46.1 Audit log created	100	0 1.15.14	55.141
37:46.1 Audit log created	100	0 1.15.14	55.141

37:46.1 Audit log created	100	0 1.15.14	55.14
37:46.1 Audit log created	100	0 1.15.14	55.14
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.138
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.1 Audit log created	100	0 1.15.14	55.139
37:46.2 Audit log created	100	0 1.15.14	55.139
37:46.2 Audit log created	100	0 1.15.14	55.138
37:46.2 Audit log created	100	0 1.15.14	55.138
37:46.2 Audit log created	100	0 1.15.14	55.138
37:46.2 Audit log created	100	0 1.15.14	55.138
37:46.2 Audit log created	100	0 1.15.14	55.137
37:46.2 Audit log created	100	0 1.15.14	55.137
37:46.2 Audit log created	100	0 1.15.14	55.137
37:46.2 Audit log created	100	0 1.15.14	55.139
37:46.2 Audit log created	100	0 1.15.14	55.139
37:46.3 Audit log created	100	0 1.15.14	55.138
12:39.8 Device disconnected from charger	98	0	55.141
12:39.8 Camera disconnected from Axon Dock X630020W7	98	0	55.141
12:44.0 Programmable button pressed			
12:44.1 Programmable button released			
37:46.4 Audit log created	96	0 1.15.14	55.143
37:46.4 Audit log created	90	0 1.15.14	55.141
06:05.7 Event button pressed			
06:06.0 Event button released			
16:50.5 Camera connected to Axon Dock X630020W7	86	0	55.141
16:50.5 Audit log created	86	0 1.15.14	55.141
16:50.5 Audit log rolled	86	0	55.141
16:51.8 Device connected to charger	86	0	55.141
16:50.0 Audit log created	100	0 1.15.14	55.14
16:50.0 Audit log created	100	0 1.15.14	55.14
16:50.0 Audit log created	100	0 1.15.14	55.14
16:50.0 Audit log created	100	0 1.15.14	55.14
16:50.0 Audit log created	100	0 1.15.14	55.139
16:50.0 Audit log created	100	0 1.15.14	55.139
16:50.1 Audit log created	100	0 1.15.14	55.139
16:50.1 Audit log created	100	0 1.15.14	55.139
16:50.1 Audit log created	100	0 1.15.14	55.138
16:50.1 Audit log created	100	0 1.15.14	55.138
16:50.1 Audit log created	100	0 1.15.14	55.138
16:50.1 Audit log created	100	0 1.15.14	55.137
16:50.1 Audit log created	100	0 1.15.14	55.137

19:37.8 Device disconnected from charger	100	0	55.137
19:37.8 Camera disconnected from Axon Dock X630020W7	100	0	55.139
20:03.1 Power button pressed			
20:06.1 Device powered off using button	100	0	55.139
20:06.5 Power button released			
52:59.2 Audit log created		1.15.14	
52:59.3 Device powered on using button	100	0	55.138
53:02.3 Audio recording disabled due to video buffering default			
52:59.3 Audit log created	92	0 1.15.14	55.136
52:59.3 Audit log created	86	0 1.15.14	55.135
52:59.3 Audit log created	80	0 1.15.14	55.133
16:04.2 Volume up button pressed			
16:04.2 Volume up button released			
16:04.4 Volume changed to high from medium using button			
16:07.6 Volume down button pressed			
16:07.8 Volume down button released			
16:08.0 Volume changed to medium from high using button			
16:10.9 Camera connected to Axon Dock X630020W7	78	0	55.143
16:10.9 Audit log created	78	0 1.15.14	55.143
16:10.9 Audit log rolled	78	0	55.142
16:11.3 Device connected to charger	78	0	55.143
16:10.0 Audit log created	99	0 1.15.14	55.142
16:10.0 Audit log created	100	0 1.15.14	55.141
16:10.0 Audit log created	100	0 1.15.14	55.14
16:10.0 Audit log created	100	0 1.15.14	55.14
16:10.0 Audit log created	100	0 1.15.14	55.14
16:10.1 Audit log created	100	0 1.15.14	55.139
16:10.1 Audit log created	100	0 1.15.14	55.139
16:10.1 Audit log created	100	0 1.15.14	55.138
16:10.1 Audit log created	100	0 1.15.14	55.138
16:10.1 Audit log created	100	0 1.15.14	55.137
16:10.1 Audit log created	100	0 1.15.14	55.138
16:10.1 Audit log created	100	0 1.15.14	55.138
16:10.1 Audit log created	100	0 1.15.14	55.138
16:10.1 Audit log created	100	0 1.15.14	55.138
49:00.3 Device disconnected from charger	99	0	55.137
49:00.4 Camera disconnected from Axon Dock X630020W7	100	0	55.137
49:03.5 Camera connected to Axon Dock X630020W7	100	0	55.14
49:03.5 Audit log created	100	0 1.15.14	55.14
49:03.5 Audit log rolled	100	0	55.139
49:04.3 Device connected to charger	100	0	55.14
49:03.0 Audit log created	100	0 1.15.14	55.139
49:03.0 Audit log created	100	0 1.15.14	55.139
49:03.0 Audit log created	100	0 1.15.14	55.139
03:01.3 Camera disconnected from Axon Dock X630020W7	100	0	55.139
03:01.3 Device disconnected from charger	100	0	55.139

49:03.0 Audit log created	94	0	1.15.14	55.138
10:06.2 Event button pressed				
10:06.3 Event button released				
49:03.1 Audit log created	88	0	1.15.14	55.136
49:03.1 Audit log created	82	0	1.15.14	55.135
57:12.1 Event button pressed				
57:12.2 Event button released				
57:12.3 Event button pressed				
57:12.3 Audio recording enabled due to video recording default				
57:12.3 Event button released				
57:12.5 Recording started due to button press	81	1		55.134 8826243e35754900af45ac6541ee22be
58:02.5 Event button pressed				
58:05.5 Recording stopped due to button press	81	1		55.046 8826243e35754900af45ac6541ee22be
58:06.2 Audio recording disabled due to video buffering default				
58:06.4 Event button released				
49:03.1 Audit log created	76	1	1.15.14	55.045
49:03.1 Audit log created	71	1	1.15.14	55.043
49:03.1 Audit log created	64	1	1.15.14	55.042
32:30.4 Power button pressed				
32:33.4 Device powered off using button	60	1		55.041
32:34.1 Power button released				
50:21.1 Audit log created			1.15.14	
50:21.2 Device powered on using button	60	1		55.04
50:24.3 Audio recording disabled due to video buffering default				
43:04.1 Power button pressed				
43:07.1 Device powered off using button	53	1		55.043
43:07.6 Power button released				
43:53.3 Device powered on using button	53	1		55.042
43:56.5 Audio recording disabled due to video buffering default				
44:18.3 Event button pressed				
44:18.4 Event button released				
44:18.5 Event button pressed				
44:18.5 Audio recording enabled due to video recording default				
44:18.5 Event button released				
44:18.7 Recording started due to button press	53	2		55.042 3bf142ff629b408da4da1a7e03ded844
50:21.0 Audit log created	52	2	1.15.14	54.84
12:11.4 Event button pressed				
12:14.4 Recording stopped due to button press	47	2		54.145 3bf142ff629b408da4da1a7e03ded844
12:15.1 Audio recording disabled due to video buffering default				
12:15.4 Event button released				
50:21.1 Audit log created	43	2	1.15.14	54.14
12:44.2 Axon application connected to device				
13:53.7 Title changed in video metadata from 'Axon Body 3 Video 2021-09-20 1757 X6033271L' to 'Signal 75' using Axon applicator				8826243e35754900af45ac6541ee22be
13:53.7 Categories 'Miscellaneous' added to video metadata using Axon applicator				8826243e35754900af45ac6541ee22be
14:41.9 Title changed in video metadata from 'Axon Body 3 Video 2021-09-20 2244 X6033271L' to 'Signal 75/47' using Axon applicator				3bf142ff629b408da4da1a7e03ded844
14:41.9 Categories 'Miscellaneous', 'Ambulance Call' added to video metadata using Axon applicator				3bf142ff629b408da4da1a7e03ded844
15:25.9 Title changed in video metadata from 'Signal 75' to 'Signal 75/57' using Axon application				8826243e35754900af45ac6541ee22be

15:25.9	Categories 'Loud Radio' added to video metadata using Axon applicator				8826243e35754900af45ac6541ee22be
15:31.2	Axon application disconnected from device				
15:45.4	Camera connected to Axon Dock X62001W9H	41	2	54.17	
15:45.5	Audit log rolled	41	2	54.139	
15:45.5	Audit log created	41	2 1.15.14	54.139	
15:46.3	Device connected to charger	41	2	54.139	
16:02.6	Video upload started when camera was docked				8826243e35754900af45ac6541ee22be
16:17.0	Date/Time synced to 09/21/2021 12:16:17.01 AM from 09/21/2021 12:16:15.53 AM				
16:24.8	Audit log successfully uploaded				
16:25.0	Audit log successfully uploaded and deleted from device	41	2	54.169	
16:29.3	Video successfully uploaded from device when docked				8826243e35754900af45ac6541ee22be
16:29.5	Video deleted from device when docked	41	1	54.258	8826243e35754900af45ac6541ee22be
16:29.6	Audit log created	41	1 1.15.14	54.258	
16:29.6	Audit log rolled	41	1	54.258	
16:29.8	Video upload started when camera was docked				3bf142ff629b408da4da1a7e03ded844
16:53.4	Audit log successfully uploaded				
16:53.6	Audit log successfully uploaded and deleted from device	41	1	54.258	
17:16.7	Audit log successfully uploaded				
17:16.9	Audit log successfully uploaded and deleted from device	41	1	54.258	
17:26.1	Audit log successfully uploaded				
17:26.2	Audit log successfully uploaded and deleted from device	41	1	54.258	
17:49.4	Audit log successfully uploaded				
17:49.6	Audit log successfully uploaded and deleted from device	42	1	54.258	
18:03.4	Audit log successfully uploaded				
18:03.6	Audit log successfully uploaded and deleted from device	42	1	54.258	
18:26.8	Audit log successfully uploaded				
18:27.0	Audit log successfully uploaded and deleted from device	42	1	54.258	
18:27.1	Audit log successfully uploaded				
18:27.3	Audit log successfully uploaded and deleted from device	42	1	54.258	
18:48.4	Audit log successfully uploaded				
18:48.6	Audit log successfully uploaded and deleted from device	42	1	54.258	
19:08.7	Audit log successfully uploaded				
19:08.9	Audit log successfully uploaded and deleted from device	42	1	54.258	
19:37.1	Audit log successfully uploaded				
19:37.3	Audit log successfully uploaded and deleted from device	42	1	54.258	
19:56.4	Audit log successfully uploaded				
19:56.6	Audit log successfully uploaded and deleted from device	42	1	54.258	
20:01.8	Audit log successfully uploaded				
20:02.0	Audit log successfully uploaded and deleted from device	42	1	54.258	
20:14.1	Audit log successfully uploaded				
20:14.3	Audit log successfully uploaded and deleted from device	43	1	54.258	
20:32.0	Video successfully uploaded from device when docked				3bf142ff629b408da4da1a7e03ded844
20:32.6	Video deleted from device when docked	43	0	55.148	3bf142ff629b408da4da1a7e03ded844
20:32.7	Audit log created	43	0 1.15.14	55.148	
20:32.7	Audit log rolled	43	0	55.148	
20:32.7	Audit log rolled	43	0	55.148	
20:32.7	Audit log created	43	0 1.15.14	55.148	

20:36.4	Audit log successfully uploaded			
20:36.6	Audit log successfully uploaded and deleted from device	43	0	55.148
20:56.8	Audit log successfully uploaded			
20:57.0	Audit log successfully uploaded and deleted from device	43	0	55.148
21:25.2	Audit log successfully uploaded			
21:25.4	Audit log successfully uploaded and deleted from device	43	0	55.148
21:35.6	Audit log successfully uploaded			
21:35.8	Audit log successfully uploaded and deleted from device	43	0	55.148
21:42.9	Audit log successfully uploaded			
21:43.1	Audit log successfully uploaded and deleted from device	43	0	55.148
22:11.3	Audit log successfully uploaded			
22:11.5	Audit log successfully uploaded and deleted from device	44	0	55.148
22:24.7	Audit log successfully uploaded			
22:24.9	Audit log successfully uploaded and deleted from device	44	0	55.148
22:32.1	Audit log successfully uploaded			
22:32.3	Audit log successfully uploaded and deleted from device	44	0	55.148
22:50.5	Audit log successfully uploaded			
22:50.7	Audit log successfully uploaded and deleted from device	44	0	55.148
22:52.8	Audit log successfully uploaded			
22:53.0	Audit log successfully uploaded and deleted from device	44	0	55.148
22:59.2	Audit log successfully uploaded			
22:59.4	Audit log successfully uploaded and deleted from device	44	0	55.148
23:17.5	Audit log successfully uploaded			
23:17.7	Audit log successfully uploaded and deleted from device	44	0	55.148
23:38.9	Audit log successfully uploaded			
23:39.1	Audit log successfully uploaded and deleted from device	44	0	55.148
24:00.3	Audit log successfully uploaded			
24:00.5	Audit log successfully uploaded and deleted from device	44	0	55.148
24:14.6	Audit log successfully uploaded			
24:14.8	Audit log successfully uploaded and deleted from device	44	0	55.148
24:27.6	Camera disconnected from Axon Dock X62001W9H	45	0	55.148
24:28.4	Device disconnected from charger	45	0	55.149
24:30.4	Programmable button pressed			
24:30.5	Programmable button released			
20:32.0	Audit log created	39	0 1.15.14	55.148
20:32.0	Audit log created	34	0 1.15.14	55.146
25:20.6	Camera connected to Axon Dock X630020W7	33	0	55.147
25:20.7	Audit log rolled	33	0	55.146
25:20.7	Audit log created	33	0 1.15.14	55.146
25:21.4	Device connected to charger	33	0	55.147
25:20.0	Audit log created	61	0 1.15.14	55.146
25:20.0	Audit log created	88	0 1.15.14	55.145
25:20.0	Audit log created	100	0 1.15.14	55.145
25:20.0	Audit log created	100	0 1.15.14	55.144
25:20.0	Audit log created	100	0 1.15.14	55.144
25:20.1	Audit log created	100	0 1.15.14	55.144
25:20.1	Audit log created	100	0 1.15.14	55.143

25:20.1 Audit log created	100	0 1.15.14	55.143
25:20.1 Audit log created	100	0 1.15.14	55.143
25:20.1 Audit log created	100	0 1.15.14	55.143
25:20.1 Audit log created	100	0 1.15.14	55.142
25:20.1 Audit log created	100	0 1.15.14	55.142
25:20.1 Audit log created	100	0 1.15.14	55.142
36:24.4 Device disconnected from charger	100	0	55.142
36:24.4 Camera disconnected from Axon Dock X630020W7	100	0	55.143
36:28.2 Programmable button pressed			
36:28.2 Programmable button released			
25:20.1 Audit log created	94	0 1.15.14	55.142
25:20.2 Audit log created	87	0 1.15.14	55.14
25:20.2 Audit log created	82	0 1.15.14	55.139
25:20.2 Audit log created	76	0 1.15.14	55.138
25:20.2 Audit log created	70	0 1.15.14	55.136
25:20.2 Audit log created	63	0 1.15.14	55.135
25:20.2 Audit log created	57	0 1.15.14	55.134
25:20.2 Audit log created	50	0 1.15.14	55.132
27:22.8 Volume up button pressed			
27:23.0 Volume up button released			
27:23.1 Volume changed to high from medium using button			
27:35.7 Camera connected to Axon Dock X62001W9H	50	0	55.14
27:35.7 Audit log rolled	49	0	55.132
27:35.7 Audit log created	49	0 1.15.14	55.132
27:36.4 Device connected to charger	49	0	55.132
28:06.0 Date/Time synced to 09/21/2021 11:28:06.01 PM from 09/21/2021 11:28:05.68 PM			
28:11.1 Audit log successfully uploaded			
28:11.4 Audit log successfully uploaded and deleted from device	50	0	55.14
28:44.4 Audit log successfully uploaded			
28:44.6 Audit log successfully uploaded and deleted from device	50	0	55.14
29:09.8 Audit log successfully uploaded			
29:10.0 Audit log successfully uploaded and deleted from device	50	0	55.14
29:36.1 Audit log successfully uploaded			
29:36.4 Audit log successfully uploaded and deleted from device	50	0	55.14
29:40.6 Audit log successfully uploaded			
29:40.8 Audit log successfully uploaded and deleted from device	50	0	55.14
30:00.9 Audit log successfully uploaded			
30:01.1 Audit log successfully uploaded and deleted from device	51	0	55.14
30:03.2 Audit log successfully uploaded			
30:03.4 Audit log successfully uploaded and deleted from device	51	0	55.14
30:21.6 Audit log successfully uploaded			
30:21.9 Audit log successfully uploaded and deleted from device	51	0	55.14
30:24.0 Audit log successfully uploaded			
30:24.2 Audit log successfully uploaded and deleted from device	51	0	55.14
30:48.4 Audit log successfully uploaded			
30:48.6 Audit log successfully uploaded and deleted from device	51	0	55.14
31:14.7 Audit log successfully uploaded			

37:50.0	Event button pressed			
37:53.0	Recording stopped due to button press	89	1	55.08 6ea56aa097cc458f8417f15bf152933d
37:53.9	Event button released			
37:54.0	Audio recording disabled due to video buffering default			
41:50.3	Power button pressed			
41:53.3	Device powered off using button	89	1	55.064
41:53.7	Power button released			
43:50.2	Device powered on using button	89	1	55.063
43:53.4	Audio recording disabled due to video buffering default			
57:34.9	Event button pressed			
57:35.0	Event button released			
57:35.1	Event button pressed			
57:35.2	Audio recording enabled due to video recording default			
57:35.2	Event button released			
57:35.4	Recording started due to button press	87	2	55.063 c1ed479801b04d56a718b67beac4cf03
14:23.0	Audit log created	84	2 1.15.14	54.47
41:35.3	Event button pressed			
41:38.3	Recording stopped due to button press	80	2	53.606 c1ed479801b04d56a718b67beac4cf03
41:38.9	Event button released			
41:39.4	Audio recording disabled due to video buffering default			
52:36.4	Axon application connected to device			
53:10.1	Axon application connected to device			
53:42.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 1637 X6033271L' to 'Signal 57' using Axon applicator			6ea56aa097cc458f8417f15bf152933d
53:42.8	Categories 'Loud Radio' added to video metadata using Axon applicator			6ea56aa097cc458f8417f15bf152933d
55:14.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 1657 X6033271L' to 'Signal 83/65s / CODE 28A' using Axon applicator			c1ed479801b04d56a718b67beac4cf03
55:14.4	Categories 'Wanted Person Located' added to video metadata using Axon applicator			c1ed479801b04d56a718b67beac4cf03
09:21.6	Event button pressed			
09:21.7	Event button released			
09:21.8	Event button pressed			
09:21.9	Audio recording enabled due to video recording default			
09:21.9	Event button released			
09:22.0	Recording started due to button press	77	3	53.598 757a5144062f46318b1be1c5f41d6002
10:02.0	Event button pressed			
10:05.0	Recording stopped due to button press	77	3	53.516 757a5144062f46318b1be1c5f41d6002
10:05.8	Event button released			
10:05.8	Audio recording disabled due to video buffering default			
14:23.1	Audit log created	77	3 1.15.14	53.515
30:52.3	Axon application disconnected from device			
14:23.1	Audit log created	71	3 1.15.14	53.513
23:07.2	Power button pressed			
23:10.4	Device powered off using button	70	3	53.513
23:10.6	Power button released			
23:59.0	Device powered on using button	70	3	53.514
24:01.1	Audio recording disabled due to video buffering default			
28:37.8	Event button pressed			
28:37.9	Event button released			
28:38.0	Event button pressed			

28:38.0	Audio recording enabled due to video recording default			
28:38.1	Event button released			
28:38.2	Recording started due to button press	69	4	53.514 0183016bf02c4daba060101d8ed37cad
33:17.8	Event button pressed			
33:20.8	Recording stopped due to button press	68	4	53.304 0183016bf02c4daba060101d8ed37cad
33:21.3	Event button released			
33:21.7	Audio recording disabled due to video buffering default			
34:50.8	Event button pressed			
34:51.0	Event button released			
34:51.0	Event button pressed			
34:51.1	Audio recording enabled due to video recording default			
34:51.2	Event button released			
34:51.3	Recording started due to button press	68	5	53.303 33326060be5345a590b12ece975db3c8
52:36.0	Event button pressed			
52:37.4	Event button released			
57:13.7	Event button pressed			
57:16.8	Recording stopped due to button press	63	5	52.547 33326060be5345a590b12ece975db3c8
57:17.5	Event button released			
57:17.7	Audio recording disabled due to video buffering default			
08:04.9	Event button pressed			
08:05.1	Event button released			
08:05.1	Event button pressed			
08:05.1	Audio recording enabled due to video recording default			
08:05.2	Event button released			
08:05.3	Recording started due to button press	63	6	52.543 2e21562e1d7d42c68c428c00f1390f2c
13:19.8	Event button pressed			
13:22.8	Recording stopped due to button press	61	6	52.315 2e21562e1d7d42c68c428c00f1390f2c
13:23.4	Event button released			
13:23.8	Audio recording disabled due to video buffering default			
14:23.1	Audit log created	61	6 1.15.14	52.313
17:58.1	Power button pressed			
18:01.3	Device powered off using button	61	6	52.313
18:01.6	Power button released			
20:30.1	Device powered on using button	61	6	52.313
20:31.9	Audio recording disabled due to video buffering default			
14:23.0	Audit log created	54	6 1.15.14	52.312
55:55.9	Axon application connected to device			
57:50.7	Video played back using Axon application			757a5144062f46318b1be1c5f41d6002
58:48.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 1809 X6033271L' to 'Signal 75' using Axon applicator			757a5144062f46318b1be1c5f41d6002
58:48.5	Categories 'Miscellaneous' added to video metadata using Axon applicator			757a5144062f46318b1be1c5f41d6002
59:17.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 1928 X6033271L' to 'Signal 47' using Axon applicator			0183016bf02c4daba060101d8ed37cad
59:17.5	Categories 'Ambulance Call' added to video metadata using Axon applicator			0183016bf02c4daba060101d8ed37cad
59:33.2	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 1934 X6033271L' to 'Signal 47' using Axon applicator			33326060be5345a590b12ece975db3c8
59:33.2	Categories 'Ambulance Call' added to video metadata using Axon applicator			33326060be5345a590b12ece975db3c8
59:49.8	Title changed in video metadata from 'Axon Body 3 Video 2021-09-22 2008 X6033271L' to 'Signal 47' using Axon applicator			2e21562e1d7d42c68c428c00f1390f2c
59:49.8	Categories 'Ambulance Call' added to video metadata using Axon applicator			2e21562e1d7d42c68c428c00f1390f2c
00:04.9	Axon application disconnected from device			

09:23.4	Event button pressed			
09:23.5	Event button released			
09:23.6	Event button pressed			
09:23.6	Audio recording enabled due to video recording default			
09:23.7	Event button released			
09:23.8	Recording started due to button press	48	7	52.309 f2c8c5b25d1a44cb92e572d9fcb7cd2d
14:23.0	Audit log created	47	7 1.15.14	52.091
14:47.6	Event button pressed			
14:50.6	Recording stopped due to button press	47	7	52.077 f2c8c5b25d1a44cb92e572d9fcb7cd2d
14:51.3	Event button released			
14:51.4	Audio recording disabled due to video buffering default			
14:23.0	Audit log created	41	7 1.15.14	52.074
51:01.0	Volume up button pressed			
51:01.1	Volume up button released			
51:01.2	Volume changed to very high from high using button			
51:06.4	Volume up button pressed			
51:06.6	Volume up button released			
51:08.9	Volume down button pressed			
51:09.2	Volume down button released			
51:09.3	Volume changed to high from very high using button			
51:09.7	Volume down button pressed			
51:09.9	Volume down button released			
51:10.0	Volume changed to medium from high using button			
51:20.9	Camera connected to Axon Dock X62001W9H	37	7	52.099
51:20.9	Audit log rolled	37	7	52.073
51:20.9	Audit log created	37	7 1.15.14	52.075
51:21.0	Device connected to charger	37	7	52.075
51:36.5	Video upload started when camera was docked			6ea56aa097cc458f8417f15bf152933d
51:49.8	Audit log successfully uploaded			
51:50.0	Audit log successfully uploaded and deleted from device	37	7	52.099
51:53.0	Date/Time synced to 09/22/2021 11:51:53.01 PM from 09/22/2021 11:51:50.94 PM			
52:15.9	Audit log successfully uploaded			
52:16.1	Audit log successfully uploaded and deleted from device	37	7	52.099
52:24.2	Video successfully uploaded from device when docked			6ea56aa097cc458f8417f15bf152933d
52:24.5	Video deleted from device when docked	37	6	52.172 6ea56aa097cc458f8417f15bf152933d
52:24.5	Audit log rolled	37	6	52.173
52:24.5	Audit log created	37	6 1.15.14	52.173
52:24.8	Video upload started when camera was docked			c1ed479801b04d56a718b67beac4cf03
52:39.3	Audit log successfully uploaded			
52:39.5	Audit log successfully uploaded and deleted from device	37	6	52.173
52:58.6	Audit log successfully uploaded			
52:58.8	Audit log successfully uploaded and deleted from device	38	6	52.173
53:07.0	Audit log successfully uploaded			
53:07.2	Audit log successfully uploaded and deleted from device	38	6	52.173
53:34.4	Audit log successfully uploaded			
53:34.6	Audit log successfully uploaded and deleted from device	38	6	52.172
53:43.8	Audit log successfully uploaded			

53:44.0	Audit log successfully uploaded and deleted from device	38	6	52.172
53:49.1	Audit log successfully uploaded			
53:49.3	Audit log successfully uploaded and deleted from device	38	6	52.172
53:51.5	Audit log successfully uploaded			
53:51.7	Audit log successfully uploaded and deleted from device	38	6	52.172
54:12.8	Audit log successfully uploaded			
54:13.0	Audit log successfully uploaded and deleted from device	38	6	52.172
54:30.2	Audit log successfully uploaded			
54:30.3	Audit log successfully uploaded and deleted from device	38	6	52.172
54:41.6	Audit log successfully uploaded			
54:41.7	Audit log successfully uploaded and deleted from device	39	6	52.172
55:07.9	Audit log successfully uploaded			
55:08.1	Audit log successfully uploaded and deleted from device	39	6	52.172
55:21.2	Audit log successfully uploaded			
55:21.5	Audit log successfully uploaded and deleted from device	39	6	52.172
55:26.6	Audit log successfully uploaded			
55:26.8	Audit log successfully uploaded and deleted from device	39	6	52.172
55:34.0	Audit log successfully uploaded			
55:34.2	Audit log successfully uploaded and deleted from device	39	6	52.172
55:56.4	Audit log successfully uploaded			
55:56.5	Audit log successfully uploaded and deleted from device	39	6	52.172
56:11.7	Audit log successfully uploaded			
56:11.8	Audit log successfully uploaded and deleted from device	39	6	52.172
56:16.0	Audit log successfully uploaded			
56:16.2	Audit log successfully uploaded and deleted from device	39	6	52.172
56:20.2	Firmware version 1.18.19 detected		1.15.14	
56:30.4	Audit log successfully uploaded			
56:30.6	Audit log successfully uploaded and deleted from device	39	6	52.093
56:55.7	Audit log successfully uploaded			
56:55.9	Audit log successfully uploaded and deleted from device	39	6	51.899
57:13.1	Audit log successfully uploaded			
57:13.3	Audit log successfully uploaded and deleted from device	40	6	51.757
57:26.3	Firmware version 1.18.19 downloaded from Evidence.com	40	6 1.15.14	51.653
57:41.4	Audit log successfully uploaded			
57:41.6	Audit log successfully uploaded and deleted from device	40	6	51.135
57:45.8	Audit log successfully uploaded			
57:46.0	Audit log successfully uploaded and deleted from device	40	6	51.135
58:07.2	Audit log successfully uploaded			
58:07.4	Audit log successfully uploaded and deleted from device	40	6	51.653
58:30.5	Audit log successfully uploaded			
58:30.7	Audit log successfully uploaded and deleted from device	40	6	51.653
58:36.9	Audit log successfully uploaded			
58:37.1	Audit log successfully uploaded and deleted from device	40	6	51.653
59:05.3	Audit log successfully uploaded			
59:05.7	Audit log successfully uploaded and deleted from device	41	6	51.653
59:30.9	Audit log successfully uploaded			
59:31.0	Audit log successfully uploaded and deleted from device	41	6	51.653

59:54.2	Audit log successfully uploaded			
59:54.3	Audit log successfully uploaded and deleted from device	41	6	51.653
00:10.5	Audit log successfully uploaded			
00:10.6	Audit log successfully uploaded and deleted from device	41	6	51.653
00:17.8	Audit log successfully uploaded			
00:18.0	Audit log successfully uploaded and deleted from device	41	6	51.653
00:45.3	Audit log successfully uploaded			
00:45.5	Audit log successfully uploaded and deleted from device	41	6	51.134
00:59.9	Firmware update to version 1.18.19 started	41	6 1.15.14	51.653
01:00.0	Device restarting due to firmware update	41	6	51.653
03:05.2	Device restarted due to firmware update	42	6	52.302
03:05.3	Device connected to charger			
03:05.7	Firmware successfully updated to 1.18.19		1.18.19	
03:06.2	Camera connected to Axon Dock X62001W9H	42	6	52.302
03:07.1	Audit log created	42	1.18.19	52.302
03:07.1	Audit log rolled	42		52.302
03:24.7	Audit log successfully uploaded			
03:24.9	Audit log successfully uploaded and deleted from device	42	6	52.302
03:40.0	Date/Time synced to 09/23/2021 12:03:40.01 AM from 09/23/2021 12:03:37.78 AM			
03:59.1	Audit log successfully uploaded			
03:59.3	Audit log successfully uploaded and deleted from device	42	6	52.301
03:59.4	Audit log successfully uploaded			
03:59.6	Audit log successfully uploaded and deleted from device	42	6	52.301
04:07.8	Audit log successfully uploaded			
04:07.9	Audit log successfully uploaded and deleted from device	42	6	52.301
04:15.1	Audit log successfully uploaded			
04:15.2	Audit log successfully uploaded and deleted from device	42	6	52.3
04:37.3	Audit log successfully uploaded			
04:37.6	Audit log successfully uploaded and deleted from device	42	6	52.3
05:03.8	Audit log successfully uploaded			
05:03.9	Audit log successfully uploaded and deleted from device	42	6	52.3
05:20.1	Audit log successfully uploaded			
05:20.3	Audit log successfully uploaded and deleted from device	43	6	52.3
05:20.4	Audit log successfully uploaded			
05:20.6	Audit log successfully uploaded and deleted from device	43	6	52.3
05:22.8	Audit log successfully uploaded			
05:23.0	Audit log successfully uploaded and deleted from device	43	6	52.3
05:48.2	Audit log successfully uploaded			
05:48.3	Audit log successfully uploaded and deleted from device	43	6	52.3
06:01.9	Audit log successfully uploaded			
06:02.1	Audit log successfully uploaded and deleted from device	43	6	52.3
06:25.3	Audit log successfully uploaded			
06:25.5	Audit log successfully uploaded and deleted from device	43	6	52.3
06:42.6	Audit log successfully uploaded			
06:42.9	Audit log successfully uploaded and deleted from device	43	6	52.3
07:05.0	Audit log successfully uploaded			
07:05.2	Audit log successfully uploaded and deleted from device	44	6	52.299

07:07.5	Audit log successfully uploaded			
07:07.7	Audit log successfully uploaded and deleted from device	44	6	52.299
07:23.8	Video successfully uploaded from device when docked			c1ed479801b04d56a718b67beac4cf03
07:24.2	Video deleted from device when docked	44	5	53.748 c1ed479801b04d56a718b67beac4cf03
07:24.3	Audit log rolled	44	5	53.748
07:24.3	Audit log created	44	5 1.18.19	53.748
07:24.5	Video upload started when camera was docked			757a5144062f46318b1be1c5f41d6002
07:30.8	Audit log successfully uploaded			
07:31.0	Audit log successfully uploaded and deleted from device	44	5	53.748
07:44.2	Audit log successfully uploaded			
07:44.3	Audit log successfully uploaded and deleted from device	44	5	53.748
07:48.5	Video successfully uploaded from device when docked			757a5144062f46318b1be1c5f41d6002
07:48.8	Video deleted from device when docked	44	4	53.831 757a5144062f46318b1be1c5f41d6002
07:48.9	Audit log created	44	4 1.18.19	53.831
07:48.9	Audit log rolled	44	4	53.831
07:49.1	Video upload started when camera was docked			0183016bf02c4daba060101d8ed37cad
08:04.5	Audit log successfully uploaded			
08:04.6	Audit log successfully uploaded and deleted from device	44	4	53.831
08:05.8	Audit log successfully uploaded			
08:06.0	Audit log successfully uploaded and deleted from device	44	4	53.831
08:24.1	Audit log successfully uploaded			
08:24.3	Audit log successfully uploaded and deleted from device	44	4	53.831
08:41.4	Audit log successfully uploaded			
08:41.6	Audit log successfully uploaded and deleted from device	44	4	53.831
08:46.3	Video successfully uploaded from device when docked			0183016bf02c4daba060101d8ed37cad
08:46.5	Video deleted from device when docked	44	3	54.04 0183016bf02c4daba060101d8ed37cad
08:46.6	Audit log rolled	44	3	54.04
08:46.6	Audit log created	44	3 1.18.19	54.04
08:46.8	Video upload started when camera was docked			33326060be5345a590b12ece975db3c8
09:08.8	Audit log successfully uploaded			
09:09.0	Audit log successfully uploaded and deleted from device	44	3	54.04
09:32.1	Audit log successfully uploaded			
09:32.3	Audit log successfully uploaded and deleted from device	45	3	54.04
09:42.4	Audit log successfully uploaded			
09:42.6	Audit log successfully uploaded and deleted from device	45	3	54.04
10:04.8	Audit log successfully uploaded			
10:05.0	Audit log successfully uploaded and deleted from device	45	3	54.04
10:13.2	Audit log successfully uploaded			
10:13.4	Audit log successfully uploaded and deleted from device	45	3	54.04
10:16.6	Audit log successfully uploaded			
10:16.7	Audit log successfully uploaded and deleted from device	45	3	54.04
10:26.9	Audit log successfully uploaded			
10:27.1	Audit log successfully uploaded and deleted from device	45	3	54.04
10:47.2	Audit log successfully uploaded			
10:47.4	Audit log successfully uploaded and deleted from device	45	3	54.04
11:12.5	Audit log successfully uploaded			
11:12.8	Audit log successfully uploaded and deleted from device	46	3	54.04

11:24.9	Audit log successfully uploaded			
11:25.1	Audit log successfully uploaded and deleted from device	46	3	54.04
11:31.3	Audit log successfully uploaded			
11:31.5	Audit log successfully uploaded and deleted from device	46	3	54.04
11:36.7	Audit log successfully uploaded			
11:36.8	Audit log successfully uploaded and deleted from device	46	3	54.04
11:50.9	Audit log successfully uploaded			
11:51.2	Audit log successfully uploaded and deleted from device	46	3	54.04
12:07.9	Video successfully uploaded from device when dockec			33326060be5345a590b12ece975db3c8
12:08.3	Video deleted from device when docked	46	2	54.79 33326060be5345a590b12ece975db3c8
12:08.4	Audit log rolled	46	2	54.79
12:08.4	Audit log created	46	2 1.18.19	54.79
12:08.6	Video upload started when camera was docked			2e21562e1d7d42c68c428c00f1390f2c
12:14.3	Audit log successfully uploaded			
12:14.5	Audit log successfully uploaded and deleted from device	46	2	54.79
12:26.6	Audit log successfully uploaded			
12:26.8	Audit log successfully uploaded and deleted from device	46	2	54.79
12:53.0	Audit log successfully uploaded			
12:53.1	Audit log successfully uploaded and deleted from device	46	2	54.79
13:10.2	Video successfully uploaded from device when dockec			2e21562e1d7d42c68c428c00f1390f2c
13:10.5	Video deleted from device when docked	46	1	55.017 2e21562e1d7d42c68c428c00f1390f2c
13:10.6	Audit log created	46	1 1.18.19	55.026
13:10.6	Audit log rolled	46	1	55.026
13:10.8	Video upload started when camera was docked			f2c8c5b25d1a44cb92e572d9fcb7cd2d
13:11.2	Audit log successfully uploaded			
13:11.4	Audit log successfully uploaded and deleted from device	46	1	55.026
13:24.6	Audit log successfully uploaded			
13:24.8	Audit log successfully uploaded and deleted from device	46	1	55.026
13:25.9	Audit log successfully uploaded			
13:26.1	Audit log successfully uploaded and deleted from device	46	1	55.026
13:35.2	Audit log successfully uploaded			
13:35.4	Audit log successfully uploaded and deleted from device	47	1	55.026
14:03.6	Audit log successfully uploaded			
14:03.9	Audit log successfully uploaded and deleted from device	47	1	55.026
14:14.9	Video successfully uploaded from device when dockec			f2c8c5b25d1a44cb92e572d9fcb7cd2d
14:15.3	Video deleted from device when docked	47	0	55.258 f2c8c5b25d1a44cb92e572d9fcb7cd2d
14:15.3	Audit log rolled	47	0	55.265
14:15.3	Audit log created	47	0 1.18.19	55.265
14:15.3	Audit log created	47	0 1.18.19	55.265
14:15.3	Audit log rolled	47	0	55.265
14:24.1	Audit log successfully uploaded			
14:24.3	Audit log successfully uploaded and deleted from device	47	0	55.265
14:43.5	Audit log successfully uploaded			
14:43.7	Audit log successfully uploaded and deleted from device	47	0	55.265
14:54.9	Audit log successfully uploaded			
14:55.1	Audit log successfully uploaded and deleted from device	47	0	55.265
15:13.2	Audit log successfully uploaded			

15:13.5 Audit log successfully uploaded and deleted from device	47	0	55.265
15:39.7 Audit log successfully uploaded			
15:39.9 Audit log successfully uploaded and deleted from device	47	0	55.265
15:56.1 Audit log successfully uploaded			
15:56.4 Audit log successfully uploaded and deleted from device	47	0	55.265
16:15.6 Audit log successfully uploaded			
16:15.8 Audit log successfully uploaded and deleted from device	48	0	55.265
16:24.0 Audit log successfully uploaded			
16:24.2 Audit log successfully uploaded and deleted from device	48	0	55.265
16:48.4 Audit log successfully uploaded			
16:48.6 Audit log successfully uploaded and deleted from device	48	0	55.265
16:48.7 Audit log successfully uploaded			
16:48.9 Audit log successfully uploaded and deleted from device	48	0	55.265
17:12.0 Audit log successfully uploaded			
17:12.2 Audit log successfully uploaded and deleted from device	48	0	55.265
17:13.5 Audit log successfully uploaded			
17:13.7 Audit log successfully uploaded and deleted from device	48	0	55.265
17:13.8 Audit log successfully uploaded			
17:14.0 Audit log successfully uploaded and deleted from device	48	0	55.265
17:15.2 Audit log successfully uploaded			
17:15.5 Audit log successfully uploaded and deleted from device	48	0	55.265
17:18.6 Audit log successfully uploaded			
17:18.8 Audit log successfully uploaded and deleted from device	48	0	55.265
17:25.9 Audit log successfully uploaded			
17:26.1 Audit log successfully uploaded and deleted from device	48	0	55.265
17:46.3 Audit log successfully uploaded			
17:46.5 Audit log successfully uploaded and deleted from device	48	0	55.265
17:47.6 Audit log successfully uploaded			
17:47.9 Audit log successfully uploaded and deleted from device	49	0	55.265
17:48.1 Audit log successfully uploaded			
17:48.3 Audit log successfully uploaded and deleted from device	49	0	55.265
18:15.5 Audit log successfully uploaded			
18:15.7 Audit log successfully uploaded and deleted from device	49	0	55.265
18:17.9 Audit log successfully uploaded			
18:18.1 Audit log successfully uploaded and deleted from device	49	0	55.265
18:21.2 Audit log successfully uploaded			
18:21.4 Audit log successfully uploaded and deleted from device	49	0	55.265
18:21.5 Audit log successfully uploaded			
18:21.7 Audit log successfully uploaded and deleted from device	49	0	55.265
18:37.9 Audit log successfully uploaded			
18:38.1 Audit log successfully uploaded and deleted from device	49	0	55.265
18:38.3 Audit log successfully uploaded			
18:38.5 Audit log successfully uploaded and deleted from device	49	0	55.265
18:53.7 Audit log successfully uploaded			
18:53.8 Audit log successfully uploaded and deleted from device	49	0	55.265
19:04.0 Audit log successfully uploaded			
19:04.2 Audit log successfully uploaded and deleted from device	49	0	55.265

19:12.3	Audit log successfully uploaded			
19:12.5	Audit log successfully uploaded and deleted from device	49	0	55.265
19:27.8	Audit log successfully uploaded			
19:28.0	Audit log successfully uploaded and deleted from device	49	0	55.265
19:30.2	Audit log successfully uploaded			
19:30.4	Audit log successfully uploaded and deleted from device	49	0	55.265
19:47.6	Audit log successfully uploaded			
19:47.8	Audit log successfully uploaded and deleted from device	49	0	55.265
19:49.9	Audit log successfully uploaded			
19:50.2	Audit log successfully uploaded and deleted from device	49	0	55.265
26:19.2	Camera disconnected from Axon Dock X62001W9H	53	0	55.266
26:19.2	Device disconnected from charger	53	0	55.266
26:19.3	Audio recording disabled due to video buffering default			
14:15.0	Audit log created	48	0 1.18.19	55.268
27:50.4	Event button pressed			
27:50.5	Event button released			
27:50.6	Event button pressed			
27:50.6	Audio recording enabled due to video recording default			
27:50.6	Event button released			
27:50.8	Recording started due to button press	46	1	55.268 efc48b46f76d40fab2753adf1bf4aeb0
37:56.8	Event button pressed			
37:59.8	Recording stopped due to button press	44	1	54.887 efc48b46f76d40fab2753adf1bf4aeb0
38:00.3	Event button released			
38:00.7	Audio recording disabled due to video buffering default			
46:59.6	Event button pressed			
46:59.8	Event button released			
46:59.8	Event button pressed			
46:59.8	Audio recording enabled due to video recording default			
47:00.0	Event button released			
47:00.0	Recording started due to button press	44	2	54.885 5dab27e758204af080db3a595cea5eda
53:14.8	Event button pressed			
53:17.8	Recording stopped due to button press	42	2	54.627 5dab27e758204af080db3a595cea5eda
53:18.2	Event button released			
53:18.8	Audio recording disabled due to video buffering default			
54:20.7	Event button pressed			
54:20.9	Event button released			
54:20.9	Event button pressed			
54:20.9	Audio recording enabled due to video recording default			
54:21.1	Event button released			
54:21.1	Recording started due to button press	42	3	54.625 19ace1ba08814306b6618f9b755092bc
04:58.9	Event button pressed			
05:01.9	Recording stopped due to button press	40	3	54.257 19ace1ba08814306b6618f9b755092bc
05:02.5	Event button released			
05:02.9	Audio recording disabled due to video buffering default			
06:58.1	Axon application connected to device			
08:05.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-23 0146 X6033271L' to 'Signal 47' using Axon application by MORAES, NILSO			5dab27e758204af080db3a595cea5eda
08:05.5	Categories 'Ambulance Call' added to video metadata using Axon application by MORAES, NILSON (M1225)			5dab27e758204af080db3a595cea5eda

08:27.4 Title changed in video metadata from 'Axon Body 3 Video 2021-09-23 0127 X6033271L' to 'Signal 47' using Axon application by MORAES, NILSO			efc48b46f76d40fab2753adf1bf4aeb0
08:27.4 Categories 'Ambulance Call' added to video metadata using Axon application by MORAES, NILSON (M1225)			efc48b46f76d40fab2753adf1bf4aeb0
08:45.0 Title changed in video metadata from 'Axon Body 3 Video 2021-09-23 0154 X6033271L' to 'Signal 47' using Axon application by MORAES, NILSO			19ace1ba08814306b6618f9b755092bc
08:45.0 Categories 'Ambulance Call' added to video metadata using Axon application by MORAES, NILSON (M1225)			19ace1ba08814306b6618f9b755092bc
08:58.7 Axon application disconnected from device			
14:15.0 Audit log created	39	3 1.18.19	54.255
44:42.0 Volume up button pressed			
44:42.1 Volume up button released			
44:42.3 Volume changed to high from medium using button			
44:46.3 Volume down button pressed			
44:46.5 Volume down button released			
44:46.7 Volume changed to medium from high using button			
44:49.7 Camera connected to Axon Dock X630020W7	37	3	54.258
44:49.7 Audit log rolled	36	3	54.258
44:49.7 Audit log created	36	3 1.18.19	54.258
44:51.2 Device connected to charger	36	3	54.258
44:49.0 Audit log created	64	3 1.18.19	54.257
44:49.0 Audit log created	90	3 1.18.19	54.256
44:49.0 Audit log created	100	3 1.18.19	54.256
44:49.0 Audit log created	100	3 1.18.19	54.256
44:49.0 Audit log created	100	3 1.18.19	54.255
44:49.0 Audit log created	100	3 1.18.19	54.255
44:49.0 Audit log created	100	3 1.18.19	54.254
44:49.0 Audit log created	100	3 1.18.19	54.254
44:49.0 Audit log created	100	3 1.18.19	54.253
44:49.0 Audit log created	100	3 1.18.19	54.257
44:49.1 Audit log created	100	3 1.18.19	54.257
33:53.2 Device disconnected from charger	100	3	54.257
33:53.2 Camera disconnected from Axon Dock X630020W7	100	3	54.257
44:49.1 Audit log created	98	3 1.18.19	54.258
44:49.1 Audit log created	91	3 1.18.19	54.257
44:49.1 Audit log created	86	3 1.18.19	54.255
44:49.1 Audit log created	81	3 1.18.19	54.254
44:49.1 Audit log created	75	3 1.18.19	54.252
44:49.1 Audit log created	70	3 1.18.19	54.251
44:49.2 Audit log created	64	3 1.18.19	54.25
44:49.2 Audit log created	58	3 1.18.19	54.248
19:54.1 Camera connected to Axon Dock X62001W9H	54	3	54.258
19:54.1 Audit log created	54	3 1.18.19	54.248
19:54.2 Audit log rolled	54	3	54.248
19:55.2 Device connected to charger	54	3	54.248
20:10.0 Video upload started when camera was docked			efc48b46f76d40fab2753adf1bf4aeb0
20:11.1 Audit log successfully uploaded			
20:11.3 Audit log successfully uploaded and deleted from device	54	3	54.258
20:25.0 Date/Time synced to 09/23/2021 11:20:25.01 PM from 09/23/2021 11:20:24.18 PM			
20:58.5 Audit log successfully uploaded			

20:58.6	Audit log successfully uploaded and deleted from device	54	3	54.258
20:59.7	Audit log successfully uploaded			
20:59.9	Audit log successfully uploaded and deleted from device	54	3	54.258
21:27.0	Audit log successfully uploaded			
21:27.2	Audit log successfully uploaded and deleted from device	54	3	54.258
21:54.4	Audit log successfully uploaded			
21:54.6	Audit log successfully uploaded and deleted from device	55	3	54.258
21:56.1	Video successfully uploaded from device when docked			efc48b46f76d40fab2753adf1bf4aeb0
21:56.4	Video deleted from device when docked	55	2	54.638 efc48b46f76d40fab2753adf1bf4aeb0
21:56.4	Audit log created	55	2 1.18.19	54.638
21:56.4	Audit log rolled	55	2	54.638
21:56.8	Video upload started when camera was docked			5dab27e758204af080db3a595cea5eda
22:09.7	Audit log successfully uploaded			
22:09.9	Audit log successfully uploaded and deleted from device	55	2	54.638
22:38.1	Audit log successfully uploaded			
22:38.2	Audit log successfully uploaded and deleted from device	55	2	54.638
22:46.4	Audit log successfully uploaded			
22:46.6	Audit log successfully uploaded and deleted from device	55	2	54.638
22:54.7	Audit log successfully uploaded			
22:54.9	Audit log successfully uploaded and deleted from device	55	2	54.638
23:06.8	Video successfully uploaded from device when docked			5dab27e758204af080db3a595cea5eda
23:07.2	Video deleted from device when docked	55	1	54.896 5dab27e758204af080db3a595cea5eda
23:07.2	Audit log created	55	1 1.18.19	54.897
23:07.2	Audit log rolled	55	1	54.897
23:07.4	Video upload started when camera was docked			19ace1ba08814306b6618f9b755092bc
23:14.0	Audit log successfully uploaded			
23:14.2	Audit log successfully uploaded and deleted from device	55	1	54.897
23:17.3	Audit log successfully uploaded			
23:17.5	Audit log successfully uploaded and deleted from device	55	1	54.897
23:38.7	Audit log successfully uploaded			
23:38.9	Audit log successfully uploaded and deleted from device	56	1	54.897
23:46.0	Audit log successfully uploaded			
23:46.2	Audit log successfully uploaded and deleted from device	56	1	54.896
24:03.6	Audit log successfully uploaded			
24:03.8	Audit log successfully uploaded and deleted from device	56	1	54.896
24:16.9	Audit log successfully uploaded			
24:17.1	Audit log successfully uploaded and deleted from device	56	1	54.896
24:22.2	Audit log successfully uploaded			
24:22.3	Audit log successfully uploaded and deleted from device	56	1	54.896
24:25.5	Audit log successfully uploaded			
24:25.6	Audit log successfully uploaded and deleted from device	56	1	54.896
24:25.7	Audit log successfully uploaded			
24:25.9	Audit log successfully uploaded and deleted from device	56	1	54.896
24:45.4	Video successfully uploaded from device when docked			19ace1ba08814306b6618f9b755092bc
24:45.8	Video deleted from device when docked	56	0	55.264 19ace1ba08814306b6618f9b755092bc
24:45.8	Audit log rolled	56	0	55.265
24:45.8	Audit log created	56	0 1.18.19	55.265

24:45.9	Audit log rolled	56	0	55.265
24:45.9	Audit log created	56	0 1.18.19	55.265
24:53.0	Audit log successfully uploaded			
24:53.2	Audit log successfully uploaded and deleted from device	56	0	55.265
24:59.4	Audit log successfully uploaded			
24:59.6	Audit log successfully uploaded and deleted from device	56	0	55.265
25:19.9	Device disconnected from charger	56	0	55.265
25:19.9	Camera disconnected from Axon Dock X62001W9H	56	0	55.269
25:23.1	Programmable button pressed			
25:23.2	Programmable button released			
38:51.7	Power button pressed			
38:54.9	Device powered off using button	55	0	55.269
38:55.2	Power button released			
25:04.1	Audit log created		1.18.19	
25:04.2	Device powered on using button	55	0	55.269
25:06.3	Audio recording disabled due to video buffering default			
00:13.3	Volume up button pressed			
00:13.5	Volume up button released			
00:13.6	Volume changed to high from medium using button			
00:15.9	Volume down button pressed			
00:16.1	Volume down button released			
00:16.2	Volume changed to medium from high using button			
00:18.8	Camera connected to Axon Dock X630020W7	51	0	55.268
00:18.8	Audit log created	51	0 1.18.19	55.268
00:18.8	Audit log rolled	51	0	55.268
00:20.2	Device connected to charger	51	0	55.268
00:18.0	Audit log created	80	0 1.18.19	55.267
00:18.0	Audit log created	99	0 1.18.19	55.266
00:18.0	Audit log created	100	0 1.18.19	55.266
00:18.0	Audit log created	100	0 1.18.19	55.266
00:18.0	Audit log created	100	0 1.18.19	55.267
00:18.0	Audit log created	100	0 1.18.19	55.268
00:18.0	Audit log created	100	0 1.18.19	55.268
00:18.0	Audit log created	100	0 1.18.19	55.267
00:18.0	Audit log created	100	0 1.18.19	55.267
00:18.0	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.267
00:18.1	Audit log created	100	0 1.18.19	55.266
00:18.1	Audit log created	100	0 1.18.19	55.266
00:18.1	Audit log created	100	0 1.18.19	55.266
00:18.1	Audit log created	100	0 1.18.19	55.265
00:18.1	Audit log created	100	0 1.18.19	55.265
00:18.1	Audit log created	100	0 1.18.19	55.265

00:18.1 Audit log created	100	0 1.18.19	55.264
00:18.1 Audit log created	100	0 1.18.19	55.264
00:18.1 Audit log created	100	0 1.18.19	55.264
00:18.1 Audit log created	100	0 1.18.19	55.264
00:18.1 Audit log created	100	0 1.18.19	55.263
00:18.2 Audit log created	100	0 1.18.19	55.263
00:18.2 Audit log created	100	0 1.18.19	55.263
00:18.2 Audit log created	100	0 1.18.19	55.263
00:18.2 Audit log created	100	0 1.18.19	55.262
00:18.2 Audit log created	100	0 1.18.19	55.262
00:18.2 Audit log created	100	0 1.18.19	55.262
00:18.2 Audit log created	100	0 1.18.19	55.262
00:18.2 Audit log created	100	0 1.18.19	55.261
00:18.2 Audit log created	100	0 1.18.19	55.261
00:18.2 Audit log created	100	0 1.18.19	55.261
00:18.2 Audit log created	100	0 1.18.19	55.261
00:18.2 Audit log created	100	0 1.18.19	55.26
00:18.2 Audit log created	100	0 1.18.19	55.26
00:18.2 Audit log created	100	0 1.18.19	55.26
00:18.2 Audit log created	100	0 1.18.19	55.26
00:18.3 Audit log created	100	0 1.18.19	55.26
27:53.2 Camera disconnected from Axon Dock X630020W7	100	0	55.26
27:53.2 Device disconnected from charger	100	0	55.26
00:18.3 Audit log created	96	0 1.18.19	55.259
00:18.3 Audit log created	90	0 1.18.19	55.258
00:18.3 Audit log created	85	0 1.18.19	55.256
00:18.3 Audit log created	79	0 1.18.19	55.255
00:18.3 Audit log created	74	0 1.18.19	55.254
00:18.3 Audit log created	67	0 1.18.19	55.252
59:26.1 Event button pressed			
59:26.2 Event button released			
59:26.3 Event button pressed			
59:26.3 Audio recording enabled due to video recording default			
59:26.4 Event button released			
59:26.5 Recording started due to button press	62	1	55.251 18fa89baa7144e5896ef3f5dcd621d6e
00:18.3 Audit log created	62	1 1.18.19	55.163
01:30.5 Event button pressed			
01:33.4 Event button released			
01:36.9 Event button pressed			
01:39.9 Recording stopped due to button press	61	1	55.12 18fa89baa7144e5896ef3f5dcd621d6e
01:40.5 Event button released			
01:40.9 Audio recording disabled due to video buffering default			
07:09.1 Event button pressed			
07:09.3 Event button released			
07:09.4 Event button pressed			
07:09.4 Audio recording enabled due to video recording default			
07:09.5 Event button released			
07:09.5 Recording started due to button press	61	2	55.119 5e03a299891d4de1bdd9176d0dcb3385

08:30.0	Event button pressed			
08:33.0	Recording stopped due to button press	61	2	55.016 5e03a299891d4de1bdd9176d0dcb3385
08:33.4	Event button released			
08:33.9	Audio recording disabled due to video buffering default			
10:01.7	Event button pressed			
10:01.8	Event button released			
10:01.9	Event button pressed			
10:01.9	Event button released			
10:01.9	Audio recording enabled due to video recording default			
10:02.1	Recording started due to button press	61	3	55.015 9a067f66ba3e429797f112a85c220c57
35:12.0	Event button pressed			
35:15.0	Recording stopped due to button press	56	3	54.177 9a067f66ba3e429797f112a85c220c57
35:15.6	Event button released			
35:15.9	Audio recording disabled due to video buffering default			
00:18.4	Audit log created	53	3 1.18.19	54.173
47:55.4	Axon application connected to device			
48:31.1	Title changed in video metadata from 'Axon Body 3 Video 2021-09-26 0159 X6033271L' to 'Signal 70' using Axon application by MORAES, NILSO			18fa89baa7144e5896ef3f5dcd621d6e
48:31.1	Categories 'Loitering' added to video metadata using Axon application by MORAES, NILSON (M1225)			18fa89baa7144e5896ef3f5dcd621d6e
48:53.4	Title changed in video metadata from 'Axon Body 3 Video 2021-09-26 0207 X6033271L' to 'Signal 70' using Axon application by MORAES, NILSO			5e03a299891d4de1bdd9176d0dcb3385
48:53.5	Categories 'Loitering' added to video metadata using Axon application by MORAES, NILSON (M1225)			5e03a299891d4de1bdd9176d0dcb3385
49:25.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-26 0210 X6033271L' to 'Signal 70/31' using Axon application by MORAES, NII			9a067f66ba3e429797f112a85c220c57
49:25.3	Categories 'Sleeper', 'Loitering' added to video metadata using Axon application by MORAES, NILSON (M1225)			9a067f66ba3e429797f112a85c220c57
49:38.7	Axon application disconnected from device			
49:53.9	Camera connected to Axon Dock X62001V12	47	3	54.188
49:54.0	Audit log created	47	3 1.18.19	54.171
49:54.0	Audit log rolled	47	3	54.172
49:54.2	Device connected to charger	47	3	54.172
50:19.8	Video upload started when camera was docked			18fa89baa7144e5896ef3f5dcd621d6e
50:25.0	Date/Time synced to 09/26/2021 03:50:25.04 AM from 09/26/2021 03:50:24.06 AM			
50:43.3	Audit log successfully uploaded			
50:43.4	Audit log successfully uploaded and deleted from device	47	3	54.188
50:52.7	Audit log successfully uploaded			
50:52.8	Audit log successfully uploaded and deleted from device	47	3	54.187
50:56.2	Video successfully uploaded from device when dockec			18fa89baa7144e5896ef3f5dcd621d6e
50:56.5	Video deleted from device when docked	48	2	54.318 18fa89baa7144e5896ef3f5dcd621d6e
50:56.6	Audit log created	48	2 1.18.19	54.318
50:56.6	Audit log rolled	48	2	54.318
50:56.8	Video upload started when camera was docked			5e03a299891d4de1bdd9176d0dcb3385
51:21.9	Audit log successfully uploaded			
51:22.1	Audit log successfully uploaded and deleted from device	48	2	54.318
51:25.2	Audit log successfully uploaded			
51:25.4	Audit log successfully uploaded and deleted from device	48	2	54.318
51:29.5	Video successfully uploaded from device when dockec			5e03a299891d4de1bdd9176d0dcb3385
51:29.8	Video deleted from device when docked	48	1	54.422 5e03a299891d4de1bdd9176d0dcb3385
51:29.9	Audit log rolled	48	1	54.423
51:29.9	Audit log created	48	1 1.18.19	54.423
51:30.1	Video upload started when camera was docked			9a067f66ba3e429797f112a85c220c57

51:30.5	Audit log successfully uploaded			
51:30.7	Audit log successfully uploaded and deleted from device	48	1	54.423
51:33.9	Audit log successfully uploaded			
51:34.1	Audit log successfully uploaded and deleted from device	48	1	54.423
51:58.2	Audit log successfully uploaded			
51:58.4	Audit log successfully uploaded and deleted from device	48	1	54.423
52:00.5	Audit log successfully uploaded			
52:00.7	Audit log successfully uploaded and deleted from device	48	1	54.423
52:21.8	Audit log successfully uploaded			
52:22.0	Audit log successfully uploaded and deleted from device	48	1	54.423
52:50.1	Audit log successfully uploaded			
52:50.3	Audit log successfully uploaded and deleted from device	48	1	54.423
52:51.4	Audit log successfully uploaded			
52:51.6	Audit log successfully uploaded and deleted from device	48	1	54.423
53:07.9	Audit log successfully uploaded			
53:08.1	Audit log successfully uploaded and deleted from device	49	1	54.422
53:16.2	Audit log successfully uploaded			
53:16.5	Audit log successfully uploaded and deleted from device	49	1	54.422
53:41.6	Audit log successfully uploaded			
53:41.8	Audit log successfully uploaded and deleted from device	49	1	54.422
53:59.0	Audit log successfully uploaded			
53:59.2	Audit log successfully uploaded and deleted from device	49	1	54.422
54:19.3	Audit log successfully uploaded			
54:19.5	Audit log successfully uploaded and deleted from device	49	1	54.422
54:46.6	Audit log successfully uploaded			
54:46.8	Audit log successfully uploaded and deleted from device	49	1	54.422
55:12.1	Video successfully uploaded from device when docked			9a067f66ba3e429797f112a85c220c57
55:12.6	Video deleted from device when docked	49	0	55.261 9a067f66ba3e429797f112a85c220c57
55:12.6	Audit log rolled	49	0	55.261
55:12.6	Audit log created	49	0 1.18.19	55.261
55:12.7	Audit log rolled	49	0	55.261
55:12.7	Audit log created	49	0 1.18.19	55.261
55:16.0	Audit log successfully uploaded			
55:16.2	Audit log successfully uploaded and deleted from device	49	0	55.261
55:23.4	Audit log successfully uploaded			
55:23.6	Audit log successfully uploaded and deleted from device	49	0	55.261
55:28.8	Audit log successfully uploaded			
55:29.1	Audit log successfully uploaded and deleted from device	49	0	55.261
55:30.2	Audit log successfully uploaded			
55:30.4	Audit log successfully uploaded and deleted from device	49	0	55.261
55:55.6	Audit log successfully uploaded			
55:55.8	Audit log successfully uploaded and deleted from device	50	0	55.261
56:04.2	Audit log successfully uploaded			
56:04.5	Audit log successfully uploaded and deleted from device	50	0	55.261
56:33.6	Audit log successfully uploaded			
56:33.9	Audit log successfully uploaded and deleted from device	50	0	55.261
56:38.0	Audit log successfully uploaded			

56:38.3 Audit log successfully uploaded and deleted from device	50	0	55.261
56:55.5 Audit log successfully uploaded			
56:55.7 Audit log successfully uploaded and deleted from device	50	0	55.261
57:05.9 Audit log successfully uploaded			
57:06.1 Audit log successfully uploaded and deleted from device	50	0	55.261
57:26.2 Audit log successfully uploaded			
57:26.5 Audit log successfully uploaded and deleted from device	50	0	55.261
57:50.6 Audit log successfully uploaded			
57:50.8 Audit log successfully uploaded and deleted from device	51	0	55.261
57:55.9 Audit log successfully uploaded			
57:56.1 Audit log successfully uploaded and deleted from device	51	0	55.261
57:59.2 Audit log successfully uploaded			
57:59.5 Audit log successfully uploaded and deleted from device	51	0	55.261
57:59.6 Audit log successfully uploaded			
57:59.9 Audit log successfully uploaded and deleted from device	51	0	55.261
58:14.0 Audit log successfully uploaded			
58:14.2 Audit log successfully uploaded and deleted from device	51	0	55.261
58:15.7 Device disconnected from charger	51	0	55.261
58:15.8 Camera disconnected from Axon Dock X62001V12	51	0	55.261
58:17.3 Programmable button pressed			
58:17.3 Programmable button released			
58:17.6 Programmable button pressed			
58:17.7 Programmable button released			
50:49.2 Event button pressed			
50:49.3 Event button released			
50:49.4 Event button pressed			
50:49.4 Audio recording enabled due to video recording default			
50:49.5 Event button released			
50:49.7 Recording started due to button press	46	1	55.265 61f4b434325c45c2b614ba297fc531e4
55:12.0 Audit log created	45	1 1.18.19	55.067
02:44.7 Event button pressed			
02:47.7 Recording stopped due to button press	44	1	54.827 61f4b434325c45c2b614ba297fc531e4
02:48.3 Event button released			
02:48.5 Audio recording disabled due to video buffering default			
03:39.4 Event button pressed			
03:39.6 Event button released			
03:39.7 Event button pressed			
03:39.7 Audio recording enabled due to video recording default			
03:39.8 Event button released			
03:39.8 Recording started due to button press	44	2	54.825 40b066c57c8849b399513b596660b5a7
09:30.2 Event button pressed			
09:33.2 Recording stopped due to button press	42	2	54.614 40b066c57c8849b399513b596660b5a7
09:34.0 Event button released			
09:34.1 Audio recording disabled due to video buffering default			
10:32.3 Axon application connected to device			
11:57.8 Title changed in video metadata from 'Axon Body 3 Video 2021-09-26 0450 X6033271L' to 'Signal 70/32' using Axon application by MORAES, NII 61f4b434325c45c2b614ba297fc531e4			
11:57.8 Categories 'Sleeper', 'Loitering' added to video metadata using Axon application by MORAES, NILSON (M1225			61f4b434325c45c2b614ba297fc531e4

12:40.9	Title changed in video metadata from 'Axon Body 3 Video 2021-09-26 0503 X6033271L' to 'Signal 70/31' using Axon application by MORAES, NII 40b066c57c8849b399513b596660b5a7			
12:40.9	Categories 'Sleeper', 'Loitering' added to video metadata using Axon application by MORAES, NILSON (M1225			40b066c57c8849b399513b596660b5a7
12:53.9	Axon application disconnected from device			
55:12.0	Audit log created	38	2 1.18.19	54.611
55:12.1	Audit log created	33	2 1.18.19	54.61
55:12.1	Audit log created	27	2 1.18.19	54.609
20:10.9	Camera connected to Axon Dock X630020W7	25	2	54.608
20:11.0	Audit log rolled	25	2	54.608
20:11.0	Audit log created	25	2 1.18.19	54.608
20:11.7	Device connected to charger	25	2	54.608
20:11.0	Audit log created	52	2 1.18.19	54.607
20:11.0	Audit log created	78	2 1.18.19	54.607
20:11.0	Audit log created	99	2 1.18.19	54.606
20:11.1	Audit log created	100	2 1.18.19	54.606
20:11.1	Audit log created	100	2 1.18.19	54.605
20:11.1	Audit log created	100	2 1.18.19	54.609
20:11.1	Audit log created	100	2 1.18.19	54.609
20:11.1	Audit log created	100	2 1.18.19	54.608
20:11.1	Audit log created	100	2 1.18.19	54.608
20:11.1	Audit log created	100	2 1.18.19	54.611
20:11.1	Audit log created	100	2 1.18.19	54.611
35:25.5	Volume up button pressed			
35:25.7	Device disconnected from charger	100	2	54.611
35:25.9	Volume up button released			
35:26.0	Camera disconnected from Axon Dock X630020W7	100	2	54.611
20:11.1	Audit log created	94	2 1.18.19	54.613
02:03.9	Power button pressed			
02:07.2	Device powered off using button	90	2	54.612
02:07.6	Power button released			
21:04.1	Audit log created		1.18.19	
21:04.2	Device powered on using button	90	2	54.612
21:06.3	Audio recording disabled due to video buffering default			
45:01.3	Power button pressed			
45:04.3	Device powered off using button	88	2	54.611
45:04.8	Power button released			
05:27.3	Audit log created		1.18.19	
05:27.4	Device powered on using button	88	2	54.611
05:30.4	Audio recording disabled due to video buffering default			
05:27.3	Audit log created	82	2 1.18.19	54.609
05:27.3	Audit log created	77	2 1.18.19	54.608
05:27.4	Audit log created	72	2 1.18.19	54.606
21:38.6	Power button pressed			
21:41.7	Device powered off using button	70	2	54.606
21:42.1	Power button released			
38:30.3	Audit log created		1.18.19	
38:30.4	Device powered on using button	70	2	54.605
38:33.5	Audio recording disabled due to video buffering default			

39:25.1	Volume up button pressed			
39:25.2	Volume up button released			
39:25.3	Volume changed to high from medium using button			
39:30.6	Volume up button pressed			
39:31.0	Volume up button released			
39:31.1	Volume changed to very high from high using button			
39:31.6	Volume up button pressed			
39:31.8	Volume up button released			
39:34.5	Volume down button pressed			
39:34.7	Volume down button released			
39:34.8	Volume changed to high from very high using button			
39:34.8	Volume down button pressed			
39:34.9	Volume down button released			
39:35.2	Volume changed to medium from high using button			
39:35.2	Volume down button pressed			
39:35.4	Volume down button released			
39:35.6	Volume changed to low from medium using button			
39:40.1	Volume up button pressed			
39:40.3	Volume up button released			
39:40.4	Volume changed to medium from low using button			
39:45.8	Camera connected to Axon Dock X62001W9H	70	2	54.618
39:45.8	Audit log created	70	2 1.18.19	54.607
39:45.8	Audit log rolled	70	2	54.607
39:46.3	Device connected to charger	70	2	54.607
40:12.2	Video upload started when camera was docked			61f4b434325c45c2b614ba297fc531e4
40:16.0	Date/Time synced to 09/27/2021 05:40:16.01 AM from 09/27/2021 05:40:15.82 AM			
40:21.1	Audit log successfully uploaded			
40:21.3	Audit log successfully uploaded and deleted from device	70	2	54.618
40:25.5	Audit log successfully uploaded			
40:25.8	Audit log successfully uploaded and deleted from device	70	2	54.618
40:27.9	Audit log successfully uploaded			
40:28.1	Audit log successfully uploaded and deleted from device	70	2	54.618
41:02.2	Audit log successfully uploaded			
41:02.4	Audit log successfully uploaded and deleted from device	71	2	54.618
41:30.5	Audit log successfully uploaded			
41:30.7	Audit log successfully uploaded and deleted from device	71	2	54.618
41:59.8	Audit log successfully uploaded			
42:00.0	Audit log successfully uploaded and deleted from device	71	2	54.618
42:09.2	Video successfully uploaded from device when docked			61f4b434325c45c2b614ba297fc531e4
42:09.6	Video deleted from device when docked	71	1	55.055 61f4b434325c45c2b614ba297fc531e4
42:09.6	Audit log rolled	71	1	55.056
42:09.6	Audit log created	71	1 1.18.19	55.056
42:09.9	Video upload started when camera was docked			40b066c57c8849b399513b596660b5a7
42:16.1	Audit log successfully uploaded			
42:16.3	Audit log successfully uploaded and deleted from device	71	1	55.056
42:22.4	Audit log successfully uploaded			
42:22.6	Audit log successfully uploaded and deleted from device	71	1	55.056

42:31.8	Audit log successfully uploaded			
42:32.0	Audit log successfully uploaded and deleted from device	71	1	55.056
42:53.1	Audit log successfully uploaded			
42:53.3	Audit log successfully uploaded and deleted from device	72	1	55.056
43:00.4	Audit log successfully uploaded			
43:00.6	Audit log successfully uploaded and deleted from device	72	1	55.056
43:05.9	Audit log successfully uploaded			
43:06.1	Audit log successfully uploaded and deleted from device	72	1	55.056
43:07.2	Video successfully uploaded from device when dockec			40b066c57c8849b399513b596660b5a7
43:07.5	Video deleted from device when docked	72	0	55.267
43:07.6	Audit log created	72	0 1.18.19	55.267
43:07.6	Audit log rolled	72	0	55.267
43:07.6	Audit log created	72	0 1.18.19	55.267
43:07.6	Audit log rolled	72	0	55.267
43:11.3	Audit log successfully uploaded			
43:11.6	Audit log successfully uploaded and deleted from device	72	0	55.267
43:12.7	Volume down button pressed			
43:12.7	Volume down button released			
43:13.3	Device disconnected from charger	72	0	55.267
43:13.3	Camera disconnected from Axon Dock X62001W9H	72	0	55.267
25:31.6	Volume up button pressed			
25:31.7	Volume up button released			
25:31.8	Volume changed to high from medium using button			
25:34.8	Volume down button pressed			
25:35.1	Volume down button released			
25:35.2	Volume changed to medium from high using button			
25:37.4	Camera connected to Axon Dock X630020W7	67	0	55.266
25:37.5	Audit log created	67	0 1.18.19	55.266
25:37.5	Audit log rolled	67	0	55.266
25:39.3	Device connected to charger	67	0	55.266
25:37.0	Audit log created	95	0 1.18.19	55.265
25:37.0	Audit log created	100	0 1.18.19	55.265
25:37.0	Audit log created	100	0 1.18.19	55.265
25:37.1	Audit log created	100	0 1.18.19	55.264
25:37.1	Audit log created	100	0 1.18.19	55.264
25:37.1	Audit log created	100	0 1.18.19	55.264
25:37.1	Audit log created	100	0 1.18.19	55.267
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.1	Audit log created	100	0 1.18.19	55.266
25:37.2	Audit log created	100	0 1.18.19	55.265
35:51.9	Volume down button pressed			
35:52.2	Device disconnected from charger	98	0	55.265
35:52.3	Volume down button released			
35:53.0	Camera disconnected from Axon Dock X630020W7	98	0	55.266

35:56.8 Programmable button pressed			
35:56.9 Programmable button released			
25:37.2 Audit log created	94	0 1.18.19	55.265
25:37.2 Audit log created	89	0 1.18.19	55.263
25:37.2 Audit log created	84	0 1.18.19	55.262
25:37.3 Audit log created	78	0 1.18.19	55.26
03:00.7 Event button pressed			
03:00.9 Event button released			
03:00.9 Event button pressed			
03:01.0 Audio recording enabled due to video recording default			
03:01.0 Event button released			
03:01.2 Recording started due to button press	75	1	55.259 511ca5887b8545ae9dd9663604fd8fd6
09:43.4 Event button pressed			
09:46.4 Recording stopped due to button press	74	1	54.986 511ca5887b8545ae9dd9663604fd8fd6
09:46.9 Event button released			
09:47.3 Audio recording disabled due to video buffering default			
25:37.3 Audit log created	73	1 1.18.19	54.985
27:43.1 Event button pressed			
27:43.2 Event button released			
27:43.3 Event button pressed			
27:43.3 Audio recording enabled due to video recording default			
27:43.4 Event button released			
27:43.5 Recording started due to button press	72	1	54.984 2613868fbfaf4c1987b80730d2ba28f3
32:07.6 Event button pressed			
32:10.6 Recording stopped due to button press	71	2	54.784 2613868fbfaf4c1987b80730d2ba28f3
32:10.8 Event button released			
32:11.3 Audio recording disabled due to video buffering default			
33:17.2 Event button pressed			
33:17.3 Event button released			
33:17.4 Event button pressed			
33:17.5 Audio recording enabled due to video recording default			
33:17.5 Event button released			
33:17.6 Recording started due to button press	71	3	54.782 34245b346cb9471eaa5691a088668c98
33:25.9 Event button pressed			
33:28.9 Recording stopped due to button press	71	3	54.757 34245b346cb9471eaa5691a088668c98
33:29.5 Event button released			
33:29.7 Audio recording disabled due to video buffering default			
25:37.3 Audit log created	66	3 1.18.19	54.742
27:29.4 Event button pressed			
27:29.5 Event button released			
27:29.6 Event button pressed			
27:29.6 Audio recording enabled due to video recording default			
27:29.7 Event button released			
27:29.8 Recording started due to button press	66	4	54.741 82e2e45fba884734a2c5798ed3b20897
29:20.1 Event button pressed			
29:23.1 Recording stopped due to button press	65	4	54.622 82e2e45fba884734a2c5798ed3b20897
29:23.6 Event button released			

29:23.9	Audio recording disabled due to video buffering default			
51:04.9	Axon application connected to device			
52:20.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-28 0003 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO 511ca5887b8545ae9dd9663604fd8fd6			
52:20.7	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			511ca5887b8545ae9dd9663604fd8fd6
52:23.5	Event button pressed			
52:23.6	Event button released			
52:23.7	Event button pressed			
52:23.7	Audio recording enabled due to video recording default			
52:23.8	Event button released			
52:23.8	Recording started due to button press	63	5	54.62 e6bb07ebdd494b3dace3c4519e2777a5
56:39.6	Event button pressed			
56:42.6	Recording stopped due to button press	63	5	54.423 e6bb07ebdd494b3dace3c4519e2777a5
56:43.1	Event button released			
56:43.4	Audio recording disabled due to video buffering default			
15:15.3	Title changed in video metadata from 'Axon Body 3 Video 2021-09-28 0027 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO 2613868fbfaf4c1987b80730d2ba28f3			2613868fbfaf4c1987b80730d2ba28f3
15:15.3	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			2613868fbfaf4c1987b80730d2ba28f3
15:29.6	Title changed in video metadata from 'Axon Body 3 Video 2021-09-28 0033 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO 34245b346cb9471eaa5691a088668c98			34245b346cb9471eaa5691a088668c98
15:29.6	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			34245b346cb9471eaa5691a088668c98
15:49.7	Title changed in video metadata from 'Axon Body 3 Video 2021-09-28 0127 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO 82e2e45fba884734a2c5798ed3b20897			82e2e45fba884734a2c5798ed3b20897
15:49.7	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			82e2e45fba884734a2c5798ed3b20897
16:12.5	Title changed in video metadata from 'Axon Body 3 Video 2021-09-28 0152 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO e6bb07ebdd494b3dace3c4519e2777a5			e6bb07ebdd494b3dace3c4519e2777a5
16:12.5	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			e6bb07ebdd494b3dace3c4519e2777a5
16:46.7	Axon application disconnected from device			
25:37.3	Audit log created	60	5 1.18.19	54.421
25:37.4	Audit log created	53	5 1.18.19	54.419
24:45.1	Camera connected to Axon Dock X62001W9H	47	5	54.428
24:45.3	Audit log created	47	5 1.18.19	54.418
24:45.3	Audit log rolled	47	5	54.418
24:49.1	Device connected to charger	47	5	54.418
25:10.8	Video upload started when camera was docked			511ca5887b8545ae9dd9663604fd8fd6
25:15.1	Date/Time synced to 09/28/2021 04:25:15.06 AM from 09/28/2021 04:25:15.29 AM			
25:45.7	Audit log successfully uploaded			
25:45.9	Audit log successfully uploaded and deleted from device	47	5	54.428
25:56.0	Audit log successfully uploaded			
25:56.2	Audit log successfully uploaded and deleted from device	47	5	54.428
25:58.3	Audit log successfully uploaded			
25:58.5	Audit log successfully uploaded and deleted from device	47	5	54.428
26:23.6	Audit log successfully uploaded			
26:23.8	Audit log successfully uploaded and deleted from device	47	5	54.428
26:33.0	Audit log successfully uploaded			
26:33.2	Audit log successfully uploaded and deleted from device	48	5	54.428
26:34.4	Audit log successfully uploaded			
26:34.6	Audit log successfully uploaded and deleted from device	48	5	54.428
26:37.8	Audit log successfully uploaded			
26:38.1	Audit log successfully uploaded and deleted from device	48	5	54.428
26:38.2	Audit log successfully uploaded			
26:38.4	Audit log successfully uploaded and deleted from device	48	5	54.428

26:44.7 Video successfully uploaded from device when dockec			511ca5887b8545ae9dd9663604fd8fd6
26:45.1 Video deleted from device when docked	48	4	54.701 511ca5887b8545ae9dd9663604fd8fd6
26:45.1 Audit log rolled	48	4	54.701
26:45.1 Audit log created	48	4 1.18.19	54.701
26:45.3 Video upload started when camera was docked			2613868fbfaf4c1987b80730d2ba28f3
26:57.6 Audit log successfully uploaded			
26:57.7 Audit log successfully uploaded and deleted from device	48	4	54.701
27:18.9 Audit log successfully uploaded			
27:19.0 Audit log successfully uploaded and deleted from device	48	4	54.701
27:41.3 Video successfully uploaded from device when dockec			2613868fbfaf4c1987b80730d2ba28f3
27:41.5 Video deleted from device when docked	48	3	54.902 2613868fbfaf4c1987b80730d2ba28f3
27:41.6 Audit log rolled	48	3	54.902
27:41.6 Audit log created	48	3 1.18.19	54.902
27:41.8 Video upload started when camera was docked			34245b346cb9471eaa5691a088668c98
27:42.1 Audit log successfully uploaded			
27:42.3 Audit log successfully uploaded and deleted from device	48	3	54.902
27:52.5 Video successfully uploaded from device when dockec			34245b346cb9471eaa5691a088668c98
27:52.7 Video deleted from device when docked	48	2	54.941 34245b346cb9471eaa5691a088668c98
27:52.8 Audit log created	48	2 1.18.19	54.941
27:52.8 Audit log rolled	48	2	54.941
27:53.0 Video upload started when camera was docked			82e2e45fba884734a2c5798ed3b20897
27:56.4 Audit log successfully uploaded			
27:56.6 Audit log successfully uploaded and deleted from device	48	2	54.941
28:13.8 Audit log successfully uploaded			
28:13.9 Audit log successfully uploaded and deleted from device	48	2	54.941
28:23.8 Video successfully uploaded from device when dockec			82e2e45fba884734a2c5798ed3b20897
28:24.1 Video deleted from device when docked	49	1	55.061 82e2e45fba884734a2c5798ed3b20897
28:24.2 Audit log rolled	49	1	55.061
28:24.2 Audit log created	49	1 1.18.19	55.061
28:24.4 Video upload started when camera was docked			e6bb07ebdd494b3dace3c4519e2777a5
28:37.1 Audit log successfully uploaded			
28:37.3 Audit log successfully uploaded and deleted from device	49	1	55.061
28:59.5 Audit log successfully uploaded			
28:59.7 Audit log successfully uploaded and deleted from device	49	1	55.061
29:03.9 Audit log successfully uploaded			
29:04.1 Audit log successfully uploaded and deleted from device	49	1	55.061
29:11.2 Audit log successfully uploaded			
29:11.4 Audit log successfully uploaded and deleted from device	49	1	55.061
29:14.6 Audit log successfully uploaded			
29:14.8 Audit log successfully uploaded and deleted from device	49	1	55.061
29:16.4 Video successfully uploaded from device when dockec			e6bb07ebdd494b3dace3c4519e2777a5
29:16.6 Video deleted from device when docked	49	0	55.258 e6bb07ebdd494b3dace3c4519e2777a5
29:16.7 Audit log rolled	49	0	55.258
29:16.7 Audit log created	49	0 1.18.19	55.258
29:16.7 Audit log rolled	49	0	55.258
29:16.7 Audit log created	49	0 1.18.19	55.258
29:43.0 Audit log successfully uploaded			

29:43.2 Audit log successfully uploaded and deleted from device	49	0	55.258
29:49.4 Audit log successfully uploaded			
29:49.6 Audit log successfully uploaded and deleted from device	49	0	55.258
29:55.7 Audit log successfully uploaded			
29:56.0 Audit log successfully uploaded and deleted from device	49	0	55.258
30:24.1 Audit log successfully uploaded			
30:24.3 Audit log successfully uploaded and deleted from device	49	0	55.258
30:38.5 Audit log successfully uploaded			
30:38.7 Audit log successfully uploaded and deleted from device	49	0	55.258
30:48.9 Audit log successfully uploaded			
30:49.1 Audit log successfully uploaded and deleted from device	49	0	55.258
30:55.3 Audit log successfully uploaded			
30:55.5 Audit log successfully uploaded and deleted from device	49	0	55.258
31:16.7 Audit log successfully uploaded			
31:16.8 Audit log successfully uploaded and deleted from device	50	0	55.258
31:27.0 Audit log successfully uploaded			
31:27.3 Audit log successfully uploaded and deleted from device	50	0	55.258
31:37.5 Audit log successfully uploaded			
31:37.7 Audit log successfully uploaded and deleted from device	50	0	55.258
31:56.9 Audit log successfully uploaded			
31:57.1 Audit log successfully uploaded and deleted from device	50	0	55.258
32:01.4 Audit log successfully uploaded			
32:01.7 Audit log successfully uploaded and deleted from device	50	0	55.258
32:24.8 Audit log successfully uploaded			
32:25.4 Audit log successfully uploaded and deleted from device	50	0	55.258
32:43.5 Audit log successfully uploaded			
32:43.7 Audit log successfully uploaded and deleted from device	50	0	55.258
33:06.9 Audit log successfully uploaded			
33:07.0 Audit log successfully uploaded and deleted from device	51	0	55.258
33:20.1 Audit log successfully uploaded			
33:20.3 Audit log successfully uploaded and deleted from device	51	0	55.258
33:45.5 Audit log successfully uploaded			
33:45.7 Audit log successfully uploaded and deleted from device	51	0	55.258
33:45.9 Audit log successfully uploaded			
33:46.1 Audit log successfully uploaded and deleted from device	51	0	55.258
33:58.3 Audit log successfully uploaded			
33:58.5 Audit log successfully uploaded and deleted from device	51	0	55.258
34:12.7 Audit log successfully uploaded			
34:13.0 Audit log successfully uploaded and deleted from device	51	0	55.258
34:39.2 Audit log successfully uploaded			
34:39.4 Audit log successfully uploaded and deleted from device	51	0	55.258
34:51.6 Audit log successfully uploaded			
34:51.8 Audit log successfully uploaded and deleted from device	51	0	55.258
34:59.9 Audit log successfully uploaded			
35:00.0 Audit log successfully uploaded and deleted from device	51	0	55.258
35:12.2 Audit log successfully uploaded			
35:12.4 Audit log successfully uploaded and deleted from device	51	0	55.258

35:14.6	Audit log successfully uploaded			
35:14.8	Audit log successfully uploaded and deleted from device	51	0	55.258
35:27.0	Audit log successfully uploaded			
35:27.2	Audit log successfully uploaded and deleted from device	52	0	55.258
35:30.4	Audit log successfully uploaded			
35:30.6	Audit log successfully uploaded and deleted from device	52	0	55.257
35:49.8	Audit log successfully uploaded			
35:50.0	Audit log successfully uploaded and deleted from device	52	0	55.257
36:15.2	Audit log successfully uploaded			
36:15.5	Audit log successfully uploaded and deleted from device	52	0	55.257
36:36.6	Audit log successfully uploaded			
36:36.8	Audit log successfully uploaded and deleted from device	52	0	55.257
37:01.0	Audit log successfully uploaded			
37:01.2	Audit log successfully uploaded and deleted from device	52	0	55.257
37:19.4	Audit log successfully uploaded			
37:19.6	Audit log successfully uploaded and deleted from device	53	0	55.257
37:35.8	Audit log successfully uploaded			
37:36.0	Audit log successfully uploaded and deleted from device	53	0	55.257
37:43.1	Audit log successfully uploaded			
37:43.3	Audit log successfully uploaded and deleted from device	53	0	55.257
37:50.5	Audit log successfully uploaded			
37:50.7	Audit log successfully uploaded and deleted from device	53	0	55.257
38:05.9	Audit log successfully uploaded			
38:06.0	Audit log successfully uploaded and deleted from device	53	0	55.257
38:28.2	Audit log successfully uploaded			
38:28.4	Audit log successfully uploaded and deleted from device	53	0	55.257
38:31.5	Audit log successfully uploaded			
38:31.8	Audit log successfully uploaded and deleted from device	53	0	55.257
38:52.0	Audit log successfully uploaded			
38:52.2	Audit log successfully uploaded and deleted from device	53	0	55.257
39:18.3	Audit log successfully uploaded			
39:18.6	Audit log successfully uploaded and deleted from device	53	0	55.257
39:27.8	Camera disconnected from Axon Dock X62001W9H	53	0	55.257
39:28.8	Device disconnected from charger	53	0	55.264
29:16.0	Audit log created	49	0 1.18.19	55.263
21:13.2	Camera connected to Axon Dock X630020W7	44	0	55.262
21:13.2	Audit log created	44	0 1.18.19	55.262
21:13.3	Audit log rolled	44	0	55.262
21:13.8	Device connected to charger	44	0	55.262
21:13.0	Audit log created	71	0 1.18.19	55.261
21:13.0	Audit log created	97	0 1.18.19	55.261
21:13.0	Audit log created	100	0 1.18.19	55.265
21:13.1	Audit log created	100	0 1.18.19	55.265
21:13.1	Audit log created	100	0 1.18.19	55.265
21:13.1	Audit log created	100	0 1.18.19	55.264
21:13.1	Audit log created	100	0 1.18.19	55.264
21:13.1	Audit log created	100	0 1.18.19	55.263

21:13.9 Audit log created	100	0 1.18.19	55.252
21:13.9 Audit log created	100	0 1.18.19	55.251
21:14.0 Audit log created	100	0 1.18.19	55.251
21:14.0 Audit log created	100	0 1.18.19	55.251
21:14.0 Audit log created	100	0 1.18.19	55.251
21:14.0 Audit log created	100	0 1.18.19	55.251
21:14.0 Audit log created	100	0 1.18.19	55.25
21:14.0 Audit log created	100	0 1.18.19	55.25
21:14.1 Audit log created	100	0 1.18.19	55.25
21:14.1 Audit log created	100	0 1.18.19	55.25
21:14.1 Audit log created	100	0 1.18.19	55.25
21:14.1 Audit log created	100	0 1.18.19	55.249
21:14.1 Audit log created	100	0 1.18.19	55.249
21:14.1 Audit log created	100	0 1.18.19	55.249
21:14.1 Audit log created	100	0 1.18.19	55.249
21:14.1 Audit log created	100	0 1.18.19	55.249
21:14.2 Audit log created	100	0 1.18.19	55.248
21:14.2 Audit log created	100	0 1.18.19	55.248
21:14.2 Audit log created	100	0 1.18.19	55.248
21:14.2 Audit log created	100	0 1.18.19	55.247
21:14.3 Audit log created	100	0 1.18.19	55.247
21:14.3 Audit log created	100	0 1.18.19	55.247
21:14.3 Audit log created	100	0 1.18.19	55.246
21:14.3 Audit log created	100	0 1.18.19	55.246
21:14.4 Audit log created	100	0 1.18.19	55.246
21:14.4 Audit log created	100	0 1.18.19	55.246
21:14.4 Audit log created	100	0 1.18.19	55.245
21:14.4 Audit log created	100	0 1.18.19	55.245
21:14.4 Audit log created	100	0 1.18.19	55.245
21:14.5 Audit log created	100	0 1.18.19	55.245
21:14.5 Audit log created	100	0 1.18.19	55.244
21:14.5 Audit log created	100	0 1.18.19	55.244
08:56.9 Device disconnected from charger	98	0	55.244
08:56.9 Camera disconnected from Axon Dock X630020W7	100	0	55.244
21:14.5 Audit log created	98	0 1.18.19	55.245
05:36.5 Power button pressed			
05:39.7 Device powered off using button	93	0	55.244
05:40.0 Power button released			
25:45.0 Audit log created		1.18.19	
25:45.1 Device powered on using button	93	0	55.244
25:47.0 Audio recording disabled due to video buffering default			
27:40.3 Power button pressed			
27:42.5 Power button released			
27:44.7 Power button pressed			
27:47.7 Device powered off using button	93	0	55.244
27:48.1 Power button released			
18:14.0 Audit log created		1.18.19	
18:14.2 Device powered on using button	93	0	55.243
18:16.3 Audio recording disabled due to video buffering default			
18:14.1 Audit log created	87	0 1.18.19	55.241

18:14.1	Audit log created	82	0	1.18.19	55.24
18:14.1	Audit log created	77	0	1.18.19	55.238
36:36.3	Event button pressed				
36:36.4	Event button released				
36:36.5	Event button pressed				
36:36.5	Audio recording enabled due to video recording default				
36:36.6	Event button released				
36:36.7	Recording started due to button press	75	1		55.238 0252611ca8ae47aea2994f5428900c60
48:08.7	Power button pressed				
48:11.1	Power button released				
48:11.5	Event button pressed				
48:14.5	Recording stopped due to button press	73	1		54.811 0252611ca8ae47aea2994f5428900c60
48:15.0	Event button released				
48:15.3	Audio recording disabled due to video buffering default				
54:48.4	Event button pressed				
54:48.5	Event button released				
54:48.6	Event button pressed				
54:48.6	Audio recording enabled due to video recording default				
54:48.7	Event button released				
54:48.7	Recording started due to button press	73	2		54.809 e4c98c7a187a4a619b0b94f88ea0fcfe
56:41.8	Event button pressed				
56:44.8	Recording stopped due to button press	72	2		54.687 e4c98c7a187a4a619b0b94f88ea0fcfe
56:45.3	Event button released				
56:45.5	Audio recording disabled due to video buffering default				
03:51.2	Event button pressed				
03:51.4	Event button released				
03:51.4	Event button pressed				
03:51.5	Audio recording enabled due to video recording default				
03:51.5	Event button released				
03:51.6	Recording started due to button press	72	3		54.686 3105a73c9bc44f068123be26a25313b6
07:28.4	Event button pressed				
07:31.4	Recording stopped due to button press	71	3		54.51 3105a73c9bc44f068123be26a25313b6
07:31.9	Event button released				
07:32.2	Audio recording disabled due to video buffering default				
18:14.2	Audit log created	70	3	1.18.19	54.509
38:47.6	Axon application connected to device				
39:12.9	Title changed in video metadata from 'Axon Body 3 Video 2021-10-02 0136 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO				0252611ca8ae47aea2994f5428900c60
39:12.9	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225				0252611ca8ae47aea2994f5428900c60
39:29.2	Title changed in video metadata from 'Axon Body 3 Video 2021-10-02 0154 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO				e4c98c7a187a4a619b0b94f88ea0fcfe
39:29.2	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225				e4c98c7a187a4a619b0b94f88ea0fcfe
39:48.0	Title changed in video metadata from 'Axon Body 3 Video 2021-10-02 0203 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO				3105a73c9bc44f068123be26a25313b6
39:48.0	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225				3105a73c9bc44f068123be26a25313b6
40:06.2	Axon application disconnected from device				
18:14.3	Audit log created	64	3	1.18.19	54.507
36:09.0	signal state changed				
36:09.1	Audio recording enabled due to video recording default				
36:09.2	Recording started due to Axon Signal Sidearm activation	63	4		54.507 31ca26384dec4043b59e15a6c6bc399c

36:13.6	Event button pressed			
36:16.6	Recording stopped due to button press	63	4	54.49 31ca26384dec4043b59e15a6c6bc399c
36:17.3	Event button released			
36:17.4	Audio recording disabled due to video buffering default			
41:38.4	Axon application connected to device			
42:21.6	Title changed in video metadata from 'Axon Body 3 Video 2021-10-02 0336 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO			31ca26384dec4043b59e15a6c6bc399c
42:21.6	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			31ca26384dec4043b59e15a6c6bc399c
42:33.4	Axon application disconnected from device			
43:12.0	Volume up button pressed			
43:12.0	Volume up button released			
43:12.3	Volume changed to high from medium using button			
43:14.8	Volume down button pressed			
43:15.1	Volume down button released			
43:15.3	Volume changed to medium from high using button			
43:43.0	Camera connected to Axon Dock X62001V12	62	4	54.469
43:43.2	Audit log created	62	4 1.18.19	54.442
43:43.2	Audit log rolled	62	4	54.442
43:44.2	Device connected to charger	62	4	54.442
44:07.9	Video upload started when camera was docked			0252611ca8ae47aea2994f5428900c60
44:14.0	Date/Time synced to 10/02/2021 03:44:14.02 AM from 10/02/2021 03:44:13.24 AM			
44:46.8	Audit log successfully uploaded			
44:47.0	Audit log successfully uploaded and deleted from device	63	4	54.469
44:53.1	Audit log successfully uploaded			
44:53.3	Audit log successfully uploaded and deleted from device	63	4	54.469
45:07.8	Audit log successfully uploaded			
45:08.0	Audit log successfully uploaded and deleted from device	63	4	54.469
45:24.2	Audit log successfully uploaded			
45:24.4	Audit log successfully uploaded and deleted from device	63	4	54.469
45:33.5	Audit log successfully uploaded			
45:33.7	Audit log successfully uploaded and deleted from device	63	4	54.469
45:52.9	Audit log successfully uploaded			
45:53.1	Audit log successfully uploaded and deleted from device	63	4	54.469
45:57.3	Video successfully uploaded from device when dockec			0252611ca8ae47aea2994f5428900c60
45:57.7	Video deleted from device when docked	63	3	54.895 0252611ca8ae47aea2994f5428900c60
45:57.8	Audit log created	63	3 1.18.19	54.896
45:57.8	Audit log rolled	63	3	54.896
45:58.0	Video upload started when camera was docked			e4c98c7a187a4a619b0b94f88ea0fcfe
46:14.3	Audit log successfully uploaded			
46:14.6	Audit log successfully uploaded and deleted from device	63	3	54.896
46:22.7	Audit log successfully uploaded			
46:22.9	Audit log successfully uploaded and deleted from device	63	3	54.896
46:29.4	Video successfully uploaded from device when dockec			e4c98c7a187a4a619b0b94f88ea0fcfe
46:29.7	Video deleted from device when docked	63	2	55.017 e4c98c7a187a4a619b0b94f88ea0fcfe
46:29.8	Audit log created	63	2 1.18.19	55.018
46:29.8	Audit log rolled	63	2	55.018
46:30.0	Video upload started when camera was docked			3105a73c9bc44f068123be26a25313b6
46:48.1	Audit log successfully uploaded			

46:48.3	Audit log successfully uploaded and deleted from device	63	2	55.018	
47:00.4	Audit log successfully uploaded				
47:00.6	Audit log successfully uploaded and deleted from device	63	2	55.018	
47:16.2	Video successfully uploaded from device when docked				3105a73c9bc44f068123be26a25313b6
47:16.4	Video deleted from device when docked	63	1	55.194	3105a73c9bc44f068123be26a25313b6
47:16.5	Audit log rolled	63	1	55.194	
47:16.5	Audit log created	63	1	55.194	
47:16.9	Video upload started when camera was docked				31ca26384dec4043b59e15a6c6bc399c
47:20.8	Audit log successfully uploaded				
47:21.0	Audit log successfully uploaded and deleted from device	63	1	55.194	
47:33.8	Video successfully uploaded from device when docked				31ca26384dec4043b59e15a6c6bc399c
47:34.0	Video deleted from device when docked	64	0	55.258	31ca26384dec4043b59e15a6c6bc399c
47:34.1	Audit log created	64	0	55.259	
47:34.1	Audit log rolled	64	0	55.259	
47:34.1	Audit log rolled	64	0	55.259	
47:34.1	Audit log created	64	0	55.259	
47:36.1	Audit log successfully uploaded				
47:36.4	Audit log successfully uploaded and deleted from device	64	0	55.259	
47:42.6	Audit log successfully uploaded				
47:42.8	Audit log successfully uploaded and deleted from device	64	0	55.259	
48:09.4	Audit log successfully uploaded				
48:09.7	Audit log successfully uploaded and deleted from device	64	0	55.259	
48:25.8	Audit log successfully uploaded				
48:26.0	Audit log successfully uploaded and deleted from device	64	0	55.259	
48:50.2	Audit log successfully uploaded				
48:50.3	Audit log successfully uploaded and deleted from device	64	0	55.259	
49:13.5	Audit log successfully uploaded				
49:13.7	Audit log successfully uploaded and deleted from device	65	0	55.259	
49:14.9	Audit log successfully uploaded				
49:15.1	Audit log successfully uploaded and deleted from device	65	0	55.259	
49:44.3	Audit log successfully uploaded				
49:44.5	Audit log successfully uploaded and deleted from device	65	0	55.259	
49:49.6	Audit log successfully uploaded				
49:49.8	Audit log successfully uploaded and deleted from device	65	0	55.259	
50:16.1	Audit log successfully uploaded				
50:16.3	Audit log successfully uploaded and deleted from device	65	0	55.259	
50:28.4	Audit log successfully uploaded				
50:28.6	Audit log successfully uploaded and deleted from device	65	0	55.259	
50:51.8	Audit log successfully uploaded				
50:52.0	Audit log successfully uploaded and deleted from device	65	0	55.259	
51:14.2	Audit log successfully uploaded				
51:14.4	Audit log successfully uploaded and deleted from device	65	0	55.259	
51:26.6	Audit log successfully uploaded				
51:26.9	Audit log successfully uploaded and deleted from device	65	0	55.259	
51:46.1	Audit log successfully uploaded				
51:46.3	Audit log successfully uploaded and deleted from device	66	0	55.259	
51:47.4	Audit log successfully uploaded				

51:47.7 Audit log successfully uploaded and deleted from device	66	0	55.259
52:12.9 Audit log successfully uploaded			
52:13.2 Audit log successfully uploaded and deleted from device	66	0	55.259
52:20.3 Audit log successfully uploaded			
52:20.5 Audit log successfully uploaded and deleted from device	66	0	55.259
52:45.7 Audit log successfully uploaded			
52:45.9 Audit log successfully uploaded and deleted from device	66	0	55.259
53:13.1 Audit log successfully uploaded			
53:13.2 Audit log successfully uploaded and deleted from device	66	0	55.259
53:41.4 Audit log successfully uploaded			
53:41.6 Audit log successfully uploaded and deleted from device	66	0	55.259
53:55.8 Audit log successfully uploaded			
53:56.0 Audit log successfully uploaded and deleted from device	66	0	55.258
54:05.5 Audit log successfully uploaded			
54:05.8 Audit log successfully uploaded and deleted from device	66	0	55.258
54:31.0 Audit log successfully uploaded			
54:31.2 Audit log successfully uploaded and deleted from device	67	0	55.258
54:31.4 Audit log successfully uploaded			
54:31.6 Audit log successfully uploaded and deleted from device	67	0	55.258
54:37.8 Audit log successfully uploaded			
54:38.0 Audit log successfully uploaded and deleted from device	67	0	55.258
54:51.1 Audit log successfully uploaded			
54:51.3 Audit log successfully uploaded and deleted from device	67	0	55.258
55:07.5 Audit log successfully uploaded			
55:07.7 Audit log successfully uploaded and deleted from device	67	0	55.258
55:07.8 Audit log successfully uploaded			
55:08.0 Audit log successfully uploaded and deleted from device	67	0	55.258
55:20.2 Audit log successfully uploaded			
55:20.4 Audit log successfully uploaded and deleted from device	67	0	55.258
55:30.6 Audit log successfully uploaded			
55:30.8 Audit log successfully uploaded and deleted from device	67	0	55.258
55:46.9 Audit log successfully uploaded			
55:47.1 Audit log successfully uploaded and deleted from device	67	0	55.258
55:47.3 Audit log successfully uploaded			
55:47.5 Audit log successfully uploaded and deleted from device	67	0	55.258
55:49.6 Audit log successfully uploaded			
55:49.8 Audit log successfully uploaded and deleted from device	68	0	55.258
55:58.0 Audit log successfully uploaded			
55:58.2 Audit log successfully uploaded and deleted from device	68	0	55.258
56:19.4 Audit log successfully uploaded			
56:19.6 Audit log successfully uploaded and deleted from device	68	0	55.258
56:19.8 Audit log successfully uploaded			
56:20.0 Audit log successfully uploaded and deleted from device	68	0	55.258
56:49.1 Audit log successfully uploaded			
56:49.4 Audit log successfully uploaded and deleted from device	68	0	55.258
57:13.5 Audit log successfully uploaded			
57:13.7 Audit log successfully uploaded and deleted from device	68	0	55.258

57:37.8	Audit log successfully uploaded			
57:38.1	Audit log successfully uploaded and deleted from device	68	0	55.258
57:47.3	Audit log successfully uploaded			
57:47.5	Audit log successfully uploaded and deleted from device	68	0	55.258
57:57.7	Audit log successfully uploaded			
57:57.9	Audit log successfully uploaded and deleted from device	68	0	55.258
58:22.1	Audit log successfully uploaded			
58:22.2	Audit log successfully uploaded and deleted from device	69	0	55.258
58:27.4	Audit log successfully uploaded			
58:27.6	Audit log successfully uploaded and deleted from device	69	0	55.258
58:43.8	Audit log successfully uploaded			
58:44.0	Audit log successfully uploaded and deleted from device	69	0	55.258
58:51.2	Audit log successfully uploaded			
58:51.3	Audit log successfully uploaded and deleted from device	69	0	55.258
58:57.5	Audit log successfully uploaded			
58:57.7	Audit log successfully uploaded and deleted from device	69	0	55.258
59:02.2	Audit log successfully uploaded			
59:02.3	Audit log successfully uploaded and deleted from device	69	0	55.258
59:02.5	Audit log successfully uploaded			
59:02.6	Audit log successfully uploaded and deleted from device	69	0	55.258
59:10.8	Audit log successfully uploaded			
59:11.0	Audit log successfully uploaded and deleted from device	69	0	55.258
59:12.1	Audit log successfully uploaded			
59:12.2	Audit log successfully uploaded and deleted from device	69	0	55.258
59:22.4	Audit log successfully uploaded			
59:22.6	Audit log successfully uploaded and deleted from device	69	0	55.258
59:35.8	Audit log successfully uploaded			
59:36.0	Audit log successfully uploaded and deleted from device	69	0	55.258
59:42.2	Audit log successfully uploaded			
59:42.4	Audit log successfully uploaded and deleted from device	69	0	55.258
59:45.6	Audit log successfully uploaded			
59:45.8	Audit log successfully uploaded and deleted from device	69	0	55.258
00:06.9	Audit log successfully uploaded			
00:07.1	Audit log successfully uploaded and deleted from device	70	0	55.258
00:22.3	Audit log successfully uploaded			
00:22.5	Audit log successfully uploaded and deleted from device	70	0	55.258
00:22.6	Audit log successfully uploaded			
00:22.8	Audit log successfully uploaded and deleted from device	70	0	55.258
00:40.0	Audit log successfully uploaded			
00:40.2	Audit log successfully uploaded and deleted from device	70	0	55.258
00:56.3	Audit log successfully uploaded			
00:56.5	Audit log successfully uploaded and deleted from device	70	0	55.258
01:13.7	Audit log successfully uploaded			
01:14.0	Audit log successfully uploaded and deleted from device	70	0	55.258
01:36.1	Audit log successfully uploaded			
01:36.3	Audit log successfully uploaded and deleted from device	70	0	55.258
01:38.6	Device disconnected from charger	70	0	55.258

01:38.7	Camera disconnected from Axon Dock X62001V12	70	0	55.258
37:28.9	Event button pressed			
37:29.0	Event button released			
37:29.1	Event button pressed			
37:29.1	Audio recording enabled due to video recording default			
37:29.2	Event button released			
37:29.2	Recording started due to button press	66	1	55.262 6afed3d61b8444eca2a42586945be48d
47:02.4	Event button pressed			
47:05.4	Recording stopped due to button press	65	1	54.898 6afed3d61b8444eca2a42586945be48d
47:06.4	Audio recording disabled due to video buffering default			
47:06.4	Event button released			
47:34.0	Audit log created	65	1 1.18.19	54.897
45:55.3	Axon application connected to device			
46:25.8	Title changed in video metadata from 'Axon Body 3 Video 2021-10-02 0437 X6033271L' to 'Signal 75' using Axon application by MORAES, NILSO			6afed3d61b8444eca2a42586945be48d
46:25.8	Categories 'Miscellaneous' added to video metadata using Axon application by MORAES, NILSON (M1225			6afed3d61b8444eca2a42586945be48d
46:48.4	Axon application disconnected from device			
47:34.0	Audit log created	58	1 1.18.19	54.895
47:34.1	Audit log created	51	1 1.18.19	54.893
47:34.1	Audit log created	45	1 1.18.19	54.892
53:33.3	Camera connected to Axon Dock X630020W7	45	1	54.892
53:33.3	Audit log rolled	44	1	54.892
53:33.3	Audit log created	44	1 1.18.19	54.892
53:33.7	Device connected to charger	44	1	54.892
53:33.0	Audit log created	73	1 1.18.19	54.891
53:33.0	Audit log created	97	1 1.18.19	54.891
53:33.0	Audit log created	100	1 1.18.19	54.89
53:33.1	Audit log created	100	1 1.18.19	54.894
53:33.1	Audit log created	100	1 1.18.19	54.894
53:33.1	Audit log created	100	1 1.18.19	54.893
53:33.1	Audit log created	100	1 1.18.19	54.893
53:33.1	Audit log created	100	1 1.18.19	54.893
53:33.1	Audit log created	100	1 1.18.19	54.892
53:33.2	Audit log created	100	1 1.18.19	54.892
53:33.3	Audit log created	100	1 1.18.19	54.895
53:33.3	Audit log created	100	1 1.18.19	54.894
53:33.3	Audit log created	100	1 1.18.19	54.894
12:07.7	Device disconnected from charger	98	1	54.894
12:08.4	Camera disconnected from Axon Dock X630020W7	100	1	54.894
12:20.5	Power button pressed			
12:23.5	Device powered off using button	100	1	54.897
12:23.9	Power button released			
06:35.1	Audit log created		1.18.19	
06:35.2	Device powered on using button	100	1	54.896
06:37.0	Audio recording disabled due to video buffering default			
10:02.2	Event button pressed			
10:02.3	Event button released			
10:02.4	Event button pressed			
10:02.4	Audio recording enabled due to video recording default			

10:02.5 Event button released			
10:02.6 Recording started due to button press	99	1	54.896 63cd3f6f4535402d9de37fe674d77257
10:51.8 Event button pressed			
10:54.8 Recording stopped due to button press	99	2	54.808 63cd3f6f4535402d9de37fe674d77257
10:55.3 Event button released			
10:55.7 Audio recording disabled due to video buffering default			
26:50.4 Event button pressed			
26:50.5 Event button released			
26:50.5 Event button pressed			
26:50.6 Audio recording enabled due to video recording default			
26:50.6 Event button released			
26:50.7 Recording started due to button press	97	2	54.807 2a0fb2e42c044bcb9e0adb56d480967f
27:09.3 Event button pressed			
27:10.4 Event button released			
27:38.1 Event button pressed			
27:41.1 Recording stopped due to button press	96	3	54.72 2a0fb2e42c044bcb9e0adb56d480967f
27:41.6 Event button released			
27:42.0 Audio recording disabled due to video buffering default			
28:20.8 Event button pressed			
28:21.0 Event button released			
28:21.1 Event button pressed			
28:21.1 Audio recording enabled due to video recording default			
28:21.2 Event button released			
28:21.3 Recording started due to button press	96	4	54.72 f391bd80607041af8e5457c3e6d87c17
28:53.0 Event button pressed			
28:53.1 Event button released			
28:53.2 Event button pressed			
28:53.3 Event button released			
29:36.5 Event button pressed			
29:39.5 Recording stopped due to button press	96	4	54.659 f391bd80607041af8e5457c3e6d87c17
29:40.0 Event button released			
29:40.3 Audio recording disabled due to video buffering default			
30:10.9 Event button pressed			
30:11.0 Event button released			
30:11.0 Event button pressed			
30:11.1 Audio recording enabled due to video recording default			
30:11.1 Event button released			
30:11.2 Recording started due to button press	96	5	54.658 169461796a3d4305b4202dd887d25ad4
30:42.3 Event button pressed			
30:45.3 Recording stopped due to button press	96	5	54.625 169461796a3d4305b4202dd887d25ad4
30:46.2 Audio recording disabled due to video buffering default			
30:46.2 Event button released			
06:35.1 Audit log created	92	5 1.18.19	54.624
50:51.1 Event button pressed			
50:51.2 Event button released			
50:51.3 Event button pressed			
50:51.3 Audio recording enabled due to video recording default			

50:51.4	Event button released			
50:51.5	Recording started due to button press	88	6	54.623 ba9c13a579364c538e5e9106847127c6
53:13.6	Event button pressed			
53:16.6	Recording stopped due to button press	88	6	54.486 ba9c13a579364c538e5e9106847127c6
53:17.1	Event button released			
53:17.4	Audio recording disabled due to video buffering default			
00:25.8	Event button pressed			
00:26.0	Event button released			
00:26.0	Event button pressed			
00:26.1	Audio recording enabled due to video recording default			
00:26.1	Event button released			
00:26.2	Recording started due to button press	87	7	54.485 d45d6c9f893c41599a988cf6bbadea09
03:42.0	Event button pressed			
03:45.0	Recording stopped due to button press	86	7	54.32 d45d6c9f893c41599a988cf6bbadea09
03:45.6	Event button released			
03:45.8	Audio recording disabled due to video buffering default			
06:35.1	Audit log created	86	7 1.18.19	54.319
06:35.1	Audit log created	81	7 1.18.19	54.318
54:22.4	Event button pressed			
54:22.5	Event button released			
54:22.6	Event button pressed			
54:22.6	Audio recording enabled due to video recording default			
54:22.7	Event button released			
54:22.7	Recording started due to button press	77	8	54.317 b452d1c8da324e3c848255c44f51eda5
57:45.4	Event button pressed			
57:48.4	Recording stopped due to button press	76	8	54.148 b452d1c8da324e3c848255c44f51eda5
57:48.8	Event button released			
57:49.4	Audio recording disabled due to video buffering default			
06:35.2	Audit log created	75	8 1.18.19	54.147
20:50.1	Axon application connected to device			
24:04.7	Select button pressed			
24:04.8	Select button released			
24:09.7	Camera connected to Axon Dock X62001W9H	74	8	54.157
24:09.8	Axon application disconnected from device			
24:09.9	Audit log rolled	74	8	54.147
24:09.9	Audit log created	74	8 1.18.19	54.147
24:10.2	Device connected to charger	74	8	54.147
24:35.0	Video upload started when camera was docked			6afed3d61b8444eca2a42586945be48d
24:40.0	Date/Time synced to 10/03/2021 04:24:40.01 AM from 10/03/2021 04:24:39.82 AM			
24:46.0	Audit log successfully uploaded			
24:46.2	Audit log successfully uploaded and deleted from device	74	8	54.157
25:05.6	Audit log successfully uploaded			
25:05.8	Audit log successfully uploaded and deleted from device	75	8	54.157
25:17.9	Audit log successfully uploaded			
25:18.1	Audit log successfully uploaded and deleted from device	75	8	54.157
25:46.2	Audit log successfully uploaded			
25:46.4	Audit log successfully uploaded and deleted from device	75	8	54.157

25:49.0	Camera disconnected from Axon Dock X62001W9H	75	8	54.157	
25:49.1	Device disconnected from charger	75	8	54.157	
25:53.2	Programmable button pressed				
25:53.3	Programmable button released				
26:22.1	Volume up button pressed				
26:22.1	Volume up button released				
26:22.3	Volume changed to high from medium using button				
26:24.7	Camera connected to Axon Dock X62001W9H	75	8	54.16	
26:24.7	Audit log created	75	8 1.18.19	54.16	
26:24.7	Audit log rolled	75	8	54.16	
26:26.1	Device connected to charger	75	8	54.16	
26:51.8	Video upload started when camera was docked				63cd3f6f4535402d9de37fe674d77257
26:55.0	Date/Time synced to 10/03/2021 04:26:55.02 AM from 10/03/2021 04:26:54.71 AM				
27:13.9	Video successfully uploaded from device when dockec				6afed3d61b8444eca2a42586945be48d
27:14.2	Video deleted from device when docked	75	7	54.523	6afed3d61b8444eca2a42586945be48d
27:14.3	Audit log created	75	7 1.18.19	54.523	
27:14.3	Audit log rolled	75	7	54.523	
27:17.4	Video successfully uploaded from device when dockec				63cd3f6f4535402d9de37fe674d77257
27:17.6	Video deleted from device when docked	75	6	54.611	63cd3f6f4535402d9de37fe674d77257
27:17.7	Audit log rolled	75	6	54.611	
27:17.7	Audit log created	75	6 1.18.19	54.611	
27:17.9	Video upload started when camera was docked				2a0fb2e42c044bcb9e0adb56d480967f
27:38.0	Audit log successfully uploaded				
27:38.2	Audit log successfully uploaded and deleted from device	75	6	54.611	
27:41.1	Video successfully uploaded from device when dockec				2a0fb2e42c044bcb9e0adb56d480967f
27:41.3	Video deleted from device when docked	75	5	54.698	2a0fb2e42c044bcb9e0adb56d480967f
27:41.3	Audit log rolled	75	5	54.698	
27:41.3	Audit log created	75	5 1.18.19	54.698	
27:41.5	Video upload started when camera was docked				f391bd80607041af8e5457c3e6d87c17
27:52.3	Audit log successfully uploaded				
27:52.5	Audit log successfully uploaded and deleted from device	75	5	54.698	
27:58.9	Video successfully uploaded from device when dockec				f391bd80607041af8e5457c3e6d87c17
27:59.2	Video deleted from device when docked	75	4	54.759	f391bd80607041af8e5457c3e6d87c17
27:59.2	Audit log created	75	4 1.18.19	54.759	
27:59.2	Audit log rolled	75	4	54.759	
27:59.4	Video upload started when camera was docked				169461796a3d4305b4202dd887d25ad4
28:09.0	Video successfully uploaded from device when dockec				169461796a3d4305b4202dd887d25ad4
28:09.3	Video deleted from device when docked	75	3	54.793	169461796a3d4305b4202dd887d25ad4
28:09.4	Audit log created	75	3 1.18.19	54.793	
28:09.4	Audit log rolled	75	3	54.793	
28:09.6	Video upload started when camera was docked				ba9c13a579364c538e5e9106847127c6
28:16.6	Audit log successfully uploaded				
28:16.7	Audit log successfully uploaded and deleted from device	75	3	54.793	
28:44.9	Audit log successfully uploaded				
28:45.0	Audit log successfully uploaded and deleted from device	76	3	54.793	
28:45.5	Video successfully uploaded from device when dockec				ba9c13a579364c538e5e9106847127c6
28:45.8	Video deleted from device when docked	76	2	54.93	ba9c13a579364c538e5e9106847127c6

28:45.8	Audit log created	76	2 1.18.19	54.93	
28:45.9	Audit log rolled	76	2	54.93	
28:46.0	Video upload started when camera was docked				d45d6c9f893c41599a988cf6bbadea09
28:56.2	Audit log successfully uploaded				
28:56.4	Audit log successfully uploaded and deleted from device	76	2	54.93	
29:19.6	Audit log successfully uploaded				
29:19.8	Audit log successfully uploaded and deleted from device	76	2	54.93	
29:28.4	Video successfully uploaded from device when docked				d45d6c9f893c41599a988cf6bbadea09
29:28.7	Video deleted from device when docked	76	1	55.094	d45d6c9f893c41599a988cf6bbadea09
29:28.8	Audit log created	76	1 1.18.19	55.095	
29:28.8	Audit log rolled	76	1	55.095	
29:29.1	Video upload started when camera was docked				b452d1c8da324e3c848255c44f51eda5
29:43.9	Audit log successfully uploaded				
29:44.2	Audit log successfully uploaded and deleted from device	76	1	55.095	
29:46.3	Audit log successfully uploaded				
29:46.5	Audit log successfully uploaded and deleted from device	76	1	55.095	
30:02.7	Audit log successfully uploaded				
30:02.9	Audit log successfully uploaded and deleted from device	77	1	55.094	
30:13.3	Video successfully uploaded from device when docked				b452d1c8da324e3c848255c44f51eda5
30:13.6	Video deleted from device when docked	77	0	55.263	b452d1c8da324e3c848255c44f51eda5
30:13.7	Audit log created	77	0 1.18.19	55.263	
30:13.7	Audit log rolled	77	0	55.263	
30:13.7	Audit log rolled	77	0	55.263	
30:13.7	Audit log created	77	0 1.18.19	55.263	
30:28.0	Audit log successfully uploaded				
30:28.1	Audit log successfully uploaded and deleted from device	77	0	55.263	
30:31.3	Audit log successfully uploaded				
30:31.5	Audit log successfully uploaded and deleted from device	77	0	55.263	
30:58.7	Audit log successfully uploaded				
30:58.9	Audit log successfully uploaded and deleted from device	77	0	55.263	
31:11.3	Device disconnected from charger	77	0	55.263	
31:11.3	Camera disconnected from Axon Dock X62001W9H	77	0	55.263	
30:13.0	Audit log created	71	0 1.18.19	55.262	
30:13.0	Audit log created	65	0 1.18.19	55.261	
30:13.1	Audit log created	60	0 1.18.19	55.259	
49:12.5	Axon application connected to device				
49:39.4	Axon application connected to device				
49:53.3	Axon application disconnected from device				
30:13.1	Audit log created	53	0 1.18.19	55.258	
30:13.1	Audit log created	46	0 1.18.19	55.257	
30:13.1	Audit log created	41	0 1.18.19	55.255	
30:13.2	Audit log created	35	0 1.18.19	55.254	
25:12.3	Camera connected to Axon Dock X630020W7	31	0	55.256	
25:12.3	Audit log rolled	31	0	55.256	
25:12.3	Audit log created	31	0 1.18.19	55.256	
25:13.3	Device connected to charger	31	0	55.256	
37:25.3	Device disconnected from charger	36	0	55.256	

37:25.3 Camera disconnected from Axon Dock X630020W7	36	0	55.256
25:12.0 Audit log created	32	0 1.18.19	55.26
26:07.7 Camera connected to Axon Dock X630020W7	32	0	55.26
26:07.8 Audit log created	32	0 1.18.19	55.26
26:07.8 Audit log rolled	32	0	55.26
26:08.3 Device connected to charger	32	0	55.26
26:07.0 Audit log created	58	0 1.18.19	55.259
26:07.0 Audit log created	84	0 1.18.19	55.258
26:07.1 Audit log created	100	0 1.18.19	55.257
26:07.1 Audit log created	100	0 1.18.19	55.257
26:07.1 Audit log created	100	0 1.18.19	55.256
26:07.1 Audit log created	100	0 1.18.19	55.256
46:43.2 Camera disconnected from Axon Dock X630020W7	98	0	55.256
46:43.3 Device disconnected from charger	98	0	55.256
46:48.0 Programmable button pressed			
46:48.0 Programmable button released			
26:07.1 Audit log created	95	0 1.18.19	55.255
26:07.1 Audit log created	89	0 1.18.19	55.254
26:07.2 Audit log created	84	0 1.18.19	55.252
26:07.2 Audit log created	78	0 1.18.19	55.251
26:07.2 Audit log created	73	0 1.18.19	55.25
26:07.2 Audit log created	67	0 1.18.19	55.248
22:51.2 Power button pressed			
22:54.3 Device powered off using button	62	0	55.247
22:54.7 Power button released			
13:00.1 Audit log created		1.18.19	
13:00.2 Device powered on using button	62	0	55.25
13:02.0 Audio recording disabled due to video buffering default			
44:54.7 Axon application connected to device			
45:16.4 Axon application disconnected from device			
13:00.1 Audit log created	55	0 1.18.19	55.249
15:20.1 Volume up button pressed			
15:20.2 Volume up button released			
15:20.3 Volume changed to very high from high using button			
15:22.3 Volume down button pressed			
15:22.6 Volume down button released			
15:22.7 Volume changed to high from very high using button			
15:25.9 Volume down button pressed			
15:26.2 Volume down button released			
15:26.3 Volume changed to medium from high using button			
15:30.1 Camera connected to Axon Dock X630020W7	54	0	55.249
15:30.2 Audit log rolled	54	0	55.249
15:30.2 Audit log created	54	0 1.18.19	55.249
15:31.1 Device connected to charger	54	0	55.249
15:30.0 Audit log created	82	0 1.18.19	55.251
15:30.0 Audit log created	100	0 1.18.19	55.25
15:30.0 Audit log created	100	0 1.18.19	55.25

15:30.1 Audit log created	100	0	1.18.19	55.25
15:30.1 Audit log created	100	0	1.18.19	55.25
15:30.1 Audit log created	100	0	1.18.19	55.25
15:30.1 Audit log created	100	0	1.18.19	55.25
15:30.1 Audit log created	100	0	1.18.19	55.249
35:17.1 Device disconnected from charger	98	0		55.249
35:17.9 Camera disconnected from Axon Dock X630020W7	98	0		55.25
35:37.7 Power button pressed				
35:40.7 Device powered off using button	100	0		55.25
35:41.2 Power button released				
48:32.0 Audit log created			1.18.19	
48:32.2 Device powered on using button	100	0		55.249
48:34.3 Audio recording disabled due to video buffering default				
56:37.7 Power button pressed				
56:37.8 Power button released				
56:40.5 Event button pressed				
56:40.7 Event button released				
56:40.7 Event button pressed				
56:40.8 Audio recording enabled due to video recording default				
56:40.8 Event button released				
56:41.0 Recording started due to button press	99	0		55.248 48b054df4b374b308ad91a3476e2f705
13:40.1 Power button pressed				
13:43.1 Device powered off using button	95	1		54.653
13:43.3 Power button released				
13:50.6 Recording stopped due to power button long press to initiate shutdown	95	1		54.649 48b054df4b374b308ad91a3476e2f705
14:45.0 Device powered on using button	95	1		54.646
14:46.9 Audio recording disabled due to video buffering default				
14:53.5 Event button pressed				
14:53.6 Event button released				
14:53.7 Event button pressed				
14:53.7 Audio recording enabled due to video recording default				
14:53.8 Event button released				
14:53.8 Recording started due to button press	95	1		54.645 76eff94da0334ea8bf907f960575fe4e
31:18.6 Event button pressed				
31:21.6 Recording stopped due to button press	92	2		54.126 76eff94da0334ea8bf907f960575fe4e
31:22.4 Event button released				
31:22.5 Audio recording disabled due to video buffering default				
47:23.1 Event button pressed				
47:23.6 Event button released				
48:32.1 Audit log created	90	2	1.18.19	54.123
21:30.1 Power button pressed				
21:30.6 Power button released				
48:32.1 Audit log created	85	2	1.18.19	54.121
48:32.1 Audit log created	79	2	1.18.19	54.12
49:02.9 Power button pressed				
49:06.0 Device powered off using button	79	2		54.12
49:06.4 Power button released				

50:59.4 Device powered on using button	79	2	54.119
51:02.5 Audio recording disabled due to video buffering default			
51:56.1 Axon application connected to device			
52:33.1 Title changed in video metadata from 'Axon Body 3 Video 2021-10-04 1756 X6033271L' to 'Signal 6' using Axon application by MORAES, NILSON			48b054df4b374b308ad91a3476e2f705
52:33.1 Categories 'Lost Property' added to video metadata using Axon application by MORAES, NILSON (M1225			48b054df4b374b308ad91a3476e2f705
52:57.8 Title changed in video metadata from 'Axon Body 3 Video 2021-10-04 1814 X6033271L' to 'Signal 6' using Axon application by MORAES, NILSON			76eff94da0334ea8bf907f960575fe4e
52:57.8 Categories 'Lost Property' added to video metadata using Axon application by MORAES, NILSON (M1225			76eff94da0334ea8bf907f960575fe4e
53:19.1 Axon application disconnected from device			
53:30.4 Power button pressed			
53:33.5 Device powered off using button	79	2	54.12
53:33.8 Power button released			
43:52.3 Audit log created		1.18.19	
43:52.3 Device powered on using button	79	2	54.12
43:55.4 Audio recording disabled due to video buffering default			
43:52.3 Audit log created	73	2 1.18.19	54.118
43:52.3 Audit log created	68	2 1.18.19	54.117
46:22.7 Axon application connected to device			
48:57.4 Axon application disconnected from device			
02:10.4 Event button pressed			
02:10.6 Event button released			
43:52.4 Audit log created	62	2 1.18.19	54.115
43:58.1 Volume up button pressed			
43:58.2 Volume up button released			
43:58.3 Volume changed to high from medium using button			
44:03.6 Volume down button pressed			
44:03.7 Volume down button released			
44:03.9 Volume changed to medium from high using button			
44:08.1 Power button pressed			
44:08.2 Power button released			
44:08.9 Camera connected to Axon Dock X62001W9H	63	2	54.136
44:08.9 Audit log rolled	62	2	54.115
44:08.9 Audit log created	62	2 1.18.19	54.118
44:09.3 Device connected to charger	62	2	54.118
44:33.7 Video upload started when camera was docked			48b054df4b374b308ad91a3476e2f705
44:37.2 Audit log successfully uploaded			
44:37.4 Audit log successfully uploaded and deleted from device	63	2	54.136
44:37.6 Audit log successfully uploaded			
44:37.8 Audit log successfully uploaded and deleted from device	63	2	54.136
44:42.0 Date/Time synced to 10/05/2021 02:44:42.01 AM from 10/05/2021 02:44:38.88 AM			
44:45.8 Audit log successfully uploaded			
44:46.0 Audit log successfully uploaded and deleted from device	63	2	54.136
45:13.6 Audit log successfully uploaded			
45:13.8 Audit log successfully uploaded and deleted from device	63	2	54.136
45:36.0 Audit log successfully uploaded			
45:36.2 Audit log successfully uploaded and deleted from device	63	2	54.136
45:42.3 Audit log successfully uploaded			
45:42.5 Audit log successfully uploaded and deleted from device	63	2	54.135

45:55.6	Audit log successfully uploaded			
45:55.8	Audit log successfully uploaded and deleted from device	63	2	54.135
45:55.9	Audit log successfully uploaded			
45:56.1	Audit log successfully uploaded and deleted from device	63	2	54.135
46:03.2	Audit log successfully uploaded			
46:03.3	Audit log successfully uploaded and deleted from device	63	2	54.135
46:12.5	Audit log successfully uploaded			
46:12.7	Audit log successfully uploaded and deleted from device	63	2	54.135
46:41.9	Audit log successfully uploaded			
46:42.0	Audit log successfully uploaded and deleted from device	63	2	54.135
46:47.2	Audit log successfully uploaded			
46:47.3	Audit log successfully uploaded and deleted from device	63	2	54.135
47:16.5	Audit log successfully uploaded			
47:16.6	Audit log successfully uploaded and deleted from device	64	2	54.135
47:30.7	Video successfully uploaded from device when docked			48b054df4b374b308ad91a3476e2f705
47:31.1	Video deleted from device when docked	64	1	54.735 48b054df4b374b308ad91a3476e2f705
47:31.2	Audit log rolled	64	1	54.735
47:31.2	Audit log created	64	1 1.18.19	54.735
47:31.4	Video upload started when camera was docked			76eff94da0334ea8bf907f960575fe4e
47:32.7	Audit log successfully uploaded			
47:32.9	Audit log successfully uploaded and deleted from device	64	1	54.735
47:37.1	Audit log successfully uploaded			
47:37.3	Audit log successfully uploaded and deleted from device	64	1	54.735
48:02.3	Audit log successfully uploaded			
48:02.4	Audit log successfully uploaded and deleted from device	64	1	54.735
48:11.6	Audit log successfully uploaded			
48:11.8	Audit log successfully uploaded and deleted from device	64	1	54.735
48:13.0	Audit log successfully uploaded			
48:13.1	Audit log successfully uploaded and deleted from device	64	1	54.735
48:15.3	Audit log successfully uploaded			
48:15.4	Audit log successfully uploaded and deleted from device	64	1	54.735
48:16.7	Audit log successfully uploaded			
48:17.0	Audit log successfully uploaded and deleted from device	64	1	54.735
48:25.1	Audit log successfully uploaded			
48:25.2	Audit log successfully uploaded and deleted from device	64	1	54.735
48:49.4	Audit log successfully uploaded			
48:49.6	Audit log successfully uploaded and deleted from device	65	1	54.735
48:53.7	Audit log successfully uploaded			
48:53.9	Audit log successfully uploaded and deleted from device	65	1	54.735
48:59.0	Audit log successfully uploaded			
48:59.2	Audit log successfully uploaded and deleted from device	65	1	54.735
49:05.6	Audit log successfully uploaded			
49:05.8	Audit log successfully uploaded and deleted from device	65	1	54.735
49:14.9	Audit log successfully uploaded			
49:15.1	Audit log successfully uploaded and deleted from device	65	1	54.735
49:40.3	Audit log successfully uploaded			
49:40.6	Audit log successfully uploaded and deleted from device	65	1	54.735

49:56.6 Video successfully uploaded from device when dockec			76eff94da0334ea8bf907f960575fe4e
49:56.9 Video deleted from device when docked	65	0	55.256 76eff94da0334ea8bf907f960575fe4e
49:57.0 Audit log rolled	65	0	55.256
49:57.0 Audit log created	65	0 1.18.19	55.256
49:57.0 Audit log created	65	0 1.18.19	55.256
49:57.0 Audit log rolled	65	0	55.256
50:08.7 Audit log successfully uploaded			
50:08.9 Audit log successfully uploaded and deleted from device	65	0	55.256
50:32.1 Audit log successfully uploaded			
50:32.3 Audit log successfully uploaded and deleted from device	65	0	55.256
50:43.2 Camera disconnected from Axon Dock X62001W9H	65	0	55.258
50:43.2 Device disconnected from charger	65	0	55.258
18:16.2 Camera connected to Axon Dock X630020W7	63	0	55.258
18:16.3 Audit log created	63	0 1.18.19	55.258
18:16.3 Audit log rolled	63	0	55.258
18:17.2 Device connected to charger	63	0	55.258
18:16.0 Audit log created	91	0 1.18.19	55.257
18:16.0 Audit log created	100	0 1.18.19	55.256
18:16.1 Audit log created	100	0 1.18.19	55.256
18:16.1 Audit log created	100	0 1.18.19	55.256
18:16.1 Audit log created	100	0 1.18.19	55.255
18:16.1 Audit log created	100	0 1.18.19	55.258
18:16.1 Audit log created	100	0 1.18.19	55.261
18:16.2 Audit log created	100	0 1.18.19	55.26
18:16.2 Audit log created	100	0 1.18.19	55.26
18:16.2 Audit log created	100	0 1.18.19	55.26
18:16.2 Audit log created	100	0 1.18.19	55.26
18:16.2 Audit log created	100	0 1.18.19	55.26
18:16.3 Audit log created	100	0 1.18.19	55.26
18:16.3 Audit log created	100	0 1.18.19	55.259
18:16.3 Audit log created	100	0 1.18.19	55.259
18:16.3 Audit log created	100	0 1.18.19	55.259
18:16.3 Audit log created	100	0 1.18.19	55.258
18:16.4 Audit log created	100	0 1.18.19	55.258
18:16.4 Audit log created	100	0 1.18.19	55.258
18:16.4 Audit log created	100	0 1.18.19	55.258
18:16.4 Audit log created	100	0 1.18.19	55.257
18:16.4 Audit log created	100	0 1.18.19	55.257
18:16.5 Audit log created	100	0 1.18.19	55.257
18:16.5 Audit log created	100	0 1.18.19	55.257
18:16.5 Audit log created	100	0 1.18.19	55.256
18:16.5 Audit log created	100	0 1.18.19	55.256
18:16.5 Audit log created	100	0 1.18.19	55.256
18:16.6 Audit log created	100	0 1.18.19	55.256
18:16.6 Audit log created	100	0 1.18.19	55.255
18:16.6 Audit log created	100	0 1.18.19	55.255
18:16.6 Audit log created	100	0 1.18.19	55.255

18:19.1 Audit log created	100	0 1.18.19	55.23
18:19.1 Audit log created	100	0 1.18.19	55.229
18:19.1 Audit log created	100	0 1.18.19	55.229
18:19.2 Audit log created	100	0 1.18.19	55.229
18:19.2 Audit log created	100	0 1.18.19	55.228
18:19.2 Audit log created	100	0 1.18.19	55.228
18:19.3 Audit log created	100	0 1.18.19	55.228
18:19.3 Audit log created	100	0 1.18.19	55.228
18:19.3 Audit log created	100	0 1.18.19	55.227
18:19.3 Audit log created	100	0 1.18.19	55.227
18:19.4 Audit log created	100	0 1.18.19	55.227
18:19.4 Audit log created	100	0 1.18.19	55.226
18:19.4 Audit log created	100	0 1.18.19	55.226
18:19.5 Audit log created	100	0 1.18.19	55.226
18:19.5 Audit log created	100	0 1.18.19	55.225
18:19.5 Audit log created	100	0 1.18.19	55.225
18:19.5 Audit log created	100	0 1.18.19	55.225
18:19.6 Audit log created	100	0 1.18.19	55.225
18:19.6 Audit log created	100	0 1.18.19	55.224
18:19.7 Audit log created	100	0 1.18.19	55.224
18:19.7 Audit log created	100	0 1.18.19	55.224
18:19.7 Audit log created	100	0 1.18.19	55.224
18:19.8 Audit log created	100	0 1.18.19	55.223
18:19.8 Audit log created	100	0 1.18.19	55.223
18:19.8 Audit log created	100	0 1.18.19	55.223
18:19.8 Audit log created	100	0 1.18.19	55.223
18:19.9 Audit log created	100	0 1.18.19	55.222
18:19.9 Audit log created	100	0 1.18.19	55.222
18:19.9 Audit log created	100	0 1.18.19	55.222
18:19.9 Audit log created	100	0 1.18.19	55.222
18:20.0 Audit log created	100	0 1.18.19	55.221
18:20.0 Audit log created	100	0 1.18.19	55.221
29:41.9 Volume up button pressed			
29:42.0 Volume up button released			
29:42.2 Device disconnected from charger	98	0	55.221
29:42.3 Camera disconnected from Axon Dock X630020W7	98	0	55.221
54:16.5 Power button pressed			
54:19.5 Device powered off using button	96	0	55.221
54:19.8 Power button released			
04:24.0 Audit log created		1.18.19	
04:24.1 Device powered on due to charger connection	94	0	55.22
04:24.3 Device connected to charger			
04:24.3 Camera connected to Axon Dock X630020W7	94	0	55.22
04:24.3 Audit log created		1.18.19	
04:24.3 Audit log rolled			
04:25.0 Camera connected to Axon Dock X630020W7	94	0	55.22
04:25.9 Audit log rolled	94		55.22

04:27.4 Audit log created	100	0 1.18.19	55.195
04:27.4 Audit log created	100	0 1.18.19	55.195
04:27.5 Audit log created	100	0 1.18.19	55.195
04:27.5 Audit log created	100	0 1.18.19	55.195
04:27.5 Audit log created	100	0 1.18.19	55.194
04:27.6 Audit log created	100	0 1.18.19	55.194
04:27.6 Audit log created	100	0 1.18.19	55.194
04:27.7 Audit log created	100	0 1.18.19	55.194
04:27.7 Audit log created	100	0 1.18.19	55.193
04:27.7 Audit log created	100	0 1.18.19	55.193
04:27.8 Audit log created	100	0 1.18.19	55.193
04:27.8 Audit log created	100	0 1.18.19	55.192
04:27.8 Audit log created	100	0 1.18.19	55.192
16:38.0 Device disconnected from charger	97	0	55.192
16:38.1 Camera disconnected from Axon Dock X630020W7	97	0	55.192
16:38.2 Audio recording disabled due to video buffering default			
16:47.9 Camera connected to Axon Dock X630020W7	100	0	55.192
16:48.0 Audit log rolled	100	0	55.192
16:48.0 Audit log created	100	0 1.18.19	55.192
16:48.0 Device connected to charger	100	0	55.192
16:47.0 Audit log created	100	0 1.18.19	55.192
16:47.1 Audit log created	100	0 1.18.19	55.192
16:47.1 Audit log created	100	0 1.18.19	55.191
16:47.1 Audit log created	100	0 1.18.19	55.191
16:47.2 Audit log created	100	0 1.18.19	55.191
16:47.2 Audit log created	100	0 1.18.19	55.191
16:47.2 Audit log created	100	0 1.18.19	55.19
16:47.3 Audit log created	100	0 1.18.19	55.19
16:47.3 Audit log created	100	0 1.18.19	55.19
16:47.4 Audit log created	100	0 1.18.19	55.19
16:47.5 Audit log created	100	0 1.18.19	55.189
16:47.5 Audit log created	100	0 1.18.19	55.189
16:47.5 Audit log created	100	0 1.18.19	55.189
16:47.6 Audit log created	100	0 1.18.19	55.188
16:47.6 Audit log created	100	0 1.18.19	55.188
16:47.6 Audit log created	100	0 1.18.19	55.188
16:47.7 Audit log created	100	0 1.18.19	55.188
16:47.7 Audit log created	100	0 1.18.19	55.187
16:47.7 Audit log created	100	0 1.18.19	55.187
16:47.8 Audit log created	100	0 1.18.19	55.187
16:47.8 Audit log created	100	0 1.18.19	55.187
16:47.9 Audit log created	100	0 1.18.19	55.186
16:47.9 Audit log created	100	0 1.18.19	55.186
16:47.9 Audit log created	100	0 1.18.19	55.186
16:48.0 Audit log created	100	0 1.18.19	55.186
16:48.0 Audit log created	100	0 1.18.19	55.185
16:48.1 Audit log created	100	0 1.18.19	55.185

16:48.1 Audit log created	100	0 1.18.19	55.185
16:48.1 Audit log created	100	0 1.18.19	55.185
16:48.2 Audit log created	100	0 1.18.19	55.184
16:48.2 Audit log created	100	0 1.18.19	55.184
16:48.3 Audit log created	100	0 1.18.19	55.184
16:48.3 Audit log created	100	0 1.18.19	55.183
16:48.3 Audit log created	100	0 1.18.19	55.183
16:48.4 Audit log created	100	0 1.18.19	55.183
16:48.4 Audit log created	100	0 1.18.19	55.183
16:48.5 Audit log created	100	0 1.18.19	55.183
16:48.5 Audit log created	100	0 1.18.19	55.182
16:48.5 Audit log created	100	0 1.18.19	55.182
16:48.6 Audit log created	100	0 1.18.19	55.182
16:48.6 Audit log created	100	0 1.18.19	55.181
16:48.7 Audit log created	100	0 1.18.19	55.181
16:48.7 Audit log created	100	0 1.18.19	55.181
16:48.7 Audit log created	100	0 1.18.19	55.181
16:48.7 Audit log created	100	0 1.18.19	55.18
16:48.8 Audit log created	100	0 1.18.19	55.18
16:48.8 Audit log created	100	0 1.18.19	55.18
16:48.8 Audit log created	100	0 1.18.19	55.18
16:48.8 Audit log created	100	0 1.18.19	55.179
16:48.9 Audit log created	100	0 1.18.19	55.179
16:48.9 Audit log created	100	0 1.18.19	55.179
16:49.0 Audit log created	100	0 1.18.19	55.178
16:49.0 Audit log created	100	0 1.18.19	55.178
16:49.0 Audit log created	100	0 1.18.19	55.178
16:49.0 Audit log created	100	0 1.18.19	55.178
16:49.1 Audit log created	100	0 1.18.19	55.177
16:49.1 Audit log created	100	0 1.18.19	55.177
16:49.1 Audit log created	100	0 1.18.19	55.177
16:49.1 Audit log created	100	0 1.18.19	55.176
16:49.2 Audit log created	100	0 1.18.19	55.176
16:49.2 Audit log created	100	0 1.18.19	55.176
04:47.9 Device powered off	100	0	55.176
05:25.0 Device powered on	96	0	55.176
05:25.2 Device connected to charger			
05:25.3 Camera connected to Axon Dock X630020W7	96	0	55.176
05:25.4 Audit log created		1.18.19	
05:25.4 Audit log rolled			
05:26.0 Camera connected to Axon Dock X630020W7	96	0	55.175
05:26.9 Audit log created	96	1.18.19	55.176
05:26.9 Audit log rolled	96		55.176
05:26.0 Audit log created	100	0 1.18.19	55.175
05:26.1 Audit log created	100	0 1.18.19	55.175
05:26.1 Audit log created	100	0 1.18.19	55.174
05:26.2 Audit log created	100	0 1.18.19	55.174

05:26.2 Audit log created	100	0 1.18.19	55.174
05:26.2 Audit log created	100	0 1.18.19	55.174
05:26.3 Audit log created	100	0 1.18.19	55.174
05:26.3 Audit log created	100	0 1.18.19	55.173
05:26.4 Audit log created	100	0 1.18.19	55.173
05:26.4 Audit log created	100	0 1.18.19	55.173
05:26.5 Audit log created	100	0 1.18.19	55.172
05:26.5 Audit log created	100	0 1.18.19	55.172
05:26.5 Audit log created	100	0 1.18.19	55.172
05:26.6 Audit log created	100	0 1.18.19	55.172
05:26.6 Audit log created	100	0 1.18.19	55.171
05:26.7 Audit log created	100	0 1.18.19	55.171
05:26.7 Audit log created	100	0 1.18.19	55.171
05:26.7 Audit log created	100	0 1.18.19	55.171
05:26.8 Audit log created	100	0 1.18.19	55.17
20:23.0 Device disconnected from charger	98	0	55.17
20:23.0 Camera disconnected from Axon Dock X630020W7	98	0	55.17
20:23.2 Audio recording disabled due to video buffering default			
20:29.0 Programmable button pressed			
20:29.0 Programmable button released			
20:35.5 Power button pressed			
20:38.5 Device powered off using button	100	0	55.17
20:39.0 Power button released			
47:08.0 Audit log created		1.18.19	
47:08.0 Device powered on due to charger connection	96	0	55.17
47:08.0 Device connected to charger			
47:08.3 Camera connected to Axon Dock X630020W7	96	0	55.17
47:08.3 Audit log rolled			
47:08.3 Audit log created		1.18.19	
47:09.0 Camera connected to Axon Dock X630020W7	96	0	55.17
47:09.9 Audit log rolled	96		55.17
47:09.9 Audit log created	96	1.18.19	55.17
47:09.0 Audit log created	100	0 1.18.19	55.169
47:09.1 Audit log created	100	0 1.18.19	55.169
47:09.1 Audit log created	100	0 1.18.19	55.169
47:09.1 Audit log created	100	0 1.18.19	55.168
47:09.2 Audit log created	100	0 1.18.19	55.168
47:09.2 Audit log created	100	0 1.18.19	55.168
47:09.3 Audit log created	100	0 1.18.19	55.168
47:09.3 Audit log created	100	0 1.18.19	55.167
47:09.3 Audit log created	100	0 1.18.19	55.167
47:09.4 Audit log created	100	0 1.18.19	55.167
47:09.4 Audit log created	100	0 1.18.19	55.167
47:09.4 Audit log created	100	0 1.18.19	55.167
47:09.5 Audit log created	100	0 1.18.19	55.167
47:09.5 Audit log created	100	0 1.18.19	55.167
47:09.6 Audit log created	100	0 1.18.19	55.167

47:11.2 Audit log created	100	0 1.18.19	55.167
47:11.2 Audit log created	100	0 1.18.19	55.167
47:11.2 Audit log created	99	0 1.18.19	55.167
47:11.2 Audit log created	99	0 1.18.19	55.167
52:09.0 Device disconnected from charger	100	0	55.167
52:09.3 Camera disconnected from Axon Dock X630020W7	100	0	55.167
52:09.4 Audio recording disabled due to video buffering default			
52:12.3 Camera connected to Axon Dock X630020W7	100	0	55.167
52:12.4 Audit log created	100	0 1.18.19	55.167
52:12.4 Audit log rolled	100	0	55.167
52:13.0 Device connected to charger	100	0	55.167
52:12.0 Audit log created	100	0 1.18.19	55.167
52:12.1 Audit log created	100	0 1.18.19	55.167
52:12.1 Audit log created	100	0 1.18.19	55.167
52:12.2 Audit log created	100	0 1.18.19	55.167
52:12.2 Audit log created	100	0 1.18.19	55.167
52:12.3 Audit log created	100	0 1.18.19	55.167
52:12.3 Audit log created	100	0 1.18.19	55.167
52:12.3 Audit log created	100	0 1.18.19	55.167
52:12.4 Audit log created	100	0 1.18.19	55.167
52:12.4 Audit log created	100	0 1.18.19	55.167
52:12.5 Audit log created	100	0 1.18.19	55.167
52:12.5 Audit log created	100	0 1.18.19	55.167
52:12.5 Audit log created	100	0 1.18.19	55.167
52:12.6 Audit log created	100	0 1.18.19	55.167
52:12.6 Audit log created	100	0 1.18.19	55.167
52:12.7 Audit log created	100	0 1.18.19	55.167
52:12.7 Audit log created	100	0 1.18.19	55.167
52:12.7 Audit log created	100	0 1.18.19	55.167
52:12.8 Audit log created	100	0 1.18.19	55.167
52:12.8 Audit log created	100	0 1.18.19	55.167
52:12.9 Audit log created	100	0 1.18.19	55.167
52:12.9 Audit log created	100	0 1.18.19	55.167
46:14.9 Volume down button pressed			
46:15.0 Camera disconnected from Axon Dock X630020W7	100	0	55.167
46:15.1 Volume down button released			
46:15.9 Volume changed to low from medium using button			
46:16.9 Programmable button pressed			
46:17.0 Device disconnected from charger	97	0	55.167
46:17.2 Programmable button released			
46:20.1 Select button pressed			
46:20.2 Select button released			
46:21.0 Select button pressed			
46:21.2 Select button released			
46:23.8 Volume up button pressed			
46:24.0 Volume up button released			
46:24.1 Volume changed to medium from low using button			

46:28.6 Power button pressed			
46:31.6 Device powered off using button	100	0	55.167
46:32.1 Power button released			